

MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE NAIG SECRETARY OF AGRICULTURE

Executive Council of Jowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

April 7, 2025

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on this date, approved payment of the following cost item:

This represents full and final payment, \$48.00 will be reverted and this allocation closed.

EXECUTIVE COUNCIL OF IOWA

Kristi Onstot

Kristi Onstot
Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services
DAS Fleet Services, Risk
Matt Bender, Department of Management
Heather Hackbarth, Department of Management

OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building Des Moines, Iowa 50319-0004

Telephone (515) 281-5834

March 4, 2025

Kristi Onstot Executive Council L O C A L

Subject: Deer Damage to Vehicle #491 on November 13, 2024

Department of Administrative Services Claim dated November 13, 2024

AOS Claim ID: 3943

In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to the damages and have found the items to be in order as shown below:

Documented request		\$ 5,570.99
Executive Council Allocation		\$ 5,618.99
Less: Previous payments This payment Total	\$ 0.00 5,570.99	\$ 5,570.99
Remaining Executive Council alloca	\$ 48.00	

We recommend reimbursement be made in the amount of \$5,570.99. This represents <u>full</u> and <u>final</u> payment of the loss. The remaining allocation should be reverted to the State Treasury.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Bri R Bris

CC: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services



KIM REYNOLDS, GOVERNOR

ADAM STEEN, DIRECTOR

Date: January 27, 2025

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Ryan Betts, DAS Fleet Risk Manager

DAS Fleet Services

Department of Administrative Services

Re: REIMBURSEMENT REQUEST - 29C20 Claim

	25-12 105 (Claim
AOS Claim #	3943
Vehicle / Event	#491/Deer
Event Date	November 13, 2024
Summary	Vehicle 491 struck a deer. (294189)
Amount Requested	\$5,570.99 - Total

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund - Disaster Aid. Please deposit into the following account: 0665-005-5790-0657.

If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,

Ryan Betts

DAS Fleet Risk Manager ryan.betts1@iowa.gov

515-281-8008









Ryan Betts **Financial User**



Warrants

Edit

Cancel

* Required fields



Warrant Information

Fiscal Year

2025 **Vendor Customer** 00003032666

Amount \$5,570.99 Line Number

1

Warrant Number 86409796 Last Updated 12/03/2024 08:08 PM

→ Issue Information

Issued

11/25/2024 12:00 AM

Duplicate No

Line Amount \$765.00

Void

No

Transaction Line Number

Comments

Transaction ID

RISK00525329002

Stop No

Redeemed Information

Redeemed

12/03/2024 12:00 AM Sequence Number

00013

Batch Number

0992

Redeemed Fund

0665

Redeemed Bank

0022

Redeemed Department

005

< COA

Fund

0665

Sub Fund

Department

005

Object Class

Appropriation

0000 Sub BSA

Show More

Object

2715

Sub Object

Unit

5790

Revenue Source

Revenue Source Class

Dept Object

Dept Revenue

Sub Unit

Sub Revenue Source

BSA



COPELAND AUTO BODY, INC.

estimates@copelandautobody.com 506 E 2nd St, P.O. Box 109, Hedrick, IA 52563 Phone: (641) 653-2140 FAX: (641) 653-4301

Workfile ID: PartsShare: b64d9eca 8fryN2

Federal ID:

42-1488559

Supplement of Record 1 with Summary

RO Number: 20763

Written By: Brandon Petrehn, 11/22/2024 8:53:18 AM

Insured:

State Of Iowa

Policy #:

Claim #:

APDS0I0294189-001

Type of Loss:

State Of Iowa

109 SE 13th St

Owner:

Date of Loss: 11/13/2024 6:00 AM Days to Repair:

Point of Impact: 01 Right Front

Des Moines, IA 50319-9018

Inspection Location:

COPELAND AUTO BODY, INC.

506 E 2nd St P.O. Box 109 Hedrick, IA 52563

Repair Facility

(641) 653-2140 Business

Insurance Company: Creative Risk Solutions

(319) 759-0739 Cell

VEHICLE

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Orange

VIN:

2C3CDXKG4NH236226

Interior Color:

Black

Mileage In:

58,474

Good

Vehicle Out: 11/21/2024

License: **GBX425**

Mileage Out:

IΑ

State:

Exterior Color: Production Date: Orange 8/2022

Condition:

Job #:

TRANSMISSION

Automatic Transmission

4 Wheel Drive

POWER

Power Steering Power Brakes

Power Windows Power Locks

Power Mirrors

Power Driver Seat **DECOR Dual Mirrors** Tinted Glass

Overhead Console

CONVENIENCE

Air Conditioning Intermittent Wipers

Tilt Wheel Cruise Control Rear Defogger

Keyless Entry

Climate Control Backup Camera

RADIO

FM Radio

Search/Seek

Message Center

Steering Wheel Touch Controls

Telescopic Wheel Parking Sensors

AM Radio

Stereo

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4) 4 Wheel Disc Brakes Front Side Impact Air Bags Head/Curtain Air Bags Hands Free Device

SEATS

Cloth Seats **Bucket Seats**

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint Two Tone Paint

OTHER Traction Control Stability Control California Emissions

Get live updates at www.carwise.com/e/4VNhVq

Page 1 11/22/2024 8:53:44 AM 312629

Supplement of Record 1 with Summary

RO Number: 20763

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Orange

Line			Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT	ВИМРЕ	R & G	RILLE					
2				O/H front bumper				3.4	
3	**		Repl	A/M CAPA Bumper cover	68267765AC	1	678.00	Incl.	3.4
4				Add for Clear Coat					1.4
5				Add for Two Tone					1.4
6	**		Repl	A/M Upper grille black crossbars	5PP33DX8AB	1	307.34	Incl.	
7			Repl	RT Bumper bracket	68226544AB	1	44.45	0.1	
8			Repl	RT Support inner	68226532AA	1	44.20	Incl.	
9			Repl	RT Support outer	68213539AC	1	12.75	Incl.	
10		S01	Repl	Nameplate "DODGE" black	68227437AA	1	107.00	0.1	
11	**	S01	Repl	A/M Closure panel	68226530AF	1	174.00	Incl.	
12	FRONT	LAMPS							
13	**		Repl	A/M RT Headlamp assy halogen	68546770AC	1	567.00	0.4	
14	**		Repl	A/M CAPA RT Side marker lamp	68214404AA	1	37.60	Incl.	
15			Repl	Aim headlamps		1		0.5	
16	RADIA	TOR SU	PPORT	Г					
17	**		Repl	A/M Radiator support	68200478AC	1	318.00	1.0	1.6
18		S01	Repl	RT Support bracket	68249076AA	1	13.00	0.1	
19	HOOD								
20	*		Blnd	Hood (ALU)					<u>1.5</u>
21	FENDE	R							
22	**		Repl	A/M CAPA RT Fender w/o wide body	68213060AC	1	284.00	1.6	2.0
23				Add for Clear Coat					0.8
24				Add for Edging					0.5
25	*			Add for Clear Coat					0.0
26			R&I	RT Fender liner 3.6, 5.7 liter				Incl.	
27	FRONT	DOOR							
28	*		Blnd	RT Door shell (HSS)					<u>1.1</u>
29			R&I	RT Belt w'strip				0.3	
30	*		R&I	RT Power mirror				<u>0.5</u>	
31			R&I	RT Handle, outside mango				0.4	
32			R&I	RT Mount plate				0.6	
33			R&I	RT R&I trim panel				0.5	
34	VEHIC	LE DIAG	NOST	ICS					
35	*	S01		Pre-repair scan		1	<u>118.65</u> m	<u>0.5</u> M	
36	*	S01		Post-repair scan		1	<u>141.50</u> m	<u>0.5</u> M	
37	MISCE	LLANEO	US OP	ERATIONS					
38	*		Repl	Cover car/bag		1	<u>5.00</u>	0.2	
39	#		Subl	Hazardous waste removal		1	3.00 T		
40	#		Repl	Corrosion protection		1	6.00 T		
41	#			Test drive to Verify Repair Quality and ADAS Function		1		0.5	

Supplement of Record 1 with Summary

RO Number: 20763

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Orange

SUBTOTALS	2,861.49	11.2	13.7

NOTES

Prior Damage Notes: None

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				2,852.49
Body Labor	10.2 hrs	@	\$ 75.00 /hr	765.00
Paint Labor	13.7 hrs	@	\$ 135.00 /hr	1,849.50
Mechanical Labor	1.0 hrs	@	\$ 95.00 /hr	95.00
Miscellaneous				9.00
Subtotal				5,570.99
Grand Total				5,570.99
Deductible				0.00
CUSTOMER PAY				0.00
INSURANCE PAY				5,570.99

RO Number: 20763

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Orange

SUPPLEMENT SUMMARY

Line			Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Chang	ed Item	S							
32	*			Pre-repair scan		1	<u>-65.00</u> m	<u>-0.5</u> M	
35	*	S01		Pre-repair scan		1	<u>118.65</u> m	<u>0.5</u> M	
33	*			Post-repair scan		1	<u>-134.95</u> m	<u>-0.5</u> M	
36	*	S01		Post-repair scan		1	<u>141.50</u> m	<u>0.5</u> M	
Added	Items								
10		S01	Repl	Nameplate "DODGE" black	68227437AA	1	107.00	0.1	
11	**	S01	Repl	A/M Closure panel	68226530AF	1	174.00	Incl.	
18		S01	Repl	RT Support bracket	68249076AA	1	13.00	0.1	
					SUBTOTALS		354.20	0.2	0.0

TOTALS SUMMARY

Category	Basis		Rate	Cost \$
Parts				354.20
Body Labor	0.2 hrs	@	\$ 75.00 /hr	15.00
Subtotal				369.20
Total Supplement Amount				369.20
NET COST OF SUPPLEMENT				369.20

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Job Total: INSURANCE PAY:	\$ \$	5,570.99 5,570.99	
Supplement S01		369.20	Brandon Petrehn
Estimate		5,201.79	Brandon Petrehn

ATTENTION: WHEELS NEED TO BE RE-TORQUED WITHIN 100 MILES. FAILURE TO DO SO MAY RESULT IN FURTHER DAMAGE!

Warranty Disclosure: Our Warranty will include our Workmanship, including neccessary refinishing for as long as you, the customer, own the vehicle. Guarantee corrective repairs will be provided at no additional cost. Warranty and workmanship guarantee may NOT include items such as normal wear and tear, prior damage, new damage or negligence.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Supplement of Record 1 with Summary

RO Number: 20763

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Orange

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 11/15/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.

D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

RO Number: 20763

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Orange

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
3	Keystone, Inc	#CH1000A24PP	\$ 678.00
	810 SE CORPORATE WOODS DR, SUITE 120	A/M CAPA Bumper cover	
	ANKENY IA 50021	Quote: 2738294053	
	(515) 727-7857	Expires: 12/28/24	
6	AutoZone	#LKQ CH1200388	\$ 307.34
	946 N Quincy Ave	A/M Upper grille black crossbars	
	Ottumwa IA 52501	Quote: 2US24DYG6J79CC2	
	(641) 682-9170	Expires: 12/13/24	
11	Keystone, Inc	#CH1224101	\$ 174.00
	810 SE CORPORATE WOODS DR, SUITE 120	A/M Closure panel	
	ANKENY IA 50021	Quote: 2744371799	
	(515) 727-7857	Expires: 01/02/25	
13	Keystone, Inc	#CH2503356	\$ 567.00
	810 SE CORPORATE WOODS DR, SUITE 120	A/M RT Headlamp assy halogen	
	ANKENY IA 50021	Quote: 2738275815	
	(515) 727-7857	Expires: 12/28/24	
14	All Star Auto Parts	#186163009	\$ 37.60
	3250 N Post Rd, Bldg 200	A/M CAPA RT Side marker lamp	
	INDIANAPOLIS IN 46226	Quote: 3014463398	
	(407) 271-8949	Expires: 11/20/24	
17	Keystone, Inc	#CH1225280	\$ 318.00
	810 SE CORPORATE WOODS DR, SUITE 120	A/M Radiator support	
	ANKENY IA 50021	Quote: 2738279867	
	(515) 727-7857	Expires: 12/28/24	
22	Keystone, Inc	#CH1241282PP	\$ 284.00
	810 SE CORPORATE WOODS DR, SUITE 120	A/M CAPA RT Fender w/o wide body	
	ANKENY IA 50021	Quote: 2738364733	
	(515) 727-7857	Expires: 12/28/24	



OFFICE OF AUDITOR OF STATE

STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building Des Moines, Iowa 50319-0004 Telephone (515) 281-5834

January 21, 2025

Kristi Onstot Executive Council LOCAL

cc:

Subject: Deer Damage to Vehicle #491 on November 13, 2024

Department of Administrative Services

Claim dated November 13, 2024

AOS Claim ID: 3943

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$5,618.99, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Pri RAS

Adam Steen, Director, Department of Administrative Services Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services

Heather Hackbarth, Department of Management