



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: November 29, 2022

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#105401/Deer
Event Date	September 9, 2022
Summary	Vehicle #105401 struck a deer. (244511)
Amount Requested	\$10,024.81 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-414-6582



Risk, DAS <das.risk@iowa.gov>

FW: SFM - FSTB F350 105401

1 message

Adams Jeannie <jadams@dps.state.ia.us>

Fri, Sep 9, 2022 at 9:44 AM

To: "ExecutiveCouncil [TOS]" <ExecutiveCouncil@tos.iowa.gov>, Tammy Hollingsworth

<Tammy.Hollingsworth@aos.iowa.gov>

Cc: "Risk, DAS (das.risk@iowa.gov)" <das.risk@iowa.gov>

This morning SFM truck 105401 hit a deer and has front end damage. We are in the process of towing it to a body shop now. More information to follow.

Jeannie Adams
ISP Fleet & Supply, Fleet Asset Manager
Department of Public Safety
30 N.E. 48th Place
Des Moines, Iowa 50313
Direct #: 515-725-0643
Cell Phone: 515-204-3019
Shop: 515-281-3277
Fax: 515-242-6321
Email: jadams@dps.state.ia.us<mailto:jadams@dps.state.ia.us>

From: Dunn Jess <dunn@dps.state.ia.us>

Sent: Friday, September 9, 2022 9:38 AM

To: Adams Jeannie <jadams@dps.state.ia.us>

Cc: Wood Daniel <wood@dps.state.ia.us>; Grossman Russell <grossman@dps.state.ia.us>

Subject: RE: SFM - FSTB F350 tow

Doubtful. Looks like a lot of front end damage though. Do I need to send the 24 hour notification to the DAS-Risk email or only the DSP vehicle damage?

Jess

From: Adams Jeannie <jadams@dps.state.ia.us<mailto:jadams@dps.state.ia.us>>

Sent: Friday, September 9, 2022 9:35 AM

To: Dunn Jess <dunn@dps.state.ia.us<mailto:dunn@dps.state.ia.us>>

Cc: Wood Daniel <wood@dps.state.ia.us<mailto:wood@dps.state.ia.us>>; Grossman Russell

<grossman@dps.state.ia.us<mailto:grossman@dps.state.ia.us>>

Subject: RE: SFM - FSTB F350 tow

Good morning Jess

Do you think it is a total?

Jeannie Adams
ISP Fleet & Supply, Fleet Asset Manager
Department of Public Safety
30 N.E. 48th Place
Des Moines, Iowa 50313
Direct #: 515-725-0643
Cell Phone: 515-204-3019
Shop: 515-281-3277
Fax: 515-242-6321
Email: jadams@dps.state.ia.us<mailto:jadams@dps.state.ia.us>

From: Dunn Jess <dunn@dps.state.ia.us<mailto:dunn@dps.state.ia.us>>
Sent: Friday, September 9, 2022 9:30 AM
To: Adams Jeannie <jadams@dps.state.ia.us<mailto:jadams@dps.state.ia.us>>
Cc: Wood Daniel <wood@dps.state.ia.us<mailto:wood@dps.state.ia.us>>; Grossman Russell
<grossman@dps.state.ia.us<mailto:grossman@dps.state.ia.us>>
Subject: SFM - FSTB F350 tow

Jeannie,

Just giving you a heads-up that a SFM-FSTB F350 pickup (Plate 105401) is being towed by Hanifen down to F&S today. I suspect it will arrive after lunch. It hit a deer this morning. I am working on the notifications, etc. Lt. Guill said you might be able to coordinate getting the estimates for repair. Would you be able to do this? If not, I can certainly arrange coming down there taking care of that. Please let me know either way.

Thanks.....Jess

Jess R. Dunn
Bureau Chief
Fire Service Training Bureau
Division of State Fire Marshal
Iowa Department of Public Safety
Building 3536 (B-59)
7105 NW 70th Avenue
Johnston, Iowa 50131-1824
Main 515-727-3426
Cell 515-559-7052

NOTICE This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.



20220909_082235.jpg
556K



State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #:

Date: <small>(Month/Day/Year)</small>	9/9/2022	Time: <small>(Time plus a.m./p.m.)</small>	8:35 AM a.m.
Vehicle Plate #:	105401	Vehicle Mileage:	86372
Vehicle Description: <small>(Yr/Make/Model/ & Vin#)</small>	2019 Ford 350 PICKUP		
Assigned To:	SFM/FSTB	Badge #	
Driven By:	Russ Grossman	Badge #	
Driver's Lic #:	898ZZ4152	Damage:	\$
Vehicle Towed: <small>(Yes / No)</small>	yes	Towed By:	Hanifen
Towed To:	Karl's Collision	Towing Cost:	\$
Seat Belt: <small>(Yes / No)</small>	Yes	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Marked
Injured/Injuries:	None		
Occupants: <small>(Other than driver)</small>			

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	YES
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

OTHER INFORMATION:

Witnesses:	NONE
Accident Location: (Street/Hwy)	eastbound on Highway 30. struck a deer just west of Hillcrest Ave.
County:	GREENE - 37
Weather/Road Conditions:	CLEAR
Narrative:	Driving east on HWY 30 deer entered the road way and was struck on the passenger side front right and center of the pickup.
Property Damage other than Vehicles:	none
Cost:	\$ est. \$9000.00
Citations Issued To: (List Charge(s) and Statute Code(s))	none

Investigating Officer:	TROOPER N CHRISTIAN
------------------------	---------------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

INVESTIGATING OFFICER'S REPORT OF MOTOR VEHICLE ACCIDENT

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Law Enforcement Case Number:
2022022256

L O C A T I O N	Date of Accident 09/09/2022	Time of Accident 08:35 Hrs.	County GREENE - 37	Accident occurred within corporate limits of (city)		Legal Intervention? <input type="checkbox"/>	Private Property? <input type="checkbox"/>	
	Literal Description US 30 E MEASURING 357 FEET WEST FROM HILLCREST AVE					County: 37	Route: _____	
	If accident occurred outside of city limits show general vicinity N NE E SE S SW W NW ○ ○ ○ ○ ○ ○ ○ ○ of nearest city					X Coordinate: 377023.937		
	On Road, Street or Highway:			At Intersection with:			Y Coordinate: 4654679.5	
	Note: Unless accident occurred at an intersection which is completely described above, use the space below to give the exact location from a milepost or definable intersection, bridge, or railroad crossing, using two distances and directions if necessary of					If Divided Highway, Provide Route (Cardinal) Travel Direction		
Milepost Number _____ Or _____ Definable intersection, bridge, or railroad crossing					NB <input type="checkbox"/> SB <input type="checkbox"/> EB <input type="checkbox"/> WB <input type="checkbox"/>			

ACCIDENT ENVIRONMENT			ROADWAY CHARACTERISTICS									
Location of First Harmful Event	Weather Conditions (up to two)		Major Contributing Circumstances Environment									
Manner of Crash/Collision			Roadway									
Light Conditions	Surface Conditions		Type of Roadway Junction/Feature									
First Harmful Event (Crash)			FRA No.									

31	WORKZONE RELATED? <input type="checkbox"/>	Yes <input type="checkbox"/> No <input type="checkbox"/>	Activity	Location	Type	Workers Present	Sex	Struck by Unit No.	Injury Status	Non-Motorist Type	Location (prior to impact)	Action (prior to crash)	Condition	Safety Equipment	Contributing Circumstances	Source of Transport	Died at scene/enroute
----	--	--	----------	----------	------	-----------------	-----	--------------------	---------------	-------------------	----------------------------	-------------------------	-----------	------------------	----------------------------	---------------------	-----------------------

N O N M O T O R I S T S	Name 001	Phone Number	DOB:	Sex	Struck by Unit No.	Injury Status	Non-Motorist Type	Location (prior to impact)	Action (prior to crash)	Condition	Safety Equipment	Contributing Circumstances	Source of Transport	Died at scene/enroute	
	Address:	Alcohol Test Given	Test Results:	Drug Test Given	Result	Charged	Yes <input type="checkbox"/> No <input type="checkbox"/>								
	Transported to:	Transported by:													
	Name	Phone Number	DOB:	Sex	Struck by Unit No.	Injury Status	Non-Motorist Type	Location (prior to impact)	Action (prior to crash)	Condition	Safety Equipment	Contributing Circumstances	Source of Transport	Died at scene/enroute	
Address:	Alcohol Test Given	Test Results:	Drug Test Given	Result	Charged	Yes <input type="checkbox"/> No <input type="checkbox"/>									
Transported to:	Transported by:														

N P O R N O V P E E H R I T C Y U L D A M R G	If Property other than vehicles damaged explain	Object Damaged	Estimate of Damage														
	Owner's Last Name	First Name	Middle Name	Phone Number													
	Address	City	State	Zip Code	Was owner or tenant notified? 1 = Yes 2 = No 9 = Unknown												

U L D A M R G	If Property other than vehicles damaged explain	Object Damaged	Estimate of Damage														
	Owner's Last Name	First Name	Middle Name	Phone Number													
	Address	City	State	Zip Code	Was owner or tenant notified? 1 = Yes 2 = No 9 = Unknown												

W I T N E S S	Last Name	First Name	Address	City	State	Zip Code	Phone Number
	Last Name	First Name	Address	City	State	Zip Code	Phone Number
	Last Name	First Name	Address	City	State	Zip Code	Phone Number
	Last Name	First Name	Address	City	State	Zip Code	Phone Number
	Last Name	First Name	Address	City	State	Zip Code	Phone Number

Is This a Secondary Crash? Y <input type="checkbox"/> N <input checked="" type="checkbox"/>	Type of Primary Incident	Roadway Clearance Date 09/09/2022	Incident Clearance Date 09/09/2022
--	--------------------------	---	--

Signature of Officer TROOPER N CHRISTIAN	Badge Number 214	Time Officer Notified of Accident 08:38 Hrs.	Roadway Clearance Time 09:00 Hrs.	Incident Clearance Time 09:29 Hrs.
Name of Agency IOWA STATE PATROL - DIST 04	Date of Report 09/09/2022	Time Officer Arrived At Scene 08:59 Hrs.	Total Roadway Clearance Time 000:22	Total Incident Clearance Time 000:51
Report Reviewed By	Date of Review	Investigation made at scene? Y <input checked="" type="checkbox"/> N <input type="checkbox"/>	T.I. No.	Other Technical Investigating Agency

INVESTIGATING OFFICER'S REPORT
OF MOTOR VEHICLE ACCIDENT

Form 4433003 (11-13)

Law Enforcement Case Number:

2022022256

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

D
I
A
G
R
A
M

Not to Scale



Highway 30



Hillcrest Ave

N
A
R
R
A
T
I
V
E

Unit 1 was eastbound on Highway 30. Unit 1 then struck a deer just west of Hillcrest Ave.

**Karl Chevrolet Collision Center
Ankeny**

Your Dealer for Life
1101 Southeast Oralabor Road, Ankeny, IA 50021
Phone: (515) 299-4337
FAX: (515) 964-2293

Workfile ID: 7d7a7bbc
PartsShare: 6X3kMZ
Federal ID: 42-1092272

Final Bill

RO Number: 889014

Customer:	Insurance:	Adjuster:	Estimator:	Michael Wright
STATE OF IOWA FIRE	STATE OF IOWA	Phone:	Create Date:	9/9/2022
		Claim:	APDSOI0244511-00	
			1	
		Loss Date:		
(515) 299-4300		Deductible:		

2019 FORD Super Duty F-350 w/Single Rear Wheels XL Crew Cab 4WD w/6.75' Box 4D SHORT 8-6.7L Turbocharged Diesel Diesel Direct Injection RED

VIN: 1FT8W3BT4KEF56473	Interior Color: BLACK	Mileage In: 86,372	Vehicle Out: 10/17/2022
License: 105401	Exterior Color: RED	Mileage Out:	
State: IA	Production Date:	Condition:	Job #: 3248

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		FRONT BUMPER						
2	E01	Remove/Replace	O/H front bumper				3.7	Body	
3	E01	Remove/Replace	LT Mount plate	1	85.66	OEM	0.0	Body	
4	E01	Remove/Replace	RT Mount plate	1	66.95	OEM	0.0	Body	
5	E01	Remove/Replace	Bumper	1	1,086.00	A/M	0.0	Body	2.1
6	E01		Add for Clear Coat						0.8
7	E01	Remove/Replace	LT Inner bracket	1	30.66	OEM	0.0	Body	
8	E01	Remove/Replace	RT Inner bracket	1	30.66	OEM	0.0	Body	
9	E01	Remove/Replace	RT Air duct	1	71.02	OEM	0.0	Body	
10	E01	Remove/Replace	LT Air duct	1	71.02	OEM	0.0	Body	
11	E01	Remove/Replace	RT Cap	1	16.17	OEM	0.2	Body	
12	E01	Remove/Replace	LT Cap	1	13.93	OEM	0.2	Body	
13	S01	Remove/Replace	LT Side bracket	1	30.07	OEM	0.0	Body	
14	S01	Remove/Replace	RT Side bracket	1	28.93	OEM	0.0	Body	
15	E01	Remove/Replace	Step pad	1	57.60	OEM	0.0	Body	
16	E01	Remove/Replace	LT Outer molding	1	49.62	OEM	0.0	Body	
17	S01	Remove/Replace	RT Outer molding	1	51.36	OEM	0.0	Body	
18	S01	Remove/Replace	Valance 4WD	1	141.62	OEM	0.0	Body	
19	E01		GRILLE						
20	E01	Remove/Replace	Grille assy gray/black	1	414.07	OEM	0.0	Body	
21	E01	Remove/Replace	Aim camera				1.0	Body	
22	S01	Remove/Replace	Emblem w/o front camera	1	87.57	OEM	0.0	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Final Bill

RO Number: 889014

2019 FORD Super Duty F-350 w/Single Rear Wheels XL Crew Cab 4WD w/6.75' Box 4D SHORT 8-6.7L Turbocharged Diesel Diesel Direct Injection RED

23	E01		FRONT LAMPS						
24	E01	Remove/Replace	RT Headlamp assy	1	704.58	OEM	0.0	Body	
25	E01	Remove/Replace	Aim headlamps				0.5	Body	
26	E01	Remove/Install	LT R&I headlamp assy				0.4	Body	
27	E01		RADIATOR SUPPORT						
28	E01	Remove/Replace	Mount panel	1	259.68	OEM	1.6	Body	
29	E01	Remove/Replace	Air shield 6.7 liter w/o distance sensor	1	122.12	OEM	0.4	Body	
30	E01	Remove/Replace	RT Air deflector 6.7 liter	1	17.63	OEM	0.0	Body	
31	E01	Remove/Replace	LT Air deflector 6.7 liter	1	18.40	OEM	0.0	Body	
32	E01	Remove/Replace	RT Inner shield 6.7 liter	1	14.93	OEM	0.0	Body	
33	E01	Remove/Replace	LT Inner shield 6.7 liter	1	16.57	OEM	0.0	Body	
34	E01	Remove/Install	Sight shield 6.7 liter				0.0	Body	
35	E01	Remove/Install	Upper tie bar (ALU)				1.2	Body	
36	E01		COOLING						
37	E01	Remove/Replace	Radiator	1	795.87	OEM	4.8	Body	
38	E01	Remove/Replace	Connector hose	1	122.73	OEM	0.4	Body	
39	S01	Remove/Replace	Aux radiator	1	768.02	A/M	0.0	Body	
40	E01	Remove/Replace	Upper shroud	1	243.20	OEM	0.0	Body	
41	E01	Remove/Replace	Lower shroud	1	210.63	OEM	0.0	Body	
42	E01		AIR CONDITIONER & HEATER						
43	E01	Remove/Replace	Condenser	1	301.82	OEM	1.1	Body	
44	E01	Remove/Replace	AC Service evacuate & recharge				1.4	Body	
45	E01	Remove/Replace	AC Service refrigerant recovery				0.4	Body	
46	E01	Remove/Replace	Deduct for Overlap				(0.5)	Body	
47	E01		HOOD						
48	E01	Remove/Replace	Hood (ALU)	1	842.90	OEM	2.2	Body	3.2
49	E01		Add for Clear Coat						1.3
50	E01		Add for Underside(Complete)						1.6
51	E01	Remove/Install	RT Hinge				0.3	Body	
52	E01		FENDER						
53	E01	Remove/Install	RT Fender liner				0.0	Body	
54	S01	Remove/Replace	RT Upper rail assy (HSS)	1	246.94	OEM	5.8	Body	1.4
55	E01	Remove/Replace	Deduct for Overlap				(1.5)	Body	
56	E01	Remove/Install	RT Mud guard factory				0.2	Body	
57	S01	Remove/Replace	RT Fender w/o wheel opening mldg single rr whl (ALU)	1	307.09	A/M	2.9	Body	2.6
58	E01		Overlap Major Adj. Panel						(0.4)
59	E01		Add for Clear Coat						0.4
60	E01		Add for Edging						0.5
61	E01		Add for Clear Coat						0.1
62	E01		FRAME						
63	S01	Remove/Replace	RT Tow hook black	1	163.27	OEM	0.3	Body	
64	S01	Remove/Replace	LT Tow hook black	1	163.27	OEM	0.3	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Final Bill

RO Number: 889014

2019 FORD Super Duty F-350 w/Single Rear Wheels XL Crew Cab 4WD w/6.75' Box 4D SHORT 8-6.7L Turbocharged Diesel Diesel Direct Injection RED

65	E01		ELECTRICAL					
66	E01	Remove/Install	RT Battery			0.5	Body	
67	E01	Remove/Install	RT Battery tray			0.3	Body	
68	E01		ENGINE					
69	E01	Remove/Install	Air cleaner assy			0.6	Body	
70	E01		CAB					
71	E01	Remove/Install	RT Cowl grille			0.4	Body	
72	E01	Remove/Install	LT Cowl grille			0.4	Body	
73	E01		FRONT DOOR					
74	E01	Blend	RT Outer panel (ALU)					1.3
75	E01	Remove/Install	RT Belt molding black			0.3	Body	
76	S01	Remove/Replace	RT Nameplate "6.7L"	1	29.78	OEM	0.2	Body
77	S01	Remove/Replace	RT Nameplate "POWER STROKE"	1	52.14	OEM	0.2	Body
78	E01	Remove/Install	RT R&I mirror			0.4	Body	
79	E01	Remove/Install	RT Run channel			0.2	Body	
80	E01	Remove/Install	RT Handle, outside black w/o cylinder			0.7	Body	
81	E01	Remove/Install	RT R&I trim panel			0.6	Body	
82	E01	Remove/Install	RT Applique XL, XLT SUPER CAB, CREW CAB, w/o keyless pad			0.3	Body	
83	E01	Remove/Install	RT Door glass Ford			0.4	Body	
84	E01	Remove/Install	RT Window regulator manual			0.4	Body	
85	E01		MISCELLANEOUS OPERATIONS					
86	E01	Remove/Replace	Corrosion protection	1	3.00	A/M	0.3	Body
87	E01	Remove/Replace	Cover Car	1	5.00	A/M		
88	E01	Sublet	Hazardous waste removal	1	5.00	Other		
89	E01	Remove/Replace	Seam sealer	1	49.95	Other	1.0	Body
90	E01	Remove/Install	decals				2.0	Body
91	S01	Remove/Replace	Coolant	5	99.65	Other		
92	E01	Repair	trim valance for plow				1.0	Body
93	E01	Remove/Install	miscellaneous wiring				2.0	Body
94	S01	Sublet	decal replacement image 360	1	513.94	Other		
95	S01		PART FREIGHT	1	52.10	Other		

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts	(2,100.81)				5,843.37
Sublet/Miscellaneous					518.94
Labor, Body			55.00	39.5	2,172.50
Labor, Refinish			100.00	14.9	1,490.00
Subtotal					10,024.81
Sales Tax					0.00
Grand Total					10,024.81
Net Total					10,024.81

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Final Bill

RO Number: 889014

2019 FORD Super Duty F-350 w/Single Rear Wheels XL Crew Cab 4WD w/6.75' Box 4D SHORT 8-6.7L Turbocharged Diesel Diesel Direct Injection RED

Estimate Version	Total \$
Original	9,388.14
Supplement S01	636.67

Insurance Total \$:	10,024.81
Received from Insurance \$:	0.00
Balance due from Insurance \$:	10,024.81

Customer Total \$:	0.00
Received from Customer \$:	0.00
Balance due from Customer \$:	0.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural