



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: November 29, 2022

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#104/Deer
Event Date	October 30, 2022
Summary	Vehicle #104 struck a deer. (247491)
Amount Requested	\$5,276.60 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-414-6582



Risk, DAS <das.risk@iowa.gov>

FW: 104 patrol car damage

1 message

Adams Jeannie <jadams@dps.state.ia.us>

Mon, Oct 31, 2022 at 11:39 AM

To: "ExecutiveCouncil [TOS]" <ExecutiveCouncil@tos.iowa.gov>, "Risk, DAS (das.risk@iowa.gov)" <das.risk@iowa.gov>

Good morning

Trooper Grell (#104) Hit a deer yesterday morning while on duty. More information to come.

Thank you

Jeannie Adams
ISP Fleet & Supply, Fleet Asset Manager
Department of Public Safety
30 N.E. 48th Place
Des Moines, Iowa 50313
Direct #: 515-725-0643
Cell Phone: 515-204-3019
Shop: 515-281-3277
Fax: 515-242-6321
Email: jadams@dps.state.ia.us<mailto:jadams@dps.state.ia.us>

From: Lewis Brett <brlewis@dps.state.ia.us>

Sent: Sunday, October 30, 2022 2:03 AM

To: vehicledamage <vehicledamage@dps.state.ia.us>; DAS.Risk (DAS.Risk@iowa.gov) <DAS.Risk@iowa.gov>

Cc: Knutson Dana <knutson@dps.state.ia.us>; Sinnwell Brian <sinnwell@dps.state.ia.us>; Duenow Keith <duenow@dps.state.ia.us>

Subject: 104 patrol car damage

Trooper Grell struck a deer this morning, October 30th at 0200 hrs. This is just the initial notification, I will complete the vehicle damage report, MARS, photos and he will get an estimate. Also, his patrol car is currently scheduled to get the front bumper fixed from previous damage on October 31st. Let us know if this changes anything with that previous damage repair.

Thanks,

Sergeant Brett Lewis # 147
Iowa Department of Public Safety
Iowa State Patrol District 8
4425 S. Washington Ave.
Mason City, IA 50401-7002

Phone: 641-424-3625

Fax: 641-423-8381

Email: brlewis@dps.state.ia.us<mailto:brlewis@dps.state.ia.us>

[Description: Description: Description: Signature Banner]

NOTICE This e-mail message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this e-mail by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this e-mail or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

image001.jpg
11K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: **DPS – Vehicle Damage; DAS – Risk**

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #: 2022026791

Date: <small>(Month/Day/Year)</small>	10/30/2022	Time: <small>(Time plus a.m./p.m.)</small>	2:00 a.m.
Vehicle Plate #:	104	Vehicle Mileage:	6,118
Vehicle Description: <small>(Yr/Make/Model/ & Vin#)</small>	2021 gray Dodge Charger AWD VIN: 2C3CDXKG7MH644671		
Assigned To:	Trp. Dalton Grell	Badge #	104
Driven By:	Trp. Dalton Grell	Badge #	104
Driver's Lic #:	772AK2798	Damage:	\$
Vehicle Towed: <small>(Yes / No)</small>	No	Towed By:	NA
Towed To:	N/A	Towing Cost:	\$NA
Seat Belt: <small>(Yes / No)</small>	Yes	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Marked
Injured/Injuries:	None		
Occupants: <small>(Other than driver)</small>	Trp. Nate Snieder #150 (FTO)		

VEHICLE #2:

DL #:	NA	State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			

Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

OTHER INFORMATION:

Witnesses:	None
Accident Location: (Street/Hwy)	330 th St. & Apple Ave
County:	Cerro Gordo
Weather/Road Conditions:	Clear
Narrative: Trp. Grell was traveling east on 330 th st. at Apple Ave when a deer entered the roadway and struck Trp. Grell's patrol car causing damage to the front bumper, push bumper and driver side fender.	
Property Damage other than Vehicles:	NA
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	NA

Investigating Officer:	Sgt. Brett Lewis #147
------------------------	-----------------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		



MEMORANDUM

TO: SGT. LEWIS #147
FROM: Trp. Grell #104
DATE: 10-30-2022
SUBJECT: VEHICLE DAMAGE

On 10-29-2022 at approximately 0150 hrs. I Trooper Dalton Grell #104 was driving East bound on 330th St. from Apple Ave. when a deer entered the roadway from the South ditch. I hit my brakes and was not able to stop in time and stuck the deer with the front of my patrol car. The deer was dead on impact and landed on the North side of the road. I sustained vehicle damage to my push bumper, grill, bumper, hood, and front driver fender. My camera did not activate during the impact and I activated it after the collision.

Trooper Dalton Grell #104



NORTH IOWA COLLISION CENTER INC.

Serving your car, light & heavy duty truck, heavy
equipment & RV repair needs.

11201 265TH ST, CLEAR LAKE, IA 50428

Phone: (641) 421-8555

FAX: (641) 421-8558

Workfile ID: e45e995e
PartsShare: 734dR4

Federal ID: 87-2591068
State ID: 1-17-020011
Resale Number: 1-17-020011
Federal EPA: IAR000007856

Preliminary Estimate

Customer: Iowa State Patrol

Written By: Scott Larson

Insured: Iowa State Patrol
Type of Loss:
Point of Impact: 12 Front

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:

Iowa State Patrol
4425 S Washington
Mason City, IA 50401
(111) 111-1111 Cell

Inspection Location:

NORTH IOWA COLLISION CENTER INC.
11201 265TH ST
CLEAR LAKE, IA 50428
Repair Facility
(641) 421-8555 Business

Insurance Company:

VEHICLE

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Silver

VIN: 2C3CDXKG7MH644671 Interior Color: Mileage In: 6,423 Vehicle Out:
License: 104 Exterior Color: Silver Mileage Out:
State: IA Production Date: 9/2021 Condition: Job #: 104

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel

Climate Control
Backup Camera
Parking Sensors

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint
Metallic Paint
Two Tone Paint

OTHER

Traction Control
Stability Control
California Emissions
Power Trunk/Liftgate

Get live updates at www.carwise.com/e/4no4Q3

Preliminary Estimate

Customer: Iowa State Patrol

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Silver

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	Rental Formula 30.7 / 4 = 78		1			
2	#						
3	FRONT BUMPER & GRILLE						
4		O/H front bumper				3.4	
5	** <>	Repl A/M CAPA Bumper cover	68267765AC	1	686.00	Incl.	3.4
6		Add for Clear Coat					1.4
7		Add for Two Tone					1.4
8		Repl Closure panel	68226530AF	1	189.00	Incl.	
9	**	Repl A/M Push Pin		4	24.00		
10	*	R&I Lower grille w/o adaptive cruise				Incl.	
11		R&I License bracket type 1				0.1	
12	#	R&I License plate				0.1	
13	#	Repl Push bar & wraps +25%		1	1,031.55	1.5	
14	#	Rpr Bumper cover - Cut holes for push bar				0.5	
15	#	Subl Shipping		1	100.00 X		
16	**	Repl A/M CAPA Upper grille black crossbars	5PP33DX8AB	1	341.00	Incl.	
17	#	Rpr Upper grille - cut holes for push bar				0.5	
18	FRONT LAMPS						
19	*	R&I LT Headlamp assy halogen				0.4	
20	HOOD						
21	*	Align Hood (ALU)				1.0	
22	*	Rpr Hood (ALU)				3.5	3.0
23		Overlap Major Non-Adj. Panel					-0.2
24		Add for Clear Coat					0.6
25	FENDER						
26	*	Rpr LT Fender w/o wide body				4.5	2.0
27		Overlap Major Adj. Panel					-0.4
28		Add for Clear Coat					0.3
29	#	R&I Decal - "STATE TROOPER" Note: Remove and clean up of adhesive				0.3	
30	**	Repl A/M Decal - "STATE TROOPER"		1		0.2	
31		R&I LT Fender liner				0.3	
32	#	R&I Radar Detection				0.5	
33	PILLARS, ROCKER & FLOOR						
34	*	R&I <u>LT Rocker molding - Loosen for paint</u>				0.3	
35	VEHICLE DIAGNOSTICS						
36	*	Subl Pre-repair scan		1	50.00 X m		
37	#	Rpr Pre Repair Scan Labor				0.5 M	
38	*	Subl Post-repair scan		1	119.95 X m		

Preliminary Estimate

Customer: Iowa State Patrol

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Silver

39	#	Rpr	Post Repair Scan Labor			0.5	M
40	MISCELLANEOUS OPERATIONS						
41	**	Repl	A/M Cover car/bag	1	10.00	0.2	
42	**	Repl	A/M Corrosion Protection	1	10.00	0.2	
43	**	Repl	A/M Cavity wax	1	10.00	0.1	
44	**	Subl	A/M Flex Additive	1	8.00		
45	#	Repl	De-Nib & Polish	1	15.00	0.6	
46			OTHER CHARGES				
47	#		Haz-Waste	1	4.00		
SUBTOTALS					2,598.50	19.2	11.5

NOTES

Prior Damage Notes:
Normal wear

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			2,324.55
Body Labor	18.2 hrs @	\$ 68.00 /hr	1,237.60
Paint Labor	11.5 hrs @	\$ 119.00 /hr	1,368.50
Mechanical Labor	1.0 hrs @	\$ 72.00 /hr	72.00
Miscellaneous			269.95
Other Charges			4.00
Subtotal			5,276.60
Grand Total			5,276.60
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			5,276.60

We appreciate the opportunity to serve you!

We offer a Limited Lifetime Warranty. Please review the following in regards to the Limited Lifetime Warranty;

The Limited Lifetime Warranty applies for the lifetime that you own the vehicle repaired.

The Limited Lifetime Warranty is not transferable.

The Limited Lifetime Warranty is for Metalwork & Paintwork for the repairs specifically itemized on your final bill. The warranty is presented with the final bill at the time of delivery after repairs are completed.

Parts, Stripes & Decals are limited to a 1 year warranty unless a Manufacturers Warranty is less or more. Mechanical Repairs are limited to 1 year as well.

There may be certain circumstances that a warranty of any kind would not apply. Your Estimator should disclose this to you if a warranty would not apply.