



**OFFICE OF AUDITOR OF STATE  
STATE OF IOWA**

Rob Sand  
Auditor of State

State Capitol Building  
Des Moines, Iowa 50319-0004  
Telephone (515) 281-5834

January 21, 2026

Kristi Onstot  
Executive Council  
L O C A L

Subject: Deer Damage to Vehicle #353 on January 1, 2026  
Department of Administrative Services  
Claim dated January 7, 2026  
AOS Claim ID: 4224

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$6,448.15, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA  
Deputy Auditor of State

CC: Kyle Wear, Fleet Services CFO, Department of Administrative Services  
Ryan Betts, Fleet Services Risk Program Manager, Department of Administrative Services  
Heather Hackbarth, Department of Management



Date: January 7, 2026

To: Tammy Hollingsworth, Auditor of State  
Victoria Newton, Treasurer of State  
Executive Council

**Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration**

Vehicle / Event	#353 / Deer
Event Date	January 1, 2026
Summary	Vehicle 353 - struck a deer (Claim # TBD)
Amount Requested	<b>\$6,448.15 TOTAL</b>
Supporting Documentation	29C20 Email Notification, Accident Report, & Repair Estimate

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Ryan Betts  
DAS Fleet Risk Program Manager  
ryan.betts1@iowa.gov  
515-281-8008

Risk, DAS <[das.risk@iowa.gov](mailto:das.risk@iowa.gov)>

## Fwd: District 13 Wildlife Vehicle Damage on 1-1-26

1 message

Risk, DAS <[das.risk@iowa.gov](mailto:das.risk@iowa.gov)>

Fri, Jan 2, 2026 at 12:41 PM

To: Tammy Hollingsworth <[tammy.hollingsworth@aos.iowa.gov](mailto:tammy.hollingsworth@aos.iowa.gov)>, TOS ExecutiveCouncil <[executivecouncil@tos.iowa.gov](mailto:executivecouncil@tos.iowa.gov)>

Please accept this email the initial 24 hour notification for an AON claim. Vehicle 353 struck a deer on 1/1/2026. I will forward all information as soon as it is received.

### DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

510 E 12<sup>th</sup> St, Des Moines, IA 50319

515-281-8008 office

[das.risk@iowa.gov](mailto:das.risk@iowa.gov)

<https://das.iowa.gov>



**All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.**

----- Forwarded message -----

From: **Morey Russell <[morey@dps.state.ia.us](mailto:morey@dps.state.ia.us)>**

Date: Fri, Jan 2, 2026 at 9:57 AM

Subject: District 13 Wildlife Vehicle Damage on 1-1-26

To: **vehicledamage <[vehicledamage@dps.state.ia.us](mailto:vehicledamage@dps.state.ia.us)>**, Risk, DAS <[das.risk@iowa.gov](mailto:das.risk@iowa.gov)>

Cc: **Andreasen Jeremy <[andreasen@dps.state.ia.us](mailto:andreasen@dps.state.ia.us)>**, Ellison Nichalus <[ellison@dps.state.ia.us](mailto:ellison@dps.state.ia.us)>, Dolf Ryan <[dolf@dps.state.ia.us](mailto:dolf@dps.state.ia.us)>, Morey Russell <[morey@dps.state.ia.us](mailto:morey@dps.state.ia.us)>

FYI:

Trooper Wall #353 was on routine patrol in Henry County at approximately 2300 hours when he was struck by a deer in the driver's side of his patrol car.

This caused damage to the left side front fender, driver and left side passenger door, and spotlight.

Vehicle damage report and other information will be forthcoming.

431

**Sergeant Russ Morey #431**  
Iowa State Patrol | District 13  
Iowa Department of Public Safety  
1300 S. Grand Avenue | Mount Pleasant, Iowa 52641  
Office: 319-385-8715  
Fax: 319-385-2743  
[morey@dps.state.ia.us](mailto:morey@dps.state.ia.us)  
<https://dps.iowa.gov/>  
<https://stophtiowa.org/>



**Department of  
Public Safety**

\*NOTICE\* This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

## **State Vehicle Damage Report**

Attach this completed form to an email along with the items identified below and send to: [vehicledamage@dps.state.ia.us](mailto:vehicledamage@dps.state.ia.us) ; [das.risk@iowa.gov](mailto:das.risk@iowa.gov)

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

**\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!**

### **STATE VEHICLE: (Mark if Act of Nature ) CASE #:**

Date: (Month/Day/Year)	01-01-25	Time: (Time plus a.m./p.m.)	11:11 pm
Vehicle Plate #:	353	Vehicle Mileage:	95,578
Vehicle Description: (Yr/Make/Model/ & Vin#)	2021 Dodge Charger VIN: 2C3CDXKG8MH644694		
Assigned To:	David Wall	Badge #	353
Driven By:	David Wall	Badge #	353
Driver's Lic #:	177AD6153	Damage:	TBD
Vehicle Towed: (Yes / No)	No	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$N/A
Seat Belt: (Yes / No)	Yes	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:	None		
Occupants: (Other than driver)	None		

### **VEHICLE #2:**

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			

Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:		Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

#### OTHER INFORMATION:

Witnesses:	Deer
Accident Location: (Street/Hwy)	1600 Block of Old Highway 34 near Mount Pleasant.
County:	Henry
Weather/Road Conditions:	Clear/dry
Trooper Wall #353 was on routine patrol when he slowed to let a deer pass in front of him. As he accelerated, a second deer ran into the driver's side of his patrol car. Damage was done to the spotlight, left front fender, driver's door, and driver's side passenger door. Vehicle was drivable.	
Property Damage other than Vehicles:	None
Cost:	\$TBD
Citations Issued To: (List Charge(s) and Statute Code(s))	None

Investigating Officer:	Trooper Gringer #440
------------------------	----------------------

#### VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			



## MEMORANDUM

**TO:** Sgt. Russ Morey #431

**FROM:** Trooper Wall #353

**DATE:** 1/1/2026

**SUBJECT: Deer 10-50**

On January 1, 2026, at about 2311 hours I was on routine patrol in the 1600 block of Old Highway 34 in Mount Pleasant when a deer entered the roadway. I slowed to let the deer go across the roadway. When that deer passed I began to accelerate again when another deer ran into the driver side door of my patrol car. It broke the spot light off and caused damage to the driver side front fender, front door and rear door. The vehicle was still drivable and taken to Post 13. The mileage on my patrol vehicle at the time of the accident was 95,578.

Submitted Respectfully,

Trooper David Wall #353  
Iowa State Patrol



## COPELAND AUTO BODY, INC.

estimates@copelandautobody.com  
506 E 2nd St, P.O. Box 109, Hedrick, IA 52563  
Phone: (641) 653-2140  
FAX: (641) 653-4301

Workfile ID: 20122d23  
Federal ID: 42-1488559

### Preliminary Estimate

RO Number: 21931

Written By: Miranda Frail

Insured: State Of Iowa

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact: 09 Left T-Bone (Left Side)

<b>Owner:</b>	<b>Inspection Location:</b>	<b>Insurance Company:</b>
State Of Iowa 301 E 7th St Des Moines, IA 50319 (319) 385-8715 Business (641) 891-0077 Cell	COPELAND AUTO BODY, INC. 506 E 2nd St P.O. Box 109 Hedrick, IA 52563 Repair Facility (641) 653-2140 Business	Creative Risk Solutions

### VEHICLE

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Gray Metallic

VIN: 2C3CDXKG8MH644694	Interior Color: Black	Mileage In: 95,640	Vehicle Out:
License: 353	Exterior Color: Gray Metallic	Mileage Out:	
State: IA	Production Date: 10/2021	Condition: Good	Job #:

#### TRANSMISSION

Automatic Transmission

4 Wheel Drive

#### POWER

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

Power Driver Seat

#### DECOR

Dual Mirrors

Tinted Glass

Overhead Console

#### CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Climate Control

Backup Camera

Parking Sensors

#### RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

#### SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

#### SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

#### WHEELS

Styled Steel Wheels

#### PAINT

Clear Coat Paint

#### OTHER

Traction Control

Stability Control

California Emissions

Get live updates at [www.carwise.com/e/5fNa3L](http://www.carwise.com/e/5fNa3L)

# Preliminary Estimate

**RO Number: 21931**

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Gray Metallic

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	<b>FRONT BUMPER &amp; GRILLE</b>						
2	R&I	R&I bumper cover				1.9	
3	#	Push Bumper				2.0	
4	<b>FRONT LAMPS</b>						
5	*	R&I LT Headlamp assy halogen				0.4	
6	<b>HOOD</b>						
7	*	Rpr Hood (ALU)				0.5	3.0
8		Add for Clear Coat					1.2
9	<b>FENDER</b>						
10	**	Repl A/M CAPA LT Fender w/o wide body	68660685AA	1	393.00	1.6	2.0
11		Overlap Major Adj. Panel					-0.4
12		Add for Clear Coat					0.3
13		Add for Edging					0.5
14		Add for Clear Coat					0.1
15		R&I LT Fender liner 3.6, 5.7 liter					Incl.
16	#	Repl Spot Light		1	350.00	2.0	M
		Note: Includes time to cut hole in fender to accept light and time to wire it.					
17	<b>WINDSHIELD</b>						
18	*	Rpr Windshield Dodge w/o rain sensor, w/o humidity sensor				0.5	
		Note: Rope Off/Mask Glass					
19	<b>PILLARS, ROCKER &amp; FLOOR</b>						
20		R&I LT Rocker molding w/o wide body w/o HELLCAT					Incl.
21	<b>FRONT DOOR</b>						
22	*	Repl LKQ LT door assy	68660701AA	1	725.00	2.1	3.1
23		Overlap Major Adj. Panel					-0.4
24		Add for Clear Coat					0.5
25		R&I LT Applique				0.2	
26		R&I LT Power mirror w/o heat, w/o memory, w/o blind spot pnt to match				0.5	
27		R&I LT Frame molding				0.3	
28	*	R&I LT Run channel				0.3	
29		R&I LT Door w'strip				0.4	
30		R&I LT Lower w'strip				0.2	
31		R&I LT Front w'strip				0.2	
32		R&I LT Door glass Dodge				0.6	
33		R&I LT Belt w'strip				0.3	
34		R&I LT Handle, outside granite				0.4	
35		R&I LT Mount plate				0.6	
36		R&I LT R&I trim panel				0.5	
37	<b>REAR DOOR</b>						

## Preliminary Estimate

**RO Number: 21931**

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Gray Metallic

## NOTES

#### Prior Damage Notes:

### Minor Hail on Roof

# Preliminary Estimate

**RO Number: 21931**

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Gray Metallic

## ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			2,078.15
Body Labor	23.0 hrs	@ \$ 78.00 /hr	1,794.00
Paint Labor	15.6 hrs	@ \$ 145.00 /hr	2,262.00
Mechanical Labor	3.0 hrs	@ \$ 100.00 /hr	300.00
Miscellaneous			14.00
Subtotal			6,448.15
<b>Grand Total</b>			<b>6,448.15</b>
Deductible			0.00
<b>CUSTOMER PAY</b>			<b>0.00</b>
<b>INSURANCE PAY</b>			<b>6,448.15</b>

ATTENTION: WHEELS NEED TO BE RE-TORQUED WITHIN 100 MILES. FAILURE TO DO SO MAY RESULT IN FURTHER DAMAGE!

Warranty Disclosure: Our Warranty will include our Workmanship, including necessary refinishing for as long as you, the customer, own the vehicle. Guarantee corrective repairs will be provided at no additional cost. Warranty and workmanship guarantee may NOT include items such as normal wear and tear, prior damage, new damage or negligence.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

**RO Number: 21931**

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Gray Metallic

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 01/02/2026, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

**SYMBOLS FOLLOWING PART PRICE:**

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category.

X=Miscellaneous Non-Taxed charge category.

**SYMBOLS FOLLOWING LABOR:**

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category.

M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

**OTHER SYMBOLS AND ABBREVIATIONS:**

Adj.=Adjacent. Align.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel.

CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.

D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part.

O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet.

UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway

Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

# Preliminary Estimate

**RO Number: 21931**

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Gray Metallic

## PARTS SUPPLIER LIST

Line	Supplier	Description	Price
10	Keystone, Inc 810 SE CORPORATE WOODS DR, SUITE 120 ANKENY IA 50021 (515) 727-7857	#CH1240282PP A/M CAPA LT Fender w/o wide body Quote: 3285149105 Expires: 02/19/26	\$ 393.00
22	Waterloo Auto Parts - Team PRP 1501 Grandview Ave. Waterloo IA 50703 (319) 234-5207	#02500821 LKQ LT door assy 6P2 4DR SED GRY Quote: CCC-424215750 Expires: 01/15/26	\$ 575.00
38	Waterloo Auto Parts - Team PRP 1501 Grandview Ave. Waterloo IA 50703 (319) 234-5207	#02304099 LKQ LT door assy 4D1 4DR SED BLK PW Quote: CCC-424224762 Expires: 01/15/26	\$ 250.00