MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MICHAEL L. NAIG SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

November 6, 2023

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved the Department of Public Safety's request for an emergency allocation in the amount of \$4,038.15, subject to audit of actual invoices. On April 19, 2023, State Patrol Vehicle #204 was damaged due to strong winds and storms. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Victoria Newton Executive Secretary

 cc: Jeannie Adams, Iowa State Patrol, Department of Public Safety DAS Risk Joel Lunde, Department of Management

> AOS Claim # 3569 TOS Job # ____



OFFICE OF AUDITOR OF STATE STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building Des Moines, Iowa 50319-0004 Telephone (515) 281-5834 Facsimile (515) 281-6518

September 25, 2023

Victoria Newton Executive Council L O C A L

Subject: Damage to Vehicle #204 due to Storms and Strong Winds on April 19, 2023 Department of Public Safety – Iowa State Patrol Claim dated June 20, 2023 AOS Claim ID: 3569

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damages. It is our conclusion that the above damage incurred by the Department of Public Safety – Iowa State Patrol is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend Executive Council approval in the amount of \$4,038.15, subject to an audit of <u>actual</u> invoices.

Sincerely,

Ernest H. Ruben, Jr., CPA Deputy Auditor of State

cc: Jeannie Adams, Iowa State Patrol, Department of Public Safety Mariah Flowers, Fleet Services Manager, Department of Administrative Services Joel Lunde, Department of Management

Governor Kim Reynolds Lt. Governor Adam Gregg

Adam Steen, Director



Date: June 20, 2023

- To: Tammy Hollingsworth, Auditor of State Victoria Newton, Treasurer of State Executive Council
- From: Mariah Flowers, Fleet Manager DAS Fleet Services Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#204/High winds
Event Date	April 19, 2023
Summary	Vehicle 204 sustained damage from high winds. (255945)
Amount Requested	\$4,038.15 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager DAS Fleet Services <u>Mariah.Flowers@iowa.gov</u> 515-414-6582



Risk, DAS <das.risk@iowa.gov>

Vehicle Damage - Trooper Ethan Achterhoff #204

1 message

Kurtz Vincent <kurtz@dps.state.ia.us>

To: "Risk, DAS" <das.risk@iowa.gov>, vehicledamage <vehicledamage@dps.state.ia.us> Cc: Williams Matthew <mwilliam@dps.state.ia.us>, Hesse Chase <hesse@dps.state.ia.us> Wed, Apr 19, 2023 at 11:52 AM

Good morning,

Trooper Ethan Achterhoff #204 sustained squad car damage early this morning from a thunderstorm with high winds. A large piece of metal roofing was blown onto his squad that was parked outside his residence. I have attached the vehicle damage report, memo, and photos. Trooper Achterhoff will be getting a repair estimate and I will pass this on with the updated damage report ASAP. Let me know if you need any further information.

Thank you,

Vince

Sergeant Vince Kurtz *495*

Iowa State Patrol District 6 HQ

503 West 44th Street

Spencer, IA 51301

712-262-1424 Office

712-732-1341 State Radio

712-262-3222 Fax

DPSCareers.com

------ Forwarded message ------From: Achterhoff Ethan <achterho@dps.state.ia.us> To: Hesse Chase <hesse@dps.state.ia.us>, Kurtz Vincent <kurtz@dps.state.ia.us>, Williams Matthew <mwilliam@dps.state.ia.us> Cc: Bcc: Date: Wed, 19 Apr 2023 13:32:28 +0000 Subject: Vehicle Damage Memo


Post 6 Supervision,

State of Iowa Mail - Vehicle Damage - Trooper Ethan Achterhoff #204

On 4/19/2023 at approximately 0300 hours my residence was impacted by severe weather including high winds. A large metal portion of an outbuilding roof was launched through the air approximately 50 feet and made contact with my patrol vehicle. My patrol vehicle sustained damage on several parts of the vehicle. Pictures of the aftermath are attached. The patrol vehicle has 75149 miles on it. Thank you.

Respectfully,

Trooper Achterhoff



IMG-5257.jpg 4205K



IMG-5261.jpg 3487K



IMG-5262.jpg 2718K



IMG-5263.jpg 2711K



IMG-5264.jpg 2709K



IMG-5265.jpg 2801K



#204 Picture 2.jpg 4205K



#204 Picture 4.jpg 2718K



#204 Picture 5.jpg 2711K

#204 Vehicle Damage Report 4-19-23.doc 97K

Vehicle Damage Memo.eml 31395K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: *DPS* – *Vehicle Damage; DAS* – *Risk*

- > One Repair Estimate from Approved State Bid Shop
- > DOT MARS Report (if reportable)
- > Memo from the Driver of the State Vehicle
- > 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

	\					
Date: (Month/Day/Year)	04-1	9-23	Time: (Time plus a.m./p.m.)	0300 a.m.		
Vehicle Plate #:	204		Vehicle Mileage:	75,149		
Vehicle Description: (Yr/Make/Model/ & Vin#)		Dodge Charger 2C3CDXKT9LH127514				
Assigned To: Eth		an Achterhoff	Badge #	204		
Driven By:	Driven By: Parked		Badge #			
Driver's Lic #:	419AF9457		Damage:	\$		
Vehicle Towed: No (Yes / No)		Towed By:	Not Towed			
Towed To: Not		Towed	Towing Cost:	\$		
Seat Belt: (Yes / No)			Type of Vehicle: (Marked/Semi /Unmarked)	Marked		
Injured/Injuries:		None				
Occupants: (Other than driver)		None				

STATE VEHICLE: (Mark if Act of Nature⊠) CASE #: 2023010315

VEHICLE #2:

DL #:	State:
Vehicle Lic. #	State:
Driver's Name:	
Driver's Address:	
Owner's Name:	
Owner's Address:	

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)		00 10 D	
Occupant(s) Wearing	ng Seat Belt: (Yes/N	lo) Yes	

OTHER INFORMATION:

Witnesses:	NONE			
Accident Location: (Street/Hwy)	2305 240th St. Milford, IA 51351			
County:	Dickinson County			
Weather/Road Conditions:	Wind / Thunderstorm			
Weather/Road Conditions: Wind / Thunderstorm Narrative: On 4/19/2023 at approximately 0300 hours my residence was impacted by severe weather including high winds. A large metal portion of an outbuilding roof was launched through the air approximately 50 feet and made contact with my patrol vehicle. My patrol vehicle sustained damage on several parts of the vehicle.				
Property Damage other than	NONE			
Vehicles:				
Cost:	\$			
Citations Issued To: (List Charge(s) and Statute Code(s))	NONE			

Investigating Officer:	Sgt. Vince Kurtz #495	
------------------------	-----------------------	--

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:	State:	
Vehicle Lic. #	State:	
Driver's Name:		

Driver's Address:				
Owner's Name:				
Owner's Address:				
Owner's Phone:				
Insurance Info: (Carrier/Policy #/Phone)				
Veh Description: (Yr/Make/Model & Vin#)				
Damage:	\$	Seat Belt: (Yes / No)	Yes	
Injured/Injuries:				
Occupants: (Other than driver)				
Occupant(s) Weari	ng Seat Belt:	(Yes/No) Yes		

QUALITY CLAIMS SOLUTIONS

105 N Krohn Place SIOUX FALLS, SD 57103 Phone: (877) 237-3727, FAX:(866) 371-2844 qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: STATE OF IOWA	Owner: STATE OF IOWA Job Number:							
	Written By: Wayne Malsam							
Insured:STATE OF IOWAType of Loss:CollisionPoint of Impact:12 Front	Policy #: UNKNOWN Date of Loss: 5/3/2023 12:00 PM	Claim #: APDSOI0255945-001 Days to Repair: 0						
Owner: STATE OF IOWA SPENCER, IA 51301	Inspection Location: KEN BORTH AUTO 301 11th St SW Spencer, IA 51301 Other (712) 262-7076 Evening	Repair Facility:						
	VEHICLE							
2020 DODG Charger Police AWD (Fleet) 4D SED	8-5.7L Gasoline Sequential MPI							

VIN: 2C3CDXKT9LH127514 License: State:	Production Date: Odometer: Condition:		terior Color: tterior Color:
TRANSMISSION	CONVENIENCE	AM Radio	Cloth Seats
Automatic Transmission	Air Conditioning	FM Radio	Bucket Seats
4 Wheel Drive	Intermittent Wipers	Stereo	Reclining/Lounge Seats
POWER	Tilt Wheel	Search/Seek	WHEELS
Power Steering	Cruise Control	Auxiliary Audio Conne	ction Styled Steel Wheels
Power Brakes	Rear Defogger	SAFETY	PAINT
Power Windows	Keyless Entry	Drivers Side Air Bag	Clear Coat Paint
Power Locks	Message Center	Passenger Air Bag	OTHER
Power Mirrors	Steering Wheel Touch Controls	Anti-Lock Brakes (4)	Traction Control
Power Driver Seat	Telescopic Wheel	4 Wheel Disc Brakes	Stability Control
DECOR	Climate Control	Front Side Impact Air	Bags California Emissions
Dual Mirrors	Backup Camera	Head/Curtain Air Bags	Power Trunk/Liftgate
Tinted Glass	Parking Sensors	Hands Free Device	
Overhead Console	RADIO	SEATS	

Owner: STATE OF IOWA

Job Number:

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

Line	1	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUMPE	R & G	RILLE			· · · ·		
2		R&I	R&I bumper cover				1.9	
3	HOOD							
4	*	Rpr	Hood (ALU)				<u>1.5</u>	3.0
5	FENDER							
6	*	Rpr	LT Fender w/o wide body				<u>1.0</u>	2.0
7			Overlap Major Adj. Panel					-0.4
8	WINDSHIELD							
9		Repl	RT Wiper blade	68194930AB	1	27.15	0.1	
10		Repl	RT Wiper arm	68082554AA	1	136.00	Incl.	
11		Repl	Linkage assy	68082553AA	1	105.00	0.4	
12	COWL							
13		Repl	Cowl grille	57010314AI	1	128.00	0.6	
14		Repl	Cowl top panel	68038078AB	1	128.00		
15		Repl	Cowl panel	68058045AB	1	159.00		
16	PILLARS, ROCK	(ER &	FLOOR					
17	*	Rpr	RT Aperture panel w/o wide body				2.0	<u>1.6</u>
18			Overlap Major Non-Adj. Panel					-0.2
19	*	Rpr	LT Aperture panel w/o wide body				5.0	<u>1.6</u>
20			Overlap Major Non-Adj. Panel					-0.2
21		R&I	RT Rocker molding				0.8	
22		R&I	LT Rocker molding				0.8	
23	FRONT DOOR							
24		Refn	RT Power mirror w/o heat, w/o					0.6
25			memory, w/o blind spot blue					
25		Defe	Overlap Minor Panel					-0.2
26		Reth	LT Power mirror w/o heat, w/o memory, w/o blind spot blue					0.6
27			Overlap Minor Panel					-0.2
28	REAR DOOR							0.2
29	*	Rpr	LT Outer panel w/o wide body				0.5	2.0
			(HSS)				<u></u>	210
30			Overlap Major Adj. Panel					-0.4
31		R&I	LT Belt w'strip				0.3	
32		R&I	LT Applique				0.2	
33		R&I	LT R&I trim panel				0.5	
34		R&I	LT Handle, outside black				0.4	
35	QUARTER PANE	EL.						
36		Blnd	RT Quarter panel					1.3
37	*	Rpr	LT Quarter panel				2.5	2.6
38			Overlap Major Adj. Panel					-0.4
39	TRUNK LID							
40	*	Rpr	Trunk lid w/police w/camera				<u>3.0</u>	2.3

Owner: STATE OF IOWA

Job Number:

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

			SUBTOTALS		696.15	26.2	17.7
#	R&I	antenna, siren				2.0	
#		Cover Car		1	5.00	0.2	
#		Corrosion Protection		1	5.00	0.1	
#		Hazardous Waste		1	3.00 X		
	R&I	R&I bumper cover				1.2	
REAR BUMPE	R						
	R&I	Backup lamp				0.3	
	R&I	LT Tail lamp assy					
	R&I	RT Tail lamp assy					
REAR LAMPS							
	R&I	Trunk lid trim				0.3	
		Clear Coat					2.5
		Overlap Major Adj. Panel					-0.4
	REAR BUMPEI # # #	REAR LAMPS R&I R&I R&I R&I R&I R&I R&I R&I R&I # R&I # I	Clear Coat R&IClear CoatR&ITrunk lid trimREAR LAMPSR&IR&IRT Tail lamp assy R&IR&IBackup lampREAR BUMPERR&I bumper cover#R&I bumper cover#Corrosion Protection#Cover Car	Clear CoatR&ITrunk lid trimREAR LAMPSR&IRT Tail lamp assyR&ILT Tail lamp assyR&IBackup lampREAR BUMPERR&IR&I bumper cover#Hazardous Waste#Corrosion Protection#R&I#R&I#R&I#R&I#Antenna, siren	Clear CoatR&ITrunk lid trimREAR LAMPSRT Tail lamp assyR&IRT Tail lamp assyR&ILT Tail lamp assyR&IBackup lampREAR BUMPERR&I bumper cover#Hazardous Waste#Corrosion Protection#Cover Car#R&I#R&I#R&I#Antenna, siren	Clear CoatR&ITrunk lid trimREAR LAMPSR&IRT Tail lamp assyR&ILT Tail lamp assyR&IBackup lampREAR BUMPERIR&IR&I bumper cover#Hazardous Waste#Corrosion Protection#Cover Car#R&IR&Iantenna, siren	Clear Coat 0.3 R&I Trunk lid trim 0.3 REAR LAMPS 0.3 R&I RT Tail lamp assy 0.3 R&I LT Tail lamp assy 0.3 R&I Backup lamp 0.3 REAR BUMPER 0.3 # K&I Numper cover # Hazardous Waste 1 3.00 X # Corrosion Protection 1 5.00 0.1 # Cover Car 1 5.00 0.2 # R&I antenna, siren 2.0

ESTIMATE TOTALS

Basis		Rate	Cost \$
		000 (100 (100 (100 (100 (100 (100 (100	693.15
26.2 hrs	@	\$ 60.00 /hr	1,572.00
17.7 hrs	@	\$ 100.00 /hr	1,770.00
			3.00
			4,038.15
			4,038.15
			0.00
	in in		0.00
			4,038.15
	26.2 hrs	26.2 hrs @	26.2 hrs @ \$ 60.00 /hr

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.