

MEMBERS OF COUNCIL

HON. KIM REYNOLDS
GOVERNOR

HON. PAUL D. PATE
SECRETARY OF STATE

HON. ROB SAND
AUDITOR OF STATE

HON. ROBY SMITH
TREASURER OF STATE

HON. MICHAEL L. NAIG
SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING
DES MOINES, IOWA 50319
PHONE: 515 281-5368

August 7, 2023

Accounting Department
Office of the Treasurer
Lucas Building
321 E 12th Street
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved the Department of Public Safety's request for an emergency allocation in the amount of \$6,552.75, subject to audit of actual invoices. On November 25, 2022, State Patrol Vehicle #443 was damaged by a deer. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Victoria Newton
Executive Secretary

cc: Jeannie Adams, Iowa State Patrol, Department of Public Safety
DAS Fleet Services
Joel Lunde, Department of Management

AOS Claim # 2401
TOS Job # _____



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

Rob Sand
Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834 Facsimile (515) 281-6518

July 31, 2023

Victoria Newton
Executive Council
L O C A L

Subject: Deer Damage to Vehicle #443 on November 25, 2022
Department of Public Safety – Iowa State Patrol
Claim dated June 2, 2023
AOS Claim ID: 2401

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Public Safety – Iowa State Patrol is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$6,552.75, subject to an audit of actual invoices.

Sincerely,

A handwritten signature in blue ink, appearing to read "Ernest H. Ruben, Jr.".

Ernest H. Ruben, Jr., CPA
Deputy Auditor of State

cc: Jeannie Adams, Iowa State Patrol, Department of Public Safety
Mariah Flowers, Fleet Services Manager, Department of Administrative Services
Joel Lunde, Department of Management



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: June 2, 2023

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#443/Deer
Event Date	November 25, 2022
Summary	Vehicle 443 struck a deer. (248250)
Amount Requested	\$6,552.75 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

A handwritten signature in blue ink that reads "mflowers".

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-414-6582



Risk, DAS <das.risk@iowa.gov>

FW: Notification to DAS - 443 - 10-50 car/deer

1 message

Adams Jeannie <jadams@dps.state.ia.us>

Mon, Nov 28, 2022 at 8:28 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, "ExecutiveCouncil [TOS]" <ExecutiveCouncil@tos.iowa.gov>, "Risk, DAS (das.risk@iowa.gov)" <das.risk@iowa.gov>

Good morning

While on duty on 11-25-2022 Trooper Knedler (#443) hit a deer. Attached are pictures and the Trooper's memo. More information to follow.

Thank you

Jeannie Adams

ISP Fleet & Supply, Fleet Asset Manager

Department of Public Safety

30 N.E. 48th Place

Des Moines, Iowa 50313

Direct #: 515-725-0643

Cell Phone: 515-204-3019

Shop: 515-281-3277

Fax: 515-242-6321

Email: jadams@dps.state.ia.us<mailto:jadams@dps.state.ia.us>

From: Adams Jeannie <jadams@dps.state.ia.us>**Sent:** Saturday, November 26, 2022 4:46 PM**To:** Risk, DAS (das.risk@iowa.gov) <das.risk@iowa.gov>**Cc:** Guill Bryan <guill@dps.state.ia.us>**Subject:** Notification to DAS - 443 - 10-50 car/deer

Please find notification for 443's vehicle damage. More information to follow.

Thank you

From: Major Wade <major@dps.state.ia.us<mailto:major@dps.state.ia.us>>**Sent:** Friday, November 25, 2022 8:12:27 PM**To:** vehicledamage <vehicledamage@dps.state.ia.us<mailto:vehicledamage@dps.state.ia.us>>**Cc:** post2sup <post2sup@dps.state.ia.us<mailto:post2sup@dps.state.ia.us>>**Subject:** FW: 10-50 car/deer

On 11/25/2022 at approximately 1840 hours Trp. Justin Knedler #443 struck a deer with issued patrol vehicle while traveling on Hwy G-76 at 25th. Avenue in Warren County. Patrol vehicle sustained damage to front and front-right fender.

Mileage 77691

VIN 2C3CDXKT0LH124226

49

From: Knedler Justin <knedler@dps.state.ia.us<mailto:knedler@dps.state.ia.us>>

Sent: Friday, November 25, 2022 7:10 PM

To: Major Wade <major@dps.state.ia.us<mailto:major@dps.state.ia.us>>

Cc: Pollard Brad <pollard@dps.state.ia.us<mailto:pollard@dps.state.ia.us>>; Mitchell Britney <bmitchel@dps.state.ia.us<mailto:bmitchel@dps.state.ia.us>>

Subject: 10-50 car/deer

6 attachments



P1000412.JPG
4858K



P1000413.JPG
4786K



P1000414.JPG
4968K



P1000415.JPG
4857K



P1000418.JPG
4998K

 **443.docx**
18K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #: 2022029059

Date: (Month/Day/Year)	11/25/2022	Time: (Time plus a.m./p.m.)	6:40 P.M.
Vehicle Plate #:	443	Vehicle Mileage:	77691
Vehicle Description: (Yr/Make/Model/ & Vin#)	2020/Dodge Charger/VIN# 2C3CDXKT0LH124226		
Assigned To:	Trp. Knedler	Badge #	443
Driven By:	Trp. Knedler	Badge #	443
Driver's Lic #:	427kk0650	Damage:	\$
Vehicle Towed: (Yes / No)	No	Towed By:	n/a
Towed To:	n/a	Towing Cost:	\$n/a
Seat Belt: (Yes / No)	Yes	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:	None		
Occupants: (Other than driver)	n/a		

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

OTHER INFORMATION:

Witnesses:	None
Accident Location: (Street/Hwy)	G-76 @ 25 th Ave.
County:	Warren County
Weather/Road Conditions:	Dry/Dry
Trp. Knedler was traveling East on G-76 near 25 th Avenue when a deer entered roadway. Trp. Knedler's patrol vehicle struck deer in roadway. Trp. Knedler's vehicle sustained damage to front and to front right fender.	
Property Damage other than Vehicles:	None
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	N/A

Investigating Officer:	Trp. Cody Frank #484
------------------------	----------------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

INVESTIGATING OFFICER'S REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement Case Number: 2022029059

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Date of Accident 11/25/2022	Time of Accident 18:40 Hrs.	County WARREN - 91	Accident occurred within corporate limits of (city)			
UNIT 1	Driver's Name - Last KNEDLER		First JUSTIN		Middle CRAIG	
	Address 1619 TRURO PAVEMENT		City OSCEOLA		State IA	
	Date of Birth		Driver's License Number 427KK0650		CDL	
	Citation Charge 1		Citation Charge 2		Citation Charge 3	
	Citation Charge 4		Citation Charge 5		Citation Charge 6	
	Male <input checked="" type="radio"/>	Female <input type="radio"/>	State IA	Class C	Endorsements L	
	Restrictions B		Yes <input type="radio"/> No <input checked="" type="radio"/>		Citation Charge 7	
	Alcohol Test Given: 1		Test Results: 1	Drug Test Given: 1	Test Result:	Re-exam: Yes <input type="radio"/> No <input checked="" type="radio"/>
	Reason for Re-Exam Request:					
	Owner's Name - Last STATE OF IOWA		First		Middle	
Address 109 SE 13TH ST		City DES MOINES		State IA	Zip 50319	
License Plate No. 443	State IA	Year 2023	VIN: 2C3CDXKT0LH124226	Color SIL	Year 2020	
Make DODG	Model CHA	Style SD				
Trailer Plate No.	State	Year	VIN:	Tow 1	Tow #	
Towed To		Approx. Cost to Repair or Replace \$5,000.00				
Insurance Company Name STATE OF IOWA			Insurance Co. Phone Number (515) 725-2243		Insurance Policy Number	
Initial Travel Direction	Veh. Act.	Veh. Config. 01	Cargo Body Type 01	Veh. Defect	Point of Initial Impact	
Most Damaged Area	Extent of Damage	Total Occ. in Veh. 1				
Special Veh. Func.	Emergency Status	Bus Use	Driver Condition	Vision Obscured	Contributing Circumstances Driver (up to two) 88	
Driver Distractions 02	Speed Limit					
Traffic Controls	Horizontal Alignment	Vertical Alignment	SEQUENCE OF EVENTS	First Event	Second Event	
Third Event	Fourth Event	Most Harmful Event				
COMMERCIAL	Carrier Name/Lessee					
	Street Address			City		
	State		Zip Code			
	Number of Axles	Gross Vehicle Weight Rating		US DOT Number	MC Number	
	Underride/Override					
	Haz Mat Involvement	Haz Mat Placard	Placard Number	Haz. Mat Released	Haz Mat Class	
	Haz Mat Name					
Trailer Plate:	State	Year	VIN			
Trailer Plate:	State	Year	VIN			
Converter Dolly	Dolly Plate:	State	Plate Year	VIN		
PERSONS INVOLVED	DRIVER OF UNIT 1		Phone Number:		Transported to:	
	Transported by:					
	Name	Phone Number	DOB:			
	Address		Transported to:		Transported by:	
	Name	Phone Number	DOB:			
	Address		Transported to:		Transported by:	
	Name	Phone Number	DOB:			
	Address		Transported to:		Transported by:	
	Name	Phone Number	DOB:			
	Address		Transported to:		Transported by:	

INVESTIGATING OFFICER'S REPORT OF MOTOR VEHICLE ACCIDENT

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Law Enforcement Case Number:
2022029059

L O C A T I O N	Date of Accident 11/25/2022	Time of Accident 18:40 Hrs.	County WARREN - 91	Accident occurred within corporate limits of (city)	Legal Intervention? <input type="checkbox"/>	Private Property? <input type="checkbox"/>	
	Literal Description G76 HIGHWAY AND 25TH AVE				County: 91	Route:	
	If accident occurred outside of city limits show general vicinity N NE E SE S SW W NW <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> of nearest city				X Coordinate: 436220.75		
	On Road, Street or Highway:			At Intersection with:	Y Coordinate: 4558651.5		
	Note: Unless accident occurred at an intersection which is completely described above, use the space below to give the exact location from a milepost or definable intersection, bridge, or railroad crossing, using two distances and directions if necessary. of				If Divided Highway, Provide Route (Cardinal) Travel Direction		
N NE E SE S SW W NW <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> and				N NE E SE S SW W NW <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>			
Milepost Number		Definable intersection, Or, bridge, or railroad crossing		NB <input type="radio"/>	SB <input type="radio"/>	EB <input type="radio"/>	WB <input type="radio"/>

ACCIDENT ENVIRONMENT				ROADWAY CHARACTERISTICS				Sex	Struck by Unit No.	Injury Status	Non-Motorist Type	Location (prior to impact)	Action (prior to crash)	Condition	Safety Equipment	Contributing Circumstances	Source of Transport	Died at scene/enroute
Location of First Harmful Event	Weather Conditions (up to two)			Major Contributing Circumstances Environment														
Manner of Crash/Collision	Surface Conditions			Roadway														
Light Conditions				Type of Roadway Junction/Feature														
First Harmful Event (Crash)	WORKZONE RELATED?	Yes <input type="radio"/>	No <input type="radio"/>	Activity	Location	Type	Workers Present											

31	WORKZONE RELATED?	Yes <input type="radio"/>	No <input type="radio"/>	Activity	Location	Type	Workers Present										
----	-------------------	---------------------------	--------------------------	----------	----------	------	-----------------	--	--	--	--	--	--	--	--	--	--

N O N M O T O R I S T S	Name 001	Phone Number	DOB:															
	Address:	Alcohol Test Given	Test Results:	Drug Test Given	Result	Charged	Yes <input type="radio"/>	No <input type="radio"/>										
	Transported to:	Transported by:																
	Name	Phone Number	DOB:															
	Address:	Alcohol Test Given	Test Results:	Drug Test Given	Result	Charged	Yes <input type="radio"/>	No <input type="radio"/>										
Transported to:	Transported by:																	

N P O R N O V P E R I T C Y U L D A M R G	If Property other than vehicles damaged explain	Object Damaged											Estimate of Damage			
	Owner's Last Name	First Name	Middle Name	Phone Number												
	Address	City	State	Zip Code	Was owner or tenant notified? 1 = Yes 2 = No 9 = Unknown											
	If Property other than vehicles damaged explain	Object Damaged											Estimate of Damage			
Owner's Last Name	First Name	Middle Name	Phone Number													
Address	City	State	Zip Code	Was owner or tenant notified? 1 = Yes 2 = No 9 = Unknown												

W I T N E S S	Last Name	First Name	Address	City	State	Zip Code	Phone Number
	Last Name	First Name	Address	City	State	Zip Code	Phone Number
	Last Name	First Name	Address	City	State	Zip Code	Phone Number
	Last Name	First Name	Address	City	State	Zip Code	Phone Number
	Last Name	First Name	Address	City	State	Zip Code	Phone Number

Is This a Secondary Crash? Y <input type="radio"/> N <input checked="" type="radio"/>	Type of Primary Incident	Roadway Clearance Date 11/25/2022	Incident Clearance Date 11/25/2022
Signature of Officer TROOPER C FRANK	Badge Number 484	Time Officer Notified of Accident 18:41 Hrs.	Roadway Clearance Time 18:41 Hrs.
Name of Agency IOWA STATE PATROL - DIST 02	Date of Report 11/25/2022	Time Officer Arrived At Scene Hrs.	Total Roadway Clearance Time 000:01
Report Reviewed By W MAJOR	Date of Review 11/26/2022	Investigation made at scene? Y <input type="radio"/> N <input type="radio"/>	T.I. No.
		Other Technical Investigating Agency	

INVESTIGATING OFFICER'S REPORT
OF MOTOR VEHICLE ACCIDENT

Form 4433003 (11-13)

Law Enforcement Case Number:

2022029059

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

D
I
A
G
R
A
M



N
A
R
R
A
T
I
V
E

Unit #1 was traveling eastbound on G-76 when a deer came out of the north ditch and struck Unit #1. The driver of Unit #1 was working in their official capacity as a peace officer of the state.



MEMORANDUM

TO: SGT. MAJOR
FROM: TROOPER KNEDLER
DATE: 11/25/22
SUBJECT: VEHICLE DAMAGE

On 11/25/22 I was on routine patrol traveling eastbound on Hwy G76/25th Ave when I struck a deer causing frontend damage and passenger side damage.

Mileage 77691
VIN 2C3CDXKT0LH124226
DL# 427kk0650
Time 1840 hours

Karl Chevrolet Collision Center Ankeny

Your Dealer for Life
1101 Southeast Oralabor Road, Ankeny, IA 50021
Phone: (515) 299-4337
FAX: (515) 964-2293

Workfile ID: 69f1b01c
PartsShare: 755Wgv
Federal ID: 42-1092272

Final Bill

RO Number: 904548

Customer:	Insurance:	Adjuster:	Estimator:
STATE OF IOWA UNIT 443	STATE OF IOWA	Phone:	Michael Wright
		Claim: 443	Create Date: 11/28/2022
(515) 975-2846		Loss Date:	
		Deductible:	

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI GREY

VIN: 2C3CDXKT0LH124226	Interior Color: BLACK	Mileage In: 77,909	Vehicle Out: 1/9/2023
License: 443	Exterior Color: GREY	Mileage Out:	
State: IA	Production Date: 12/2019	Condition:	Job #: 3780

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		FRONT BUMPER & GRILLE						
2	E01	Remove/Replace	O/H front bumper				3.4	Body	
3	E01	Remove/Replace	Bumper cover	1	819.00	OEM	0.0	Body	3.4
4	E01		Add for Clear Coat						1.4
5	E01		Add for Two Tone						
6	E01	Remove/Replace	Closure panel	1	197.00	OEM	0.0	Body	
7	E01	Remove/Replace	Energy absorber	1	112.00	OEM	0.0	Body	
8	E01	Remove/Replace	Impact bar (UHS)	1	382.00	OEM	0.7	Body	
9	E01	Remove/Replace	Upper grille black crossbars	1	405.00	OEM	0.0	Body	
10	S01	Remove/Replace	Lower grille w/o adaptive cruise	1	98.00	A/M	0.0	Body	
11	E01		FRONT LAMPS						
12	E01	Remove/Replace	RT Headlamp assy halogen	1	827.00	OEM	0.4	Body	
13	E01	Remove/Replace	Aim headlamps				0.5	Body	
14	E01		RADIATOR SUPPORT						
15	E01	Remove/Replace	Radiator support	1	345.00	OEM	1.0	Body	1.0
16	E01	Remove/Replace	Evacuate & recharge				1.4	Body	
17	E01	Remove/Replace	Refrigerant recovery				0.4	Body	
18	E01	Remove/Replace	RT Air guide 1-piece guide all	1	27.00	OEM	0.1	Body	
19	E01		HOOD						
20	E01	Repair	Hood (ALU)				5.0	Body	3.0
21	E01		Add for Clear Coat						1.2
22	E01		FENDER						
23	E01	Remove/Replace	RT Fender w/o wide body	1	370.00	OEM	1.6	Body	2.0

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Final Bill

RO Number: 904548

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI GREY

24	E01		Overlap Major Adj. Panel						(0.4)
25	E01		Add for Clear Coat						0.3
26	E01		Add for Edging						0.5
27	E01		Add for Clear Coat						0.1
28	S01	Remove/Replace	LT Fender liner 3.6, 5.7 liter	1	112.00	A/M	0.3	Body	
29	S01	Remove/Replace	RT Fender liner 3.6, 5.7 liter	1	112.00	A/M	0.0	Body	
30	S01	Repair	RT Bumper bracket				1.0	Body	
31	E01		FRONT DOOR						
32	E01	Repair	RT Outer panel (HSS)				3.0	Body	2.1
33	E01		Overlap Major Adj. Panel						(0.4)
34	E01		Add for Clear Coat						0.3
35	E01	Remove/Install	RT Belt w'strip				0.3	Body	
36	E01	Remove/Install	RT Power mirror w/o heat, w/o memory, w/o blind spot blue				0.5	Body	
37	E01	Remove/Install	RT Handle, outside black				0.4	Body	
38	E01	Remove/Install	RT Mount plate				0.6	Body	
39	E01	Remove/Install	RT R&I trim panel				0.5	Body	
40	E01		MISCELLANEOUS OPERATIONS						
41	E01	Sublet	Hazardous waste removal	1	6.20	Other			
42	E01	Remove/Replace	Flex additive	1	5.00	A/M			
43	E01	Remove/Replace	Cover Car	1	10.00	A/M			
44	E01	Remove/Replace	Corrosion protection	1	5.00	A/M	0.1	Body	
45	S01		Post Repair Scan- Per OEM Guideline				0.5	Body	
46	S01	Remove/Replace	SETINA BAR	1	777.57	Other	3.0	Body	
47	S01		remove decals				2.0	Body	

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts	(975.52)				3,628.05
Sublet/Miscellaneous					6.20
Labor, Body			55.00	26.7	1,468.50
Labor, Refinish			100.00	14.5	1,450.00
Subtotal					6,552.75
Sales Tax					0.00
Grand Total					6,552.75
Net Total					6,552.75

Estimate Version	Total \$
Original	6,065.68
Supplement S01	487.07

Insurance Total \$: 6,552.75
 Received from Insurance \$: 0.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Final Bill

RO Number: 904548

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI GREY

Balance due from Insurance \$:	6,552.75
Customer Total \$:	0.00
Received from Customer \$:	0.00
Balance due from Customer \$:	0.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

1/25/2023 9:51:19 AM