MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE NAIG SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

August 7, 2023

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on this date, approved payment of the following cost item:

This represents full and final payment.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Victoria Newton Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services DAS Fleet Services, Risk Joel Lunde, Department of Management

> AOS Claim # 3437 TOS Job # 2372



OFFICE OF AUDITOR OF STATE STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building Des Moines, Iowa 50319-0004 Telephone (515) 281-5834 Facsimile (515) 281-6518

August 2, 2023

Victoria Newton Executive Council L O C A L

Subject: Vehicle #1948 Vandalized on January 4, 2023 Department of Administrative Services Claim dated January 19, 2023 AOS Claim ID: 3437

In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to the loss and have found the items to be in order as shown below:

Documented request			<u>\$</u>	2,558.00
Executive Council Allocation			\$	2,558.00
Less: Previous payments This payment Total	\$	0.00 2,558.00	\$	2,558.00
Remaining Executive Council alloc	ation		<u>\$</u>	0.00

We recommend reimbursement be made in the amount of \$2,558.00. This represents <u>full</u> and <u>final</u> payment of the loss.

Sincerely,

Ernest H. Ruben, Jr., CPA Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services Mariah Flowers, Fleet Services Manager, Department of Administrative Services

Governor Kim Reynolds Lt. Governor Adam Gregg

Adam Steen, Director



Date: June 2, 2023

- To: Tammy Hollingsworth, Auditor of State Victoria Newton, Treasurer of State Executive Council
- From: Mariah Flowers, Fleet Manager DAS Fleet Services Department of Administrative Services

Re: REIMBURSEMENT REQUEST - 29C20 Claim

Claim #	3437
Vehicle / Event	#1948/Vandalized
Event Date	January 4, 2023
Summary	Vehicle 1948 was vandalized while parked at the official domicile location. (250070)
Amount Requested	\$2,558.00 - FINAL INVOICE

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: 0665-005-5790-0657.

If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager DAS Fleet Services <u>Mariah.Flowers@iowa.gov</u> 515-414-6582 6/2/23, 11:09 AM

Warrants

M	enu	I

Fiscal Year	Warrant Number	Line Number	Line Amount	Issued	Redeemed	Vendor Customer
✓ 2023	72479275	1	\$2,558.00	05/08/2023	05/15/2023	00003203981
First Prev Next I	Last					
Search 🗸 🗸	8					
Warrant Informa	ation					
Fiscal Yea	r: 2023		Amount : \$	2,558.00		
Warrant Numbe	r: 72479275	Vendo	r Customer : 0			
Line Numbe	r: 1	La	st Updated : 5	15/23		
Issue Information	n					
	Issued : 05/08/2	2023	Voi	d : 🗌		
	ment ID : RISK00	0523128602	Duplicat	e : 🗌		
Document Line	Number: 1		Sto	p:		
Line	Amount : \$2,558	.00				
Co	mments :					
Redeemed Info	rmation	1				
	deemed : 05/15/20	023	Batch Num	ber: 0000		
	ed Bank : 0000		Sequence Num	ber: 05929		
Redeeme	ed Fund: 0665					
Redeemed Depa	artment: 005					
Fund Accounting	9.					ne and a second s
Fund :	0665		Object :	2715	Dept Object	et:
Sub Fund :			Sub Object :		Dept Revenu	e :
Department :	005		Object Class :			
Unit :	5790	Re	venue Source :			
Sub Unit :		Sub Re	venue Source :			
Appropriation :	0000	Revenue	Source Class :			
			BSA :			
			Sub BSA :			
✓Detail Accountin	19					
Location :		Repo	orting :		Major Prog	gram :
Sub Location :		Sub Repo	orting :		Prog	gram :
	2020		Task :		Р	hase :
Activity :	2920					
	2920	Sub	Task :		Program Pe	eriod :
Activity :	2920		Task : Drder :		Program Pe	eriod :

<u>Top</u>

M & M COLLISION

2131 EDGINGTON AVE, ELDORA, IA 50627 Phone: (641) 858-3886 5659e64e 77VqpG

Preliminary Estimate

	hool, Training			Job Number: 000
		Written By: Jeremy	/ McStockard	
nsured: S	School, Training	Policy #:	Claim #:	
ype of Loss: Date of Loss: oint of Impact:		Date of Loss:	Days to Repa	ir: O
)wner:		Inspection Location:	Insurance C	Company:
chool, Training		M & M COLLISION		
		2131 EDGINGTON AVE		
		ELDORA, IA 50627		
		Repair Facility		
		(641) 858-3886 Business		
		VEHIC	LE	
018 DODG Grand (Caravan SE 4D VAN	6-3.6L Flex Fuel Sequential MPI		
	N: 2C4RDGBGXJR255227 Interior Color: Mileage In:			
IN: 2C4RDGE	3GXJR255227	Interior Color:	Mileage In:	Vehicle Out:
IN: 2C4RDGE icense:	3GXJR255227	Interior Color: Exterior Color:	Mileage In: Mileage Out:	Vehicle Out:
	3GXJR255227		2.	Vehicle Out: Job #: 0006
icense:		Exterior Color:	Mileage Out:	Job #: 0006
icense: tate: IA	ION	Exterior Color: Production Date: CONVENIENCE	Mileage Out: Condition:	Job #: 0006 Cloth Seats
icense: tate: IA TRANSMISS	ION	Exterior Color: Production Date:	Mileage Out: Condition: FM Radio Stereo	Job #: 0006 Cloth Seats Bucket Seats
icense: tate: IA TRANSMISS Automatic Tra	ION Insmission	Exterior Color: Production Date: CONVENIENCE Air Conditioning	Mileage Out: Condition: FM Radio	Job #: 0006 Cloth Seats Bucket Seats Reclining/Lounge Seats
icense: tate: IA TRANSMISS Automatic Tra POWER	ION Insmission	Exterior Color: Production Date: CONVENIENCE Air Conditioning Intermittent Wipers	Mileage Out: Condition: FM Radio Stereo Search/Seek CD Player	Job #: 0006 Cloth Seats Bucket Seats Reclining/Lounge Seats 3rd Row Seat
icense: tate: IA TRANSMISS Automatic Tra POWER Power Steerin	ION Insmission g	Exterior Color: Production Date: CONVENIENCE Air Conditioning Intermittent Wipers Tilt Wheel	Mileage Out: Condition: FM Radio Stereo Search/Seek	Job #: 0006 Cloth Seats Bucket Seats Reclining/Lounge Seats 3rd Row Seat Retractable Seats
icense: tate: IA TRANSMISS Automatic Tra POWER Power Steerin Power Brakes	ION Insmission g	Exterior Color: Production Date: CONVENIENCE Air Conditioning Intermittent Wipers Tilt Wheel Cruise Control	Mileage Out: Condition: FM Radio Stereo Search/Seek CD Player Auxiliary Audio Connection SAFETY	Job #: 0006 Cloth Seats Bucket Seats Reclining/Lounge Seats 3rd Row Seat Retractable Seats WHEELS
icense: tate: IA TRANSMISS Automatic Tra POWER Power Steerin Power Brakes Power Window	ION Insmission g ws	Exterior Color: Production Date: CONVENIENCE Air Conditioning Intermittent Wipers Tilt Wheel Cruise Control Rear Defogger	Mileage Out: Condition: FM Radio Stereo Search/Seek CD Player Auxiliary Audio Connection SAFETY Drivers Side Air Bag	Job #: 0006 Cloth Seats Bucket Seats Reclining/Lounge Seats 3rd Row Seat Retractable Seats
icense: tate: IA TRANSMISS Automatic Tra POWER Power Steerin Power Brakes Power Window Power Locks	ION Insmission g vs	Exterior Color: Production Date: CONVENIENCE Air Conditioning Intermittent Wipers Tilt Wheel Cruise Control Rear Defogger Keyless Entry	Mileage Out: Condition: FM Radio Stereo Search/Seek CD Player Auxiliary Audio Connection SAFETY Drivers Side Air Bag Passenger Air Bag	Job #: 0006 Cloth Seats Bucket Seats Reclining/Lounge Seats 3rd Row Seat Retractable Seats WHEELS Styled Steel Wheels
icense: tate: IA TRANSMISS Automatic Tra POWER Power Steerin Power Brakes Power Windov Power Locks Power Mirrors	ION Insmission g vs	Exterior Color: Production Date: CONVENIENCE Air Conditioning Intermittent Wipers Tilt Wheel Cruise Control Rear Defogger Keyless Entry Steering Wheel Touch Controls	Mileage Out: Condition: FM Radio Stereo Search/Seek CD Player Auxiliary Audio Connection SAFETY Drivers Side Air Bag	Job #: 0006 Cloth Seats Bucket Seats Reclining/Lounge Seats 3rd Row Seat Retractable Seats WHEELS Styled Steel Wheels PAINT
icense: tate: IA TRANSMISS Automatic Tra POWER Power Steerin Power Brakes Power Windov Power Locks Power Mirrors Heated Mirrors	ION Insmission g vs	Exterior Color: Production Date: CONVENIENCE Air Conditioning Intermittent Wipers Tilt Wheel Cruise Control Rear Defogger Keyless Entry Steering Wheel Touch Controls Rear Window Wiper	Mileage Out: Condition: FM Radio Stereo Search/Seek CD Player Auxiliary Audio Connection SAFETY Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4)	Job #: 0006 Cloth Seats Bucket Seats Bucket Seats Reclining/Lounge Seats 3rd Row Seat Retractable Seats WHEELS Styled Steel Wheels PAINT Clear Coat Paint OTHER
icense: tate: IA TRANSMISS Automatic Tra POWER Power Steerin Power Brakes Power Window Power Locks Power Mirrors Heated Mirrors DECOR	ION Insmission g ws	Exterior Color: Production Date: CONVENIENCE Air Conditioning Intermittent Wipers Tilt Wheel Cruise Control Rear Defogger Keyless Entry Steering Wheel Touch Controls Rear Window Wiper Telescopic Wheel	Mileage Out: Condition: FM Radio Stereo Search/Seek CD Player Auxiliary Audio Connection SAFETY Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4) 4 Wheel Disc Brakes	Job #: 0006 Cloth Seats Bucket Seats Reclining/Lounge Seats 3rd Row Seat Retractable Seats WHEELS Styled Steel Wheels PAINT Clear Coat Paint
icense: tate: IA TRANSMISS Automatic Tra POWER Power Steerin Power Brakes Power Window Power Locks Power Mirrors Heated Mirrors DECOR Dual Mirrors	ION Insmission g ws	Exterior Color: Production Date: CONVENIENCE Air Conditioning Intermittent Wipers Tilt Wheel Cruise Control Rear Defogger Keyless Entry Steering Wheel Touch Controls Rear Window Wiper Telescopic Wheel Climate Control	Mileage Out: Condition: FM Radio Stereo Search/Seek CD Player Auxiliary Audio Connection SAFETY Drivers Side Air Bag Passenger Air Bag Passenger Air Bag Anti-Lock Brakes (4) 4 Wheel Disc Brakes Traction Control Stability Control	Job #: 0006 Cloth Seats Bucket Seats Bucket Seats Reclining/Lounge Seats 3rd Row Seat Retractable Seats WHEELS Styled Steel Wheels PAINT Clear Coat Paint OTHER Rear Spoiler
icense: tate: IA TRANSMISS Automatic Tra POWER Power Steerin Power Brakes Power Window Power Window Power Locks Power Mirrors Heated Mirrors DECOR Dual Mirrors Body Side Mol	ION Insmission g ws s dings	Exterior Color: Production Date: CONVENIENCE Air Conditioning Intermittent Wipers Tilt Wheel Cruise Control Rear Defogger Keyless Entry Steering Wheel Touch Controls Rear Window Wiper Telescopic Wheel Climate Control Dual Air Condition	Mileage Out: Condition: FM Radio Stereo Search/Seek CD Player Auxiliary Audio Connection SAFETY Drivers Side Air Bag Passenger Air Bag Passenger Air Bag Anti-Lock Brakes (4) 4 Wheel Disc Brakes Traction Control	Job #: 0006 Cloth Seats Bucket Seats Reclining/Lounge Seats 3rd Row Seat Retractable Seats WHEELS Styled Steel Wheels PAINT Clear Coat Paint OTHER Rear Spoiler California Emissions

Customer: School, Training

Job Number: 0006

2018 DODG Grand Caravan SE 4D VAN 6-3.6L Flex Fuel Sequential MPI

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BU	MPER						
2			O/H front bumper				2.0	
3	* <>	Repl	Bumper cover	68088966AB	1	322.00	Incl.	3.0
4			Add for Clear Coat					1.2
5			Add for moldings				0.3	
6	FENDER							
7	*	Rpr	RT Fender				2.0	2.2
8			Overlap Major Non-Adj. Panel					-0.2
9			Add for Clear Coat					0.4
10	FRONT DO	OR						
11	*	Rpr	RT Door shell				2.5	2.3
12			Overlap Major Adj. Panel					-0.4
13			Add for Clear Coat					0.4
14		R&I	RT Belt w'strip black				0.4	
15		R&I	RT R&I mirror				0.3	
16		R&I	RT Handle, outside w/o easy entry matt black				0.3	
17	SIDE LOAD	ING DOO	R					
18	*	Rpr	RT Door shell				2.5	2.4
19			Overlap Major Adj. Panel					-0.4
20			Add for Clear Coat					0.4
21		R&I	RT Belt w'strip black				0.3	
22		R&I	RT Lower w'strip				0.1	
23		R&I	RT Handle, outside matt black				0.4	
24		R&I	RT R&I trim panel				0.5	
25		Repl	LT Applique front all	5020667AA	1	110.00	0.2	0.3
26			Add for Clear Coat					0.1
27	#	Subl	Hazardous waste removal		1	3.00		
28	#	Repl	Cover Car		1	5.00 T		
29	#	Repl	Flex additive		1	5.00 T		
30	#	(and the second	Final bill		1			
		Constanting of the second	CHECKETONE CONTRACTORIZIONE IN CONTRACTORIZIONAL CARRIER CONTRACTORIZIONE	SUBTOTALS		445.00	11.8	11.7

Customer: School, Training

Job Number: 0006

2018 DODG Grand Caravan SE 4D VAN 6-3.6L Flex Fuel Sequential MPI

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				435.00
Body Labor	11.8 hrs	@	\$ 70.00 /hr	826.00
Paint Labor	11.7 hrs	@	\$ 70.00 /hr	819.00
Paint Supplies	11.7 hrs	@	\$ 40.00 /hr	468.00
Miscellaneous				10.00
Subtotal				2,558.00
Grand Total				2,558.00
Deductible				0.00
CUSTOMER PAY				0.00
INSURANCE PAY				2,558.00



OFFICE OF AUDITOR OF STATE

STATE OF IOWA

State Capitol Building Des Moines, Iowa 50319-0004 Telephone (515) 281-5834 Facsimile (515) 281-6518 Rob Sand Auditor of State

January 31, 2023

Victoria Newton Executive Council L O C A L

Subject: Vehicle #1948 Vandalized on January 4, 2023 Department of Administrative Services Claim dated January 19, 2023 AOS Claim ID: 3437

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$2,558.00, subject to an audit of <u>actual</u> invoices.

Sincerely,

Ernest H. Ruben, Jr., CPA Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services Mariah Flowers, Fleet Services Manager, Department of Administrative Services Joel Lunde, Department of Management