MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MICHAEL L. NAIG SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

August 7, 2023

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved the Department of Public Safety's request for an emergency allocation in the amount of \$16,058.80, subject to audit of actual invoices. On May 7, 2023, State Patrol Vehicle #981 was damaged by hail. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Victoria Newton Executive Secretary

cc: Jeannie Adams, Iowa State Patrol, Department of Public Safety

DAS Fleet Services

Joel Lunde, Department of Management

TOR OF STATE OF TO

OFFICE OF AUDITOR OF STATE

STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004

Telephone (515) 281-5834 Facsimile (515) 281-6518

August 2, 2023

Victoria Newton Executive Council L O C A L

Subject: Hail Damage to Vehicle #981 on May 7, 2023

Department of Public Safety - Iowa State Patrol

Claim dated June 20, 2023


AOS Claim ID: 3515

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Public Safety – Iowa State Patrol is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$16,058.80, subject to an audit of <u>actual</u> invoices.

Sincerely,

Ernest H. Ruben, Jr., CPA Deputy Auditor of State

cc: Jeannie Adams, Iowa State Patrol, Department of Public Safety Mariah Flowers, Fleet Services Manager, Department of Administrative Services Joel Lunde, Department of Management





Date: June 20, 2023

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Mariah Flowers, Fleet Manager

DAS Fleet Services

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#981/Hail
Event Date	May 7, 2023
Summary	Vehicle 981 sustained hail damage during a storm. (256507)
Amount Requested	\$16,058.80 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager

DAS Fleet Services

Mariah.Flowers@iowa.gov

515-414-6582



Risk, DAS <das.risk@iowa.gov>

FW: Nolan Tahoe: #981

1 message

Adams Jeannie <jadams@dps.state.ia.us>

Mon, May 8, 2023 at 9:03 AM

To: "ExecutiveCouncil [TOS]" <ExecutiveCouncil@tos.iowa.gov>, Tammy Hollingsworth

<Tammy.Hollingsworth@aos.iowa.gov>

Cc: "Risk, DAS (das.risk@iowa.gov)" <das.risk@iowa.gov>

Storm 5-7-2023

Jeannie Adams
ISP Fleet & Supply, Fleet Asset Manager
Department of Public Safety
30 N.E. 48th Place
Des Moines, Iowa 50313
Direct #: 515-725-0643
Cell Phone: 515-204-3019

Shop: 515-281-3277 Fax: 515-242-6321

Email: jadams@dps.state.ia.us<mailto:jadams@dps.state.ia.us>

From: Noelck Christopher <noelck@dps.state.ia.us>

Sent: Monday, May 8, 2023 8:19 AM

To: Adams Jeannie < jadams@dps.state.ia.us>

Cc: Lamp Scott <selamp@dps.state.ia.us>; Waymire Patrick <waymire@dps.state.ia.us>; Nolan Bradley

<bnolan@dps.state.ia.us>
Subject: Nolan Tahoe: #981

Good Morning,

SA Nolan received a significant amount of hail damage on his way into training yesterday. Damage includes windshield and cosmetic damage on almost every panel of the Tahoe. SA Nolan is going to contact SafeLite to see if we can get the windshield fixed. The vehicle is drivable.

Since this was an act of nature damage. What are our next steps.

Thank you C. J.

C. J. Noelck, Special Agent in Charge

Field Intelligence Operations

Division of Intelligence and Fusion Center

Iowa Department of Public Safety

215 East 7<x-apple-data-detectors://0/0>th<x-apple-data-detectors://0/0> St.<x-apple-data-detectors://0/0>

Des Moines, IA 50319-0049<x-apple-data-detectors://0/0>

Office: (515)-725-6323

Cell: (712)-250-0116<tel:(712)-250-0116>

noelck@dps.state.ia.us<mailto:noelck@dps.state.ia.us>

NOTICE This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us; das.risk@iowa.gov

- > One Repair Estimate from Approved State Bid Shop
- > DOT MARS Report (if reportable)
- > Memo from the Driver of the State Vehicle
- > 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #:

OTATE VEHICLE. (Walk II Act of Nature) CASE #:								
Date:	05/07/2023		Time:	4:40 pm				
(Month/Day/Year)			(Time plus a.m./p.m.)	•				
Vehicle Plate #:	215	ILS	Vehicle Mileage:	13101				
Vehicle								
Description: (Yr/Make/Model/ & Vin#)	202	2 Chevy Tahoe	9					
Assigned To:	Nolan		Badge #	I-76				
Driven By:	Nolan		Badge #	I-76				
Driver's Lic #:			Damage:	\$10,000+				
Vehicle Towed: (Yes / No)	NA		Towed By:	NA				
Towed To:	NA		Towing Cost:	\$				
Seat Belt:			Type of Vehicle:					
(Yes / No)			(Marked/Semi /Unmarked)					
Injured/Injuries:		NA						
Occupants: (Other than driver)		0						

VEHICLE #2:

DL #:	NA	State:
Vehicle Lic. #		State:
Driver's Name:		
Driver's Address:		
Owner's Name:		
Owner's Address:		

Owner's Phone:						
Insurance Info:						
(Carrier/Policy #/Phone)						
Veh Description: (Yr/Make/Model & Vin#)						
(TI/Make/Model & VIII#)						
Damage:	\$	Seat	Belt:			
Darriago.	P	(Yes /				
Injured/Injuries:						
Occupants: (Other than driver)				7		
Occupant(s) Wearing	r Seat B	elt: (Yes/No)				
Occupant(3) Wearing	y Ocal D	ert. (Yes/No)				
OTUED INCODMAT	ON.					
OTHER INFORMATION Witnesses:	ION:	NA				
Accident Location:			0 1/1/1/0/			
(Street/Hwy)		Westbound I-80 MM184				
County:		Poweshiek				
Weather/Road Condi	itions:					
On May 7, 2023, I wa	as trave	ling westbound	d on I-80 near	MM184 around		
4:40 pm, when traff						
rain, and hail. It beg						
shattering it along v						
and passenger side						
an overpass to seel	shelte	r under. At the	conclusion of	f the storm I		
observed hail dama						
were submitted with			took photogr			
		p - 1				
Property Damage oth	er than	None				
Vehicles:						
Cost:		\$				
Citations Issued To:	1	VA				
(List Charge(s) and Statute C						
Investigating Officer:						
	200					

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:	NA NA	State:	
Vehicle Lic. #		State:	

Driver's Name:						
Driver's Address:						
Owner's Name:						
Owner's Address:		100000				
Owner's Phone:						
Insurance Info:						
(Carrier/Policy #/Phone)						
Veh Description:						
(Yr/Make/Model & Vin#)						
Damage:	\$		Seat B	elt:		
			(Yes / No)		
Injured/Injuries:						
Occupants:		8	46.			
(Other than driver)					772	2000
Occupant(s) Wearing	ng Seat Belt:	(Yes/No)				

QUALITY CLAIMS SOLUTIONS

105 N Krohn Place SIOUX FALLS, SD 57103

Phone: (877) 237-3727, FAX:(866) 371-2844 qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: NOLAN, BRADLEY Job Number:

Written By: Ryland Malsam

Insured: NOLAN, BRADLEY Type of Loss:

Comprehensive

Point of Impact: 27 Hail

Policy #: UNK

Date of Loss: 6/6/2023 12:00 PM Claim #: Days to Repair:

APDSOI0256507-001

0

Workfile ID:

8edc1af1

Owner: Inspection Location:

NOLAN, BRADLEY 100 LAKEWOOD TERRACE CLINTON, IA 52732

CLASSIC BODYWORKS

213 17TH AVE N CLINTON, IA 52732

Other

(563) 243-2688 Evening

Repair Facility:

VEHICLE

2022 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection

VIN:

1GNSKLED3NR334923

Production Date:

Interior Color:

License:

Odometer:

0

Exterior Color:

State:

Condition:

TRANSMISSION CONVENIENCE **RADIO** Hands Free Device Automatic Transmission Air Conditioning AM Radio Xenon or L.E.D. Headlamps 4 Wheel Drive Intermittent Wipers FM Radio Positraction **POWER** Tilt Wheel Stereo Lane Departure Warning Power Steering Cruise Control Search/Seek **ROOF** Power Brakes Rear Defogger Auxiliary Audio Connection Luggage/Roof Rack Power Windows Keyless Entry SAFETY **SEATS** Power Locks Alarm

Power Mirrors Message Center

Heated Mirrors

Power Driver Seat Power Passenger Seat

DECOR Dual Mirrors Privacy Glass Steering Wheel Touch Controls Rear Window Wiper

Telescopic Wheel Climate Control **Dual Air Condition** Backup Camera

Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4) 4 Wheel Disc Brakes Traction Control

Stability Control Front Side Impact Air Bags Head/Curtain Air Bags

3rd Row Seat WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

TRUCK Trailer Hitch Trailering Package

6/7/2023 7:21:02 AM 314048 Page 1

Estimate of Record

Owner: NOLAN, BRADLEY Job Number:

2022 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection

Console/Storage

Parking Sensors

Communications System

Running Boards/Side Steps

Estimate of Record

Owner: NOLAN, BRADLEY

Job Number:

2022 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection

	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
#		* tax exempt state vehicle*		1			
FRONT BUMP	ER & G	RILLE					
	R&I	R&I bumper cover				1.7	
	R&I	R&I grille assy				0.2	
FRONT LAMPS	5						
	R&I	RT Headlamp assy				0.5	
	R&I	LT Headlamp assy				0.5	
HOOD							
	Repl	Hood	85112715	1	1,151.27	1.5	3.2
		Add for Underside(Complete)					1.6
FENDER							
	Repl		84384211	1	767.63	2.4	2.2
		Overlap Major Adj. Panel					-0.4
	35 2	Add for Edging					0.5
	Repl	RT Nameplate "Z71"	85003753	1	35.82		
	Repl	LT Nameplate "Z71"	85003751	1	35.82		
	Blnd	LT Fender					1.1
#		PDR EFT FENDER		1	100.00		
ELECTRICAL *	DOT	A					
ROOF	R&I	Antenna assy w/o sat radio				0.3	
ROOF	Repl	Doof novel w/s harmen wills	0.46077.40				
	кері	Roof panel w/o luggage rails	84607740	1	192.40	22.0	5.4
	Repl	Overlap Major Non-Adj. Panel	04027000		67.00		-0.2
		RT Roof molding w/o luggage rack	84827998	1	67.98	Incl.	
	Repl	LT Roof molding w/o luggage rack	84827997	1	67.98	Incl.	
	R&I	R&I headliner				Incl.	
PILLARS, ROC	KER &	FLOOR					
	Repl	RT Uniside assy	85595979	1	1,721.23 s	32.2	8.0
		Overlap Major Adj. Panel					-0.4
	R&I	RT Frt rocker mldg w/o pwr assist step				0.8	
	R&I	RT Rear rocker mldg w/o pwr assist step				Incl.	
*	R&I	RT Step bar assy black				0.7	
*	Subl	LT Uniside assy +25%		1	<u>281.25</u> s		
FRONT DOOR							
		RT Door shell w/o body side moldings	84926004	1	1,075.00	5.4	3.1
		170					-0.4
		was visit and the same and the	84844388	1	59.65	Incl.	0.1
		Elian Delia del Colo Company de la Colo Colo Colo Colo Colo Colo Colo C					
		epl		epl RT Belt molding chrome 84844388	epl RT Belt molding chrome 84844388 1	epl RT Belt molding chrome 84844388 1 59.65	epl RT Belt molding chrome 84844388 1 59.65 Incl.

Estimate of Record

Own	er: NOLAN, B	RADI	LEY				Job N	lumber:
2022 C	HEV Tahoe Comm	ercial 4	WD (Fleet) 4D UTV 8-5.3L Gasoline Di	rect Injection				
39		Repl	RT Nameplate "TAHOE" black	84707393	1	31.45	0.2	
40		R&I	RT Rear applique				Incl.	
41		R&I	RT R&I mirror				Incl.	
42		R&I	RT R&I trim panel				Incl.	
43		R&I	RT Handle, outside w/o chrome				Incl.	
44	REAR DOOR							
45		Repl	RT Door shell w/o body side moldings	84926044	1	1,075.00	4.6	3.1
46			Overlap Major Adj. Panel					-0.4
47			Clear Coat					2.5
48		Repl	RT Belt molding chrome	84914983	1	63.77	Incl.	
49		Repl	RT Upper molding black	84988671	1	75.93	0.2	
50		R&I	RT Front applique				Incl.	
51		R&I	RT Rear applique				Incl.	
52		R&I	RT R&I trim panel				Incl.	
53	*	R&I	RT Handle, outside w/o chrome				Incl.	
54	QUARTER PAN	IEL						
55		Repl	RT Front molding chrome	85136433	1	124.28	0.2	
56		Repl	RT Upper molding black	84864987	1	200.15	0.2	
57		R&I	RT Qtr glass GM, w/o glass breakage sensor w/o privacy tint				Incl.	
58	#		Urethane Kit		1	10.00		
59		Repl	LT Upper molding black	84864986	1	200.15	0.2	
60	*	Subl	LT Quarter panel +25%		1	218.75		
61	LIFT GATE							
62		R&I	R&I liftgate assy				1.4	
63	REAR LAMPS							
64		Repl	RT Tail lamp	84849417	1	618.82	0.4	
65	REAR BUMPER							
66		R&I	R&I bumper cover				Incl.	
67	VEHICLE DIAG	inost:						
68	*		Pre-repair scan		1	<u>75.00</u> m		
69	*		Post-repair scan		1	<u>75.00</u> m		
70	#		panel bond		1	50.00		
			Note: open to invoice on supplement					
71	#		seam sealer		1	10.00	0.5	
72	#		Cover Car		1	5.00	0.2	
73	#		Corrosion Protection		1	5.00	0.1	
74	#		Hazardous Waste		1	3.00		
75	#		additional materials		1	488.10		
				SUBTOTALS		9,017.80	76.6	28.9

Owner: NOLAN, BRADLEY

Job Number:

2022 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection

ESTIMATE TOTALS

Category	Basis	Basis		Cost \$	
Parts				9,017.80	
Body Labor	76.6 hrs	@	\$ 62.00 /hr	4,749.20	
Paint Labor	28.9 hrs	@	\$ 62.00 /hr	1,791.80	
Paint Supplies				500.00	
Subtotal			 	16,058.80	
Total Cost of Repairs				16,058.80	
Deductible				0,00	
Total Adjustments				0.00	
Net Cost of Repairs				16,058.80	

MyPriceLink Estimate ID / Quote ID:

1095353259767373824 / 124447610

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.

Estimate calculated using a preset user threshold amount for the paint and material cost.