MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE



Executibe Council of Jowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

February 3, 2025

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$7,841.61, subject to an audit of actual invoices. On December 23, 2024, Vehicle #93 was damaged by a deer. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

(risti Onstot

Kristi Onstot

Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services

DAS Fleet Services, Risk

Matt Bender, Department of Management

Heather Hackbarth, Department of Management

OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

January 21, 2025

Kristi Onstot Executive Council L O C A L

Subject: Deer Damage to Vehicle #93 on December 23, 2024

Department of Administrative Services Claim dated December 27, 2024

AOS Claim ID: 3949

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$7,841.61, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Bu R Bus

cc: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



KIM REYNOLDS, GOVERNOR CHRIS COURNOYER, LT. GOVERNOR ADAM STEEN, DIRECTOR

Date: December 27, 2024

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#93 / Animal
Event Date	December 23, 2024
Summary	Vehicle 93 - struck a deer. (296961)
Amount Requested	\$7,841.61 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s)

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Ryan Betts

DAS Fleet Services ryan.betts1@iowa.gov

515-281-8008



Risk, DAS <das.risk@iowa.gov>

Fwd: Trooper Flaherty car deer accident

1 message

Risk, DAS <das.risk@iowa.gov>

Fri, Dec 27, 2024 at 8:57 AM

To: Tammy Hollingsworth < Tammy. Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil < executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 93 struck a deer on 12/23/2024. I will forward all information as soon as it is received.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

109 SE 13th St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov

https://das.iowa.gov



----- Forwarded message -----

From: Anderson Allen <aanderso@dps.state.ia.us>

Date: Mon, Dec 23, 2024 at 8:24 AM

Subject: Trooper Flaherty car deer accident

To: DAS.Risk@iowa.gov <das.risk@iowa.gov>, vehicledamage <vehicledamage@dps.state.ia.us> Cc: Taylor Aaron <ataylor@dps.state.ia.us>, Sitzman Joseph <sitzman@dps.state.ia.us>, Major Wade

<major@dps.state.ia.us>

AII,

On 12-23-24 at 08:00 Trooper Flaherty # 93 struck a deer with his state issued patrol vehicle. The accident accrued on hwy 169 on the south edge of Desoto. Estimate and vehicle damage report will follow.

Respectfully,

Sergeant Allen Anderson

Assistant District Commander

Iowa State Patrol- District 2

1619 Truro Pavement

Osceola, IA 50213

https://dps.iowa.gov/

https://dpscareers.com/



NOTICE This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: DPS – Vehicle Damage; DAS – Risk

- One Repair Estimate from Approved State Bid Shop
- > DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- > 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature⊠) CASE #: 2024031634

D	111111111111111111111111111111111111111	Nature) CASE #:	2024031634
Date:	12/23/24	Time:	08:00 a.m.
(Month/Day/Year)		(Time plus a.m./p.m.)	G.III.
Vehicle Plate #:	93	Vehicle Mileage:	13,700
Vehicle			10,100
Description:	2023 Ford F150 p	olice responder	
(Yr/Make/Model/ &	Vin # 1FTFW1P89	PKEAS345	
Vin#)			
Assigned To:	Darren Flaherty	Badge #	93
Driven By:	Darren Flaherty	Badge #	93
Driver's Lic #:	676YY3101		
Vehicle Towed:		Damage:	\$7841.61
(Yes / No)	Yes	Towed By:	Diversified
Towed To:	Karls Chev Stuart	Towing Cost:	\$0000
Seat Belt:	Yes	Type of Vehicle:	Marked
(Yes / No)		(Marked/Semi /Unmarked)	Markeu
Injured/Injuries:	None	(*************************************	
Occupants:	1		
(Other than driver)			

VEHICLE #2:

DI II	·	
DL #:	State:	
Vehicle Lic. #	State:	
Driver's Name:	State.	
Driver's Address:		
Owner's Name:		
Owner's Address:		
Owner's Address:		

Owner's Phone:					
Insurance Info:					
(Carrier/Policy #/Phone)					
Veh Description:					
(Yr/Make/Model & Vin#)					
Domogo	Φ.		T =		
Damage:	\$		Seat B		
Injured/Injuries:			(Yes / No)	
Occupants:					
(Other than driver)					
Occupant(s) Weari	ng Seat B	elt: (Yes/No)	res	
OTHER INFORMA	TION:				
Witnesses:					
Accident Location:		Hwv 169	south e	dge of Desc	nto
(Street/Hwy)		,	oodiii o	age of Desc	7.0
County:		Dallas			
Weather/Road Con	ditions:	Dry			
Narrative:					
UNIT 1 WAS NORT	HBOUND	ON HIG	HWAY 1	169 WHEN	A DEFR
ENTERED THE TR	AVELED	PORTION	I FROM	THE WEST	UNIT 1 WAS
UNABLE TO AVOID	COLLIS	ION AND	STRUC	K THE DEF	R IN THE
FRONT LEFT COR	NER OF	THE VEHI	CLE.		
Proporty Domage					
Property Damage of	ther than				
	ther than				
	ther than	\$			
		\$			
Vehicles: Cost: Citations Issued To:		\$			
Vehicles: Cost: Citations Issued To:		\$			
Vehicles: Cost: Citations Issued To: (List Charge(s) and Statute	Code(s))		rooper l	Miller # 125	
Vehicles: Cost: Citations Issued To: (List Charge(s) and Statute	Code(s))		「rooper I	Miller # 125	
Vehicles: Cost: Citations Issued To: (List Charge(s) and Statute	Code(s))		rooper l	Miller # 125	
Vehicles: Cost: Citations Issued To: (List Charge(s) and Statute Investigating Officer	Code(s))	1			
Vehicles: Cost: Citations Issued To: (List Charge(s) and Statute Investigating Officer VEHICLE #3: (If nee	Code(s))	1			
Vehicles: Cost: Citations Issued To: (List Charge(s) and Statute) Investigating Officer VEHICLE #3: (If need copies of this porti	Code(s))	1	ehicles,	please ma	
Vehicles: Cost: Citations Issued To: (List Charge(s) and Statute) Investigating Officer VEHICLE #3: (If necopies of this portion of the porti	Code(s))	1	ehicles,	please ma e:	
Vehicles: Cost: Citations Issued To: (List Charge(s) and Statute) Investigating Officer VEHICLE #3: (If necopies of this porti DL #: Vehicle Lic. #	Code(s))	1	ehicles,	please ma e:	
Vehicles: Cost: Citations Issued To:	Code(s))	1	ehicles,	please ma e:	

Our and a N					
Owner's Name:					
Owner's Address:					
Owner's Phone:					
Insurance Info:					
(Carrier/Policy #/Phone)					
Veh Description:					
(Yr/Make/Model & Vin#)					
Damage:	\$	Coot	D - 14:	1	
Damago.	Ψ		Belt:	Yes	
Injured/Injuries:		(Yes /	No)		
_					
Occupants:					
(Other than driver)	_				
Occupant(s) Wearing	ng Seat Belt:	(Yes/No)	Yes		

Your Dealer for Life 324 sw 8th st, Exit 93 and I-80, Stuart, IA 50250 Phone: (515) 523-8201

Workfile ID: PartsShare:

a09f9552 8jBqMk

Federal ID:

82-1627153

Preliminary Estimate

RO Number: 107497

Written By: TONY HOOVER

Insured:

Iowa State Patrol

Policy #:

Claim #:

Type of Loss:

Point of Impact: 11 Left Front

Date of Loss:

Days to Repair: 0

Owner:

Inspection Location:

Iowa State Patrol

Other

Insurance Company: IOWA STATE PATROL

VEHICLE

2023 FORD F-150 Police Responder XL SuperCrew 4WD w/5.5' Box (Fleet) 4D P/U 6-3.5L Turbocharged Gasoline Port/Direct Injection WHITE (yz)

VIN:

1FTFW1P89PKEAS345

Interior Color:

GRAY

Mileage In:

13,992

Vehicle Out:

License: 93

Exterior Color:

WHITE (yz)

Mileage Out:

State:

IΑ

Production Date:

2/2023

Condition:

Good

Job #:

4886

TRANSMISSION

Automatic Transmission

4 Wheel Drive

POWER

Power Steering

Power Brakes

Power Windows

Power Locks Power Mirrors

Power Driver Seat

DECOR

Dual Mirrors Tinted Glass Overhead Console

CONVENIENCE

Air Conditioning Intermittent Wipers

Tilt Wheel

Cruise Control

Steering Wheel Touch Controls

Telescopic Wheel

Backup Camera

Parking Sensors

RADIO

AM Radio FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control

Stability Control Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

Positraction

SEATS

Cloth Seats

Bucket Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

TRUCK

Rear Step Bumper

Trailer Hitch

Trailering Package

RO Number: 107497

2023 FORD F-150 Police Responder XL SuperCrew 4WD w/5.5' Box (Fleet) 4D P/U 6-3.5L Turbocharged Gasoline Port/Direct Injection WHITE (yz)

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUI	IPER				. που φ	-	
2	#		R&I Push Bar		1		3.0	
3			O/H bumper assy				4.2	
4		R&I	in in its in in its in				Incl.	
5		R&I	LT Hole cover w/o fog lamps				Incl.	
6		R&I	Valance inner				0.1	
7		R&I	RT Valance outer				Incl.	
8		R&I	LT Valance outer				Incl.	
9		Repl	Upper molding	ML3Z17D957CAPTM	1	572.03	Incl.	1.4
10		R&I	Lower deflector w/tow hook w/o active shutter				Incl.	1.7
11		R&I	RT Outer cover w/o TREMOR				Incl.	
12		R&I	LT Outer cover w/o TREMOR				Incl.	
13		R&I	Center cover w/engine htr				Incl.	
14		R&I	Lower molding black				Incl.	
15	*	Rpr	Bumper w/o front park aid black				2.0	2.1
16			Add for Clear Coat				2.0	0.8
17	GRILLE			4.60				0.0
18		Repl	Grille carbon black	ML3Z8200AA	1	490.75	1.4	
19	*		Emblem w/o front camera				0.1	
20	FRONT LAM	PS					<u>0.1</u>	
21		Repl	LT Headlamp assy	ML3Z13008K	1	1,116.22	0.7	
22			Aim headlamps			,	0.5	
23	RADIATOR S						0.0	
24		Repl	Shutter upper	ML3Z8475D	1	629.20 m	Incl. M	
25		Repl	Sight shield	ML3Z19E525A	1	65.00	Incl.	
26	*	Rpr	Radiator support (ALU)				2.0	
27		Repl	LT Side shield	ML3Z8311D	1	14.47	0.1	
28	COOLING						0.1	
29		Repl	Trans cooler	ML3Z7869C	1	198.33 m	0.8	
	HOOD			The second secon				
31		Repl	Hood w/o Tremor (ALU)	ML3Z16612D	1	816.52	1.5	3.2
32			Add for Clear Coat					1.3
33		,	Add for Underside(Complete)					1.6
34			Insulator w/o Tremor				Incl.	1.0
35			Front w'strip w/o Tremor				Incl.	
36		R&I F	RT Side w'strip				Incl.	
37		R&I L	T Side w'strip				Incl.	
	FENDER						2.1.6.1	
39			T Fender (ALU)	VL3Z16006E	1	371.07	3.1	2.2
0			Overlap Major Non-Adj. Panel			ar and	5.1	-0.2
1		A	Add for Clear Coat					0.4
2		^	add for Edging					0.4

RO Number: 107497

2023 FORD F-150 Police Responder XL SuperCrew 4WD w/5.5' Box (Fleet) 4D P/U 6-3.5L Turbocharged Gasoline Port/Direct Injection WHITE (yz)

				SUBTOTALS		4,817.11		27.0	15.9
J/	π	R&I	Electrical components and Lights					2.0	
67	#		Four wheel alignment		1	94.95	Т		
66	#		Hazardous waste removal		1	5.00	T		
65	#		/ 10%						
64	#		De-Nib Sand and buff - 20% first						
63	#		Feather edge, prime and block		1	8.00			
62	**	Repl	A/M Flex additive		1	10.00 8.00	1		0.3
61	**	Repl	A/M Corrosion protection		1		_		
60	**	Repl	A/M Cover Car		1	10.00			
59	#		Headlight initialization (programming)		1	150.00		<u>0.5</u> 14	
58	*	Rpr	Post-repair scan				m	0.5 M	
57	*	Rpr	Pre-repair scan				m	<u>0.5</u> M	
56	VEHICLE DIA	GNOST	ICS					U./	
55		R&I	LT R&I trim panel					0.7	
54		R&I	LT Handle, outside black					0.3	
53		R&I	LT Applique w/o keyless pad					0.2 0.3	
52		R&I	LT Run channel					0.3	
51		R&I	LT Belt molding black					0.3	0.4
50			Add for Clear Coat						-0.2
49			Overlap Major Non-Adj. Panel					2.0	2.1
48	*	Rpr	LT Outer panel (ALU)						
47	FRONT DOO		21 Hameplate 1 130 AL					0.2	
46	*	R&I	LT Nameplate "F-150 XL"					<u>Incl.</u>	
45	*	R&I	LT Rear insulator	ML3Z16103K	1	242.17	'	Incl.	
44		Repl	LT Lower brace LT Fender liner XL, SSV	ML3Z16A143B	1	23.40)	0.1	

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts			Nate	4,707.16
Parts Discount	\$ 4,539.16		-12.0 %	-544.70
Body Labor	26.0 hrs	@	\$ 65.00 /hr	
Paint Labor	15.9 hrs	@	\$ 113.00 /hr	1,690.00
Mechanical Labor	1.0 hrs	@	\$ 113.00 /hr \$ 82.50 /hr	1,796.70
Miscellaneous	1.0 1113	w	\$ 62.30 /111	82.50
Subtotal				109.95
Grand Total				7,841.61
ar 700x 000 (2005)				7,841.61
Deductible				0.00
CUSTOMER PAY				0.00
INSURANCE PAY				
				7,841.61

RO Number: 107497

2023 FORD F-150 Police Responder XL SuperCrew 4WD w/5.5' Box (Fleet) 4D P/U 6-3.5L Turbocharged Gasoline Port/Direct Injection WHITE (yz)

THIS IS A PRELIMINARY ESTIMATE. ACTUAL COST TO REPAIR MAY BE DIFFERENT

LIMITED LIFETIME WARRANTY--SEE BODY SHOP PERSONNEL FOR DETAILS

***IF AFTERMARKET PARTS (PARTS MADE BY A SOURCE OTHER THAN THE ORIGINAL MANUFACTURER OF THAT

PART) ARE USED THEY WILL BE IDENTIFIED BY "QUAL.REPL.PART" IN THE MFG. PART NO. COLUMN

DUE TO MANY UNFORESEEN CIRCUMSTANCES IN THE REPAIRING OF VEHICLES, WE REGRET THAT WE CAN

ONLY ESTIMATE, NOT PROMISE, A COMPLETION TIME.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

RO Number: 107497

2023 FORD F-150 Police Responder XL SuperCrew 4WD w/5.5' Box (Fleet) 4D P/U 6-3.5L Turbocharged Gasoline Port/Direct Injection WHITE (yz)

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR2MA21, CCC Data Date 12/16/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

 $\label{eq:memoral} \begin{tabular}{ll} m=$MOTOR Mechanical component. & s=$MOTOR Structural component. & T=$Miscellaneous Taxed charge category. & T=$Miscellaneous Non-Taxed charge category. & T=$Miscella$

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.

D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

324 sw 8th st, Exit 93 and I-80, Stuart, IA 50250

			Image I	Report			
Owner:	Iowa State Patrol	Insurance:	IOWA STATE	Estimator:	TONY HOOVER	Vahisla O. I	
RO Number:	107497	Claim Number:		_otimator.	TOWN HOOVER	Vehicle Out:	
Year:	2023	Color:	WHITE (yz)	License Plate:	93	Drodustis - D-1	2/2000
Make:	FORD	Body Style:	4D P/U	State:	IA	Production Date:	2/2023
Model:	F-150 Police Respo	Engine:	6-3.5L Turbochar			Mileage In:	13,992
	·		TOTAL PURPORNAL	VIIV.	1FTFW1P89PKEAS345	Condition:	Good



12/23/2024 Comments:



12/23/2024 Comments:



12/23/2024 Comments:



12/23/2024 Comments:



12/23/2024 Comments:



12/23/2024 Comments:

324 sw 8th st, Exit 93 and I-80, Stuart, IA 50250

	Image Report								
Owner:	Iowa State Patrol	Insurance:	IOWA STATE	Estimator:	TONY HOOVER	Vehicle Out:			
RO Number:	107497	Claim Number:			TOTAL MOOVER	venicie out.			
Year:	2023	Color:	WHITE (yz)	License Plate:	93	Production Date:	2/2023		
Make:	FORD	Body Style:	4D P/U	State:	IA	Mileage In:	13,992		
Model:	F-150 Police Respo	Engine:	6-3.5L Turbochar	VIN:	1FTFW1P89PKEAS345	Condition:	Good		



12/23/2024 Comments:



12/23/2024 Comments:



12/23/2024 Comments:



12/23/2024 Comments:



12/23/2024 Comments:



12/23/2024 Comments:

324 sw 8th st, Exit 93 and I-80, Stuart, IA 50250

		Marie W. Com	Image l	Report			
Owner:	Iowa State Patrol	Insurance:	IOWA STATE	Estimator:	TONY HOOVER	Valida O	
RO Number:	107497	Claim Number:	_	Estimator.	TONT HOOVER	Vehicle Out:	
Year:	2023	Color:	WHITE (yz)	License Plate:	93	Dro dustis a Dal	2/222
Make:	FORD	Body Style:	4D P/U	State:	IA	Production Date:	2/2023
Model:	F-150 Police Respo	Engine:	6-3.5L Turbochar		1FTFW1P89PKEAS345	Mileage In: Condition:	13,992
				* 2. * 1	II II WIFO3FKEASS45	Condition:	Good



12/23/2024 Comments:



12/23/2024 Comments:



12/23/2024 Comments:



12/23/2024 Comments:



12/23/2024 Comments:



12/23/2024 Comments:

324 sw 8th st, Exit 93 and I-80, Stuart, IA 50250

		Amarin	Image I	Report			
Owner:	Iowa State Patrol	Insurance:	IOWA STATE	Estimator:	TONY HOOVER	Vahiala Out	
RO Number:	107497	Claim Number:		Localidadi.	TONT HOUVER	Vehicle Out:	
Year:	2023	Color:	WHITE (yz)	License Plate:	93	Draduation Det	2/2000
Make:	FORD	Body Style:	4D P/U	State:	IA	Production Date:	2/2023
Model:	F-150 Police Respo	Engine:	6-3.5L Turbochar			Mileage In:	13,992
	·		: ar bochar	A TIA'	1FTFW1P89PKEAS345	Condition:	Good



12/23/2024 Comments:



12/24/2024 E01 Comments:



12/24/2024 E01 Comments:



12/23/2024 Comments:



12/24/2024 E01 Comments:



12/24/2024 E01 Comments:

324 sw 8th st, Exit 93 and I-80, Stuart, IA 50250

Image Report							
Owner:	Iowa State Patrol	Insurance:	IOWA STATE	Estimator:	TONY HOOVER	Vehicle Out:	
RO Number:	107497	Claim Number:			, , , , , , , , , , , , , , , , , , ,	vernere out.	
Year:	2023	Color:	WHITE (yz)	License Plate:	93	Production Date:	2/2023
Make:	FORD	Body Style:	4D P/U	State:	IA	Mileage In:	13,992
Model:	F-150 Police Respo	Engine:	6-3.5L Turbochar	VIN:	1FTFW1P89PKEAS345	Condition:	Good



12/24/2024 E01 Comments:



12/24/2024 E01 Comments:



12/24/2024 E01 Comments:



12/24/2024 E01 Comments:



12/24/2024 E01 Comments:



12/24/2024 E01 Comments: