MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE



# Executibe Council of Jowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

February 3, 2025

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$6,538.47, subject to an audit of actual invoices. On November 19, 2024, Vehicle #236 was damaged by a deer. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

(risti Onstot

Kristi Onstot

**Executive Secretary** 

cc: Adam Steen, Director, Department of Administrative Services

DAS Fleet Services, Risk

Matt Bender, Department of Management

Heather Hackbarth, Department of Management

## OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

January 21, 2025

Kristi Onstot Executive Council L O C A L

Subject: Deer Damage to Vehicle #236 on November 19, 2024

Department of Administrative Services Claim dated November 21, 2024

AOS Claim ID: 3944

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$6,538.47, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Bri R Bris

cc: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



KIM REYNOLDS, GOVERNOR

ADAM STEEN, DIRECTOR

Date: November 21, 2024

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

**Executive Council** 

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#236 / Animal
Event Date	November 19, 2024
Summary	Vehicle 236 - struck a deer (claim# TBD)
Amount Requested	\$6,538.47 Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s)

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Rvan Betts

DAS Fleet Services ryan.betts@iowa.gov

515-281-8008



Risk, DAS <das.risk@iowa.gov>

## Fwd: Patrol Car vs. Deer (Act of Nature)

1 message

Risk, DAS <das.risk@iowa.gov>

Wed, Nov 20, 2024 at 8:17 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 236 struck a deer on 11/19/2024. I will forward all information as soon as it is received.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

#### **DAS Risk**

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

109 SE 13<sup>th</sup> St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov

https://das.iowa.gov



----- Forwarded message -----

From: Beenen Brian <beenen@dps.state.ia.us>

Date: Wed, Nov 20, 2024 at 7:54 AM Subject: Patrol Car vs. Deer (Act of Nature)

To: vehicledamage <vehicledamage@dps.state.ia.us>, DAS Risk <das.risk@iowa.gov>

Cc: Guill Bryan <guill@dps.state.ia.us>, Adams Jeannie <jadams@dps.state.ia.us>, Beck Michelle

<beck@dps.state.ia.us>

All,

Attached are the required documents for Sgt. Beck's patrol car vs. deer collision that occurred yesterday afternoon. An estimate will be obtained this afternoon and submitted. Let us know if you have any questions.

Thanks,

Brian

## Lieutenant Brian N. Beenen ★66★

#### **District Commander**

Iowa State Patrol | District 9

1510 West 1<sup>st</sup> Street | Cedar Falls, Iowa 50613

Office: 319-266-2677

Fax: 319-266-2228

beenen@dps.state.ia.us

https://dps.iowa.gov/

https://dpscareers.com/



\*NOTICE\* This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

#### 11 attachments



**IMG\_0093.jpg** 3626K



**IMG\_0094.jpg** 2982K



**IMG\_0095.jpg** 1707K



**IMG\_0096.jpg** 1879K




**IMG\_0090.jpg** 3322K



**IMG\_0091.jpg** 3151K



**IMG\_0092.jpg** 2816K



MARS\_Unit\_Report-2024028804.pdf 141K



432037\_\_Certification\_of\_Officer\_Involved\_in\_a\_Motor\_Vehicle\_Accident\_While\_in\_the\_Line\_of\_Duty\_YfrYAIAGGMSU4i3A.pdf
340K

**State Vehicle Damage Report** 

Attach this completed form to an email along with the items identified below and send to: DPS – Vehicle Damage; DAS – Risk

- > One Repair Estimate from Approved State Bid Shop
- > DOT MARS Report (if reportable)
- > Memo from the Driver of the State Vehicle
- > 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature⊠) CASE #: 2024028804

OIAIL VEINOL	L. Imain ii Aotoi	Mataro / Orto / II.	LULTULUUUT	
Date: (Month/Day/Year)	11/19/2024	Time: (Time plus a.m./p.m.)	1730 p.m.	
Vehicle Plate #:	236	Vehicle Mileage:	111422	
Vehicle 1 late #.	230	verlicie Mileage.	111422	
	2020 Dodge Cha	raer		
Description: (Yr/Make/Model/ & Vin#)	VIN: 2C3CDXKT5LH124223			
Assigned To:	Sgt. Beck	Badge #	236	
Driven By:	Sgt. Beck	Badge #	236	
Driver's Lic #:	809AK5835	Damage:	\$3,000.00 Est.	
Vehicle Towed: (Yes / No)	No	Towed By:		
Towed To:		Towing Cost:	\$	
Seat Belt: (Yes / No)	Yes	Type of Vehicle: (Marked/Semi /Unmarked)	Marked	
Injured/Injuries:	None			
Occupants: (Other than driver)	None			

## **VEHICLE #2:**

DL #:	State:	
Vehicle Lic. #	State:	
Driver's Name:		
Driver's Address:		
Owner's Name:		
Owner's Address:		
Owner's Phone:		

Carrier/Policy #/Phone   Veh Description: (Yr/Make/Model & Vin#)
Damage: \$ Seat Belt: (Yes/No) No  Injured/Injuries: Occupants: (Other than driver)  Occupant(s) Wearing Seat Belt: (Yes/No) Yes  OTHER INFORMATION:  Witnesses: None Accident Location: (Street/Hwy) County: Tama Weather/Road Conditions: Clear/Dry Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles:
Injured/Injuries:  Occupants: (Other than driver)  Occupant(s) Wearing Seat Belt: (Yes/No)  OTHER INFORMATION:  Witnesses: Accident Location: (Street/Hwy)  County: Tama  Weather/Road Conditions: Clear/Dry  Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles:  Nocupant(s) Yes  Yes  OTHER INFORMATION:  Yes  OTHER INFORMATION:  Yes  OTHER INFORMATION:  Ves  Ves  OTHER INFORMATION:  Ves  Ves  OTHER INFORMATION:  Ves  OTHER I
Injured/Injuries:  Occupants: (Other than driver)  Occupant(s) Wearing Seat Belt: (Yes/No)  OTHER INFORMATION:  Witnesses: Accident Location: (Street/Hwy)  County: Tama  Weather/Road Conditions: Clear/Dry  Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles:  Nocupant(s) Yes  Yes  OTHER INFORMATION:  Yes  OTHER INFORMATION:  Yes  OTHER INFORMATION:  Ves  Ves  OTHER INFORMATION:  Ves  Ves  OTHER INFORMATION:  Ves  OTHER I
Injured/Injuries: Occupants: (Other than driver)  Occupant(s) Wearing Seat Belt: (Yes/No)  OTHER INFORMATION:  Witnesses: Accident Location: (Street/Hwy)  County: Tama  Weather/Road Conditions:  Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles:  None  None
Occupant(s) Wearing Seat Belt: (Yes/No)  OTHER INFORMATION:  Witnesses: Accident Location: (Street/Hwy) County: Weather/Road Conditions: Clear/Dry Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles:
Occupant(s) Wearing Seat Belt: (Yes/No)  OTHER INFORMATION:  Witnesses: None Accident Location: (Street/Hwy)  County: Tama  Weather/Road Conditions: Clear/Dry  Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles:
OTHER INFORMATION:  Witnesses: None Accident Location: Highway 96 (Tama/Marshall County Line)  County: Tama  Weather/Road Conditions: Clear/Dry  Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles:
Witnesses: Accident Location: (Street/Hwy) County: Tama Weather/Road Conditions: None Clear/Dry Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles: None
Witnesses: Accident Location: (Street/Hwy) County: Tama Weather/Road Conditions: None Clear/Dry Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles: None
Witnesses: Accident Location: (Street/Hwy) County: Tama Weather/Road Conditions: Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles: None Highway 96 (Tama/Marshall County Line) Clear/Dry Arrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.
Accident Location: (Street/Hwy)  County: Tama  Weather/Road Conditions:     Clear/Dry  Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles:  None
County: Tama  Weather/Road Conditions: Clear/Dry  Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles:
Weather/Road Conditions: Clear/Dry Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles:
Narrative: Sgt. Beck was traveling eastbound on Hwy 96 and collided into a deer which was crossing the roadway.  Property Damage other than Vehicles:
deer which was crossing the roadway.  Property Damage other than Vehicles:
Property Damage other than Vehicles:
Vehicles:
Vehicles:
Vehicles:
Vehicles:
Vehicles:
Coots
Cost: \$
Citations Issued To:
(List Charge(s) and Statute Code(s))
Investigating Officer: Lt. Brian Beenen #66
Lt. Brian Beenen #00
VEHICLE #3: (If needed) (For more vehicles, please make extra
copies of this portion)
DL #: State:
Vehicle Lic. # State:
Driver's Name:
Driver's Address:
Owner's Name:
Owner's Address:

Owner's Phone:					
Insurance Info: (Carrier/Policy #/Phone)					
Veh Description: (Yr/Make/Model & Vin#)					
Damage:	\$	Seat (Yes /	Belt:	Yes	
Injured/Injuries:					
Occupants: (Other than driver)					
Occupant(s) Wearing	ng Seat Belt:	(Yes/No)	Yes		



## WITHAM COLLISION CENTER

FORD-CHEVROLET-VW-KIA 2033 LAPORTE RD, WATERLOO, IA 50702 Phone: (319) 234-4200

Workfile ID: PartsShare: 6e428196 8g6y8d

Federal ID:

42-1060951

## **Preliminary Estimate**

RO Number: 16002861

Written By: Branden Frederick

Insured:

ISP 236

Policy #:

Claim #:

Type of Loss:

Point of Impact:

Date of Loss:

Days to Repair: 0

Owner: ISP 236

**Inspection Location:** 

WITHAM COLLISION CENTER

2033 LAPORTE RD WATERLOO, IA 50702

Repair Facility

(319) 234-4200 Business

**Insurance Company:** 

#### **VEHICLE**

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

VIN:

2C3CDXKT5LH124223

Interior Color:

Mileage In:

Vehicle Out:

License:

Exterior Color:

Mileage Out:

State:

IΑ

Production Date:

Condition:

Job #:

**TRANSMISSION** 

Automatic Transmission

4 Wheel Drive

Power Steering Power Brakes

Power Windows

Power Locks

Power Mirrors

**DECOR** 

**Dual Mirrors** 

Tinted Glass

Power Driver Seat

Overhead Console

**POWER** 

Intermittent Wipers

Tilt Wheel

Cruise Control

**CONVENIENCE** 

Air Conditioning

Rear Defogger

Keyless Entry

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Climate Control

Backup Camera Parking Sensors

**RADIO** 

AM Radio

FM Radio Stereo

Search/Seek

Auxiliary Audio Connection

**SAFETY** 

Drivers Side Air Bag

Passenger Air Bag Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags Hands Free Device

**SEATS** 

Cloth Seats **Bucket Seats** 

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

**PAINT** 

Clear Coat Paint

**OTHER** 

Traction Control Stability Control

California Emissions

## **RO Number: 16002861**

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUM	1PER & G	RILLE					
2			O/H front bumper				3.4	
3	** <>	Repl	A/M CAPA Bumper cover	68267765AC	1	678.00	Incl.	3.4
4			Add for Clear Coat					1.4
5			Add for fog lamps				0.3	
6	**	Repl	A/M CAPA Upper grille black crossbars	5PP33DX8AB	1	371.00	Incl.	
7		Repl	RT Bumper bracket	68226544AB	1	44.45	0.1	
8	**	Repl	A/M CAPA Closure panel	68226530AF	1	186.00	Incl.	
9		Repl	License bracket w/o SRT	68238771AC	1	41.65	0.1	
10		Repl	RT Support outer	68213539AC	1	12.75	Incl.	
11		Repl	RT Support inner	68226532AA	1	44.20	Incl.	
12	FRONT LAM	IPS						
13		R&I	RT R&I headlamp assy				0.3	
14	**	Repl	A/M CAPA LT Headlamp assy halogen	68541681AA	1	763.00	0.4	
15			Aim headlamps				0.5	
16	HOOD							
17	*	Rpr	Hood (ALU)				<u>1.5</u>	3.0
18			Overlap Major Non-Adj. Panel					-0.2
19			Add for Clear Coat					0.6
20		R&I	Insulator				0.3	
21	FENDER							
22		Repl	RT Fender w/o wide body	68213060AC	1	458.00	1.6	2.0
23			Overlap Major Adj. Panel					-0.4
24			Add for Clear Coat					0.3
25			Add for Edging					0.5
26		R&I	RT Fender liner 3.6, 5.7 liter				Incl.	
27	FRONT DOO	)R						
28	*	Blnd	RT Door shell (HSS)					<u>1.1</u>
29	*	R&I	RT Power mirror				<u>0.5</u>	
30			RT Handle, outside black				0.4	
31		R&I	RT R&I trim panel				0.5	
32	#	R&I	decal				1.0	
33	MISCELLAN	EOUS OP	PERATIONS					
34	#		Hazardous waste removal		1	4.00 T		
35	#	Repl	Flex Additive		1	5.00		
36	#		Corrosion protection		1	10.00	0.3	
37	#	Rpr	Feather Prime and Block					1.0
38	#		4 Wheel Alignment		1	140.00		
39	#	Repl	Push Bar per invoice		1	951.03	1.0	
40	#		Pre Scan		1		1.0 M	
41	#		Post Scan		1		1.0 M	

#### **RO Number: 16002861**

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

Category	Basis		Rate	Cost \$
Parts				3,705.08
Parts Discount	\$ 601.05		-10.0 %	-60.11
ody Labor	12.2 hrs	@	\$ 75.00 /hr	915.00
Paint Labor	12.7 hrs	@	\$ 135.00 /hr	1,714.50
Mechanical Labor	2.0 hrs	@	\$ 130.00 /hr	260.00
Miscollangous				4 00

**SUBTOTALS** 

INSURANCE PAY	6,538.47
CUSTOMER PAY	0.00
Deductible	0.00
Grand Total	6,538.47
Subtotal	6,538.47
Miscellaneous	4.00

3,709.08

14.2

12.7

AUTHORIZED AND ACCEPTED: YOU ARE HEREBY AUTHORIZED TO MAKE THE ABOVE REPAIRS. I UNDERSTAND THAT PAYMENT IN FULL WILL BE DUE UPON RELEASE OF VEHICLE, INCLUDING ADDITIONAL SUPPLEMENTAL DAMAGE CHARGES, AND HEREBY GRANT YOU AND/YOUR EMPLOYEES, PERMISSION TO OPERATE THE CAR, TRUCK, OR VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS, OR ELSEWHERE FOR THE PURPOSE OF TESTING AND / OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON THE ABOVE CAR, TRUCK, OR VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO THE VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT, OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

AUTHORIZED BY:	DATE

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR VEHICLE. ANY WARRANTIES APPLICABLE TO THE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OV YOUR VEHICLE.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

#### RO Number: 16002861

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 11/15/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

#### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

#### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

#### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.

D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

## **RO Number: 16002861**

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

## **PARTS SUPPLIER LIST**

Line	Supplier	Description	Price
3	Keystone, Inc	#CH1000A24PP	\$ 678.00
	100 EAST 5TH ST	A/M CAPA Bumper cover	
	WATERLOO IA 50703	Quote: 2749224326	
	(800) 258-8885	Expires: 01/04/25	
6	Keystone, Inc	#CH1200388PP	\$ 371.00
U	•		\$ 371.00
	100 EAST 5TH ST	A/M CAPA Upper grille black crossbars	
	WATERLOO IA 50703	Quote: 2749227669	
	(800) 258-8885	Expires: 01/04/25	
		W6U4884484	
8	Keystone, Inc	#CH1224101C	\$ 186.00
	100 EAST 5TH ST	A/M CAPA Closure panel	
	WATERLOO IA 50703	Quote: 2749270598	
	(800) 258-8885	Expires: 01/04/25	
14	Keystone, Inc	#CH2502337C	\$ 763.00
1.	• •		Ψ 7 03.00
	100 EAST 5TH ST	A/M CAPA LT Headlamp assy halogen	
	WATERLOO IA 50703	Quote: 2749258580	
	(800) 258-8885	Expires: 01/04/25	