

MEMBERS OF COUNCIL

HON. KIM REYNOLDS  
GOVERNOR

HON. PAUL D. PATE  
SECRETARY OF STATE

HON. ROB SAND  
AUDITOR OF STATE

HON. ROBY SMITH  
TREASURER OF STATE

HON. MIKE. NAIG  
SECRETARY OF AGRICULTURE



## Executive Council of Iowa

CAPITOL BUILDING  
DES MOINES, IOWA 50319  
PHONE: 515 281-5368

August 19, 2024

Accounting Department  
Office of the Treasurer  
Lucas Building  
321 E 12<sup>th</sup> Street  
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$12,187.22, subject to an audit of actual invoices. On June 27, 2024, Vehicle #160 was damaged by a deer. Request was to cover repair costs.


EXECUTIVE COUNCIL OF IOWA

*Victoria Newton*

Victoria Newton  
Acting Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services  
DAS Fleet Services, Risk  
Matt Bender, Department of Management  
Heather Hackbarth, Department of Management

AOS Claim # 3853  
TOS Job # \_\_\_\_\_



**OFFICE OF AUDITOR OF STATE**  
STATE OF IOWA

Rob Sand  
Auditor of State

State Capitol Building  
Des Moines, Iowa 50319-0004  
Telephone (515) 281-5834

August 5, 2024

Kristi Onstot  
Executive Council  
L O C A L

Subject: Deer Damage to Vehicle #160 on June 27, 2024  
Department of Administrative Services  
Claim dated July 1, 2024  
AOS Claim ID: 3853

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$12,187.22, subject to an audit of actual invoices.

Sincerely,

A handwritten signature in black ink, appearing to read "Brian R. Brustkern".

Brian R. Brustkern, CPA  
Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services  
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services  
Heather Hackbarth, Department of Management



Governor Kim Reynolds  
Lt. Governor Adam Gregg

Adam Steen, Director

Date: July 1, 2024

To: Tammy Hollingsworth, Auditor of State  
Victoria Newton, Treasurer of State  
Executive Council

From: Karl Bubser, Fleet Administrator  
DAS Fleet Services  
Department of Administrative Services

**Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration**

Vehicle / Event	#160/Animal
Event Date	June 27, 2024
Summary	Vehicle 160 struck a deer. (284166)
Amount Requested	\$11,691.72 - Estimate \$ 495.50 - Tow <b>\$12,187.22 - Total</b>
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

A handwritten signature in black ink, appearing to read "Karl Bubser".

Karl Bubser, Fleet Administrator  
DAS Fleet Services  
Karl.Bubser@iowa.gov  
515-281-3162

---

**Fwd: 160 car/deer**

1 message

**Risk, DAS** <das.risk@iowa.gov>

Mon, Jul 1, 2024 at 1:53 PM

To: TOS ExecutiveCouncil &lt;executivecouncil@tos.iowa.gov&gt;, Tammy Hollingsworth &lt;Tammy.Hollingsworth@aos.iowa.gov&gt;

Apologies, somehow this was not sent. Please accept this email as initial 24 hr notification for AON

**All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.**

Thank you,


**DAS Risk**

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

109 SE 13<sup>th</sup> St, Des Moines, IA 50319

515-281-3162 office

[das.risk@iowa.gov](mailto:das.risk@iowa.gov)<https://das.iowa.gov>

----- Forwarded message -----

From: **Andreasen Jeremy** <andrease@dps.state.ia.us>

Date: Thu, Jun 27, 2024 at 8:39 AM

Subject: 160 car/deer

To: vehicledamage &lt;vehicledamage@dps.state.ia.us&gt;, Risk, DAS (das.risk@iowa.gov) &lt;das.risk@iowa.gov&gt;

Cc: post12sup &lt;post12sup@dps.state.ia.us&gt;

For the purposes of 24 notification for act of nature collisions: Trooper Popp #160 struck a deer on US 61 in Des Moines County on today's date at 0232 am. Damage report is forthcoming.

**Sergeant Jeremy Andreasen ★161★**

Iowa State Patrol | District 13

Iowa Department of Public Safety

1300 S. Grand Avenue | Mount Pleasant, Iowa 52641

Office: 319-385-8715

Fax: 319-385-2743

[andrease@dps.state.ia.us](mailto:andrease@dps.state.ia.us)<https://dps.iowa.gov/><https://dpscareers.com/>



**Department of  
Public Safety**

**\*NOTICE\*** This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

## State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: [vehicledamage@dps.state.ia.us](mailto:vehicledamage@dps.state.ia.us) ; [das.risk@iowa.gov](mailto:das.risk@iowa.gov)

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

### STATE VEHICLE: (Mark if Act of Nature ) CASE #: 2024016076

Date: <small>(Month/Day/Year)</small>	06/27/2024	Time: <small>(Time plus a.m./p.m.)</small>	2:32 AM
Vehicle Plate #:	160	Vehicle Mileage:	32,650
Vehicle Description: <small>(Yr/Make/Model/ &amp; Vin#)</small>	2021 Dodge Charger VIN: 2C3CDXKG3MH644697		
Assigned To:	Nicholas Popp	Badge #	160
Driven By:	Nicholas Popp	Badge #	160
Driver's Lic #:	726AJ7674	Damage:	\$11,691.72
Vehicle Towed: <small>(Yes / No)</small>	Yes	Towed By:	Mid Town
Towed To:	Durant Collision	Towing Cost:	\$495.50
Seat Belt: <small>(Yes / No)</small>	Yes	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Marked
Injured/Injuries:	None		
Occupants: <small>(Other than driver)</small>			

### VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

**OTHER INFORMATION:**

Witnesses:			
Accident Location: (Street/Hwy)	US 61		
County:	Des Moines		
Weather/Road Conditions:	Clear/Dry		
State Vehicle #1 was southbound on Highway 61 in Des Moines County when it struck a deer in the roadway.			
Property Damage other than Vehicles:	None		
Cost:	\$		
Citations Issued To: (List Charge(s) and Statute Code(s))			

Investigating Officer:	Sgt Andreasen #161
------------------------	--------------------

**VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)**

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

### INVESTIGATING OFFICER'S REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement Case Number:

**2024016076**

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Date of Accident <b>06/27/2024</b>	Time of Accident <b>02:32</b> Hrs.	County <b>DES MOINES - 29</b>	Accident occurred within corporate limits of (city)			
Driver's Name - Last <b>POPP</b>		First <b>NICHOLAS</b>		Middle <b>DAVID</b>		
Address <b>22650 20TH AVE</b>		City <b>STOCKTON</b>		State <b>IA</b>	Zip <b>52769-0000</b>	
Date of Birth <b>06/02/1999</b>	Driver's License Number <b>726AJ7674</b>	CDL Yes No <input type="radio"/> <input checked="" type="radio"/>	Citation Charge 1		Citation Charge 2	
Male <input checked="" type="radio"/> Female <input type="radio"/>	State <b>IA</b>	Class <b>C</b>	Endorsements	Restrictions	Citation Charge 3	
Alcohol Test Given: <b>1</b>	Test Results:	Drug Test Given: <b>1</b>	Test Result:	Re-exam: Yes No <input type="radio"/> <input checked="" type="radio"/>	Reason for Re-Exam Request:	
Owner's Name - Last <b>STATE OF IOWA</b>		First		Middle		
Address <b>109 SE 13TH ST</b>		City <b>DES MOINES</b>		State <b>IA</b>	Zip <b>50319-9018</b>	
License Plate No. <b>160</b>	State <b>IA</b>	Year	VIN: <b>2C3CDXKG3MH644697</b>	Color <b>GRY</b>	Year <b>2021</b>	
Trailer Plate No.	State	Year	VIN:	Tow <b>2</b>	Tow #	
Insurance Company Name <b>STATE OF IOWA</b>			Insurance Co. Phone Number	Insurance Policy Number <b>SELF INSURED</b>		
Initial Travel Direction	Veh. Act.	Veh. Config. <b>01</b>	Cargo Body Type <b>01</b>	Veh. Defect	Point of Initial Impact	
Special Veh. Func	Emergency Status	Bus Use	Driver Condition	Vision Obscured	Contributing Circumstances Driver (up to two) <b>88</b>	
Traffic Controls	Horizontal Alignment	Vertical Alignment	SEQUENCE OF EVENTS	First Event	Second Event	
Carrier Name/Lessee			Most Damaged Area			
Street Address			City		State Zip Code	
Number of Axles		Gross Vehicle Weight Rating		US DOT Number	MC Number	
Haz Mat Involvement		Haz Mat Placard	Placard Number	Haz. Mat Released	Haz Mat Class	
Trailer Plate:	State	Year	VIN			
Trailer Plate:	State	Year	VIN			
Converter Dolly	Dolly Plate:	State	Plate Year	VIN		
DRIVER OF UNIT 1			Sex	Seating Position	Injury Status	
			Occupant Protection	Airbag Deployment	Ejection	Ejection Path
Phone Number:			Transported to:		Transported by:	
Name			Phone Number	DOB:		
Address			Transported to:		Transported by:	
Name			Phone Number	DOB:		
Address			Transported to:		Transported by:	
Name			Phone Number	DOB:		
Address			Transported to:		Transported by:	
Name			Phone Number	DOB:		
Address			Transported to:		Transported by:	

INVESTIGATING OFFICER'S REPORT OF MOTOR VEHICLE ACCIDENT

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Law Enforcement Case Number: 2024016076

Accident details including Date of Accident (06/27/2024), Time of Accident (02:32 Hrs.), County (DES MOINES - 29), and Literal Description (SB 23000 BLK US 61).

ACCIDENT ENVIRONMENT and ROADWAY CHARACTERISTICS sections, including location of first harmful event, weather conditions, and roadway features.

First Harmful Event (Crash) details: 31 WORKZONE RELATED? Yes No Activity Location Type Workers Present.

NON-MOTORIST 1: Name 001, Address, Alcohol Test Given, Test Results, Drug Test Given, Result, Charged Yes No.

NON-MOTORIST 2: Name, Address, Alcohol Test Given, Test Results, Drug Test Given, Result, Charged Yes No.

NP OR NOVPEHRITCYULDAMRG: If Property other than vehicles damaged explain, Object Damaged, Estimate of Damage.

Owner's Last Name, First Name, Middle Name, Phone Number, Address, City, State, Zip Code.

Owner's Last Name, First Name, Middle Name, Phone Number, Address, City, State, Zip Code.

Witness 1: Last Name, First Name, Address, City, State, Zip Code, Phone Number.

Witness 2: Last Name, First Name, Address, City, State, Zip Code, Phone Number.

Witness 3: Last Name, First Name, Address, City, State, Zip Code, Phone Number.

Is This a Secondary Crash? Y N, Type of Primary Incident, Roadway Clearance Date (06/27/2024), Incident Clearance Date (06/27/2024).

Signature of Officer (SERGEANT J ANDREASEN), Badge Number (161), Time Officer Notified of Accident (02:32 Hrs.), Roadway Clearance Time (02:54 Hrs.), Incident Clearance Time (02:54 Hrs.).

Name of Agency (IOWA STATE PATROL - DIST 13), Date of Report (06/27/2024), Time Officer Arrived At Scene (02:32 Hrs.), Total Roadway Clearance Time (000:22), Total Incident Clearance Time (000:22).

Report Reviewed By (R DOLF), Date of Review (06/27/2024), Investigation made at scene? Y N, T.I. No., Other Technical Investigating Agency.

INVESTIGATING OFFICER'S REPORT  
OF MOTOR VEHICLE ACCIDENT

Form 4433003 (11-13)

Law Enforcement Case Number:


2024016076

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

D  
I  
A  
G  
R  
A  
M



US 61



N  
A  
R  
R  
A  
T  
I  
V  
E

UNIT 1 WAS SOUTHBOUND AND STRUCK A DEER IN THE ROADWAY.



## MEMORANDUM

**TO:** SGT Helton #118

**FROM:** TRP Popp #160

**DATE:** 06/27/2024

**SUBJECT:** Vehicle Damage

On 06/27/2024 at approx. 0232 hours, I was traveling southbound in the 3200 block of Highway 61, just north of Mediapolis (ISP Case #2024016076) Des Moines County to respond to a T.I. request in Burlington (ISP Case #2024016075). In the area, a deer ran from the east side of the ditch, and onto the roadway directly in front of my squad car causing disabling damage to the front bumper/hood, as well as radiator. Mileage on my vehicle at the time of the accident was 32,650. On call supervisor was contacted and a 10-50 report was done by 161.

Thanks,

Trooper Nicholas Popp #160

# DURANT COLLISION REPAIR

1303 5th St, P O Box 638, DURANT, IA 52747

Phone: (563) 785-6353, Fax: (563) 785-6659

## Image Report

Owner:	Iowa State Patrol	Insurance:		Estimator:	Craig Moeller	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2021	Color:	GRAY	License Plate:	160	Production Date:	9/2021
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	32,650
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG3MH644697	Condition:	Good



6/28/2024  
 Comments:



6/28/2024  
 Comments: RR



6/28/2024  
 Comments: RF



6/28/2024  
 Comments: LF



6/28/2024  
 Comments: LR



6/28/2024  
 Comments: MILEAGE 32,650

# DURANT COLLISION REPAIR

1303 5th St, P O Box 638, DURANT, IA 52747

Phone: (563) 785-6353, Fax: (563) 785-6659

## Image Report

Owner:	Iowa State Patrol	Insurance:		Estimator:	Craig Moeller	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2021	Color:	GRAY	License Plate:	160	Production Date:	9/2021
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	32,650
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG3MH644697	Condition:	Good



6/28/2024

Comments: FRONT



6/28/2024

Comments: RT FENDER




6/28/2024

Comments: RT FENDER



6/28/2024

Comments: RT HEADLAMP



6/28/2024

Comments: LT HEADLAMP



6/28/2024

Comments: FRONT


# DURANT COLLISION REPAIR

1303 5th St, P O Box 638, DURANT, IA 52747

Phone: (563) 785-6353, Fax: (563) 785-6659

## Image Report

Owner:	Iowa State Patrol	Insurance:		Estimator:	Craig Moeller	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2021	Color:	GRAY	License Plate:	160	Production Date:	9/2021
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	32,650
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG3MH644697	Condition:	Good




6/28/2024  
Comments:




6/28/2024  
Comments: HORN RT




6/28/2024  
Comments: HORN LT



6/28/2024  
Comments: HOOD LABEL



6/28/2024  
Comments: HOOD LABEL



6/28/2024  
Comments: HOOD LATCH


# DURANT COLLISION REPAIR

1303 5th St, P O Box 638, DURANT, IA 52747


Phone: (563) 785-6353, Fax: (563) 785-6659

## Image Report


Owner:	Iowa State Patrol	Insurance:		Estimator:	Craig Moeller	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2021	Color:	GRAY	License Plate:	160	Production Date:	9/2021
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	32,650
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG3MH644697	Condition:	Good




6/28/2024  
Comments: HOOD CABLE



6/28/2024  
Comments: AIR CLEANER



6/28/2024  
Comments: AIR CLEANER



6/28/2024  
Comments: AIR CLEANER



6/28/2024  
Comments: HOOD INSULATOR



6/28/2024  
Comments: VINTAG


# DURANT COLLISION REPAIR

1303 5th St, P O Box 638, DURANT, IA 52747


Phone: (563) 785-6353, Fax: (563) 785-6659

## Image Report


Owner:	Iowa State Patrol	Insurance:		Estimator:	Craig Moeller	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2021	Color:	GRAY	License Plate:	160	Production Date:	9/2021
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	32,650
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG3MH644697	Condition:	Good



6/28/2024 E01  
Comments: BRAKE LINES



6/28/2024 E01  
Comments:



6/28/2024 E01  
Comments: REPAIR LT FENDER



**DURANT COLLISION REPAIR**

durantcollision@iowatelecom.net  
1303 5th St, P O Box 638, DURANT, IA 52747  
Phone: (563) 785-6353  
FAX: (563) 785-6659

Workfile ID: 1fce878a  
PartsShare: 82pCLB  
Federal ID: 202958038  
State ID: 116006756

**Preliminary Estimate**

**Customer: Iowa State Patrol**

Written By: Craig Moeller

Insured: Iowa State Patrol  
Type of Loss:  
Point of Impact: 12 Front

Policy #:  
Date of Loss:

Claim #:  
Days to Repair: 0

**Owner:**  
Iowa State Patrol  
22365 20th Ave.  
Stockton, IA 52769  
(563) 284-9501 Day

**Inspection Location:**  
DURANT COLLISION REPAIR  
1303 5th St  
P O Box 638  
DURANT, IA 52747  
Repair Facility  
(563) 785-6353 Business

**Insurance Company:**

**VEHICLE**

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI GRAY

VIN: 2C3CDXKKG3MH644697 Interior Color: Mileage In: 32,650 Vehicle Out:  
License: 160 Exterior Color: GRAY Mileage Out:  
State: IA Production Date: 9/2021 Condition: Good Job #:

**TRANSMISSION**

Automatic Transmission  
4 Wheel Drive

**POWER**

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors  
Power Driver Seat

**DECOR**

Dual Mirrors  
Tinted Glass  
Overhead Console

**CONVENIENCE**

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Keyless Entry  
Message Center  
Steering Wheel Touch Controls  
Telescopic Wheel  
Climate Control  
Backup Camera  
Parking Sensors

**RADIO**

AM Radio  
FM Radio  
Stereo  
Search/Seek  
Auxiliary Audio Connection

**SAFETY**

Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)  
4 Wheel Disc Brakes  
Front Side Impact Air Bags  
Head/Curtain Air Bags  
Hands Free Device

**SEATS**

Cloth Seats  
Bucket Seats  
Reclining/Lounge Seats

**WHEELS**

Styled Steel Wheels

**PAINT**

Clear Coat Paint

**OTHER**

Traction Control  
Stability Control  
California Emissions

Get live updates at [www.carwise.com/e/4PLD55](http://www.carwise.com/e/4PLD55)

**Preliminary Estimate**

**Customer: Iowa State Patrol**

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI GRAY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
<b>1</b>		<b>FRONT BUMPER &amp; GRILLE</b>					
2		O/H front bumper				3.4	
3	* <>	Repl Bumper cover	68267765AC	1	<u>707.38</u>	Incl.	3.4
4		Add for Clear Coat					1.4
5	#	R&I Applique				1.0	
6	#	Refn Black Applique					1.2
7		Repl RT Support inner	68226532AA	1	44.20	Incl.	
8		Repl LT Support inner	68226533AA	1	44.20	Incl.	
9		Repl RT Support outer	68213539AC	1	12.75	Incl.	
10		Repl LT Support outer	68213538AC	1	12.75	Incl.	
11	*	Repl License bracket w/o SRT	68238771AC	1	<u>33.00</u>	0.1	
12	*	Repl Lower grille w/o adaptive cruise	68214782AB	1	<u>106.68</u>	Incl.	
13	*	Repl Closure panel	68226530AF	1	<u>181.20</u>	Incl.	
14	*	Repl Energy absorber	68214783AA	1	<u>98.16</u>	Incl.	
15	*	Repl Impact bar (UHS)	68100209AF	1	<u>340.80</u>	0.7	
16	*	Repl Upper grille black crossbars	5PP33DX8AB	1	<u>361.20</u>	Incl.	
17	#	Repl PB FENER WRAP		1		2.0	
18	#	Repl PB400 PUSH BUMPER		1		2.0	
<b>19</b>		<b>FRONT LAMPS</b>					
20	*	Repl RT Headlamp assy halogen	68546770AC	1	<u>737.00</u>	0.4	
21	*	Repl LT Headlamp assy halogen	68546771AC	1	<u>778.00</u>	0.4	
<b>22</b>		<b>HOOD</b>					
23	*	Repl Hood (ALU)	68265445AB	1	<u>1,080.00</u>	1.5	3.0
24		Overlap Major Non-Adj. Panel					-0.2
25		Add for Clear Coat					0.6
26		Add for Underside(Complete)					1.5
27		Add for Clear Coat					0.3
28		Repl Insulator	68438681AA	1	206.00	Incl.	
<b>29</b>		<b>INFORMATION LABELS</b>					
30		Rpl information labels				0.3	
31		Repl Emission label 3.6 liter all	68495570AA	1	5.35	Incl.	
32		Repl AC label R-134a	68259899AC	1	3.80	Incl.	
<b>33</b>		<b>RADIATOR SUPPORT</b>					
34	*	Repl Radiator support	68200478AC	1	<u>318.00</u>	1.0	1.6
35		Evacuate & recharge				m 1.4	M
36		Refrigerant recovery				m 0.4	M
37		Aim headlamps				0.5	
38		Repl RT Air guide 1-piece guide all	68212036AB	1	35.45	0.1	
39		Repl LT Air guide 1-piece guide all	68212037AB	1	35.45	0.1	
<b>40</b>		<b>COOLING</b>					
41	**	Repl A/M Radiator	68050126AB	1	172.69	m 1.8	M
42		Deduct for Overlap					-0.5 M
43		Repl Upper hose	55038160AE	1	63.35	m 0.5	

**Preliminary Estimate**

**Customer: Iowa State Patrol**

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI GRAY

44		Deduct for Overlap					-0.3	
45	**	Repl A/M Fan Assy	5137714AA	1	199.02	m	0.3	M
46		Repl Thermostat hsng	5184977AH	1	64.25	m	1.0	
47	<b>AIR CONDITIONER &amp; HEATER</b>							
48	**	Repl A/M Condenser assy	68085784AA	1	231.19	m	1.5	M
49		Deduct for Overlap					-1.0	M
50	<b>ELECTRICAL</b>							
51		Repl Low note horn	68238001AC	1	47.40	m	0.2	
52		Repl High note horn	68238002AE	1	46.45	m	0.2	
53	#	Repl Brake Bundle	68235491AC	1	210.00		1.6	M
54	#	Repl Whelan Siren and bracket		1	440.00		1.0	
		Note: SA315P SAK37						
55	<b>ENGINE</b>							
56		Repl Air inlet duct	68413346AA	1	200.00	m	0.3	
57		Repl Air cleaner assy w/police	68413351AB	1	423.00	m	0.5	
58		Repl Shield	5182345AE	1	60.70		0.2	
59	<b>FENDER</b>							
60	*	Rpr LT Fender w/o wide body					2.5	2.0
61		Overlap Major Adj. Panel						-0.4
62		Add for Clear Coat						0.3
63	#	REMOVE "STATE TROOPER" AND REINSTALL AFTER PAINT LT FENDER		1			1.0	
64	*	Rpr RT Fender w/o wide body					4.5	2.0
65		Overlap Major Adj. Panel						-0.4
66	*	Add for Clear Coat						0.3
67	#	REMOVE "STATE TROOPER" AND REINSTALL AFTER PAINT RT FENDER		1			1.0	
68	**	A/M ***** ADD-ONS *****		1				
69	#	Repl Cover Car		1	10.00			
70	#	Rpr Color sand and buff					2.0	
71	#	Repl Corrosion protection primer		1	10.00			
72	<b>VEHICLE DIAGNOSTICS</b>							
73	*	Pre-repair scan		1		m	0.5	M
74	*	Post-repair scan		1		m	0.5	M
<b>SUBTOTALS</b>					<b>7,319.42</b>		<b>34.6</b>	<b>16.6</b>

**Preliminary Estimate**

---

**Customer: Iowa State Patrol**

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI GRAY

**ESTIMATE TOTALS**

<b>Category</b>	<b>Basis</b>	<b>Rate</b>	<b>Cost \$</b>
Parts			7,319.42
Body Labor	28.1 hrs @	\$ 68.00 /hr	1,910.80
Paint Labor	16.6 hrs @	\$ 115.00 /hr	1,909.00
Mechanical Labor	6.5 hrs @	\$ 85.00 /hr	552.50
Subtotal			11,691.72
<b>Grand Total</b>			<b>11,691.72</b>
Deductible			0.00
<b>CUSTOMER PAY</b>			<b>0.00</b>
<b>INSURANCE PAY</b>			<b>11,691.72</b>

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

## Preliminary Estimate

### Customer: Iowa State Patrol

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI GRAY

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 06/17/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

#### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

#### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

#### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

**Preliminary Estimate**

**Customer: Iowa State Patrol**

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI GRAY

**PARTS SUPPLIER LIST**

<b>Line</b>	<b>Supplier</b>	<b>Description</b>	<b>Price</b>
3	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68267765AC Bumper cover Quote: 2446257786 Expires: 07/27/24	\$ 707.38
11	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68238771AC License bracket w/o SRT Quote: 2442961959 Expires: 07/27/24	\$ 33.00
12	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68214782AB Lower grille w/o adaptive cruise Quote: 2446356102 Expires: 07/27/24	\$ 106.68
13	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68226530AF Closure panel Quote: 2443258437 Expires: 07/27/24	\$ 181.20
14	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68214783AA Energy absorber Quote: 2445658458 Expires: 07/27/24	\$ 98.16
15	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68100209AF Impact bar (UHS) Quote: 2445658486 Expires: 07/27/24	\$ 340.80
16	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#5PP33DX8AB Upper grille black crossbars Quote: 2442160110 Expires: 07/27/24	\$ 361.20
20	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68546770AC RT Headlamp assy halogen Quote: 2444858597 Expires: 07/27/24	\$ 737.00
21	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68546771AC LT Headlamp assy halogen Quote: 2441560216 Expires: 07/27/24	\$ 778.00

## Preliminary Estimate

### Customer: Iowa State Patrol

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI GRAY

23	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68265445AB Hood (ALU) Quote: 2445057633 Expires: 07/27/24	\$ 1,080.00
34	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68200478AC Radiator support Quote: 2445263485 Expires: 07/27/24	\$ 318.00
41	Keystone, Inc 4725 44TH STREET MOLINE IL 61265 (309) 517-2450	#RAD13157 A/M Radiator Quote: 2562843318 Expires: 08/13/24	\$ 172.69
45	Keystone, Inc 4725 44TH STREET MOLINE IL 61265 (309) 517-2450	#CH3115184 A/M Fan Assy Quote: 2562903205 Expires: 08/13/24	\$ 199.02
48	Keystone, Inc 4725 44TH STREET MOLINE IL 61265 (309) 517-2450	#CND3948 A/M Condenser assy Quote: 2562844107 Expires: 08/13/24	\$ 231.19

**Preliminary Estimate**

**Customer: Iowa State Patrol**

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI GRAY

**ALTERNATE PARTS USAGE**

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI GRAY

VIN: 2C3CDXKG3MH644697 Interior Color: Mileage In: 32,650 Vehicle Out:  
License: 160 Exterior Color: GRAY Mileage Out:  
State: IA Production Date: 9/2021 Condition: Good Job #:

<b>Alternate Part Type</b>	<b>Selection Method</b>	<b># Of Times Notified Of Available Parts</b>	<b># Of Parts Selected</b>
Aftermarket	Automatically List	3	4
Optional OEM	Automatically List	0	0
Reconditioned	Automatically List	0	0
Recycled	N/A	0	0

# MIDTOWN TOWING & REPAIR

1516 Isett Ave.  
 MUSCATINE, IA 52761  
 Phone (563) 264-2231  
 FAX # (563) 264-2171

## TOWING REPORT

Name: <i>Iowa State Patrol</i>		Date: <i>6-27-24</i>	Time: <i>3:00 AM</i>
Address:		City:	State:
Home Phone:	Insurance Company:	Insurance Phone:	
Alternate Phone:	Year: <i>21</i>	Make: <i>Dodge</i>	Model: <i>Charger</i>
License: <i>160</i>	VIN: <i>2C3CD8K63MN649697</i>		
Odometer: <i>32,650</i>	ADDRESS TOWED FROM: <i>US-61 MediaPolis</i>		
PURCHASE ORDER NO.	ADDRESS TOWED TO: <i>Durant Collision</i>		
STORAGE IN DATE	2ND TOW:		
STORAGE OUT DATE			
TOTAL DAYS STORED			
MILEAGE FINISH			
MILEAGE START			
MILEAGE TOTAL			
REMARKS: <i>LEAD #375</i>	<input type="checkbox"/> START <input type="checkbox"/> BATTERY <input type="checkbox"/> FLAT TIRE <input type="checkbox"/> GAS <input type="checkbox"/> LOCKOUT <input checked="" type="checkbox"/> WRECK <input checked="" type="checkbox"/> TOW <input type="checkbox"/> CARRIER <input checked="" type="checkbox"/> FLAT BED <input type="checkbox"/> INSURED		
RECEIVED DISTRICT 12 JUN 27 2024 By: <i>JW</i>		TOWING CHARGE: <i>Accident</i> SERVICE CHARGE: STORAGE CHARGE:	
<input type="checkbox"/> VISA <input type="checkbox"/> MC <input type="checkbox"/> AMX <input type="checkbox"/> DISCOVER		321.00 174.50 495.50	