

MEMBERS OF COUNCIL

HON. KIM REYNOLDS
GOVERNOR

HON. PAUL D. PATE
SECRETARY OF STATE

HON. ROB SAND
AUDITOR OF STATE

HON. ROBY SMITH
TREASURER OF STATE

HON. MIKE. NAIG
SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING
DES MOINES, IOWA 50319
PHONE: 515 281-5368

December 2, 2024

Accounting Department
Office of the Treasurer
Lucas Building
321 E 12th Street
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$8,499.79, subject to an audit of actual invoices. On September 8, 2024, Vehicle #330 was damaged by a deer. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Kristi Onstot

Kristi Onstot
Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services
DAS Fleet Services, Risk
Matt Bender, Department of Management
Heather Hackbarth, Department of Management

AOS Claim # 3906
TOS Job # _____



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

Rob Sand
Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

November 4, 2024

Kristi Onstot
Executive Council
L O C A L

Subject: Deer Damage to Vehicle #330 on September 8, 2024
Department of Administrative Services
Claim dated September 11, 2024
AOS Claim ID: 3906

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. The Department requested an allocation of \$9,094.78; however, the estimate from the vendor includes sales tax of \$594.99. This amount will be deducted from the Department's request. Therefore, we recommend an Executive Council allocation in the amount of \$8,499.79, subject to an audit of actual invoices.

Sincerely,

A handwritten signature in black ink, appearing to read "Brian R. Brustkern".

Brian R. Brustkern, CPA
Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



Department of Administrative Services

KIM REYNOLDS, GOVERNOR

ADAM STEEN, DIRECTOR

Date: September 11, 2024

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Table with 2 columns: Field Name, Value. Rows include Vehicle / Event (#330/Deer), Event Date (September 11, 2024), Summary (Vehicle 330 struck a deer. (289502)), Amount Requested (\$9,094.78 - Estimate), and Supporting Documentation (29C20 Email Notification, Accident Report, Repair Estimate(s), Photos).

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Handwritten signature of Mariah Fucaloro

Mariah Fucaloro, Fleet Manager
DAS Fleet Services
mariah.fucaloro@iowa.gov
515-414-6582



Risk, DAS <das.risk@iowa.gov>

Fwd: Trooper Foley #330 vehicle damage

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Sep 9, 2024 at 2:35 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS Executive Council <executivecouncil@tos.iowa.gov>, Jeannie R Adams <jadams@dps.state.ia.us>

Please accept this email as initial 24 hr notification for AON, vehicle 330 struck a deer on 9/8/2024. I will forward all information as soon as it is received.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

109 SE 13th St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov<https://das.iowa.gov>

----- Forwarded message -----

From: **Dolf Ryan** <dolf@dps.state.ia.us>

Date: Mon, Sep 9, 2024 at 9:20 AM

Subject: Trooper Foley #330 vehicle damage

To: vehicledamage <vehicledamage@dps.state.ia.us>, das.risk@iowa.gov <das.risk@iowa.gov>

Cc: J alas Dean <jalas@dps.state.ia.us>, Morey Russell <morey@dps.state.ia.us>, Andreasen Jeremy <andrease@dps.state.ia.us>

Trooper Foley received substantial vehicle damage from striking a deer last night. An estimate and required paperwork will be forthcoming.

Sergeant Ryan Dolf ★361★

Iowa State Patrol | District 13

Iowa Department of Public Safety

1300 S Grand Avenue, Suite #201

Mount Pleasant, Iowa 52641

Office: 319-385-8715

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

*****Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!**

STATE VEHICLE: (Mark if Act of Nature) CASE #: 2024022789

Date: <small>(Month/Day/Year)</small>	09/08/24	Time: <small>(Time plus a.m./p.m.)</small>	11:43PM
Vehicle Plate #:	330	Vehicle Mileage:	114854
Vehicle Description: <small>(Yr/Make/Model/ & Vin#)</small>	Silver 2020 Dodge Charger VIN: 2C3CDXKTXLH127523		
Assigned To:	Dakota Foley	Badge #	330
Driven By:	Dakota Foley	Badge #	330
Driver's Lic #:	721AJ0293	Damage:	\$Pending
Vehicle Towed: <small>(Yes / No)</small>	Yes	Towed By:	Rairden's Towing
Towed To:	ABRA Ft. Madison	Towing Cost:	\$Pending
Seat Belt: <small>(Yes / No)</small>	Yes	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Marked
Injured/Injuries:	None		
Occupants: <small>(Other than driver)</small>			

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			

Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:		Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

OTHER INFORMATION:

Witnesses:			
Accident Location: (Street/Hwy)	NB Hwy 61 Bypass MM2		
County:	Lee County		
Weather/Road Conditions:	Clear/Dry		
<p>On 09/08/24 at approximately 11:43 PM, I was responding to an active domestic abuse assault at Casey's General Store (3530 Main St., Keokuk, IA) traveling northbound HWY 61 Bypass 2mm with my emergency lights activated when a deer ran out into the roadway. I was unable to avoid striking the deer as the deer ran out into my lane of traffic. The deer struck my vehicle's push bar, rolled onto my hood, and struck my windshield. The deer then deflected off my windshield and launched approximately 30 feet in front of my vehicle and onto the west roadway should where I pronounced it deceased. The deer caused heavy damage to my push bar, front bumper, hood, radiator/engine compartment, and front passenger quarter panel, which disabled my vehicle.</p>			
Property Damage other than Vehicles:	None		
Cost:	\$		
Citations Issued To: (List Charge(s) and Statute Code(s))			

Investigating Officer:	Trp. Riley
------------------------	------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			

Driver's Address:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

INVESTIGATING OFFICER'S REPORT OF MOTOR VEHICLE ACCIDENT

Form Number:
2024022789

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Date of Accident 09/08/2024	Time of Accident 23:41 Hrs.	County LEE - 56	Accident occurred within corporate limits of (city) KEOKUK - 3942																		
U N I T 1	Driver's Name - Last FOLEY			First DAKOTA			Middle														
	Address 1300 S GRAND AVE STE 201			City MT PLEASANT			State IA	Zip 52641													
	Date of Birth 04/01/1992		Driver's License Number 721AJ0293		CDL	Citation Charge 1		Citation Charge 2													
	Male <input checked="" type="radio"/>	Female <input type="radio"/>	State IA	Class D	Endorsements 3	Restrictions	Citation Charge 3		Citation Charge 4												
	Alcohol Test Given: 1		Test Results:		Drug Test Given: 1	Test Result:	Re-exam: Yes <input type="radio"/> No <input checked="" type="radio"/>	Reason for Re-Exam Request:													
	Owner's Name - Last STATE OF IOWA			First			Middle														
	Address 1300 S GRAND AVE STE 201			City MT PLEASANT			State IA	Zip 52641													
	License Plate No. 330	State IA	Year 2024	VIN: 2C3CDXKTXLH127523			Color SIL	Year 2020	Make DODG	Model CHARGER	Style 4D										
	Trailer Plate No.	State	Year	VIN:			Tow 3	Tow #	Towed To JIM BAIER BY RAIDEN	Approx. Cost to Repair or Replace \$8,000.00											
	Insurance Company Name STATE OF IOWA				Insurance Co. Phone Number		Insurance Policy Number														
Initial Travel Direction	Veh. Act.	Veh. Config. 01	Cargo Body Type 01	Veh. Defect	Point of Initial Impact	Most Damaged Area	Extent of Damage	Total Occ. in Veh. 1													
Special Veh. Func.	Emergency Status	Bus Use	Driver Condition	Vision Obscured	Contributing Circumstances Driver (up to two) 88		Driver Distractions 02	Speed Limit													
Traffic Controls	Horizontal Alignment	Vertical Alignment	SEQUENCE OF EVENTS	First Event 31	Second Event	Third Event	Fourth Event	Most Harmful Event 31													
C O M M E R C I A L	Carrier Name/Lessee																				
	Street Address					City			State	Zip Code											
	Number of Axles		Gross Vehicle Weight Rating			US DOT Number		MC Number	Override/Override												
	Haz Mat Involvement		Haz Mat Placard	Placard Number	Haz. Mat Released	Haz Mat Class	Haz Mat Name														
	Trailer Plate:		State	Year	VIN																
	Trailer Plate:		State	Year	VIN																
	Converter Dolly		Dolly Plate:		State	Plate Year	VIN														
P E R S O N S I N J U R E D	DRIVER OF UNIT 1			Phone Number:		Injury Status		Occupant Protection		Airbag Deployment		Ejection		Ejection Path		Trapped/extricated		Source of Transport		Disposal/scene/route	
				Transported to:		Transported by:		01													
	Name			Phone Number			DOB:														
	Address			Transported to:			Transported by:														
	Name			Phone Number			DOB:														
	Address			Transported to:			Transported by:														
	Name			Phone Number			DOB:														
	Address			Transported to:			Transported by:														
	Name			Phone Number			DOB:														
	Address			Transported to:			Transported by:														

INVESTIGATING OFFICER'S REPORT OF MOTOR VEHICLE ACCIDENT

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Form Number: 2024022789

LOCATION: Date of Accident 09/08/2024, Time of Accident 23:41 Hrs., County LEE - 56, Accident occurred within corporate limits of (city) KEOKUK - 3942. Literal Description: US 61 N/JOHNSON ST RD. X Coordinate: 633521.187, Y Coordinate: 4474484.

ACCIDENT ENVIRONMENT: Location of First Harmful Event, Weather Conditions (up to two) 01, Manner of Crash/Collision 01, Light Conditions, Surface Conditions. ROADWAY CHARACTERISTICS: Major Contributing Circumstances Environment 06, Roadway, Type of Roadway Junction/Feature, FRA No.

First Harmful Event (Crash) 31, WORKZONE RELATED? Yes No, Activity, Location, Type, Workers Present. Includes checkboxes for Sex, Struck by Unit No., Injury Status, Non-Motorist Type, Location (prior to impact), Action (prior to crash), Condition, Safety Equipment, Contributing Circumstances, Source of Transport, and District/scene/route.

NONMOTORISTS: Name 001, Phone Number, DOB, Address, Alcohol Test Given, Test Results, Drug Test Given, Result, Charged Yes No. Includes fields for transported to and by.

NP OR NO VP: If Property other than vehicles damaged explain, Object Damaged, Estimate of Damage. Owner's Last Name, First Name, Middle Name, Phone Number, Address, City, State, Zip Code, Was owner or tenant notified? 1 = Yes 2 = No 9 = Unknown.

ITCY: If Property other than vehicles damaged explain, Object Damaged, Estimate of Damage. Owner's Last Name, First Name, Middle Name, Phone Number, Address, City, State, Zip Code, Was owner or tenant notified? 1 = Yes 2 = No 9 = Unknown.

WITNESSES: Last Name, First Name, Address, City, State, Zip Code, Phone Number. Includes five witness rows.

Is This a Secondary Crash? Y N, Type of Primary Incident, Roadway Clearance Date 09/09/2024, Incident Clearance Date 09/09/2024. Signature of Officer TROOPER J RILEY, Badge Number 429, Time Officer Notified of Accident 23:41 Hrs., Roadway Clearance Time 00:15 Hrs., Incident Clearance Time 00:15 Hrs. Name of Agency IOWA STATE PATROL - DIST 13, Date of Report 09/09/2024, Time Officer Arrived At Scene 23:50 Hrs., Total Roadway Clearance Time 000:34, Total Incident Clearance Time 000:34. Report Reviewed By D JALAS, Date of Review 09/10/2024, Investigation made at scene? Y N, T.I. No., Other Technical Investigating Agency.

INVESTIGATING OFFICER'S REPORT
OF MOTOR VEHICLE ACCIDENT


Form 4433003 (11-13)

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Form Number: 2024022789

D
I
A
G
R
A
M

Johnson St Rd



US 61 bypass

N
A
R
R
A
T
I
V
E

Unit one was traveling northbound on US 61 near Johnson St Rd when a deer entered the roadway and struck unit 1.



MEMORANDUM

TO: Sgt. Ryan Dolf #361

FROM: Trooper Dakota Foley #330

DATE: 09/10/24

SUBJECT: Unit #330 Vehicle Damage

On 09/08/24 at approximately 11:43 PM, I was responding to an active domestic abuse assault at Casey's General Store (3530 Main St., Keokuk, IA) traveling northbound HWY 61 Bypass 2mm with my emergency lights activated when a deer ran out into the roadway. I was unable to avoid striking the deer as the deer ran out into my lane of traffic. The deer struck my vehicle's push bar, rolled onto my hood, and struck my windshield. The deer then deflected off my windshield and launched approximately 30 feet in front of my vehicle and onto the west roadway should where I pronounced it deceased. The deer caused heavy damage to my push bar, front bumper, hood, radiator/engine compartment, and front passenger quarter panel, which disabled my vehicle.

Case #: 2024022789

Vehicle Information: Silver 2020 Dodge Charger (VIN: 2C3CDXKTXLH127523)

Mileage: 114854

Sincerely,

Trooper Dakota Foley #330



Abra - Jim Baier Fort Madison

5701 Avenue O, Fort Madison, IA 52627
Phone: (319) 372-8120

Workfile ID: b0261c5c
Federal ID: 420982103
State ID: 1-56-007451
Federal EPA: NED9817236513
State EPA: NED9817236513

Preliminary Estimate

Customer: IOWA STATE PATROL

Written By: Marcus Garcia

Insured: IOWA STATE PATROL
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
IOWA STATE PATROL
(319) 396-4414 Cell

Inspection Location:
Abra - Jim Baier Fort Madison
5701 Avenue O
Fort Madison, IA 52627
Repair Facility
(319) 372-8120 Business

Insurance Company:
CUSTOMER PAY

VEHICLE

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Silver

VIN: 2C3CDXKTXLH127523
License: 330
State: IA

Interior Color:
Exterior Color: Silver
Production Date: 1/2020

Mileage In: 114,854
Mileage Out:
Condition:
Vehicle Out:
Job #:

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera
Parking Sensors

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection
SAFETY
Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions

Preliminary Estimate

Customer: IOWA STATE PATROL

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Silver

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER & GRILLE					
2		O/H front bumper		0	0.00	3.4	0.0
3	** <>	Repl A/M CAPA Bumper cover	68267765AC	1	675.00	Incl.	3.4
4		Add for Clear Coat		0	0.00	0.0	1.4
5	**	Repl A/M CAPA Lower grille w/o adaptive cruise	68214782AB	1	101.00	Incl.	0.0
6	**	Repl A/M CAPA Upper grille black crossbars	5PP33DX8AB	1	369.00	Incl.	0.0
7		Repl Nameplate "DODGE" black	68227437AA	1	107.00	0.1	0.0
8	**	Repl A/M CAPA Closure panel	68226530AF	1	181.00	Incl.	0.0
9	**	Repl A/M BRUSH GUARD		1	0.00	2.5	0.0
10	#	R&I POLICE LIGHTS		0	0.00	2.0	0.0
11		FRONT LAMPS					
12	**	Repl A/M CAPA RT Headlamp assy halogen	68541680AA	1	702.00	0.4	0.0
13		Aim headlamps		0	0.00	0.5	0.0
14	**	Repl A/M CAPA LT Headlamp assy halogen	68541681AA	1	802.00	0.4	0.0
15		RADIATOR SUPPORT					
16	**	Repl A/M CAPA Radiator support	68200478AC	1	333.00	1.0	1.6
17		Evacuate & recharge		0	0.00 m	1.4 M	0.0
18		Refrigerant recovery		0	0.00 m	0.4 M	0.0
19		COOLING					
20	**	Repl A/M Shroud	68050294AC	1	199.18 m	0.6	0.0
21		AIR CONDITIONER & HEATER					
22	**	Repl A/M Condenser assy	68085784AA	1	231.41 m	1.5	0.0
23		HOOD					
24	**	Repl A/M CAPA Hood (ALU)	68265445AB	1	1,085.00	1.5	3.0
25		Overlap Major Non-Adj. Panel		0	0.00	0.0	-0.2
26		Add for Clear Coat		0	0.00	0.0	0.6
27		Add for Underside(Complete)		0	0.00	0.0	1.5
28		Repl Latch w/o remote start	55113787AB	1	125.00	0.4	0.0
29		Repl Insulator retainer	4878883AA	9	61.20	0.0	0.0
30		FENDER					
31		R&I RT R&I fender assy		0	0.00	1.5	0.0
32	*	Rpr LT Fender w/o wide body		0	0.00	2.5	2.0
33		Overlap Major Adj. Panel		0	0.00	0.0	-0.4
34		Add for Clear Coat		0	0.00	0.0	0.3
35		R&I RT Fender liner 3.6, 5.7 liter		0	0.00	0.3	0.0
36		R&I LT Fender liner 3.6, 5.7 liter		0	0.00	0.3	0.0
37		ENGINE					
38	*	Repl LKQ Air cleaner assy w/police +25%	68413349AB	1	325.00 m	0.5	0.0
39	#	Hazardous waste removal		1	5.00	0.0	0.0

Preliminary Estimate

Customer: IOWA STATE PATROL

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Silver

40	#	Repl	Cover Car	1	5.00	0.0	0.0
41	#	Repl	Corrosion Protection	1	5.00	0.0	0.0
42	#		UNSEEN DAMAGE OPEN, PENDING TEARDOWN	1	0.00	0.0	0.0
SUBTOTALS					5,311.79	21.2	13.2

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			5,311.79
Body Labor	19.4 hrs @	\$ 70.00 /hr	1,358.00
Paint Labor	13.2 hrs @	\$ 70.00 /hr	924.00
Mechanical Labor	1.8 hrs @	\$ 100.00 /hr	180.00
Paint Supplies	13.2 hrs @	\$ 55.00 /hr	726.00
Subtotal			8,499.79
Sales Tax	\$ 8,499.79 @	7.0000 %	594.99
Grand Total			9,094.78

THE ABOVE IS AN ESTIMATE BASED ON OUR INSPECTION AND DOES NOT COVER ANY ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK HAS BEEN OPENED UP. THERE IS A LIMITED LIFETIME GUARANTEE ON WORKMANSHIP AND REFINISHING.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Customer: IOWA STATE PATROL

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Silver

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 09/04/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: IOWA STATE PATROL

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Silver

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
3	Keystone, Inc 110 THUNDERBIRD LANE EAST PEORIA IL 61611 (309) 698-0700	#CH1000A24PP A/M CAPA Bumper cover Quote: 2652749132 Expires: 10/26/24	\$ 675.00
5	Keystone, Inc 110 THUNDERBIRD LANE EAST PEORIA IL 61611 (309) 698-0700	#CH1036140C A/M CAPA Lower grille w/o adaptive cruise Quote: 2652753423 Expires: 10/26/24	\$ 101.00
6	Keystone, Inc 110 THUNDERBIRD LANE EAST PEORIA IL 61611 (309) 698-0700	#CH1200388C A/M CAPA Upper grille black crossbars Quote: 2652754123 Expires: 10/26/24	\$ 369.00
8	Keystone, Inc 110 THUNDERBIRD LANE EAST PEORIA IL 61611 (309) 698-0700	#CH1224101C A/M CAPA Closure panel Quote: 2652758014 Expires: 10/26/24	\$ 181.00
12	Keystone, Inc 110 THUNDERBIRD LANE EAST PEORIA IL 61611 (309) 698-0700	#CH2503337C A/M CAPA RT Headlamp assy halogen Quote: 2652750453 Expires: 10/26/24	\$ 702.00
14	Keystone, Inc 110 THUNDERBIRD LANE EAST PEORIA IL 61611 (309) 698-0700	#CH2502337C A/M CAPA LT Headlamp assy halogen Quote: 2652751177 Expires: 10/26/24	\$ 802.00
16	Keystone, Inc 110 THUNDERBIRD LANE EAST PEORIA IL 61611 (309) 698-0700	#CH1225280PP A/M CAPA Radiator support Quote: 2652756627 Expires: 10/26/24	\$ 333.00
20	Keystone, Inc 110 THUNDERBIRD LANE EAST PEORIA IL 61611 (309) 698-0700	#CH3115184 A/M Shroud Quote: 2652776822 Expires: 10/26/24	\$ 199.18
22	Keystone, Inc 110 THUNDERBIRD LANE EAST PEORIA IL 61611 (309) 698-0700	#CND3948 A/M Condenser assy Quote: 2652775627 Expires: 10/26/24	\$ 231.41

Preliminary Estimate

Customer: IOWA STATE PATROL

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Silver

24	Keystone, Inc 110 THUNDERBIRD LANE EAST PEORIA IL 61611 (309) 698-0700	#CH1230305PP A/M CAPA Hood (ALU) Quote: 2652764727 Expires: 10/26/24	\$ 1,085.00
<hr/>			
38	LKQ Corp 2101 Beloit Avenue Janesville WI 53546 (800) 362-9451	#~384723809 LKQ Air cleaner assy w/police +25% Air Cleaner 5.7,AUTO,RWD 5.7L,S#\$K0785 Quote: 2652797830 Expires: 10/26/24	\$ 260.00