

MEMBERS OF COUNCIL

HON. KIM REYNOLDS
GOVERNOR

HON. PAUL D. PATE
SECRETARY OF STATE

HON. ROB SAND
AUDITOR OF STATE

HON. ROBY SMITH
TREASURER OF STATE

HON. MIKE. NAIG
SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING
DES MOINES, IOWA 50319
PHONE: 515 281-5368

November 4, 2024

Accounting Department
Office of the Treasurer
Lucas Building
321 E 12th Street
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for a supplemental emergency allocation in the amount of \$1,228.65, which brings the total allocation to \$8,804.45. On July 5, 2024, Vehicle #465 was damaged by a deer. Request was to cover repair costs.

This represents full and final payment and this allocation will be closed.

EXECUTIVE COUNCIL OF IOWA

A handwritten signature in cursive script that reads "Kristi Onstot".

Kristi Onstot
Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services
DAS Fleet Services, Risk
Matt Bender, Department of Management
Heather Hackbarth, Department of Management

AOS Claim # 3870
TOS Job # _____



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

Rob Sand
Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

October 10, 2024

Kristi Onstot
Executive Council
L O C A L

Subject: Deer Damage to Vehicle #465 on July 5, 2024
Department of Administrative Services
Claim dated July 8, 2024
AOS Claim ID: 3870

The Department's request included a supplemental allocation request of \$1,228.65 because additional damages were identified. We recommend Executive Council approval of the supplemental allocation of \$1,228.65, which increases the allocation to \$8,804.45. In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to this loss. We have found the items to be in order as shown below:


Documented request			<u>\$ 8,804.45</u>
Executive Council allocation (Revised)			\$ 8,804.45
Less:			
Previous payments	\$	0.00	
This payment		<u>8,804.45</u>	
Total			<u>\$ 8,804.45</u>
Remaining Executive Council allocation			<u>\$ 0.00</u>

We recommend that reimbursement be made in the amount of \$8,804.45. This represents full and final payment on this allocation.

Sincerely,

Brian R. Brustkern, CPA
Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: August 28, 2024

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Fucaloro, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: REIMBURSEMENT REQUEST - 29C20 Claim

AOS Claim #	3870
Vehicle / Event	#465/Deer
Event Date	July 5, 2024
Summary	Vehicle 465 struck a deer. (284570)
Amount Requested	\$8,804.45 - Total

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: **0665-005-5790-0657**.

If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,

Mariah Fucaloro, Fleet Manager
DAS Fleet Services
mariah.fucaloro@iowa.gov
515-414-6582

Warrants

Edit

Cancel

* Required fields

Warrant Information

Fiscal Year 2025	Amount \$8,804.45	Warrant Number 86305826
Vendor Customer 00002088178	Line Number 1	Last Updated 08/08/2024 09:55 PM

Issue Information

Issued 08/05/2024 12:00 AM	Void No	Transaction ID RISK00525205001A
Duplicate No	Transaction Line Number 1	Stop No
Line Amount \$1,696.00	Comments	

Redeemed Information

Redeemed 08/08/2024 12:00 AM	Batch Number 0992	Redeemed Bank 0022
Sequence Number 00001	Redeemed Fund 0665	Redeemed Department 005

COA

Fund 0665	Object 2715	Dept Object -
Sub Fund -	Sub Object -	Dept Revenue -
Department 005	Unit 5790	Sub Unit -
Object Class -	Revenue Source -	Sub Revenue Source -
Appropriation 0000	Revenue Source Class -	BSA -
Sub BSA -		

Show More

Bodensteiner Body Werks

24 1st Avenue NE
Waukon, IA 52172

Invoice


Date	Invoice #
7/19/2024	2829

Bill To
Iowa State Patrol

P.O. No.	Terms	Project
465		

Description	Qty	Rate	Amount
repairs on car 465 as per estimate claim #apds010284570-001		8.804.45	8.804.45T

Subtotal	\$8.804.45
Sales Tax	\$0.00
Total	\$8.804.45
Payments/Credits	\$0.00
Balance Due	\$8.804.45



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

Rob Sand
Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

August 5, 2024

Kristi Onstot
Executive Council
L O C A L

Subject: Deer Damage to Vehicle #465 on July 5, 2024
Department of Administrative Services
Claim dated July 8, 2024
AOS Claim ID: 3870

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$7,575.80 subject to an audit of actual invoices.

Sincerely,

A handwritten signature in black ink, appearing to read "Brian R. Brustkern".

Brian R. Brustkern, CPA
Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: July 8, 2024

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Karl Bubser, Fleet Administrator
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#465/Animal
Event Date	July 5, 2024
Summary	Vehicle 465 struck a deer. (284570)
Amount Requested	\$7,575.80 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Karl Bubser, Fleet Administrator
DAS Fleet Services
Karl.Bubser@iowa.gov
515-281-3162



29C20

Risk, DAS <das.risk@iowa.gov>

Mon, Jul 8, 2024 at 8:30 AM

Draft To: TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>, Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 465 struck a deer on 7/5/24. I will forward all information as soon as it is received.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

109 SE 13th St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov

<https://das.iowa.gov>



Department of
Administrative Services

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: *DPS – Vehicle Damage; DAS – Risk*

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #: 2024016857

Date: <small>(Month/Day/Year)</small>	7/5/24	Time: <small>(Time plus a.m./p.m.)</small>	9:53 p.m.
Vehicle Plate #:	465	Vehicle Mileage:	13,465
Vehicle Description: <small>(Yr/Make/Model/ & Vin#)</small>	2022 Dodge Charger VIN: 2c3cdxkg9nh256360		
Assigned To:	Teague	Badge #	465
Driven By:	Teague	Badge #	465
Driver's Lic #:	458AF3501	Damage:	\$
Vehicle Towed: <small>(Yes / No)</small>	Yes	Towed By:	
Towed To:		Towing Cost:	\$
Seat Belt: <small>(Yes / No)</small>	Yes	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Marked
Injured/Injuries:			
Occupants: <small>(Other than driver)</small>			

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			

Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

OTHER INFORMATION:

Witnesses:			
Accident Location: (Street/Hwy)	Hwy 76 / Jefferson Road		
County:	Allamakee		
Weather/Road Conditions:	Clear / Normal		
Narrative: Trooper Teague was traveling northwest on Highway 76 west Jefferson Road when he came in contact with a deer causing damage to his driver's side headlight, driver door, and his driver's side window won't roll up.			
Property Damage other than Vehicles:			
Cost:	\$		
Citations Issued To: (List Charge(s) and Statute Code(s))			

Investigating Officer:	
------------------------	--

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

MEMORANDUM

TO: Sgt. Burns #28
FROM: Joe Teague
DATE: 7-5-24
SUBJECT: Squad vs. Deer Hwy 76

- Case # 2024016857
- Date / Time of collision: Approximately 21:51 hours on 7-5-2024
- Mileage: 13465
- Veh year / Make / VIN #: 2022/DODGE CHARGER/2c3cdxkg9nh256360
- Location of collision: West of Jefferson Rd on hwy 76. Traveling north bound on hwy 76.
- #465 DL #: 458af3501

I was patrolling westbound on 76 just west of Jefferson rd. A deer came from the south ditch, and I struck the deer with the front left portion of my guard rail. The deer caused damage to the side of my door and front left portion of the squad car. The headlight is cracked, and traction control service light came on upon traveling for the accident report. The driver side window doesn't roll up. The vehicle functions fine outside of the above listed items.

**INVESTIGATING OFFICER'S REPORT
OF MOTOR VEHICLE ACCIDENT**

Law Enforcement Case Number:

2024016857

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Date of Accident 07/05/2024		Time of Accident 21:51 Hrs.		County ALLAMAKEE - 03		Accident occurred within corporate limits of (city)									
UNIT	Driver's Name - Last TEAGUE					First JOSEPH			Middle						
	Address 114 DORCHESTER DRIVE					City DORCHESTER			State IA	Zip 52140					
	Date of Birth 04/15/1996		Driver's License Number 458AF3501		CDL Yes <input type="radio"/> No <input checked="" type="radio"/>	Citation Charge 1		Citation Charge 2							
	Male <input checked="" type="radio"/> Female <input type="radio"/>	State IA	Class C	Endorsements	Restrictions	Citation Charge 3		Citation Charge 4							
	Alcohol Test Given: 1		Test Results:		Drug Test Given: 1	Test Result:	Re-exam: Yes <input type="radio"/> No <input checked="" type="radio"/>	Reason for Re-Exam Request:							
	Owner's Name - Last STATE OF IOWA					First			Middle						
	Address 109 SE 13TH ST					City DES MOINES			State IA	Zip 50319					
	License Plate No. 465	State IA	Year 2099	VIN: 2C3CDXKKG9NH256360		Color SIL	Year 2022	Make DODG	Model CHARGER POLI	Style SD					
	Trailer Plate No.	State	Year	VIN:		Tow 1	Tow #	Towed To	Approx. Cost to Repair or Replace \$4,500.00						
	Insurance Company Name STATE OF IOWA					Insurance Co. Phone Number		Insurance Policy Number							
Initial Travel Direction	Veh. Act.	Veh. Config. 01	Cargo Body Type 01	Veh. Defect	Point of Initial Impact	Most Damaged Area	Extent of Damage	Total Occ. in Veh. 1							
Special Veh. Func.	Emergency Status	Bus Use	Driver Condition	Vision Obscured	Contributing Circumstances Driver (up to two) 88		Driver Distractions 02	Speed Limit							
Traffic Controls	Horizontal Alignment	Vertical Alignment	SEQUENCE OF EVENTS	First Event	Second Event	Third Event	Fourth Event	Most Harmful Event							
COMMERCIAL	Carrier Name/Lessee														
	Street Address					City			State	Zip Code					
	Number of Axles		Gross Vehicle Weight Rating			US DOT Number		MC Number		Underride/Override					
	Haz Mat Involvement	Haz Mat Placard	Placard Number	Haz. Mat Released	Haz Mat Class	Haz Mat Name									
	Trailer Plate:	State	Year	VIN											
	Trailer Plate:	State	Year	VIN											
	Converter Dolly	Dolly Plate:	State	Plate Year	VIN										
PERSONNEL INJURED	DRIVER OF UNIT 1					Sex	Seating Position	Injury Status	Occupant Protection	Airbag Deployment	Ejection	Ejection Path	Trapped/extracted	Source of Transport	Disabilities/Impairments
	Phone Number:					Transported to:	Transported by:								
	Name				Phone Number		DOB:								
	Address					Transported to:			Transported by:						
	Name				Phone Number		DOB:								
	Address					Transported to:			Transported by:						
	Name				Phone Number		DOB:								
	Address					Transported to:			Transported by:						
	Name				Phone Number		DOB:								
	Address					Transported to:			Transported by:						

INVESTIGATING OFFICER'S REPORT OF MOTOR VEHICLE ACCIDENT

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Law Enforcement Case Number: 2024016857

LOCATIONS: Date of Accident 07/05/2024, Time of Accident 21:51 Hrs., County ALLAMAKEE - 03, Accident occurred within corporate limits of (city) IA 76 N 3915 FEET WEST OF JEFFERSON RD, Legal Intervention? Private Property? County: 03, Route: X Coordinate: 627582.437, Y Coordinate: 4785196

ACCIDENT ENVIRONMENT: Location of First Harmful Event, Weather Conditions, Manner of Crash/Collision, Light Conditions, ROADWAY CHARACTERISTICS: Major Contributing Circumstances Environment, Roadway, Type of Roadway Junction/Feature, FRA No.

First Harmful Event (Crash) 31, WORKZONE RELATED?, Yes No, Activity, Location, Type, Workers Present

NONMOTORISTS: Name 001, Phone Number, DOB, Sex, Struck by Unit No., Injury Status, Non-Motorist Type, Location (prior to impact), Action (prior to crash), Condition, Safety Equipment, Contributing Circumstances, Source of Transport, Location (scene/route)

Address, Alcohol Test Given, Test Results, Drug Test Given, Result, Charged Yes No

Transported to, Transported by

Name, Phone Number, DOB, Sex, Struck by Unit No., Injury Status, Non-Motorist Type, Location (prior to impact), Action (prior to crash), Condition, Safety Equipment, Contributing Circumstances, Source of Transport, Location (scene/route)

Address, Alcohol Test Given, Test Results, Drug Test Given, Result, Charged Yes No

Transported to, Transported by

NP: If Property other than vehicles damaged explain, Object Damaged, Estimate of Damage

Owner's Last Name, First Name, Middle Name, Phone Number

Address, City, State, Zip Code, Was owner or tenant notified? 1 = Yes 2 = No 9 = Unknown

NP: If Property other than vehicles damaged explain, Object Damaged, Estimate of Damage

Owner's Last Name, First Name, Middle Name, Phone Number

Address, City, State, Zip Code, Was owner or tenant notified? 1 = Yes 2 = No 9 = Unknown

WITNESSES: Last Name, First Name, Address, City, State, Zip Code, Phone Number

Last Name, First Name, Address, City, State, Zip Code, Phone Number

Last Name, First Name, Address, City, State, Zip Code, Phone Number

Last Name, First Name, Address, City, State, Zip Code, Phone Number

Last Name, First Name, Address, City, State, Zip Code, Phone Number

Is This a Secondary Crash? Y N, Type of Primary Incident, Roadway Clearance Date 07/05/2024, Incident Clearance Date 07/05/2024

Signature of Officer SERGEANT R BURNS, Badge Number 028, Time Officer Notified of Accident 21:51 Hrs., Roadway Clearance Time 21:53 Hrs., Incident Clearance Time 21:53 Hrs.

Name of Agency IOWA STATE PATROL - DIST 10, Date of Report 07/05/2024, Time Officer Arrived At Scene 21:52 Hrs., Total Roadway Clearance Time 000:02, Total Incident Clearance Time 000:02

Report Reviewed By, Date of Review, Investigation made at scene? Y N, T.I. No., Other Technical Investigating Agency

INVESTIGATING OFFICER'S REPORT
OF MOTOR VEHICLE ACCIDENT


Form 4433003 (11-13)

Law Enforcement Case Number:

2024016857


MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

D
I
A
G
R
A
M



N
A
R
R
A
T
I
V
E

Unit One was westbound on Highway 76 when it came in contact with a deer causing damage to a headlight and passenger side door.





BODENSTEINER BODY WERKS

24 - 1ST AVENUE NE, bodiebmb@rconnect.com, WAUKON, IA 52172

Phone: (563) 568-2046, Fax: (563) 568-2237


Image Report

Owner:	iowa state patrol	Insurance:		Estimator:	Brian Bodensteiner	Vehicle Out:	
Job Number:		Claim Number:					
Year:	2022	Color:		License Plate:		Production Date:	
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG9NH256360	Condition:	



7/6/2024
Comments:

7/6/2024
Comments:



7/6/2024
Comments:

7/6/2024
Comments:



7/6/2024
Comments:

7/6/2024
Comments:


BODENSTEINER BODY WERKS

24 - 1ST AVENUE NE, bodiebmb@rconnect.com, WAUKON, IA 52172


Phone: (563) 568-2046, Fax: (563) 568-2237

Image Report


Owner:	iowa state patrol	Insurance:		Estimator:	Brian Bodensteiner	Vehicle Out:	
Job Number:		Claim Number:					
Year:	2022	Color:		License Plate:		Production Date:	
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG9NH256360	Condition:	




7/6/2024
Comments:



7/6/2024
Comments:



7/6/2024
Comments:



7/6/2024
Comments:



7/6/2024
Comments:



7/6/2024
Comments:

BODENSTEINER BODY WERKS

24 - 1ST AVENUE NE, bodiebmb@rconnect.com, WAUKON, IA 52172


Phone: (563) 568-2046, Fax: (563) 568-2237

Image Report


Owner:	iowa state patrol	Insurance:		Estimator:	Brian Bodensteiner	Vehicle Out:	
Job Number:		Claim Number:					
Year:	2022	Color:		License Plate:		Production Date:	
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG9NH256360	Condition:	



7/6/2024
Comments:



7/6/2024
Comments:



7/6/2024
Comments:



7/6/2024
Comments:



7/6/2024
Comments:



7/6/2024
Comments:


BODENSTEINER BODY WERKS

24 - 1ST AVENUE NE, bodiebmb@rconnect.com, WAUKON, IA 52172


Phone: (563) 568-2046, Fax: (563) 568-2237

Image Report


Owner:	iowa state patrol	Insurance:		Estimator:	Brian Bodensteiner	Vehicle Out:	
Job Number:		Claim Number:					
Year:	2022	Color:		License Plate:		Production Date:	
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG9NH256360	Condition:	



7/6/2024
Comments:



7/6/2024
Comments:



7/6/2024
Comments:

BODENSTEINER BODY WERKS



Lifetime Warrentee Collision Repairs
 24 - 1ST AVENUE NE, bodiebmb@rconnect.com,
 WAUKON, IA 52172
 Phone: (563) 568-2046
 FAX: (563) 568-2237

Workfile ID: 78ed8fe3
 PartsShare: 82TNJy
 Federal ID: 03-0442-700
 State ID: 1-03-004954

Preliminary Estimate

Customer: iowa state patrol 465

Job Number:

Written By: Brian Bodensteiner

Insured: iowa state patrol 465
 Type of Loss:
 Point of Impact:

Policy #:
 Date of Loss:

Claim #:
 Days to Repair: 0

Owner:
 iowa state patrol 465
 (515) 320-3149 Business

Inspection Location:
 BODENSTEINER BODY WERKS
 24 - 1ST AVENUE NE
 bodiebmb@rconnect.com
 WAUKON, IA 52172
 Repair Facility
 (563) 568-2046 Business

Insurance Company:

VEHICLE

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

VIN: 2C3CDXKG9NH256360
 License:
 State: IA

Interior Color:
 Exterior Color:
 Production Date:

Mileage In:
 Mileage Out:
 Condition:

Vehicle Out:
 Job #:

TRANSMISSION

Automatic Transmission
 4 Wheel Drive

POWER

Power Steering
 Power Brakes
 Power Windows
 Power Locks
 Power Mirrors
 Power Driver Seat

DECOR

Dual Mirrors
 Tinted Glass
 Overhead Console

CONVENIENCE

Air Conditioning
 Intermittent Wipers
 Tilt Wheel
 Cruise Control
 Rear Defogger
 Keyless Entry
 Message Center
 Steering Wheel Touch Controls
 Telescopic Wheel

RADIO

Climate Control
 Backup Camera
 Parking Sensors

AM Radio

FM Radio
 Stereo
 Search/Seek
 Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
 Passenger Air Bag
 Anti-Lock Brakes (4)
 4 Wheel Disc Brakes
 Front Side Impact Air Bags
 Head/Curtain Air Bags
 Hands Free Device

SEATS

Cloth Seats
 Bucket Seats
 Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
 Stability Control
 California Emissions

Preliminary Estimate

Customer: iowa state patrol 465

Job Number:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER & GRILLE					
2	R&I	R&I bumper cover				1.9	
3	*	Rpr Bumper cover				<u>2.0</u>	3.4
4		Add for Clear Coat					1.4
5	*	R&I Lower grille w/o adaptive cruise				<u>0.3</u>	
6	R&I	License bracket w/o SRT				0.1	
7	R&I	Upper grille black crossbars				0.7	
8		FRONT LAMPS					
9	Repl	LT Headlamp assy halogen	68546771AC	1	930.00	0.4	
10		HOOD					
11	**	Repl A/M CAPA Hood (ALU)	68265445AB	1	1,085.00	1.5	3.0
12		Add for Clear Coat					1.2
13		Add for Underside(Complete)					1.5
14		FENDER					
15	Repl	LT Fender w/o wide body	68213061AC	1	458.00	1.6	2.0
16		Overlap Major Adj. Panel					-0.4
17		Add for Clear Coat					0.3
18		Add for Edging					0.5
19	*	Blnd RT Fender w/o wide body					<u>1.0</u>
20		FRONT DOOR					
21	Repl	LT Door shell (HSS)	68268055AC	1	1,230.00	5.7	3.1
22		Overlap Major Adj. Panel					-0.4
23		Add for Clear Coat					0.5
24	R&I	LT Applique				Incl.	
25	R&I	LT Frame molding				0.3	
26	*	R&I LT Power mirror				<u>Incl.</u>	
27	R&I	LT Door glass Dodge				Incl.	
28	R&I	LT Window regulator				Incl.	
29	*	R&I LT Run channel				<u>Incl.</u>	
30	R&I	LT Mount plate				Incl.	
31	R&I	LT Handle, outside black				Incl.	
32	R&I	LT R&I trim panel				Incl.	
33		REAR DOOR					
34	*	Rpr LT Outer panel w/o wide body (HSS)				<u>2.0</u>	2.0
35		Overlap Major Adj. Panel					-0.4
36		Add for Clear Coat					0.3
37	R&I	LT Belt w/strip				0.3	
38	R&I	LT Handle, outside black				0.4	
39	R&I	LT R&I trim panel				0.5	
40	#	R&I push bumper				2.5	
41		VEHICLE DIAGNOSTICS					
42	*	Subl Pre-repair scan		1	<u>128.00</u> X m		

Preliminary Estimate

Customer: iowa state patrol 465

Job Number:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

43	*	Subl	Post-repair scan	1	X m		
44	#	Repl	and fender decals	1		1.5	
SUBTOTALS				3,831.00		21.7	19.0

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			3,703.00
Body Labor	21.7 hrs @	\$ 64.00 /hr	1,388.80
Paint Labor	19.0 hrs @	\$ 124.00 /hr	2,356.00
Miscellaneous			128.00
Subtotal			7,575.80
Grand Total			7,575.80
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			7,575.80

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Preliminary Estimate

Customer: iowa state patrol 465

Job Number:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 07/01/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: iowa state patrol 465

Job Number:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
11	Keystone, Inc 2400 KERPER BLVD., SUITE E100A DUBUQUE IA 52001 (563) 556-5030	#CH1230305PP A/M CAPA Hood (ALU) Quote: 2570255004 Expires: 08/22/24	\$ 1,085.00