MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE

SEAL SEAL STATE OF 10

# Executive Council of Jowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

January 6, 2025

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$16,433.01, subject to an audit of actual invoices. On October 11, 2024, Vehicle #440 was damaged by a deer. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

(risti Onstot

Kristi Onstot

**Executive Secretary** 

cc: Adam Steen, Director, Department of Administrative Services

DAS Fleet Services, Risk

Matt Bender, Department of Management

Heather Hackbarth, Department of Management

# OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

November 26, 2024

Kristi Onstot Executive Council L O C A L

Subject: Deer Damage to Vehicle #440 on October 11, 2024

Department of Administrative Services

Claim dated October 25, 2024

AOS Claim ID: 3926

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$16,433.01, subject to an audit of <u>actual</u> invoices.

Sincerely,

Brian R. Brustkern, CPA

Phi R. Br.

Deputy Auditor of State

CC: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



KIM REYNOLDS, GOVERNOR

ADAM STEEN, DIRECTOR

Date: October 25, 2024

Tammy Hollingsworth, Auditor of State To:

Victoria Newton, Treasurer of State

**Executive Council** 

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#440 / Animal
Event Date	October 11, 2024
Summary	Vehicle 440 - struck a deer. (292129)
Amount Requested	\$16,433.01 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s)

If you have any questions or are in need of additional information, please do not hesitate to contact me.


Ryan Betts

**DAS Fleet Services** 

ryan.betts@iowa.gov

515-281-8008





Risk, DAS <das.risk@iowa.gov>

Fwd: 440 car v deer

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Oct 14, 2024 at 12:17 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hour notification for AON, vehicle 440 struck a deer on 10/11/24.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

#### **DAS Risk**

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

109 SE 13<sup>th</sup> St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov

https://das.iowa.gov



----- Forwarded message -----

From: Andreasen Jeremy <andrease@dps.state.ia.us>

Date: Sat, Oct 12, 2024 at 8:10 PM

Subject: 440 car v deer

To: vehicledamage <vehicledamage@dps.state.ia.us>, das.risk@iowa.gov <das.risk@iowa.gov>

Cc: Jalas Dean <jalas@dps.state.ia.us>, Morey Russell <morey@dps.state.ia.us>, Dolf Ryan <dolf@dps.state.ia.us>

Attached are the documents related to a patrol car v. deer collision that occurred last night. The patrol car is at Copeland's Auto Body and we will send the estimate as soon as we receive it.

#### Sergeant Jeremy Andreasen ★161★

Iowa State Patrol | District 13

Iowa Department of Public Safety

1300 S. Grand Avenue | Mount Pleasant, Iowa 52641

Office: 319-385-8715

Fax: 319-385-2743

andrease@dps.state.ia.us

https://dps.iowa.gov/

https://dpscareers.com/



\*NOTICE\* This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

#### 8 attachments



**IMG\_5880.jpeg** 2710K



**IMG\_5881.jpeg** 2014K



**IMG\_5885.jpeg** 2396K



IMG\_5878.jpeg 1748K



IMG\_5879.jpeg 2902K



**440 State Vehicle Damage Rpt Oct 11.doc** 103K



 $\begin{array}{l} \textbf{MARS\_Unit\_Report-2024025585.pdf} \\ 140 \textbf{K} \end{array}$ 



Car deer memo 10-11-2024.doc 51K

# **State Vehicle Damage Report**

Attach this completed form to an email along with the items identified below and send to: <a href="mailto:vehicledamage@dps.state.ia.us">vehicledamage@dps.state.ia.us</a>; <a href="mailto:das.risk@jowa.gov">das.risk@jowa.gov</a>

- One Repair Estimate from Approved State Bid Shop
- > DOT MARS Report (if reportable)
- > Memo from the Driver of the State Vehicle
- > 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature ≥ ) CASE #: 2024025585

STATE VEHICLE	⊏. (n	iark ii Act oi	nature ) CASE #:	<b>ZUZ4UZ</b> 3383
Date:	10/1	1/24	Time:	8:59PM
(Month/Day/Year)			(Time plus a.m./p.m.)	
Vehicle Plate #:	440		Vehicle Mileage:	35,895
Vehicle Description: (Yr/Make/Model/ & Vin#)		2 Dodge Char 2C3CDXKG8	•	
Assigned To:	Jare	d Gringer	Badge #	440
Driven By:	Jare	d Gringer	Badge #	440
Driver's Lic #:	607	AH9294	Damage:	\$
Vehicle Towed: No			Towed By:	
Towed To:			Towing Cost:	\$
Seat Belt: (Yes / No)	Yes		Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:		None		
Occupants: (Other than driver)				

# **VEHICLE #2:**

DL #:	State:	
Vehicle Lic. #	State:	
Driver's Name:		
Driver's Address:		
Owner's Name:		
Owner's Address:		

Owner's Phone:				
Insurance Info:				
(Carrier/Policy #/Phone)				
Veh Description:				
(Yr/Make/Model & Vin#)				
Damage:	\$		Seat Belt: (Yes / No)	
Injured/Injuries:				
Occupants:				
(Other than driver)				
Occupant(s) Weari	ng Seat B	elt: (Yes/No	o)	
OTHER INFORMA	TION:			
Witnesses:				
Accident Location:		US 63 @	24 mm	
(Street/Hwy)				
County:		Davis		
Weather/Road Con	iditions:	Clear/Dr	У	
Property Damage o	other than	None		
Vehicles:		¢.		
Cost: Citations Issued To		\$		
Citations issued To (List Charge(s) and Statute	-			
(Liet enarge(e) and etatate	, , , , , , , , , , , , , , , , , , , ,			
Investigating Office	r:		David Wall #353	3
VEHICLE #3: (If ne	eded) (F	or more	vehicles, pleas	e make extra copies
this portion) `				
DL #:			State:	
Vehicle Lic. #			State:	
Driver's Name.				·
Driver's Name: Driver's Address:				

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Weari	ng Seat Belt: (Yes/	(No) Yes	

# **QUALITY CLAIMS SOLUTIONS**

105 N Krohn Place SIOUX FALLS, SD 57103 Phone: (877) 237-3727, FAX:(605) 800-8591

qcs@qcsdirect.com

For:

# **QUALITY CLAIMS SOLUTIONS**

Creative Risk Solutions

**Estimate of Record** 

**Owner: IOWA, STATE OF** Job Number:

Written By: Julian Martinez

UNK

Insured: IOWA, STATE OF

Collision

Point of Impact: 01 Right Front

Date of Loss:

Policy #:

10/18/2024 12:00 PM

Claim #:

APDSOI0292129-001

Workfile ID:

7a716f69

Days to Repair:

Repair Facility:

Owner:

IOWA, STATE OF 109 SE 13TH ST

Type of Loss:

DES MOINES, IA 50319

**Inspection Location:** 

COPELAND AUTO BODY INC.

506 E 2ND STREET

HEDRICK, IA 52563

Other

(641) 653-2140 Evening

**VEHICLE** 

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

VIN:

2C3CDXKG8NH256365

Production Date:

Interior Color:

License:

Odometer:

35,918

Exterior Color:

State:

Condition:

**TRANSMISSION** 

Automatic Transmission

4 Wheel Drive

**POWER** 

Power Steering

Power Brakes

Power Windows Power Locks

Power Mirrors

Power Driver Seat

**DECOR** 

**Dual Mirrors** Tinted Glass

Overhead Console

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Message Center

Steering Wheel Touch Controls Telescopic Wheel

Climate Control

Backup Camera Parking Sensors

**RADIO** 

AM Radio

FM Radio Stereo

Search/Seek

Auxiliary Audio Connection

**SAFETY** 

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4) 4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags Hands Free Device

**SEATS** 

Cloth Seats

**Bucket Seats** 

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

**PAINT** 

Clear Coat Paint

**OTHER** 

Traction Control Stability Control

California Emissions

# **Owner: IOWA, STATE OF**

Job Number:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUM	PER & G	RILLE					
2	#	Repl	Push bumper- subject to invoice		1	1.00	2.0	
3			O/H front bumper				3.4	
4	<>	Repl	Bumper cover	68267765AC	1	1,010.00	Incl.	3.4
5		Repl	RT Support outer	68213539AC	1	12.75	Incl.	
6		Repl	RT Support inner	68226532AA	1	44.20	Incl.	
7	FRONT LAM	PS						
8	*	Repl	RT Headlamp assy halogen	68546770AC	1	737.00	0.4	
9	RADIATOR S	SUPPORT						
10	*	Repl	Radiator support	68200478AC	1	442.00	1.0	0.0
11	HOOD							
12	*	Blnd	Hood (ALU)					<u>1.5</u>
13	FENDER							
14		Repl	RT Fender w/o wide body	68213060AC	1	458.00	1.6	2.0
15			Overlap Major Non-Adj. Panel					-0.2
16			Add for Edging					0.5
17			Add for Clear Coat					0.1
18	RESTRAINT	SYSTEM	S					,
19		Repl	RT Head air bag	68222742AG	1	941.00 m	0.8 M	
20			Air bag system diagnosis			m	0.5 M	
21		Repl	RT Retractor assy black	1HZ06DX9AI	1	436.00	0.7	
22		Repl	RT Side impact sens front door	68284054AA	1	15.00 m	0.2 M	
23		Repl	LT Retractor assy black	1HZ05DX9AI	1	426.00	0.7	
24		Repl	LT Buckle end black	6MS011X9AA	1	295.00	0.2	
25		Repl	LT Adjuster	68080745AD	1	73.45	0.2	
26		Repl	RT Ft seat air bag	5108076AF	1	831.00 m	0.3 M	
27		Repl	Control module w/police	68371749AA	1	480.00 m	0.6 M	
28		Repl	RT Ft impact sensor	68284054AA	1	15.00 m	0.3 M	
29		Repl	RT Head air bag support	68044050AC	1	79.15		
30		Repl	RT Buckle end black	6MS001X9AA	1	313.00	0.2	
31		Repl	RT Adjuster	68080745AD	1	73.45	0.2	
32	SEATS & TR	ACKS						
33		Repl	Seat back frame driver seat w/8 way power	68593541AA	1	988.00	1.6	
34		Repl	Seat back panel passenger seat black	1UY02DX9AC	1	376.00	Incl.	
35		Repl	RT Seat back pad w/o heated seat code D7, S7 or W7	68110560AB	1	226.00	Incl.	
36		Repl	RT Seat back cover black code BB	5SZ22DX9AB	1	707.00	Incl.	
37		Repl	RT Side trim panel w/o memory pkg	68103691AA	1	49.75		
38	#	Repl	SAB Jumper wire harness		1	31.46	0.2 M	
39		R&I	RT R&I front seat				0.5	

	er: IOWA, STA			L'-LMDT			Job Nu	ımber:
40	ROOF	AWD	(Fleet) 4D SED 6-3.6L Gasoline Sec	quential MPI				
41		Repl	Headliner w/o sunroof w/storage tray	7KW90DX9AB	1	1,365.00	3.9	
42	PILLARS, ROCK	FR &						
43			RT W/S pillar trim w/police	5LN24DX9AF	1	89.85	Incl.	
44		Repl		1KL28DX9AI	1	313.00	Incl.	
45	FRONT DOOR				-	313.00	THEIL	
46		Repl	RT Door shell (HSS)	68268054AC	1	1,020.00	5.7	3.1
47			Overlap Major Adj. Panel	0020003 1/10		1,020100	3.7	-0.4
48	# F	Repl			1	15.00		011
49	REAR DOOR				-	13100		
50		Rpr	RT Outer panel w/o wide body (HSS)				<u>1.0</u>	2.0
51			Overlap Major Adj. Panel					-0.4
52			Clear Coat					2.5
53		R&I	RT Belt w'strip				0.3	
54		R&I	RT Handle, outside destroyer				0.4	
			gray					
55		R&I	RT R&I trim panel				0.5	
56	QUARTER PANE	L						
57	F	Repl	RT Upper qtr trim	1KL82DX9AD	1	142.00	Incl.	
58	VEHICLE DIAGN	IOST:	ICS					
59	* F	Repl	Pre-repair scan		1	<u>60.00</u> m	<u>0.5</u> M	
60	* F	Repl	Post-repair scan		1	<u>129.95</u> m	<u>0.5</u> M	
61	#		Disarm airbags		1		0.1	
62	#		D&R battery		1		0.1	
63	#		Memory Function resets		1		0.1	
64	#		Hazardous Waste		1	3.00 X		
65	#		Cover Car		1	5.00	0.2	
66	#		Corrosion Protection		1	5.00	0.1	
67	#		Flex Agent		1	5.00		
68	#		Seam selaer		1	25.00		
69	#		Test drive to verify ADAS functions		1		0.5	
				SUBTOTALS		12,239.01	29.5	14.1

**Owner: IOWA, STATE OF** 

Job Number:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

#### **ESTIMATE TOTALS**

Category	Basis		Rate	Cost \$
Parts				12,236.01
Body Labor	25.6 hrs	@	\$ 75.00 /hr	1,920.00
Paint Labor	14.1 hrs	@	\$ 135.00 /hr	1,903.50
Mechanical Labor	3.9 hrs	@	\$ 95.00 /hr	370.50
Miscellaneous				3.00
Subtotal				16,433.01
Total Cost of Repairs				16,433.01
Deductible				0.00
Total Adjustments				0.00
Net Cost of Repairs				16,433.01

## THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.

Owner: IOWA, STATE OF Job Number:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 10/17/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

#### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

# SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

#### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.

D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.