



Governor Kim Reynolds  
Lt. Governor Adam Gregg  
Adam Steen, Director

Date: October 5, 2021

To: Tammy Hollingsworth, Auditor of State  
Victoria Newton, Treasurer of State  
Executive Council

From: Mariah Flowers, Fleet Manager  
DAS Fleet Services  
Department of Administrative Services

**Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration**

Vehicle / Event	# 2213 & 105974/Derecho
Event Date	August 10, 2020
Summary	Vehicles 2213 & 105974 sustained damage from Derecho. (211001, 211009)
Amount Requested	\$5,897.17 - Estimate \$ 70.00 - Review Invoice <b>\$5,967.17 - Total</b>
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager  
DAS Fleet Services  
[Mariah.Flowers@iowa.gov](mailto:Mariah.Flowers@iowa.gov)  
515-725-2243



Risk, DAS &lt;das.risk@iowa.gov&gt;

**Storm Damage 8/10/2020**

1 message

2213, 1105974  
211007, 211009

Risk, DAS &lt;das.risk@iowa.gov&gt;

Tue, Aug 18, 2020 at 10:01 AM

To: Tammy Hollingsworth &lt;Tammy.Hollingsworth@aos.iowa.gov&gt;, TOS ExecutiveCouncil &lt;executivecouncil@tos.iowa.gov&gt;

We just received 5 more reports of damage from the 8/10/2020 storm. Can I send those for 29c20 reimbursement still?

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

**DAS Fleet Services**

Phone: (515) 281-3162

FAX: (515) 281-6370

<http://das.iowa.gov>

BE GREEN -- Please consider the environment before printing this e-mail.

## Vehicle Accident Report

### Time and location of accident

Accident Date (Mo/Day/Year)	Time	No. of Vehicles
Monday, August 10, 2020	1:00 p.m.	1
County	State	
Linn	Iowa	


### Vehicle 1 (State vehicle)

Driver's Name		Work Street Address	
N/A		1240 26th Ave. Ct. SW	
Driver's License No./State		City, State, Zip	
N/A		Cedar Rapids, IA 52404	
Date of Birth	Department	Work Phone	Home Phone
N/A	DHS	319-892-6800	
License Plate No.	VIN	Year, Make, Model	
2213	1G11Z5S34LU104592	2020 Chevy Impala	
Estimate (\$) of Damage		Description of Damage	
		Derecho	

### Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

Driver's Name		Street Address	
Driver's License No./State		City, State, Zip	
Date of Birth	Work Phone	Home Phone	License Plate No.
Description of Damage			

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
Vehicle No. 2/ Name and Address	Describe Injuries
Witness	
Name	Address/Phone
Name	Address/Phone

Accident Diagram	
<p><b>Complete diagram below, include a description of what happened.</b>            Use the outline below to sketch the scene of your accident,            writing in street or highway names or numbers.            Use number 1 to indicate the State vehicle.</p>	
	<p>This car was park in the parking lot at            1240 26th Ave. Ct. SW, Cedar Rapids,            Iowa 52404 during the time of Derecho</p>

**QUALITY CLAIMS SOLUTIONS**

7405 S Bitterroot Pl. Suite 100  
SIOUX FALLS, SD 57108  
Phone: (877) 237-3727, FAX:(866) 371-2844  
qcs@qcsdirect.com

Workfile ID:

77ba86f4

For:

**QUALITY CLAIMS SOLUTIONS**

DAS Fleet Services  
Phone: (877) 544-7843

**Estimate of Record****Owner: STATE OF IOWA DEPT. OF HUMAN SERVIC****Job Number:**

Written By: Dennis Jorgensen, NY-6FH6  
Adjuster: Mike, Long, (877) 544-7843 Business

Insured: STATE OF IOWA DEPT. OF HUMAN SERVIC Policy #: UNKNOWN Claim #: APDSOI0211001-001V1  
Type of Loss: Collision Date of Loss: 10/12/2020 12:00 PM Days to Repair: 0  
Point of Impact: 09 Left T-Bone (Left Side)

**Owner:**

STATE OF IOWA DEPT. OF HUMAN  
SERVIC  
CEDAR RAPIDS, IA 52404

**Inspection Location:**

5 SEASONS AUTO REBUILDERS  
  
5913 16TH AVE SW  
CEDAR RAPIDS, IA 62404  
Other  
(319) 396-8683 Evening

**Repair Facility:****VEHICLE**

2020 CHEV Impala LT1 4D SED 6-3.6L Flex Fuel Direct Injection

VIN: 1G11Z5S34LU104592 Production Date: Interior Color:  
License: Odometer: 0 Exterior Color:  
State: Condition:

**TRANSMISSION**

Automatic Transmission  
Overdrive

**POWER**

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors  
Heated Mirrors  
Power Driver Seat

**DECOR**

Dual Mirrors

**CONVENIENCE**

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Keyless Entry  
Alarm  
Message Center  
Steering Wheel Touch Controls  
Telescopic Wheel  
Climate Control  
Remote Starter

**RADIO**

AM Radio  
FM Radio  
Stereo  
Search/Seek  
Auxiliary Audio Connection  
Premium Radio  
Satellite Radio  
**SAFETY**  
Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)  
4 Wheel Disc Brakes

Communications System  
Hands Free Device

**SEATS**

Cloth Seats  
Bucket Seats

**WHEELS**

Aluminum/Alloy Wheels

**PAINT**

Clear Coat Paint

**OTHER**

Traction Control  
Stability Control  
Signal Integrated Mirrors

## Estimate of Record

---

**Owner: STATE OF IOWA DEPT. OF HUMAN SERVIC**

**Job Number:**

2020 CHEV Impala LT1 4D SED 6-3.6L Flex Fuel Direct Injection

Console/Storage

Backup Camera

Front Side Impact Air Bags

Power Trunk/Gate Release

# Estimate of Record

Owner: STATE OF IOWA DEPT. OF HUMAN SERVIC

Job Number:

2020 CHEV Impala LT1 4D SED 6-3.6L Flex Fuel Direct Injection

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		<b>FRONT BUMPER &amp; GRILLE</b>					
2	R&I	R&I bumper cover				1.7	
3		<b>FRONT LAMPS</b>					
4	R&I	LT R&I headlamp assy				0.3	
5		<b>FENDER</b>					
6	*	Rpr LT Fender				<u>4.0</u>	2.2
7		Add for Clear Coat					0.9
8	R&I	LT Fender liner				0.4	
9		<b>WHEELS</b>					
10	Repl	LT/Rear Wheel, alloy 18" code: RT4	84507698	1	433.50 m	0.3	
11		<b>FRONT DOOR</b>					
12	*	Rpr LT Door shell w/o molding				<u>4.0</u>	2.0
13		Overlap Major Non-Adj. Panel					-0.2
14		Add for Clear Coat					0.4
15	R&I	LT Belt molding				0.3	
16	Repl	LT Nameplate "IMPALA"	84445338	1	44.10	0.3	
17	R&I	LT R&I mirror				0.3	
18	R&I	LT Handle, outside w/passive entry w/o chrome				0.4	
19	R&I	LT R&I trim panel				0.5	
20		<b>REAR DOOR</b>					
21	*	Rpr LT Door shell w/o molding				<u>2.0</u>	2.0
22		Overlap Major Non-Adj. Panel					-0.2
23		Add for Clear Coat					0.4
24	R&I	LT Belt molding				0.3	
25	R&I	LT Handle, outside w/o chrome w/passive				0.4	
26	R&I	LT R&I trim panel				0.5	
27		<b>QUARTER PANEL</b>					
28	*	Rpr LT Quarter panel				<u>4.0</u>	2.6
29		Overlap Major Adj. Panel					-0.4
30		Add for Clear Coat					0.4
31	R&I	LT Wheelhouse liner				0.4	
32	*	R&I LT Emblem				<u>0.2</u>	
33	R&I	LT Quarter glass GM all				1.4	
34		<b>REAR LAMPS</b>					
35	R&I	LT Tail lamp assy				0.3	
36		<b>REAR BUMPER</b>					
37	R&I	R&I bumper cover				1.6	
38	#	Hazardous Waste		1	3.00		
39	#	Cover Car		1	5.00	0.2	
40	#	Corrosion Protection		1	5.00	0.1	

## Estimate of Record

Owner: **STATE OF IOWA DEPT. OF HUMAN SERVIC**

Job Number:

2020 CHEV Impala LT1 4D SED 6-3.6L Flex Fuel Direct Injection

41	#	Tire Mount/ Balance	1	15.00		
<b>SUBTOTALS</b>				<b>505.60</b>	<b>23.9</b>	<b>10.1</b>

### ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				505.60
Body Labor	23.9 hrs	@	\$ 65.00 /hr	1,553.50
Paint Labor	10.1 hrs	@	\$ 105.00 /hr	1,060.50
Subtotal				3,119.60
<b>Total Cost of Repairs</b>				<b>3,119.60</b>
Deductible				0.00
<b>Total Adjustments</b>				<b>0.00</b>
<b>Net Cost of Repairs</b>				<b>3,119.60</b>

**MyPriceLink Estimate ID / Quote ID:**

745259866410459136 / 74916920

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.





1815 16th Ave. S.W.  
Cedar Rapids, Iowa 52404  
Phone (319) 364-BODY

# PAINTING-FRAME & UNIBODY-INSURANCE WORK

CUSTOMER'S ORDER NO.		PHONE		DATE	
3263				12/10/20	
NAME State of IA. DHS					
ADDRESS					
SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	PAID OUT
QTY.	DESCRIPTION			PRICE	AMOUNT
	2020 Chev. Impala				
	<del>Paint &amp; Materials</del>				
	PARTS (Prices Subject To Invoice)				
	Services	Hrs @	Hr.		
	Sublet Or Painting				
	Sub Total			505 60	505 60
	Paint-Matrl-Hdw			1553 50	1553 50
				1060 50	1060 50
RECEIVED BY				TAX	Exempt
				TOTAL	319 60

G-1000000-010 All claims and returned goods must be accompanied by this bill.

4469

Thank You



Quality Claims Solutions

## Quality Claims Solutions

7405 S. Bitterroot Pl. #100  
Sioux Falls, SD 57108  
Phone: 877.237.3727  
Fax: 866.371.2844  
Federal Tax ID: 46-0461202

**INVOICE =**

Attention/Adjuster: Mike Long  
Company Name: DAS Fleet Services  
Address: 109 SE 13th St  
Des Moines, IA 503190000

Invoice No: APDSOI0211001-001V1  
Date: 10/13/2020 2:42:52PM  
Customer ID: IWAA  
Claim Number: APDSOI0211001-001V1  
Vehicle Owner: STATE OF IOWA DEPT. OF HUM

Quantity	Description	Unit Price	Extended Amou
1.00	Technical Estimate Review	\$ 35.00	\$ 35.00

**Item Total:** \$ 35.00

**Sales Tax:** N/A

**Invoice Total:** \$ 35.00

***Your Solution for Today's Claims***

[www.qcsdirect.com](http://www.qcsdirect.com)

## Vehicle Accident Report

### Time and location of accident

Accident Date (Mo/Day/Year)	Time	No. of Vehicles
Monday, August 10, 2020	1:00 p.m.	1
County	State	
Linn	Iowa	


### Vehicle 1 (State vehicle)

Driver's Name		Work Street Address	
N/A		1240 26th Ave. Ct. SW	
Driver's License No./State		City, State, Zip	
N/A		Cedar Rapids, IA 52404	
Date of Birth	Department	Work Phone	Home Phone
N/A	DHS	319-892-6800	
License Plate No.	VIN	Year, Make, Model	
105974	1FAHP2D877GG113669	2016 Chevy Impala	
Estimate (\$) of Damage		Description of Damage	
		Derecho	

### Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

Driver's Name		Street Address	
Driver's License No./State		City, State, Zip	
Date of Birth	Work Phone	Home Phone	License Plate No.
Description of Damage			

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
Vehicle No. 2/ Name and Address	Describe Injuries
Witness	
Name	Address/Phone
Name	Address/Phone

Accident Diagram	
<p><b>Complete diagram below, include a description of what happened.</b>            Use the outline below to sketch the scene of your accident,            writing in street or highway names or numbers.            Use number 1 to indicate the State vehicle.</p>	
	<p>This car was park in the parking lot at            1240 26th Ave. Ct. SW, Cedar Rapids,            Iowa 52404 during the time Derecho</p>

**QUALITY CLAIMS SOLUTIONS**

7405 S Bitterroot Pl. Suite 100  
SIOUX FALLS, SD 57108  
Phone: (877) 237-3727, FAX:(866) 371-2844  
qcs@qcsdirect.com

Workfile ID: b112e64b

For:

**QUALITY CLAIMS SOLUTIONS**

DAS Fleet Services  
Phone: (877) 544-7843

**Estimate of Record**

**Owner: STATE OF IOWA HUMAN SERVICES**

**Job Number:**

Written By: Chuck Tilton, CT- 2437980  
Adjuster: Mike, Long, (877) 544-7843 Business

Insured: STATE OF IOWA HUMAN SERVICES Policy #: NOT PROVIDED Claim #: APDSOI0211009001V1  
Type of Loss: Collision Date of Loss: 10/12/2020 12:00 PM Days to Repair: 0  
Point of Impact: 09 Left T-Bone (Left Side)

**Owner:**

STATE OF IOWA HUMAN SERVICES  
CEDAR RAPIDS, IA 52404  
(319) 892-6830 Business

**Inspection Location:**

5 SEASONS AUTO REBUILDERS  
5913 16TH AVE SW  
CEDAR RAPIDS, IA 62404  
Other  
(319) 396-8683 Evening

**Repair Facility:****VEHICLE**

2016 FORD Taurus SE FWD 4D SED 6-3.5L Gasoline Sequential MPI white YZ

VIN: 1FAHP2D87GG113669 Production Date: Interior Color:  
License: Odometer: 77,732 Exterior Color: white YZ  
State: Condition:

**TRANSMISSION**

Automatic Transmission

**POWER**

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

Power Driver Seat

Power Passenger Seat

**DECOR**

Dual Mirrors

Tinted Glass

Console/Storage

Overhead Console

**CONVENIENCE**

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Backup Camera

**RADIO**

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

Auxiliary Audio Connection

**SAFETY**

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

**SEATS**

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

**WHEELS**

Aluminum/Alloy Wheels

**PAINT**

Clear Coat Paint

**OTHER**

Traction Control

Stability Control

California Emissions

# Estimate of Record

Owner: STATE OF IOWA HUMAN SERVICES

Job Number:

2016 FORD Taurus SE FWD 4D SED 6-3.5L Gasoline Sequential MPI white YZ

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		<b>FRONT BUMPER</b>					
2	R&I	R&I bumper cover				1.8	
3		<b>FRONT LAMPS</b>					
4	R&I	LT R&I headlamp assy				0.3	
5		<b>FENDER</b>					
6	Blnd	LT Fender					1.0
7	R&I	LT Fender liner				0.4	
8	*	R&I LT Nameplate w/o SHO				<u>0.2</u>	
9		<b>FRONT DOOR</b>					
10	Repl	LT Outer panel	AG1Z5420201A	1	554.57	7.3	2.3
11		Add for Clear Coat					0.9
12		Add for Edging					0.5
13		Add for Clear Coat					0.1
14	R&I	LT Door w'strip				Incl.	
15	R&I	LT R&I door assy				Incl.	
16	R&I	LT Belt w'strip				Incl.	
17	*	R&I LT Applique w/o Police				<u>Incl.</u>	
18	R&I	LT R&I mirror				Incl.	
19	R&I	LT R&I outside handle				Incl.	
20	R&I	LT R&I trim panel				Incl.	
21		<b>REAR DOOR</b>					
22	*	Rpr LT Door shell				<u>6.0</u>	2.3
23		Overlap Major Adj. Panel					-0.4
24		Add for Clear Coat					0.4
25	*	R&I LT Side molding				<u>0.3</u>	
26	R&I	LT Belt w'strip				0.3	
27	R&I	LT R&I outside handle				0.4	
28		<b>QUARTER PANEL</b>					
29	Blnd	LT Quarter panel					1.1
30	R&I	LT Wheelhouse liner				0.4	
31	*	Rpr LT Lower molding				<u>0.5</u>	0.3
32		Add for Clear Coat					0.1
33	*	R&I LT Lower molding				<u>0.2</u>	
34	*	R&I LT Upper molding w/o SHO				<u>0.2</u>	
35		<b>REAR LAMPS</b>					
36	R&I	LT Tail lamp assy				0.4	
37		<b>REAR BUMPER</b>					
38	*	R&I <u>R&amp;I bumper cover - drop</u>				<u>0.8</u>	
39	#	Hazardous Waste		1	5.00		
40	#	Cover Car		1	5.00		
41	#	Corrosion Protection		1	10.00		
42	#	R&I Door decals		1		0.5	

## Estimate of Record

**Owner: STATE OF IOWA HUMAN SERVICES**

**Job Number:**

2016 FORD Taurus SE FWD 4D SED 6-3.5L Gasoline Sequential MPI white YZ

<b>SUBTOTALS</b>	<b>574.57</b>	<b>20.0</b>	<b>8.6</b>
------------------	---------------	-------------	------------

### ESTIMATE TOTALS

Category	Basis			Rate	Cost \$
Parts					574.57
Body Labor	20.0 hrs	@		\$ 65.00 /hr	1,300.00
Paint Labor	8.6 hrs	@		\$ 65.00 /hr	559.00
Paint Supplies	8.6 hrs	@		\$ 40.00 /hr	344.00
Subtotal					2,777.57
<b>Total Cost of Repairs</b>					<b>2,777.57</b>
Deductible					0.00
<b>Total Adjustments</b>					<b>0.00</b>
<b>Net Cost of Repairs</b>					<b>2,777.57</b>

**MyPriceLink Estimate ID / Quote ID:**

745026997285036032 / 74903550

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.



## Quality Claims Solutions

7405 S. Bitterroot Pl. #100  
Sioux Falls, SD 57108  
Phone: 877.237.3727  
Fax: 866.371.2844  
Federal Tax ID: 46-0461202

---

---

**INVOICE =**

Attention/Adjuster: Mike Long  
Company Name: DAS Fleet Services  
Address: 109 SE 13th St  
Des Moines, IA 503190000

Invoice No: APDSOI0211009001V1  
Date: 10/13/2020 2:30:08PM  
Customer ID: IWAA  
Claim Number: APDSOI0211009001V1  
Vehicle Owner: STATE OF IOWA HUMAN SERV

Quantity	Description	Unit Price	Extended Amou
1.00	Technical Estimate Review	\$ 35.00	\$ 35.00

**Item Total:** \$ 35.00

**Sales Tax:** N/A

**Invoice Total:** \$ 35.00

---

---

***Your Solution for Today's Claims***

[www.qcsdirect.com](http://www.qcsdirect.com)





1815 16th Ave. S.W.  
Cedar Rapids, Iowa 52404  
Phone (319) 364-BODY

**PAINTING-FRAME & UNIBODY-INSURANCE WORK**

CUSTOMER'S ORDER # <b>3186</b>		PHONE		DATE <b>1/4/21</b>	
NAME					
ADDRESS <b>Iowa State DHS</b>					
<b>#105974</b>					
SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT	PAID OUT
QTY.	DESCRIPTION			PRICE	AMOUNT
	<b>16 Ford Taurus</b>				
PARTS (Prices Subject To Invoice)					
Services Hrs @ Hr.					<b>554 57</b>
Sublet Or Painting					<b>1300 00</b>
Sub Total					<b>903 00</b>
Paint-Mat'l-Hdw					
TAX					<b>Exempt</b>
TOTAL					<b>277 57</b>

© PRODUCT 512 All claims and returned goods must be accompanied by this bill

4500

*Thank You*