



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: November 30, 2021

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#1071/Deer
Event Date	November 8, 2021
Summary	Vehicle #1071 struck a deer. (228860)
Amount Requested	\$2,167.85 - Estimate <u>\$ 35.00 - Review Invoice</u> \$2,202.85 - Total
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-725-2243



Risk, DAS <das.risk@iowa.gov>

29C20

1 message

Risk, DAS <das.risk@iowa.gov>

Wed, Nov 10, 2021 at 10:32 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil
<executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 1071 struck a deer on 11/8/2021. I will forward all information as soon as it is received.

228860

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



**Department of
Administrative Services**
*Empowering People
Collaboration
Customer Service*

DAS Fleet Services, Risk

Iowa Department of Administrative Services
Division of Business and Property Services
Office: 515-725-2243
Das.Risk@iowa.gov
<https://das.iowa.gov>

----- Forwarded message -----

From: **Platt, Scott** <scott.platt@dia.iowa.gov>

Date: Tue, Nov 9, 2021 at 9:59 AM

Subject: Vehicle Accident / Damage Report

To: DAS Risk <das.risk@iowa.gov>

Cc: Mark Speltz <mark.speltz@dia.iowa.gov>, Michelle Boyd <michelle.boyd@dia.iowa.gov>

I'm emailing to report damage to my State issued vehicle due to a deer strike.

Driver: Scott Platt

Department: DIA, Food & Consumer Safety Bureau

Vehicle #: 1071

VIN#: 3FA6PoG76HR316934

Make/Model/Year: 2017 Ford Fusion

Estimated Odometer Mileage: 64,712

Date of event: 11/8/2021

Time of Event: Approximately 5:50 pm

Location of Event: Keokuk County, Highway 21 approximately 2.5 miles north of Highway 92.

Event details: A male buck deer exited the ditch onto the shoulder of the road and was proceeding to cross the highway with his head down. This male deer had a rack of antlers. I did not have time to slow down or to move to the opposite lane of the highway and as I passed the deer I believe his antlers clipped the side of the car, causing damage to the mirror and painted surfaces.

Damage to the vehicle appears to be mostly cosmetic in nature. The right side passengers mirror is broken, although the mirror assembly is still intact and the outer mirror cover came off. I was able to return to the site of

Vehicle Accident Report

Time and location of accident

Accident Date (Mo/Day/Year)	Time	No. of Vehicles
11/09/2021	17:50 pm	1
County	State	
Keokuk	Iowa	

Vehicle 1 (State vehicle)

Driver's Name		Work Street Address	
Scott Platt		321 East 12th Street	
Driver's License No./State		City, State, Zip	
062BB3817 - IA		Des Moines, IA 50319-0083	
Date of Birth	Department	Work Phone	Home Phone
02/14/1970	DIA, Food Bureau	(515) 669-3953	(641) 295-3808
License Plate No.	VIN	Year, Make, Model	
1071	3FA6P0G76HR316934	2017 Ford Fusion	
Estimate (\$) of Damage		Description of Damage	
\$2,335.22		Passenger's side mirror glass and cover broken. Scratches to paint on the right front panel and passenger's side door.	

Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

Driver's Name		Street Address	
Driver's License No./State		City, State, Zip	
Date of Birth	Work Phone	Home Phone	License Plate No.
Description of Damage			

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
Vehicle No. 2/ Name and Address	Describe Injuries
Witness	
Name	Address/Phone
Name	Address/Phone

Accident Diagram	
<p>Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers. Use number 1 to indicate the State vehicle.</p>	
<p>The diagram shows a cross street intersection on the left. To the right, a vertical line represents Hwy 21, with an arrow pointing upwards labeled 'Hwy 21'. A vehicle labeled '1' is shown on Hwy 21, traveling southbound (indicated by an arrow pointing up towards the 'South' label). To the right of the vehicle, a small rectangle represents a deer crossing the highway. The text 'Deer' is written next to it. The 'South' label is at the top right, and the 'North' label is at the bottom right.</p> <p>Traveling southbound on HWY 21 when a deer exited the ditch and started to cross the highway. The deer's antlers clipped the passenger's side of the vehicle (front panel, passenger mirror, and passenger's door) causing damage to the vehicle.</p>	

QUALITY CLAIMS SOLUTIONS

7405 S Bitterroot Pl. Suite 100
SIOUX FALLS, SD 57108
Phone: (877) 237-3727, FAX:(866) 371-2844
qcs@qcsdirect.com

Workfile ID:

22eefeed

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record**Owner: STATE OF IOWA****Job Number:**

Written By: David Kelley

Insured:	STATE OF IOWA	Policy #:	NOT PROVIDED	Claim #:	APDSOI0228860-001
Type of Loss:	Collision	Date of Loss:	11/11/2021 12:00 PM	Days to Repair:	0
Point of Impact:	02 Right Front Pillar (Right Side)				

Owner:

STATE OF IOWA
109 SE 13TH ST
DES MOINES, IA 50319

Inspection Location:

Copeland Collision Center
1308 17th ave E
Oskaloosa, IA 52577
Other
(641) 676-6060 Evening

Repair Facility:**VEHICLE**

2017 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI TAN

VIN:	3FA6P0G76HR316934	Production Date:		Interior Color:	
License:		Odometer:	64,713	Exterior Color:	TAN
State:		Condition:			

TRANSMISSION

Automatic Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors

DECOR

Dual Mirrors
Tinted Glass
Console/Storage
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Backup Camera

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags

Hands Free Device

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions

Estimate of Record

Owner: STATE OF IOWA

Job Number:

2017 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI TAN

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER & GRILLE					
2	R&I	R&I bumper cover				1.2	
3		FRONT LAMPS					
4	R&I	RT Headlamp assy w/o signature lamps				0.3	
5		FENDER					
6	*	Rpr RT Fender				3.0	2.0
7		Add for Clear Coat					0.8
8	R&I	RT Upper molding bright/black				0.2	
9	R&I	RT Fender liner w/o turbo w/2.5 liter DOHC				0.3	
10		PILLARS, ROCKER & FLOOR					
11	R&I	RT Rocker molding				0.7	
12		FRONT DOOR					
13	R&I	RT Belt molding				0.3	
14	*	Rpr RT Outer panel				3.0	2.3
15		Overlap Major Adj. Panel					-0.4
16		Add for Clear Coat					0.4
17	R&I	RT Door glass FORD w/o laminate				0.6	
18	R&I	RT Handle, outside w/o passive entry				0.3	
19	R&I	RT R&I trim panel				0.5	
20	Repl	RT Mirror assy	FS7Z17682B	1	221.20	0.5	
21	Repl	RT Mirror cover	DS7Z17D742AAPT	1	55.25	0.2	0.5
22		Overlap Minor Panel					-0.2
23		Add for Clear Coat					0.1
24	#	Repl DECAL-AS PER INVOICE		1		0.3	
25	R&I	RT Applique all w/o keyless lock pad				0.2	
26		REAR DOOR					
27	*	Rpr RT Outer panel				1.0	2.3
28		Overlap Major Adj. Panel					-0.4
29		Add for Clear Coat					0.4
30	R&I	RT Belt molding				0.3	
31	*	R&I RT Applique front				0.2	
32	R&I	RT Applique rear				0.2	
33	R&I	RT Door glass FORD				0.3	
34	R&I	RT Window regulator				0.3	
35	R&I	RT Handle, outside w/o passive entry				0.3	
36	R&I	RT R&I trim panel				0.5	
37	#	PRE REPAIR SCAN		1	50.00	0.5 M	
38	#	POST REPAIR SCAN		1	50.00	0.5 M	

Estimate of Record

Owner: STATE OF IOWA

Job Number:

2017 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI TAN

39	#	Hazardous Waste	1	3.00	
40	#	Cover Car	1	5.00	0.2
41	#	Corrosion Protection	1	6.00	
SUBTOTALS				390.45	15.9 7.8

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			390.45
Body Labor	14.9 hrs @	\$ 62.15 /hr	926.04
Paint Labor	7.8 hrs @	\$ 100.00 /hr	780.00
Mechanical Labor	1.0 hrs @	\$ 71.36 /hr	71.36
Subtotal			2,167.85
Total Cost of Repairs			2,167.85
Deductible			0.00
Total Adjustments			0.00
Net Cost of Repairs			2,167.85

MyPriceLink Estimate ID / Quote ID:

888088566649856000 / 95956327

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.



Quality Claims Solutions

Quality Claims Solutions

105 N Krohn Place

Sioux Falls, SD 57103

Phone: 877.237.3727

Fax: 866.371.2844

Federal Tax ID: 46-0461202

INVOICE =

Attention/Adjuster: Jessica Hackbarth

Company Name: DAS Fleet Services

Address: 109 SE 13th St
Des Moines, IA 50319

Invoice No: APDSOI0228860-001-3219

Date: 11/11/2021 3:01 PM

Customer ID: IWAA

Claim Number: APDSOI0228860-001

Vehicle Owner: STATE OF IOWA

Quantity	Description	Unit Price	Extended Amount
1	Technical Estimate Review	\$35.00	\$35.00

Item Total: \$35.00

Sales Tax: N/A

Invoice Total:

\$35.00