

Governor Kim Reynolds Lt. Governor Adam Gregg

Adam Steen, Director

Date: November 30, 2021

To: Tammy Hollingsworth, Auditor of State Victoria Newton, Treasurer of State

Executive Council

From: Mariah Flowers, Fleet Manager

DAS Fleet Services

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#443/Raccoon
Event Date	October 31, 2021
Summary	Vehicle #443 struck a raccoon. (228986)
Amount Requested	\$2,477.85 - Estimate \$ 35.00 - Review Invoice \$2,512.85 - Total
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager

DAS Fleet Services

Mariah.Flowers@iowa.gov

515-725-2243

Hoover State Office Building | 1305 East Walnut Street | Des Moines, IA 50319 | (515) 281-5360 | http://das.iowa.gov

11/1/21, 4:03 PM

State of Iowa Mail - FW: ISP 443 24 hr notice veh dam nature



Risk, DAS <das.risk@iowa.gov>

FW: ISP 443 24 hr notice veh dam nature

1 message

Adams Jeannie <jadams@dps.state.ia.us>

Mon, Nov 1, 2021 at 8:27 AM

To: "executivecouncil@tos.iowa.gov" <executivecouncil@tos.iowa.gov>, "Tammy.Hollingsworth@auditor.state.ia.us" <Tammy.Hollingsworth@auditor.state.ia.us>

Cc: "DAS.Risk@iowa.gov" <DAS.Risk@iowa.gov>, Guill Bryan <guill@dps.state.ia.us>

Good morning

Please accept this as a 24 hour notice on behalf of post 2 for Trooper Knedler (#443). Trooper Knedler hit a raccoon on 10-31-2021. I will forward more information as it becomes available.

Thank you

Jeannie Adams

ISP Fleet & Supply, Fleet Asset Manager

Department of Public Safety

30 N.E. 48th Place

Des Moines, Iowa 50313

Direct #: 515-725-0643

Cell Phone: 515-204-3019

Shop: 515-281-3277

Fax: 515-242-6321

Email: jadams@dps.state.ia.us

From: Major Wade <major@dps.state.ia.us> Sent: Sunday, October 31, 2021 8:58 PM

To: vehicledamage <vehicledamage@dps.state.ia.us>

Cc: Pollard Brad <pollard@dps.state.ia.us>; Anderson Allen <aanderso@dps.state.ia.us>; Taylor Aaron

<ataylor@dps.state.ia.us>

Subject: ISP 443 24 hr notice veh dam nature

ΑII,

https://mail.google.com/mail/b/ALGkd0y-UQu-Y5l9tswdZCD0tGTc2OQp0UEJInCeMJ7JhXIrTZYk/u/0/?ik=fc086bf76c&view=pt&search=all&permthid=t... 1/2

2

On 10/31/21 at approximately 2015 hours Trooper Knedler #443 struck a raccoon with patrol vehicle, while traveling northbound on Hwy 169, causing damage to the patrol vehicle.

Mileage 40969

2c3cdxkt0lh124226 VIN

Thanks,

Sgt. Major #49

From: Knedler Justin <knedler@dps.state.ia.us>

Sent: Sunday, October 31, 2021 8:34 PM
To: Pollard Brad <pollard@dps.state.ia.us>; Taylor Aaron <ataylor@dps.state.ia.us>; Major Wade

<major@dps.state.ia.us>; Anderson Allen <aanderso@dps.state.ia.us>

Subject: 10-50 patrol car/racoon

2 attachments



IMG952783.jpg 270K

443.docx 18K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: <u>vehicledamage@dps.state.ia.us</u>; <u>das.risk@iowa.gov</u>

- > One Repair Estimate from Approved State Bid Shop
- > DOT MARS Report (if reportable)
- > Memo from the Driver of the State Vehicle
- > 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature⊠) CASE #: 2021026558

		mant in 7 tot on i	100101 J 0710 = 111	ZUZ 10Z0330
Date:	10/3	31/2021	Time:	8:16 p.m.
(Month/Day/Year)			(Time plus a.m./p.m.)	
Vehicle Plate #:	443		Vehicle Mileage:	40969
Vehicle				
Description: (Yr/Make/Model/ & Vin#)	202	0 Dodge Char	0LH124226	
Assigned To:	or or more participation	P JUSTIN EDLER	Badge #	443
Driven By:	TRP JUSTIN KNEDLER		Badge #	443
Driver's Lic #:	427KK0650		Damage:	\$2440.85
Vehicle Towed: (Yes / No)	NO		Towed By:	N/A
Towed To: N/A			Towing Cost:	\$N/A
Seat Belt: YES		3	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:		NONE		
Occupants: (Other than driver)				

VEHICLE #2:

DL #:	State:	
Vehicle Lic. #	State:	
Driver's Name:		
Driver's Address:		
Owner's Name:		

August 2018

Owner's Phone: Insurance Info: (Carrier/Policy #/Phone) Veh Description: (Yr/Make/Model & Vin#) Damage: Seat Belt: (Yes / No) Doccupants: Obertan driver) Occupants(s) Wearing Seat Belt: (Yes/No) Doctupant(s) Wearing Seat Belt: (Yes/No)	W				***	
Insurance Info: (Carrier/Policy #/Phone) Weh Description: (Yr/Make/Model & Vin#) Damage: \$ Seat Belt: (Yes / No) Injured/Injuries: Occupants: Ober than driver) Obccupants(s) Wearing Seat Belt: (Yes/No) DTHER INFORMATION: Witnesses: Accident Location: HWY 169 58 MILE MARKER Street/Hwy) County: MADISON Weather/Road Conditions: CLOUDY/DRY Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle struck as a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than None (Property Damage other than None (Property Damage other than State) (Property Damage other than None (Property Damage other than State) (Property Damage other than	Owner's Address:					
Carrier/Policy #/Phone Veh Description: Yr/Make/Model & Vin#)	Owner's Phone:					
Veh Description: (Yr/Make/Model & Vin#) Damage: Seat Belt:	Insurance Info:					
Companies Seat Belt: (Yes / No)	(Carrier/Policy #/Phone)					7
Damage: \$ Seat Belt: (Yes / No) Injured/Injuries: Occupants: Other than driver) Occupant(s) Wearing Seat Belt: (Yes/No) OCTHER INFORMATION: Witnesses: Accident Location: HWY 169 58 MILE MARKER Street/Hwy) MADISON Weather/Road Conditions: CLOUDY/DRY Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than /ehicles: Cost: \$N/A Citations Issued To: List Charge(s) and Statute Code(s)) None Mone //EHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: (ehicle Lic. # State: (chicle Lic. # St						
Injured/Injuries: Occupants: Occupant(s) Wearing Seat Belt: (Yes/No) Occupation Seat Belt: (Yes/No	(Tr/Make/Model & VIII#)					
Injured/Injuries: Occupants: Other than driver) Occupant(s) Wearing Seat Belt: (Yes/No) OTHER INFORMATION: Witnesses: Accident Location: HWY 169 58 MILE MARKER Street/Hwy) County: MADISON Weather/Road Conditions: CLOUDY/DRY Frooper Knedler #443 was on routine patrol while operating issued marked batrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than None /ehicles: Cost: \$N/A Citations Issued To: List Charge(s) and Statute Code(s)) None VEHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: State: Vehicle Lic. # State:	Damage:	\$		Seat Belt:		
Occupants: Other than driver) Occupant(s) Wearing Seat Belt: (Yes/No) OTHER INFORMATION: Witnesses: Accident Location: Street/Hwy) County: MADISON Weather/Road Conditions: CLOUDY/DRY Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than //ehicles: Cost:	1.1			(Yes / No)		
Occupant(s) Wearing Seat Belt: (Yes/No) OTHER INFORMATION: Witnesses: Accident Location: HWY 169 58 MILE MARKER Street/Hwy) County: MADISON Weather/Road Conditions: CLOUDY/DRY Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than Aller of the country o			38		- 310	
Occupant(s) Wearing Seat Belt: (Yes/No) OTHER INFORMATION: Witnesses: Accident Location: HWY 169 58 MILE MARKER Street/Hwy) County: MADISON Weather/Road Conditions: CLOUDY/DRY Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than None //ehicles: Cost: \$N/A Citations Issued To: List Charge(s) and Statute Code(s)) None //EHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: State: //ehicle Lic. # State: //ehicle Lic. # State:						
OTHER INFORMATION: Witnesses: Accident Location: Street/Hwy) County: MADISON Weather/Road Conditions: CLOUDY/DRY Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than None / Chicles: Cost: Cost: SN/A Citations Issued To: List Charge(s) and Statute Code(s)) Investigating Officer: Sgt. Wade Major #49 VEHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: Vehicle Lic. # State: Vehicle Lic. # State: Vehicle Lic. # Striver's Name:		ng Seat B	elt: (Yes/	No)	* 10	
Witnesses: Accident Location: Street/Hwy) County: MADISON Weather/Road Conditions: CLOUDY/DRY Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than //ehicles: Cost: SN/A Citations Issued To: List Charge(s) and Statute Code(s)) Investigating Officer: Sgt. Wade Major #49 VEHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: Vehicle Lic. # Driver's Name:			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
Witnesses: Accident Location: Street/Hwy) County: MADISON Weather/Road Conditions: CLOUDY/DRY Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than //ehicles: Cost: SN/A Citations Issued To: List Charge(s) and Statute Code(s)) Investigating Officer: Sgt. Wade Major #49 VEHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: Vehicle Lic. # Driver's Name:						
Witnesses: Accident Location: Street/Hwy) County: MADISON Weather/Road Conditions: CLOUDY/DRY Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than //ehicles: Cost: SN/A Citations Issued To: List Charge(s) and Statute Code(s)) Investigating Officer: Sgt. Wade Major #49 VEHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: Vehicle Lic. # Driver's Name:						
Accident Location: Street/Hwy) County: MADISON Weather/Road Conditions: CLOUDY/DRY Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than None Property Damage other than None Property Damage other than None Itations Issued To: List Charge(s) and Statute Code(s)) None Sgt. Wade Major #49 WEHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: Vehicle Lic. # State: Vehicle Lic. # State: Vehicle Lic. # State: Vehicle Lic. # State: Veriver's Name:	OTHER INFORMA	TION:				
Street/Hwy) County: MADISON Weather/Road Conditions: CLOUDY/DRY Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than /ehicles: Cost: \$N/A Citations Issued To: Sylvade Major #49 The HICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: State: Cehicle Lic. # State: Cehicle Lic. # State: Cover's Name:	Witnesses:					
County: Meather/Road Conditions: CLOUDY/DRY Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than None	Accident Location:		HWY 1	69 58 MILE MAR	KER	
Weather/Road Conditions: CLOUDY/DRY Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than Vone Vehicles: Cost: Cost: Cost: SN/A Citations Issued To: List Charge(s) and Statute Code(s)) None VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion) DL #: Vehicle Lic. # Oriver's Name:			MADIO	ON		
Trooper Knedler #443 was on routine patrol while operating issued marked patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than None						
patrol vehicle, 2020 Dodge Charger. Trooper Knedler's patrol vehicle struck a raccoon in roadway. As a result Trooper Knedler's patrol vehicle sustained minor damage. Property Damage other than Vone Property Damage other than Vone Property Damage other than Vone Property Damage other than None State: State: Property Damage other than None Property Damage other than None Property Damage other than None State: State: Property Damage other than None State: State: Property Damage other than None Property Damage other than None State: State: Property Damage other than None State: State: Property Damage other than None State: State: Property Damage other than None State: State: State: Property Damage other than None Property Damage other than None State: State: State: State: Property Damage other than None Property Damage other than None Property Damage other than None State: Stat	and the second s					
Property Damage other than //ehicles: Cost: Citations Issued To: List Charge(s) and Statute Code(s)) None Sgt. Wade Major #49 /EHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: State: /ehicle Lic. # Driver's Name:						
Property Damage other than //ehicles: Cost: \$N/A Citations Issued To: None Investigating Officer: Sgt. Wade Major #49 //EHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: State: //ehicle Lic. # Driver's Name:						
Property Damage other than Vone /ehicles: Cost: \$N/A Citations Issued To: None Investigating Officer: Sgt. Wade Major #49 /EHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: State: /ehicle Lic. # Driver's Name:		1.50	esuit III	poper Kriedier's p	alioi ve	nicie
/ehicles: Cost: \$N/A Citations Issued To: None List Charge(s) and Statute Code(s)) None None Sgt. Wade Major #49 /EHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: State: /ehicle Lic. # State: Oriver's Name:	sustained millor da	maye.				
/ehicles: Cost: \$N/A Citations Issued To: None List Charge(s) and Statute Code(s)) None None Sgt. Wade Major #49 /EHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: State: /ehicle Lic. # State: Oriver's Name:						
/ehicles: Cost: \$N/A Citations Issued To: None List Charge(s) and Statute Code(s)) None None Sgt. Wade Major #49 /EHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) DL #: State: /ehicle Lic. # State: Oriver's Name:			1			
Cost: \$N/A Citations Issued To: None Investigating Officer: Sgt. Wade Major #49 /EHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion) DL #: State: State: State: /ehicle Lic. # State: Driver's Name:		ther than	None			
Citations Issued To: List Charge(s) and Statute Code(s)) None None Sgt. Wade Major #49 /EHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) OL #: State: /ehicle Lic. # Oriver's Name:			A			
Sgt. Wade Major #49	Cost:			10		
/EHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) OL #: /ehicle Lic. # Oriver's Name:		·	None			
/EHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) OL #: Vehicle Lic. # Oriver's Name:	(List Charge(s) and Statute	Code(s))	10.		3444	
/EHICLE #3: (If needed) (For more vehicles, please make extra copies of his portion) OL #: Vehicle Lic. # Oriver's Name:	Investigating Office	r:		Sat Wade Maio	or #49	
his portion) OL #: Vehicle Lic. # Oriver's Name:	<u> </u>			- g		
his portion) OL #: Vehicle Lic. # Oriver's Name:						
his portion) OL #: Vehicle Lic. # Oriver's Name:	VEHICLE #3: (If ne	eded) (F	or more	vehicles, pleas	e make	extra copies o
OL #: State: Vehicle Lic. # State: Oriver's Name:	this portion)	, (,		ooloioo (
/ehicle Lic. # State:	DL #:	0.00	30-40	State:		
Driver's Name:	Vehicle Lic. #					
	Driver's Name:	2 2 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	107			
711VCI 3 Addi C33.	Driver's Address:	we we will also well also we will also we will also we will also we will also we wi				

opies of			
August 2018			

Owner's Name:					
Owner's Address:					
Owner's Phone:					
Insurance Info: (Carrier/Policy #/Phone)					
Veh Description: (Yr/Make/Model & Vin#)					
Damage:	\$	Seat Belt: (Yes / No)	Yes		
Injured/Injuries:					
Occupants: (Other than driver)					
Occupant(s) Wearing Seat Belt: (Yes/No) Yes					

QUALITY CLAIMS SOLUTIONS

7405 S Bitterroot Pl. Suite 100 SIOUX FALLS, SD 57108 Phone: (877) 237-3727, FAX:(866) 371-2844

qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: TJ IWOA STATE PATROL Job Number:

Written By: David Kelley

TJ IWOA STATE PATROL Insured:

Collision

Policy #:

UNKNOWN Date of Loss: 11/12/2021 12:00 PM

Days to Repair: 0

Claim #:

Workfile ID:

APDSOI0228986-001

18e58661

Point of Impact: 12 Front

Owner:

Type of Loss:

TJ IWOA STATE PATROL Creston, IA 50801

Inspection Location: F & M BODY SHOP

> 901 S DIVISION ST CRESTON, IA 50601

Other

(641) 782-5115 Evening

Repair Facility:

VEHICLE

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

VIN: License:

State:

2C3CDXKTOLH124226

Production Date:

Odometer:

AM Radio

SAFETY

Condition:

TRANSMISSION Automatic Transmission 4 Wheel Drive **POWER** Power Steering

Power Brakes Power Windows Power Locks

Power Mirrors Power Driver Seat **DECOR Dual Mirrors**

Tinted Glass Overhead Console CONVENIENCE

Air Conditioning Intermittent Wipers

Tilt Wheel Cruise Control

Rear Defogger Keyless Entry Message Center

Steering Wheel Touch Controls

Telescopic Wheel Climate Control Backup Camera

Parking Sensors **RADIO**

Cloth Seats

Interior Color:

Exterior Color:

FM Radio **Bucket Seats** Stereo Reclining/Lounge Seats

Search/Seek WHEELS

Styled Steel Wheels PAINT

Clear Coat Paint **OTHER**

Traction Control Stability Control California Emissions Power Trunk/Liftgate

Page 1

Hands Free Device **SEATS**

Auxiliary Audio Connection

Drivers Side Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Head/Curtain Air Bags

Front Side Impact Air Bags

Passenger Air Bag

11/12/2021 2:55:57 PM 314048

Estimate of Record

Owner: TJ IWOA STATE PATROL

Job Number:

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUMPE	R						
2			O/H front bumper				3.4	
3		Repl	Bumper cover	68267765AC	1	740.00	Incl.	3.4
4			Add for Clear Coat					1.4
5	*	Repl	Lower grille w/o adaptive cruise	68214782AB	1	83.65	Incl.	
6	COOLING							
7		Repl	Upper seal	68050130AB	1	73.20		
8	AIR CONDITIO	NER 8	& HEATER					
9		Repl	Condenser assy	68085784AA	1	521.00 m	1.5 M	
10			AC Service evacuate & recharge			m	1.4 M	
11	#		Hazardous Waste		1	3.00		
12	#		Evacuate/ Rechage R134a		1	25.00		
13	#		Flex Agent		1	5.00		
14	#		Tint Color		1			0.5
15	#	R&I	GRILLE PUSH GUARD				1.5	
				SUBTOTALS		1,450,85	7.8	5.3

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts			***	1,450.85
Body Labor	4.9 hrs	@	\$ 60.00 /hr	294.00
Paint Labor	5.3 hrs	@	\$ 60.00 /hr	318.00
Mechanical Labor	2.9 hrs	@	\$ 70.00 /hr	203.00
Paint Supplies	5.3 hrs	@	\$ 40.00 /hr	212.00
Subtotal				2,477.85
Total Cost of Repairs				2,477.85
Deductible				0.00
Total Adjustments				0.00
Net Cost of Repairs				2,477.85

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.

11/12/2021 2:55:57 PM 314048 Page 2



Quality Claims Solutions

105 N Krohn Place Sioux Falls, SD 57103 Phone: 877.237.3727 Fax: 866.371.2844

Federal Tax ID: 46-0461202

= INVOICE =

Attention/Adjuster: Jessica Hackbarth

Company Name: DAS Fleet Services

Address:

109 SE 13th St

Des Moines, IA 50319

Invoice No: APDSOI0228986-001-3317

Date: 11/12/2021 2:56 PM

Customer ID: IWAA

Claim Number: APDSOI0228986-001

Vehicle Owner: TJ IWOA STATE PATROL

Quantity	Description	Unit Price	Extended Amount
1	Technical Estimate Review	\$35.00	\$35.00

Item Total: \$35.00

Sales Tax:

N/A

Invoice Total:

\$35.00

Your Solution for Today's Claims www.qcsdirect.com