



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: October 4, 2021

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#261 & 159/Hail
Event Date	August 28, 2021
Summary	Trooper #261 & 159 sustained hail damage. (225559, 225415)
Amount Requested	\$13,198.30 - Estimates <u>\$ 514.25 - Review Invoices</u> \$13,712.55 - Total
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-725-2243

FW: Hail damage #261 & #159

1 message

Guill Bryan <guill@dps.state.ia.us>

Mon, Aug 30, 2021 at 4:19 PM

To: "ExecutiveCouncil@tos.iowa.gov" <ExecutiveCouncil@tos.iowa.gov>, "das.risk@iowa.gov" <das.risk@iowa.gov>, "tammy.hollingsworth@aos.iowa.gov" <tammy.hollingsworth@aos.iowa.gov>

Executive Council and Tammy,

Please accept below as 24 hr notification of hail damage sustained by Troopers Hilt #261 and Troopers Zylstra #159. Trooper's Zylstra's vehicle damage submission is attached. Estimate is for \$7790.88 in damage. ISP would like to pursue 29C20 reimbursement for this AON event.

I will forward #261 reports upon Receipt and thank you in advance for your consideration.

V/R

Bryan

Lt. Bryan Guill ★498★

Commander Fleet & Supply

Iowa Department of Public Safety

30 NE 48th Place

Des Moines, IA 50313

F&S Main 515-281-3391

Direct 515-281-3118

Cell 515-201-9958

guill@dps.state.ia.us

1033program@dps.state.ia.us

****Notice**** This e-mail message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this e-mail by an unintended recipient is prohibited. If you have received this e-mail in error, please notify the sender by return e-mail and destroy all copies of the original

message. No representation is made that this e-mail or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

From: Kurtz Vincent <kurtz@dps.state.ia.us>
Sent: Saturday, August 28, 2021 8:51 PM
To: Guill Bryan <guill@dps.state.ia.us>
Cc: Williams Matthew <mwilliam@dps.state.ia.us>; Hesse Chase <hesse@dps.state.ia.us>
Subject: Hail damage #261 & #159

Lt Guill-

Both Troopers Hilt #261 and Zylstra #159 are reporting hail damage to their squad cars from storms going through Lyon County tonight. They will be submitting estimates to me on Monday and I will forward on the completed reports to you ASAP.

Thank you.

Sgt Vince Kurtz#495

----- Forwarded message -----

From: Zylstra Jeff <zylstra@dps.state.ia.us>
To: Hesse Chase <hesse@dps.state.ia.us>, Kurtz Vincent <kurtz@dps.state.ia.us>, Williams Matthew <mwilliam@dps.state.ia.us>
Cc:
Bcc:
Date: Sun, 29 Aug 2021 13:42:52 +0000
Subject: storm damage

I have hail damage on my squad from the storm about 2000 hours on august 28. I will get an estimate tomorrow from c and h. thanks 159

4 attachments

 **storm damage.eml**
8K

 **#159 Photos 8-28-21.pdf**
3853K

 **#159 Estimate 8-28-21.pdf**
120K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: **DPS – Vehicle Damage; DAS – Risk**

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature ☒) CASE #: 2021021216

Date: (Month/Day/Year)	8-28-2021	Time: (Time plus a.m./p.m.)	20:00 p.m.
Vehicle Plate #:	159	Vehicle Mileage:	40,380
Vehicle Description: (Yr/Make/Model/ & Vin#)	2020 DODGE CHARGER VIN # 2c3cdxkt0lh127515		
Assigned To:	Jeffrey Zylstra	Badge #	159
Driven By:	Parked	Badge #	
Driver's Lic #:		Damage:	\$7790.88
Vehicle Towed: (Yes / No)	No	Towed By:	Not Towed
Towed To:	Not Towed	Towing Cost:	\$Not Towed
Seat Belt: (Yes / No)	Yes	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:	None		
Occupants: (Other than driver)	None		

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

OTHER INFORMATION:

Witnesses:	NONE
Accident Location: (Street/Hwy)	1434 Coolidge Ave, Larchwood IA
County:	Lyon
Weather/Road Conditions:	Severe Thunderstorm
<p>Narrative: On 8-28-21 Trooper Zylstra's squad car was parked at his residence as he was off duty. A severe thunderstorm passed through and his squad car sustained damage from hail.</p>	
Property Damage other than Vehicles:	NONE
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	NONE

Investigating Officer:	Sgt. Vince Kurtz #495
------------------------	-----------------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			

Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

Date: 9/ 7/2021 12:34 PM
 Estimate ID: 8441090011
 Estimate Version: 0
 Committed
 Profile ID: * Mitchell

Property Damage Appraisers (PDA Sioux City)

P.O. Box 144, Collins, IA 50055
 (712) 276-4990
 Fax: (712) 276-6609
 Email: pdasiouxcity@pdaorg.net

* Not An Authorization For Repair *
 Read disclaimers following appraisal calculations.

Damage Assessed By: LAYNE MOSHER
 Classification: Field

Appraised For: MIKE LONG

Condition Code: Good
 Date of Loss: 9/ 7/2021
 Deductible: 0.00
 File Number: 8441090011
 Claim Number: APDSOI0225415-001
 Type of Loss: Comprehensive

Insured: STATE OF IOWA
 Owner: STATE OF IOWA
 Address: 836 HOLDER ST, LARCHWOOD, IA 51241

Mitchell Service: 911667

Description: 2020 Dodge Charger Police
 Body Style: 4D Sed
 VIN: 2C3CDXKT0LH127515
 Mileage: 41,554
 OEM/ALT: A
 Parts Profile: Sioux City
 Color: Silver
 Options: POWER DRIVER SEAT, POWER BRAKE, CRUISE CONTROL, FM RADIO
 Vehicle Production Date: 2/20
 Drive Train: 5.7L Inj 8 Cyl 5A AWD
 License: 159 IA
 Parts Profile Version: 2

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	100374	BDY	REMOVE/INSTALL	Frt Bumper Cover			
2	900500	BDY*	REMOVE/INSTALL	Push Bar	Existing		2.0 #
3	100559	BDY	REMOVE/REPLACE	Hood Panel (Alum)	** QRP Certified	952.00	1.6
4	AUTO	REF	REFINISH	Hood Outside			C 2.8
5	AUTO	REF	REFINISH	Add For Hood Underside			C 1.4
6	100002	REF	BLEND	R Fender Outside			C 0.8
7	100379	REF	BLEND	L Fender Outside			C 0.8
8	AUTO	BDY	PAINTLESS REPAIR	R Fender Panel	** QUAL REPL PART	225.00	#
9				1 NICKEL SIZE DENT			
10				7 QUARTER SIZE DENTS			
11				7 HALF DOLLAR SIZE DENTS			
12	AUTO	BDY	PAINTLESS REPAIR	L Fender Panel	** QRP Certified	175.00	#
13				11 QUARTER SIZE DENTS			
14	102438	BDY	REMOVE/INSTALL	R Fender Splash Shield	Existing		INC r
15	102439	BDY	REMOVE/INSTALL	L Fender Splash Shield	Existing		INC r
16	101303	BDY	PAINTLESS REPAIR	R Door Opening Panel	Sublet	275.00	* 0.0*#
17				8 QUARTER 3 HALF INCLUDES: DOUBLE PANEL			
18	101304	BDY	PAINTLESS REPAIR	L Door Opening Panel	Sublet	125.00	* 0.0*#
19				8 QUARTER INCLUDES DOUBLE PANEL			
20	102049	BDY	REMOVE/INSTALL	R Rocker Moulding			0.4
21	102050	BDY	REMOVE/INSTALL	L Rocker Moulding			0.4
22	900500	BDY*	REMOVE/INSTALL	Fender Decals	Existing		0.6* r
23	AUTO	BDY	PAINTLESS REPAIR	R Frt Door Shell (Steel/HSS)	Sublet	175.00	#
24				7 QUARTER SIZE DENTS			
25				3 HALF DOLLAR SIZE DENTS			

ESTIMATE RECALL NUMBER: 09/07/2021 12:34:43 8441090011

Mitchell Data Version: OEM: JUL_21_V

Alternate Parts: 09/07/2021 12:15:04

Copyright (C) 1994 - 2021 Mitchell International

Software Version: 7.1.241

All Rights Reserved

Page 1 of 4

Date: 9/ 7/2021 12:34 PM
 Estimate ID: 8441090011
 Estimate Version: 0
 Committed
 Profile ID: * Mitchell

26	AUTO	BDY	PAINTLESS REPAIR	L Frt Door Shell (Steel/HSS)	Sublet	125.00	#
27				3 QUARTER SIZE DENTS			
28				1 HALF DOLLAR SIZE DENT			
29	101463	BDY	REMOVE/REPLACE	R Frt Otr Door Belt Moulding	57010348AC	108.00	0.2
30	AUTO	BDY	PAINTLESS REPAIR	R Rear Door Shell (Steel/HSS)	Sublet	125.00	#
31				4 QUARTER SIZE DENTS			
32	AUTO	BDY	PAINTLESS REPAIR	L Rear Door Shell (Steel/HSS)	Sublet	125.00	#
33				4 QUARTER SIZE DENTS			
34	100739	BDY	REMOVE/REPLACE	R Rear Upr Door Adhesive Moulding	57010506AN	118.00	0.2
35	AUTO	BDY	PAINTLESS REPAIR	Roof Panel	Sublet	1,200.00	
36				80 QUARTER SIZE DENTS			
37				22 HALF DOLLAR SIZE DENTS			
38	900500	BDY *	REMOVE/INSTALL	Police Equipment On Roof	Existing		2.0* r
39	101699	BDY	REMOVE/INSTALL	Roof Headliner			4.4 #
40	AUTO	BDY	PAINTLESS REPAIR	R Quarter Outer Panel	Sublet	237.50	#
41				8 NICKEL SIZE DENTS			
42				8 QUARTER SIZE DENTS			
43	AUTO	BDY	PAINTLESS REPAIR	L Quarter Outer Panel	Sublet	237.50	#
44				10 NICKEL SIZE DENTS			
45				10 QUARTER SIZE DENTS			
46	101795	BDY	REMOVE/INSTALL	Luggage Lid Assy			0.5
47	101797	BDY	REMOVE/INSTALL	Luggage Trim Panel			0.3
48	AUTO	BDY	PAINTLESS REPAIR	Luggage Lid Panel	Sublet	425.00	
49				32 QUARTER SIZE DENTS			
50				6 HALF DOLLAR SIZE DENTS			
51	100462	BDY	REMOVE/INSTALL	R Rear Combination Lamp			0.6 #
52	100463	BDY	REMOVE/INSTALL	L Rear Combination Lamp			0.6 #
53	936012		ADD'L COST	Hazardous Waste Disposal		5.00 *	
54	AUTO	REF	ADD'L OPR	Clear Coat			2.1
55	933005	BDY	ADD'L OPR	Restore Corrosion Protection		10.00 *	

* - Judgment Item
 # - Labor Note Applies
 ** QRP Certified - Quality Replacement Parts - Certified
 ** QUAL REPL PART - Quality Replacement Parts
 C - Included in Clear Coat Calc
 r - CEG R&R Time Used For This Labor Operation

UCC/NEW WORLD-DFW
 1720 E. HWY 356
 (214)352-1191 EXT. 232
 IRVING
 TX 75060
 (214) 352-1191

KEystone-INS QUALITY PRT
 8206 J ST.
 OMAHA
 NE 68127
 (402) 553-0230 (800) 642-1432

8	Sublet	225.00	3	** CH1230305C	952.00
12	Sublet	175.00			

Date: 9/ 7/2021 12:34 PM
 Estimate ID: 8441090011
 Estimate Version: 0
 Committed
 Profile ID: * Mitchell

Recycler Information Section:

McChesney Auto
 2707 Waukon Ave
 Somers IA 50586
 515-467-5546;nofaxnumber

30 2012 Dodge	CHARGER	R.	VA	250.00
Part Number: 20082				
Description:0P2,RH,WHT,DECAL, RIGHT REAR SIDE DOOR				
32 2012 Dodge	CHARGER	L.	VA	400.00
Part Number: 18197				
Description:SCRATCH,PS2 SLV, LEFT REAR SIDE DOOR				

Disclaimer: Recycled part pricing may represent either actual pricing (the price at which the recycler is willing to sell the part for in its existing condition) or undamaged pricing (the price at which the recycler would sell the part if it was in undamaged condition).
 If you are unsure, please contact the automotive recycler.

Remarks

The vehicle has hail damage all over.

Estimate Totals

I. Labor Subtotals		Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary		Amount
Body		15.8	62.00	10.00	3,450.00	4,439.60 T	Taxable Parts		1,178.00
Refinish		7.9	107.00	0.00	0.00	845.30 T	Total Replacement Parts Amount		1,178.00
Taxable Labor						5,284.90			
Labor Summary		23.7				5,284.90			
III. Additional Costs				Amount		IV. Adjustments		Amount	
Taxable Costs				5.00		Insurance Deductible		0.00	
Total Additional Costs				5.00		Customer Responsibility		0.00	
						I. Total Labor:		5,284.90	
						II. Total Replacement Parts:		1,178.00	
						III. Total Additional Costs:		5.00	
						Gross Total:		6,467.90	
						IV. Total Adjustments:		0.00	
						Net Total:		6,467.90	

Point(s) of Impact

16 Non-Collision (P)

Insurance Co: DAS FLEET SERVICES
 DES MOINES, IA 50139
 Work Phone: (877) 544-7843

Inspection Site: Dollar General
 Address: 1430 IA 9
 Larchwood, IA 51241

Inspection Date: 9/ 7/2021

ESTIMATE RECALL NUMBER: 09/07/2021 12:34:43 8441090011

Mitchell Data Version: OEM: JUL_21_V

Alternate Parts: 09/07/2021 12:15:04

Copyright (C) 1994 - 2021 Mitchell International

Software Version: 7.1.241

All Rights Reserved

Due upon receipt

INVOICE

BILL TO Attn: MIKE LONG DAS FLEET SERVICES 109 SE 13TH ST DES MOINESIA 50139	INVOICE NUMBER	INVOICE DATE
	844-0167186	09/07/2021
	CLIENT CODE	
	DAS105001	
	BUSINESS LINE / LOSS TYPE	
	A - Commercial Auto	

FOR INQUIRIES:	SUBMIT PAYMENT TO:
PDA Sioux City, IA #844	Property Damage Appraisers, Inc.
pdasiouxcity@pdaorg.net	75-1160563
(712) 276-4990	Dept #161, P.O. Box 1000
	Memphis, TN 38148-0161
Please reference the invoice number and enclose a copy of the invoice on all payments.	

INSURED	CLAIMANT	ASSIGNMENT DATE	PDA ASSIGNMENT #
STATE OF IOWA		09/02/2021	844-109-0011
CLAIM #	POLICY #	LOSS DATE	REFERENCE #
APDSOI0225415-001			

SERVICE FEE: (1 Unit(s) @ \$179.00) \$ 179.00

Mileage: (37.00 miles) @ \$1.25 \$ 46.25

ACH Payment Info:
Bank: First Horizon Bank
ABA (US): 084000026 Bank
Account: 220002525824
Email Remit Information to:
achbackup@pdaorg.net

Click [here](https://pdaclientportal.com) to pay your invoice at PDAClientPortal.com

Same-Day Service. Guaranteed. PDA now offers expedited service for standard auto claims in select markets.

****WE HAVE CHANGED OUR BANK REMITTANCE INFORMATION AS NOTED ABOVE PLEASE UTILIZE OUR PORTAL FOR ALL OTHER ELECTRONIC PAYMENTS.****

*Terms: Professional fees due upon receipt. Interest accrues at 1% per month.
Please include the invoice number on all payments.*

TOTAL CHARGES:	225.25
INVOICE TOTAL:	\$ 225.25

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: **DPS – Vehicle Damage; DAS – Risk**

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature ☒) CASE #: 2021021219

Date: (Month/Day/Year)	8-28-2021	Time: (Time plus a.m./p.m.)	19:55 p.m.
Vehicle Plate #:	261	Vehicle Mileage:	55,005
Vehicle Description: (Yr/Make/Model/ & Vin#)	2019 DODGE CHARGER VIN # 2C3CDXKT2KH577262		
Assigned To:	Brian Hilt	Badge #	261
Driven By:	Brian Hilt	Badge #	261
Driver's Lic #:	679XX2244	Damage:	\$7018.90
Vehicle Towed: (Yes / No)	No	Towed By:	Not Towed
Towed To:	Not Towed	Towing Cost:	\$Not Towed
Seat Belt: (Yes / No)	Yes	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:	None		
Occupants: (Other than driver)	None		

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Driver's Address:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

Date: 9/ 9/2021 01:41 PM
 Estimate ID: 8441090039
 Estimate Version: 0
 Committed
 Profile ID: * Mitchell

Property Damage Appraisers (PDA Sioux City)

P.O. Box 144, Collins, IA 50055
 (712) 276-4990
 Fax: (712) 276-6609
 Email: pdasiouxcity@pdaorg.net

* Not An Authorization For Repair *
 Read disclaimers following appraisal calculations.

Damage Assessed By: LAYNE MOSHER
 Classification: Field

Appraised For: JESSICA HACKBARTH

Condition Code: Good
 Date of Loss: 8/28/2021
 Deductible: 0.00
 File Number: 8441090039
 Claim Number: APDSOI0225559-001

Type of Loss: Comprehensive

Insured: STATE OF IOWA
 Owner: STATE OF IOWA
 Address: DOON, IA

Mitchell Service: 911667

Description: 2019 Dodge Charger Police
 Body Style: 4D Sed
 VIN: 2C3CDXKT2KH577262
 Mileage: 56,122
 OEM/ALT: A
 Parts Profile: Sioux City
 Color: Silver
 Options: POWER DRIVER SEAT, POWER WINDOW, POWER STEERING, POWER BRAKE

Vehicle Production Date: 1/19
 Drive Train: 5.7L Inj 8 Cyl 5A AWD
 License: 261 IA

Parts Profile Version: 2

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	100374	BDY	REMOVE/INSTALL	Frt Bumper Cover			2.0 #
2	100377	BDY	REMOVE/INSTALL	R Front Combination Lamp			0.4 #
3	100389	BDY	REMOVE/INSTALL	L Front Combination Lamp			0.4 #
4	100559	BDY	REMOVE/REPLACE	Hood Panel (Alum)	** QRP Certified	952.00	1.6
5	AUTO	REF	REFINISH	Hood Outside			C 2.8
6	AUTO	REF	REFINISH	Add For Hood Underside			C 1.4
7	100002	REF	BLEND	R Fender Outside			C 0.8
8	100379	REF	BLEND	L Fender Outside			C 0.8
9	AUTO	BDY	PAINTLESS REPAIR	R Fender Panel	** QUAL REPL PART	125.00	#
10				3 QUARTER SIZE DENTS			
11	AUTO	BDY	PAINTLESS REPAIR	L Fender Panel	** QRP Certified	125.00	#
12				2 QUARTER SIZE DENTS			
13	102438	BDY	REMOVE/INSTALL	R Fender Splash Shield	Existing		INC r
14	102439	BDY	REMOVE/INSTALL	L Fender Splash Shield	Existing		INC r
15	900500	BDY*	REMOVE/INSTALL	State Trooper Fender Decals	Existing		0.6* r
16	101303	BDY	PAINTLESS REPAIR	R Door Opening Panel	Sublet	275.00	* 0.0*#
17	101304	BDY	PAINTLESS REPAIR	L Door Opening Panel	Sublet	275.00	* 0.0*#
18	102049	BDY	REMOVE/INSTALL	R Rocker Moulding			0.4
19	102050	BDY	REMOVE/INSTALL	L Rocker Moulding			0.4
20	AUTO	BDY	PAINTLESS REPAIR	R Frt Door Shell (Steel/HSS)	Sublet	125.00	#
21				3 QUARTER SIZE DENTS			
22				1 HALF DOLLAR SIZE DENT			
23	AUTO	BDY	PAINTLESS REPAIR	L Frt Door Shell (Steel/HSS)	Sublet	125.00	#
24				3 QUARTER SIZE DENTS			
25	102091	BDY	REMOVE/INSTALL	R Frt Otr Door Belt Moulding			1.1 #

ESTIMATE RECALL NUMBER: 09/09/2021 13:41:31 8441090039

Mitchell Data Version: OEM: JUL_21_V

Alternate Parts: 09/09/2021 13:14:14

Copyright (C) 1994 - 2021 Mitchell International

Software Version: 7.1.241

All Rights Reserved

Page 1 of 4

Date: 9/ 9/2021 01:41 PM
 Estimate ID: 8441090039
 Estimate Version: 0
 Committed
 Profile ID: * Mitchell

26	102092	BDY	REMOVE/INSTALL	L Frt Otr Door Belt Moulding			1.1	#
27	101468	BDY	REMOVE/REPLACE	L Frt Upr Door Adhesive Moulding	57010505AM	101.00	0.2	
28	AUTO	BDY	PAINTLESS REPAIR	R Rear Door Shell (Steel/HSS)	Sublet	175.00	#	
29				7 QUARTER SIZE DENTS				
30	AUTO	BDY	PAINTLESS REPAIR	L Rear Door Shell (Steel/HSS)	Sublet	175.00	#	
31				7 QUARTER SIZE DENTS				
32	100735	BDY	REMOVE/INSTALL	R Rear Otr Door Belt Moulding			0.2	
33	100736	BDY	REMOVE/INSTALL	L Rear Otr Door Belt Moulding			0.2	
34	AUTO	BDY	PAINTLESS REPAIR	Roof Panel	Sublet	1,090.00	*	
35				77 QUARTER SIZE DENTS				
36				16 HALF DOLLAR SIZE DENTS				
37				LARGE DENT @ \$240.00				
38	900500	BDY*	REMOVE/INSTALL	Emergency Roof Equipment	Existing		1.0*	r
39	AUTO	BDY	PAINTLESS REPAIR	R Quarter Outer Panel	Sublet	175.00	#	
40				8 QUARTER SIZE DENTS				
41	AUTO	BDY	PAINTLESS REPAIR	L Quarter Outer Panel	Sublet	175.00	#	
42				7 QUARTER SIZE DENTS				
43				2 HALF DOLLAR SIZE DENTS				
44	103148	BDY	REMOVE/REPLACE	Luggage Lid Panel	68312401AG	520.00	1.8	
45	AUTO	REF	REFINISH	Luggage Lid Outside			C 2.2	
46	AUTO	BDY	REMOVE/REPLACE	Add w/Rear View Camera			0.4	
47	AUTO	REF	REFINISH	Luggage Lid Underside			C 1.0	
48	900500	BDY*	REMOVE/INSTALL	Luggage Lid Emergency Equipment	Existing		3.0*	r
49	100462	BDY	REMOVE/INSTALL	R Rear Combination Lamp			0.6	#
50	100463	BDY	REMOVE/INSTALL	L Rear Combination Lamp			0.6	#
51	936012		ADD'L COST	Hazardous Waste Disposal		5.00	*	
52	933002	REF	ADD'L OPR	Clear Coat			2.5*	
53	933003	REF	ADD'L OPR	Tint Color			0.5*	
54	933005	BDY	ADD'L OPR	Restore Corrosion Protection		10.00	*	
55	933018	REF	ADD'L OPR	Mask For Overspray		5.00	*	0.2*

* - Judgment Item
 # - Labor Note Applies
 ** QRP Certified - Quality Replacement Parts - Certified
 ** QUAL REPL PART - Quality Replacement Parts
 C - Included in Clear Coat Calc
 r - CEG R&R Time Used For This Labor Operation

KEYSTONE-INS QUALITY PRT	UCC/NEW WORLD-DFW	
2400 KERPER BLVD.	1720 E. HWY 356	
STE. E100A	(214)352-1191 EXT. 232	
DUBUQUE	IRVING	
IA 52004	TX 75060	
(319) 566-5030 (800) 747-2500	(214) 352-1191	
4 ** CH1230305C	9 Sublet	125.00
	11 Sublet	125.00

Date: 9/ 9/2021 01:41 PM
 Estimate ID: 8441090039
 Estimate Version: 0
 Committed
 Profile ID: * Mitchell

Recycler Information Section:

McChesney Auto
 2707 Waukon Ave
 Somers IA 50586
 515-467-5546;nofaxnumber

28 2012 Dodge CHARGER R. VA 250.00
 Part Number: 20082
 Description:0P2,RH,WHT,DECAL, RIGHT REAR SIDE DOOR

Disclaimer: Recycled part pricing may represent either actual pricing
 (the price at which the recycler is willing to sell the part for in its
 existing condition) or undamaged pricing (the price at which the recycler
 would sell the part if it was in undamaged condition).
 If you are unsure, please contact the automotive recycler.

Remarks

The vehicle has hail damage all over.

Estimate Totals

		Units	Rate	Add'l Labor Amount	Sublet Amount	Totals			Amount
I.	Labor Subtotals						II.	Part Replacement Summary	
	Body	16.0	62.00	10.00	2,840.00	3,842.00 T		Taxable Parts	1,573.00
	Refinish	12.2	107.00	5.00	0.00	1,310.40 T		Total Replacement Parts Amount	1,573.00
	Taxable Labor					5,152.40			
	Labor Summary	28.2				5,152.40			
III.	Additional Costs					Amount	IV.	Adjustments	Amount
	Taxable Costs					5.00		Insurance Deductible	0.00
	Total Additional Costs					5.00		Customer Responsibility	0.00
							I.	Total Labor:	5,152.40
							II.	Total Replacement Parts:	1,573.00
							III.	Total Additional Costs:	5.00
								Gross Total:	6,730.40
							IV.	Total Adjustments:	0.00
								Net Total:	6,730.40

Point(s) of Impact

16 Non-Collision (P)

Insurance Co: DAS FLEET SERVICES
 DES MOINES, IA 50139
 Work Phone: (877) 544-7843

Inspection Site: Sioux County Sheriff's Office
 Address: 4363 Ironwood Ave
 Orange City, IA 51041
 Inspection Date: 9/ 9/2021

ESTIMATE RECALL NUMBER: 09/09/2021 13:41:31 8441090039

Mitchell Data Version: OEM: JUL_21_V

Alternate Parts: 09/09/2021 13:14:14

Copyright (C) 1994 - 2021 Mitchell International

Software Version: 7.1.241

All Rights Reserved

Due upon receipt

INVOICE

INVOICE NUMBER	INVOICE DATE
844-0167304	09/09/2021

BILL TO
Attn: JESSICA HACKBARTH DAS FLEET SERVICES 109 SE 13TH ST DES MOINESIA 50139

CLIENT CODE
DAS105001
BUSINESS LINE / LOSS TYPE
A - Commercial Auto

FOR INQUIRIES:
PDA Sioux City, IA #844 pdasiouxcity@pdaorg.net (712) 276-4990

SUBMIT PAYMENT TO:
Property Damage Appraisers, Inc. 75-1160563 Dept #161, P.O. Box 1000 Memphis, TN 38148-0161 <i>Please reference the invoice number and enclose a copy of the invoice on all payments.</i>

INSURED	CLAIMANT	ASSIGNMENT DATE	PDA ASSIGNMENT #
STATE OF IOWA		09/09/2021	844-109-0039
CLAIM #	POLICY #	LOSS DATE	REFERENCE #
APDSOI0225559-001		08/28/2021	

SERVICE FEE: (1 Unit(s) @ \$179.00) \$ 179.00

Mileage: (88.00 miles) @ \$1.25 \$ 110.00

ACH Payment Info:
Bank: First Horizon Bank
ABA (US): 084000026 Bank
Account: 220002525824
Email Remit Information to:
achbackup@pdaorg.net

Click [here](https://pdaclientportal.com) to pay your invoice at PDAClientPortal.com

Same-Day Service. Guaranteed. PDA now offers expedited service for standard auto claims in select markets.

****WE HAVE CHANGED OUR BANK REMITTANCE INFORMATION AS NOTED ABOVE PLEASE UTILIZE OUR PORTAL FOR ALL OTHER ELECTRONIC PAYMENTS.****

*Terms: Professional fees due upon receipt. Interest accrues at 1% per month.
Please include the invoice number on all payments.*

TOTAL CHARGES:	289.00
INVOICE TOTAL:	\$ 289.00