

MEMBERS OF COUNCIL

HON. KIM REYNOLDS  
GOVERNOR

HON. PAUL D. PATE  
SECRETARY OF STATE

HON. ROB SAND  
AUDITOR OF STATE

HON. ROBY SMITH  
TREASURER OF STATE

HON. MIKE. NAIG  
SECRETARY OF AGRICULTURE



## Executive Council of Iowa

CAPITOL BUILDING  
DES MOINES, IOWA 50319  
PHONE: 515 281-5368

July 15, 2024

Accounting Department  
Office of the Treasurer  
Lucas Building  
321 E 12<sup>th</sup> Street  
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for a supplemental emergency allocation in the amount of \$604.40. This brings the total allocation and payment to \$4,845.57. On March 26, 2024, Vehicle #109 was damaged by a deer. Request was to cover repair costs.

This represents full and final payment.

EXECUTIVE COUNCIL OF IOWA

*Kristi Onstot*

Kristi Onstot  
Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services  
DAS Fleet Services, Risk  
Matt Bender, Department of Management  
Heather Hackbarth, Department of Management

AOS Claim # 3722  
TOS Job # \_\_\_\_\_



OFFICE OF AUDITOR OF STATE  
STATE OF IOWA

Rob Sand  
Auditor of State

State Capitol Building  
Des Moines, Iowa 50319-0004  
Telephone (515) 281-5834 Facsimile (515) 281-6518

July 3, 2024

Kristi Onstot  
Executive Council  
L O C A L

Subject: Deer Damage to Vehicle #109 on March 26, 2024  
Department of Administrative Services  
Claim dated March 28, 2024  
AOS Claim ID: 3722

The Department's request included a supplemental allocation request of \$604.40 because additional damages were identified. We recommend Executive Council approval of the supplemental allocation of \$604.40, which increases the allocation to \$4,845.57. In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to this loss. We have found the items to be in order as shown below:

Documented request			\$	<u>4,845.57</u>
Executive Council allocation (Revised)			\$	4,845.57
Less:				
Previous payments	\$	0.00		
This payment		<u>4,845.57</u>		
Total			\$	<u>4,845.57</u>
Remaining Executive Council allocation			\$	<u>0.00</u>

We recommend that reimbursement be made in the amount of \$4,845.57. This represents full and final payment on this allocation.

Sincerely,

Brian R. Brustkern, CPA  
Deputy Auditor of State

CC: Adam Steen, Director, Department of Administrative Services  
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services



Governor Kim Reynolds  
Lt. Governor Adam Gregg  
Adam Steen, Director

Date: May 14, 2024

To: Tammy Hollingsworth, Auditor of State  
Victoria Newton, Treasurer of State  
Executive Council

From: Karl Bubser, Fleet Administrator  
DAS Fleet Services  
Department of Administrative Services

Re: **REIMBURSEMENT REQUEST - 29C20 Claim**

AOS Claim #	3722
Vehicle / Event	#109/Animal
Event Date	March 26, 2024
Summary	Vehicle 109 struck a deer. (277662)
Amount Requested	<b>\$4,845.57 - TOTAL</b>

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: **0665-005-5790-0657**.

If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,

Karl Bubser, Fleet Administrator  
DAS Fleet Services  
karl.bubser@iowa.gov  
515-281-3162

# Warrants

Edit

Cancel

\* Required fields

## Warrant Information

<b>Fiscal Year</b> 2024	<b>Amount</b> \$4,845.57	<b>Warrant Number</b> 73042205
<b>Vendor Customer</b> 00003030887	<b>Line Number</b> 1	<b>Last Updated</b> 05/08/2024 09:26 PM

## Issue Information

<b>Issued</b> 05/08/2024 12:00 AM	<b>Void</b> No	<b>Transaction ID</b> RISK00524128003
<b>Duplicate</b> No	<b>Transaction Line Number</b> 1	<b>Stop</b> No
<b>Line Amount</b> \$1,162.80	<b>Comments</b>	

## Redeemed Information

<b>Redeemed</b> -	<b>Batch Number</b> -	<b>Redeemed Bank</b> -
<b>Sequence Number</b> -	<b>Redeemed Fund</b> -	<b>Redeemed Department</b> -

## COA

<b>Fund</b> 0665	<b>Object</b> 2715	<b>Dept Object</b> -
<b>Sub Fund</b> -	<b>Sub Object</b> -	<b>Dept Revenue</b> -
<b>Department</b> 005	<b>Unit</b> 5790	<b>Sub Unit</b> -
<b>Object Class</b> -	<b>Revenue Source</b> -	<b>Sub Revenue Source</b> -
<b>Appropriation</b> 0000	<b>Revenue Source Class</b> -	<b>BSA</b> -
<b>Sub BSA</b> -		

▶ Show More

# Warrants

Edit

Cancel

\* Required fields

## Warrant Information

<b>Fiscal Year</b> 2024	<b>Amount</b> \$4,845.57	<b>Warrant Number</b> 73042205
<b>Vendor Customer</b> 00003030887	<b>Line Number</b> 2	<b>Last Updated</b> 05/08/2024 09:26 PM

## Issue Information

<b>Issued</b> 05/08/2024 12:00 AM	<b>Void</b> No	<b>Transaction ID</b> RISK00524128003
<b>Duplicate</b> No	<b>Transaction Line Number</b> 2	<b>Stop</b> No
<b>Line Amount</b> \$238.00	<b>Comments</b>	

## Redeemed Information

<b>Redeemed</b> -	<b>Batch Number</b> -	<b>Redeemed Bank</b> -
<b>Sequence Number</b> -	<b>Redeemed Fund</b> -	<b>Redeemed Department</b> -

## COA

<b>Fund</b> 0665	<b>Object</b> 2715	<b>Dept Object</b> -
<b>Sub Fund</b> -	<b>Sub Object</b> -	<b>Dept Revenue</b> -
<b>Department</b> 005	<b>Unit</b> 5790	<b>Sub Unit</b> -
<b>Object Class</b> -	<b>Revenue Source</b> -	<b>Sub Revenue Source</b> -
<b>Appropriation</b> 0000	<b>Revenue Source Class</b> -	<b>BSA</b> -
<b>Sub BSA</b> -		

▶ Show More

# Warrants

Edit

Cancel

\* Required fields

## Warrant Information

<b>Fiscal Year</b> 2024	<b>Amount</b> \$4,845.57	<b>Warrant Number</b> 73042205
<b>Vendor Customer</b> 00003030887	<b>Line Number</b> 3	<b>Last Updated</b> 05/08/2024 09:26 PM

## Issue Information

<b>Issued</b> 05/08/2024 12:00 AM	<b>Void</b> No	<b>Transaction ID</b> RISK00524128003
<b>Duplicate</b> No	<b>Transaction Line Number</b> 3	<b>Stop</b> No
<b>Line Amount</b> \$989.00	<b>Comments</b>	

## Redeemed Information

<b>Redeemed</b> -	<b>Batch Number</b> -	<b>Redeemed Bank</b> -
<b>Sequence Number</b> -	<b>Redeemed Fund</b> -	<b>Redeemed Department</b> -

## COA

<b>Fund</b> 0665	<b>Object</b> 2715	<b>Dept Object</b> -
<b>Sub Fund</b> -	<b>Sub Object</b> -	<b>Dept Revenue</b> -
<b>Department</b> 005	<b>Unit</b> 5790	<b>Sub Unit</b> -
<b>Object Class</b> -	<b>Revenue Source</b> -	<b>Sub Revenue Source</b> -
<b>Appropriation</b> 0000	<b>Revenue Source Class</b> -	<b>BSA</b> -
<b>Sub BSA</b> -		

▶ Show More

# Warrants

Edit

Cancel

\* Required fields

## Warrant Information

<b>Fiscal Year</b> 2024	<b>Amount</b> \$4,845.57	<b>Warrant Number</b> 73042205
<b>Vendor Customer</b> 00003030887	<b>Line Number</b> 4	<b>Last Updated</b> 05/08/2024 09:26 PM

## Issue Information

<b>Issued</b> 05/08/2024 12:00 AM	<b>Void</b> No	<b>Transaction ID</b> RISK00524128003
<b>Duplicate</b> No	<b>Transaction Line Number</b> 4	<b>Stop</b> No
<b>Line Amount</b> \$2,455.77	<b>Comments</b>	

## Redeemed Information

<b>Redeemed</b> -	<b>Batch Number</b> -	<b>Redeemed Bank</b> -
<b>Sequence Number</b> -	<b>Redeemed Fund</b> -	<b>Redeemed Department</b> -

## COA

<b>Fund</b> 0665	<b>Object</b> 2715	<b>Dept Object</b> -
<b>Sub Fund</b> -	<b>Sub Object</b> -	<b>Dept Revenue</b> -
<b>Department</b> 005	<b>Unit</b> 5790	<b>Sub Unit</b> -
<b>Object Class</b> -	<b>Revenue Source</b> -	<b>Sub Revenue Source</b> -
<b>Appropriation</b> 0000	<b>Revenue Source Class</b> -	<b>BSA</b> -
<b>Sub BSA</b> -		

Show More



# DURANT COLLISION REPAIR

durantcollision@iowatelecom.net  
 1303 5th St, P O Box 638, DURANT, IA 52747  
 Phone: (563) 785-6353  
 FAX: (563) 785-6659

Workfile ID: 6465a242  
 PartsShare: 7RLphb  
 Federal ID: 202958038

## Final Bill

### RO Number: 1742

Customer:	Insurance:	Adjuster:	Estimator:	Craig Moeller
Iowa State Patrol		Phone:	Create Date:	3/26/2024
22365 20th Ave.		Claim:	APDSOI277662-001	
Stockton, IA 52769		Loss Date:		
(563) 284-9501		Deductible:		

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI silver

VIN: 2C3CDXKT1KH622773	Interior Color:	Mileage In: 135,935	Vehicle Out:
License: 109	Exterior Color: silver	Mileage Out:	
State: IA	Production Date: 3/2019	Condition: Good	Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		<b>FRONT BUMPER &amp; GRILLE</b>						
2	E01	Repair	Bumper cover				3.5	Body	3.4
3	E01		Add for Clear Coat						1.4
4	E01	Remove/Install	PUSH BAR AND WRAP				2.0	Body	
5	E01	Alignment	PUSH BAR AND WRAP				1.0	Body	
6	E01	Remove/Install	REMOVE AND REINSTALL BLACK APPLIQUE				1.0	Body	
7	E01	Remove/Replace	RT Air duct	1	68.40	OEM			
8	E01	Remove/Replace	RT Bumper bracket	1	42.45	OEM	0.1	Body	
9	E01	Remove/Replace	LT Support inner	1	30.00	OEM			
10	E01	Remove/Replace	LT Support outer	1	12.10	OEM			
11	S01	Remove/Replace	Upper grille black crossbars	1	369.00	A/M	0.7	Body	
12	S01	Remove/Replace	Closure panel	1	181.00	A/M	0.1	Body	
13	E01		<b>FRONT LAMPS</b>						
14	E01	Remove/Replace	LT Headlamp assy halogen	1	851.00	OEM	0.4	Body	
15	E01	Remove/Replace	Aim headlamps				0.5	Body	
16	E01		<b>RADIATOR SUPPORT</b>						
17	E01	Remove/Replace	Front shield w/police	1	222.82	OEM	0.4	Body	
18	E01	Remove/Replace	Splash shield AWD w/police	1	135.00	OEM	0.2	Body	
19	E01	Remove/Replace	Radiator support	1	296.00	OEM	1.0	Body	1.6
20	E01	Remove/Replace	Evacuate & recharge				1.4	Mech	
21	E01	Remove/Replace	Refrigerant recovery				0.4	Mech	
22	E01		<b>FENDER</b>						
23	E01	Repair	LT Fender				4.0	Body	2.0
24	E01		Overlap Major Non-Adj. Panel						(0.2)
25	E01		Add for Clear Coat						0.4
26	E01	Remove/Install	Decal"State Trooper"				0.6	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural



**Final Bill**

**RO Number: 1742**

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI silver

27	E01	Remove/Replace	LT Fender liner 3.6, 5.7 liter	1	114.00	OEM	0.3	Body
28	E01		***** ADD-ONS *****			A/M		
29	E01	Remove/Replace	Cover Car	1	10.00	Other		
30	E01	Repair	Color sand and buff				1.0	Body
31	E01	Remove/Replace	Corrosion protection primer	1	10.00	Other		
32	E01	Remove/Replace	RT Fender liner 3.6, 5.7 liter	1	114.00	OEM	0.3	Body
33	E01		<b>VEHICLE DIAGNOSTICS</b>					
34	E01		Pre-repair scan			OEM	0.5	Mech
35	E01		Post-repair scan			OEM	0.5	Mech

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					2,455.77
Labor, Body			68.00	17.1	1,162.80
Labor, Refinish			115.00	8.6	989.00
Labor, Mechanical			85.00	2.8	238.00
<b>Subtotal</b>					<b>4,845.57</b>
Sales Tax					0.00
<b>Grand Total</b>					<b>4,845.57</b>
<b>Net Total</b>					<b>4,845.57</b>

Estimate Version	Total \$
Original	4,241.17
Supplement S01	604.40

Insurance Total \$:	4,845.57
Received from Insurance \$:	0.00
<b>Balance due from Insurance \$:</b>	<b>4,845.57</b>
Customer Total \$:	0.00
Received from Customer \$:	0.00
<b>Balance due from Customer \$:</b>	<b>0.00</b>

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural



Governor Kim Reynolds  
Lt. Governor Adam Gregg  
Adam Steen, Director

Date: March 28, 2024

To: Tammy Hollingsworth, Auditor of State  
Victoria Newton, Treasurer of State  
Executive Council

From: Karl Bubser, Fleet Administrator  
DAS Fleet Services  
Department of Administrative Services

**Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration**

Vehicle / Event	#109/Animal
Event Date	March 26, 2024
Summary	Vehicle 109 struck a deer. (277662)
Amount Requested	\$4,241.17 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Karl Bubser, Fleet Administrator  
DAS Fleet Services  
Karl.Bubser@iowa.gov  
515-281-3162



Risk, DAS &lt;das.risk@iowa.gov&gt;

---

**Fwd: Trooper Smith #109 Car Vs. Deer.**

1 message

Risk, DAS &lt;das.risk@iowa.gov&gt;

Wed, Mar 27, 2024 at 11:14 AM

To: Jeannie R Adams &lt;jadams@dps.state.ia.us&gt;, "Guill, Bryan [DPS]" &lt;guill@dps.state.ia.us&gt;, Tammy Hollingsworth &lt;Tammy.Hollingsworth@aos.iowa.gov&gt;, TOS ExecutiveCouncil &lt;executivecouncil@tos.iowa.gov&gt;

Please accept this email as initial 24 hr notification for AON, vehicle 109 struck a deer on 3/26/2024. I will forward all information as soon as it is received.

**All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.**

Thank you,

**DAS Risk**

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

109 SE 13<sup>th</sup> St, Des Moines, IA 50319

515-281-3162 office

[das.risk@iowa.gov](mailto:das.risk@iowa.gov)<https://das.iowa.gov>Department of  
Administrative Services

----- Forwarded message -----

From: **Saldivar David** <saldivar@dps.state.ia.us>

Date: Wed, Mar 27, 2024 at 7:57 AM

Subject: Trooper Smith #109 Car Vs. Deer.

To: das.risk@iowa.gov &lt;das.risk@iowa.gov&gt;, vehicledamage &lt;vehicledamage@dps.state.ia.us&gt;

Cc: post12sup &lt;post12sup@dps.state.ia.us&gt;, Guill Bryan &lt;guill@dps.state.ia.us&gt;

Please let us know if you need anything else. Thank You!

Sergeant David Saldivar **281**

Iowa State Patrol / District 12

22365 20<sup>th</sup> Avenue

## State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: [vehicledamage@dps.state.ia.us](mailto:vehicledamage@dps.state.ia.us) ; [das.risk@iowa.gov](mailto:das.risk@iowa.gov)

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

**STATE VEHICLE: (Mark if Act of Nature  ) CASE #: 2024007631**

Date: <small>(Month/Day/Year)</small>	03/26/2024	Time: <small>(Time plus a.m./p.m.)</small>	6:18 AM
Vehicle Plate #:	109	Vehicle Mileage:	135887
Vehicle Description: <small>(Yr/Make/Model/ &amp; Vin#)</small>	2019 Dodge Charger VIN: 2C3CDXKT1KH622773		
Assigned To:	Trp. Smith	Badge #	109
Driven By:	Trp. Smith	Badge #	109
Driver's Lic #:	220DD5706	Damage:	\$4241.17
Vehicle Towed: <small>(Yes / No)</small>	NO	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$0.00
Seat Belt: <small>(Yes / No)</small>	Yes	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Marked
Injured/Injuries:	None		
Occupants: <small>(Other than driver)</small>	None		

**VEHICLE #2:**

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

**OTHER INFORMATION:**

Witnesses:	None
Accident Location: (Street/Hwy)	Hwy 64 EB at Jct of Lead Mine Rd.
County:	Jones
Weather/Road Conditions:	Clear/Dry
Unit 1 struck a deer.	
Property Damage other than Vehicles:	None
Cost:	\$ 0.00
Citations Issued To: (List Charge(s) and Statute Code(s))	None

Investigating Officer:	Sgt. Saldivar
------------------------	---------------

**VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)**

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

**INVESTIGATING OFFICER'S REPORT  
OF MOTOR VEHICLE ACCIDENT**

Law Enforcement Case Number:

**2024007631**

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Date of Accident <b>03/26/2024</b>		Time of Accident <b>06:18</b> Hrs.		County <b>JONES - 53</b>		Accident occurred within corporate limits of (city)														
<b>UNIT 1</b>	Driver's Name - Last <b>SMITH</b>					First <b>BLAINE</b>			Middle <b>ROBERT</b>											
	Address <b>22365 20TH AVE</b>					City <b>STOCKTON</b>			State <b>IA</b>	Zip <b>52769</b>										
	Date of Birth <b>03/13/1993</b>		Driver's License Number <b>220DD5706</b>		CDL	Citation Charge 1		Citation Charge 2												
	Male <input checked="" type="radio"/>	Female <input type="radio"/>	State <b>IA</b>	Class <b>C</b>	Endorsements	Restrictions	Yes <input type="radio"/> No <input checked="" type="radio"/>	Citation Charge 3		Citation Charge 4										
	Alcohol Test Given: <b>1</b>		Test Results:		Drug Test Given: <b>1</b>	Test Result:	Re-exam: Yes <input type="radio"/> No <input checked="" type="radio"/>	Reason for Re-Exam Request:												
	Owner's Name - Last <b>STATE OF IOWA</b>					First			Middle											
	Address <b>109 SE 13TH ST</b>					City <b>DES MOINES</b>			State <b>IA</b>	Zip <b>50319</b>										
	License Plate No. <b>109</b>	State <b>IA</b>	Year	VIN: <b>2C3CDXKT1KH622773</b>		Color <b>SIL</b>	Year <b>2019</b>	Make <b>DODG</b>	Model <b>CHARGER POLI</b>	Style <b>4D</b>										
	Trailer Plate No.	State	Year	VIN:		Tow <b>1</b>	Tow #	Towed To	Approx. Cost to Repair or Replace <b>\$4,241.00</b>											
	Insurance Company Name					Insurance Co. Phone Number		Insurance Policy Number												
Initial Travel Direction	Veh. Act.	Veh. Config. <b>01</b>	Cargo Body Type <b>01</b>	Veh. Defect	Point of Initial Impact	Most Damaged Area	Extent of Damage	Total Occ. in Veh. <b>1</b>												
Special Veh. Func.	Emergency Status	Bus Use	Driver Condition	Vision Obscured	Contributing Circumstances Driver (up to two) <b>88</b>		Driver Distractions <b>02</b>	Speed Limit												
Traffic Controls	Horizontal Alignment	Vertical Alignment	SEQUENCE OF EVENTS	First Event	Second Event	Third Event	Fourth Event	Most Harmful Event												
<b>COMMERCIAL</b>	Carrier Name/Lessee																			
	Street Address					City			State	Zip Code										
	Number of Axles		Gross Vehicle Weight Rating			US DOT Number		MC Number		Underride/Override										
	Haz Mat Involvement	Haz Mat Placard	Placard Number	Haz. Mat Released	Haz Mat Class	Haz Mat Name														
	Trailer Plate:	State	Year	VIN																
	Trailer Plate:	State	Year	VIN																
	Converter Dolly	Dolly Plate:	State	Plate Year	VIN															
					Sex	Seating Position	Injury Status	Occupant Protection	Airbag Deployment	Ejection	Ejection Path	Traps/extricates	Source of Transport	01	01					
	DRIVER OF UNIT 1					Phone Number:					Transported to:					Transported by:				
	Name					Phone Number					DOB:									
Address					Transported to:					Transported by:										
Name					Phone Number					DOB:										
Address					Transported to:					Transported by:										
Name					Phone Number					DOB:										
Address					Transported to:					Transported by:										
Name					Phone Number					DOB:										
Address					Transported to:					Transported by:										
<b>PERSONS INJURED</b>	Name					Phone Number					DOB:									
	Address					Transported to:					Transported by:									

INVESTIGATING OFFICER'S REPORT OF MOTOR VEHICLE ACCIDENT

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Law Enforcement Case Number: 2024007631

LOCATIONS: Date of Accident 03/26/2024, Time of Accident 06:18 Hrs., County JONES - 53, Accident occurred within corporate limits of (city) Legal Intervention? Private Property? Literal Description IA 64 E AND LEAD MINE RD, X Coordinate: 645842.125, Y Coordinate: 4660804

ACCIDENT ENVIRONMENT: Location of First Harmful Event, Weather Conditions, Manner of Crash/Collision, Light Conditions, ROADWAY CHARACTERISTICS: Major Contributing Circumstances Environment, Roadway, Type of Roadway Junction/Feature, FRA No.

First Harmful Event (Crash) 31, WORKZONE RELATED?, Yes No, Activity, Location, Type, Workers Present

NONMOTORISTS: Name 001, Phone Number, DOB, Address, Alcohol Test Given, Test Results, Drug Test Given, Result, Charged, Yes No

PROPERTY DAMAGE: If Property other than vehicles damaged explain, Object Damaged, Estimate of Damage, Owner's Last Name, First Name, Middle Name, Phone Number, Address, City, State, Zip Code, Was owner or tenant notified?

WITNESSES: Last Name, First Name, Address, City, State, Zip Code, Phone Number

Is This a Secondary Crash? Y N, Type of Primary Incident, Roadway Clearance Date 03/26/2024, Incident Clearance Date 03/26/2024, Signature of Officer TROOPER M KLEBE, Badge Number 172, Time Officer Notified of Accident 06:32 Hrs., Roadway Clearance Time 06:24 Hrs., Incident Clearance Time 11:20 Hrs., Name of Agency PCV, Date of Report 03/26/2024, Time Officer Arrived At Scene 11:00 Hrs., Total Roadway Clearance Time 000:06, Total Incident Clearance Time 005:02, Report Reviewed By, Date of Review, Investigation made at scene? Y N, T.I. No., Other Technical Investigating Agency



INVESTIGATING OFFICER'S REPORT  
OF MOTOR VEHICLE ACCIDENT

Form 4433003 (11-13)

Law Enforcement Case Number:


2024007631

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

D  
I  
A  
G  
R  
A  
M



HWY 64 EB AND LEAD MINE RD



N  
A  
R  
R  
A  
T  
I  
V  
E

Unit 1 was traveling EB on Hwy 64 near Lead Mine Rd. Unit 1 struck a deer.


# DURANT COLLISION REPAIR

1303 5th St, P O Box 638, DURANT, IA 52747

Phone: (563) 785-6353, Fax: (563) 785-6659

## Image Report

Owner:	Iowa State Patrol	Insurance:		Estimator:	Craig Moeller	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2019	Color:	silver	License Plate:	109	Production Date:	3/2019
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	135,935
Model:	Charger Police AW...	Engine:	8-5.7L Gasoline S...	VIN:	2C3CDXKT1KH622773	Condition:	Good



3/26/2024

Comments:



3/26/2024

Comments: LF



3/26/2024

Comments: RF




3/26/2024

Comments: RR



3/26/2024

Comments: LR



3/26/2024

Comments: ODOMETER 135,935

# DURANT COLLISION REPAIR

1303 5th St, P O Box 638, DURANT, IA 52747

Phone: (563) 785-6353, Fax: (563) 785-6659


## Image Report

Owner:	Iowa State Patrol	Insurance:		Estimator:	Craig Moeller	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2019	Color:	silver	License Plate:	109	Production Date:	3/2019
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	135,935
Model:	Charger Police AW...	Engine:	8-5.7L Gasoline S...	VIN:	2C3CDXKT1KH622773	Condition:	Good




3/26/2024

Comments: FRONT



3/26/2024

Comments: REPAIR FENDER




3/26/2024

Comments: LT HEADLAMP




3/26/2024

Comments: LT FENDER



3/26/2024

Comments: REPAIR BUMPER



3/26/2024

Comments: LF

# DURANT COLLISION REPAIR

1303 5th St, P O Box 638, DURANT, IA 52747

Phone: (563) 785-6353, Fax: (563) 785-6659

## Image Report

Owner:	Iowa State Patrol	Insurance:		Estimator:	Craig Moeller	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2019	Color:	silver	License Plate:	109	Production Date:	3/2019
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	135,935
Model:	Charger Police AW...	Engine:	8-5.7L Gasoline S...	VIN:	2C3CDXKT1KH622773	Condition:	Good




3/26/2024

Comments: LICENSE



3/26/2024

Comments:



3/26/2024

Comments: undercover front gone



3/26/2024

Comments: rt liner and ducts gone



3/26/2024

Comments: undercover rear gone



3/26/2024

Comments: lt liner


# DURANT COLLISION REPAIR

1303 5th St, P O Box 638, DURANT, IA 52747

Phone: (563) 785-6353, Fax: (563) 785-6659

## Image Report

Owner:	Iowa State Patrol	Insurance:		Estimator:	Craig Moeller	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2019	Color:	silver	License Plate:	109	Production Date:	3/2019
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	135,935
Model:	Charger Police AW...	Engine:	8-5.7L Gasoline S...	VIN:	2C3CDXKT1KH622773	Condition:	Good



3/26/2024  
Comments: VINTAG



3/26/2024 E01  
Comments: radiator support



3/26/2024 E01  
Comments: It side bumper brackets



## MEMORANDUM

**TO:** SGT. SALDIVAR

**FROM:** TRP. SMITH

**DATE:** 3/26/2024

**SUBJECT:** CAR VS. DEER

Sgt. Saldivar,

On 3/26/24 at approximately 0618hrs, I hit a deer that was crossing Highway 64 SE of Anamosa. My milage at that time was 135887. The damage was minimal, breaking the left headlight cover and took a tiny chunk out of the grill. I have already taken it to Durant Collision for an estimate.

Thanks,  
Trooper Blaine Smith #109



# DURANT COLLISION REPAIR

durantcollision@iowatelecom.net  
1303 5th St, P O Box 638, DURANT, IA 52747  
Phone: (563) 785-6353  
FAX: (563) 785-6659

Workfile ID: 6465a242  
PartsShare: 7RLphb  
Federal ID: 202958038  
State ID: 116006756

## Preliminary Estimate

**Customer: Iowa State Patrol**

Written By: Craig Moeller

Insured: Iowa State Patrol  
Type of Loss:  
Point of Impact: 11 Left Front

Policy #:  
Date of Loss:

Claim #:  
Days to Repair: 0

**Owner:**  
Iowa State Patrol  
22365 20th Ave.  
Stockton, IA 52769  
(563) 284-9501 Day

**Inspection Location:**  
DURANT COLLISION REPAIR  
1303 5th St  
P O Box 638  
DURANT, IA 52747  
Repair Facility  
(563) 785-6353 Business

**Insurance Company:**

## VEHICLE

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI silver

VIN: 2C3CDXKT1KH622773 Interior Color: Mileage In: 135,935 Vehicle Out:  
License: 109 Exterior Color: silver Mileage Out:  
State: IA Production Date: 3/2019 Condition: Good Job #:

### TRANSMISSION

Automatic Transmission  
4 Wheel Drive

### POWER

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors  
Power Driver Seat

### DECOR

Dual Mirrors  
Tinted Glass  
Overhead Console

### CONVENIENCE

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Keyless Entry  
Message Center  
Steering Wheel Touch Controls

Telescopic Wheel

Climate Control

Backup Camera

Parking Sensors

### RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

### SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

### SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

### WHEELS

Styled Steel Wheels

### PAINT

Clear Coat Paint

### OTHER

Traction Control

Stability Control

California Emissions

Power Trunk/Liftgate

Get live updates at [www.carwise.com/e/4KATJ3](http://www.carwise.com/e/4KATJ3)

**Preliminary Estimate**

**Customer: Iowa State Patrol**

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI silver

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
<b>1 FRONT BUMPER &amp; GRILLE</b>							
2	* <>	Rpr Bumper cover				3.5	3.4
3		Add for Clear Coat					1.4
4	#	R&I PUSH BAR AND WRAP				2.0	
5	#	Algn PUSH BAR AND WRAP				1.0	
		Note: PULL AND ALIGN					
6	#	R&I REMOVE AND REINSTALL BLACK APPLIQUE				1.0	
		Note: TO PAINT BUMPER SILVER AFTER CRACK REPAIRS					
7		Repl RT Air duct	68214812AA	1	68.40		
8		Repl RT Bumper bracket	68226544AB	1	42.45	0.1	
9	*	Repl LT Support inner	68226533AA	1	30.00		
10		Repl LT Support outer	68213538AC	1	12.10		
<b>11 FRONT LAMPS</b>							
12	*	Repl LT Headlamp assy halogen	68541681AA	1	851.00	0.4	
13		Aim headlamps				0.5	
<b>14 RADIATOR SUPPORT</b>							
15	*	Repl Front shield w/police	68231862AA	1	222.82	0.4	
16		Repl Splash shield AWD w/police	4806075AB	1	135.00	0.2	
17	*	Repl Radiator support	68200478AC	1	296.00	1.0	1.6
18		Evacuate & recharge				m 1.4 M	
19		Refrigerant recovery				m 0.4 M	
<b>20 FENDER</b>							
21	*	Rpr LT Fender				4.0	2.0
22		Overlap Major Non-Adj. Panel					-0.2
23		Add for Clear Coat					0.4
24	#	R&I Decal"State Trooper"				0.6	
25	*	Repl LT Fender liner 3.6, 5.7 liter	68205937AH	1	114.00	0.3	
26	**	A/M ***** ADD-ONS *****		1			
27	#	Repl Cover Car		1	10.00		
28	#	Rpr Color sand and buff				1.0	
29	#	Repl Corrosion protection primer		1	10.00		
30	*	Repl RT Fender liner 3.6, 5.7 liter	68205936AH	1	114.00	0.3	
<b>31 VEHICLE DIAGNOSTICS</b>							
32	*	Pre-repair scan		1		m 0.5 M	
33	*	Post-repair scan		1		m 0.5 M	
<b>SUBTOTALS</b>					<b>1,905.77</b>	<b>19.1</b>	<b>8.6</b>



**Preliminary Estimate**

**Customer: Iowa State Patrol**

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI silver

**ESTIMATE TOTALS**

<b>Category</b>	<b>Basis</b>	<b>Rate</b>	<b>Cost \$</b>
Parts			1,905.77
Body Labor	16.3 hrs @	\$ 68.00 /hr	1,108.40
Paint Labor	8.6 hrs @	\$ 115.00 /hr	989.00
Mechanical Labor	2.8 hrs @	\$ 85.00 /hr	238.00
Subtotal			4,241.17
<b>Grand Total</b>			<b>4,241.17</b>
Deductible			0.00
<b>CUSTOMER PAY</b>			<b>0.00</b>
<b>INSURANCE PAY</b>			<b>4,241.17</b>

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

## Preliminary Estimate

### Customer: Iowa State Patrol

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI silver

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 03/15/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

#### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

#### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

#### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

**Preliminary Estimate**

**Customer: Iowa State Patrol**

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI silver

**PARTS SUPPLIER LIST**

<b>Line</b>	<b>Supplier</b>	<b>Description</b>	<b>Price</b>
9	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68226533AA LT Support inner Quote: 2040384381 Expires: 04/24/24	\$ 30.00
12	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68541681AA LT Headlamp assy halogen Quote: 2044769575 Expires: 04/24/24	\$ 851.00
15	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68231862AA Front shield w/police Quote: 2044389914 Expires: 04/24/24	\$ 222.82
17	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68200478AC Radiator support Quote: 2044392891 Expires: 04/24/24	\$ 296.00
25	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68205937AH LT Fender liner 3.6, 5.7 liter Quote: 2043783759 Expires: 04/24/24	\$ 114.00
30	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68205936AH RT Fender liner 3.6, 5.7 liter Quote: 2046758737 Expires: 04/24/24	\$ 114.00

**Preliminary Estimate**

**Customer: Iowa State Patrol**

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI silver

**ALTERNATE PARTS USAGE**

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI silver

VIN: 2C3CDXKT1KH622773 Interior Color: Mileage In: 135,935 Vehicle Out:  
License: 109 Exterior Color: silver Mileage Out:  
State: IA Production Date: 3/2019 Condition: Good Job #:

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	0	1
Optional OEM	Automatically List	0	0
Reconditioned	Automatically List	0	0
Recycled	N/A	0	0