



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: September 8, 2022

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#414/Wind
Event Date	December 7, 2021
Summary	Vehicle #414 sustained wind damage. (230690)
Amount Requested	\$2,041.60 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-414-6582



Risk, DAS <das.risk@iowa.gov>

Fwd: FW: Vehicle damage to driver's door 12/07/2021

1 message

Risk, DAS <das.risk@iowa.gov>
To: Electronic Claims <eclaims@creativerisksolutions.com>

Tue, Dec 21, 2021 at 10:09 AM

Vehicle 414
Agency 595

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



DAS Fleet Services, Risk
Iowa Department of Administrative Services
Division of Business and Property Services
Office: 515-725-2243
Das.Risk@iowa.gov
<https://das.iowa.gov>

----- Forwarded message -----

From: **Adams Jeannie** <jadams@dps.state.ia.us>
Date: Wed, Dec 8, 2021 at 2:15 PM
Subject: FW: Vehicle damage to driver's door 12/07/2021
To: Tammy.Hollingsworth@auditor.state.ia.us <Tammy.Hollingsworth@auditor.state.ia.us>, executivecouncil@tos.iowa.gov <executivecouncil@tos.iowa.gov>
Cc: DAS.Risk@iowa.gov <DAS.Risk@iowa.gov>

Good afternoon

We were notified today that while 414 was out on patrol the wind caught his door and sprung the hinges.

The pictures and SVD report are attached. An estimate will be forthcoming. We will supply more information as it comes in.

Thank you

Jeannie Adams
ISP Fleet & Supply, Fleet Asset Manager
Department of Public Safety
30 N.E. 48th Place

Des Moines, Iowa 50313

Direct #: 515-725-0643

Cell Phone: 515-204-3019

Shop: 515-281-3277

Fax: 515-242-6321

Email: jadams@dps.state.ia.us

From: J alas Dean <jalas@dps.state.ia.us>

Sent: Wednesday, December 8, 2021 9:52 AM

To: Guill Bryan <guill@dps.state.ia.us>; Adams Jeannie <jadams@dps.state.ia.us>

Cc: J alas Dean <jalas@dps.state.ia.us>; Morey Russell <morey@dps.state.ia.us>; Andreasen Jeremy <andreasen@dps.state.ia.us>; Dolf Ryan <dolf@dps.state.ia.us>

Subject: FW: Vehicle damage to driver's door 12/07/2021

Lt. Guill and Jeannie,

Here is the notification of an act of nature damage to a patrol car last evening. Damage report will follow.

Thanks, Dean

From: Morey Russell <morey@dps.state.ia.us>

Sent: Wednesday, December 08, 2021 9:47 AM

To: J alas Dean <jalas@dps.state.ia.us>

Cc: Andreasen Jeremy <andreasen@dps.state.ia.us>; Dolf Ryan <dolf@dps.state.ia.us>

Subject: FW: Vehicle damage to driver's door 12/07/2021

414 had damage last night.

Wasn't sure if it should be fixed – I told him yes and he sent me a memo.

I'll work on a damage report today.

431

From: Meislahn Brian <meislahn@dps.state.ia.us>

Sent: Tuesday, December 7, 2021 9:17 PM

To: Morey Russell <morey@dps.state.ia.us>

Subject: Vehicle damage to driver's door 12/07/2021

Sgt. Morey,

While making a traffic stop south of exit 53 on US 63NB on 12/07/2021, strong winds threw my driver's door open and extended it passed the normal range. This caused the hinges to not function properly, put a crease in the driver's door, and the driver's door and front fender then rubbed against each other. I drove it to Copeland's in Hedrick, and they were able to push the hinges in and pull the front fender out further. The driver's door is opening without contacting the fender at this time. My vehicle has 91,189 miles on it.

Thank you,

Brian #414

3 attachments



IMG_0107.JPG
2715K

 **State Vehicle Damage Rpt form - updated .doc**
86K

 **State of Iowa Meislahn.pdf**
187K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #: 2021029557

Date: (Month/Day/Year)	12/07/21	Time: (Time plus a.m./p.m.)	4:00 pm
Vehicle Plate #:	414	Vehicle Mileage:	91,189
Vehicle Description: (Yr/Make/Model/ & Vin#)	2019 Dodge Charger 2C3CDXKT9KH622746		
Assigned To:	Trp. Meislahn	Badge #	414
Driven By:	Trp. Meislahn	Badge #	414
Driver's Lic #:		Damage:	\$None
Vehicle Towed: (Yes / No)	No	Towed By:	None
Towed To:	None	Towing Cost:	\$0.00
Seat Belt: (Yes / No)	No	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:	None		
Occupants: (Other than driver)	None		

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

OTHER INFORMATION:

Witnesses:			
Accident Location: (Street/Hwy)	Exit 53 on US 63 nb		
County:	Mahaska		
Weather/Road Conditions:	Clear/Dry/Windy		
Trooper Meislahn was making a traffic stop. As he exited his car, the wind caught the door and opened it past the door stop. This caused damage to the door hinges and put a crease/dent in the front portion of the door. The door was difficult to open and would not function properly. A local body shop was able to reset the hinges so the door opens/closes in a normal manner. Trooper Meislahn notified supervision about the damage.			
Property Damage other than Vehicles:	None		
Cost:	\$0.00		
Citations Issued To: (List Charge(s) and Statute Code(s))	None		

Investigating Officer:	Sgt. Russ Morey #431
------------------------	----------------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

QUALITY CLAIMS SOLUTIONS

7405 S Bitterroot Pl. Suite 100
SIOUX FALLS, SD 57108
Phone: (877) 237-3727, FAX:(866) 371-2844
qcs@qcsdirect.com

Workfile ID: dba963cf

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: STATE OF IOWA

Job Number:

Written By: Chuck Tilton, CT- 2437980

Insured:	STATE OF IOWA	Policy #:	UNK	Claim #:	APDSOI0230690-001
Type of Loss:	Collision	Date of Loss:	12/21/2021 12:00 PM	Days to Repair:	0
Point of Impact:	10 Left Front Pillar (Left Side)				

Owner:

STATE OF IOWA
OSKALOOSA, IA 52577

Inspection Location:

Copeland Collision Center
1308 17th ave E
Oskaloosa, IA 52577
Other
(641) 676-6060 Evening

Repair Facility:

VEHICLE

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Grey

VIN:	2C3CDXKT9KH622746	Production Date:		Interior Color:	
License:		Odometer:	91,250	Exterior Color:	Grey
State:		Condition:			

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera
Parking Sensors

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions
Power Trunk/Liftgate

Estimate of Record

Owner: STATE OF IOWA

Job Number:

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Grey

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER					
2	R&I	R&I bumper cover				1.9	
3	#	R&I Push bar				1.0	
4		FENDER					
5	*	Rpr LT Fender				3.0	2.0
6		Add for Clear Coat					0.8
7	#	Decals		1		1.0	
8	R&I	RT Fender liner 3.6, 5.7 liter				0.3	
9	R&I	LT Fender liner 3.6, 5.7 liter				0.3	
10		FRONT DOOR					
11	*	Rpr LT Door shell (HSS)				4.0	2.1
12		Overlap Major Adj. Panel					-0.4
13		Add for Clear Coat					0.3
14		Add for Edging					0.5
15	#	Decals		1		1.0	
16	R&I	LT Power mirror w/o heat, w/o memory, w/o blind spot blue				0.5	
17	Repl	LT Applique	57010427AE	1	161.00	0.2	
18	R&I	LT R&I trim panel				0.5	
19	R&I	LT Handle, outside black				0.4	
20	Repl	LT Upper hinge	55113661AC	1	80.20	0.3	0.5
21	Repl	LT Lower hinge	55113665AI	1	82.00	0.3	0.5
22		Overlap Minor Panel					-0.2
23	#	Pre scan		1	50.00	0.5 M	
24	#	Post scan		1	50.00	0.5 M	
25	#	Cover Car		1	5.00	0.2	
26	#	Corrosion Protection		1	6.00		
SUBTOTALS					434.20	15.9	6.1

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			434.20
Body Labor	14.9 hrs @	\$ 62.15 /hr	926.04
Paint Labor	6.1 hrs @	\$ 100.00 /hr	610.00
Mechanical Labor	1.0 hrs @	\$ 71.36 /hr	71.36
Subtotal			2,041.60
Total Cost of Repairs			2,041.60
Deductible			0.00
Total Adjustments			0.00
Net Cost of Repairs			2,041.60