MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE

Executive Council of Iowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

July 1, 2024

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$3,920.80, subject to the audit of actual invoices. On May 8, 2024, Vehicle #1085 was damaged by a deer. Request was to cover repair costs.

This represents full and final payment.

EXECUTIVE COUNCIL OF IOWA

Kristi Onstot

Kristi Onstot Executive Secretary

Adam Steen, Director, Department of Administrative Services
 DAS Fleet Services, Risk
 Matt Bender, Department of Management
 Heather Hackbarth, Department of Management

(

OFFICE OF AUDITOR OF STATE

STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004

Telephone (515) 281-5834 Facsimile (515) 281-6518

May 21, 2024

Kristi Onstot Executive Council L O C A L

Subject: Deer Damage to Vehicle #1085 on May 8, 2024

Department of Administrative Services

Claim dated May 14, 2024

AOS Claim ID: 3748

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$3,920.80, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Bri R Briss

CC: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services
Heather Hackbarth, Department of Management





Date: May 14, 2024

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Karl Bubser, Fleet Administrator

DAS Fleet Services

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#1085/Animal
Event Date	May 8, 2024
Summary	Vehicle 1085 sustained hail damage. (280689) AOS #3748
Amount Requested	\$3,920.80 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Karl Bubser, Fleet Administrator

DAS Fleet Services Karl.Bubser@iowa.gov

515-281-3162



29C20

Risk, DAS <das.risk@iowa.gov>

Thu, May 9, 2024 at 8:41 AM

Draft To: TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>, Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 1085 struck a deer on 5/8/24. I will forward all information as soon as it is received.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

DAS Risk

Central Procurement and Fleet Services Enterprise


Iowa Department of Administrative Services

109 SE 13th St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov

https://das.iowa.gov





Department of Administrative Services
DAS Fleet Services- Risk Management
109 SE 13th St
Des Moines, IA 50319

Vehicle Accident Report Form

- Render aid or assistance to the injured (per Iowa Code 321.262).
- The State of Iowa is self-insured. Refer to the insurance card and accident report procedures online or in your glove box packet. If the accident involves another party, exchange information with the driver or property owner. Do not admit fault or attempt to settle your claim.
- Call local law enforcement, if a fatality, injury or property damage has occurred, and obtain a police report. On the Capitol complex, call lowa State Patrol, Post 16 at 515-281-5608.
- Within the first 24 hours, report accident or damage to DAS Fleet Services (515-281-3162 or <u>DAS.Risk@iowa.gov</u>), your agency fleet contact, and supervisor. Damage caused by an act of nature or unavoidable cause MUST be reported to DAS Fleet Services within 24 hours of the incident to qualify for contingent fund use (<u>per Iowa Code 29C.20</u>).
- For an estimate, locate the nearest contracted auto body repair shop in the Contracted Service Providers map. A contracted auto body shop within 30 miles should be used if available.
- If towing is necessary, contact DAS Fleet Services (515-281-3162) for assistance. After hours, call National Automobile Club (NAC) FleetRescue* (866-329-3471) or local law enforcement.
- Within 72 hours, print and submit a completed Accident Report Form, including a cost estimate from the auto body shop to DAS.Risk@iowa.gov.
- Any accident in the State of Iowa that causes death, personal injury, or total property damage of \$1,500 or more must be reported on an Iowa Accident Report Form UNLESS the accident is investigated by a law enforcement agency and a report is filed. Failure to return an accident report form within 72 hours may result in suspension of driving privileges.

Vehicle Accident Report


Time and location of acci	dene			
Accident Date (Mo/Day/Year)		Time	No. of Vehicles	
05/0	08/2024	3:45pm	1	
County		State		
Ko	ssuth	lowa		
Vehicle 1 (State vehicle)				
Driver's Name		Work Street Address		
Kevin I	H Wiemers	2804 9	00th Ave	
Driver's License No./State		City, State, Zip		
074	bb6485	Burt, lov	va, 50522	
Date of Birth	Department	Work Phone	Home Phone	
09/21/1979	Feed & Fertilizer	515-249-3129	515-320-2269	
License Plate No.	VIN	Year, Make, Model		
1085	2G11X5S33K9154241	2019, Chevrolet, Impala		
Estimate (\$) of Damage		Description of Damage		
No official estimate sought at this curre	•	Damage caused by an act of nature. Damage to grill,bumper cover, hood and drivers side headlamp from deer hit.		
Vehicle 2 (other vehicle) i	f more than two vehicles-use a	dditional forms		
Driver's Name		Street Address		
Driver's License No./State		City, State, Zip		
Date of Birth	Work Phone	Home Phone	License Plate No.	
Description of Damage				

Property Damage other than vehicle (fence, utility pole, etc)				
Owner's Name, Address and Phone	Description of Property Damaged			
	none			
Injured Persons (attach additional sheets if necessary)				
Vehicle No. 1/ Name and Address	Describe Injuries			
	no injuries			
Vehicle No. 2/ Name and Address	Describe Injuries			
Witness	andra de Maria de Carlos de Ca Carlos de Carlos de C			
Name	Address/Phone			
No witness				
Name	Address/Phone			

Accident Diagram

Complete diagram below, include a description of what happened.

Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers.
Use number 1 to indicate the State vehicle.



I was traveling east on US Hwy18 coming to the intersection of Kossuth Co gravel road 80th ave when 3 deer crossed the road in front of me and before I got stopped I hit a deer with the front of my car at a estimated speed of less then 20mph. The deer fell down and slide to the side of the road where it got back up and ran off.

	Accident Information Exchange Sheet
Other Vehicle information	
Driver's Name	
Street Address	
Driver Phone	
Driver's License No./State	
Vehicle Plate No.	
Vehicle year, make, model	
VIN	
Insurance Company Name	
Policy No.	
Agent name	
Agent phone	
Owner's Name/Address (if different)	
Submit this information a	long with the accident report to DAS Fleet Service within 72 hours of the accident.
Complete the n	ext section, tear at the dotted line and give to the other party involved.
State Vehicle Insurance Info	rmation
Driver's Name	
Driver's License No./State	
Vehicle Plate No.	
Vehicle year, makel, model	
VIN	
	The State of Iowa is self-insured. Ou have any questions regarding an accident, please contact OAS Fleet Services at 515-281-3162 of DAS.Risk@iowa.gov

KEMNA PROFESSIONAL AUTO BODY 617 HIGHWAY 18 W

ALGONA, IA 50511

TEL: (515) 295-7569 FAX: (515) 295-7569 EMAIL:DOUG_THILGES@KEMNA.COM TAX ID:# 42-1078287

*** PRELIMINARY ESTIMATE ***

05/13/2024 09:57 AM

Owner

Owner: Kevin Wiemers State of Iowa

Address:

Cell: (515)320-2269

Inspection

Inspection Date: 05/13/2024 10:00 AM

Primary Impact: Front

Inspection Type: Secondary Impact:

Appraiser Name: Doug Thilges

Address: 617 Hwy 18 W City State Zip: Algona, IA 50511 Appraiser License #2:

Work/Day: (515)295-2406

FAX:

Repairer

Repairer: Kemna Professional Auto Body

Contact:

Address: 617 Highway 18 W

Work/Day: (515)295-7569 FAX: (515)295-7957

City State Zip: Algona, IA 50511

Email: doug_thilges@kemna.com

Work/Day:

Target Complete Date/Time:

Days To Repair: 3

Vehicle

OEM Part Price Quote ID: 136390143

2019 Chevrolet Impala LS W/ 1FL 4 DR Sedan

6cyl Gasoline 3.6 6-Speed Automatic

Lic Expire: VIN: 2G11X5S33K9154241

Prod Date: Mileage: 81,357

Veh Insp#: Mileage Type: Actual

Condition: Code: U4183A

Ext. Color: WHITE Int. Color: Jet Black/Dark Titanium

Ext. Refinish: Two-Stage Int. Refinish: Two-Stage Ext. Paint Code: 50,GAZ,WA8624 Int. Trim Code: H0X

Options - AudaVIN Information Received

18 Inch Alloy Wheels1st Row LCD Monitor(s)2nd Row Head Airbags60/40 Bench SeatAM/FM StereoAir ConditioningAnti-Lock BrakesArmrest(s)Auto Headlamp ControlAuxiliary Audio InputCarpetingCenter ConsoleClimate Control For A/CCompact Spare TireCruise Control

Climate Control For A/C Compact Spare Tire Cruise Control
Daytime Running Lights Driver Information Sys Dual Airbags
Elect. Stability Control Electric Parking Brake Electric Steering
Electronic Compass Emergency S.O.S. System Engine Stop/Start

Floor Mats	Halogen Headlights	Head Airbags
High Definition Radio	IPOD Control	Illuminated Visor Mirror
In-Vehicle WiFi	Intermittent Wipers	Keyless Access System
Keyless Entry System	Keyless Ignition System	Knee Air Bags
Laminated Glass	Lighted Entry System	Navigation System
OnStar System	Overhead Console	Power Brakes
Power Door Locks	Power Drivers Seat	Power Mirrors
Power Steering	Power Windows	Privacy Glass
Pwr Driver Lumbar Supp	Rear Center Arm Rest	Rear Side Airbags
Rear View Camera	Rear Window Defroster	Rem Trunk-L/Gate Release
Side Airbags	SiriusXM Satellite Radio	Split Folding Rear Seat
Stability Cntrl Suspensn	Strg Wheel Radio Control	Tachometer
Theft Deterrent System	Tilt & Telescopic Steer	Tinted Glass
Tire Pressure Monitor	Traction Control System	Trip Computer
USB Audio Input(s)	Vehicle Tracking Service	Velour/Cloth Seats
Wireless Audio Streaming	Wireless Phone Connect	

AudaVIN options are listed in bold-italic fonts

Damages									
Line Op	Guide	МС	Description	on	MFR.Part No.	Price	ADJ% B%	Hours	R
Front End D	anal An	dlan							
Front End P 1 E	28	<u>u Lan</u>	Grille Ass	ombly	84720376 GM Part	\$421.30		1.7	SM
2 EC	41			•		\$910.00*		0.3	RF
2 EC	41			Assy,Halogen LT	Replace Economy	99 10.00		0.3	Kr
2 N	973		>> Keysto		Additional Labor			0.4	CN4
3 N	973		Headlamp	S AIM	Additional Labor			0.4	SM
Radiator Su	pport								
4 E	283		Cover.Rad	d Supt Panel	84364840 GM Part	\$100.80		INC	SM
			, , ,			*			
ront Body	And Wir	ndshi	<u>eld</u>						
5 E	83		Panel, Hoo	od	84380741 GM Part	\$1,114.20		0.9	SM
6 L	83	13	Panel,Hoo	od	Refinish 3.0 Surface 1.2 Edge 0.6 Two-stage setup 0.8 Two-stage			5.6	RF
Manage Forts									
Vianual Entr 7 SB	<u>ies</u>		Hozordou	s Waste Removal	Sublet Beneir	\$10.00*			SM
7 SB 8 N			Pre scan	s waste Removal	Sublet Repair Additional Labor	*			SM
					Additional Labor	\$75.00*			
			post scan			\$75.00*		0.5*	SM
10 EC	ltama		seam seal	er/ tube	Replace Economy	\$45.00*		0.5*	SM
10	Items								
			MC	Message					
			13	INCLUDES 0	6 HOURS FIRST PANEL TV	VO-STAGE ALLO	WANCE		

Estimate Total & Entries

 OEM Parts
 \$1,636.30

 Other Parts
 \$1,105.00

 Paint & Materials
 5.9 Hours @ \$62.00
 \$365.80

Parts & Material Total \$3,107.10

Labor Rate Replace Repair Hrs Total Hrs
Hrs

\$85.50	3.1	0.4	3.5	\$299.25		
\$124.00						
\$115.00						
\$85.50	5.9		5.9	\$504.45		
			9.4 Hc		\$803.70	
				\$10.00		
					\$3,920.80	
					\$3,920.80	
	\$124.00 \$115.00	\$124.00 \$115.00	\$124.00 \$115.00	\$124.00 \$115.00 \$85.50 5.9 5.9	\$124.00 \$115.00 \$85.50 5.9 5.9 \$504.45 9.4 Hours	\$124.00 \$115.00 \$85.50 5.9 5.9 \$504.45 9.4 Hours \$803.70 \$10.00 \$3,920.80

Alternate Parts Y/04/00/00/04/04 Cumulative 04/00/00/04/04 Zip Code: 50511 Default

OEM Part Prices DT 05/13/2024 09:57 AM EstimateID 1219298578023849984 QuoteID 136390143

Recycled Parts Y/0/0 Zip Code: 50511

Rate Name Default

Audatex Estimating 10.27.135 ES 05/13/2024 11:50 AM REL 10.27.135 DT 04/01/2024 DB 05/08/2024

State Disclosure: Not Selected

© 2024 Audatex North America, LLC.

1.4 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM= Replace PXN Reman/Rebit
UM= Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2024 Audatex North America, LLC. AUDATEX is a trademark owned by Audatex North America, LLC. All rights reserved.