

MEMBERS OF COUNCIL

HON. KIM REYNOLDS  
GOVERNOR

HON. PAUL D. PATE  
SECRETARY OF STATE

HON. ROB SAND  
AUDITOR OF STATE

HON. ROBY SMITH  
TREASURER OF STATE

HON. MIKE. NAIG  
SECRETARY OF AGRICULTURE



## Executive Council of Iowa

CAPITOL BUILDING  
DES MOINES, IOWA 50319  
PHONE: 515 281-5368

July 1, 2024

Accounting Department  
Office of the Treasurer  
Lucas Building  
321 E 12<sup>th</sup> Street  
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for a supplemental emergency allocation in the amount of \$1,125.14, subject to the audit of actual invoices. This increases the allocation to \$3,275.06. On February 19, 2024, Vehicle #27 was damaged by a raccoon. Request was to cover repair costs.

This represents full and final payment.

EXECUTIVE COUNCIL OF IOWA

*Kristi Onstot*

Kristi Onstot  
Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services  
DAS Fleet Services, Risk  
Matt Bender, Department of Management  
Heather Hackbarth, Department of Management

AOS Claim # 3704  
TOS Job # \_\_\_\_\_



OFFICE OF AUDITOR OF STATE  
STATE OF IOWA

Rob Sand  
Auditor of State

State Capitol Building  
Des Moines, Iowa 50319-0004  
Telephone (515) 281-5834 Facsimile (515) 281-6518

May 21, 2024

Kristi Onstot  
Executive Council  
L O C A L

Subject: Raccoon Damage to Vehicle #27 on February 19, 2024  
Department of Administrative Services  
Claim dated February 29, 2024  
AOS Claim ID: 3704

The Department's request included a supplemental allocation request of \$1,125.14 because additional damages were identified. We recommend Executive Council approval of the supplemental allocation of \$1,125.14, which increases the allocation to \$3,275.06. In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to this loss. We have found the items to be in order as shown below:

Documented request		\$	<u>3,275.06</u>
Executive Council allocation (Revised)		\$	3,275.06
Less:			
Previous payments	\$	0.00	
This payment		<u>3,275.06</u>	
Total		\$	<u>3,275.06</u>
Remaining Executive Council allocation		\$	<u>0.00</u>

We recommend that reimbursement be made in the amount of \$3,275.06. This represents full and final payment on this allocation.

Sincerely,

Brian R. Brustkern, CPA  
Deputy Auditor of State

CC: Adam Steen, Director, Department of Administrative Services  
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services



Governor Kim Reynolds  
Lt. Governor Adam Gregg  
Adam Steen, Director

Date: May 14, 2024

To: Tammy Hollingsworth, Auditor of State  
Victoria Newton, Treasurer of State  
Executive Council

From: Karl Bubser, Fleet Administrator  
DAS Fleet Services  
Department of Administrative Services

Re: REIMBURSEMENT REQUEST - 29C20 Claim

AOS Claim #	3704
Vehicle / Event	#27/Animal
Event Date	February 19, 2024
Summary	Vehicle 27 struck a raccoon. (275445)
Amount Requested	<b>\$3,275.06 - TOTAL</b>

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: **0665-005-5790-0657**.

If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,

Karl Bubser, Fleet Administrator  
DAS Fleet Services  
karl.bubser@iowa.gov  
515-281-3162

# Warrants

Edit

Cancel

\* Required fields

## Warrant Information

<b>Fiscal Year</b> 2024	<b>Amount</b> \$3,275.06	<b>Warrant Number</b> 73038310
<b>Vendor Customer</b> 00003030887	<b>Line Number</b> 1	<b>Last Updated</b> 05/06/2024 08:01 PM

## Issue Information

<b>Issued</b> 05/06/2024 12:00 AM	<b>Void</b> No	<b>Transaction ID</b> RISK00524124004
<b>Duplicate</b> No	<b>Transaction Line Number</b> 1	<b>Stop</b> No
<b>Line Amount</b> \$537.20	<b>Comments</b>	

## Redeemed Information

<b>Redeemed</b> -	<b>Batch Number</b> -	<b>Redeemed Bank</b> -
<b>Sequence Number</b> -	<b>Redeemed Fund</b> -	<b>Redeemed Department</b> -

## COA

<b>Fund</b> 0665	<b>Object</b> 2715	<b>Dept Object</b> -
<b>Sub Fund</b> -	<b>Sub Object</b> -	<b>Dept Revenue</b> -
<b>Department</b> 005	<b>Unit</b> 5790	<b>Sub Unit</b> -
<b>Object Class</b> -	<b>Revenue Source</b> -	<b>Sub Revenue Source</b> -
<b>Appropriation</b> 0000	<b>Revenue Source Class</b> -	<b>BSA</b> -
<b>Sub BSA</b> -		

▶ Show More

# Warrants

Edit

Cancel

\* Required fields

## Warrant Information

<b>Fiscal Year</b> 2024	<b>Amount</b> \$3,275.06	<b>Warrant Number</b> 73038310
<b>Vendor Customer</b> 00003030887	<b>Line Number</b> 2	<b>Last Updated</b> 05/06/2024 08:01 PM

## Issue Information

<b>Issued</b> 05/06/2024 12:00 AM	<b>Void</b> No	<b>Transaction ID</b> RISK00524124004
<b>Duplicate</b> No	<b>Transaction Line Number</b> 2	<b>Stop</b> No
<b>Line Amount</b> \$238.00	<b>Comments</b>	

## Redeemed Information

<b>Redeemed</b> -	<b>Batch Number</b> -	<b>Redeemed Bank</b> -
<b>Sequence Number</b> -	<b>Redeemed Fund</b> -	<b>Redeemed Department</b> -

## COA

<b>Fund</b> 0665	<b>Object</b> 2715	<b>Dept Object</b> -
<b>Sub Fund</b> -	<b>Sub Object</b> -	<b>Dept Revenue</b> -
<b>Department</b> 005	<b>Unit</b> 5790	<b>Sub Unit</b> -
<b>Object Class</b> -	<b>Revenue Source</b> -	<b>Sub Revenue Source</b> -
<b>Appropriation</b> 0000	<b>Revenue Source Class</b> -	<b>BSA</b> -
<b>Sub BSA</b> -		

Show More

# Warrants

Edit

Cancel

\* Required fields

## Warrant Information

<b>Fiscal Year</b> 2024	<b>Amount</b> \$3,275.06	<b>Warrant Number</b> 73038310
<b>Vendor Customer</b> 00003030887	<b>Line Number</b> 3	<b>Last Updated</b> 05/06/2024 08:01 PM

## Issue Information

<b>Issued</b> 05/06/2024 12:00 AM	<b>Void</b> No	<b>Transaction ID</b> RISK00524124004
<b>Duplicate</b> No	<b>Transaction Line Number</b> 3	<b>Stop</b> No
<b>Line Amount</b> \$782.00	<b>Comments</b>	

## Redeemed Information

<b>Redeemed</b> -	<b>Batch Number</b> -	<b>Redeemed Bank</b> -
<b>Sequence Number</b> -	<b>Redeemed Fund</b> -	<b>Redeemed Department</b> -

## COA

<b>Fund</b> 0665	<b>Object</b> 2715	<b>Dept Object</b> -
<b>Sub Fund</b> -	<b>Sub Object</b> -	<b>Dept Revenue</b> -
<b>Department</b> 005	<b>Unit</b> 5790	<b>Sub Unit</b> -
<b>Object Class</b> -	<b>Revenue Source</b> -	<b>Sub Revenue Source</b> -
<b>Appropriation</b> 0000	<b>Revenue Source Class</b> -	<b>BSA</b> -
<b>Sub BSA</b> -		

Show More

# Warrants

Edit

Cancel

\* Required fields

## Warrant Information

<b>Fiscal Year</b> 2024	<b>Amount</b> \$3,275.06	<b>Warrant Number</b> 73038310
<b>Vendor Customer</b> 00003030887	<b>Line Number</b> 4	<b>Last Updated</b> 05/06/2024 08:01 PM

## Issue Information

<b>Issued</b> 05/06/2024 12:00 AM	<b>Void</b> No	<b>Transaction ID</b> RISK00524124004
<b>Duplicate</b> No	<b>Transaction Line Number</b> 4	<b>Stop</b> No
<b>Line Amount</b> \$1,717.86	<b>Comments</b>	

## Redeemed Information

<b>Redeemed</b> -	<b>Batch Number</b> -	<b>Redeemed Bank</b> -
<b>Sequence Number</b> -	<b>Redeemed Fund</b> -	<b>Redeemed Department</b> -

## COA

<b>Fund</b> 0665	<b>Object</b> 2715	<b>Dept Object</b> -
<b>Sub Fund</b> -	<b>Sub Object</b> -	<b>Dept Revenue</b> -
<b>Department</b> 005	<b>Unit</b> 5790	<b>Sub Unit</b> -
<b>Object Class</b> -	<b>Revenue Source</b> -	<b>Sub Revenue Source</b> -
<b>Appropriation</b> 0000	<b>Revenue Source Class</b> -	<b>BSA</b> -
<b>Sub BSA</b> -		

Show More



# DURANT COLLISION REPAIR

durantcollision@iowatelecom.net  
 1303 5th St, P O Box 638, DURANT, IA 52747  
 Phone: (563) 785-6353  
 FAX: (563) 785-6659

Workfile ID: 0d5aeb5b  
 PartsShare: 7NY5pG  
 Federal ID: 202958038

## Final Bill

### RO Number: 1716

Customer:	Insurance:	Adjuster:	Estimator:	Craig Moeller
Iowa State Patrol		Phone:	Create Date:	2/20/2024
22365 20th Ave.		Claim:	APDSOI0275445-00	
			1	
Stockton, IA 52769		Loss Date:		
(563) 284-9501		Deductible:		

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI gray

VIN: 2C3CDXKG6NH256364	Interior Color:	Mileage In: 38,451	Vehicle Out:
License: 27	Exterior Color: gray	Mileage Out:	
State: IA	Production Date: 11/2022	Condition: Good	Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		<b>FRONT BUMPER &amp; GRILLE</b>						
2	E01	Remove/Replace	O/H front bumper				3.4	Body	
3	E01	Remove/Replace	Bumper cover	1	645.19	OEM	0.0	Body	3.4
4	E01		Add for Clear Coat						1.4
5	E01	Remove/Install	PUSH BAR AND WRAP				2.0	Body	
6	E01	Remove/Install	APPLIQUE						
7	E01	Repair	ADD FOR 2 TONE						1.2
8	E01	Remove/Replace	LT Air duct	1	66.60	OEM			
9	E01	Remove/Install	License bracket				0.1	Body	
10	S01	Remove/Replace	LT Bumper bracket	1	42.45	OEM	0.1	Body	
11	E01		<b>RADIATOR SUPPORT</b>						
12	E01	Remove/Replace	Front shield w/police	1	251.93	OEM	0.0	Body	
13	S01	Remove/Replace	Crossmember	1	273.00	A/M	0.5	Body	0.8
14	E01		<b>FRONT LAMPS</b>						
15	E01	Remove/Replace	LT Fog lamp bezel halogen	1	27.20	OEM	0.0	Body	
16	E01		***** ADD-ONS *****			A/M			
17	E01	Remove/Replace	Cover Car	1	10.00	Other			
18	S02		<b>AIR CONDITIONER &amp; HEATER</b>						
19	S02	Remove/Replace	Condenser assy	1	224.80	A/M	1.5	Body	
20	S02		Evacuate & Recharge				1.4	Mech	
21	S02		Refrigerant Recovery				0.4	Mech	
22	E01		<b>VEHICLE DIAGNOSTICS</b>						
23	E01		Pre-repair scan			OEM	0.5	Mech	
24	E01		Post-repair scan			OEM	0.5	Mech	
25	S01		<b>COOLING</b>						
26	S01	Remove/Replace	Radiator	1	176.69	A/M	1.8	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural



**Final Bill**

**RO Number: 1716**

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI gray

27	S01	Remove/Replace	Deduct for Overlap	(0.5)	Body
28	S02	Remove/Replace	Deduct for Overlap	(1.0)	Body

<b>Estimate Totals</b>	<b>Discount \$</b>	<b>Markup \$</b>	<b>Rate \$</b>	<b>Total Hours</b>	<b>Total \$</b>
Parts					1,717.86
Labor, Body			68.00	7.9	537.20
Labor, Refinish			115.00	6.8	782.00
Labor, Mechanical			85.00	2.8	238.00
<b>Subtotal</b>					<b>3,275.06</b>
Sales Tax					0.00
<b>Grand Total</b>					<b>3,275.06</b>
<b>Net Total</b>					<b>3,275.06</b>

<b>Estimate Version</b>	<b>Total \$</b>
Original	2,149.92
Supplement S01	972.14
Supplement S02	153.00

Insurance Total \$:	3,275.06
Received from Insurance \$:	0.00
<b>Balance due from Insurance \$:</b>	<b>3,275.06</b>
Customer Total \$:	0.00
Received from Customer \$:	0.00
<b>Balance due from Customer \$:</b>	<b>0.00</b>

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural



**Department of  
Administrative Services**  
*Empowering People  
Collaboration  
Customer Service*

Governor Kim Reynolds  
Lt. Governor Adam Gregg  
Adam Steen, Director

Date: February 29, 2024

To: Tammy Hollingsworth, Auditor of State  
Victoria Newton, Treasurer of State  
Executive Council

From: Karl Bubser, Fleet Administrator  
DAS Fleet Services  
Department of Administrative Services


**Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration**

Vehicle / Event	#27/Animal
Event Date	February 19, 2024
Summary	Vehicle 27 struck a raccoon. (275445)
Amount Requested	\$2,149.92 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Karl Bubser, Fleet Administrator  
DAS Fleet Services  
Karl.Bubser@iowa.gov  
515-281-3162



OFFICE OF AUDITOR OF STATE  
STATE OF IOWA

Rob Sand  
Auditor of State

State Capitol Building  
Des Moines, Iowa 50319-0004  
Telephone (515) 281-5834 Facsimile (515) 281-6518

April 12, 2024

Victoria Newton  
Executive Council  
LOCAL

Subject: Raccoon Damage to Vehicle #27 on February 19, 2024  
Department of Administrative Services  
Claim dated February 29, 2024  
AOS Claim ID: 3704

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$2,149.92, subject to an audit of actual invoices.

Sincerely,

A handwritten signature in black ink, appearing to read "Brian R. Brustkern".

Brian R. Brustkern, CPA  
Deputy Auditor of State

CC: Adam Steen, Director, Department of Administrative Services  
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services  
Heather Hackbarth, Department of Management



AOS # 3704

Risk, DAS <das.risk@iowa.gov>

29C20

Risk, DAS <das.risk@iowa.gov>

Draft To: TOS Executive Council <executivecouncil@tos.iowa.gov>, Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, Mariah Fucaloro <mariah.fucaloro@iowa.gov>, Jeannie R Adams <jadams@dps.state.ia.us>

Wed, Feb 21, 2024 at 9:59 AM

4

Vehicle 27 struck a raccoon on 2/19/24. Can this be accepted? Initial 24 hr notification was sent to the department on 2/20 but Risk did not receive an email until 2/21. Vehicle damage report is attached.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

109 SE 13<sup>th</sup> St, Des Moines, IA 50319

515-281-3162 office

[das.risk@iowa.gov](mailto:das.risk@iowa.gov)

<https://das.iowa.gov>



Department of Administrative Services

## State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

**STATE VEHICLE: (Mark if Act of Nature  ) CASE #: 2024004648**

Date: <small>(Month/Day/Year)</small>	2/19/2024	Time: <small>(Time plus a.m./p.m.)</small>	8:30 PM
Vehicle Plate #:	27	Vehicle Mileage:	38,348
Vehicle Description: <small>(Yr/Make/Model/ &amp; Vin#)</small>	2022 Dodge Charger Vin # 2C3CDXKG6NH256364		
Assigned To:	Trp. Allen	Badge #	27
Driven By:	Trp. Allen	Badge #	27
Driver's Lic #:	339AE6155	Damage:	\$2149.92
Vehicle Towed: <small>(Yes / No)</small>	NO	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$0
Seat Belt: <small>(Yes / No)</small>	Yes	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Marked
Injured/Injuries:	None		
Occupants: <small>(Other than driver)</small>	Trooper Brian Smith		

**VEHICLE #2:**

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

**OTHER INFORMATION:**

Witnesses:	None
Accident Location: (Street/Hwy)	Interstate 80 @ Mile Marker 282
County:	Scott County
Weather/Road Conditions:	Clear/Dry
On 02/19/2024 at approximately 2030 hours, Trooper Allen, was traveling westbound on Interstate 80 near mile marker 282 when he struck a raccoon running across the roadway. The mileage on his patrol vehicle was at approximately 38,348 miles during the incident and Trooper Brian Smith was riding with him at the time.	
Property Damage other than Vehicles:	None
Cost:	\$0
Citations Issued To: (List Charge(s) and Statute Code(s))	N/A

Investigating Officer:	Sgt. Saldivar # 281
------------------------	---------------------

**VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)**

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

**INVESTIGATING OFFICER'S REPORT  
OF MOTOR VEHICLE ACCIDENT**

Law Enforcement Case Number:  
**2024004648**

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Date of Accident <b>02/19/2024</b>		Time of Accident <b>20:30</b> Hrs.		County <b>SCOTT - 82</b>		Accident occurred within corporate limits of (city)									
<b>U N I T 1</b>	Driver's Name - Last <b>ALLEN</b>					First <b>THOMAS</b>			Middle <b>JOHN</b>						
	Address <b>22365 20TH AVE.</b>					City <b>STOCKTON</b>			State <b>IA</b>	Zip <b>52769</b>					
	Date of Birth <b>04/24/1995</b>		Driver's License Number <b>339AE6155</b>		CDL	Citation Charge 1		Citation Charge 2							
	Male <input checked="" type="radio"/>	Female <input type="radio"/>	State <b>IA</b>	Class <b>C</b>	Endorsements <b>LPS</b>	Restrictions <b>3EKM</b>	Yes <input type="radio"/> No <input checked="" type="radio"/>	Citation Charge 3		Citation Charge 4					
	Alcohol Test Given: <b>1</b>		Test Results:		Drug Test Given: <b>1</b>	Test Result:	Re-exam: Yes <input type="radio"/> No <input checked="" type="radio"/>	Reason for Re-Exam Request:							
	Owner's Name - Last <b>STATE OF IOWA</b>					First			Middle						
	Address <b>22365 20TH AVE.</b>					City <b>STOCKTON</b>			State <b>IA</b>	Zip <b>52769</b>					
	License Plate No. <b>27</b>	State <b>IA</b>	Year <b>2024</b>	VIN: <b>2C3CDXKG6NH256364</b>		Color <b>GRY</b>	Year <b>2020</b>	Make <b>DODG</b>	Model <b>CHARGER</b>	Style <b>4DR</b>					
	Trailer Plate No.	State	Year	VIN:		Tow <b>1</b>	Tow #	Towed To	Approx. Cost to Repair or Replace <b>\$214,992.00</b>						
	Insurance Company Name <b>STATE OF IOWA</b>					Insurance Co. Phone Number		Insurance Policy Number							
Initial Travel Direction	Veh. Act.	Veh. Config. <b>01</b>	Cargo Body Type <b>01</b>	Veh. Defect	Point of Initial Impact	Most Damaged Area	Extent of Damage	Total Occ. in Veh. <b>2</b>							
Special Veh. Func.	Emergency Status	Bus Use	Driver Condition	Vision Obscured	Contributing Circumstances Driver (up to two) <b>88</b>		Driver Distractions <b>02</b>	Speed Limit							
Traffic Controls	Horizontal Alignment	Vertical Alignment	SEQUENCE OF EVENTS	First Event	Second Event	Third Event	Fourth Event	Most Harmful Event							
<b>C O M M E R C I A L</b>	Carrier Name/Lessee														
	Street Address					City			State	Zip Code					
	Number of Axles		Gross Vehicle Weight Rating			US DOT Number		MC Number		Underride/Override					
	Haz Mat Involvement		Haz Mat Placard		Placard Number	Haz. Mat Released	Haz Mat Class	Haz Mat Name							
	Trailer Plate:		State	Year	VIN										
	Trailer Plate:		State	Year	VIN										
	Converter Dolly		Dolly Plate:		State	Plate Year	VIN								
<b>P E R S O N S  I N J U R E D</b>	<b>DRIVER OF UNIT 1</b>					Sex	Seating Position	Injury Status	Occupant Protection	Airbag Deployment	Ejection	Ejection Path	Trapped/Extricated	Source of Transport	Drag/Scene/Evidence
	Phone Number: <b>(563) 284-9501</b>					Transported to:									
	Name					Phone Number		DOB:		Transported by:					
	Address					Transported to:					Transported by:				
	Name					Phone Number		DOB:		Transported by:					
	Address					Transported to:					Transported by:				
	Name					Phone Number		DOB:		Transported by:					
	Address					Transported to:					Transported by:				
	Name					Phone Number		DOB:		Transported by:					
	Address					Transported to:					Transported by:				



INVESTIGATING OFFICER'S REPORT OF MOTOR VEHICLE ACCIDENT

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

Law Enforcement Case Number: 2024004648

LOCATIONS: Date of Accident 02/19/2024, Time of Accident 20:30 Hrs., County SCOTT - 82, Accident occurred within corporate limits of (city) Legal Intervention? Private Property? Literal Description 180 W @ 282 MILE MARKER, X Coordinate: 680749.25, Y Coordinate: 4611035

ACCIDENT ENVIRONMENT: Location of First Harmful Event, Weather Conditions, Manner of Crash/Collision, Light Conditions, ROADWAY CHARACTERISTICS: Major Contributing Circumstances Environment, Roadway, Type of Roadway Junction/Feature, FRA No.

First Harmful Event (Crash) 31, WORKZONE RELATED?, Yes No, Activity, Location, Type, Workers Present

NONMOTORISTS: Name 001, Phone Number, DOB, Address, Alcohol Test Given, Test Results, Drug Test Given, Result, Charged Yes No

PROPERTY DAMAGE: If Property other than vehicles damaged explain, Object Damaged, Estimate of Damage, Owner's Last Name, First Name, Middle Name, Phone Number, Address, City, State, Zip Code, Was owner or tenant notified?

WITNESSES: Last Name, First Name, Address, City, State, Zip Code, Phone Number

Is This a Secondary Crash? Y N, Type of Primary Incident, Roadway Clearance Date 02/19/2024, Incident Clearance Date 02/19/2024, Signature of Officer SERGEANT D SALDIVAR, Badge Number 281, Time Officer Notified of Accident 20:30 Hrs., Roadway Clearance Time 20:30 Hrs., Incident Clearance Time 20:30 Hrs., Name of Agency IOWA STATE PATROL - DIST 12, Date of Report 02/19/2024, Time Officer Arrived At Scene 20:30 Hrs., Total Roadway Clearance Time 000:00, Total Incident Clearance Time 000:00, Report Reviewed By, Date of Review, Investigation made at scene? Y N, T.I. No., Other Technical Investigating Agency

INVESTIGATING OFFICER'S REPORT  
OF MOTOR VEHICLE ACCIDENT


Form 4433003 (11-13)

Law Enforcement Case Number:

2024004648

MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

D  
I  
A  
G  
R  
A  
M



N  
A  
R  
R  
A  
T  
I  
V  
E

Unit on was west bound on I-80 and struck a raccoon.



## MEMORANDUM

**TO:** SERGEANT SALDIVAR  
**FROM:** TRP. THOMAS ALLEN  
**DATE:** 02/19/2024  
**SUBJECT:** VEHICLE DAMAGE DUE TO RACCOON HIT

On 02/19/2024 at approximately 2030 hours, I, Trooper Allen, was traveling westbound on Interstate 80 near mile marker 282 when I struck a raccoon running across the roadway. The mileage on my patrol vehicle was at approximately 38,348 miles during the incident and Trooper Brian Smith was riding with me at the time.



# DURANT COLLISION REPAIR

durantcollision@iowatelecom.net  
1303 5th St, P O Box 638, DURANT, IA 52747  
Phone: (563) 785-6353  
FAX: (563) 785-6659

Workfile ID: 0d5aeb5b  
PartsShare: 7NY5pG  
Federal ID: 202958038  
State ID: 116006756

## Preliminary Estimate

**Customer: Iowa State Patrol**

Written By: Craig Moeller

Insured: Iowa State Patrol  
Type of Loss:  
Point of Impact: 11 Left Front

Policy #:  
Date of Loss:

Claim #:  
Days to Repair: 0

**Owner:**  
Iowa State Patrol  
22365 20th Ave.  
Stockton, IA 52769  
(563) 284-9501 Day

**Inspection Location:**  
DURANT COLLISION REPAIR  
1303 5th St  
P O Box 638  
DURANT, IA 52747  
Repair Facility  
(563) 785-6353 Business

**Insurance Company:**

## VEHICLE

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI gray

VIN: 2C3CDXKG6NH256364 Interior Color: Mileage In: 38,451 Vehicle Out:  
License: 27 Exterior Color: gray Mileage Out:  
State: IA Production Date: 11/2022 Condition: Good Job #:

### TRANSMISSION

Automatic Transmission  
4 Wheel Drive

### POWER

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors  
Power Driver Seat

### DECOR

Dual Mirrors  
Tinted Glass  
Overhead Console

### CONVENIENCE

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Keyless Entry  
Message Center  
Steering Wheel Touch Controls

Telescopic Wheel

Climate Control

Backup Camera

Parking Sensors

### RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

### SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

### SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

### WHEELS

Styled Steel Wheels

### PAINT

Clear Coat Paint

### OTHER

Traction Control

Stability Control

California Emissions

Power Trunk/Liftgate

Get live updates at [www.carwise.com/e/4J6j4w](http://www.carwise.com/e/4J6j4w)

**Preliminary Estimate**

**Customer: Iowa State Patrol**

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI gray

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		<b>FRONT BUMPER &amp; GRILLE</b>					
2		O/H front bumper				3.4	
3	* <>	Repl Bumper cover	68267765AC	1	<u>645.19</u>	Incl.	3.4
4		Add for Clear Coat					1.4
5	#	R&I PUSH BAR AND WRAP				2.0	
6	#	R&I APPLIQUE					
		Note: TO BE PAINTED BLACK					
7	#	Rpr ADD FOR 2 TONE					1.2
8		Repl LT Air duct	68214813AA	1	66.60		
9		R&I License bracket				0.1	
10		<b>RADIATOR SUPPORT</b>					
11	*	Repl Front shield w/police	68231862AA	1	<u>251.93</u>	Incl.	
12		<b>FRONT LAMPS</b>					
13		Repl LT Fog lamp bezel halogen	68226543AA	1	27.20	Incl.	
14	**	A/M ***** ADD-ONS *****		1			
15	#	Repl Cover Car		1	10.00		
16		<b>VEHICLE DIAGNOSTICS</b>					
17	*	Pre-repair scan		1	m	0.5 M	
18	*	Post-repair scan		1	m	0.5 M	
<b>SUBTOTALS</b>					<b>1,000.92</b>	<b>6.5</b>	<b>6.0</b>

**ESTIMATE TOTALS**

Category	Basis	Rate	Cost \$
Parts			1,000.92
Body Labor	5.5 hrs @	\$ 68.00 /hr	374.00
Paint Labor	6.0 hrs @	\$ 115.00 /hr	690.00
Mechanical Labor	1.0 hrs @	\$ 85.00 /hr	85.00
Subtotal			2,149.92
<b>Grand Total</b>			<b>2,149.92</b>
Deductible			0.00
<b>CUSTOMER PAY</b>			<b>0.00</b>
<b>INSURANCE PAY</b>			<b>2,149.92</b>

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

## Preliminary Estimate

### Customer: Iowa State Patrol

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI gray

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 02/15/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

#### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

#### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

#### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

**Preliminary Estimate**

**Customer: Iowa State Patrol**

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI gray

**PARTS SUPPLIER LIST**

<b>Line</b>	<b>Supplier</b>	<b>Description</b>	<b>Price</b>
3	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68267765AC Bumper cover Quote: 1775793275 Expires: 03/20/24	\$ 645.19
11	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68231862AA Front shield w/police Quote: 1775863035 Expires: 03/20/24	\$ 251.93

**Preliminary Estimate**

**Customer: Iowa State Patrol**

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI gray

**ALTERNATE PARTS USAGE**

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI gray

VIN: 2C3CDXKG6NH256364 Interior Color: Mileage In: 38,451 Vehicle Out:  
License: 27 Exterior Color: gray Mileage Out:  
State: IA Production Date: 11/2022 Condition: Good Job #:

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	0	1
Optional OEM	Automatically List	0	0
Reconditioned	Automatically List	0	0
Recycled	N/A	0	0



# DURANT COLLISION REPAIR

1303 5th St, P O Box 638, DURANT, IA 52747

Phone: (563) 785-6353, Fax: (563) 785-6659

## Image Report

Owner:	Iowa State Patrol	Insurance:	Estimator:	Craig Moeller	Vehicle Out:		
RO Number:		Claim Number:					
Year:	2022	Color:	gray	License Plate:	27	Production Date:	11/2022
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	38,451
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG6NH256364	Condition:	Good



2/20/2024  
Comments: VINTAG




2/20/2024  
Comments: LF



2/20/2024  
Comments: LR



2/20/2024  
Comments: RR



2/20/2024  
Comments: RF



2/20/2024  
Comments:


# DURANT COLLISION REPAIR

1303 5th St, P O Box 638, DURANT, IA 52747

Phone: (563) 785-6353, Fax: (563) 785-6659


## Image Report

Owner:	Iowa State Patrol	Insurance:		Estimator:	Craig Moeller	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2022	Color:	gray	License Plate:	27	Production Date:	11/2022
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	38,451
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG6NH256364	Condition:	Good




2/20/2024

Comments: FRT UNDERCOVER




2/20/2024

Comments:



2/20/2024

Comments: MILEAGE 38,451



2/20/2024

Comments: VINTAG