

MEMBERS OF COUNCIL

HON. KIM REYNOLDS
GOVERNOR

HON. PAUL D. PATE
SECRETARY OF STATE

HON. ROB SAND
AUDITOR OF STATE

HON. ROBY SMITH
TREASURER OF STATE

HON. MIKE. NAIG
SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING
DES MOINES, IOWA 50319
PHONE: 515 281-5368

March 4, 2024

Accounting Department
Office of the Treasurer
Lucas Building
321 E 12th Street
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$15,929.35, subject to the audit of actual invoices. On December 29, 2023, various vehicles were vandalized. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Victoria Newton
Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services
DAS Fleet Services, Risk
Matt Bender, Department of Management
Heather Hackbarth, Department of Management

AOS Claim # 3664
TOS Job # _____



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

Rob Sand
Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004

Telephone (515) 281-5834 Facsimile (515) 281-6518

February 12, 2024

Victoria Newton
Executive Council
L O C A L

Subject: Damages to Various Vehicles Due to Vandalism on December 29, 2023
Department of Administrative Services
Claim dated January 18, 2024
AOS Claim ID: 3664

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. The Department requested two allocations for a total of \$16,030.86; however, one vendor estimate included sales tax of \$101.51. This amount will be deducted from the Department's request. Therefore, we recommend an Executive Council allocation in the amount of \$15,929.35, subject to an audit of actual invoices.

Sincerely,

A handwritten signature in black ink, appearing to read "Brian R. Brustkern".

Brian R. Brustkern, CPA
Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



Governor Kim Reynolds
 Lt. Governor Adam Gregg
 Adam Steen, Director

Also see page 11 - this is 2 allocations combined

Date: January 18, 2024

To: Tammy Hollingsworth, Auditor of State
 Victoria Newton, Treasurer of State
 Executive Council

From: Karl Bubser, Fleet Administrator
 DAS Fleet Services
 Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#2050, 2613/Vandalism
Event Date	December 28, 2023
Summary	Vehicle 2613, 2050 were vandalized. (272990-002, 272990-004)
Amount Requested	\$2,922.47 - 2613 Estimates <u>\$ 541.42 - 2050 Estimate</u> \$3,463.89 - TOTAL
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Karl Bubser, Fleet Administrator
 DAS Fleet Services
 Karl.Bubser@iowa.gov
 515-281-3162

3664

Vehicle Accident Report

Time and location of accident

Accident Date (Mo/Day/Year)	Time	No. of Vehicles
12/28/2023	Overnight	1
County	State	
Polk	IA	


Vehicle 1 (State vehicle)

Driver's Name		Work Street Address	
NA		6450 Corporate Drive	
Driver's License No./State		City, State, Zip	
NA		Johnston, IA 50131	
Date of Birth	Department	Work Phone	Home Phone
NA	NA	NA	NA
License Plate No.	VIN	Year, Make, Model	
2613	1GNEVLK1PJ228000	2023 CHEVROLET TRAVERSE	
Estimate (\$) of Damage		Description of Damage	
\$1500		Front windshield is cracked and needs to be replaced. Hood dented in 2 spots. The car was vadalized in Iowa PBS parking lot overnight.	

Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

Driver's Name		Street Address	
NA		NA	
Driver's License No./State		City, State, Zip	
NA		NA	
Date of Birth	Work Phone	Home Phone	License Plate No.
NA	NA	NA	NA
Description of Damage			
NA			

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
NA	NA
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
NA	NA
Vehicle No. 2/ Name and Address	Describe Injuries
NA	NA
Witness	
Name	Address/Phone
NA	NA
Name	Address/Phone
NA	NA

Accident Diagram	
<p>Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers. Use number 1 to indicate the State vehicle.</p>	
	<p>Vehicle windshield was cracked by vandals, who also left 2 dents in the hood while it sat in its usual spot overnight in the IowaPBS parking lot at 6450 Corporate Drive in Johnston Iowa. Johnston police apprehended the suspects and have an active investigation going.</p> <p>Johnston PD Contact Info: Officer Josh Seinkiewicz Case #1919</p>



BOB BROWN CHEVROLET
 3600 111TH ST, URBANDALE, IA 50322
 Phone: (515) 278-7866
 FAX: (515) 278-7808

Workfile ID: da8c86
 PartsShare: 7K97
 Federal ID: 42-08462

Preliminary Estimate

Customer: STATE OF IOWA (PBS)

Job Number:

Written By: Scott Matlage

Insured: STATE OF IOWA (PBS) Policy #: Claim #:
 Type of Loss: Date of Loss: Days to Repair: 0
 Point of Impact:

Owner: STATE OF IOWA (PBS) **Inspection Location:** BOB BROWN CHEVROLET
 3600 111TH ST
 URBANDALE, IA 50322
 Repair Facility
 (515) 278-7866 Business **Insurance Company:**

VEHICLE

2023 CHEV Traverse LS AWD (Fleet) 4D UTV 6-3.6L Gasoline Direct Injection WHITE

VIN: 1GNEVLKW1PJ228000 Interior Color: Mileage In: 9,583 Vehicle Out:
 License: 2613 Exterior Color: WHITE Mileage Out:
 State: IA Production Date: 3/2023 Condition: Job #:

TRANSMISSION

Automatic Transmission
 4 Wheel Drive

POWER

Power Steering
 Power Brakes
 Power Windows
 Power Locks
 Power Mirrors
 Heated Mirrors
 Power Driver Seat

DECOR

Dual Mirrors
 Body Side Moldings
 Privacy Glass
 Console/Storage

CONVENIENCE

Air Conditioning
 Intermittent Wipers
 Tilt Wheel
 Cruise Control
 Rear Defogger
 Keyless Entry
 Alarm
 Message Center
 Steering Wheel Touch Controls
 Rear Window Wiper
 Climate Control
 Dual Air Condition
 Backup Camera
 Parking Sensors

RADIO

AM Radio
 FM Radio
 Stereo
 Search/Seek
 Auxiliary Audio Connection
 Satellite Radio

SAFETY

Drivers Side Air Bag
 Passenger Air Bag
 Anti-Lock Brakes (4)
 4 Wheel Disc Brakes
 Traction Control
 Stability Control
 Front Side Impact Air Bags
 Head/Curtain Air Bags
 Communications System

Hands Free Device
 Xenon or L.E.D. Headlamps
 Blind Spot Detection
 Lane Departure Warning

SEATS

Cloth Seats
 Bucket Seats
 3rd Row Seat

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Signal Integrated Mirrors



Preliminary Estimate



Customer: STATE OF IOWA (PBS)

Job Number

Vehicle: CHEV Traverse LS AWD (Fleet) 4D UTV 6-3.6L Gasoline Direct Injection WHITE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		HOOD					
2	Repl	Hood	84023477	1	958.20	1.7	3.0
3		Add for Clear Coat					1.2
4		Add for Underside(Complete)					1.5
5	Repl	Insulator retainer	20064875	6	34.92		
6	#	Refn Tint Paint					0.5
7	#	Subl Hazardous Waste Disposal		1	4.00 T		
SUBTOTALS					997.12	1.7	6.2

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			993.12
Body Labor	1.7 hrs @	\$ 72.00 /hr	122.40
Paint Labor	6.2 hrs @	\$ 0.00 /hr	0.00
Paint Supplies	6.2 hrs @	\$ 122.00 /hr	756.40
Miscellaneous			4.00
Subtotal			1,875.92
Grand Total			1,875.92

MyPriceLink Estimate ID / Quote ID:

1172189824115810304 / 132808526

THIS ESTIMATE IS BASED ON A VISUAL INSPECTION AND DOES NOT INCLUDE ADDITIONAL PARTS OR LABOR THAT MAY BE REQUIRED TO COMPLETE REPAIRS. PART PRICES ARE SUBJECT TO INVOICE.

****WE OFFER A LIMITED LIFETIME WARRANTY FOR AS LONG AS THE CUSTOMER OWNS THE VEHICLE****

SAFELITE FULFILLMENT, INC.



CUSTOMER SERVICE CENTER 1-800-835-2257

IF YOU HAVE ANY QUESTIONS REGARDING
PAYMENT OF THIS INVOICE: 1-800-835-2092

INVOICE 05533-603394

PLEASE REMIT PAYMENT TO:
SAFELITE FULFILLMENT, INC
P.O. BOX 633197
CINCINNATI, OH 45263-3197
PLEASE WRITE INVOICE NUMBER ON CHECK

INVOICE: 01/04/24 BD
ORDERED: 01/02/24 INSTALLED: 01/04/24
W.O. # : 804357 REFERRAL#: 000000
INSURED:
IA DAS FLEET SERVICES
109 SE 13TH ST
DES MOINES IA 50319-0000
PH1:515-725-2243 PH2:

IA DAS FLEET SERVICES
109 SE 13TH ST
DES MOINES IA 50319

Acct #: 225018

POLICY# :
CLAIM # : 2613
AUTH/VER: CHAD

PO#/REF : NA
LOSS LOC:
LOSS DATE/CAUSE: 01/04/24

2023 CHEVROLET TRAVERSE 4 DOOR UTIL DOOR UTILNA							ARR: INSTORE
VIN: 1GNEVLKW1PJ228000 LICENSE/ST: 2613 IA							MILEAGE: 9,597
							STOCK #: 2613
QTY	PART #	LIST	SELLING	LABOR	KIT	MATERIAL	EXTENSION
1	DW02413 GTY	979.31	636.55	85.00	25.00	.00	746.55
	SOLAR~FORWARD COLLISION A						
1	RECAL DYNAMIC	.00	.00	300.00	.00	.00	300.00
	ADAS DYNAMIC RECAL SERV						
PART TOTAL							661.55
LABOR TOTAL							385.00
SUB-TOTAL							1046.55
SALES TAX							0.00
PAY THIS AMOUNT							1046.55
TERMS:							

ADDITIONAL INFO/CLAIMANT

SERVICED BY: COUNTY/B
SAFELITE AUTOGLASS # 05533
CLIVE IA 50325-0000
SAFELITE TAX ID #: 36-4523816
00462-225018-603394

STORE LIC #:
010324-225018-225018

IA DAS FLEET SERVICES
109 SE 13TH ST
DES MOINES IA 50319

0000000020240104742

30064

Vehicle Accident Report

Time and location of accident

Accident Date (Mo/Day/Year)	Time	No. of Vehicles
12/28/2023	Overnight	1
County	State	
Polk	IA	


Vehicle 1 (State vehicle)

Driver's Name		Work Street Address	
NA		6450 Corporate Drive	
Driver's License No./State		City, State, Zip	
NA		Johnston, IA 50131	
Date of Birth	Department	Work Phone	Home Phone
NA	NA	NA	NA
License Plate No.	VIN	Year, Make, Model	
2050	1GNSKKECXKR285765	2019 CHEVROLET SUBURBAN	
Estimate (\$) of Damage		Description of Damage	
\$500		Front windshield is shattered and needs to be replaced. The car was vadalized in Iowa PBS parking lot overnight.	

Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

Driver's Name		Street Address	
NA		NA	
Driver's License No./State		City, State, Zip	
NA		NA	
Date of Birth	Work Phone	Home Phone	License Plate No.
NA	NA	NA	NA
Description of Damage			
NA			

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
NA	NA
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
NA	NA
Vehicle No. 2/ Name and Address	Describe Injuries
NA	NA
Witness	
Name	Address/Phone
NA	NA
Name	Address/Phone
NA	NA

Accident Diagram	
<p>Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers. Use number 1 to indicate the State vehicle.</p>	
	<p>Vehicle windshield was shattered by vandals while it sat in the IowaPBS parking lot at 6450 Corporate Drive in Johnston Iowa. Johnston police apprehended the suspects and have an active investigation going. Case # is</p>

SAFELITE FULFILLMENT, INC.



CUSTOMER SERVICE CENTER 1-800-835-2257

IF YOU HAVE ANY QUESTIONS REGARDING
PAYMENT OF THIS INVOICE: 1-800-835-2092

INVOICE 01502-226058

PLEASE REMIT PAYMENT TO:
SAFELITE FULFILLMENT, INC
P.O. BOX 633197
CINCINNATI, OH 45263-3197
PLEASE WRITE INVOICE NUMBER ON CHECK

INVOICE: 01/04/24
ORDERED: 01/02/24 INSTALLED: 01/04/24
W.O. # : 804359 REFERRAL#: 000000
INSURED:
IA DAS FLEET SERVICES
109 SE 13TH ST
DES MOINES IA 50319-0000
PH1:515-725-2243 PH2:

IA DAS FLEET SERVICES
109 SE 13TH ST
DES MOINES IA 50319

Acct #: 225018

POLICY# :
CLAIM # : 2050
AUTH/VER: CHAD

PO#/REF : 1
LOSS LOC:
LOSS DATE/CAUSE: 01/04/24

2019 CHEVROLET SUBURBAN 4 DOOR UTIL DOOR UTILNA							ARR: MOBILE
VIN: 1GNSKKECXKR285765					LICENSE/ST: 2050	IA	MILEAGE: 1
							STOCK #: 2050
QTY	PART #	LIST	SELLING	LABOR	KIT	MATERIAL	EXTENSION
1	DW02133 GBY	643.25	418.11	85.00	25.00	.00	528.11
	RAIN SENSOR~SOLAR~ACOUSTI						
1	RS 101 PAD	13.31	13.31	.00	.00	.00	13.31
	RAIN SENSOR ADHESIVE						
PART TOTAL							456.42
LABOR TOTAL							85.00
SUB-TOTAL							541.42
SALES TAX							0.00
P A Y T H I S A M O U N T							541.42
TERMS:							

ADDITIONAL INFO/CLAIMANT

STORE LIC #:
010324-225018-225018

SERVICED BY: COUNTY/B
SAFELITE AUTOGLASS # 01502
GRIMES IA 50111-0000
SAFELITE TAX ID #: 36-4523816
00462-225018-226058

IA DAS FLEET SERVICES
109 SE 13TH ST
DES MOINES IA 50319

000000020240104742



Governor Kim Reynolds
 Lt. Governor Adam Gregg
 Adam Steen, Director

Date: January 18, 2024

To: Tammy Hollingsworth, Auditor of State
 Victoria Newton, Treasurer of State
 Executive Council

From: Karl Bubser, Fleet Administrator
 DAS Fleet Services
 Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#105210, 1143, 117536, 8028, 8053, 8091/Vandalism
Event Date	December 28, 2023
Summary	Vehicles were vandalized. (272990-001, 272990-003, 272988-001 thru 004)
Amount Requested	\$ 1,875.92 - 105210 Estimate \$ 1,875.92 - 1143 Estimate \$ 702.59 - 117536 Estimate \$ 5,719.38 - 8028 Estimate \$ 841.57 - 8091 Estimate <u>\$ 1,551.59 - 8053 Estimate</u> \$12,566.97 - TOTAL
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Fucaloro, Fleet Manager
 DAS Fleet Services
mariah.fucaloro@iowa.gov
 515-414-6582



Risk, DAS <das.risk@iowa.gov>

RE: 29C20

1 message

Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>

Wed, Jan 17, 2024 at 11:12 AM

To: "Risk, DAS" <das.risk@iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Cc: Zemira Rahmanovic <Zemira.Rahmanovic@aos.iowa.gov>

212990-001-105210
212990-003-1143

EDU
117536-212988-001
8028-212988-002
8053-212988-004
8091-212988-003

Notification of 29C.20 Damages Received – AOS Claim #3665

From: karl.bubser@iowa.gov <karl.bubser@iowa.gov> **On Behalf Of** Risk, DAS

Sent: Tuesday, January 2, 2024 9:07 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@AOS.IOWA.GOV>; TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Subject: 29C20

CAUTION: This email originated from outside of AOS. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Please accept this email as initial 24 hr notification for AON, multiple vehicles for the Department of Education and Public Television on 12/29/23. I will forward all information as soon as it is received.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

109 SE 13th St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov


<https://das.iowa.gov>



Vehicle Accident Report

Time and location of accident			
Accident Date (Mo/Day/Year)		Time	No. of Vehicles
12/28/2023		Overnight	1
County		State	
Polk		IA	
Vehicle 1 (State vehicle)			
Driver's Name		Work Street Address	
NA		6450 Corporate Drive	
Driver's License No./State		City, State, Zip	
NA		Johnston, IA 50131	
Date of Birth	Department	Work Phone	Home Phone
NA	NA	NA	NA
License Plate No.	VIN	Year, Make, Model	
105210	1GNEVLKW1PJ228126	2023 CHEVROLET TRAVERSE	
Estimate (\$) of Damage		Description of Damage	
\$1500		Large dent in hood. The car was vadalized in Iowa PBS parking lot overnight.	
Vehicle 2 (other vehicle) if more than two vehicles-use additional forms			
Driver's Name		Street Address	
NA		NA	
Driver's License No./State		City, State, Zip	
NA		NA	
Date of Birth	Work Phone	Home Phone	License Plate No.
NA	NA	NA	NA
Description of Damage			
NA			

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
NA	NA
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
NA	NA
Vehicle No. 2/ Name and Address	Describe Injuries
NA	NA
Witness	
Name	Address/Phone
NA	NA
Name	Address/Phone
NA	NA

Accident Diagram	
<p>Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers. Use number 1 to indicate the State vehicle.</p>	
	<p>Vandals left a large dent in the hood while it sat in its usual spot overnight in the IowaPBS parking lot at 6450 Corporate Drive in Johnston Iowa. Johnston police apprehended the suspects and have an active investigation going.</p> <p>Johnston PD Contact Info: Officer Josh Seinkiewicz Case #1919</p>



BOB BROWN CHEVROLET
 3600 111TH ST, URBANDALE, IA 50322
 Phone: (515) 278-7866
 FAX: (515) 278-7808

Workfile ID: f36561
 PartsShare: 7K5
 Federal ID: 42-08462

Preliminary Estimate

Customer: STATE OF IOWA (PBS)

Job Number:

Written By: Scott Matlage

Insured: STATE OF IOWA (PBS)
 Type of Loss:
 Point of Impact:

Policy #:
 Date of Loss:

Claim #:
 Days to Repair: 0

Owner:
 STATE OF IOWA (PBS)

Inspection Location:
 BOB BROWN CHEVROLET
 3600 111TH ST
 URBANDALE, IA 50322
 Repair Facility
 (515) 278-7866 Business

Insurance Company:

VEHICLE

2023 CHEV Traverse LS AWD (Fleet) 4D UTV 6-3.6L Gasoline Direct Injection WHITE

VIN: 1GNEVLKW1PJ228126	Interior Color:	Mileage In: 12,483	Vehicle Out:
License: 105210	Exterior Color: WHITE	Mileage Out:	
State: IA	Production Date: 3/2023	Condition:	Job #:

TRANSMISSION

Automatic Transmission
 4 Wheel Drive

POWER

Power Steering
 Power Brakes
 Power Windows
 Power Locks
 Power Mirrors
 Heated Mirrors
 Power Driver Seat

DECOR

Dual Mirrors
 Body Side Moldings
 Privacy Glass
 Console/Storage

CONVENIENCE

Air Conditioning
 Intermittent Wipers
 Tilt Wheel
 Cruise Control
 Rear Defogger
 Keyless Entry
 Alarm
 Message Center
 Steering Wheel Touch Controls
 Rear Window Wiper
 Climate Control
 Dual Air Condition
 Backup Camera
 Parking Sensors

RADIO

AM Radio
 FM Radio
 Stereo
 Search/Seek
 Auxiliary Audio Connection
 Satellite Radio
SAFETY
 Drivers Side Air Bag
 Passenger Air Bag
 Anti-Lock Brakes (4)
 4 Wheel Disc Brakes
 Traction Control
 Stability Control
 Front Side Impact Air Bags
 Head/Curtain Air Bags
 Communications System

Hands Free Device
 Xenon or L.E.D. Headlamps
 Blind Spot Detection
 Lane Departure Warning

SEATS

Cloth Seats
 Bucket Seats
 3rd Row Seat

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Signal Integrated Mirrors



Preliminary Estimate

Customer: STATE OF IOWA (PBS)

Job Number

2019 CHEV Traverse LS AWD (Fleet) 4D UTV 6-3.6L Gasoline Direct Injection WHITE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		HOOD					
2	Repl	Hood	84023477	1	958.20	1.7	3.0
3		Add for Clear Coat					1.2
4		Add for Underside(Complete)					1.5
5	Repl	Insulator retainer	20064875	6	34.92		
6	#	Refn Tint Paint					0.5
7	#	Subl Hazardous Waste Disposal		1	4.00 T		
SUBTOTALS					997.12	1.7	6.2

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			993.12
Body Labor	1.7 hrs @	\$ 72.00 /hr	122.40
Paint Labor	6.2 hrs @	\$ 0.00 /hr	0.00
Paint Supplies	6.2 hrs @	\$ 122.00 /hr	756.40
Miscellaneous			4.00
Subtotal			1,875.92
Grand Total			1,875.92

MyPriceLink Estimate ID / Quote ID:

1172186028279078912 / 132807499

THIS ESTIMATE IS BASED ON A VISUAL INSPECTION AND DOES NOT INCLUDE ADDITIONAL PARTS OR LABOR THAT MAY BE REQUIRED TO COMPLETE REPAIRS. PART PRICES ARE SUBJECT TO INVOICE.

****WE OFFER A LIMITED LIFETIME WARRANTY FOR AS LONG AS THE CUSTOMER OWNS THE VEHICLE****

Vehicle Accident Report

Time and location of accident			
Accident Date (Mo/Day/Year)	Time	No. of Vehicles	
12/28/2023	Overnight	1	
County	State		
Vehicle 1 (State vehicle)			
Driver's Name		Work Street Address	
NA		6450 Corporate Drive	
Driver's License No./State		City, State, Zip	
NA		Johnston, IA 50131	
Date of Birth	Department	Work Phone	Home Phone
NA	NA	NA	NA
License Plate No.	VIN	Year, Make, Model	
1143	1GNEVMKW5LJ168786	2020	
Estimate (\$) of Damage		Description of Damage	
\$500		The car was vadalized in Iowa PBS parking lot overnight. Hood dented	
Vehicle 2 (other vehicle) if more than two vehicles-use additional forms			
Driver's Name		Street Address	
NA		NA	
Driver's License No./State		City, State, Zip	
NA		NA	
Date of Birth	Work Phone	Home Phone	License Plate No.
NA	NA	NA	NA
Description of Damage			
NA			

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
NA	NA
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
NA	NA
Vehicle No. 2/ Name and Address	Describe Injuries
NA	NA
Witness	
Name	Address/Phone
NA	NA
Name	Address/Phone
NA	NA

Accident Diagram
<p>Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers. Use number 1 to indicate the State vehicle.</p>



BOB BROWN CHEVROLET
 3600 111TH ST, URBANDALE, IA 50322
 Phone: (515) 278-7866
 FAX: (515) 278-7808

Workfile ID: ba16f
 PartsShare: 7K
 Federal ID: 42-08467

Preliminary Estimate

Customer: STATE OF IOWA (PBS)

Job Number:

Written By: Scott Matlage

Insured: STATE OF IOWA (PBS)
 Type of Loss:
 Point of Impact:

Policy #:
 Date of Loss:

Claim #:
 Days to Repair: 0

Owner:
 STATE OF IOWA (PBS)

Inspection Location:
 BOB BROWN CHEVROLET
 3600 111TH ST
 URBANDALE, IA 50322
 Repair Facility
 (515) 278-7866 Business

Insurance Company:

VEHICLE

2020 CHEV Traverse LT2 AWD w/Cloth Interior (Fleet) 4D UTV 6-3.6L Gasoline Direct Injection WHITE

VIN: 1GNEVMKW5LJ168786	Interior Color:	Mileage In: 77,641	Vehicle Out:
License: 1143	Exterior Color: WHITE	Mileage Out:	
State: IA	Production Date: 11/2019	Condition:	Job #:

TRANSMISSION

Automatic Transmission
 4 Wheel Drive

POWER

Power Steering
 Power Brakes
 Power Windows
 Power Locks
 Power Mirrors
 Heated Mirrors
 Power Driver Seat

DECOR

Dual Mirrors
 Body Side Moldings
 Privacy Glass
 Console/Storage

CONVENIENCE

Air Conditioning
 Intermittent Wipers
 Tilt Wheel
 Cruise Control
 Rear Defogger
 Keyless Entry
 Alarm
 Message Center
 Steering Wheel Touch Controls
 Rear Window Wiper
 Climate Control
 Dual Air Condition
 Backup Camera
 Parking Sensors

RADIO

AM Radio
 FM Radio

Stereo
 Search/Seek
 Auxiliary Audio Connection
 Satellite Radio

SAFETY

Drivers Side Air Bag
 Passenger Air Bag
 Anti-Lock Brakes (4)
 4 Wheel Disc Brakes
 Traction Control
 Stability Control
 Front Side Impact Air Bags
 Head/Curtain Air Bags
 Communications System
 Hands Free Device
 Xenon or L.E.D. Headlamps
 Blind Spot Detection

Lane Departure Warning

ROOF

Luggage/Roof Rack

SEATS

Cloth Seats
 Bucket Seats
 3rd Row Seat

WHEELS

Aluminum/Alloy Wheels


PAINT

Clear Coat Paint

OTHER

Fog Lamps
 Signal Integrated Mirrors

Preliminary Estimate



Customer: STATE OF IOWA (PBS)

Job Number

Vehicle: CHEV Traverse LT2 AWD w/Cloth Interior (Fleet) 4D UTV 6-3.6L Gasoline Direct Injection WHITE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	HOOD						
2	Repl	Insulator retainer	20064875	6	34.92		
3	Repl	Hood	84023477	1	958.20	1.7	3.0
4		Add for Clear Coat					1.2
5		Add for Underside(Complete)					1.5
6	#	Refn Tint Paint					0.5
7	#	Subl Hazardous Waste Disposal		1	4.00 T		
SUBTOTALS					997.12	1.7	6.2

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			993.12
Body Labor	1.7 hrs @	\$ 72.00 /hr	122.40
Paint Labor	6.2 hrs @	\$ 0.00 /hr	0.00
Paint Supplies	6.2 hrs @	\$ 122.00 /hr	756.40
Miscellaneous			4.00
Subtotal			1,875.92
Grand Total			1,875.92

MyPriceLink Estimate ID / Quote ID:

1172180699063525376 / 132807042

THIS ESTIMATE IS BASED ON A VISUAL INSPECTION AND DOES NOT INCLUDE ADDITIONAL PARTS OR LABOR THAT MAY BE REQUIRED TO COMPLETE REPAIRS. PART PRICES ARE SUBJECT TO INVOICE.

****WE OFFER A LIMITED LIFETIME WARRANTY FOR AS LONG AS THE CUSTOMER OWNS THE VEHICLE****

Vehicle Accident Report

Time and location of accident

Accident Date (Mo/Day/Year)	Time	No. of Vehicles
1/29	1:00 AM	2
County	State	
Polk	Iowa	


Vehicle 1 (State vehicle)

Driver's Name		Work Street Address	
Jonathan Karli		6500 Corporate Drive	
Driver's License No./State		City, State, Zip	
566AG1201		Johnston, IA 50131	
Date of Birth	Department	Work Phone	Home Phone
11/6/85	Dept of Ed	515-979-8139	
License Plate No.	VIN	Year, Make, Model	
117536		Ford Fusion	
Estimate (\$) of Damage		Description of Damage	
Greg S from Stew Hansen will send to Mariah directly		left side mirror ripped off completely	

Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

Driver's Name		Street Address	
Jonathan Karli		6500 Corporate Drive	
Driver's License No./State		City, State, Zip	
566AG1201		Johnston, IA 50131	
Date of Birth	Work Phone	Home Phone	License Plate No.
11/6/85	515-979-8139		8091
Description of Damage			
left side mirror and casing taken off turn signal ripped out of vehicle			

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
Vehicle No. 2/ Name and Address	Describe Injuries
Witness	
Name	Address/Phone
Name	Address/Phone

Accident Diagram	
<p>Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers. Use number 1 to indicate the State vehicle.</p>	
	<p>Vehicles were vandalized overnight while parked at the Heartland AEA office in Johnston.</p>



Stew Hansen's Urbandale Collision Center

"We Hear You"

12103 Hickman Road, Urbandale, IA 50323

Phone: (515) 331-2904

FAX: (515) 331-2914

Workfile ID: 4c9ef2da

PartsShare: 7K8wQx

Federal ID: 204805431

Preliminary Estimate

Customer: State Of Iowa

Written By: Gino Astone

Insured: State Of Iowa

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 1

Point of Impact:

Owner:

State Of Iowa
301 E 7th St
Des Moines, IA 50319
(515) 979-8139 Cell

Inspection Location:

Stew Hansen's Urbandale Collision Center
12103 Hickman Road
Urbandale, IA 50323
Repair Facility
(515) 331-2904 Business

Insurance Company:

CUSTOMER PAY

VEHICLE

2019 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI Silver-J7

VIN: 3FA6P0G7XKR209697

Interior Color: Black

Mileage In: 95,463

Vehicle Out:

License: 117536

Exterior Color: Silver-J7

Mileage Out:

State: IA

Production Date: 3/2019

Condition: Good

Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

DECOR

Dual Mirrors

Tinted Glass

Console/Storage

Overhead Console

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Backup Camera

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

Blind Spot Detection

Lane Departure Warning

SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

WHEELS

Wheel Covers

PAINT

Clear Coat Paint

OTHER

Traction Control

Stability Control

California Emissions

Preliminary Estimate

Customer: State Of Iowa

2019 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI Silver-J7

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT DOOR					
2	R&I	LT R&I trim panel				0.5	
3	Repl	LT Mirror assy w/o memory Note: Kyle Quote#161388	KS7Z17683ZA	1	287.47	0.5	0.8
4		Add for Clear Coat					0.2
5		Dis/reassmble to refrn				0.6	
6	Repl	LT Mirror cover Note: Kyle Quote#161388	DS7Z17D743AAPT	1	60.52	0.2	0.5
7		Overlap Minor Panel					-0.2
8		Add for Clear Coat					0.1
9	#	Tint Color		1			0.5
10		MISCELLANEOUS OPERATIONS					
11	**	Repl A/M Haz Waste		1	8.00		
SUBTOTALS					355.99	1.8	1.9

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			355.99
Body Labor	1.8 hrs @	\$ 68.00 /hr	122.40
Paint Labor	1.9 hrs @	\$ 68.00 /hr	129.20
Paint Supplies	1.9 hrs @	\$ 50.00 /hr	95.00
Subtotal			702.59
Grand Total			702.59
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			702.59

This estimate is based on a visual inspection and does not include additional parts or labor that may be required to complete the repairs.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Vehicle Accident Report

Time and location of accident

Accident Date (Mo/Day/Year)	Time	No. of Vehicles
1/29	1:00 AM	2
County	State	
Polk	Iowa	

Vehicle 1 (State vehicle)


Driver's Name		Work Street Address	
Jonathan Karli		6500 Corporate Drive	
Driver's License No./State		City, State, Zip	
566AG1201		Johnston, IA 50131	
Date of Birth	Department	Work Phone	Home Phone
11/6/85	Dept of Ed	515-979-8139	
License Plate No.	VIN	Year, Make, Model	
8028		Chevy Malibu	
Estimate (\$) of Damage		Description of Damage	
Greg S from Stew Hansen will send to Mariah directly		cases of sides mirror ripped off damage to the roof - major dent	

Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

Driver's Name		Street Address	
Jonathan Karli		6500 Corporate Drive	
Driver's License No./State		City, State, Zip	
566AG1201		Johnston, IA 50131	
Date of Birth	Work Phone	Home Phone	License Plate No.
11/6/85	515-979-8139		8053
Description of Damage			
side mirror cases ripped off potentially small dents throughout vehicle windshield wipers damaged			

Third vehicle # 8091

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
Vehicle No. 2/ Name and Address	Describe Injuries
Witness	
Name	Address/Phone
Name	Address/Phone

Accident Diagram	
<p>Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers. Use number 1 to indicate the State vehicle.</p>	
	<p>Vehicles were vandalized overnight while parked at the Heartland AEA office in Johnston.</p>



Stew Hansen's Urbandale Collision Center

"We Hear You"

12103 Hickman Road, Urbandale, IA 50323
Phone: (515) 331-2904
FAX: (515) 331-2914

Workfile ID: 16a35b47
PartsShare: 7KBQP5
Federal ID: 204805431

Preliminary Estimate

Customer: State Of Iowa

Written By: Gino Astone

Insured: State Of Iowa Policy #: Claim #:
Type of Loss: Date of Loss: Days to Repair: 6
Point of Impact:

Owner: State Of Iowa
301 E 7th St
Des Moines, IA 50319
(515) 979-8139 Cell

Inspection Location: Stew Hansen's Urbandale Collision Center
12103 Hickman Road
Urbandale, IA 50323
Repair Facility
(515) 331-2904 Business

Insurance Company: CUSTOMER PAY

VEHICLE

2020 CHEV Malibu LS (Fleet) 4D SED 4-1.5L Turbocharged Gasoline Direct Injection Silver-636R

VIN: 1G1ZC5ST8LF076675 Interior Color: Black Mileage In: 45,147 Vehicle Out:
License: 8028 Exterior Color: Silver-636R Mileage Out:
State: IA Production Date: 12/2019 Condition: Good Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Brakes
Power Windows
Power Locks
Power Mirrors

DECOR

Dual Mirrors

CONVENIENCE

Air Conditioning
Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Backup Camera

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Communications System

Hands Free Device

SEATS

Cloth Seats

Bucket Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control

Stability Control

Preliminary Estimate

Customer: State Of Iowa

2020 CHEV Malibu LS (Fleet) 4D SED 4-1.5L Turbocharged Gasoline Direct Injection Silver-636R

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER & GRILLE					
2	R&I	R&I bumper cover Note: Time includes upper reinforcements, molding strip, lower cover, lower deflector, upper retainer, absorber, upper grille, lower grille, grille surround and harness. This part is eligible for a Core Charge. Part Price does not include the Core Charge.				2.1	
3	**	Repl A/M CAPA Lower cover Note: Time includes R&I/R&R lower deflector. Time is after bumper cover is removed. This part is eligible for a Core Charge. Part Price does not include the Core Charge.	84584222	1	228.00	0.9	
4	**	Repl A/M CAPA Lower deflector	23397792	1	86.00	Incl.	
5		HOOD					
6	R&I	R&I hood assy				0.8	
7	*	Rpr Hood Note: Dent upper right side of panel				<u>3.0</u>	2.8
8		Add for Clear Coat					1.1
9	R&I	Insulator				0.3	
10	Repl	Insulator retainer	20064875	6	34.92		
11		ELECTRICAL					
12	*	R&I Battery Note: D&R				<u>0.1</u>	
13	R&I	GPS antenna paint to match				0.3	
14		WINDSHIELD					
15	*	Subl <u>R&I Windshield GM w/o collision alert, w/acoustic glass</u>		1	<u>187.50</u>		
16	**	Repl A/M URETHANE WINDOW KIT #086093		1	96.71		
17		ROOF					
18	*	Repl Roof panel Note: 2.4 deducted for windshield 2.6 deducted for backglass	23387898	1	941.48	<u>13.0</u>	3.4
19		Overlap Major Non-Adj. Panel					-0.2
20		Add for Clear Coat					0.6
21	**	Repl A/M HEAVY BODIED WHITE SEAM SEALER#40477 (Roof)		2	164.86	<u>Incl.</u>	
22	Repl	Rear header	22987011	1	20.04	Incl.	0.6
23	Repl	Rear bow	22987010	1	17.71	0.8	
24		FRONT DOOR					
25	Repl	RT Mirror assy w/o heated w/o object warng	84705490	1	310.93	0.5	
26	Repl	LT Mirror assy w/o heated w/o object warng	84705487	1	310.93	0.5	
27	Repl	RT Mirror cover paint to match	23372288	1	85.83	0.2	0.5
28		Overlap Minor Panel					-0.2
29		Add for Clear Coat					0.1
30	Repl	LT Mirror cover paint to match	23372287	1	89.26	0.2	0.5

Preliminary Estimate

Customer: State Of Iowa

2020 CHEV Malibu LS (Fleet) 4D SED 4-1.5L Turbocharged Gasoline Direct Injection Silver-636R

31		Overlap Minor Panel				-0.2
32		Add for Clear Coat				0.1
33	R&I	RT R&I trim panel			0.6	
34	R&I	LT R&I trim panel			0.6	
35	BACK GLASS					
36	*	Subl R&I Back glass GM	1	187.50	T	
37	**	Repl A/M URETHANE WINDOW KIT #086093	1	96.71		
38	VEHICLE DIAGNOSTICS					
39	*	Rpr Pre-repair scan		m	0.5	M
40	*	Rpr Post-repair scan		m	0.5	M
41	MISCELLANEOUS OPERATIONS					
42	**	Repl A/M CORROSION	1	15.00		
43	**	Repl A/M COVER CAR EXTERIOR	1	5.00		
44	**	Repl A/M HAZARDOUS WASTE	1	8.00		
45	#	Refn TINT COLOR				0.5
SUBTOTALS				2,886.38	24.9	9.6

NOTES

Prior Damage Notes:
Hail

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			2,886.38
Body Labor	23.9 hrs @	\$ 68.00 /hr	1,625.20
Paint Labor	9.6 hrs @	\$ 68.00 /hr	652.80
Mechanical Labor	1.0 hrs @	\$ 75.00 /hr	75.00
Paint Supplies	9.6 hrs @	\$ 50.00 /hr	480.00
Subtotal			5,719.38
Grand Total			5,719.38
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			5,719.38

MyPriceLink Estimate ID / Quote ID:

1174367148030566400 / 133005291

This estimate is based on a visual inspection and does not include additional parts or labor that may be required to complete the repairs.



Stew Hansen's Urbandale Collision Center

"We Hear You"

12103 Hickman Road, Urbandale, IA 50323
Phone: (515) 331-2904
FAX: (515) 331-2914

Workfile ID: 214d4d06
PartsShare: 7KfRKt
Federal ID: 204805431

Preliminary Estimate

Customer: State Of Iowa

Written By: Gino Astone

Insured: State Of Iowa Policy #: Claim #:
Type of Loss: Date of Loss: Days to Repair: 0
Point of Impact: 10 Left Front Pillar (Left Side)

Owner: State Of Iowa
301 E 7th St
Des Moines, IA 50319
(515) 979-8139 Cell

Inspection Location: Stew Hansen's Urbandale Collision Center
12103 Hickman Road
Urbandale, IA 50323
Repair Facility
(515) 331-2904 Business

Insurance Company: CUSTOMER PAY

VEHICLE

2016 CHEV Impala Limited LS (Fleet) 4D SED 6-3.6L Flex Fuel Direct Injection Silver-636R

VIN: 2G1WA5E37G1146006 Interior Color: Black Mileage In: 96,621 Vehicle Out:
License: 8091 Exterior Color: Silver-636R Mileage Out:
State: IA Production Date: 1/2016 Condition: Good Job #:

TRANSMISSION

Automatic Transmission
Overdrive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Body Side Moldings

Tinted Glass

Console/Storage
Wood Interior Trim

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls

RADIO

AM Radio

FM Radio
Stereo

Search/Seek

CD Player

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags

Communications System

Hands Free Device

SEATS

Cloth Seats
Bucket Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
Power Trunk/Liftgate

Preliminary Estimate

Customer: State Of Iowa

2016 CHEV Impala Limited LS (Fleet) 4D SED 6-3.6L Flex Fuel Direct Injection Silver-636R

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		ELECTRICAL					
2	*	R&I Battery				m	<u>0.1</u>
3		STEERING COLUMN					
4		Repl Combo switch Note: SHGMC Sheila Quote#21568	15289426	1	88.25		
5	#	Subl Install Combo Switch Note: 1.3 X 130.00 Labor per Alldata		1	169.00		
6		FRONT DOOR					
7		Repl LT Mirror assy w/o defogger grained Note: SHGMC Sheila Quote#21568	25947195	1	266.12	0.3	0.9
8		Add for Clear Coat					0.2
9		R&I LT R&I trim panel				0.4	
10		VEHICLE DIAGNOSTICS					
11	*	Rpr Pre-repair scan				m	<u>0.5</u> M
12	*	Rpr Post-repair scan				m	<u>0.5</u> M
13		MISCELLANEOUS OPERATIONS					
14	#	Refn Tint Color					0.5
SUBTOTALS					523.37	1.8	1.6

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			523.37
Body Labor	0.8 hrs @	\$ 68.00 /hr	54.40
Paint Labor	1.6 hrs @	\$ 68.00 /hr	108.80
Mechanical Labor	1.0 hrs @	\$ 75.00 /hr	75.00
Paint Supplies	1.6 hrs @	\$ 50.00 /hr	80.00
Subtotal			841.57
Grand Total			841.57
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			841.57

MyPriceLink Estimate ID / Quote ID:

1172555958572818432 / 132872304



Stew Hansen's Urbandale Collision Center

"We Hear You"

12103 Hickman Road, Urbandale, IA 50323

Phone: (515) 331-2904

FAX: (515) 331-2914

Workfile ID:

PartsShare:

Federal ID:

b03d7

7Kn

204805



Preliminary Estimate

Customer: State Of Iowa

Written By: Gino Astone
Adjuster: Hansen, Butch

Insured: State Of Iowa
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 1

Owner:

State Of Iowa
301 E 7th St
Des Moines, IA 50319
(515) 979-8139 Cell

Inspection Location:

Stew Hansen's Urbandale Collision Center
12103 Hickman Road
Urbandale, IA 50323
Repair Facility
(515) 331-2904 Business

Insurance Company:

CUSTOMER PAY

VEHICLE

2020 CHEV Malibu LS (Fleet) 4D SED 4-1.5L Turbocharged Gasoline Direct Injection Silver-636R

VIN: 1G1ZC5ST4LF076768	Interior Color: Black	Mileage In: 47,542	Vehicle Out:
License: 8053	Exterior Color: Silver-636R	Mileage Out:	
State: IA	Production Date: 12/2019	Condition: Good	Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Brakes
Power Windows
Power Locks
Power Mirrors

DECOR

Dual Mirrors

CONVENIENCE

Air Conditioning
Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Backup Camera

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Communications System

Hands Free Device

SEATS

Cloth Seats

Bucket Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control

Stability Control



Preliminary Estimate



Customer: State Of Iowa

2017 Malibu LS (Fleet) 4D SED 4-1.5L Turbocharged Gasoline Direct Injection Silver-636R

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		WINDSHIELD					
2	*	Subl Replace Windshield NAGS Note: Larry to order and install		1	581.25		
3	**	Repl A/M URETHANE WINDOW KIT #086093		1	25.00		
4		Repl LT Wiper arm	23353585	1	50.47	Incl.	
5		Repl LT Wiper blade	84589418	1	36.95	0.1	
6		COWL					
7		R&I Cowl grille				0.7	
8		FRONT DOOR					
9		Repl RT Mirror cover black Note: SHGMC Patrick Quote#21610	84026842	1	62.28	0.2	
10		Repl RT Mirror assy w/o heated w/o object warnng Note: SHGMC Patrick Quote#21610	84705490	1	310.93	0.5	
11		R&I RT R&I trim panel				0.6	
12		VEHICLE DIAGNOSTICS					
13	*	Rpr Pre-repair scan				m 0.5	M
14	*	Rpr Post-repair scan				m 0.5	M
15		MISCELLANEOUS OPERATIONS					
16	**	Repl A/M HAZARDOUS WASTE		1	8.00		
SUBTOTALS					1,074.88	3.1	0.0

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			1,074.88
Body Labor	2.1 hrs @	\$ 82.00 /hr	172.20
Mechanical Labor	1.0 hrs @	\$ 176.00 /hr	176.00
Body Supplies	1.8 hrs @	\$ 15.00 /hr	27.00
Subtotal			1,450.08
Sales Tax	\$ 1,450.08 @	7.0000 %	101.51
Grand Total			1,551.59
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			1,551.59

MyPriceLink Estimate ID / Quote ID:

1173639432645910528 / 132898918