MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE

Executive Council of Iowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

March 4, 2024

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$13,794.46, subject to the audit of actual invoices. On November 21, 2023, Vehicle #418 was damaged by a deer. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Victoria Newton Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services

DAS Fleet Services, Risk

Matt Bender, Department of Management

Heather Hackbarth, Department of Management

TOR OF STATE OF TO

OFFICE OF AUDITOR OF STATE

STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004

Telephone (515) 281-5834 Facsimile (515) 281-6518

February 12, 2024

Victoria Newton Executive Council L O C A L

Subject: Deer Damage to Vehicle #418 on November 21, 2023

Department of Administrative Services

Claim dated December 7, 2023

AOS Claim ID: 3645


In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$13,794.46, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Bri R. Bris

CC: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services
Heather Hackbarth, Department of Management





Date: December 7, 2023

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Karl Bubser, Fleet Administrator

DAS Fleet Services

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#418/Deer		
Event Date	November 21, 2023		
Summary Vehicle 418 hit a deer. (270381)			
Amount Requested	\$13,794.46 - Total Valuation		
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos		

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Karl Bubser, Fleet Administrator

DAS Fleet Services Karl.Bubser@iowa.gov

515-281-3162



Risk, DAS <das.risk@iowa.gov>

29C20

Risk, DAS <das.risk@iowa.gov>

Mon, Nov 27, 2023 at 10:24 AM

<Tammy.Hollingsworth@aos.iowa.gov>, Jeannie R Adams <jadams@dps.state.ia.us> Draft To: TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>, Tammy Hollingsworth

forward all information as soon as it is received. Please accept this email as initial 24 hr notification for AON, vehicle 418 struck a deer on 11/21/23. I will

repairs to vehicles once approval is given. reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident

Thank you,

DAS Risk

Central Procurement and Fleet Services Enterprise

lowa Department of Administrative Services

109 SE 13th St, Des Moines, IA 50319

515-281-3162 office

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us, DAS.risk@iowa.gov, Area Captain & Post #3 Supervisors

- > One Repair Estimate from Approved State Bid Shop
- > DOT MARS Report (if reportable)
- > Memo from the Driver of the State Vehicle
- > 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature⊠) CASE #: 2023029791

OTATE VEHICL	L. (Mark II Act Of	Mature / CASE #.	2023023131					
Date: (Month/Day/Year)	11/21/23	Time: (Time plus a.m./p.m.)	9:16 p.m.					
Vehicle Plate #:	418	Vehicle Mileage:	100616					
Vehicle	110	verlicie ivilleage.	100010					
Description:	2020 Dodge Char) Dodge Charger						
(Yr/Make/Model/ & 2C3CDXKT8LH115063								
Assigned To:	Corey Moore	Badge #	418					
Driven By:	Corey Moore	Badge #	418					
Driver's Lic #:	704XX4347	Damage:	\$18,228					
Vehicle Towed: (Yes / No)	Yes	Towed By:						
Towed To:	Karl Chevrolet Stuart	Towing Cost:	\$0					
Seat Belt: (Yes / No)	Yes	Type of Vehicle: (Marked/Semi /Unmarked)	Marked					
Injured/Injuries:								
Occupants: (Other than driver)								

VEHICLE #2:

DL #:	State:	
Vehicle Lic. #	State:	
Driver's Name:		
Driver's Address:		
Owner's Name:		
Owner's Address:		

	Г									
Owner's Phone:			100000							
Insurance Info:										
(Carrier/Policy #/Phone)										
Veh Description:										
(Yr/Make/Model & Vin#)										
Domogo:	c		04	D = 14.	NI-					
Damage:	\$		Yes /	Belt:	No					
Injured/Injuries:		2 22 200	1 (1007	110)						
Occupants:										
(Other than driver)				T						
Occupant(s) Wearing	ng Seat B	elt: (Yes/No)	Yes						
OTHER INFORMA	TION:									
Witnesses:	11014.									
Accident Location:		Highway	Highway 148 and North Lane RD							
(Street/Hwy)		ingilway 140 and North Lane ND								
County:		Adams	A							
Weather/Road Con	ditions:	Normal								
Narrative: On 11/2	21/23 at 9:	16 PM Tr	ooper	Moore #41	18 was heading to					
assist Cass County										
was black charger v	with no tai	llights and	d doin	g over 100	MPH. A deer ran					
out from the west di										
The accident occurr	red at Hw	y 148 and	North	Lane RD	in Adams County.					
Mileage 100616										
Property Damage o	ther than									
Vehicles:	<u> </u>	Φ.	- X-200							
Cost:		\$								
Citations Issued To: (List Charge(s) and Statute										
(List Charge(s) and Statute	Code(s))									
Investigating Officer	:		Sgt Cı	unningham	#36					
VEHICLE #2.										
VEHICLE #3:		26.31.00		4-4						
DL #: Vehicle Lic. #				tate:						
			5	tate:						
Driver's Name:										

Driver's Address:						
Owner's Name:						
Owner's Address:						
Owner's Phone:						
Insurance Info: (Carrier/Policy #/Phone)						
Veh Description: (Yr/Make/Model & Vin#)						
Damage:	\$		Seat (Yes / I		No	
Injured/Injuries:						
Occupants: (Other than driver)						
Occupant(s) Wearing	ng	Seat Belt: (Yes/No)		Yes		

Form 4433003 (11-13)

INVESTIGATING OFFICER'S REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement Case Number: 2023029791

Sheet 1 of 3

MAIL REPORTS TO: lowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204

	of Accident 1/2023	Time of 21:16	Acciden Hrs		unty AMS -	- 02					Accide	nt occu	rred wi	thin co	rporat	e limits o	of (city)						
U	Driver's Nam MOORE	e - Last									First CORE	Y						Middle					
N	Address 2025 HUNT										City COUNCIL BLUFFS					State IA	Zip 515	03-00	00				
T 1	Date of Birth 09/14/1971		Driver's 704XX4	347		V. (1980) (1984)		CC	DL s No		tion Cha		880				Citation	Charge	2				
	Male Female	IA	Class C			l	Restrictio B	ons C		Cita	tion Cha	rge 3					Citation	Charge	4				
	Alcohol Test		Test R	esults:	1		est Give	n: Te	st Res	sult:	Re-exa	im: Ye	s No		son fo	Re-Exa	m Reque	est:					
	Owner's Nam STATE OF IC										First							Middle)				
	Address 109 SE 13TH										City DES M	OINES	1.0%					State IA	Zip 503	19			
	License Plate		IA		2C3C	DXKT	8LH1150	063			Color GRY			Year 2020	0 0	lake ODG	Walled St.	Model CHAR			Style PC		
	Trailer Plate N	XXXXXXXX		Year	VIN:				2007	-34	Tow 1	Tow #				owed To			3.450	ox. Cost , 228.0		r or Repla	ace
	Insurance Co	OWA					I				Insurar						Policy N						
	Initial Travel [0			Cargo E										ed Area			_	1		n Veh.
	Special Veh.			940 - 0.4.0.00000			al Alignn		\perp			88					er (up to	02	!				
	Carrier Name		OHZOHIA	Alighn	nent	veruc	ar Alignn		SEQI OF E	VENT		t Event	S	econd	Event	Third	Event	Fourth	Even	t M	ost Ha	ırmful l	Event
C	Street Addres						_				City							State	Tz:-	0-4-			
M	Number of Ax		Gross	s Vehic	le We	ight R	ating				US DO	T Numb	nor.	T _N /	1C Nur	nhar	-	Under		Code			
E R	Haz Mat Invol	acceptable		Vat Pla			ard Numi	ber TH	łaz M	at Rel	leased		Mat Cla			t Name		Onden	ide/O	vernu			
C	Trailer Plate:	-	State	Yea	ır	VIN																	
A L	Trailer Plate:		State	Yea	ır	VIN								_		lion	otection	yment			cated	Insport	at scene/enroute
	Converter Dol	lly	Dolly	Plate:		State	Plate \	rear V	'IN					4		Seating Position	Occupant Protection	Airbag Deployment	lion	ction Path	pped/extricated	rce of Transport	at scene
	-					Phor	ne Numb	er: (71	2) 328	3-8001	ľ				×ex	Sea	000	Airb	Ejection	Ejec	Trap	01	01
P E	DRIV	ER OF	UNIT	1		Tran	sported t	o:								Tra	ansported	by:					
E R S	Name							Phone	Numb	ber		D	OB:										
I V	Address										Transpo	rted to:				Tra	ansported	by:					
ΙU	Name							Phone	Numb	ber		D	OB:										
NN	Address										Transpor					Tra	ansported	by:					
J T	Name							Phone	Numb				OB:										
1 0	Address							Dhar-	Muss'		Transpoi		OD:			Tra	nsported	by:					
	Name							Phone	inumb				OB:			-							
	,										Transpor	tea to:				Ira	insported	by:					

OF MOTOR VEHICLE ACCIDENT Law Enforcement Case Number: MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204 2023029791 Date of Accident Time of Accident County Accident occurred within corporate limits of (city) Legal Private 11/21/2023 21:16 ADAMS - 02 Hrs. Intervention? Property? 0 Literal Description County: Route: C **IA 148 N 36MM** 02 N NE E SE S SW W NW If accident occurred outside of X Coordinate: Т city limits show general vicinity of nearest city 352351.968 1 On Road, Street or Highway: At Intersection with: Y Coordinate: 0 4546196 Note: Unless accident occurred at an intersection which is completely described above, use the space below to give the exact location from a milepost or definable intersection, bridge, or railroad crossing, using two distances and directions if neccessaryof If Divided Highway, Provide Route NF F SE S SW W NW (Cardinal) Travel Direction SE S SW W NW NB SB WR EB and Definable intersection, Milepost Number bridge, or railroad crossing Or ACCIDENT ENVIRONMENT ROADWAY CHARACTERISTICS Location of First Harmful Event Weather Conditions (up to two) Major Contributing Circumstances Environment Contributing Circumstances Location (prior to impact Manner of Crash/Collision Roadway Action (prior to crash) at scene/enroute Non-Motorist Type Light Conditions Safety Equipment Surface Conditions Type of Roadway Junction/Feature Struck by Unit Injury Status Condition First Harmful Event (Crash) WORKZONE Yes No Activity Location Type Workers Present RELATED? Sex Name 001 DOB: Phone Number 0 Address: Alcohol Test Given Test Results: Drug Test Given Result Charged Yes No NM 0 Transported to: Transported by: Т 0 Name Phone Number DOB: R Address: Alcohol Test Given Test Results: Drug Test Given Charged Yes No S T Transported to: Transported by: S Object Damaged If Property other than Estimate of Damage vehicles damaged explain OR Owner's Last Name N O First Name Middle Name Phone Number V P EE Address City State Zip Code Was owner or tenant notified? H R 1 = Yes 2 = No 9 = Unknown IT Object Damaged If Property other than Estimate of Damage vehicles damaged explain Owner's Last Name First Name Middle Name Phone Number L D A M Address City State Zip Code Was owner or tenant notified? RG 1 = Yes 2 = No 9 = Unknown ast Name First Name Address City State Zip Code Phone Number W Address Last Name First Name City State Zip Code Phone Number T N Last Name First Name Address City State Zip Code Phone Number E S Last Name First Name Address City State Zip Code Phone Number S Last Name First Name Address City State Zip Code Phone Number Is This a Secondary Crash? Type of Primary Incident Roadway Clearance Date Incident Clearance Date N (11/21/2023 11/21/2023 Signature of Officer Badge Number Time Officer Notified of Accident Roadway Clearance Time Incident Clearance Time TROOPER D GELNER 105 21:16 22:30 Hrs Hrs. Name of Agency Date of Report Time Officer Arrived At Scene Total Roadway Clearance Time Total Incident Clearance Time **IOWA STATE PATROL - DIST 03** 11/21/2023 21:42 000:00 001:14 Hrs. Report Reviewed By Date of Review Investigation made at scene? T.I. No. Other Technical Investigating Agency M WESACK 11/27/2023 Y N (

Form 4433003 (11-13)

INVESTIGATING OFFICER'S REPORT OF MOTOR VEHICLE ACCIDENT

Sheet 3 of 3

Law Enforcement Case Number:

2023029791

MA	MAIL REPORTS TO: Iowa Department of Transportation, Office of Driver Services, P.O. Box 9204, Des Moines, Iowa 50306-9204	
D I A G R A M	Not to scale	
NARRATIVE		struck a deer in the roadway.



MEMORANDUM

TO:

Lt. M. Wesack #412

FROM:

TROOPER COREY MOORE #418

DATE:

11/21/2023

SUBJECT:

Vehicle damage

Lt. Wesack

On 11/21/23 Cass County was in a purist South on Hwy 148 with a black charger with no taillights and doing over 100 MPH. I advised radio I would be in route to assist. As I was in route I heard that Adams county was sending an officer also. While heading that way with my lights and sirens activated I heard that the vehicle had finally stopped but Cass county deputy was waiting for second officer to arrive. I also then later heard traffic that there was one subject in custody and that he was going clear the car. I continued that way in case I was still needed. I wassn't sure if second officer had arrived yet. I overheard that they were going to take the patch so I began so slow down and a deer ran out from the West side and I struck deer. Location Hwy 148 and North Lane RD in Adams County. Mileage 100616

Trooper C. B. Moore #418





Karl Chevrolet of Stuart

Your Dealer for Life 324 sw 8th st, Exit 93 and I-80, Stuart, IA 50250 Phone: (515) 523-8201

Workfile ID: PartsShare: ee2f8c32 7G2Yzm

Federal ID:

82-1627153

Preliminary Estimate

Customer: Iowa State Patrol #418

Written By: Anthony Adams

Insured:

Owner:

Iowa State Patrol #418

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact: 12 Front

Inspection Location:

Insurance Company:

Iowa State Patrol #418

2025 HUNT AVE

COUNCIL BLUFFS, IA 51503

(641) 414-1079 Cell

Karl Chevrolet of Stuart

324 sw 8th st

Exit 93 and I-80 Stuart, IA 50250

Repair Facility

(515) 523-8201 Business

VEHICLE

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI GRAY

VIN:

2C3CDXKT8LH115063

Interior Color:

BLACK

Mileage In:

100,617 Vehicle Out:

License:

418

Exterior Color:

GRAY

Mileage Out:

State:

IA

Production Date:

12/2019

Condition:

Excellent

Job #:

TRANSMISSION

Automatic Transmission

4 Wheel Drive

POWER

Power Steering

Power Brakes

Power Windows

Power Locks **Power Mirrors**

Power Driver Seat

DECOR Dual Mirrors Tinted Glass

Overhead Console

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control Rear Defogger

Keyless Entry

Message Center

Steering Wheel Touch Controls

Telescopic Wheel Climate Control Backup Camera Parking Sensors

RADIO

AM Radio

FM Radio Stereo

Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4) 4 Wheel Disc Brakes Front Side Impact Air Bags

Head/Curtain Air Bags Hands Free Device

SEATS

Cloth Seats **Bucket Seats**

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control Stability Control California Emissions Power Trunk/Liftgate

11/22/2023 5:36:20 PM

416746

Page 1

Customer: Iowa State Patrol #418

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI GRAY

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUMP	ER & G	RILLE					
2			O/H front bumper				3.4	
3		Repl	Bumper cover	68267765AC	1	924.00	Incl.	3.4
4			Add for Clear Coat					1.4
5	#	Repl	FRONT BUMPER GUARD-OPEN FOR INVOICE		1			
6		Repl	Closure panel	68226530AF	1	229.00	Incl.	
7		Repl	RT Support inner	68226532AA	1	40.55	Incl.	
8		Repl	LT Support inner	68226533AA	1	40.55	Incl.	
9		Repl	RT Support outer	68213539AC	1	11.50	Incl.	
10		Repl	LT Support outer	68213538AC	1	11.50	Incl.	
11		Repl	RT Bumper bracket	68226544AB	1	40.55	0.1	
12		Repl	LT Bumper bracket	68226545AB	1	40.55	0.1	
13		Repl	Energy absorber	68214783AA	1	127.00	Incl.	
14		Repl	Impact bar (UHS)	68100209AF	1	434.00	0.7	
15		Repl	Lower grille w/o adaptive cruise	68214782AB	1	139.00	Incl.	
16		Repl	LT Air duct	68214813AA	1	64.15		
17		Repl	License bracket type 1	68202631AB	1	67.15	0.1	
18		Repl	Upper grille black crossbars	5PP33DX8AB	1	459.00	Incl.	
19	#	Repl	WHELEN SIREN-OPEN FOR INVOICE		1		1.5	
20	FRONT LAMPS	;						
21		Repl	RT Headlamp assy halogen	68541680AA	1	922.00	0.4	
22			Aim headlamps				0.5	
23		Repl	LT Headlamp assy halogen	68541681AA	1	1,175.00	0.4	
24		Repl	LT Side marker lamp	68214405AA	1	49.45	Incl.	
25	RADIATOR SU	PPORT	•					
26		Repl	Radiator support	68200478AC	1	405.00	1.0	1.6
open		Repl	RT Air guide 2-piece guide, upper 5.7, 6.4 liter	68085804AA	1	77.05	0.1	
open		Repl	LT Air guide 2-piece guide, upper 5.7, 6.4 liter	68085805AA	1	77.05	0.1	
29		Repl	RT Air guide 2-piece guide, lower 5.7, 6.4 liter	68202656AB	1	27.35	0.1	
30		Repl	LT Air guide 2-piece guide, lower 5.7, 6.4 liter	68202657AB	1	27.35	0.1	
31	*	R&I	Crossmember				0.5	
32	*	Repl	LT Mount bracket	5065533AC	1	18.30	0.5	0.0
33		Repl	Front shield w/police	68231862AA	1	313.00	Incl.	
34		Repl	Front shield pin	68331806AA	5	36.50		
35		Repl	Splash shield AWD w/police	4806075AB	1	129.00	0.2	
36	COOLING							
37		Repl	Radiator	68050126AB	1	685.00 m	2.3	
38			Deduct for Overlap				-0.5	

Customer: Iowa State Patrol #418

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI GRAY

39		Repl	Shroud	68050294AC	1	290.00	m	0.6	
40	#	Repl	ENGINE COOLANT		2	50.00			
41	AIR CONDITIO	NER 8	& HEATER						
42		Repl	Condenser assy	68085784AA	1	658.00	m	1.5	
43			AC Service evacuate & recharge				m	1.4	
44			AC Service refrigerant recovery				m	0.4	
45			Deduct for Overlap					-1.0	
46	#	Repl	R1234YF REFRIGERANT		21	378.00			
47		Repl	Suction line o-ring	68100682AA	1	29.00			
48		Repl	Discharge line o-ring to condenser	68100680AA	1	29.00			
49	HOOD	Martin Marc	2000 2000 2000						
50		Repl		68265445AB	1	1,435.00		1.5	3.
51			Add for Clear Coat						1.
52			Add for Underside(Complete)						1.
53			Add for Clear Coat						0.
54		Repl	Insulator	68438681AA	1	183.00		Incl.	
55		Repl	RT Hinge	55113550AG	1	106.00		0.3	0.
56			Overlap Minor Panel						-0.
57		Repl	Insulator retainer	4878883AA	9	54.45			
58		Repl	LT Hinge	55113551AG	1	106.00		0.3	0.
59			Overlap Minor Panel						-0.
60	FENDER								
61		Repl	RT Fender w/o wide body	68213060AC	1	418.00		1.6	2.0
52			Overlap Major Adj. Panel						-0.
63			Add for Clear Coat						0.
54			Add for Edging						0.
65			Add for Clear Coat						0.:
66	#	Repl	VINYL STICKER		1			0.5	
57		Repl	LT Fender w/o wide body	68213061AC	1	418.00		1.6	2.
58			Overlap Major Adj. Panel						-0.4
59			Add for Clear Coat						0.3
70			Add for Edging						0.5
71			Add for Clear Coat						0.:
72		Repl	LT Fender liner 3.6, 5.7 liter	68205937AH	1	158.00		Incl.	
73		Repl	LT Fender liner retainer	6506132AA	4	38.00			
74		Repl	LT Apron assy from 03/2014 (HSS)	68444165AA	1	196.00	s	7.0	1.5
75			Overlap Major Non-Adj. Panel						-0.2
76		Repl	LT Upper rail (HSS)	68043927AD	1	398.00	S	Incl.	0.8
77			Overlap Minor Panel					00.55004000	-0.2
78		Repl	LT Upper inner rail (HSS)	68037593AA	1	407.00	S	Incl.	0.8
79			Overlap Minor Panel	and the first state of the first to the	4055	encitati K			-0.2
80		Repl	LT Bumper bracket	5065269AC	1	84.90	S	0.8	0.3
81			Add for Clear Coat		-		_	2.0	0.0

Customer: Iowa State Patrol #418

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI GRAY

83		Repl	Air cleaner assy w/police	68413349AB	1	432.00 m	0.5	
84		Repl	Air inlet duct	68413344AA	1	122.00 m	0.3	
85	WHEELS							
86		Repl	LT/Front Hub cap	4895432AA	1	127.00		
87	COWL							
88		R&I	Cowl grille				0.6	
89	PILLARS, ROC	KER &	FLOOR					
90	*	Rpr	LT Aperture panel w/o wide body				<u>1.0</u>	4.
91			Overlap Major Adj. Panel					-0.
92	*		Add for Clear Coat					0.
93	#	R&I	EMERGENCY LAMP				1.0	
94	#	R&I	FLOOD LAMP				1.0	
95	FRONT DOOR							
96		R&I	LT R&I door assy				1.2	
97	*	Rpr	LT Outer panel (HSS)				<u>1.5</u>	2.
98			Overlap Major Adj. Panel					-0.
99	*		Add for Clear Coat					0.
100	#	Repl	VINYL STICKER		1		0.5	
101		R&I	LT Belt w'strip				0.3	
102		Blnd	RT Outer panel (HSS)					1.
103		R&I	RT Belt w'strip				0.3	
104		R&I	RT Applique				0.2	
105		R&I	LT Applique				0.2	
106		R&I	RT Frame molding				0.3	
107		R&I	LT Frame molding				0.3	
108		R&I	RT Power mirror w/o heat, w/o memory, w/o blind spot blue				0.5	
109		R&I	LT Power mirror w/o heat, w/o memory, w/o blind spot blue				0.5	
110		R&I	RT Handle, outside destroyer gray				0.4	
111		R&I	LT Handle, outside destroyer gray				0.4	
112		R&I	RT R&I trim panel				0.5	
113		R&I	LT R&I trim panel				0.5	
114		R&I	RT Frame trim standard audio				0.3	
115		R&I	LT Frame trim standard audio				0.3	
116	QUARTER PAN	EL						
117		Blnd	LT Quarter panel w/o wide body					1.3
118		R&I	LT Wheelhouse liner w/o vented bumper				0.4	
119		R&I	Fuel door				0.3	
120	*	R&I	Fuel pocket				0.5	
121	#	Repl	VINYL STICKER		1		0.5	
122	REAR LAMPS							
123		R&I	LT Tail lamp assy				0.3	

Customer: Iowa State Patrol #418 2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI GRAY 125 R&I R&I bumper cover 1.2 126 Repl A/M Corrosion protection 1 10.00 T 0.3 127 Repl A/M Cover Car 1 10.00 ** 128 Repl A/M Flex additive 1 8.00 129 Refn Feather edge, prime and block 1.0 130 De-Nib Sand and buff - 20% first 3.0 / 10% 131 Setup & measure 1 T 1.5

NOTES

SUBTOTALS

Prior Damage Notes: NONE

132

133

134

135

136

137

138

#

#

#

**

ESTIMATE TOTALS

Rpr TIE DOWN AND PULL

Hazardous waste removal

Pre Repair Scan- Per OEM

Post Repair Scan- Per OEM

Four wheel alignment

Adjacent weld zones,

A/M Cover interior

Guideline

Guideline

Subl

Subl

Rpr

Repl

Category	Basis		Rate	Cost \$
Parts				12,710.90
Parts Discount	\$ 12,259.90		-12.0 %	-1,471.19
Body Labor	48.6 hrs	@	\$ 63.00 /hr	3,061.80
Paint Labor	35,3 hrs	@	\$ 104.00 /hr	3,671.20
Mechanical Labor	1.0 hrs	@	\$ 80.00 /hr	80.00
Miscellaneous				175.45
Subtotal				18,228.16
Grand Total				18,228.16
Deductible				0.00
CUSTOMER PAY				0.00
INSURANCE PAY				18,228.16

1

1

1

1

5.00 T

160.45 X

5.00

12,886.35

2.0

0.9

0.3

0.5 M

0.5 M

49.6

0.9

35.3

THIS IS A PRELIMINARY ESTIMATE. ACTUAL COST TO REPAIR MAY BE DIFFERENT LIMITED LIFETIME WARRANTY--SEE BODY SHOP PERSONNEL FOR DETAILS

***IF AFTERMARKET PARTS (PARTS MADE BY A SOURCE OTHER THAN THE ORIGINAL MANUFACTURER OF THAT

PART) ARE USED THEY WILL BE IDENTIFIED BY "QUAL.REPL.PART" IN THE MFG. PART NO.

DAS - Fleet

Loss/Risk valuation Calculation

Variables - Input:	
Agency	595
Vehicle Number	418
Vehicle - Yr, Make, Mode	
VIN#	2020 Dodge Charger Police 2C3CDXKT8LH115063
Date of Report	
Claim Number	11/21/2023
Mileage	270381
wineage	100,616
Dealership Price - Off Contract	\$40,770.00
Purchase Price - On Contract	\$25,934.19
NADA - Trade in - Clean Value @ Time of Loss	\$21,686.00
Calculations:	
Dealership Price - Off Contract	\$40,770.00
Purchase Price - On Contract	\$25,934.19
Diffe	rence \$14,835.81
Percentage Diffe	rence 36.39%
NADA Value @ Time of Loss or purchase price, which ever is lower	\$21,686.00
Percentage Decrease for Contract Price	36.39%
Loss calculated	13,794.46
Loss Amount to be Provided to Agency:	\$12.704.4C
and the specific states and the specific states and the specific states and the specific states are specif	\$13,794.46
NADA Value @ Time of Loss or purchase price, which ever is lower	4.0.00
Repair Estimate	\$13,794.46
Damage Disclosure Needed (Over 70%)	\$18,228.16
Parinage pisciosare Needed (Over 7070)	132.14%