



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

Rob Sand
Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

June 27, 2025

Kristi Onstot
Executive Council
L O C A L

Subject: Hail Damages to Vehicle #469 on April 17, 2025
Department of Administrative Services
Claim dated April 25, 2025
AOS Claim ID: 4051

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$8,075.25, subject to an audit of actual invoices.

Sincerely,

A handwritten signature in dark ink, appearing to read "Brian R. Brustkern".

Brian R. Brustkern, CPA
Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



Department of
Administrative Services

KIM REYNOLDS, GOVERNOR
CHRIS COURNOYER, LT. GOVERNOR

ADAM STEEN, DIRECTOR

Date: April 25, 2025

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#469 / Hail
Event Date	April 18, 2025
Summary	Vehicle 469 - hail damage (Claim # 305159)
Amount Requested	\$8,075.25 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, & Repair Estimate

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Ryan Betts
DAS Fleet Risk Manager
ryan.betts1@iowa.gov
515-281-8008



Risk, DAS <das.risk@iowa.gov>

Fwd: Trp. Andrew Hansen Hail Damage - April 17

1 message

Risk, DAS <das.risk@iowa.gov>

Tue, Apr 22, 2025 at 11:15 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 469 sustained hail damage on 4/17/2025. Initial documentation is attached.

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

510 E 12th St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov<https://das.iowa.gov>

#4051

**Department of
Administrative Services**

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

----- Forwarded message -----

From: **Johnson Kevin** <kjohnson@dps.state.ia.us>

Date: Tue, Apr 22, 2025 at 11:09 AM

Subject: Trp. Andrew Hansen Hail Damage - April 17

To: DAS.Risk@iowa.gov <das.risk@iowa.gov>, vehicledamage <vehicledamage@dps.state.ia.us>

Cc: Schweitzberger Chad <schweitz@dps.state.ia.us>, Bardsley Jason <bardsley@dps.state.ia.us>, Elwood Nathan <elwood@dps.state.ia.us>

Good morning,

Attached are the damage documents for Trp. Hansen's patrol that received hail damage from the April 17th storm. This is the last documentation from the four District 3 patrol cars that received hail damage.

Thank you.

Lieutenant Kevin Johnson ★87★
District Commander

Iowa State Patrol | District 3
2025 Hunt Ave | Council Bluffs, Iowa 51503
Office: 712-328-8001
kjohnson@dps.state.ia.us

<https://dps.iowa.gov/>

<https://dpscareers.com/>



NOTICE This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

10 attachments



Photo 1.jpg
96K



Photo 2.jpg
64K




Photo 3.jpg
56K



Photo 4.jpg
84K



Photo 5.jpg
72K



Photo 6.jpg
78K




Photo 7.jpg
58K

 **Trp. Hansen - Damage Report 04.17.25.doc**
96K

 **Trp. Hansen - Damage Memorandum 04.17.25.doc**
29K

 **Trp. Hansen - Damage Estimate 04.17.25.pdf**
1892K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us, DAS.risk@iowa.gov, Area Captain & Post #3 Supervisors

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

*****Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!**

STATE VEHICLE: (Mark if Act of Nature ☒) CASE #: 2025009732

Date: (Month/Day/Year)	4/17/25	Time: (Time plus a.m./p.m.)	8:20 p.m.
Vehicle Plate #:	469	Vehicle Mileage:	46500
Vehicle Description: (Yr/Make/Model/ & Vin#)	22/Dodge/Charger 2C3CDXKG1NH240976		
Assigned To:	Trp. Hansen	Badge #	469
Driven By:	Parked	Badge #	469
Driver's Lic #:	089BB6052	Damage:	\$8,075.25
Vehicle Towed: (Yes / No)	No	Towed By:	
Towed To:	N/A	Towing Cost:	\$0
Seat Belt: (Yes / No)	Yes	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:	N/A		
Occupants: (Other than driver)	N/A		

VEHICLE #2:

DL #:	State:
Vehicle Lic. #	State:
Driver's Name:	
Driver's Address:	
Owner's Name:	
Owner's Address:	

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:	None		
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt:	(Yes/No)	Yes	

OTHER INFORMATION:

Witnesses:	
Accident Location: (Street/Hwy)	100 Jackson Blvd Tabor, IA
County:	Fremont
Weather/Road Conditions:	Severe storms
<p>Narrative: Trp. Hansen's patrol car was parked at his residence when severe weather moved through the area. Trp. Hansen's car received hail damage from the storm as it passed.</p>	
Property Damage other than Vehicles:	
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	

Investigating Officer:	Sgt. Bardsley #37
------------------------	-------------------

VEHICLE #3:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		



MEMORANDUM

TO: Post 3 Supervisors

FROM: Trooper Andy Hansen

DATE: 16:12

SUBJECT: Vehicle Damage

On April 17, 2025 at approximately 20:20 hours, I, Trooper Hansen was at my residence during a severe hail storm. I was off duty and my patrol car was parked in my driveway. I had to take shelter in my basement during the storm due to a Tornado in the area. When I checked outside after the storm passed, I observed large hail outside of my residence. I observed golfball and baseball sized hail. My patrol car sustained extensive dents all over the body from the hail.

All Makes Collision Center
524 23rd Ave Council Bluffs, IA 51501
Phone: (712) 256-3195

*** PRELIMINARY ESTIMATE ***

04/22/2025 07:48 AM

Owner

Owner: state of iowa

Control Information

Loss Date: 07:47
File # : 469

Loss Type:
Accounting # :

Inspection

Inspection Date: 04/22/2025 08:05 AM

Inspection Type:

Assigned Date/Time: 07:47 AM
First Contact Date/Time: 07:47 AM
Second Contact Date/Time: 07:47 AM

Received Date/Time: 07:47 AM
Appointment Date/Time: 07:47 AM

Appraiser Name: Kortnie Getzschman

Appraiser License #2 :

Repairer

Repairer: ALL MAKES COLLISION
Address: 524 23rd ave

Contact: KARL GETZSCHMAN
Work/Day: (712)256-3195
Cell: (712)355-0860
Work/Day:

City State Zip: COUNCIL BLUFFS, IA 51501
Email: KARL.AAAUTO@LIVE.COM

Repair Start Date/Time: 07:47 AM
Repair Complete Date/Time: 07:47 AM
Target Complete Date/Time: 07:47 AM

Vehicle Drop Off Date/Time: 07:47 AM
Vehicle Pick Up Date/Time: 07:47 AM
Days To Repair: 26

Vehicle

2022 Dodge Charger Police 4 DR Sedan
6 cyl Gas Flex Fuel 3.6
8-Speed Automatic

Lic Expire:
Veh Insp# :
Condition:
Ext. Refinish: Two-Stage

VIN: 2C3CDXKG1NH240976
Mileage Type: Actual
Code: N3183F
Int. Refinish: Two-Stage

Options

1st Row LCD Monitor(s)
AM/FM Radio
Anti-Lock Brakes
Automatic Power Locks
Black Grille
Cargo Lamp
Color-Keyed Bumper(s)

2nd Row Head Airbags
Aluminum Trim
Armrest(s)
Auxiliary Audio Input
Bright Interior Trim
Center Console
Courtesy/Warning Lights

4-Wheel Drive
Analog Gauges
Auto Adjust Suspension
Black Exterior Trim
Bucket Seats
Chrome Trim
Cruise Control

Daytime Running Lights	Driver Knee Airbag	Dual Air Conditioning
Dual Airbags	Dual Exhaust System	Elect. Stability Control
Electro-Hyd Steering	Electronic Compass	Fuel Door Release
Full Size Spare Tire	Head Airbags	Heated W/S Wiper Washers
Heated Wiper Park	Heavy Duty Cooling	Heavy Duty Suspension
Illuminated Visor Mirror	Independnt Rear Suspensn	Inside Rearview Mirror
Interior Lighting	Intermittent Wipers	Keyless Entry System
Keyless Ignition System	LED Brakelights	Laminated Glass
Leather Steering Wheel	Lighted Entry System	Overhead Console
Power Door Locks	Power Drivers Seat	Power Mirrors
Power Steering	Power Windows	Projector Beam Headlamps
Pwr Accessory Outlet(s)	Racks And Bins	Rain-Sensing W/S Wipers
Rear Bench Seat	Rear View Camera	Rear Window Defroster
Reverse Sensing System	Side Airbags	Spring Suspension
Steel Wheels	Strg Wheel Radio Control	Tachometer
Temperature Gauge(s)	Theft Deterrent System	Tilt & Telescopic Steer
Tinted Glass	Tire Pressure Monitor	Touch Screen Display
Traction Control System	Trip Computer	Velour/Cloth Seats
Wireless Audio Streaming	Wireless Phone Connect	

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
Front Body And Windshield									
1	E	83		Panel,Hood Aluminum	68265445AB	\$1,565.00		1.2	SM
2	L	83	13	Panel,Hood	Refinish 3.1 Surface 1.2 Edge 0.6 Two-stage setup 0.8 Two-stage			5.7	RF
3	BR	103		Fender,Front LT	Blend Refinish 0.9 Blend 0.4 Two-stage			1.3	RF
4	I	104		Fender,Front RT	Repair			5.0*	SM
5	L	104		Fender,Front RT	Refinish 2.1 Surface 0.4 Two-stage			2.5	RF
Roof									
6	I	341		Panel,Roof >> base ball size hail	Repair			12.5*	SM
7	L	341		Panel,Roof	Refinish 3.3 Surface INC Two-stage			3.3	RF
8	RI	347		Roof Headliner R & I	R & I Assembly			4.6	SM
Front Doors									
9	I	208		Door Shell,Front RT	Repair			6.0*	SM
10	L	208		Door Shell,Front RT	Refinish 2.2 Surface 0.4 Two-stage			2.6	RF
11	RI	130		W/Strip,Belt Outer LT	R & I Assembly			0.2	SM
12	RI	131		W/Strip,Belt Outer RT	R & I Assembly			0.2	SM
13	RI	229		Mirror,Outer R/C LT	R & I Assembly			0.9	SM
14	RI	230		Mirror,Outer R/C RT	R & I Assembly			0.8	SM
15	RI	227		Handle,Front Door Otr LT	R & I Assembly			0.2	SM
16	RI	228		Handle,Front Door Otr RT	R & I Assembly			0.2	SM

Rear Doors					
17	I	287	Door Shell,Rear LT	Repair	4.0* SM
18	L	287	Door Shell,Rear LT	Refinish	2.3 RF
				2.2 Surface	
				0.1 Two-stage	
19	RI	325	W/Strip,Belt Outer LT	R & I Assembly	0.2 SM
20	RI	305	Handle,Rear Door Otr LT	R & I Assembly	0.2 SM

Quarter And Rocker Panel					
21	I	503	07 Panel,Bodyside Front LT	Repair	6.5* SM
22	L	503	Panel,Bodyside Front LT	Refinish	3.8 RF
				3.2 Surface	
				0.6 Two-stage	
23	SB	504	Panel,Bodyside Front RT	Sublet Repair	\$250.00* SM
24	I	1389	Pnl,Qtr (in Window Opn LT	Repair	7.5* SM
25	L	1389	Pnl,Qtr (in Window Opn LT	Refinish	2.2 RF
				2.2 Surface	
				INC Two-stage	
26	SB	1390	Pnl,Qtr (in Window Opn RT	Sublet Repair	\$325.00* SM

Deck Lid And Back Glass					
27	I	479	Lid,Rear Deck	Repair	7.0* SM
28	L	479	Lid,Rear Deck	Refinish	2.4 RF
				2.4 Surface	
				INC Two-stage	
29	E	500	N/Plate,Deck Lid	68216156AB	\$78.00 0.2 SM
30	E	506	01 N/Plate,Deck Lid	68216155AA	\$79.25 0.2 SM

Manual Entries					
31	I		remove and install lightba	Repair	SM*
31	Items				
		MC	Message		
		01	CALL DEALER FOR EXACT PART # / PRICE		
		07	STRUCTURAL PART AS IDENTIFIED BY I-CAR		
		13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE		

Estimate Total & Entries

OEM Parts		\$1,722.25		
Parts & Material Total				\$1,722.25
Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs
Sheet Metal (SM)	\$55.00	9.1	48.5	57.6 \$3,168.00
Mech/Elec (ME)	\$55.00			
Frame (FR)	\$55.00			
Refinish (RF)	\$100.00	26.1		26.1 \$2,610.00
Labor Total			83.7 Hours	\$5,778.00
Sublet Repairs			\$575.00	
Gross Total				\$8,075.25
Net Total				\$8,075.25

Alternate Parts Y/02/00/00/02/02 Cumulative 02/00/00/02/02 Zip Code: 51501 Default
Rate Name Default

Audatex Estimating 8.2.530 ES 04/22/2025 08:32 AM REL 8.2.530 DT 03/01/2025
State Disclosure:Not Selected
© 2025 Audatex North America, LLC.

A 50% Blend Refinish calculation of basecoat refinish labor was used for applicable panels on this estimate.
3.3 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.
ESTIMATE CALCULATED USING THE 2.5 HOUR MAXIMUM ALLOWANCE FOR TWO-STAGE REFINISH OF NON-FLEX, EXTERIOR SURFACES.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM= Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2025 Audatex North America, LLC.
AUDATEX is a trademark owned by Audatex North America, LLC. All rights reserved.