



Date: October 6, 2021

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Mariah Flowers, Fleet Manager

DAS Fleet Services

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	# 2318/Hail
Event Date	July 9, 2021
Summary	Vehicle 2318 sustained hail damage during a storm. (225062)
Amount Requested	\$5,694.60 - Estimate \$ 206.50 - Review Invoice \$5,901.10 - Total
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager

DAS Fleet Services

Mariah.Flowers@iowa.gov

515-725-2243

Vehicle Accident Report

Time and location of accide	ent		
Accident Date (Mo/Day/Year)		Time	No. of Vehicles
7/19/21		200 am	1
County		State	-
Black Ho	ank	Fowa	***************************************
Vehicle 1 (State vehicle)			
Driver's Name	7 2 7 7 2 7 1 2 1 2 1 2 1 2 1 2 1 2 1 2	Work Street Address	
Der Ann Sc	liveiner	1404 Ash	
Driver's License No./State		City, State, Zip	
Ja 897 223	3176	Atlantic Da	50022
Date of Birth	Department	Work Phone	Home Phone
9-21-63	Lottern	712-254-145	-9
License Plate No.	VIN	Year, Make, Model	
CIS 095	2 CYRCICG	2021 Chryster	Voyager CX
	2 C4 RC ICG 2ML553029	Description of Damage	0 0
# Wot sure	- estimate	Hail Dame	190
done 8/18	191	7,100	or
Vehicle 2 (other vehicle) if n	nore than two vehicles-use ac	ditional forms	
Driver's Name		Street Address	
Driver's License No./State		City, State, Zip	
Date of Birth	Wark Phone	Home Phone	License Plate No.
Description of Damage			

Date: 10/4/2021 01:05 PM

Estimate ID: 7761080071

Estimate Version: 1

Supplement: 1 (PF) 10/4/2021 01:04:31

Profile ID: * Mitchell

Property Damage Appraisers (PDA Des Moines)

P.O. Box 144, Collins, IA 50055 (515) 222-1906 Fax: (515) 222-1929 Email: pdadesmoines@pdaorg.net

* Not An Authorization For Repair * Read disclaimers following appraisal calculations.

Damage Assessed By: CALEB CUTLER Supplemented By: CALEB CUTLER

Appraised For: MIKE LONG

Classification: Field

Condition Code: Good

Deductible: 0.00

File Number:

7761080071

Claim Number: APDSOI0225062-001

Insured: STATE OF IOWA Owner: STATE OF IOWA

Mitchell Service: 912204

Description: 2021 Chrysler Voyager LX

Body Style: Van

Vehicle Production Date: 3/21 Drive Train: 3.6L Inj 6 Cyl FWD

VIN: 2C4RC1CG2MR553029

License: CIS095 IA

10,992

Mileage: OEM/ALT: 0

Search Code: 776

Type of Loss: Other

Color:

SILVER

PASSENGER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW, POWER STEERING REAR WINDOW DEFOGGER, AIR CONDITION, REAR WINDOW WIPER, CRUISE CONTROL TILT STEERING COLUMN, AM/FM STEREO, DRIVER AIRBAG, HEATED EXTERIOR MIRROR

REAR (DUAL-ZONE) AC, FRONT SIDE AIRBAG WITH HEAD PROTECTION
ANTI-LOCK BRAKE SYS., TRACTION CONTROL, ALUM/ALLOY WHEELS, REARVIEW CAMERA

TIRE INFLATION/PRESSURE MONITOR, AUXILIARY INPUT BLUETOOTH WIRELESS CONNECTIVITY, SATELLITE RADIO

POWER ADJUSTABLE EXTERIOR MIRROR, PRIVACY GLASS, AUTO AIR CONDITION
TRIP COMPUTER, FIRST ROW BUCKET SEAT, SECOND ROW BUCKET SEAT, THIRD ROW SEAT

REAR HEATING, VENTILATION & AIR CONDITIONING, CLOTH SEAT, SIDE AIRBAGS AUTOMATIC HEADLIGHTS, SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION, THIRD DOOR

MP3 PLAYER, DAYTIME RUNNING LIGHTS, 4 DOORS

DRIVER SEAT WITH POWER LUMBAR SUPPORT, ELECTRONIC STABILITY CONTROL

KEYLESS ENTRY SYSTEM, REAR SPOILER, SMART KEY SYSTEM

STEERING WHEEL AUDIO CONTROLS

Line	Entry	Labor		Line Item	Part Type/	Dollar	Labor	r
Item	Number	Туре	Operation	Description	Part Number	Amount	Units	
				Hood		A-1400		
1	200709	BDY	REMOVE/INSTALL	Hood Assy			0.6	
S1 2		BDY	PAINTLESS REPAIR	Hood Panel (Alum)	Sublet	727.50 *	7	#
3				25 NICKEL SIZE DENTS				
4				INCLUDES: ALUMINUM PANEL				
5	200447	BDY	REMOVE/INSTALL	Hood Insulator	Existing		0.3	r
				Front Fender				
S1 6		BDY	PAINTLESS REPAIR	R Fender Panel	Sublet	110.00 *	#	#
7				5 QUARTER SIZE DENTS				
8		BDY	PAINTLESS REPAIR	L Fender Panel	Sublet	100.00	#	#
9				1 NICKEL SIZE DENT				
10	200553	BDY	REMOVE/INSTALL	L Fender Liner	Existing		0.4	r
				Rocker/Pillars				
S1 11	200579	BDY	PAINTLESS REPAIR	R Door Opening Panel	Sublet	227.50 *	0.0*#	‡
			MBER: 08/27/2021 0 OEM: SEP_21_V0929	9:39:44 7761080071				
Sof	tware Ver	sion:	7.1.241	Copyright (C) 1994 - 2021 Mitchell International All Rights Reserved		Page 1	of	4

Date: 10/ 4/2021 01:05 PM
Estimate ID: 7761080071
Estimate Version: 1
Supplement: 1 (P F) 10/ 4/2021 01:04:31

					Profile ID:		,, 2021 01.01.0
12				6 NICKEL SIZE DENTS	Trome 15.	riterien	
13				INCLUDES: DOUBLE PANEL			
14	200580	BDY	PAINTLESS REPAIR	L Door Opening Panel	Sublet	187.50	* 0.0*#
15				6 NICKEL SIZE DENTS			
16				INCLUDES: DOUBLE PANEL			
				Front Door			
S1 17		BDY	PAINTLESS REPAIR	R Frt Door Shell (Steel/HSS/UHSS)	Sublet	218.75	#
18				15 QUARTER SIZE DENTS			
19				INCLUDES: Double Panel			
20	201042		REMOVE/REPLACE	R Frt Door Upper Moulding	68497890AB	59.25	0.3
21	201043	BDY	REMOVE/REPLACE	L Frt Door Upper Moulding	68497891AB	59.25	0.3
				Side Door			
22	201069	BDY	REMOVE/REPLACE	R Otr Side Door Belt Mldg	68188798AF	82.50	0.3
				Van Side Panel			
S1 23		BDY	PAINTLESS REPAIR	R Van Side Panel	Sublet	218.75	*
24				1 NICKEL SIZE DENT			
25		BDY	PAINTLESS REPAIR	L Van Side Panel	Sublet	150.00	
26				6 NICKEL SIZE DENTS			
27	200284		REMOVE/REPLACE	R Van Side Moulding	68497494AA	215.00	0.3
28	200285	BDY	REMOVE/REPLACE	L Van Side Moulding	68497495AA	215.00	0.3
12.122				Roof			
S1 29		BDY	PAINTLESS REPAIR	Roof Panel (UHSS)	Sublet	2,355.00	*
30				151 NICKEL SIZE DENTS			
31				INCLUDES: TALL ROOF PANEL			
32	200104		REMOVE/INSTALL	R Roof Moulding			0.4
33	200105		REMOVE/INSTALL	L Roof Moulding			0.4
34	200106		REMOVE/INSTALL	Roof Antenna			0.3 #
35	200473	BDA	REMOVE/INSTALL	Roof Headliner			4.2 #
26	200470	DDV	DEMONE (THICTALL	<u>Liftgate</u>			
36	200479		REMOVE/INSTALL	Liftgate Assy		0.000 10.000 00.000	1.2
37		BDY	PAINTLESS REPAIR	Liftgate Repair Panel	Sublet	125.00	#
38				3 NICKEL SIZE DENTS			
39				INCLUDES: Double Panel			
40	200461	BDV	DEMONE (INCTALL	Rear Lamps			81 981
41			REMOVE/INSTALL	R Rear Combination Lamp			0.3
41	200462	וטט	REMOVE/INSTALL	L Rear Combination Lamp			0.3
42	933005	PDV	ADD'L OPR	Additional Operations Restore Corrosion Protection		40.5-	
42	933003	ועט	ADD L OFK	Restore Corrosion Protection		10.00	•

^{* -} Judgment Item

Estimate Totals

I.	Labor Subtotals Body	Units 9.9	Rate 64.00	Add'l Labor Amount 10.00	Sublet Amount 4,420.00	Totals	 II.	Part Replacement Summary Taxable Parts	Amount 631,00
	0.00,00000 ₹ 0	Taxable	Labor			5,063.60		Total Replacement Parts Amount	631.00
	Labor Summary	9.9				5,063.60			

ESTIMATE RECALL NUMBER: 08/27/2021 09:39:44 7761080071

Mitchell Data Version: OEM: SEP_21_V0929

Copyright (C) 1994 - 2021 Mitchell International All Rights Reserved

Software Version:

7.1.241

^{# -} Labor Note Applies

r - CEG R&R Time Used For This Labor Operation Paintless Repair calculations provided by Dent Wizard.

Date: 10/4/2021 01:05 PM

Estimate ID: 7761080071

Estimate Version: 1

Supplement: 1 (P F) 10/4/2021 01:04:31 Profile ID: * Mitchell

III.	Additional Costs	Amount	IV.	Adjustments	Amount
	Total Additional Costs	0.00		Insurance Deductible	0.00
				Customer Responsibility	0.00
			I. II. III.	Total Labor: Total Replacement Parts: Total Additional Costs: Gross Total:	5,063.60 631.00 0.00 5,694.60
			IV.	Total Adjustments: Net Total: Less Original Net Total: Net Supplement Amount: S1: CALEB CUTLER	0.00 5,694.60 3,687.10 2,007.50

Point(s) of Impact 16 Non-Collision (P)

> Insurance Co: DAS FLEET SERVICES DES MOINES, IA 50139

Work Phone: (877) 544-7843

Inspection Site: IOWA LOTTERY

Address: 13001 UNIVERSITY AVE

CLIVE, IA 50325

Inspection Date: 8/27/2021

Body Shop: STEW HANSEN'S DODGE CITY BODY SHOP

Address: 12103 HICKMAN RD

DES MOINES, IA 50322

Telephone: (877) 841-4585 Fax Phone: (515) 331-2914 State Lic. No: 204805431

Email: BBIEGHLER@STEWHANSENS.COM

THIS IS NOT AN AUTHORIZATION FOR REPAIR. ALL COSTS OF REPAIRS ARE THE SOLE RESPONSIBILITY OF THE VEHICLE OWNER, WHO MUST AUTHORIZE ALL REPAIRS. FAILURE TO DELIVER A COPY OF THIS APPRAISAL TO THE REPAIR SHOP BY THE VEHICLE OWNER MAY RESULT IN OUT OF POCKET EXPENSE TO THE VEHICLE OWNER. PROVIDING A COPY OF THIS APPRAISAL IS NOT AN ACCEPTANCE OF COVERAGE OR LIABILITY AND ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE DETERMINED BY THE INSURANCE CARRIER.

DEDUCTIBLES MAY OR MAY NOT BE ADDRESSED OR INCLUDED IN THIS APPRAISAL. IF APPLICABLE, THE REPAIRER SHOULD COLLECT THE DEDUCTIBLE FROM THE VEHICLE OWNER PRIOR TO THE RELEASE OF THE REPAIRED VEHICLE.

IT IS THE REPAIRER'S RESPONSIBILITY TO SEND NOTIFICATION OF THE SUPPLEMENT VIA FAX OR EMAIL TO PDA AT 515-222-1929 OR pdadesmoines@pdaorg.net INCLUDING A STATEMENT WHETHER THE REPAIRS HAVE BEEN HALTED ON THE VEHICLE. PDA WILL RESPOND TO YOUR REQUEST WITHIN24 HOURS. PLEASE ALLOW 48 HOURS TO COMPLETE THE SUPPLEMENT PROCESSING FROM THE DATE OF REQUEST TO ENSURE TIMELY RELEASE OF THE VEHICLE.

THIS APPRAISAL IS SUBJECT TO THE COMPLETE REVIEW AND APPROVAL BY THE ASSIGNING INSURANCE COMPANY TO ASSURE ACCURACY, COST EFFECTIVENESS,

ESTIMATE RECALL NUMBER: 08/27/2021 09:39:44 7761080071

Mitchell Data Version: OEM: SEP_21_V0929

Copyright (C) 1994 - 2021 Mitchell International

All Rights Reserved



Due upon receipt

INVOICE NUMBER

INVOICE

INVOICE DATE

		IIII TOTOL HOMBER		INVOICE BATE	
		776-0279)133	08/27/2021	
BILL TO			CLIENT COD)E	
Attn: MIKE LONG DAS FLEET SERVICES		DAS105001			
109 SE 13TH ST			BUSINESS LINE / LC	OSS TYPE	
DES MOINESIA 50139		A - Commercia	l Auto		
FOR INQUIRIES		SUBMIT PAYMEN	IT TO:		
PDA Des Moines, IA #776	Property Damage /	Appraisers, Inc.			
pdadesmoines@pdaorg.net (515) 222-1906		75-1160563 Dept #161, P.O. Bo Memphis, TN 3814	8-0161		
INSURED	CLAIMANT			a copy of the invoice on all payment	
	CLAIMANT		SIGNMENT DATE	PDA ASSIGNMENT #	
STATE OF IOWA			08/24/2021	776-108-0071	
CLAIM#	POLICY#		LOSS DATE	REFERENCE #	
APDSOI0225062-001	20				
	FEE: (1 Unit(s) @ \$179.0	00)		\$ 179.00 \$ 27.50	

ACH Payment Info: Bank: First Horizon Bank ABA (US): 084000026 Bank Account: 220002525824 Email Remit Information to: achbackup@pdaorg.net

Click here to pay your invoice at PDAClientPortal.com

Same-Day Service. Guaranteed. PDA now offers expedited service for standard auto claims in selec	t markets.	- 10 - 10 - 10 - 10 - 10 - 10 - 10 - 10
WE HAVE CHANGED OUR BANK REMITTANCE INFORMATION AS NOTED ABOVE PLEASE UTILIZE OUR PORTAL FOR ALL OTHER ELECTRONIC PAYMENTS.	TOTAL CHARGES:	206.50
Terms: Professional fees due upon receipt. Interest accrues at 1% per month.	:	
Please include the invoice number on all payments.	INVOICE TOTAL:	\$ 206.50