



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: October 4, 2021

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#1079/Deer
Event Date	July 23, 2021
Summary	Vehicle 1079 struck a deer.
Amount Requested	\$2,630.56- Estimate <u>\$ 35.00 - Review Invoice</u> \$2,665.56 - Total
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-725-2243

223937

Fwd: IDALS Vehicle Tip Sheet

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Jul 26, 2021 at 12:02 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS Executive Council <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 1079 struck a deer on 7/23/2021 . I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

**DAS Fleet Services, Risk**

Iowa Department of Administrative Services
Division of Business and Property Services
Office: 515-725-2243
Das.Risk@iowa.gov
<https://das.iowa.gov>

estimate

----- Forwarded message -----

From: **Krutzfeldt, Lloyd** <Lloyd.Krutzfeldt@iowaagriculture.gov>

Date: Mon, Jul 26, 2021 at 9:53 AM

Subject: RE: IDALS Vehicle Tip Sheet

To: Potter, Lisa <Lisa.Potter@iowaagriculture.gov>, DAS.Risk@iowa.gov <DAS.Risk@iowa.gov>

Cc: Keller, Alan <Alan.Keller@iowaagriculture.gov>

From: Potter, Lisa
Sent: Friday, July 23, 2021 7:59 AM
To: Krutzfeldt, Lloyd
Subject: IDALS Vehicle Tip Sheet

Lisa K Potter

Accounting Tech 2

(515)281-5713

Lisa.potter@iowaagriculture.gov



IOWA DEPARTMENT OF
AGRICULTURE &
LAND STEWARDSHIP

Wallace State Office Building

502 E. 9th St. Des Moines, IA 50319



1079 7-23-21 Accident Report.pdf

1375K

Vehicle Accident Report

Time and location of accident

Accident Date (Mo/Day/Year)	Time	No. of Vehicles
07/23/2021	05:30	1
County	State	
Tama	Iowa	

Vehicle 1 (State vehicle)

Driver's Name		Work Street Address	
Lloyd Krutzfeldt		1103 Estelle St.	
Driver's License No./State		City, State, Zip	
725XX7676 / Iowa		Dyart, Iowa 52224	
Date of Birth	Department	Work Phone	Home Phone
09/10/1958	Agriculture	(515) 975-7183	(319) 476-3791
License Plate No.	VIN	Year, Make, Model	
1079	3FA6P0G7XKR151719	2019, Ford, Fusion	
Estimate (\$) of Damage		Description of Damage	
		Left front fender, possibly left front door and left front quarter panel	

Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

Driver's Name		Street Address	
Driver's License No./State		City, State, Zip	
Date of Birth	Work Phone	Home Phone	License Plate No.
Description of Damage			

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
Vehicle No. 2/ Name and Address	Describe Injuries
Witness	
Name	Address/Phone
Name	Address/Phone

Accident Diagram

Complete diagram below, include a description of what happened.
 Use the outline below to sketch the scene of your accident,
 writing in street or highway names or numbers.
 Use number 1 to indicate the State vehicle.

N

Deer

① ← 1079

Hwy E29 approx 4 1/2 m west of
V18

1079 deer hit

1 message

Krutzfeldt, Lloyd <Lloyd.Krutzfeldt@iowaagriculture.gov>

Mon, Jul 26, 2021 at 11:39 AM

To: "DAS.Risk@iowa.gov" <DAS.Risk@iowa.gov>, "Potter, Lisa" <Lisa.Potter@iowaagriculture.gov>

From: Krutzfeldt, Lloyd

Sent: Monday, July 26, 2021 7:14 AM

To: Krutzfeldt, Lloyd

Subject:



1079 deer hit

1 message

Krutzfeldt, Lloyd <Lloyd.Krutzfeldt@iowaagriculture.gov>

Mon, Jul 26, 2021 at 11:39 AM

To: "DAS.Risk@iowa.gov" <DAS.Risk@iowa.gov>, "Potter, Lisa" <Lisa.Potter@iowaagriculture.gov>

From: Krutzfeldt, Lloyd

Sent: Monday, July 26, 2021 7:14 AM

To: Krutzfeldt, Lloyd

Subject:



QUALITY CLAIMS SOLUTIONS

7405 S Bitterroot Pl. Suite 100
SIOUX FALLS, SD 57108
Phone: (877) 237-3727, FAX:(866) 371-2844
qcs@qcsdirect.com

Workfile ID: 178a10e8

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: DEPARTMENT OF AG

Job Number:

Written By: David Kelley

Insured: DEPARTMENT OF AG	Policy #: NOT PROVIDED	Claim #: APDSOI0223937-001
Type of Loss: Collision	Date of Loss: 7/31/2021 12:00 PM	Days to Repair: 0
Point of Impact: 12 Front		

Owner:

DEPARTMENT OF AG
WATERLOO, IA 50702

Inspection Location:

WITHAM COLLISION CENTER
2033 LAPORTE RD
WATERLOO, IA 50702
Other
(319) 236-7217 Evening

Repair Facility:

VEHICLE

2019 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI WHITE

VIN: 3FA6P0G7XKR151719	Production Date:	Interior Color:
License:	Odometer: 45,355	Exterior Color: WHITE
State:	Condition:	

TRANSMISSION

Automatic Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors

DECOR

Dual Mirrors
Tinted Glass
Console/Storage
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Backup Camera

RADIO

AM Radio
FM Radio

Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device
Blind Spot Detection
Lane Departure Warning

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Wheel Covers

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
Signal Integrated Mirrors
California Emissions

Estimate of Record

Owner: DEPARTMENT OF AG

Job Number:

2019 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI WHITE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER & GRILLE					
2		O/H front bumper				2.7	
3	Repl	Bumper cover w/o auto park w/o tow hook	KS7Z17D957ADPTM	1	669.10	Incl.	3.0
4		Add for Clear Coat					1.2
5	R&I	License bracket				0.2	
6		FRONT LAMPS					
7	R&I	RT Headlamp assy w/o signature lamps				0.3	
8	*	LT Headlamp assy w/o signature lamps				<u>0.0</u>	
		Note: Time is after bumper cover is removed. Time includes mount bracket.					
9		FENDER					
10	Repl	RT Fender	HS7Z16005A	1	249.30	1.6	2.0
11		Add for Clear Coat					0.8
12		Add for Edging					0.5
13		Deduct for Overlap				-0.3	
14	R&I	RT Fender liner w/o turbo w/2.5 liter DOHC				Incl.	
15	R&I	RT Upper molding bright/black				Incl.	
16		FRONT DOOR					
17	*	Rpr RT Outer panel				<u>0.5</u>	2.3
18		Overlap Major Adj. Panel					-0.4
19		Add for Clear Coat					0.4
20	R&I	RT Belt molding				0.3	
21	R&I	RT R&I mirror				0.4	
22	R&I	RT Handle, outside w/o passive entry				0.3	
23	R&I	RT R&I trim panel				0.5	
24	#	Hazardous Waste		1	3.00		
25	#	Flex Agent		1	5.00		
26	#	Color Sand/ Buff		1			0.5
27	#	Corrosion Protection		1	10.00	0.3	
28	#	Cover Car		1	5.00	0.2	
29	#	POST SCAN		1		1.0 M	
SUBTOTALS					941.40	8.0	10.3

Estimate of Record

Owner: DEPARTMENT OF AG

Job Number:

2019 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI WHITE

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			941.40
Parts Discount	\$ 918.40	-10.0 %	-91.84
Body Labor	7.0 hrs @	\$ 60.00 /hr	420.00
Paint Labor	10.3 hrs @	\$ 120.00 /hr	1,236.00
Mechanical Labor	1.0 hrs @	\$ 125.00 /hr	125.00
Subtotal			2,630.56
Total Cost of Repairs			2,630.56
Deductible			0.00
Total Adjustments			0.00
Net Cost of Repairs			2,630.56

MyPriceLink Estimate ID / Quote ID:

850746227929653248 / 90327382

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.



Quality Claims Solutions

Quality Claims Solutions

105 N Krohn Place
Sioux Falls, SD 57103
Phone: 877.237.3727
Fax: 866.371.2844

Federal Tax ID: 46-0461202

INVOICE =

Attention/Adjuster: Mike Long
Company Name: DAS Fleet Services
Address: 109 SE 13th St
Des Moines, IA 50319

Invoice No: APDSOI0223937-001-8733
Date: 08/5/2021 9:12 AM
Customer ID: IWAA
Claim Number: APDSOI0223937-001
Vehicle Owner: DEPARTMENT OF AG

Quantity	Description	Unit Price	Extended Amount
1	Technical Estimate Review	\$35.00	\$35.00

Item Total: \$35.00

Sales Tax: N/A

Invoice Total: \$35.00