



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: July 28, 2021

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Risk Coordinator
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#455, 202, 155/Hail
Event Date	July 9, 2021
Summary	Vehicles 455, 202, 155 sustained hail damage. (Fleet Ref# 223215, 223210, 223211)
Amount Requested	\$4,988.94 - Estimates <u>\$ 35.00 - QCS Invoice</u> \$5,023.94 - Total
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Risk Coordinator
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-725-2243



Fwd: Hail Damage - ISP District 1 Cars - 455, 202, 155.

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Jul 19, 2021 at 10:57 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicles 455, 202 & 155 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



DAS Fleet Services, Risk
Iowa Department of Administrative Services
Division of Business and Property Services
Office: 515-725-2243
Das.Risk@iowa.gov
<https://das.iowa.gov>

223215
223210
223211

----- Forwarded message -----

From: **Ludwig Nathan** <nludwig@dps.state.ia.us>

Date: Wed, Jul 14, 2021 at 9:04 AM

Subject: Hail Damage - ISP District 1 Cars - 455, 202, 155.

To: vehicledamage <vehicledamage@dps.state.ia.us>, das.risk@iowa.gov <das.risk@iowa.gov>

Cc: Guill Bryan <guill@dps.state.ia.us>, Current Michael <current@dps.state.ia.us>, Adams Jeannie <jadams@dps.state.ia.us>

Attached are the required documents for Sgt. Ryan Everett (455), Trooper Spencer Baltes (202) & Trooper Joe Long (155).

I am waiting on an estimate from Trooper Scott Bogdanki (61) and will send by the end of the week.

Thank you

Lieutenant Nathan Ludwig ★ 390 ★

District 1 Commander

Iowa State Patrol

Cell: 515-745-2863

nludwig@dps.state.ia.us



IOWA STATE PATROL

Guided by Tradition, Driven to Serve

COURTESY SERVICE PROTECTION

16 attachments



1.jpg
1740K




2.jpg
2110K




3.jpg
2365K

4.jpg
2017K



 **State Vehicle Damage Report ISP 202 7-9-21.Form.doc**
107K

 **#202HailDamageMemo.docx**
18K


 **Image_Report.pdf**
4095K

 **Preliminary_Estimate.pdf**
72K

 **State Vehicle Damage Report ISP 155 7-9-21.Form.doc**
107K

 **HAIL MEMO.doc**
30K

 **Image_Report.pdf**
3285K

 **Preliminary_Estimate.pdf**
72K

 **Image_Report.pdf**
4536K

 **Preliminary_Estimate.pdf**
71K

 **state vehicle damage form.docx**
38K

 **Everett-Hail Damage Memo.docx**
198K



State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) **CASE #:2021016414**

Date: (Month/Day/Year)	7-9-21	Time: (Time plus a.m./p.m.)	1330hr.
Vehicle Plate #:	455	Vehicle Mileage:	87,000
Vehicle Description: (Yr/Make/Model/ & Vin#)	2016 Dodge Charger 2C3CDXKT3GH319694		
Assigned To:	Sgt. Ryan Everett	Badge #	455
Driven By:	Sgt. Ryan Everett	Badge #	455
Driver's Lic #:		Damage:	\$1,447.29
Vehicle Towed: (Yes / No)	No	Towed By:	
Towed To:		Towing Cost:	\$
Seat Belt: (Yes / No)	Yes	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:			
Occupants: (Other than driver)			

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

OTHER INFORMATION:

Witnesses:			
Accident Location: (Street/Hwy)			
County:	Polk		
Weather/Road Conditions:			
Narrative: Sgt. Everett's patrol car sustained damage from a hailstorm on 7-9-21. Sgt. Everett's patrol car was parked at his residence in Grimes as he was off duty.			
Property Damage other than Vehicles:			
Cost:	\$		
Citations Issued To: (List Charge(s) and Statute Code(s))			

Investigating Officer:	
------------------------	--

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

**Karl Chevrolet Collision Center
Ankeny**

Your Dealer for Life
1101 Southeast Oralabor Road, Exit 90 and I-35,
Ankeny, IA 50021
Phone: (515) 299-4337
FAX: (515) 964-2293

Workfile ID: d7b250b2
PartsShare: 6kJtQn
Federal ID: 42-1092272
State ID: na
Federal EPA: iado65212904
State EPA: iado65212904

Preliminary Estimate

Customer: STATE OF IOWA 455

Written By: Mark Michael Wright

Insured: STATE OF IOWA 455 Policy #: Claim #: 455
Type of Loss: Date of Loss: Days to Repair: 0
Point of Impact:

Owner: STATE OF IOWA 455
(515) 725-0010 Business

Inspection Location: Karl Chevrolet Collision Center Ankeny
1101 Southeast Oralabor Road
Exit 90 and I-35
Ankeny, IA 50021
Repair Facility
(515) 299-4337 Business

Insurance Company: STATE OF IOWA

VEHICLE

2016 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI SILVER

VIN: 2C3CDXKT3GH319694 Interior Color: BLACK Mileage In: 86,679 Vehicle Out:
License: 455 Exterior Color: SILVER Mileage Out:
State: IA Production Date: 8/2016 Condition: Job #:

TRANSMISSION

4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control

RADIO

AM Radio

FM Radio

Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions
Power Trunk/Liftgate

Get live updates at www.carwise.com/e/43C3Ro

Preliminary Estimate

Customer: STATE OF IOWA 455

2016 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI SILVER

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		HOOD					
2	*	PDR Hood (ALU) +25% Note: PDR 10 quarter		1	<u>218.75</u> T		
3		R&I Insulator				0.3	
4		FENDER					
5	*	PDR LT Fender +25% Note: PDR 1 quarter		1	<u>125.00</u> T		
6		ROOF					
7	*	PDR Roof panel w/o sunroof +25% Note: PDR 8 quarter		1	<u>281.25</u> T		
8		R&I R&I headliner				3.4	
9		FRONT DOOR					
10	*	PDR LT Outer panel (HSS) +25% Note: PDR 1 quarter		1	<u>125.00</u> T		
11		REAR DOOR					
12		Repl LT Applique	57010429AD	1	212.00	0.2	
13		QUARTER PANEL					
14	*	PDR LT Quarter panel +25% Note: PDR 1 nickel		1	<u>93.75</u> T		
15	*	PDR RT Quarter panel +25% Note: PDR 2 quarter		1	<u>125.00</u> T		
16		TRUNK LID					
17	*	PDR Trunk lid w/police w/o camera +25% Note: PDR 5 quarter		1	<u>125.00</u> T		
18	#	R&I LIGHT BAR				1.0	
SUBTOTALS					1,305.75	4.9	0.0

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			212.00
Parts Discount	\$ 212.00	-28.0 %	-59.36
Body Labor	4.9 hrs @	\$ 41.00 /hr	200.90
PDR			1,093.75
Subtotal			1,447.29
Grand Total			1,447.29
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			1,447.29

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: *DPS – Vehicle Damage; DAS – Risk*

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #: 2021016414

Date: (Month/Day/Year)	7/9/2021	Time: (Time plus a.m./p.m.)	1300 p.m.
Vehicle Plate #:	202	Vehicle Mileage:	75,185
Vehicle Description: (Yr/Make/Model/ & Vin#)	2018 Dodge Charger 2C3CDXKT5JH330221		
Assigned To:	Trp. Spencer Baltes	Badge #	202
Driven By:	Trp. Spencer Baltes	Badge #	202
Driver's Lic #:	256DD2304	Damage:	\$2258.75
Vehicle Towed: (Yes / No)	No	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$
Seat Belt: (Yes / No)	No	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:	None		
Occupants: (Other than driver)	None		

VEHICLE #2:

DL #:	N/A	State:	N/A
Vehicle Lic. #		State:	IA
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:	NONE		
Occupants: (Other than driver)	N/A		
Occupant(s) Wearing Seat Belt: (Yes/No)		No	

OTHER INFORMATION:

Witnesses:			
Accident Location: (Street/Hwy)			
County:		Polk	
Weather/Road Conditions:		Dark/Dry	
Narrative: Trooper Baltes was attending DPS In-service training at Camp Dodge on 7/9/21. A severe thunderstorm rolled through the area with high winds and hail. Trooper Baltes's patrol car sustained hail damage to the hood, roof and trunk. There was no damage to the glass or horizontal surfaces of the car.			
Property Damage other than Vehicles:			
Cost:		\$	
Citations Issued To: (List Charge(s) and Statute Code(s))			

Investigating Officer:	
------------------------	--

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			

Driver's Address:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	No		

QUALITY CLAIMS SOLUTIONS

Workfile ID: 9bc2c17b

7405 S Bitterroot Pl. Suite 100
SIOUX FALLS, SD 57108
Phone: (877) 237-3727, FAX:(866) 371-2844
qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: STATE OF IOWA UNIT 202

Job Number:

Written By: David Kelley

Insured: STATE OF IOWA UNIT 202 Policy #: UNKNOWN Claim #: APDSOI0223210-001
Type of Loss: Collision Date of Loss: 7/20/2021 12:00 PM Days to Repair: 0
Point of Impact: 27 Hail

Owner: STATE OF IOWA UNIT 202
Ankeny, IA 50021
Inspection Location: KARL CHEVROLET COLLISION CENTER
ANK
1101 SOUTHEAST ORLABOR ROAD
Ankeny, IA 50021
Other
(515) 299-4337 Evening
Repair Facility:

VEHICLE

2018 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI SILVER

VIN: 2C3CDXKT5JH330221 Production Date: Interior Color: BLACK
License: Odometer: 75,294 Exterior Color: SILVER
State: Condition:

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera

RADIO

AM Radio

FM Radio

Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats

Bucket Seats
Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions
Power Trunk/Liftgate

Estimate of Record

Owner: STATE OF IOWA UNIT 202

Job Number:

2018 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI SILVER

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		HOOD					
2	R&I	Insulator				0.3	
3	*	Subl Hood (ALU)-PDR REPAIR 50 QUARTER		1	468.75		
4		FENDER					
5	*	Subl RT Fender-PDR REPAIR 1 QUARTER +25%		1	125.00		
6		ROOF					
7	R&I	R&I headliner				3.4	
8	*	Subl Roof panel w/o sunroof-PDR REPAIR 20 QUARTER +25%		1	406.25		
9		PILLARS, ROCKER & FLOOR					
10	*	Subl LT Aperture panel-PDR REPAIR 3 QUARTER +25%		1	125.00		
11		REAR DOOR					
12	*	Subl RT Outer panel (HSS)-PDR REPAIR 1 NICKEL +25%		1	93.75		
13	*	Subl LT Outer panel (HSS)-PDR REPAIR 2 NICKEL +25%		1	93.75		
14		QUARTER PANEL					
15	*	Subl RT Quarter panel-PDR REPAIR 16 QUARTER +25%		1	281.25		
16		TRUNK LID					
17	R&I	Trunk lid trim				0.3	
18	*	Subl Trunk lid w/police w/camera-PDR REPAIR 34 QUARTER +25%		1	375.00		
19	#	R&I REMOVE LIGHT BAR				1.0	
SUBTOTALS					1,968.75	5.0	0.0

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			1,968.75
Body Labor	5.0 hrs @	\$ 41.00 /hr	205.00
Subtotal			2,173.75
Total Cost of Repairs			2,173.75
Deductible			0.00
Total Adjustments			0.00
Net Cost of Repairs			2,173.75



Quality Claims Solutions

Quality Claims Solutions

105 N Krohn Place
Sioux Falls, SD 57103
Phone: 877.237.3727
Fax: 866.371.2844
Federal Tax ID: 46-0461202

INVOICE =

Attention/Adjuster: Mike Long
Company Name: DAS Fleet Services
Address: 109 SE 13th St
Des Moines, IA 50319

Invoice No: APDSOI0223210-001-9879
Date: 07/20/2021 3:04 PM
Customer ID: IWAA
Claim Number: APDSOI0223210-001
Vehicle Owner: STATE OF IOWA UNIT 202

Quantity	Description	Unit Price	Extended Amount
1	Technical Estimate Review	\$35.00	\$35.00

Item Total: \$35.00

Sales Tax: N/A

Invoice Total: \$35.00

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: **DPS – Vehicle Damage; DAS – Risk**

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #: 2021016414

Date: (Month/Day/Year)	7/9/2021	Time: (Time plus a.m./p.m.)	1300 p.m.
Vehicle Plate #:	155	Vehicle Mileage:	77,855
Vehicle Description: (Yr/Make/Model/ & Vin#)	2019 Dodge Charger 2C3CDXKT2KH577276		
Assigned To:	Trp. Joe Long	Badge #	155
Driven By:	Trp. Joe Long	Badge #	155
Driver's Lic #:		Damage:	\$1367.90
Vehicle Towed: (Yes / No)	No	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$
Seat Belt: (Yes / No)	No	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:	None		
Occupants: (Other than driver)	None		

VEHICLE #2:

DL #:	N/A	State:	N/A
Vehicle Lic. #		State:	IA
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			

Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:	NONE		
Occupants: (Other than driver)	N/A		
Occupant(s) Wearing Seat Belt: (Yes/No)	No		

OTHER INFORMATION:

Witnesses:	
Accident Location: (Street/Hwy)	
County:	Boone
Weather/Road Conditions:	
Narrative: Trooper Long's patrol car sustained damage from a hailstorm on 7-9-21. Trooper Long's patrol car was parked at his residence in Madrid as he was off duty.	
Property Damage other than Vehicles:	
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	

Investigating Officer:	
------------------------	--

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	No		

**Karl Chevrolet Collision Center
Ankeny**

Your Dealer for Life
1101 Southeast Oralabor Road, Exit 90 and I-35,
Ankeny, IA 50021
Phone: (515) 299-4337
FAX: (515) 964-2293

Workfile ID: 180d69b5
PartsShare: 6kFp2z
Federal ID: 42-1092272
State ID: na
Federal EPA: iado65212904
State EPA: iado65212904

Preliminary Estimate

Customer: STATE OF IOWA UNIT 155

Written By: Mark Michael Wright

Insured: STATE OF IOWA UNIT 155 Policy #: Claim #: 155
Type of Loss: Date of Loss: Days to Repair: 0
Point of Impact:

Owner: STATE OF IOWA UNIT 155
(515) 725-0010 Business
Inspection Location: Karl Chevrolet Collision Center Ankeny
1101 Southeast Oralabor Road
Exit 90 and I-35
Ankeny, IA 50021
Repair Facility
(515) 299-4337 Business
Insurance Company: STATE OF IOWA

VEHICLE

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI SILVER

VIN: 2C3CDXKT2KH577276 Interior Color: BLACK Mileage In: 75,672 Vehicle Out:
License: 155 Exterior Color: SILVER Mileage Out:
State: IA Production Date: 1/2019 Condition: Job #:

TRANSMISSION

4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera
Parking Sensors

RADIO

AM Radio

FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats

Bucket Seats
Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions
Power Trunk/Liftgate

Get live updates at www.carwise.com/e/43A5EC

Preliminary Estimate

Customer: STATE OF IOWA UNIT 155

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI SILVER

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		HOOD					
2	*	PDR Hood (ALU) +25% Note: PDR 25 quarter		1	<u>281.25</u> T		
3		ROOF					
4		R&I R&I headliner				3.4	
5	*	PDR Roof panel w/o sunroof +25% Note: PDR 5 quarter		1	<u>187.50</u> T		
6		PILLARS, ROCKER & FLOOR					
7	*	PDR LT Aperture panel +25% Note: PDR 2 quarter		1	<u>125.00</u> T s		
8	*	PDR RT Aperture panel +25% Note: PDR 2 quarter		1	<u>125.00</u> T s		
9		QUARTER PANEL					
10	*	PDR RT Quarter panel +25% Note: PDR 3 quarter		1	<u>125.00</u> T		
11	*	PDR LT Quarter panel +25% Note: PDR 3 quarter		1	<u>125.00</u> T		
12		TRUNK LID					
13	*	PDR Trunk lid w/police w/camera +25% Note: PDR 6 quarter		1	<u>218.75</u> T		
14	#	R&I LIGHT BAR				1.0	
SUBTOTALS					1,187.50	4.4	0.0

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			0.00
Body Labor	4.4 hrs @	\$ 41.00 /hr	180.40
PDR			1,187.50
Subtotal			1,367.90
Grand Total			1,367.90
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			1,367.90

THIS IS A PRELIMINARY ESTIMATE. ACTUAL COST TO REPAIR MAY BE DIFFERENT

LIMITED LIFETIME WARRANTY--SEE BODY SHOP PERSONNEL FOR DETAILS

***IF AFTERMARKET PARTS (PARTS MADE BY A SOURCE OTHER THAN THE ORIGINAL MANUFACTURER OF THAT