



Governor Kim Reynolds  
Lt. Governor Adam Gregg  
Adam Steen, Director

Date: July 29, 2021

To: Tammy Hollingsworth, Auditor of State  
Victoria Newton, Treasurer of State  
Executive Council

From: Mariah Flowers, Risk Coordinator  
DAS Fleet Services  
Department of Administrative Services

**Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration**

Vehicle / Event	#111, 697, 74, 902, 633/Hail
Event Date	July 9, 2021
Summary	Vehicles sustained hail damage. (Fleet Ref# 223318, 223874, 223743, 223285, 223291)
Amount Requested	\$15,847.15 - Estimates <u>\$ 180.25 - PDA/QCS Invoices</u> <b>\$16,027.40 - Total</b>
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Risk Coordinator  
DAS Fleet Services  
[Mariah.Flowers@iowa.gov](mailto:Mariah.Flowers@iowa.gov)  
515-725-2243

223318

**Fwd: Trooper McFarland #111 Hail Damage 7/9/21**

1 message

\$4,139.80

Risk, DAS &lt;das.risk@iowa.gov&gt;

Tue, Jul 20, 2021 at 10:51 AM

To: Tammy Hollingsworth &lt;Tammy.Hollingsworth@aos.iowa.gov&gt;, TOS ExecutiveCouncil &lt;executivecouncil@tos.iowa.gov&gt;

Please accept this email as initial 24 hr notification for AON, vehicle 111 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

**All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.**

Thank you,

**DAS Fleet Services, Risk**

Iowa Department of Administrative Services  
Division of Business and Property Services  
Office: 515-725-2243  
Das.Risk@iowa.gov  
<https://das.iowa.gov>

----- Forwarded message -----

From: **Lancaster James** <lancaste@dps.state.ia.us>

Date: Mon, Jul 19, 2021 at 10:43 AM

Subject: Trooper McFarland #111 Hail Damage 7/9/21

To: vehicledamage &lt;vehicledamage@dps.state.ia.us&gt;, das.risk@iowa.gov &lt;das.risk@iowa.gov&gt;

Cc: Guill Bryan &lt;guill@dps.state.ia.us&gt;, Halverson David &lt;dhalvers@dps.state.ia.us&gt;, Votroubek Brian &lt;votroube@dps.state.ia.us&gt;

All Concerned:

On 7/9/21 at approximately 1330 hours Trooper McFarland's fully marked Tahoe was parked in a parking lot at Camp Dodge for IFAK Training. Severe weather came through the area and hail damage occurred to the hood and roof. Attached are three photos, memo, State Vehicle Damage Report, and estimate. Thanks!

Sergeant James Lancaster #349

Iowa State Patrol / District 12

22365 20th Avenue

Stockton, Iowa, 52769

Office: 563-284-9501


Cell: 515-371-5974

Fax: 563-284-9504

Email: lancaste@dps.state.ia.us.

---


**6 attachments**




**IMG\_2021-07-19\_10-29-44.JPG**  
42K




**IMG\_2021-07-19\_10-29-53.JPG**  
49K



**IMG\_2021-07-19\_10-30-03.JPG**  
45K

 **document\_98.pdf**  
19K

 **111 Memo.docx**  
18K

 **111 Hail State Vehicle Damage Report.doc**  
95K

## State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: **DPS – Vehicle Damage; DAS – Risk**

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

**STATE VEHICLE: (Mark if Act of Nature  ) CASE #: 2021016414**

Date: <small>(Month/Day/Year)</small>	7/9/2021	Time: <small>(Time plus a.m./p.m.)</small>	01:30 p.m.
Vehicle Plate #:	111	Vehicle Mileage:	66160
Vehicle Description: <small>(Yr/Make/Model/ &amp; Vin#)</small>	2019 Chevrolet Tahoe Police VIN# 1GNSKDEC5KR240695		
Assigned To:	Trp. Trent McFarland	Badge #	111
Driven By:		Badge #	
Driver's Lic #:	162CC9512	Damage:	\$\$4,139.80
Vehicle Towed: <small>(Yes / No)</small>	No	Towed By:	
Towed To:	N/A	Towing Cost:	\$N/A
Seat Belt: <small>(Yes / No)</small>	Yes	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Marked
Injured/Injuries:	None		
Occupants: <small>(Other than driver)</small>	None		

**VEHICLE #2:**

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

**OTHER INFORMATION:**

Witnesses:			
Accident Location: (Street/Hwy)	Camp Dodge IFAK Training Parking Lot		
County:	Polk		
Weather/Road Conditions:	Severe Weather Hail		
Narrative: On 7/9/21 at approximately 1330 hours Trooper McFarland's fully marked Tahoe was parked in a parking lot at Camp Dodge for IFAK Training. Severe weather came through the area and hail damage occurred to the hood and roof.			
Property Damage other than Vehicles:			
Cost:	\$4,139.80		
Citations Issued To: (List Charge(s) and Statute Code(s))			

Investigating Officer:	
------------------------	--

**VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)**

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			

Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

**QUALITY AUTO REBUILDERS INC.**

2201 7th Ave, Marion, IA 52302  
Phone: (319) 377-6326  
FAX: (319) 377-8514

Workfile ID: efc0b17f  
PartsShare: 6m2xsv  
Federal ID: 42-0930083

**Preliminary Estimate**

**Customer: Iowa State Patrol, Iowa State Patrol**

**Job Number:**

Written By: Bill Lee III

Insured: Iowa State Patrol, Iowa State Patrol

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 5

Point of Impact: 27 Hail

**Owner:**

Iowa State Patrol, Iowa State Patrol

**Inspection Location:**

QUALITY AUTO REBUILDERS INC.  
2201 7th Ave  
Marion, IA 52302  
Repair Facility  
(319) 377-6326 Business

**Insurance Company:**

**VEHICLE**

2019 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection Silver

VIN: 1GNSKDECSKR240695

Interior Color:

Mileage In: 67,320

Vehicle Out:

License: 111

Exterior Color: Silver

Mileage Out:

State: IA

Production Date:

Condition:

Job #:

**TRANSMISSION**

4 Wheel Drive

**POWER**

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors  
Heated Mirrors  
Power Driver Seat  
Power Passenger Seat

**DECOR**

Dual Mirrors  
Privacy Glass

Console/Storage

**CONVENIENCE**

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Keyless Entry  
Alarm  
Message Center  
Steering Wheel Touch Controls  
Rear Window Wiper  
Climate Control  
Dual Air Condition

Backup Camera

Parking Sensors

**RADIO**

CD Player

**SAFETY**

Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)  
4 Wheel Disc Brakes  
Traction Control  
Stability Control  
Front Side Impact Air Bags  
Head/Curtain Air Bags  
Communications System

Positraction

**SEATS**

Cloth Seats  
Reclining/Lounge Seats  
3rd Row Seat

**WHEELS**

Styled Steel Wheels

**PAINT**

Clear Coat Paint

**TRUCK**

Trailer Hitch  
Trailer Package  
Running Boards/Side Steps

Get live updates at [www.carwise.com/e/43MAWM](http://www.carwise.com/e/43MAWM)

**Preliminary Estimate**

**Customer: Iowa State Patrol, Iowa State Patrol**

**Job Number:**

2019 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection Silver

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		<b>HOOD</b>					
2	**	Repl A/M CAPA Hood	84348410	1	1,100.00	1.1	3.3
3		Add for Clear Coat					1.3
4		Add for Underside(Complete)					1.6
5		Add for Clear Coat					0.3
6	#	R&I Hood vents				3.0	
7		<b>FENDER</b>					
8	#	Subl Hazardous waste removal		1	4.00 T		
9	*	PDR LT Fender Tahoe Note: PDR 8 quarter		1	<u>150.00</u> T		
10	*	PDR RT Fender Tahoe Note: PDR 6 nickel		1	<u>125.00</u> T		
11		<b>ROOF</b>					
12	*	PDR Roof panel w/o PPV, SSV w/o roof rack +50% Note: PDR 80 quarter tall and glue pull to avoid interior removal		1	<u>975.00</u> T		
13		<b>PILLARS, ROCKER &amp; FLOOR</b>					
14	*	PDR RT Uniside assy +25% Note: PDR 6 quarter		1	<u>187.50</u> T s		
15	*	PDR LT Uniside assy +25% Note: PDR 8 quarter		1	<u>187.50</u> T s		
16		<b>FRONT DOOR</b>					
17	*	PDR LT Door shell Tahoe & Yukon Note: PDR 2 nickel		1	<u>75.00</u> T		
18		Repl LT Upper molding chrome	23173661	1	159.00	0.2	
19		<b>QUARTER PANEL</b>					
20	*	PDR LT Quarter panel Note: PDR 2 nickel		1	<u>75.00</u> T		
21	#	Repl Corrosion protection		1	5.00 T	0.3	
22	#	Refn Color tint / color match					0.5
<b>SUBTOTALS</b>					<b>3,043.00</b>	<b>4.6</b>	<b>7.0</b>

**Preliminary Estimate**

**Customer: Iowa State Patrol, Iowa State Patrol**

**Job Number:**

2019 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection Silver

**ESTIMATE TOTALS**

<b>Category</b>	<b>Basis</b>	<b>Rate</b>	<b>Cost \$</b>
Parts			1,259.00
Body Labor	4.6 hrs @	\$ 68.00 /hr	312.80
Paint Labor	7.0 hrs @	\$ 112.00 /hr	784.00
Miscellaneous			9.00
PDR			1,775.00
Subtotal			4,139.80
<b>Grand Total</b>			<b>4,139.80</b>
Deductible			0.00
<b>CUSTOMER PAY</b>			<b>0.00</b>
<b>INSURANCE PAY</b>			<b>4,139.80</b>

**MyPriceLink Estimate ID / Quote ID:**

845413755817828352 / 89533368

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

223874

**Fwd: FW: Hail claim damage form and estimate for CAR 697 DCI**

1 message

#2889

Risk, DAS &lt;das.risk@iowa.gov&gt;

Mon, Jul 26, 2021 at 8:50 AM

To: Tammy Hollingsworth &lt;Tammy.Hollingsworth@aos.iowa.gov&gt;, TOS ExecutiveCouncil &lt;executivecouncil@tos.iowa.gov&gt;

Please accept this email as initial 24 hr notification for AON, vehicle 697 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

**DAS Fleet Services, Risk**

Iowa Department of Administrative Services  
Division of Business and Property Services  
Office: 515-725-2243  
Das.Risk@iowa.gov  
<https://das.iowa.gov>

----- Forwarded message -----

From: **Guill Bryan** <guill@dps.state.ia.us>

Date: Fri, Jul 23, 2021 at 4:26 PM

Subject: FW: Hail claim damage form and estimate for CAR 697 DCI

To: Risk, DAS &lt;das.risk@iowa.gov&gt;, vehicledamage &lt;vehicledamage@dps.state.ia.us&gt;

*Lt. Bryan Guill* ★498★

Commander Fleet &amp; Supply

Iowa Department of Public Safety

30 NE 48<sup>th</sup> Place

Des Moines, IA 50313

F&amp;S Main 515-281-3391

Direct 515-281-3118

Cell 515-201-9958

[guill@dps.state.ia.us](mailto:guill@dps.state.ia.us)[1033program@dps.state.ia.us](mailto:1033program@dps.state.ia.us)

**\*\*Notice\*\*** This e-mail message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this e-mail by an unintended recipient is prohibited. If you have received this e-mail in error, please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this e-mail or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

**From:** Lamp Scott <selamp@dps.state.ia.us>  
**Sent:** Thursday, July 22, 2021 4:46 PM  
**To:** Adams Jeannie <jadams@dps.state.ia.us>; Guill Bryan <guill@dps.state.ia.us>  
**Cc:** Current Michael <current@dps.state.ia.us>  
**Subject:** Hail claim damage form and estimate for CAR 697 DCI

FYI, this is the last vehicle that I have to submit claim forms on, it will be repaired.

Scott E. Lamp, M.A. | Special Agent in Charge

Iowa Division of Criminal Investigation - Department of Public Safety

Iowa Department of Public Safety | Division of Criminal Investigation

Support Operations Bureau: Administration//Transcription//CCH Records-Dissemination

Identification//Fingerprints//Training// Equipment//Fleet & Supply


215 East 7<sup>th</sup> Street | Des Moines | Iowa 50319  
Office: 515-725-6025 (phone) | Cell: 712-898-0478

State Peace Officer proudly serving since 1994, Badge # I-65  
[selamp@dps.state.ia.us](mailto:selamp@dps.state.ia.us)

*Correspondence is Discoverable in State/Federal Courts*

**\*NOTICE\*** This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited.

If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message.



---

**6 attachments**



**Vehicle 697 hail claim.jpg**  
48K



**Vehicle 697 hail photo 1.jpg**  
39K



**Vehicle 697 hail photo 2.jpg**  
40K



**Vehicle 697 hail photo 3.jpg**  
38K

 **7-22-21 Dent Eliminators hail estimate for Car 697.pdf**  
85K

 **State Vehicle Damage Rpt form, 697 hail from 7-09-21.doc**  
105K

## State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: [vehicledamage@dps.state.ia.us](mailto:vehicledamage@dps.state.ia.us) ; [das.risk@iowa.gov](mailto:das.risk@iowa.gov)

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

### STATE VEHICLE: (Mark if Act of Nature ) CASE #:

Date: (Month/Day/Year)	7-09-2021	Time: 3:00pm (Time plus a.m./p.m.)	
Vehicle Plate #:	697	Vehicle Mileage:	56906
Vehicle Description: (Yr/Make/Model/ & Vin#)	2013 Chevy Captiva, 4 door SUV, VIN is 3GNAL2EK6D624702		
Assigned To:	Scott Lamp	Badge #	I-65
Driven By:	Scott Lamp	Badge #	I-65
Driver's Lic #:	540xx9335	Damage:	Hail dents
Vehicle Towed: (Yes / No)	NA	Towed By:	
Towed To:		Towing Cost:	
Seat Belt: (Yes / No)		Type of Vehicle: (Marked/Semi /Unmarked)	
Injured/Injuries:			
Occupants: (Other than driver)	NA		

### VEHICLE #2:

DL #:	NONE	State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

**OTHER INFORMATION:**

Witnesses:	NONE
Accident Location: (Street/Hwy)	
County:	
Weather/Road Conditions:	
Vehicle 697 was parked in the Oran Pape lot on 7-09-21 and has several hail dents on hood and roof. 7-22-21 estimate for repairs from Dent Eliminators is \$2,889.00	
Property Damage other than Vehicles:	
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	

Investigating Officer:	
------------------------	--

**VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)**

DL #:	NONE	State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			

Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			



# Dent Eliminators

<https://www.denteliminators.com/>

**ESTIMATE# 1214**

Date: 07/22/2021

Estimated By: Dent Eliminators

## state of iowa 2

Year: 2013	Vin: 3GNAL2EK6DS624702	Total: <b>\$2,700.00</b>
Make: Chevrolet	Stock/Ro#:	
Model: Captiva Sport	Odometer:	
Color: Silver	License:	

**Services Summary:**

**Hail:** \$2,250.00 - **RT Fender:** \$150.00, **RT Rear Door:** \$150.00, **RT Quarter:** \$150.00, **LT Rear Door:** \$100.00, **LT Front Door:** \$150.00, **LT Fender:** \$150.00, **Hood:** \$120.00, **RT Roof Rail:** \$187.50, **LT Roof Rail:** \$312.50, **Roof:** \$780.00

**R&I/R&R:** \$450.00 - **Hood:** \$48.00, **LT Fender:** \$24.00, **RT Fender:** \$24.00, **LT Front Door:** \$24.00, **LT Rear Door:** \$24.00, **RT Rear Door:** \$24.00, **Roof:** \$186.00, **RT Quarter:** \$24.00, **Trunk:** \$72.00

Service Type	Description	Body Hours	Paint Hours	Total
<b>Hood</b>				
PDR - \$120.00   R&I - \$48.00				
PDR	101-150 dents, Quarter	-	-	-
Add-On	Oversized Dents, 3 @ \$40.00	-	-	\$120.00
Labor, R&I	Insulator	0.3	-	\$18.00
Labor, R&I	Hood	0.5	-	\$30.00
<b>LT Fender</b>				
PDR - \$150.00   R&I - \$24.00				
PDR	6-15 dents, Quarter	-	-	\$150.00
Labor, R&I	Fender Liner	0.4	-	\$24.00
<b>RT Fender</b>				
PDR - \$150.00   R&I - \$24.00				
PDR	6-15 dents, Quarter	-	-	\$150.00
Labor, R&I	Fender Liner	0.4	-	\$24.00
<b>LT Front Door</b>				
PDR - \$150.00   R&I - \$24.00				
PDR	6-15 dents, Quarter	-	-	\$150.00
Labor, R&I	Interior Trim Panel	0.4	-	\$24.00
<b>LT Rear Door</b>				
PDR - \$100.00   R&I - \$24.00				
PDR	1-5 dents, Quarter	-	-	\$100.00
Labor, R&I	Interior Trim Panel	0.4	-	\$24.00
<b>RT Rear Door</b>				
PDR - \$150.00   R&I - \$24.00				
PDR	6-15 dents, Quarter	-	-	\$150.00
Labor, R&I	Interior Trim Panel	0.4	-	\$24.00
<b>Roof</b>				
PDR - \$780.00   R&I - \$186.00				
PDR	101-150 dents, Quarter	-	-	\$700.00
Add-On	Oversized Dents, 2 @ \$40.00	-	-	\$80.00
Labor, R&I	Headliner	2.8	-	\$168.00
Labor, R&I	Antenna	0.3	-	\$18.00
<b>LT Roof Rail</b>				
PDR - \$312.50				
PDR	16-30 dents, Quarter	-	-	\$250.00
Add-On	Glue Pull, 25.0%	-	-	\$62.50

**RT Roof Rail**

PDR - \$187.50				
PDR	6-15 dents, Quarter	-	-	\$150.00
Add-On	Glue Pull, 25.0%	-	-	\$37.50

**RT Quarter**

PDR - \$150.00   R&I - \$24.00				
PDR	6-15 dents, Quarter	-	-	\$150.00
Labor, R&I	Taillight	0.4	-	\$24.00

**Trunk**

R&I - \$72.00				
Labor, R&I	Liftgate	1.2	-	\$72.00

**Estimate Totals**

Service Type	Rate	Hours	Total
<b>PDR</b>	--	--	\$2,250.00
<b>Labor, R&amp;I / R&amp;R</b>	\$60.00	7.5	\$450.00

**Subtotal: \$2,700.00**

**Taxable Subtotal: \$2,700.00**

**Tax Rate Labor (7.00%): \$189.00**

**ESTIMATE TOTAL: \$2,889.00**

By signing above, I hereby authorize DENT ELIMINATORS to perform the estimated repairs to my vehicle(s), and hereby grant you and/or your employees, permission to operate the vehicle(s) herein described on streets, highways or elsewhere for the purpose of testing and/or inspection and/or transport to the repair location. DENT ELIMINATORS will not be held responsible for loss or damage to the vehicle(s) or any articles left in the vehicle in case of fire, theft, accident or any other cause beyond our control.

223743

**Fwd: Tjepkes Vehicle Damage**

1 message

\$4,158.36

Risk, DAS <das.risk@iowa.gov>

Tue, Jul 27, 2021 at 1:24 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 74 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



**DAS Fleet Services, Risk**  
Iowa Department of Administrative Services  
Division of Business and Property Services  
Office: 515-725-2243  
Das.Risk@iowa.gov  
<https://das.iowa.gov>

----- Forwarded message -----

From: **Tjepkes Brett** <tjepkes@dps.state.ia.us>

Date: Tue, Jul 27, 2021 at 9:53 AM

Subject: Tjepkes Vehicle Damage

To: vehicledamage <vehicledamage@dps.state.ia.us>, das.risk@iowa.gov <das.risk@iowa.gov>

Good morning,

Please accept the attached vehicle damage report from severe weather hail incident on July 9, 2021. Included in the estimate is minor damage sustained in a separate incident to the plastic shield under the front bumper and significant wear/sun damage to all four interior door panels.

Thank you,

*Brett A. Tjepkes*, Executive Officer

Office of the Commissioner

Iowa Department of Public Safety


Oran Pape State Office Bldg.

215 E. 7<sup>th</sup> St.

Des Moines, IA 50319

O: 515-725-6181 C: 515-205-0206

[tjepkes@dps.state.ia.us](mailto:tjepkes@dps.state.ia.us)



*\*NOTICE\* This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.*

---

**10 attachments**



**front left interior door panel.jpg**  
59K



**front right interior door panel.jpg**  
55K

**rear left interior door panel.JPG**  
52K



**rear right interior door panel.jpg**  
53K



**front bumper shield.jpg**  
257K



**hail 1.jpg**  
217K



**hail 2.jpg**  
216K

**hail 3.jpg**  
74K



 **Tjepkes State Vehicle Damage Rpt form.doc**  
88K

 **Tjepkes estimate.pdf**  
272K

## State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: [vehicledamage@dps.state.ia.us](mailto:vehicledamage@dps.state.ia.us) ; [das.risk@iowa.gov](mailto:das.risk@iowa.gov)

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

### STATE VEHICLE: (Mark if Act of Nature ) CASE #:

Date: (Month/Day/Year)	July 9, 2021	Time: (Time plus a.m./p.m.)	2:30 p.m.
Vehicle Plate #:	DDG002	Vehicle Mileage:	51,991
Vehicle Description: (Yr/Make/Model/ & Vin#)	2017 Dodge Charger		
Assigned To:	Brett Tjepkes	Badge # 74	
Driven By:	Parked	Badge #	
Driver's Lic #:	783YY9832	Damage:	\$
Vehicle Towed: (Yes / No)	No	Towed By:	
Towed To:		Towing Cost:	\$
Seat Belt: (Yes / No)		Type of Vehicle: (Marked/Semi /Unmarked)	
Injured/Injuries:			
Occupants: (Other than driver)			

### VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

**OTHER INFORMATION:**

Witnesses:	Oran Pape State Office Bldg. employees
Accident Location: (Street/Hwy)	215 E. 7 <sup>th</sup> St., Des Moines, IA 50319
County:	Polk
Weather/Road Conditions:	Severe Thunderstorm, Hail
<b>** Please Include narrative of events here**</b>	
On July 9, 2021 at approximately 2:30 p.m., while parked at the Oran Pape State Office Building my state issued vehicle sustained hail damage from a severe thunderstorm.	
Property Damage other than Vehicles:	None
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	

Investigating Officer:	
------------------------	--

**VEHICLE #3: (if needed) (For more vehicles, please make extra copies of this portion)**

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			

Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			



**Stew Hansen's Urbandale Collision Center**

"We Hear You"

12103 Hickman Road, Urbandale, IA 50323

Phone: (515) 331-2904

FAX: (515) 331-2914

Workfile ID: 444d2d4b  
PartsShare: 6mvdPv  
Federal ID: 204805431

**Preliminary Estimate**

**Customer: State Of Iowa**

Written By: Brad Bieghler

Insured: State Of Iowa  
Type of Loss:  
Point of Impact: 19 All Over

Policy #:  
Date of Loss:

Claim #:  
Days to Repair: 0

**Owner:**  
State Of Iowa

**Inspection Location:**  
Stew Hansen's Urbandale Collision Center  
12103 Hickman Road  
Urbandale, IA 50323  
Repair Facility  
(515) 331-2904 Business

**Insurance Company:**  
STATE OF IOWA

**VEHICLE**

2017 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI BLACK

VIN: 2C3CDXKT0HH546827	Interior Color: BLACK	Mileage In: 52,419	Vehicle Out:
License: DGG002	Exterior Color: BLACK	Mileage Out:	
State: IA	Production Date:	Condition: Good	Job #:

**TRANSMISSION**

4 Wheel Drive

**POWER**

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors  
Power Driver Seat

**DECOR**

Dual Mirrors  
Tinted Glass  
Overhead Console

**CONVENIENCE**

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Keyless Entry  
Message Center  
Steering Wheel Touch Controls  
Telescopic Wheel

**CLIMATE CONTROL**

**RADIO**  
AM Radio

**FM Radio**

Stereo  
Search/Seek  
Auxiliary Audio Connection

**SAFETY**

Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)  
4 Wheel Disc Brakes  
Front Side Impact Air Bags  
Head/Curtain Air Bags

Hands Free Device

**SEATS**

Cloth Seats  
Bucket Seats  
Reclining/Lounge Seats

**WHEELS**

Styled Steel Wheels

**PAINT**

Clear Coat Paint

**OTHER**

Traction Control  
Stability Control  
California Emissions  
Power Trunk/Liftgate

## Preliminary Estimate

**Customer: State Of Iowa**

2017 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI BLACK

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		<b>HOOD</b>					
2	R&I	R&I hood assy				0.6	
3	*	PDR Hood (ALU) +25% Note: PDR 18 quarter		1	<u>281.25</u>		
4	R&I	Insulator				0.3	
5		<b>FENDER</b>					
6	*	PDR LT Fender Note: PDR 3 quarter		1	<u>100.00</u>		
7	Repl	LT Fender liner 3.6, 5.7 liter	68205937AG	1	123.00	0.3	
8		<b>ROOF</b>					
9	*	PDR Roof panel w/o sunroof Note: PDR 38 quarter		1	<u>475.00</u>		
10	R&I	R&I headliner				3.4	
11		<b>PILLARS, ROCKER &amp; FLOOR</b>					
12	*	PDR RT Aperture panel +25% Note: PDR 4 quarter		1	<u>125.00</u> s		
13	*	PDR LT Aperture panel +25% Note: PDR 3 quarter		1	<u>125.00</u> s		
14		<b>FRONT DOOR</b>					
15	*	PDR LT Outer panel (HSS) Note: PDR 3 quarter		1	<u>100.00</u>		
16	*	PDR RT Outer panel (HSS) Note: PDR 2 quarter		1	<u>100.00</u>		
17	Repl	RT Door trim panel dark aluminum trim black, all	5SJ522X9AG	1	905.00	0.6	
18	Repl	LT Door trim panel dark aluminum trim black, all	5SJ532X9AG	1	819.00	0.6	
19		<b>REAR DOOR</b>					
20	*	PDR RT Outer panel (HSS) Note: PDR 2 quarter		1	<u>100.00</u>		
21	*	PDR LT Outer panel (HSS) Note: PDR 2 quarter		1	<u>100.00</u>		
22	Repl	RT Door trim panel w/black trim black	5SD92DX9AF	1	147.00	0.6	
23	Repl	LT Door trim panel w/black trim black	5SD93DX9AF	1	147.00	0.6	
24		<b>QUARTER PANEL</b>					
25	*	PDR RT Quarter panel Note: PDR 8 quarter		1	<u>150.00</u>		
26	*	PDR LT Quarter panel Note: PDR 4 quarter		1	<u>100.00</u>		
27		<b>TRUNK LID</b>					
28	R&I	R&I trunk lid				0.8	

## Preliminary Estimate

**Customer: State Of Iowa**

2017 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI BLACK

29	*	PDR	Trunk lid w/police w/o camera	1	175.00		
			Note: PDR 12 quarter				
30		<b>VEHICLE DIAGNOSTICS</b>					
31	*	Rpr	Post-repair scan			m	0.5 M
32		<b>MISCELLANEOUS OPERATIONS</b>					
33	**	Repl	A/M CORROSION	1	15.00		
<b>SUBTOTALS</b>					<b>4,087.25</b>	<b>8.3</b>	<b>0.0</b>

### NOTES

Prior Damage Notes:  
NONE

### ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			2,156.00
Parts Discount	\$ 2,141.00	-15.0 %	-321.15
Body Labor	7.8 hrs @	\$ 44.20 /hr	344.76
Mechanical Labor	0.5 hrs @	\$ 95.00 /hr	47.50
PDR			1,931.25
Subtotal			4,158.36
<b>Grand Total</b>			<b>4,158.36</b>
Deductible			0.00
<b>CUSTOMER PAY</b>			<b>0.00</b>
<b>INSURANCE PAY</b>			<b>4,158.36</b>

This estimate is based on a visual inspection and does not include additional parts or labor that may be required to complete the repairs.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

## Preliminary Estimate

### Customer: State Of Iowa

2017 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI BLACK

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 07/09/2021, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2022 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

#### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

#### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

#### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blend=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

## Preliminary Estimate

### Customer: State Of Iowa

2017 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI BLACK

### ALTERNATE PARTS USAGE

2017 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI BLACK

VIN: 2C3CDXKT0HH546827 Interior Color: BLACK Mileage In: 52,419 Vehicle Out:  
License: DGG002 Exterior Color: BLACK Mileage Out:  
State: IA Production Date: Condition: Good Job #:

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	0	1
Optional OEM	Manually List	0	0
Reconditioned	Automatically List	0	0
Recycled	N/A	0	0



223285

Risk, DAS <das.risk@iowa.gov>

**Fwd: 2020 Dodge Durango Hail Damage Paperwork**

\$1073.48

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Jul 19, 2021 at 3:59 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 902 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



**DAS Fleet Services, Risk**  
Iowa Department of Administrative Services  
Division of Business and Property Services  
Office: 515-725-2243  
Das.Risk@iowa.gov  
<https://das.iowa.gov>

----- Forwarded message -----

From: **Richardson Scott** <richards@dps.state.ia.us>  
Date: Fri, Jul 16, 2021 at 9:08 AM  
Subject: 2020 Dodge Durango Hail Damage Paperwork  
To: vehicledamage <vehicledamage@dps.state.ia.us>, das.risk@iowa.gov <das.risk@iowa.gov>  
Cc: Pierce Richard <pierce@dps.state.ia.us>, Hove Heath <hove@dps.state.ia.us>, Duden Joshua <duden@dps.state.ia.us>

Please see attached documentation for a 2020 Dodge Durango that suffered hail damage in the storm on Friday July 9<sup>th</sup>, 2021.


**Scott Richardson**

Assistant System Administrator  
Iowa Department of Public Safety  
Interoperability Communications Bureau  
215 E. 7<sup>th</sup> St.  
Des Moines, IA 50319  
Office 515-725-6255  
Cell 515-418-2953




---

**5 attachments**




**IMG\_0667a.jpg**  
65K




**IMG\_0659b.jpg**  
120K



**IMG\_0657c.jpg**  
116K

 **2020 Dodge Durango Hail Damage 07-09-2021 - State Vehicle Damage Rpt form - updated\_.doc**  
88K

 **2020 Dodge Durango Hail Estimate.pdf**  
123K

## State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: [vehicledamage@dps.state.ia.us](mailto:vehicledamage@dps.state.ia.us) ; [das.risk@iowa.gov](mailto:das.risk@iowa.gov)

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

**STATE VEHICLE: (Mark if Act of Nature  ) CASE #:** 2021016666

Date: <small>(Month/Day/Year)</small>	07-09-2021	Time: <small>(Time plus a.m./p.m.)</small>	2:05PM
Vehicle Plate #:	902	Vehicle Mileage:	7,500
Vehicle Description: <small>(Yr/Make/Model/ &amp; Vin#)</small>	2020 Dodge Durango 1C4RDHFG5LC441706		
Assigned To:	Pool Vehicle	Badge #	
Driven By:	Vehicle parked in lot	Badge #	
Driver's Lic #:	N/A	Damage:	\$ 1,073.48
Vehicle Towed: <small>(Yes / No)</small>		Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$ N/A
Seat Belt: <small>(Yes / No)</small>	N/A	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	?
Injured/Injuries:	N/A		
Occupants: <small>(Other than driver)</small>	None – Parked in lot during hail storm		

### VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

**OTHER INFORMATION:**

Witnesses:			
Accident Location: (Street/Hwy)		JFHQ Parking lot	
County:		Polk	
Weather/Road Conditions:		Hail Storm	
<p><b>** Please Include narrative of events here**</b>  Hail Storm on Friday July 9<sup>th</sup>, 2021 at approximately 2:05 PM caused hail damage to 2020 Dodge Durango listed above. Vehicle was parked in parking lot at Joint Forces Headquarters ( JFHQ ) in Johnston, IA.</p>			
Property Damage other than Vehicles:		None	
Cost:		\$	
Citations Issued To: (List Charge(s) and Statute Code(s))			

Investigating Officer:	
------------------------	--

**VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)**

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			

Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			



**CALIBER - DES MOINES - MERLE HAY RD**

RESTORING THE RHYTHM OF YOUR LIFE  
4416 Merle Hay Rd, Des Moines, IA 50310  
Phone: (515) 278-4170  
FAX: (515) 278-4178

Workfile ID: 15270323  
Federal ID: 33-0730794  
State ID: na  
Federal EPA: na  
State EPA: na

**Preliminary Estimate**

**Customer: IOWA DEPARTMENT OF PUBLIC SAFETY**

Written By: Gabriel Gymer

Insured: IOWA DEPARTMENT OF PUBLIC SAFETY Policy #: Claim #: RICHARDSON07/14/2021  
Type of Loss: Date of Loss: Days to Repair: 0  
Point of Impact:

**Owner:** IOWA DEPARTMENT OF PUBLIC SAFETY (515) 418-2953 Cell  
**Inspection Location:** CALIBER - DES MOINES - MERLE HAY RD 4416 Merle Hay Rd Des Moines, IA 50310 Repair Facility (515) 278-4170 Business  
**Insurance Company:** CUSTOMER PAY

**VEHICLE**

2020 DODG Durango Special Service RWD (Fleet) 4D UTV 6-3.6L Gasoline Sequential MPI

VIN: 1C4RDHFG5LC441706 Interior Color: Mileage In: 7,569 Vehicle Out:  
License: 902 Exterior Color: Mileage Out:  
State: IA Production Date: 9/2020 Condition: Job #:

**TRANSMISSION**

Automatic Transmission

**POWER**

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors  
Heated Mirrors  
Power Driver Seat

**DECOR**

Dual Mirrors  
Privacy Glass  
Console/Storage  
Overhead Console

**CONVENIENCE**

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Keyless Entry  
Message Center  
Steering Wheel Touch Controls  
Rear Window Wiper  
Telescopic Wheel  
Climate Control  
Dual Air Condition  
Backup Camera  
Parking Sensors

**RADIO**

AM Radio  
FM Radio  
Stereo  
Search/Seek  
Auxiliary Audio Connection

**SAFETY**

Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)  
4 Wheel Disc Brakes  
Traction Control  
Stability Control  
Front Side Impact Air Bags  
Head/Curtain Air Bags

Hands Free Device

**SEATS**

Cloth Seats  
Bucket Seats  
Reclining/Lounge Seats

**WHEELS**

Aluminum/Alloy Wheels

**PAINT**

Clear Coat Paint

**OTHER**

Fog Lamps  
Rear Spoiler  
California Emissions

**TRUCK**

Rear Step Bumper

**Preliminary Estimate**

**Customer: IOWA DEPARTMENT OF PUBLIC SAFETY**

2020 DODG Durango Special Service RWD (Fleet) 4D UTV 6-3.6L Gasoline Sequential MPI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	PDR Hood		1	200.00 X		
2	#	PDR Roof +25%		1	343.75 X		
3	#	PDR Lt. Roof Rail		1	75.00 X		
4	#	PDR Lt. Fender		1	75.00 X		
5	#	PDR R&I		1	200.00		
6	#	Repl Corrosion Protection Primer		1	12.00 T	0.3	
7	#	Pre-repair scan		1	X	0.5	
8	#	Post-repair scan		1	X	0.5	
<b>SUBTOTALS</b>					<b>905.75</b>	<b>1.3</b>	<b>0.0</b>

**ESTIMATE TOTALS**

Category	Basis	Rate	Cost \$
Parts			200.00
Body Labor	1.3 hrs @	\$ 75.00 /hr	97.50
Miscellaneous			705.75
Subtotal			1,003.25
Sales Tax	\$ 1,003.25 @	7.0000 %	70.23
<b>Grand Total</b>			<b>1,073.48</b>

=====  
 Caliber Collision is the industry leader in quality collision repair. Since day one, our highest purpose has been to get people just like you back on the road as quickly as possible and fully restored to the rhythm of your life. You can be sure we do everything possible to ensure your complete satisfaction including:

- Personalized, high quality service from the largest collision repair company in the U.S.
- Consistently ranked among the highest customer satisfaction scores in the industry.
- Approved by every major insurance company in the U.S.
- Expedited car rental and towing services to get you back on the road again in no time.
- Repair work backed by a written, lifetime warranty honored at every location.
- 24/7/365 customer service to answer questions and put your mind at ease.

This is a preliminary estimate based on visible damage. There may be additional repairs needed once the vehicle is taken apart by our I-CAR Gold Class technicians to identify any additional damage.

If an insurance company has written an estimate for you, please provide us with a copy. Properly endorsed insurance company checks are welcome as payment for the repair of your vehicle. Caliber Collision gladly accepts all major credit cards, debit cards, cashier's and traveler's checks. See your Caliber Collision center for details on acceptance of personal checks.

Before leaving your vehicle with us, please remove all important personal and valuable items from your vehicle. Caliber Collision is not responsible for belongings left in your vehicle.

Please let us know how we can be of further assistance, and when we can schedule an appointment for your vehicle to be repaired.

223291

358657

**Fwd: Vehicle #633 hail damage**

1 message

Risk, DAS &lt;das.risk@iowa.gov&gt;

Mon, Jul 19, 2021 at 4:13 PM

To: Tammy Hollingsworth &lt;Tammy.Hollingsworth@aos.iowa.gov&gt;, TOS ExecutiveCouncil &lt;executivecouncil@tos.iowa.gov&gt;

Please accept this email as initial 24 hr notification for AON, vehicle 633 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

**DAS Fleet Services, Risk**

Iowa Department of Administrative Services  
Division of Business and Property Services  
Office: 515-725-2243  
Das.Risk@iowa.gov  
<https://das.iowa.gov>

----- Forwarded message -----

From: **Jobes David** <jobes@dps.state.ia.us>

Date: Fri, Jul 16, 2021 at 11:50 AM

Subject: Vehicle #633 hail damage

To: vehicledamage &lt;vehicledamage@dps.state.ia.us&gt;, Risk, DAS &lt;das.risk@iowa.gov&gt;

Cc: Lamp Scott &lt;selamp@dps.state.ia.us&gt;, Feddersen Paul &lt;fedderse@dps.state.ia.us&gt;

Thank you.

David Jobes, Assistant Director

Division of Criminal Investigation

Special Enforcement Operations Bureau

Iowa Department of Public Safety


215 E. 7th Street

Des Moines, IA 50319

515-725-6014 Office

515-725-6020 Fax

jobes@dps.state.ia.us



*\*NOTICE\* This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.*

---

### 5 attachments



**IMG\_0021.jpg**  
1559K



**IMG\_0022.jpg**  
1535K



**IMG\_0023.jpg**  
1666K

 **20210716113628874.pdf**  
45K

 **Vehicle 633 Jobs Damage Rpt 07092021.doc**  
101K

## State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: [vehicledamage@dps.state.ia.us](mailto:vehicledamage@dps.state.ia.us) ; [das.risk@iowa.gov](mailto:das.risk@iowa.gov)

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

### STATE VEHICLE: (Mark if Act of Nature ) CASE #:

Date: (Month/Day/Year)	07/09/2021	Time: (Time plus a.m./p.m.)	2:00 p.m.
Vehicle Plate #:	633 JXL 825	Vehicle Mileage:	72,493
Vehicle Description: (Yr/Make/Model/ & Vin#)	2017 Chevrolet Impala 2G1105S3XH9174791		
Assigned To:	David Jobes	Badge #	I-97
Driven By:	David Jobes	Badge #	I-97
Driver's Lic #:	805ZZ1098	Damage:	\$3586.51
Vehicle Towed: (Yes / No)	No	Towed By:	
Towed To:		Towing Cost:	\$
Seat Belt: (Yes / No)	Parked	Type of Vehicle: (Marked/Semi /Unmarked)	Unmarked
Injured/Injuries:	None		
Occupants: (Other than driver)	None		

### VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

**OTHER INFORMATION:**

Witnesses:			
Accident Location: (Street/Hwy)	Camp Dodge, MCTC		
County:	Polk		
Weather/Road Conditions:	Parked, heavy thunderstorm with large hail		
<b>** Please Include narrative of events here**</b>			
<p>Vehicle was parked at MCTC at Camp Dodge during training. A heavy thunderstorm with large hail moved through the area causing damage to the vehicle as well as numerous other vehicles.</p>			
Property Damage other than Vehicles:	None		
Cost:	\$		
Citations Issued To: (List Charge(s) and Statute Code(s))			

Investigating Officer:	
------------------------	--

**VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)**

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

**Karl Chevrolet Collision Center  
Ankeny**

Your Dealer for Life  
1101 Southeast Oralabor Road, Exit 90 and I-35,  
Ankeny, IA 50021  
Phone: (515) 299-4337  
FAX: (515) 964-2293

Workfile ID:           cbaf4ab4  
PartsShare:           6kZZ5n  
Federal ID:            42-1092272

**Estimate**

**RO Number:**

Customer:	Insurance:	Adjuster:	Estimator:	Mark Michael
STATE OF IOWA	STATE OF IOWA	Phone:	Create Date:	7/16/2021
		Claim:		
		Loss Date:		
		Deductible:		

2017 CHEV Impala LT1 4D SED 6-3.6L Flex Fuel Direct Injection SILVER

VIN: 2G1105S3XH9174791	Interior Color: BLACK	Mileage In: 72,557	Vehicle Out:
License: JXL825	Exterior Color: SILVER	Mileage Out:	
State: IA	Production Date: 3/2017	Condition:	Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		<b>HOOD</b>						
2	E01	PDR	Hood NOTE: PDR 70 quarter	1	450.00	Other			
3	E01		<b>FENDER</b>						
4	E01	PDR	RT Fender NOTE: PDR 2 quarter	1	100.00	Other			
5	E01	PDR	LT Fender NOTE: PDR 3 quarter	1	100.00	Other			
6	E01		<b>ROOF</b>						
7	E01	PDR	Roof panel NOTE: PDR 200 quarter	1	975.00	Other			
8	E01	Remove/Install	R&I headliner				3.1	Body	
9	E01		<b>PILLARS, ROCKER &amp; FLOOR</b>						
10	E01	PDR	RT Uniside assy NOTE: PDR 8 quarter	1	150.00	Other			
11	E01	PDR	LT Uniside assy NOTE: PDR 13 quarter	1	150.00	Other			
12	E01		<b>FRONT DOOR</b>						
13	E01	Remove/Replace	RT Belt molding	1	120.17	OEM	0.3	Body	
14	E01	Remove/Replace	LT Reveal molding	1	103.62	OEM	0.2	Body	
15	E01	Remove/Replace	LT Belt molding	1	120.17	OEM	0.3	Body	
16	E01		<b>REAR DOOR</b>						
17	E01	PDR	RT Outer panel w/o molding NOTE: PDR 1 quarter	1	100.00	Other			

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

## Estimate

**RO Number:**

2017 CHEV Impala LT1 4D SED 6-3.6L Flex Fuel Direct Injection SILVER

18	E01	Remove/Replace	RT Reveal molding	1	106.95	OEM	0.2	Body
19	E01		<b>TRUNK LID</b>					
20	E01	PDR	Trunk lid	1	450.00	Other		
NOTE: PDR 60 quarter								

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts	(126.25)	618.75			3,418.41
Labor, Body			41.00	4.1	168.10
<b>Subtotal</b>					<b>3,586.51</b>
Sales Tax					0.00
<b>Grand Total</b>					<b>3,586.51</b>
<b>Net Total</b>					<b>3,586.51</b>

Estimate Version	Total \$
Original	3,586.51

Insurance Total \$:	3,586.51
Received from Insurance \$:	0.00
<hr/> Balance due from Insurance \$:	<hr/> 3,586.51
Customer Total \$:	0.00
Received from Customer \$:	0.00
<hr/> Balance due from Customer \$:	<hr/> 0.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Due upon receipt

# INVOICE

INVOICE NUMBER	INVOICE DATE
<b>776-0277685</b>	<b>07/23/2021</b>

BILL TO
Attn: MIKE LONG DAS FLEET SERVICES 109 SE 13TH ST DES MOINESIA 50139

CLIENT CODE
DAS105001
BUSINESS LINE / LOSS TYPE
A - Commercial Auto

FOR INQUIRIES:
PDA Des Moines, IA #776  pdadesmoines@pdaorg.net (515) 222-1906

SUBMIT PAYMENT TO:
Property Damage Appraisers, Inc. 75-1160563 Dept #161, P.O. Box 1000 Memphis, TN 38148-0161  <i>Please reference the invoice number and enclose a copy of the invoice on all payments.</i>

INSURED	CLAIMANT	ASSIGNMENT DATE	PDA ASSIGNMENT #
STATE OF IOWA		07/21/2021	776-107-0241
CLAIM #	POLICY #	LOSS DATE	REFERENCE #
APDSOI0223291-001			

SERVICE FEE: ( 1 Unit(s) @ \$179.00 ) \$ 179.00

Mileage: ( 1.00 miles ) @ \$1.25 \$ 1.25

ACH Payment Info:  
Bank: First Horizon Bank  
ABA (US): 084000026 Bank  
Account: 220002525824  
Email Remit Information to:  
achbackup@pdaorg.net

**Click [here](http://PDAClientPortal.com) to pay your invoice at PDAClientPortal.com**

**Same-Day Service. Guaranteed.** PDA now offers expedited service for standard auto claims in select markets.

\*\*WE HAVE CHANGED OUR BANK REMITTANCE INFORMATION AS NOTED ABOVE PLEASE UTILIZE OUR PORTAL FOR ALL OTHER ELECTRONIC PAYMENTS.\*\*

TOTAL CHARGES:	180.25
INVOICE TOTAL:	<b>\$ 180.25</b>

*Terms: Professional fees due upon receipt. Interest accrues at 1% per month.  
Please include the invoice number on all payments.*