



Governor Kim Reynolds
 Lt. Governor Adam Gregg
 Adam Steen, Director

Date: October 4, 2021

To: Tammy Hollingsworth, Auditor of State
 Victoria Newton, Treasurer of State
 Executive Council

From: Mariah Flowers, Fleet Manager
 DAS Fleet Services
 Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	# 191/Raccoon
Event Date	January 11, 2021
Summary	Trooper #191 struck a raccoon (214466)
Amount Requested	\$2,485.00 - Estimate <u>\$ 35.00 - Review Invoice</u> \$2,520.00
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

 Mariah Flowers, Fleet Manager
 DAS Fleet Services
Mariah.Flowers@iowa.gov
 515-725-2243

214406

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #: 2021000656

Date: (Month/Day/Year)	1/11/21	Time: (Time plus a.m./p.m.)	0130
Vehicle Plate #:	191	Vehicle Mileage:	66300
Vehicle Description: (Yr/Make/Model/ & Vin#)	2018 Dodge Charger 2C3CDXKT5JH330218		
Assigned To:	Trp. Rose Ives	Badge #	191
Driven By:	Trp. Rose Ives	Badge #	191
Driver's Lic #:	647XX6495	Damage:	\$2,882.00
Vehicle Towed: (Yes / No)	No	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$N/A
Seat Belt: (Yes / No)	Yes	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:	None		
Occupants: (Other than driver)	None		

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

OTHER INFORMATION:

Witnesses:			
Accident Location: (Street/Hwy)	SB I-29 MM 41		
County:	Mills		
Weather/Road Conditions:	Clear, Dry		
Trooper was southbound on I-29 at the 41 mm when she struck a raccoon that was in the roadway causing damage to the right front bumper.			
Property Damage other than Vehicles:	None		
Cost:	\$		
Citations Issued To: (List Charge(s) and Statute Code(s))	N/A		

Investigating Officer:	Lt J. Ehler #212
------------------------	------------------

QUALITY CLAIMS SOLUTIONS

7405 S Bitterroot Pl. Suite 100
SIOUX FALLS, SD 57108
Phone: (877) 237-3727, FAX:(866) 371-2844
qcs@qcsdirect.com

Workfile ID: d1212ed1

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: POLICE, STATE OF IOWA

Job Number:

Written By: Dennis Jorgensen, NY-6FH6

Insured:	POLICE, STATE OF IOWA	Policy #:	NOT PROVIDED	Claim #:	214466V1
Type of Loss:	Collision	Date of Loss:	1/12/2021 12:00 PM	Days to Repair:	0
Point of Impact:	12 Front				

Owner: POLICE, STATE OF IOWA COUNCIL BLUFFS, IA 51501	Inspection Location: All Makes Collision Ctr 1625 ave j council bluffs, IA 51501 Other (712) 256-3195 Evening	Repair Facility:
--	---	-------------------------

VEHICLE

2018 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

VIN:	2C3CDXKT5JH330218	Production Date:		Interior Color:	
License:		Odometer:	0	Exterior Color:	
State:		Condition:			

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel

CLIMATE CONTROL

Climate Control
Backup Camera

RADIO

AM Radio

FM Radio

Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions
Power Trunk/Liftgate

Estimate of Record

Owner: POLICE, STATE OF IOWA

Job Number:

2018 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER					
2		O/H front bumper				3.5	
3	*	Repl Bumper cover	5PP39TZZAE	1	<u>680.00</u>	Incl.	3.2
4		Add for Clear Coat					1.3
5		RADIATOR SUPPORT					
6	*	Rpr Radiator support				<u>3.0</u>	1.0
7		Repl Crossmember	5065240AH	1	259.00	0.5	
8		Repl Front shield w/police	68231862AA	1	225.00	Incl.	
9	*	Repl Splash shield AWD w/police	4806075AB	1	<u>80.00</u>	0.2	
10		AIR CONDITIONER & HEATER					
11	**	Repl A/M Condenser assy	68085784AA	1	<u>221.00</u> m	1.5 M	
12		AC Service evacuate & recharge				m 1.4 M	
13		AC Service refrigerant recovery				m 0.4 M	
SUBTOTALS					1,465.00	10.5	5.5

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			1,465.00
Body Labor	7.2 hrs @	\$ 50.00 /hr	360.00
Paint Labor	5.5 hrs @	\$ 90.00 /hr	495.00
Mechanical Labor	3.3 hrs @	\$ 50.00 /hr	165.00
Subtotal			2,485.00
Total Cost of Repairs			2,485.00
Deductible			0.00
Total Adjustments			0.00
Net Cost of Repairs			2,485.00

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.



Quality Claims Solutions

Quality Claims Solutions

7405 S. Bitterroot Pl. #100

Sioux Falls, SD 57108

Phone: 8787.237.3727

Fax: 866.371.2844

Federal Tax ID: 46-0461202

INVOICE =

Attention/Adjuster: Deb Anderson

Company Name: DAS Fleet Services

Address: 109 SE 13th St
Des Moines, IA 50319

Invoice No: 214466V1-1390

Date: 01/14/2021 1:59 PM

Customer ID: IWAA

Claim Number: 214466V1

Vehicle Owner: STATE OF IOWA

Quantity	Description	Unit Price	Extended Amount
1	Technical Estimate Review	\$35.00	\$35.00

Item Total: \$35.00

Sales Tax: N/A

Invoice Total: \$35.00

ALL MAKES COLLISION CENTER

~We Meet Great People By Accident~

524-23rd Ave
Council Bluffs, IA 51501
712-256-3195



Customer's Order No.		Date		2 3 2021		
Name <u>State of Iowa</u>						
Address						
SOLD BY	CASH	C. O. D.	CHARGE	ON ACCT.	MDSE RETD.	PAID OUT
QUAN.	DESCRIPTION		PRICE	AMOUNT		
	Claim #214468					
	Repair per QCS estimate					
	TAX					
	TOTAL			2485.00		
0005136			Rec'd by			

All claims and returned goods MUST be accompanied by this bill.

GS-2013 PRINTED IN USA

Thank You

