

Governor Kim Reynolds
 Lt. Governor Adam Gregg
 Adam Steen, Director

Date: October 4, 2021

To: Tammy Hollingsworth, Auditor of State
 Victoria Newton, Treasurer of State
 Executive Council

From: Mariah Flowers, Fleet Manager
 DAS Fleet Services
 Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#77/Weather
Event Date	August 11, 2021
Summary	Vehicle 77 had a tree fall on it. (224770)
Amount Requested	\$6,155.34 - Estimate <u>\$ 516.56 - Review Invoice</u> \$6,671.90 - Total
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager
 DAS Fleet Services
Mariah.Flowers@iowa.gov
 515-725-2243



8-11-2021 Trp. Gent #77 SVD - Tree fell on car / 29C20 Notification

1 message

Adams Jeannie <jadams@dps.state.ia.us>

Tue, Aug 17, 2021 at 8:40 AM

To: "executivecouncil@tos.iowa.gov" <executivecouncil@tos.iowa.gov>,

"Tammy.Hollingsworth@auditor.state.ia.us" <Tammy.Hollingsworth@auditor.state.ia.us>

Cc: "das.risk@iowa.gov" <das.risk@iowa.gov>

Executive Council and Tammy,

Please see attached SVD damage submission on behalf of Trp. Gent. He had a tree fall onto his vehicle while parked at his home causing \$7,701.98 in damage. Please accept the attached email as the 24hr notification.

ISP would respectfully request 29C20 re-imbusement for this AON event.

Thanks in advance for your consideration. Please let me know if you have any questions.

V/R

Jeannie Adams

ISP Fleet & Supply, Fleet Asset Manager

Department of Public Safety

30 N.E. 48th Place

Des Moines, Iowa 50313

Direct #: 515-725-0643

Cell Phone: 515-204-3019

Shop: 515-281-3277

Fax: 515-242-6321

Email: jadams@dps.state.ia.us

6 attachments

pic1.jpeg.jpg
255K




pic6.jpeg.jpg
365K



pic5.jpeg.jpg
300K

 **77 State Vehicle Damage Rpt form - updated .doc**
87K

 **vehicle damage 8-12-21 MEMORANDUM.doc**
29K

 **Trooper 77 Estimate.pdf**
188K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #: 2021019934

Date: <small>(Month/Day/Year)</small>	08/11/21	Time: <small>(Time plus a.m./p.m.)</small>	11:00 PM
Vehicle Plate #:	77	Vehicle Mileage:	41,200
Vehicle Description: <small>(Yr/Make/Model/ & Vin#)</small>	2020 Dodge Charger VIN 2C3CDXKTXLH124220		
Assigned To:	Mark Gent	Badge #	77
Driven By:		Badge #	
Driver's Lic #:		Damage:	\$
Vehicle Towed: <small>(Yes / No)</small>	NO	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$N/A
Seat Belt: <small>(Yes / No)</small>	N/A	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	MARKED
Injured/Injuries:	NONE		
Occupants: <small>(Other than driver)</small>	0		

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

OTHER INFORMATION:

Witnesses:			
Accident Location: (Street/Hwy)	1304 Kiwi Avenue, Kalona, IA 52247		
County:	Washington		
Weather/Road Conditions:	High winds		
<p>In the late evening of 8/11/21 I heard a crash outside my residence. A main branch from a Maple tree had fallen onto my patrol car while it was parked in my driveway. Damage was caused to the hood, driver's quarter panel, rear driver's quarter panel and upper door jamb above rear passenger door. The Post was notified and pictures were sent.</p>			
Property Damage other than Vehicles:	None		
Cost:	\$		
Citations Issued To: (List Charge(s) and Statute Code(s))			

Investigating Officer:	Sgt. Dolf #361
------------------------	----------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

Date: 8/25/2021 01:27 PM
 Estimate ID: 2331080063
 Estimate Version: 0
 Committed
 Profile ID: * PDA IA

Property Damage Appraisers (PDA Bettendorf)

P.O. Box 248, Bettendorf, IA 52722
 (563) 355-2805
 Fax: (563) 888-1405
 Email: pdabettendorf@pdaorg.net

Not An Authorization For repair
 Read disclaimers following appraisal calculations.

Damage Assessed By: Jeff Cuppy
 Classification: Field

Appraised For: MIKE LONG

Condition Code: Good
 Date of Loss: 8/16/2021
 Contact Date: 8/25/2021
 Deductible: 0.00
 File Number: 2331080063
 Claim Number: APDSOI0224770-001

Type of Loss: Other
 Arrival Date: 8/25/2021
 Date Assigned: 8/25/2021

Insured: State of Iowa Contact Senior Troope
 Owner: State of Iowa Contact Senior Troope
 Address: 1300 S Grand Ave, Mount Pleasant, IA 52641
 Telephone: Work Phone: (319) 385-8715

Mitchell Service: 911667

Description: 2020 Dodge Charger Police
 Body Style: 4D Sed
 VIN: 2C3CDXKTXLH124220
 Mileage: 43,360
 OEM/ALT: A
 Parts Profile: Bettendorf
 Color: Grey
 Options: PASSENGER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING, POWER BRAKE REAR WINDOW DEFOGGER, TILT STEERING COLUMN, LUGGAGE RACK, ANTI-LOCK BRAKE SYS. CD PLAYER

Vehicle Production Date: 12/19
 Drive Train: 5.7L Inj 8 Cyl 5A AWD
 License: 77 IA

Parts Profile Version: 2

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	103519	BDY	REMOVE/REPLACE	Inform Label Emission Information	68470484AA	5.00	
2	100387	BDY	OVERHAUL	Frnt Bumper Cover Assy			4.0 #
3	900500	BDY *	REMOVE/INSTALL	Push Bar	Existing		1.0* r
4	100932	BDY	REPAIR	Frnt Bumper Cover	Existing		1.0* #
5		REF	REFINISH/REPAIR	Frnt Bumper Cover			C 2.6*
6				MODIFIED REFINISH WITH FULL CLEAR COAT			
7	100559	BDY	REMOVE/REPLACE	Hood Panel (Alum)	** QRP Certified	952.00	1.6
8	AUTO	REF	REFINISH	Hood Outside			C 2.8
9	AUTO	REF	REFINISH	Add For Hood Underside			C 1.4
10	101042	BDY	REPAIR	R Fender Panel	Existing		1.0* #
11		REF	REFINISH/REPAIR	R Fender Panel			C 1.5*
12				MODIFIED REFINISH WITH FULL CLEAR COAT			
13	101043	BDY	REMOVE/REPLACE	L Fender Panel	** QRP Certified	268.00	0.9 #
14	AUTO	BDY	REMOVE/INSTALL	Frnt Bumper Cover			INC #
15	AUTO	REF	REFINISH	L Fender Outside			C 1.6
16	AUTO	REF	REFINISH	L Add To Edge Fender			C 0.5
17	102438	BDY	REMOVE/INSTALL	R Fender Splash Shield	Existing		INC r
18	102439	BDY	REMOVE/INSTALL	L Fender Splash Shield	Existing		INC r
19	101285	REF	REFINISH	R Roof Rail			C 1.6 #
20	101286	REF	BLEND	L Roof Rail			C 0.6 #
21	101303	BDY	REPAIR	R Door Opening Panel	Existing		8.0* #
22				Rt Roof Rail Repair.			

ESTIMATE RECALL NUMBER: 08/25/2021 13:27:09 2331080063

Mitchell Data Version: OEM: AUG_21_V0825

Alternate Parts: 08/25/2021 12:45:03

Software Version: 7.1.241

Copyright (C) 1994 - 2021 Mitchell International
 All Rights Reserved

Page 1 of 4

Date: 8/25/2021 01:27 PM
 Estimate ID: 2331080063
 Estimate Version: 0
 Committed
 Profile ID: * PDA IA

23	900500	BDY *	REMOVE/INSTALL	Light Bar, Roof	Existing	1.5* r
24	101415	REF	REFINISH	L Frt Door Outside		C 1.9
25	102090	BDY	REMOVE/INSTALL	L Frt Rear View Mirror		INC #
26	102092	BDY	REMOVE/INSTALL	L Frt Otr Door Belt Moulding		1.1 #
27	100839	BDY	REMOVE/INSTALL	L Frt Door Trim Panel		INC
28	101827	BDY	REMOVE/INSTALL	L Frt Otr Door Handle		0.3 #
29	100004	REF	BLEND	R Rear Door Outside		C 0.9
30	101102	REF	REFINISH	L Rear Door Outside		C 1.8
31	100735	BDY	REMOVE/INSTALL	R Rear Otr Door Belt Moulding		0.2
32	100736	BDY	REMOVE/INSTALL	L Rear Otr Door Belt Moulding		0.2
33	100745	BDY	REMOVE/INSTALL	R Rear Door Trim Panel		0.4
34	100746	BDY	REMOVE/INSTALL	L Rear Door Trim Panel		0.4
35	100763	BDY	REMOVE/INSTALL	R Rear Otr Door Handle		0.3 #
36	100764	BDY	REMOVE/INSTALL	L Rear Otr Door Handle		0.3 #
37	100871	REF	BLEND	L Fuel Door		INC #
38	100290	BDY	REPAIR	R Quarter Outer Panel	Existing	4.0* #
39	AUTO	REF	REFINISH	R Quarter Panel Outside		C 2.1
40	100291	BDY	REPAIR	L Quarter Outer Panel	Existing	5.0* #
41	AUTO	REF	REFINISH	L Quarter Panel Outside		C 1.9
42	103898	BDY	REMOVE/INSTALL	L Quarter Fuel Door	Existing	0.3 r
43	931127	MCH	ADD'L LABOR OP	Pre Repair Scan	Existing	0.5*
44	931128	MCH	ADD'L LABOR OP	Post Repair Scan	Existing	0.5*
45	900500	MCH*	ADD'L LABOR OP	AsTech Pre-Post Scans Per Invoice.	Sublet	0.0*
46	102843	BDY	REMOVE/INSTALL	R Quarter Shield	Existing	0.4 r
47	102844	BDY	REMOVE/INSTALL	L Quarter Shield	Existing	0.4 r
48	100005	REF	BLEND	Luggage Lid Outside		1.2*
49				Upper Surface Only		
50	900500	BDY *	REMOVE/INSTALL	Radio Antennas	Existing	1.0* r
51	100462	BDY	REMOVE/INSTALL	R Rear Combination Lamp		INC #
52	100463	BDY	REMOVE/INSTALL	L Rear Combination Lamp		INC #
53	100904	BDY	REMOVE/INSTALL	Rear Combination Lamp		0.4 #
54	AUTO	BDY	REMOVE/INSTALL	Luggage Trim Panel		0.3
55	100894	BDY	REMOVE/INSTALL	Rear Bumper Cover		1.6 #
56	936012		ADD'L COST	Hazardous Waste Disposal		4.00 *
57	936014		ADD'L COST	Flex Additive		6.00 *
58	933002	REF	ADD'L OPR	Clear Coat		2.5*
59	900500	BDY *	ADD'L LABOR OP	Remove Decals & Adhesive For Repairs.	Existing	1.0*
60	933005	BDY	ADD'L OPR	Restore Corrosion Protection		12.00 * 0.6*
61	933018	REF	ADD'L OPR	Mask For Overspray		5.00 * 0.3*

* - Judgment Item
 # - Labor Note Applies
 ** QRP Certified - Quality Replacement Parts - Certified
 C - Included in Clear Coat Calc
 r - CEG R&R Time Used For This Labor Operation

KEYSTONE-INS QUALITY PRT
 2400 KERPER BLVD.
 STE. E100A
 DUBUQUE
 IA 52004
 (319) 566-5030 (800) 747-2500

KEYSTONE-INS QUALITY PRT
 4725 44TH ST.
 MOLINE
 IL 61265
 (309) 517-2450 (800) 233-0518

7 ** CH1230305C 952.00 13 ** CH1240282C 268.00

ESTIMATE RECALL NUMBER: 08/25/2021 13:27:09 2331080063

Mitchell Data Version: OEM: AUG_21_V0825

Alternate Parts: 08/25/2021 12:45:03

Software Version: 7.1.241

Copyright (C) 1994 - 2021 Mitchell International
 All Rights Reserved

Page 2 of 4

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	37.2	62.15	12.00	0.00	2,323.98 T	Taxable Parts	1,225.00
Refinish	25.2	100.00	5.00	0.00	2,525.00 T		
Mechanical	1.0	71.36	0.00	0.00	71.36 T	Total Replacement Parts Amount	1,225.00
Taxable Labor					4,920.34		
Labor Summary	63.4				4,920.34		
III. Additional Costs					Amount	IV. Adjustments	
Taxable Costs					10.00	Insurance Deductible	
Total Additional Costs					10.00	Customer Responsibility	
						I. Total Labor:	
						II. Total Replacement Parts:	
						III. Total Additional Costs:	
						Gross Total:	
						6,155.34	
						IV. Total Adjustments:	
						Net Total:	
						0.00	
						6,155.34	

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Point(s) of Impact

10 Left Front Side (P), 2 Right Front Side (S), 3 Right Side (S), 4 Right Rear Side (S), 8 Left Rear Side (S)
 11 Left Front Corner (S)

Insurance Co: DAS FLEET SERVICES
 DES MOINES, IA 50139
 Work Phone: (877) 544-7843

Inspection Site: State Patrol Office
 Address: 1300 S Grand Ave
 Mount Pleasant, IA 52641
 (319) 385-8715
 Inspection Date: 8/25/2021

Body Shop: COPELAND AUTO BODY
 Address: 506 E 2nd St
 Hedrick, IA 52563
 Telephone: (641) 653-2410
 Fax Phone: (641) 653-4301
 State Lic. No: 42-1488559

Due upon receipt

INVOICE

INVOICE NUMBER	INVOICE DATE
233-0079360	08/25/2021

BILL TO
Attn: MIKE LONG DAS FLEET SERVICES 109 SE 13TH ST DES MOINESIA 50139

CLIENT CODE
DAS105001
BUSINESS LINE / LOSS TYPE
A - Commercial Auto

FOR INQUIRIES:
PDA Bettendorf, IA #233 pdabettendorf@pdaorg.net (563) 355-2805

SUBMIT PAYMENT TO:
Property Damage Appraisers, Inc. 75-1160563 Dept #161, P.O. Box 1000 Memphis, TN 38148-0161 <i>Please reference the invoice number and enclose a copy of the invoice on all payments.</i>

INSURED	CLAIMANT	ASSIGNMENT DATE	PDA ASSIGNMENT #
of Iowa Contact Senior Trooper Mark		08/25/2021	233-108-0063
CLAIM #	POLICY #	LOSS DATE	REFERENCE #
APDSOI0224770-001			

SERVICE FEE: (1 Unit(s) @ \$179.00)	\$ 179.00
Mileage: (174.00 miles) @ \$1.20	\$ 208.80
Long Distance Drive Time/Mile: 174.00 miles @\$0.74/mile	\$ 128.76
<p>ACH Payment Info: Bank: First Horizon Bank ABA (US): 084000026 Bank Account: 220002525824 Email Remit Information to: achbackup@pdaorg.net</p> <p>Click here to pay your invoice at PDAClientPortal.com</p>	

Same-Day Service. Guaranteed. PDA now offers expedited service for standard auto claims in select markets.

<p>**WE HAVE CHANGED OUR BANK REMITTANCE INFORMATION AS NOTED ABOVE PLEASE UTILIZE OUR PORTAL FOR ALL OTHER ELECTRONIC PAYMENTS.**</p> <p><i>Terms: Professional fees due upon receipt. Interest accrues at 1% per month. Please include the invoice number on all payments.</i></p>	TOTAL CHARGES:	516.56
	:	
	INVOICE TOTAL:	\$ 516.56