



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: October 5, 2021

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	# 2164/Hail
Event Date	July 9, 2021
Summary	Vehicle 2164 sustained hail damage during a storm. (223943)
Amount Requested	\$2,908.50 - Estimate <u>\$ 35.00 - Review Invoice</u> \$2,943.50 - Total
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-725-2243

223943

Fwd: Hail damage report - 2164

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Jul 19, 2021 at 11:19 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 2164 sustained hail damage on 7/9/2021 . I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

**DAS Fleet Services, Risk**

Iowa Department of Administrative Services

Division of Business and Property Services

Office: 515-725-2243

Das.Risk@iowa.gov

<https://das.iowa.gov>ESTIMATE APPT
7/29/21

----- Forwarded message -----

From: Tuttle, Scott <Scott.Tuttle@iowaagriculture.gov>

Date: Tue, Jul 13, 2021 at 8:06 PM

Subject: Hail damage report

To: Potter, Lisa <Lisa.Potter@iowaagriculture.gov>

Cc: DAS.Risk@iowa.gov <DAS.Risk@iowa.gov>

 **AccidentReportForm.pdf**
245K

Vehicle Accident Report

Time and location of accident			
Accident Date (Mo/Day/Year)	Time	No. of Vehicles	
Friday July 9, 2021	1:10PM	1	
County	State		
Boone	Iowa		
Vehicle 1 (State vehicle)			
Driver's Name		Work Street Address	
		1250 Java Place	
Driver's License No./State		City, State, Zip	
		Ogden, Iowa 50212	
Date of Birth	Department	Work Phone	Home Phone
	IDALS	515-306-5435	
License Plate No.	VIN	Year, Make, Model	
2164	3FA6P0G76JR207606	2018 Ford Fusion	
Estimate (\$) of Damage		Description of Damage	
		Hail storm damage	
Vehicle 2 (other vehicle) if more than two vehicles-use additional forms			
Driver's Name		Street Address	
Driver's License No./State		City, State, Zip	
Date of Birth	Work Phone	Home Phone	License Plate No.
Description of Damage			

Vehicle Accident Report

Time and location of accident

Accident Date (Mo/Day/Year)	Time	No. of Vehicles
Friday July 9, 2021	1:10PM	1
County	State	
Boone	Iowa	

Vehicle 1 (State vehicle)

Driver's Name		Work Street Address	
		1250 Java Place	
Driver's License No./State		City, State, Zip	
		Ogden, Iowa 50212	
Date of Birth	Department	Work Phone	Home Phone
	IDALS	515-306-5435	
License Plate No.	VIN	Year, Make, Model	
2164	3FA6P0G76JR207606	2018 Ford Fusion	
Estimate (\$) of Damage		Description of Damage	
		Hail storm damage	

Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

Driver's Name		Street Address	
Driver's License No./State		City, State, Zip	
Date of Birth	Work Phone	Home Phone	License Plate No.
Description of Damage			

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
Vehicle No. 2/ Name and Address	Describe Injuries
Witness	
Name	Address/Phone
Name	Address/Phone

Accident Diagram
<p>Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers. Use number 1 to indicate the State vehicle.</p>



DON AND SONS BODY SHOP, INC

Expertise/Convenience/Reliability
1003 E. Lincoln Way, Ames, IA 50010
Phone: (515) 232-5602
FAX: (515) 232-5614

Workfile ID: 048f5694
PartsShare: 6mTcsW
Federal ID: 42-1203162
State ID: 85-1203162
Federal EPA: Not Needed
State EPA: Not Needed

Preliminary Estimate

Customer: TUTTLE, SCOTT

Written By: Travis Simpson

Insured: TUTTLE, SCOTT
Type of Loss:
Point of Impact: 27 Hail

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
TUTTLE, SCOTT
(515) 206-5435 Cell

Inspection Location:
DON AND SONS BODY SHOP, INC
1003 E. Lincoln Way
Ames, IA 50010
Repair Facility
(515) 232-5602 Business

Insurance Company:
STATE OF IOWA

VEHICLE

2018 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI WHITE

VIN: 3FA6P0G76JR207606
License: 2164
State: IA

Interior Color: BLACK
Exterior Color: WHITE
Production Date:

Mileage In: 84,608
Mileage Out:
Condition: Excellent
Vehicle Out:
Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors

DECOR

Dual Mirrors
Tinted Glass
Console/Storage
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Backup Camera

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
CD Player
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags

Hands Free Device

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions

Get live updates at www.carwise.com/e/44gHcX

Preliminary Estimate

Customer: TUTTLE, SCOTT

2018 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI WHITE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		HOOD					
2	*	Subl Hood (ALU) Note: 16-30 HD ADD FOR ALUMINUM 25%		1	<u>593.75</u>		
3		R&I R&I hood assy				0.6	
4		R&I Insulator				0.2	
5		FENDER					
6	*	Subl RT Fender Note: 1-5 QTR ADD FOR GLUE 25%		1	<u>110.00</u>		
7	*	Subl LT Fender Note: 6-15 QTR ADD FOR GLUE 25%		1	<u>175.00</u>		
8		ROOF					
9	*	Subl Roof panel Note: 16-30 QTR		1	<u>425.00</u>		
10		R&I R&I headliner				2.8	
11		PILLARS, ROCKER & FLOOR					
12	*	Subl LT Aperture panel Note: 6-15 QTR ADD FOR GLUE 25%		1	<u>343.75</u> s		
13	*	Subl RT Aperture panel		1	<u>231.25</u> s		
14		FRONT DOOR					
15	*	Subl LT Door shell Note: 1-5 QTR		1	<u>110.00</u>		
16		REAR DOOR					
17	*	Subl LT Door shell frm 04/04/2016 Note: 6-15 QTR		1	<u>218.75</u>		
18		QUARTER PANEL					
19	*	Subl LT Quarter panel Note: 1-5 QTR ADD FOR GLUE 25%		1	<u>110.00</u>		
20		TRUNK LID					
21	*	Subl Trunk lid w/o spoiler Note: 16-30 QTR		1	<u>325.00</u>		
22		R&I Trunk lid trim				0.2	
SUBTOTALS					2,642.50	3.8	0.0

Preliminary Estimate

Customer: TUTTLE, SCOTT

2018 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI WHITE

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			2,642.50
Body Labor	3.8 hrs @	\$ 70.00 /hr	266.00
Subtotal			2,908.50
Grand Total			2,908.50
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			2,908.50

MyPriceLink Estimate ID / Quote ID:

850037812244783104 /

THANK YOU FOR CHOOSING DON & SONS BODY SHOP FOR ALL OF YOUR COLLISION NEEDS! WE APPRECIATE YOUR BUSINESS.

This estimate is based on a visual inspection and does not include additional parts or labor that may be required to complete repairs. Part prices are current and may be subject to a parts price change, dependent upon ordering date.

TOTAL LOSS VEHICLES WILL BE ASSESSED STORAGE FEES. OUTSIDE STORAGE IS \$35/DAY AND INSIDE STORAGE IS \$55/DAY.

Total loss vehicles are also subject to a base administration fee of \$150.00.

Finance charges may apply to unpaid balances.

ALL CREDIT/DEBIT CARD TRANSACTIONS ARE SUBJECT TO A 5% CONVENIENCE FEE.

PARTIAL REPAIRS ARE USUALLY AN OPTION FOR OUR CUSTOMERS IF THEY CHOOSE. DON & SONS WILL NOT ALLOW PARTIAL REPAIRS IF WE DEEM THE VEHICLE TO BE UNSAFE TO DRIVE.

IN THE EVENT THAT THE CUSTOMER CHOOSES NOT TO DO A FULL REPAIR, BUT CHOOSES A PARTIAL REPAIR, DON & SONS WARRANTY IS VOID. PLEASE ASK IF YOU HAVE ANY CONCERNS REGARDING THIS POLICY.

THANK YOU!



Quality Claims Solutions

Quality Claims Solutions

105 N Krohn Place
Sioux Falls, SD 57103
Phone: 877.237.3727
Fax: 866.371.2844
Federal Tax ID: 46-0461202

INVOICE =

Attention/Adjuster: Mike Long
Company Name: DAS Fleet Services
Address: 109 SE 13th St
Des Moines, IA 50319

Invoice No: APDSOI0223943-001-4528
Date: 08/2/2021 1:50 PM
Customer ID: IWAA
Claim Number: APDSOI0223943-001
Vehicle Owner: SCOTT TUTTLE

Quantity	Description	Unit Price	Extended Amount
1	Technical Estimate Review	\$35.00	\$35.00

Item Total: \$35.00

Sales Tax: N/A

Invoice Total: \$35.00