



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: July 29, 2021

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Risk Coordinator
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#696, 319, 61, 31, 775/Hail
Event Date	July 9, 2021
Summary	Vehicles sustained hail damage. (Fleet Ref# 223320,223322,223240,223284, 223286)
Amount Requested	\$13,734.55 - Estimates \$ 70.00 - PDA/QCS Invoices \$13,804.55 - Total
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Risk Coordinator
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-725-2243



Risk, DAS <das.risk@iowa.gov>

223320

247043

Fwd: FW: Hail repair estimate, CAR 696

1 message

Risk, DAS <das.risk@iowa.gov>

Tue, Jul 20, 2021 at 11:00 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 696 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



DAS Fleet Services, Risk
Iowa Department of Administrative Services
Division of Business and Property Services
Office: 515-725-2243
Das.Risk@iowa.gov
<https://das.iowa.gov>

----- Forwarded message -----

From: **Adams Jeannie** <jadams@dps.state.ia.us>

Date: Mon, Jul 19, 2021 at 11:03 AM

Subject: FW: Hail repair estimate, CAR 696

To: vehicledamage <vehicledamage@dps.state.ia.us>, DAS.Risk (DAS.Risk@iowa.gov) <DAS.Risk@iowa.gov>

Jeannie Adams

ISP Fleet & Supply, Fleet Asset Manager

Department of Public Safety

30 N.E. 48th Place

Des Moines, Iowa 50313

Direct #: 515-725-0643

Cell Phone: 515-204-3019

Shop: 515-281-3277

Fax: 515-242-6321

Email: jadams@dps.state.ia.us

From: Lamp Scott <selamp@dps.state.ia.us>
Sent: Monday, July 19, 2021 9:57 AM
To: Adams Jeannie <jadams@dps.state.ia.us>; Guill Bryan <guill@dps.state.ia.us>
Cc: Current Michael <current@dps.state.ia.us>
Subject: Hail repair estimate, CAR 696

Scott E. Lamp, M.A. | Special Agent in Charge

Iowa Division of Criminal Investigation - Department of Public Safety

Iowa Department of Public Safety | Division of Criminal Investigation

Support Operations Bureau: Administration//Transcription//CCH Records-Dissemination

Identification//Fingerprints//Training// Equipment//Fleet & Supply

215 East 7th Street | Des Moines | Iowa 50319
Office: 515-725-6025 (phone) | Cell: 712-898-0478

State Peace Officer proudly serving since 1994, Badge # I-65
selamp@dps.state.ia.us

Correspondence is Discoverable in State/Federal Courts

NOTICE This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain

confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited.

If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message.



8 attachments

Vehicle 696 hail claim.jpg
80K



Vehicle 696 hail photo 1.jpg
47K



Vehicle 696 hail photo 2.jpg
53K



Vehicle 696 hail photo 3.jpg
41K



Vehicle 696 hail photo 4.jpg
60K

Vehicle 696 hail photo 5.jpg
65K



 **State Vehicle Damage Rpt form, 696 hail from 7-09-21.doc**
105K

 **7-19-21 Dent Eliminators estimate, car 696.pdf**
100K



St Ores, Heather
 | 5153434703 | selamp@dps.state.ia.us

DCI CAR 696

Year: 2020
 Make: Chevrolet
 Model: Equinox
 Color: Black

Vin: 2GNAX5EV0L6243439
 Stock/Ro#:
 Odometer:
 License:

Total: **\$2,309.00**

Services Summary:

Hail: \$1,835.00 - **Hood:** \$468.75, **LT Roof Rail:** \$231.25, **RT Quarter:** \$125.00, **RT Front Door:** \$155.00, **RT Fender:** \$155.00, **RT Roof Rail:** \$231.25, **Roof:** \$468.75
R&I/R&R: \$474.00 - **Hood:** \$60.00, **RT Fender:** \$42.00, **RT Front Door:** \$48.00, **Roof:** \$204.00, **RT Quarter:** \$36.00, **Trunk:** \$84.00

Service Type	Description	Body Hours	Paint Hours	Total
Hood				
PDR - \$468.75 R&I - \$60.00				
PDR	16-30 dents, Quarter	-	-	\$375.00
Add-On	Aluminum, 25.0%	-	-	\$93.75
Labor, R&I	Insulator	0.3	-	\$18.00
Labor, R&I	Hood	0.7	-	\$42.00
RT Fender				
PDR - \$155.00 R&I - \$42.00				
PDR	1-5 dents, Quarter	-	-	\$155.00
Labor, R&I	Headlamp	0.3	-	\$18.00
Labor, R&I	Fender Liner	0.4	-	\$24.00
RT Front Door				
PDR - \$155.00 R&I - \$48.00				
PDR	1-5 dents, Quarter	-	-	\$155.00
Labor, R&I	Interior Trim Panel	0.8	-	\$48.00
Roof				
PDR - \$468.75 R&I - \$204.00				
PDR	16-30 dents, Quarter	-	-	\$375.00
Add-On	Ribbed Roof, 25.0%	-	-	\$93.75
Labor, R&I	Headliner	3.2	-	\$192.00
Labor, R&I	Antenna	0.2	-	\$12.00
LT Roof Rail				
PDR - \$231.25				
PDR	1-5 dents, Quarter	-	-	\$185.00
Add-On	Glue Pull, 25.0%	-	-	\$46.25
RT Roof Rail				
PDR - \$231.25				
PDR	1-5 dents, Quarter	-	-	\$185.00
Add-On	Glue Pull, 25.0%	-	-	\$46.25
RT Quarter				
PDR - \$125.00 R&I - \$36.00				
PDR	1-5 dents, Nickel	-	-	\$125.00
Labor, R&I	Taillight	0.3	-	\$18.00
Labor, R&I	Wheel Liner	0.3	-	\$18.00
Trunk				
R&I - \$84.00				

Labor, R&I

Liftgate

1.4

-

\$84.00

Estimate Totals

Service Type	Rate	Hours	Total
PDR	--	--	\$1,835.00
Labor, R&I / R&R	\$60.00	7.9	\$474.00

Subtotal: \$2,309.00

Taxable Subtotal: \$2,309.00

Tax Rate Labor (7.00%): \$161.63

ESTIMATE TOTAL: \$2,470.63

By signing above, I hereby authorize DENT ELIMINATORS to perform the estimated repairs to my vehicle(s), and hereby grant you and/or your employees, permission to operate the vehicle(s) herein described on streets, highways or elsewhere for the purpose of testing and/or inspection and/or transport to the repair location. DENT ELIMINATORS will not be held responsible for loss or damage to the vehicle(s) or any articles left in the vehicle in case of fire, theft, accident or any other cause beyond our control.



Quality Claims Solutions

Quality Claims Solutions

105 N Krohn Place
Sioux Falls, SD 57103
Phone: 877.237.3727

Fax: 866.371.2844
Federal Tax ID: 46-0461202

INVOICE =

Attention/Adjuster: Mike Long
Company Name: DAS Fleet Services
Address: 109 SE 13th St
Des Moines, IA 50319

Invoice No: APDSOI0223320-001-6549
Date: 07/27/2021 12:39 PM
Customer ID: IWAA
Claim Number: APDSOI0223320-001
Vehicle Owner: HEATHER ST. ORES

Quantity	Description	Unit Price	Extended Amount
1	Technical Estimate Review	\$35.00	\$35.00

Item Total: \$35.00

Sales Tax: N/A

Invoice Total: \$35.00

223322

Fwd: damage estimate for hail damage. July 9 storm - #319

1 message

288175

Risk, DAS <das.risk@iowa.gov>

Tue, Jul 20, 2021 at 11:08 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 319 sustained hail damage on 7/20/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

**DAS Fleet Services, Risk**

Iowa Department of Administrative Services
 Division of Business and Property Services
 Office: 515-725-2243
 Das.Risk@iowa.gov
<https://das.iowa.gov>

----- Forwarded message -----

From: **Flowers, Mariah** <mariah.flowers@iowa.gov>
 Date: Mon, Jul 19, 2021 at 2:08 PM
 Subject: Fwd: damage estimate for hail damage. July 9 storm - #319
 To: DAS Risk <das.risk@iowa.gov>

**Mariah Flowers, CPM**

Iowa Department of Administrative Services
 Fleet Services
 Office/Mobile: 515-414-6582
 mariah.flowers@iowa.gov
<https://das.iowa.gov>

----- Forwarded message -----

From: **Stine Mark** <stine@dps.state.ia.us>
 Date: Mon, Jul 19, 2021 at 12:37 PM
 Subject: damage estimate for hail damage. July 9 storm
 To: vehicledamage <vehicledamage@dps.state.ia.us>

Attached is the estimate for my hail damage. I obtained the estimate at Caliber Collision on Merle Hay Road which was formerly 1Collision/R Jones (which held the state contract and the gentleman I spoke to advised that they still do).

I have pictures but they are hard to see the dents due to lighting.

Let me know if you need anything further.

Thank you,

Major Mark Stine ★319★

Field Operations Officer

Iowa State Patrol

Headquarters


Des Moines, IA

515-725-0624


641-745-7849 (cell)

stine@dps.state.ia.us

mstine@mocic.riss.net



2 attachments

 **319 hail State Vehicle Damage Report.Form (002).doc**
109K

 **319 hail estimate.pdf**
154K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: *DPS – Vehicle Damage; DAS – Risk*

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #:

Date: <small>(Month/Day/Year)</small>	July 9, 2021	Time: <small>(Time plus a.m./p.m.)</small>	12:30 p.m.
Vehicle Plate #:	HZG332	Vehicle Mileage:	99331
Vehicle Description: <small>(Yr/Make/Model/ & Vin#)</small>	2017 Dodge Charger 2C3CDXKT2HH546831		
Assigned To:	Mark Stine	Badge #	319
Driven By:	Mark Stine	Badge #	319
Driver's Lic #:	745AA7645	Damage:	\$6881.75
Vehicle Towed: <small>(Yes / No)</small>	No	Towed By:	
Towed To:		Towing Cost:	\$
Seat Belt: <small>(Yes / No)</small>	Yes	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Unmarked
Injured/Injuries:	none		
Occupants: <small>(Other than driver)</small>	none		

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			

Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

OTHER INFORMATION:

Witnesses:	none
Accident Location: (Street/Hwy)	Camp Dodge, Johnston, IA
County:	Polk
Weather/Road Conditions:	Thunderstorm
Narrative: Vehicle was parked in a parking lot at Camp Dodge while driver was attending training. A thunderstorm passed through the area and large hail fell on the car causing multiple dents to the top, hood and trunk mostly.	
Property Damage other than Vehicles:	none
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	none

Investigating Officer:	Major Mark Stine #319
------------------------	-----------------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)		Yes	



Quality Claims Solutions

Quality Claims Solutions

105 N Krohn Place
Sioux Falls, SD 57103
Phone: 877.237.3727
Fax: 866.371.2844
Federal Tax ID: 46-0461202

INVOICE =

Attention/Adjuster: Mike Long
Company Name: DAS Fleet Services
Address: 109 SE 13th St
Des Moines, IA 50319

Invoice No: APDSOI0223322-001-8488
Date: 07/21/2021 2:30 PM
Customer ID: IWAA
Claim Number: APDSOI0223322-001
Vehicle Owner: STATE OF IOWA

Quantity	Description	Unit Price	Extended Amount
1	Technical Estimate Review	\$35.00	\$35.00

Item Total: \$35.00

Sales Tax: N/A

Invoice Total: \$35.00



Risk, DAS <das.risk@iowa.gov>

223240

#91145

Fwd: FW: 61 Vehicle damage

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Jul 19, 2021 at 1:56 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 61 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



DAS Fleet Services, Risk
Iowa Department of Administrative Services
Division of Business and Property Services
Office: 515-725-2243
Das.Risk@iowa.gov
<https://das.iowa.gov>

----- Forwarded message -----

From: **Ludwig Nathan** <n ludwig@dps.state.ia.us>
Date: Wed, Jul 14, 2021 at 10:57 AM
Subject: FW: 61 Vehicle damage
To: das.risk@iowa.gov <das.risk@iowa.gov>, vehicledamage <vehicledamage@dps.state.ia.us>

This is the last for District 1.

Thank you

Lieutenant Nathan Ludwig ★ 390 ★

District 1 Commander

Iowa State Patrol

Iowa Department of Public Safety

Cell: 515-745-2863

nludwig@dps.state.ia.us



IOWA STATE PATROL

Guided by Tradition, Driven to Serve

COURTESY SERVICE PROTECTION

From: Champlin Corey <champlin@dps.state.ia.us>
Sent: Wednesday, July 14, 2021 10:52 AM
To: Ludwig Nathan <nludwig@dps.state.ia.us>
Subject: 61 Vehicle damage

This should be everything for 61. I think we have them all done aside from 115 and 354 that are at Camp Dodge

Sgt. Corey Champlin ★220★

Iowa State Patrol-District 1

Des Moines, Iowa 50313

Office: (515)725-0010

Cell: (515)218-4054

champlin@dps.state.ia.us

7 attachments



IMG_2021-07-13_09-45-01.jpeg
2234K



IMG_2021-07-13_09-45-16.jpeg
1715K

IMG_2021-07-13_09-45-32.jpeg
2150K



 **State Vehicle Damage Report ISP 61 7-9-21.Form.doc**
108K

 **Preliminary_Estimate.pdf**
72K

 **Image_Report.pdf**
3299K

 **61Haildamage.doc**
28K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: **DPS – Vehicle Damage; DAS – Risk**

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #: 2021016414

Date: <small>(Month/Day/Year)</small>	7/9/2021	Time: <small>(Time plus a.m./p.m.)</small>	1300 p.m.
Vehicle Plate #:	61	Vehicle Mileage:	59,908
Vehicle Description: <small>(Yr/Make/Model/ & Vin#)</small>	2019 Dodge Charger 2C3CDXKT9KH577274		
Assigned To:	Trp. Scott Bogdanski	Badge #	61
Driven By:	Trp. Scott Bogdanski	Badge #	61
Driver's Lic #:	416LL8265	Damage:	\$911.45
Vehicle Towed: <small>(Yes / No)</small>	No	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$
Seat Belt: <small>(Yes / No)</small>	No	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Marked
Injured/Injuries:	None		
Occupants: <small>(Other than driver)</small>	None		

VEHICLE #2:

DL #:	N/A	State:	N/A
Vehicle Lic. #		State:	IA
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:	NONE		
Occupants: (Other than driver)	N/A		
Occupant(s) Wearing Seat Belt: (Yes/No)	No		

OTHER INFORMATION:

Witnesses:			
Accident Location: (Street/Hwy)			
County:	Polk		
Weather/Road Conditions:			
Narrative: Trooper Bogdanski's vehicle sustained hail damage on 7/9/21 when a thunderstorm rolled through Polk county. Trooper Bogdanski's patrol car was parked at his residence as he was off duty when the damage was sustained.			
Property Damage other than Vehicles:			
Cost:	\$		
Citations Issued To: (List Charge(s) and Statute Code(s))			

Investigating Officer:	
------------------------	--

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			

Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	No		

**Karl Chevrolet Collision Center
Ankeny**

Your Dealer for Life
1101 Southeast Oralabor Road, Exit 90 and I-35,
Ankeny, IA 50021
Phone: (515) 299-4337
FAX: (515) 964-2293

Workfile ID: 725af88d
PartsShare: 6kPCJ8
Federal ID: 42-1092272
State ID: na
Federal EPA: iado65212904
State EPA: iado65212904

Preliminary Estimate

Customer: STATE OF IOWA UNIT 61

Written By: Mark Michael Wright

Insured: STATE OF IOWA UNIT 61 Policy #: Claim #: 61
Type of Loss: Date of Loss: Days to Repair: 0
Point of Impact:

Owner: STATE OF IOWA UNIT 61
(515) 725-0010 Business
Inspection Location: Karl Chevrolet Collision Center Ankeny
1101 Southeast Oralabor Road
Exit 90 and I-35
Ankeny, IA 50021
Repair Facility
(515) 299-4337 Business
Insurance Company: STATE OF IOWA

VEHICLE

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI SILVER

VIN: 2C3CDXKT9KH577274 Interior Color: BLACK Mileage In: 60,004 Vehicle Out:
License: 61 Exterior Color: SILVER Mileage Out:
State: IA Production Date: 1/2019 Condition: Job #:

TRANSMISSION

4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera
Parking Sensors

RADIO

AM Radio

FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats

Bucket Seats
Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions
Power Trunk/Liftgate

Get live updates at www.carwise.com/e/43FiYY

Preliminary Estimate

Customer: STATE OF IOWA UNIT 61

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI SILVER

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		HOOD					
2	*	PDR Hood (ALU) +25% Note: PDR 14 nickel		1	187.50 T		
3		R&I Insulator				0.3	
4		ROOF					
5	*	PDR Roof panel w/o sunroof +25% Note: PDR 4 nickel		1	156.25 T		
6		R&I R&I headliner				3.4	
7		PILLARS, ROCKER & FLOOR					
8	*	PDR LT Aperture panel +25% Note: PDR 1 quarter		1	125.00 T s		
9		QUARTER PANEL					
10	*	PDR LT Quarter panel +25% Note: PDR 1 quarter		1	125.00 T		
11		TRUNK LID					
12	*	PDR Trunk lid w/police w/camera +25% Note: PDR 2 quarter		1	125.00 T		
13	#	R&I LIGHT BAR				1.0	
SUBTOTALS					718.75	4.7	0.0

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			0.00
Body Labor	4.7 hrs @	\$ 41.00 /hr	192.70
PDR			718.75
Subtotal			911.45
Grand Total			911.45
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			911.45

THIS IS A PRELIMINARY ESTIMATE. ACTUAL COST TO REPAIR MAY BE DIFFERENT

LIMITED LIFETIME WARRANTY--SEE BODY SHOP PERSONNEL FOR DETAILS

***IF AFTERMARKET PARTS (PARTS MADE BY A SOURCE OTHER THAN THE ORIGINAL MANUFACTURER OF THAT PART) ARE USED THEY WILL BE IDENTIFIED BY "QUAL.REPL.PART" IN THE MFG. PART NO. COLUMN

Fwd: #31 Hail Damage 7-9-21

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Jul 19, 2021 at 3:16 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 31 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

**DAS Fleet Services, Risk**

Iowa Department of Administrative Services
 Division of Business and Property Services
 Office: 515-725-2243
 Das.Risk@iowa.gov
<https://das.iowa.gov>

----- Forwarded message -----

From: **Jalas Dean** <jalas@dps.state.ia.us>

Date: Thu, Jul 15, 2021 at 2:28 PM

Subject: #31 Hail Damage 7-9-21

To: vehicledamage <vehicledamage@dps.state.ia.us>, Risk, DAS (das.risk@iowa.gov) <das.risk@iowa.gov>

Cc: Morey Russell <morey@dps.state.ia.us>, Andreasen Jeremy <andrease@dps.state.ia.us>, Dolf Ryan <dolf@dps.state.ia.us>, Jalas Dean <jalas@dps.state.ia.us>

Please find attached the paperwork for hail damage that occurred to #31's patrol car on 7-9-21.

Thanks, Dean

LIEUTENANT DEAN JALAS *231*

District Commander

Iowa State Patrol District #13

1300 S Grand Ave. Suite #201

Mount Pleasant, Iowa 52641

Phone (319) 385-8715

Fax (319) 385-2743

jalas@dps.state.ia.us<mailto:jalas@dps.state.ia.us>

NOTICE This email message (including any file attachments transmitted with it) is for the sole use of the intended recipients(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this email in error, please notify the sender by return email and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.



1.jpg
58K




2.jpg
51K



3.jpg
56K




4.jpg
60K




5.jpg
40K


6.jpg
53K




7.jpg
53K



8.jpg
50K



9.jpg
39K



10.jpg
51K

 noname
0K

 31 Hail Estimate.pdf
180K

 **MEMO 31 VEHICLE HAIL DAMAGE.docx**
18K

 **31 State Vehicle Damage Rpt form.doc**
87K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #: 2021016414

Date: (Month/Day/Year)	07/09/2021	Time: (Time plus a.m./p.m.)	1900
Vehicle Plate #:	31	Vehicle Mileage:	35,400
Vehicle Description: (Yr/Make/Model/ & Vin#)	2020 Dodge Charger VIN:2C3CDXKT4LH130451		
Assigned To:	Trp Lundy Anderson	Badge #	31
Driven By:	Parked	Badge #	
Driver's Lic #:		Damage:	\$1,238.75
Vehicle Towed: (Yes / No)	N/A	Towed By:	
Towed To:		Towing Cost:	\$
Seat Belt: (Yes / No)		Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:			
Occupants: (Other than driver)	None		

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

OTHER INFORMATION:

Witnesses:			
Accident Location: (Street/Hwy)		410 S Main St Danville, IA 52623	
County:		Des Moines	
Weather/Road Conditions:		Damaging storm with hail	
<p>On the evening of 07/09/21 a heavy storm with hail affected the area of Trooper Ryan Menke's residence in Des Moines County. Trooper Menke was utilizing Trooper Lundy Anderson's patrol car and it was parked at his residence. The following day, Trooper Menke noticed the hail damage to Trooper Anderson's patrol car.</p>			
Property Damage other than Vehicles:		None	
Cost:		\$	
Citations Issued To: (List Charge(s) and Statute Code(s))			

Investigating Officer:	SGT Andreasen #161
------------------------	--------------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			

Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		



COPELAND AUTO BODY, INC.

506 E 2nd St, P.O. Box 109, Hedrick, IA 52563
Phone: (641) 653-2140
FAX: (641) 653-4301

Workfile ID: ba97f533
PartsShare: 6kQw3k
Federal ID: 42-1488559

Preliminary Estimate

Customer: State Of Iowa

Job Number:

Written By: Steve Copeland

Insured: State Of Iowa Policy #: Claim #: 31HAIL
Type of Loss: Date of Loss: Days to Repair: 0
Point of Impact:

Owner:	Inspection Location:	Insurance Company:
State Of Iowa	COPELAND AUTO BODY, INC.	Creative Risk Solutions
301 E 7th St	506 E 2nd St	
Des Moines, IA 50319	P.O. Box 109	
(319) 385-8715 Business	Hedrick, IA 52563	
	Repair Facility	
	(641) 653-2140 Business	

VEHICLE

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Silver

VIN: 2C3CDXKT4LH130451	Interior Color:	Mileage In: 35,543	Vehicle Out:
License:	Exterior Color: Silver	Mileage Out:	
State:	Production Date: 2/2020	Condition:	Job #:

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera
Parking Sensors

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions
Power Trunk/Liftgate

Get live updates at www.carwise.com/e/43FS2b

Preliminary Estimate

Customer: State Of Iowa

Job Number:

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Silver

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		HOOD					
2	*	PDR Hood (ALU) Note: PDR 15 nickel, 5 half		1	<u>300.00</u>		
3	#	Oversize Dents (\$40 each) (1 item)		1	40.00		
4	#	Aluminum Upcharge (25%)		1	75.00		
5		FENDER					
6	*	PDR RT Fender w/wide body Note: PDR 5 nickel		1	<u>75.00</u>		
7	#	Double Panel/Glue Pull Upcharge (25%)		1	18.75		
8		ROOF					
9	*	PDR Roof panel w/o sunroof Note: PDR 5 quarter		1	<u>150.00</u>		
10	#	Double Panel/Glue Pull Upcharge (25%)		1	37.50		
11	#	RT Roof Rail		1	125.00		
12		REAR DOOR					
13	*	PDR RT Door shell w/wide body (HSS) Note: PDR 5 nickel		1	<u>75.00</u>		
14	#	Double Panel/Glue Pull Upcharge (25%)		1	18.75		
15		QUARTER PANEL					
16	*	PDR LT Quarter panel w/wide body Note: PDR 5 nickel		1	<u>75.00</u>		
17	#	Double Panel/Glue Pull Upcharge (25%)		1	18.75		
18	*	PDR RT Quarter panel w/wide body Note: PDR 5 quarter		1	<u>100.00</u>		
19	#	Double Panel/Glue Pull Upcharge (25%)		1	25.00		
20		TRUNK LID					
21	*	PDR Trunk lid w/police w/camera Note: PDR 5 nickel		1	<u>75.00</u>		
22	#	Corrosion Protection		1	30.00		
SUBTOTALS					1,238.75	0.0	0.0

Preliminary Estimate

Customer: State Of Iowa

Job Number:

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Silver

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			388.75
PDR			850.00
Subtotal			1,238.75
Grand Total			1,238.75
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			1,238.75



Risk, DAS <das.risk@iowa.gov>

223286

023197

Fwd: FW: Hail Damage Vehicle Report

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Jul 19, 2021 at 3:26 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 775 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



DAS Fleet Services, Risk
Iowa Department of Administrative Services
Division of Business and Property Services
Office: 515-725-2243
Das.Risk@iowa.gov
<https://das.iowa.gov>

----- Forwarded message -----

From: Risk, DAS <das.risk@iowa.gov>
Date: Mon, Jul 19, 2021 at 3:25 PM
Subject: Fwd: FW: Hail Damage Vehicle Report
To: Electronic Claims <eclaims@creativerisksolutions.com>

Vehicle 775
Agency 595

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



DAS Fleet Services, Risk
Iowa Department of Administrative Services
Division of Business and Property Services
Office: 515-725-2243
Das.Risk@iowa.gov
<https://das.iowa.gov>

----- Forwarded message -----

From: Adams Jeannie <jadams@dps.state.ia.us>
Date: Mon, Jul 12, 2021 at 12:58 PM

Subject: FW: Hail Damage Vehicle Report

To: vehicledamage <vehicledamage@dps.state.ia.us>, DAS.Risk (DAS.Risk@iowa.gov) <DAS.Risk@iowa.gov>

Jeannie Adams

ISP Fleet & Supply, Fleet Asset Manager

Department of Public Safety

30 N.E. 48th Place

Des Moines, Iowa 50313

Direct #: 515-725-0643

Cell Phone: 515-204-3019

Shop: 515-281-3277

Fax: 515-242-6321

Email: jadams@dps.state.ia.us

From: Shupe Bryan <shupe@dps.state.ia.us>

Sent: Monday, July 12, 2021 11:57 AM

To: Humphrey Ronald <humphrey@dps.state.ia.us>; Lamp Scott <selamp@dps.state.ia.us>; Adams Jeannie <jadams@dps.state.ia.us>

Cc: Wood Daniel <wood@dps.state.ia.us>

Subject: Hail Damage Vehicle Report

Ron asked me to forward this to you all.

The hood sustained the most damage but the roof and bed topper also have a few dings. They are however shallow and the sun/heat have "repaired" some of them already. Photos were attempted but the damage doesn't show up.

Did not include an estimate as I was unsure if the damage will be repaired or repaired as a group with paint less dent removal.

Have a good week.

Bryan Shupe

Special Agent

Iowa State Fire Marshal Division

Arson & Explosives Bureau

shupe@dps.state.ia.us

(641)425-8813



2 attachments

 **State Vehicle Damage Rpt form - updated_.doc**
102K

 **2017 Ford Super Duty - Estimate.pdf**
519K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #:

Date: <small>(Month/Day/Year)</small>	7/9/2021	Time: <small>(Time plus a.m./p.m.)</small>	@2:30 p.m.
Vehicle Plate #:	708ALL -75	Vehicle Mileage:	84150
Vehicle Description: <small>(Yr/Make/Model/ & Vin#)</small>	2017/Ford/F250/1FT7W2B61HE271015		
Assigned To:	Shupe	Badge #	775
Driven By:	Shupe	Badge #	775
Driver's Lic #:	674WW4264	Damage:	\$
Vehicle Towed: <small>(Yes / No)</small>	No	Towed By:	
Towed To:		Towing Cost:	\$
Seat Belt: <small>(Yes / No)</small>	No	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Unmarked
Injured/Injuries:	None		
Occupants: <small>(Other than driver)</small>	None		

VEHICLE #2:

DL #:	N/A	State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

OTHER INFORMATION:

Witnesses:	N/A
Accident Location: (Street/Hwy)	Camp Dodge Counter Drug Training Center
County:	Polk
Weather/Road Conditions:	Hail, Rain
<p>I was attending tactical medicine TCCC training at Camp Dodge when a brief hail storm went over. Looking outside the hail stones appeared approximately quarter size.</p> <p>Photos were attempted but the numerous dents are too shallow to show up in photographs.</p>	
Property Damage other than Vehicles:	None
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	N/A

Investigating Officer:	Shupe
------------------------	-------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			



**NORTH IOWA COLLISION CENTER
INC.**

Serving your car, light & heavy duty truck, heavy
equipment & RV repair needs.
11201 265TH ST, CLEAR LAKE, IA 50428
Phone: (641) 421-8555
FAX: (641) 421-8558

Workfile ID: 69820863
PartsShare: 6kQL9Q
Federal ID: 26-1573911
State ID: 1-17-017868
Resale Number: 1-17-017868
Federal EPA: IAR000007856

Preliminary Estimate

Customer: State of Iowa Fire Marshal

Written By: Scott Larson

Insured: State of Iowa Fire Marshal Policy #: Claim #:
Type of Loss: Date of Loss: Days to Repair: 5
Point of Impact: 27 Hail

Owner: State of Iowa Fire Marshal
4425 S Washington
Mason City, IA 50401
(641) 425-8813 Cell
Inspection Location: NORTH IOWA COLLISION CENTER INC.
11201 265TH ST
CLEAR LAKE, IA 50428
Repair Facility
(641) 421-8555 Business
Insurance Company:

VEHICLE

2017 FORD Super Duty F-250 w/Single Rear Wheels XL Crew Cab 4WD w/6.75' Box 4D SHORT 8-6.2L Flex Fuel Sequential MPI Silver

VIN: 1FT7W2B61HED71015 Interior Color: Mileage In: 84,755 Vehicle Out:
License: 708ALL Exterior Color: Silver Mileage Out:
State: IA Production Date: 5/2017 Condition: Job #:

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Message Center
Telescopic Wheel

RADIO

AM Radio
FM Radio
Stereo
Search/Seek

CD Player
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags

SEATS

Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

California Emissions

TRUCK

Rear Step Bumper
Trailer Hitch

Get live updates at www.carwise.com/e/43G2Yf

Preliminary Estimate

Customer: State of Iowa Fire Marshal

2017 FORD Super Duty F-250 w/Single Rear Wheels XL Crew Cab 4WD w/6.75' Box 4D SHORT 8-6.2L Flex Fuel Sequential MPI Silver

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	ADDITIONAL DAYS MAY OCCUR DUE TO SUBLETS & ADDITIONAL PARTS		1			
2	#	Repair Formula 20.4 / 4 = 5 day repair		1			
3	FRONT BUMPER						
4	R&I	R&I bumper assy				1.4	
5	GRILLE						
6	R&I	Grille assy chrome				1.0	
7	FRONT LAMPS						
8	R&I	RT R&I headlamp assy Note: LABOR: Time is after grille assembly is removed. Time includes R&R bulbs and trim molding.				0.4	
9	R&I	LT R&I headlamp assy Note: LABOR: Time is after grille assembly is removed. Time includes R&R bulbs and trim molding.				0.4	
10	HOOD						
11	**	Repl Opt OEM Hood (ALU)	HC3Z16612A	1	786.67	2.2	3.2
12		Add for Clear Coat					1.3
13		Add for Underside(Complete)					1.6
14	**	Repl A/M Seam Sealer		1	20.00	0.5	
15	FENDER						
16	*	PDR RT Fender w/o wheel opening mldg (ALU) Note: PDR 1 nickel		1	<u>75.00</u> T		
17	*	PDR LT Fender w/o wheel opening mldg (ALU) Note: PDR 1 nickel		1	<u>75.00</u> T		
18	Blnd	RT Fender w/o wheel opening mldg (ALU)					1.3
19	Blnd	LT Fender w/o wheel opening mldg (ALU)					1.3
20	R&I	RT Nameplate "F-250 STX "				0.2	
21	R&I	LT Nameplate "F-250 STX "				0.2	
22	R&I	RT Fender liner Note: Remove liner to access backside for R&I of nameplate				0.6	
23	R&I	LT Fender liner				0.6	
24	R&I	RT Rear molding w/narrow molding				0.1	
25	R&I	LT Rear molding w/narrow molding				0.1	
26	CAB						
27	#	PDR Roof panel (ALU) Note: \$450.00 + 25% mark up for aluminum = \$562.50. An additional 25% mark up added for extended panel \$112.50 = \$675.00		1	675.00 T		
28	R&I	R&I headliner				4.3	
29	FRONT DOOR						

Preliminary Estimate

Customer: State of Iowa Fire Marshal

2017 FORD Super Duty F-250 w/Single Rear Wheels XL Crew Cab 4WD w/6.75' Box 4D SHORT 8-6.2L Flex Fuel Sequential MPI Silver

30	*	PDR	LT Door shell (ALU) +25% Note: PDR 1 nickel	1	93.75	T	
31	REAR DOOR						
32	*	PDR	LT Door shell (ALU) +25% Note: PDR 1 nickel	1	93.75	T	
33	MISCELLANEOUS OPERATIONS						
34	**	Repl	A/M Cover car/bag	1	10.00		0.2
35	#						
36	**	Repl	A/M Truck Cap - ARE / SD SB DCU 26" +25% Note: Line-x of Mason City 641-424-2220 / ARE Distributor - Pricing includes installation. Approx 7-8 weeks out for availability	1	2,625.00		
37	#		Labor - Delliver and pick up to Line-x	1			0.5
38			OTHER CHARGES				
39	#		Haz-Waste	1	4.00		
SUBTOTALS					4,458.17		12.7
							8.7

NOTES

Prior Damage Notes:
Normal wear

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			3,441.67
Body Labor	12.7 hrs @	\$ 65.00 /hr	825.50
Paint Labor	8.7 hrs @	\$ 109.00 /hr	948.30
PDR			1,012.50
Other Charges			4.00
Subtotal			6,231.97
Grand Total			6,231.97
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			6,231.97

MyPriceLink Estimate ID / Quote ID:

844621742193254400 /