



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: October 5, 2021

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	# 105115/Hail
Event Date	July 9, 2021
Summary	Vehicle 105115 sustained hail damage during a storm. (224982)
Amount Requested	\$4,869.76 - Estimate <u>\$ 231.00 - Review Invoice</u> \$5,100.76 - Total
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-725-2243

224982

105115

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Jul 12, 2021 at 11:02 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 105115 sustained hail damage on 7/9/2021 . I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



DAS Fleet Services, Risk
Iowa Department of Administrative Services
Division of Business and Property Services
Office: 515-725-2243
Das.Risk@iowa.gov
<https://das.iowa.gov>

AR
EST

Vehicle Accident Report

Time and location of accident

Accident Date (Mo/Day/Year)	Time	No. of Vehicles
7/9/2021	12pm-3pm	1
County	State	
polk	iowa	

Vehicle 1 (State vehicle)

Driver's Name		Work Street Address	
Brandi Wilkins		1710 NE Gateway Ct Apt. 212	
Driver's License No./State		City, State, Zip	
		Grimes IA 50111	
Date of Birth	Department	Work Phone	Home Phone
11/11/1993	DIA	5157209460	5156642220
License Plate No.	VIN	Year, Make, Model	
9601313AE	3FA6P0G79LR215430	2020 Ford Fusion	
Estimate (\$) of Damage		Description of Damage	
TBD		Hail damage	

Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

Driver's Name		Street Address	
Driver's License No./State		City, State, Zip	
Date of Birth	Work Phone	Home Phone	License Plate No.
Description of Damage			

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
Vehicle No. 2/ Name and Address	Describe Injuries
Witness	
Name	Address/Phone
Name	Address/Phone

Accident Diagram	
<p>Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers. Use number 1 to indicate the State vehicle.</p>	
	<p>I was at 2740 Douglas Ave. in the parking lot when a hail storm happened. My car was parked. No other vehicles were involved in this accident.</p>

Date: 8/23/2021 01:47 PM
 Estimate ID: 7761080061
 Estimate Version: 0
 Committed
 Profile ID: * Mitchell
 Quote ID: 91536809

Property Damage Appraisers (PDA Des Moines)

P.O. Box 144, Collins, IA 50055
 (515) 222-1906
 Fax: (515) 222-1929
 Email: pdadesmoines@pdaorg.net

* Not An Authorization For Repair *
 Read disclaimers following appraisal calculations.

Damage Assessed By: CALEB CUTLER
 Classification: Field

Appraised For: MIKE LONG

Condition Code: Good
 Deductible: 0.00
 File Number: 7761080061
 Claim Number: APDSOI0224982-001

Type of Loss: Comprehensive

Insured: STATE OF IOWA
 Owner: STATE OF IOWA
 Address: 1710 NE GATEWAY CT APT 212, GRIMES, IA 50111
 Telephone: Work Phone: (515) 664-2220

Cell Phone: (515) 720-9460

Mitchell Service: 911656

Description: 2020 Ford Fusion S
 Body Style: 4D Sed
 VIN: 3FA6P0G79LR215430
 Mileage: 8,077
 OEM/ALT: O
 Color: WHITE

Drive Train: 2.5L Inj 4 Cyl 6A FWD
 License: 105115 IA

Search Code: 776

Options: PASSENGER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING, REAR WINDOW DEFOGGER
 AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN, AM/FM STEREO, DRIVER AIRBAG
 FRONT SIDE AIRBAG WITH HEAD PROTECTION, ANTI-LOCK BRAKE SYS., TRACTION CONTROL
 REARVIEW CAMERA, REMOTE IGNITION, TIRE INFLATION/PRESSURE MONITOR
 ANTI-THEFT SYSTEM, AUXILIARY INPUT, BLUETOOTH WIRELESS CONNECTIVITY
 POWER ADJUSTABLE EXTERIOR MIRROR, TRIP COMPUTER, FIRST ROW BUCKET SEAT
 TELEMATIC SYSTEMS, CLOTH SEAT, SIDE AIRBAGS, AUTOMATIC HEADLIGHTS
 SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION
 INTERIOR AUTOMATIC DAY/NIGHT OR ELECTROCHROMATIC MIRROR, MP3 PLAYER
 DAYTIME RUNNING LIGHTS, DRIVER SEAT WITH POWER LUMBAR SUPPORT
 ELECTRONIC STABILITY CONTROL, KEYLESS ENTRY SYSTEM, RAIN SENSING WIPERS
 REAR BENCH SEAT, SIDE BLIND ZONE ALERT, SMART KEY SYSTEM
 STEERING WHEEL AUDIO CONTROLS

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Hood</u>							
1	101972	BDY	REMOVE/INSTALL	Hood Assy			0.6
2		BDY	PAINTLESS REPAIR	Hood Panel (Alum)	Sublet	837.50 *	
3				65 QUARTER SIZE DENTS			
4				LARGE DENT @ \$150.00			
5				INCLUDES: ALUMINUM PANEL			
6	101974	BDY	REMOVE/INSTALL	Hood Insulator	Existing		0.3 r
<u>Front Fender</u>							
7		BDY	PAINTLESS REPAIR	L Fender Panel	Sublet	125.00	#
8				1 QUARTER SIZE DENT			
9	103506	BDY	REMOVE/INSTALL	L Fender Liner	Existing		0.4 r
<u>Rocker/Pillars/Floor</u>							
10	101443	BDY	PAINTLESS REPAIR	R Door Opening Panel	Sublet	156.25 *	0.0*#
11				1 NICKEL SIZE DENT			

ESTIMATE RECALL NUMBER: 08/23/2021 13:47:50 7761080061
 Mitchell Data Version: OEM: AUG_21_V0823

Copyright (C) 1994 - 2021 Mitchell International
 All Rights Reserved

Software Version: 7.1.241

Page 1 of 4

Date: 8/23/2021 01:47 PM
 Estimate ID: 7761080061
 Estimate Version: 0
 Committed
 Profile ID: * Mitchell
 Quote ID: 91536809

12			INCLUDES: DOUBLE PANEL			
13	101444	BDY	PAINTLESS REPAIR	L Door Opening Panel	Sublet	156.25 * 0.0*#
14			2 NICKEL SIZE DENTS			
15			INCLUDES: DOUBLE PANEL			
			<u>Front Door</u>			
16		BDY	PAINTLESS REPAIR	L Frt Door Shell	Sublet	125.00 #
17			1 NICKEL SIZE DENT			
18			INCLUDES: Double Panel			
19	100285	BDY	REMOVE/REPLACE	L Frt Otr Door Belt Moulding	DS7Z 5421453 E	126.03 0.2
			<u>Rear Door</u>			
20		BDY	PAINTLESS REPAIR	R Rear Door Shell	Sublet	125.00
21			1 NICKEL SIZE DENT			
22			INCLUDES: Double Panel			
23		BDY	PAINTLESS REPAIR	L Rear Door Shell	Sublet	125.00
24			4 NICKEL SIZE DENTS			
25			INCLUDES: Double Panel			
26	102007	BDY	REMOVE/REPLACE	L Rear Otr Door Belt Moulding	DS7Z 5425861 A	100.38 0.2
			<u>Roof</u>			
27		BDY	PAINTLESS REPAIR	Roof Panel	Sublet	1,450.00 * #
28			125 QUARTER SIZE DENTS			
29			LARGE DENT @ \$250.00			
30	102284	BDY	REMOVE/INSTALL	Roof Headliner		4.6 #
			<u>Quarter Panel</u>			
31		BDY	PAINTLESS REPAIR	R Quarter Outer Panel	Sublet	156.25 #
32			2 QUARTER SIZE DENTS			
33			INCLUDES: Double Panel			
34		BDY	PAINTLESS REPAIR	L Quarter Outer Panel	Sublet	312.50 #
35			16 QUARTER SIZE DENTS			
36			INCLUDES: Double Panel			
			<u>Luggage Lid</u>			
37	102704	BDY	REMOVE/INSTALL	Luggage Lid Assy		0.4 #
38		BDY	REMOVE/INSTALL	Inr Luggage Lid Trim		0.3
39	102705	BDY	REMOVE/INSTALL	Luggage Trim Panel		0.7 #
40		BDY	PAINTLESS REPAIR	Luggage Lid Panel	Sublet	550.00
41			55 QUARTER SIZE DENTS			
			<u>Rear Lamps</u>			
42	101788	BDY	REMOVE/INSTALL	R Rear Combination Lamp		0.3
43	101789	BDY	REMOVE/INSTALL	L Rear Combination Lamp		0.3
			<u>Additional Operations</u>			
44	933005	BDY	ADD'L OPR	Restore Corrosion Protection		10.00 *

* - Judgment Item
 # - Labor Note Applies
 r - CEG R&R Time Used For This Labor Operation
 Paintless Repair calculations provided by Dent Wizard.

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	8.3	62.00	10.00	4,118.75	4,643.35	Taxable Parts	226.41
						Total Replacement Parts Amount	226.41
Labor Summary	8.3				4,643.35		

ESTIMATE RECALL NUMBER: 08/23/2021 13:47:50 7761080061
 Mitchell Data Version: OEM: AUG_21_V0823

Software Version: 7.1.241 Copyright (C) 1994 - 2021 Mitchell International All Rights Reserved

Date: 8/23/2021 01:47 PM
 Estimate ID: 7761080061
 Estimate Version: 0
 Committed
 Profile ID: * Mitchell
 Quote ID: 91536809

III. Additional Costs	<u>Amount</u>	IV. Adjustments	<u>Amount</u>
Total Additional Costs	0.00	Insurance Deductible	0.00
		Customer Responsibility	0.00
		I. Total Labor:	4,643.35
		II. Total Replacement Parts:	226.41
		III. Total Additional Costs:	0.00
		Gross Total:	4,869.76
		IV. Total Adjustments:	0.00
		Net Total:	4,869.76

Point(s) of Impact

16 Non-Collision (P)

Insurance Co: DAS FLEET SERVICES
 DES MOINES, IA 50139
 Work Phone: (877) 544-7843

Inspection Site: ZORA ROOFTOP BAR
 Address: 2120 INGERSOLL AVE
 DES MOINES, IA 50312
 Inspection Date: 8/23/2021

Body Shop: CALIBER COLLISION
 Address: 4416 Merle Hay Rd
 DES MOINES, IA 50310
 Telephone: (515) 278-4170
 State Lic. No: 33-0730794
 Email: GABRIEL.GYMER@CALIBERCOLLISION.COM

*****Notice*****
 THIS IS NOT AN AUTHORIZATION FOR REPAIR. ALL COSTS OF REPAIRS ARE THE SOLE RESPONSIBILITY OF THE VEHICLE OWNER, WHO MUST AUTHORIZE ALL REPAIRS. FAILURE TO DELIVER A COPY OF THIS APPRAISAL TO THE REPAIR SHOP BY THE VEHICLE OWNER MAY RESULT IN OUT OF POCKET EXPENSE TO THE VEHICLE OWNER. PROVIDING A COPY OF THIS APPRAISAL IS NOT AN ACCEPTANCE OF COVERAGE OR LIABILITY AND ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE DETERMINED BY THE INSURANCE CARRIER.

*****Notice*****
 DEDUCTIBLES MAY OR MAY NOT BE ADDRESSED OR INCLUDED IN THIS APPRAISAL. IF APPLICABLE, THE REPAIRER SHOULD COLLECT THE DEDUCTIBLE FROM THE VEHICLE OWNER PRIOR TO THE RELEASE OF THE REPAIRED VEHICLE.

*****Supplement Procedure Notice*****
 IT IS THE REPAIRER'S RESPONSIBILITY TO SEND NOTIFICATION OF THE SUPPLEMENT VIA FAX OR EMAIL TO PDA AT 515-222-1929 OR pdadesmoines@pdaorg.net INCLUDING A STATEMENT WHETHER THE REPAIRS HAVE BEEN HALTED ON THE VEHICLE. PDA WILL RESPOND TO YOUR REQUEST WITHIN 24 HOURS. PLEASE ALLOW 48 HOURS TO COMPLETE THE SUPPLEMENT PROCESSING FROM THE DATE OF REQUEST TO ENSURE TIMELY RELEASE OF THE VEHICLE.

*****Notice*****
 THIS APPRAISAL IS SUBJECT TO THE COMPLETE REVIEW AND APPROVAL BY THE ASSIGNING INSURANCE COMPANY TO ASSURE ACCURACY, COST EFFECTIVENESS, AND THAT ACCEPTED INDUSTRY REPAIR STANDARDS ARE MET. THE INSURANCE COMPANY LISTED HAS THE RIGHT TO ACCEPT OR REJECT ANY PART OR ALL OF THIS APPRAISAL OR MAKE ANY CHANGES THEY FEEL NECESSARY.

ESTIMATE RECALL NUMBER: 08/23/2021 13:47:50 7761080061
 Mitchell Data Version: OEM: AUG_21_V0823

Software Version: 7.1.241

Copyright (C) 1994 - 2021 Mitchell International
 All Rights Reserved



CALIBER - DES MOINES - MERLE HAY RD

RESTORING THE RHYTHM OF YOUR LIFE
4416 Merle Hay Rd, Des Moines, IA 50310
Phone: (515) 278-4170
FAX: (515) 278-4178

Workfile ID: bccbcd33
Federal ID: 33-0730794
State ID: na
Federal EPA: na
State EPA: na

Supplement of Record 1 with Summary

RO Number: 1456000315

Written By: John Mull, 9/8/2021 3:39:56 PM
Adjuster: long, mike, (515) 221-7127 Cell

Insured: WILKINS, BRANDI Policy #: Claim #: WIKINS07/30/21
Type of Loss: Date of Loss: Days to Repair: 0
Point of Impact:

Owner: WILKINS, BRANDI (515) 720-9460 Cell
Inspection Location: CALIBER - DES MOINES - MERLE HAY RD
4416 Merle Hay Rd
Des Moines, IA 50310
Repair Facility
(515) 278-4170 Business
Insurance Company: OTHER

VEHICLE

2020 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI WHITE

VIN: 3FA6P0G79LR215430 Interior Color: Mileage In: 8,578 Vehicle Out: 9/8/2021
License: 105115 Exterior Color: WHITE Mileage Out: 8,578
State: IA Production Date: 6/2020 Condition: Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors

DECOR

Dual Mirrors
Tinted Glass
Console/Storage
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Remote Starter
Backup Camera

RADIO

AM Radio

FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device
Blind Spot Detection
Lane Departure Warning

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Wheel Covers

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions

Supplement of Record 1 with Summary

RO Number: 1456000315

2020 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI WHITE

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint	
1	#	S01	== THIS IS A FINAL BILL ==		1				
2	#	S01	== PLEASE REMIT TO : ==		1				
3	#	S01	== 2941 LAKE VISTA DRIVE ==		1				
4	#	S01	== LEWISVILLE, TX 75067 ==		1				
5	HOOD								
6		R&I	R&I hood assy				0.6		
7	#		PDR Hood		1	837.50 X			
8	*	R&I	Insulator				<u>0.3</u>		
9	FENDER								
10	*	R&I	LT Fender liner w/o turbo w/2.5 liter DOHC				<u>0.4</u>		
11	#		PDR Lt. Fender		1	125.00 X			
12	#		PDR Rt. Roof Rail		1	156.25 X			
13	#		PDR Lt. Roof Rail		1	156.25 X			
14	FRONT DOOR								
15	*	Repl	LT Belt molding	DS7Z5421453E	1	126.03	<u>0.2</u>		
16	#		PDR Lt. F Door		1	125.00 X			
17	REAR DOOR								
18	*	Repl	LT Belt molding	DS7Z5425861A	1	100.38	<u>0.2</u>		
19	#		PDR Rt. R Door		1	125.00 X			
20	#		PDR Lt. R Door		1	125.00 X			
21	ROOF								
22	*	R&I	R&I headliner				<u>4.6</u>		
23	#		PDR Roof		1	1,450.00 X			
24	#		PDR Rt. Qtr.		1	156.25 X			
25	#		PDR Lt. Qtr.		1	312.50 X			
26	TRUNK LID								
27	*	R&I	R&I trunk lid				<u>1.4</u>		
28	#		PDR Deck Lid		1	550.00 X			
29	REAR LAMPS								
30	*	R&I	RT Tail lamp assy				<u>0.3</u>		
31	*	R&I	LT Tail lamp assy				<u>0.3</u>		
32	#		PDR ECOAT		1	10.00 X			
SUBTOTALS						4,355.16	8.3	0.0	

Supplement of Record 1 with Summary

RO Number: 1456000315

2020 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI WHITE

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			226.41
Body Labor	8.3 hrs @	\$ 62.00 /hr	514.60
Miscellaneous			4,128.75
Subtotal			4,869.76
Grand Total			4,869.76
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			4,869.76

MyPriceLink Estimate ID / Quote ID:

857684659369156608 / 91539931

Supplement of Record 1 with Summary

RO Number: 1456000315

2020 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI WHITE

SUPPLEMENT SUMMARY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Added Items							
1	#	S01	== THIS IS A FINAL BILL ==		1		
2	#	S01	== PLEASE REMIT TO : ==		1		
3	#	S01	== 2941 LAKE VISTA DRIVE ==		1		
4	#	S01	== LEWISVILLE, TX 75067 ==		1		
SUBTOTALS					0.00	0.0	0.0

TOTALS SUMMARY

Category	Basis	Rate	Cost \$
Parts			0.00
Subtotal			0.00

MyPriceLink Estimate ID / Quote ID:

857684659369156608 / 91539931

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate	4,869.76	Gabriel Gymer
Supplement S01	0.00	John Mull
Job Total:	\$ 4,869.76	
INSURANCE PAY:	\$ 4,869.76	



Due upon receipt

INVOICE

INVOICE NUMBER	INVOICE DATE
776-0279015	08/23/2021

BILL TO
Attn: MIKE LONG DAS FLEET SERVICES 109 SE 13TH ST DES MOINESIA 50139

CLIENT CODE
DAS105001
BUSINESS LINE / LOSS TYPE
A - Fleet

FOR INQUIRIES:
PDA Des Moines, IA #776 pdadesmoines@pdaorg.net (515) 222-1906

SUBMIT PAYMENT TO:
Property Damage Appraisers, Inc. 75-1160563 Dept #161, P.O. Box 1000 Memphis, TN 38148-0161 <i>Please reference the invoice number and enclose a copy of the invoice on all payments.</i>

INSURED	CLAIMANT	ASSIGNMENT DATE	PDA ASSIGNMENT #
STATE OF IOWA		08/20/2021	776-108-0061
CLAIM #	POLICY #	LOSS DATE	REFERENCE #
APDSOI0224982-001			

SERVICE FEE: (1 Unit(s) @ \$186.00) \$ 186.00
 Mileage: (36.00 miles) @ \$1.25 \$ 45.00

ACH Payment Info:
 Bank: First Horizon Bank
 ABA (US): 084000026 Bank
 Account: 220002525824
 Email Remit Information to:
 achbackup@pdaorg.net

Click [here](http://PDAclientPortal.com) to pay your invoice at PDAclientPortal.com

Same-Day Service. Guaranteed. PDA now offers expedited service for standard auto claims in select markets.

****WE HAVE CHANGED OUR BANK REMITTANCE INFORMATION AS NOTED ABOVE PLEASE UTILIZE OUR PORTAL FOR ALL OTHER ELECTRONIC PAYMENTS.****

TOTAL CHARGES:	231.00
:	
INVOICE TOTAL:	\$ 231.00

Terms: Professional fees due upon receipt. Interest accrues at 1% per month. Please include the invoice number on all payments.