



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

Rob Sand
Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

July 29, 2025

Kristi Onstot
Executive Council
L O C A L

Subject: Damages to Vehicle #51 During Winter Storm on April 17, 2025
Department of Administrative Services
Claim dated April 22, 2025
AOS Claim ID: 4053

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$3,295.75 subject to an audit of actual invoices.

Sincerely,

A handwritten signature in black ink, appearing to read "Brian R. Brustkern".

Brian R. Brustkern, CPA
Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



**Department of
Administrative Services**

KIM REYNOLDS, GOVERNOR
CHRIS COURNOYER, LT. GOVERNOR

ADAM STEEN, DIRECTOR

Date: April 22, 2025

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#51 / Hail
Event Date	April 17, 2025
Summary	Vehicle 51 - sustained hail damage (Claim # 305067)
Amount Requested	\$3,295.75 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, & Repair Estimate

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Ryan Betts
DAS Fleet Risk Manager
ryan.betts1@iowa.gov
515-281-8008



Risk, DAS <das.risk@iowa.gov>

Fwd: 51 Vehicle Damage from Hail Storm

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Apr 21, 2025 at 12:38 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 51 sustained hail damage on 4/17/2025. Estimate is attached, I will send the allocation letter later this week.

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

510 E 12th St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov<https://das.iowa.gov>**Department of
Administrative Services**

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

----- Forwarded message -----

From: **Elwood Nathan** <elwood@dps.state.ia.us>

Date: Mon, Apr 21, 2025 at 12:18 PM

Subject: 51 Vehicle Damage from Hail Storm

To: Risk, DAS <das.risk@iowa.gov>, vehicledamage <vehicledamage@dps.state.ia.us>

Cc: Johnson Kevin <kjohnson@dps.state.ia.us>, Bardsley Jason <bardsley@dps.state.ia.us>, Schweitzberger Chad <schweitz@dps.state.ia.us>

Attached is information concerning Trp. Brinker's #51 patrol car damage from the hail storm that travelled through District 3 on 4/17/25.

Sgt. Nate Elwood ★305★

Iowa State Patrol | District 3

Iowa Department of Public Safety

2025 Hunt Ave | Council Bluffs, Iowa 51503

Office: 712-328-8001

elwood@dps.state.ia.us

<https://dps.iowa.gov/>

<https://dpscareers.com/>



NOTICE This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

6 attachments



Photo 1.jpeg
3495K




Photo 2.jpeg
2919K



Photo 3.jpeg
3238K



Trp. Brinker - Damage Memorandum 04.17.25.doc

41K



Trp. Brinker - Damage Report 04.17.25.doc

97K



51 Hail.pdf

1342K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us, DAS.risk@iowa.gov, Area Captain & Post #3 Supervisors

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

*****Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!**

STATE VEHICLE: (Mark if Act of Nature ☒) CASE #: 2025009732

Date: <small>(Month/Day/Year)</small>	4/17/25	Time: <small>(Time plus a.m./p.m.)</small>	19:30 p.m.
Vehicle Plate #:	294PMM	Vehicle Mileage:	12,689
Vehicle Description: <small>(Yr/Make/Model/ & Vin#)</small>	2023 Chevy Tahoe 1GNSKLED2PR288956		
Assigned To:	Trp Brinker	Badge #	51
Driven By:	Trp Brinker	Badge #	51
Driver's Lic #:	912AA3854	Damage:	\$3,295.75
Vehicle Towed: <small>(Yes / No)</small>	No	Towed By:	
Towed To:		Towing Cost:	\$0
Seat Belt: <small>(Yes / No)</small>	Yes	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Unmarked
Injured/Injuries:	N/A		
Occupants: <small>(Other than driver)</small>	N/A		

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:	None		
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt:	(Yes/No)	Yes	

OTHER INFORMATION:

Witnesses:	
Accident Location: (Street/Hwy)	I-80 at the 17MM
County:	Pottawattamie
Weather/Road Conditions:	Severe Storms
<p>Narrative: On 4/17/2024 a severe weather event travelled through District 3. This event produced large hail, severe winds, and tornadic activity. Troopers Brinker #51, Hansen #469, and Hofer #346 sustained damage to their patrol vehicles as a result of the storm.</p>	
Property Damage other than Vehicles:	
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	

Investigating Officer:	Sgt. Elwood #305
------------------------	------------------

VEHICLE #3:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		



MEMORANDUM

TO: Supervision
FROM: Trp. Brinker
DATE: 17:36
SUBJECT: Vehicle Damage

Supervision,

On April 17th, 2025, at approximately 7:30 PM, I was patrolling on Interstate 80 near Underwood, Iowa. I got caught in a storm that involved large hail and attempted to pull under an overhang at a gas station. Today I washed my car and inspected for damage. I observed a handful of minor dents on my hood, and one larger dent with a few small dents on the roof of my patrol vehicle.

Mileage: 12,694

All Makes Collision Center
524 23rd Ave Council Bluffs, IA 51501
Phone: (712) 256-3195

*** PRELIMINARY ESTIMATE ***

04/21/2025 11:55 AM

Owner

Owner: state of iowa

Control Information

Loss Date: 11:54
File # : 51

Loss Type:
Accounting # :

Inspection

Inspection Date: 04/21/2025 11:59 AM

Inspection Type:

Assigned Date/Time: 11:54 AM
First Contact Date/Time: 11:54 AM
Second Contact Date/Time: 11:54 AM

Received Date/Time: 11:54 AM
Appointment Date/Time: 11:54 AM

Appraiser Name: Kortnie Getzschman

Appraiser License #2 :

Repairer

Repairer: ALL MAKES COLLISION
Address: 524 23rd ave

Contact: KARL GETZSCHMAN
Work/Day: (712)256-3195
Cell: (712)355-0860
Work/Day:

City State Zip: COUNCIL BLUFFS, IA 51501
Email: KARL.AAAUTO@LIVE.COM

Repair Start Date/Time: 11:54 AM
Repair Complete Date/Time: 11:54 AM
Target Complete Date/Time: 11:54 AM

Vehicle Drop Off Date/Time: 11:54 AM
Vehicle Pick Up Date/Time: 11:54 AM
Days To Repair: 2

Vehicle

OEM Part Price Quote ID: ****

2023 Chevrolet Tahoe Commercial 4 DR Wagon
8cyl Gasoline 5.3
10 Speed Automatic

Lic Expire:
Veh Insp# :
Condition:
Ext. Refinish: Two-Stage

VIN: 1GNSKLED2PR288956
Mileage Type: Actual
Code: U7445A
Int. Refinish: Two-Stage

Options

1st Row LCD Monitor(s)
4-Wheel Drive
Alarm System
Auto Headlamp Control
Cargo Lamp
Color-Keyed Bumper(s)

2nd Row Head Airbags
AM/FM CD Player
Aluminum/Alloy Wheels
Auxiliary Audio Input
Cargo/Trunk Net
Cruise Control

3rd Row Head Airbags
Active Grille Shutter
Anti-Lock Brakes
Camper/Towing Package
Center Console
Daytime Running Lights

Digital Clock	Driver Information Sys	Dual Air Conditioning
Dual Airbags	Elect. Stability Control	Floor Mats
Full Size Spare Tire	Halogen Headlights	Head Airbags
Heated Power Mirrors	Heavy Duty Cooling	Hi-Flow Air Cleaner
In-Vehicle WiFi	Intermittent Wipers	Lighted Entry System
Locking Differential	MP3 Decoder	OnStar System
Power Brakes	Power Door Locks	Power Drivers Seat
Power Steering	Power Windows	Privacy Glass
Pwr Accessory Outlet(s)	Pwr Driver Lumbar Supp	Rain-Sensing W/S Wipers
Rear Liftgate	Rear View Camera	Rear Window Defroster
Rear Window Wiper/Washer	Reverse Sensing System	Side Airbags
Side Steps	Split Folding Rear Seat	Stability Cntrl Suspensn
Strg Wheel Radio Control	Theft Deterrent System	Third Seat (trucks)
Three Zone Climate Ctrl	Tinted Glass	Tire Pressure Monitor
Touch Screen Display	Tow Hooks	Traction Control System
Trailer Hitch	USB Audio Input(s)	Velour/Cloth Seats
Wireless Audio Streaming	Wireless Phone Connect	

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Front Body And Windshield										
1	SB	83		Panel,Hood Aluminum	Sublet Repair	\$560.00*	+25.00			SM
Roof										
2	SB	341		Panel,Roof	Sublet Repair	\$950.00*				SM
3	RI	1440		Roof Headliner R & I	R & I Assembly				3.9	SM
Front Doors										
4	SB	208		Door Shell,Front RT Aluminum	Sublet Repair	\$225.00*				SM
Rear Doors										
5	SB	288		Door Shell,Rear RT Aluminum	Sublet Repair	\$200.00*				SM
Quarter And Rocker Panel										
6	SB	201		Panel Assy,Body Side LT >> upper rail	Sublet Repair	\$225.00*				SM
7	SB	202		Panel Assy,Body Side RT >> glue pull	Sublet Repair	\$625.00*	+25.00			SM
7	Items									

Estimate Total & Entries

Labor	Rate	Replace	Repair Hrs	Total Hrs	
		Hrs			
Sheet Metal (SM)	\$55.00	3.9		3.9	\$214.50
Mech/Elec (ME)	\$55.00				
Frame (FR)	\$55.00				
Refinish (RF)	\$100.00				
Labor Total				3.9 Hours	\$214.50
Sublet Repairs					\$3,081.25
Gross Total					\$3,295.75

Net Total

\$3,295.75

Alternate Parts Y/00/00/00/00/00 Cumulative 00/00/00/00/00 Zip Code: 51501 Default
OEM Part Prices DT 04/21/2025 11:59 AM EstimateID 1343628322520702976 QuoteID ****
Rate Name Default

Audatex Estimating 8.2.530 ES 04/21/2025 12:04 PM REL 8.2.530 DT 03/01/2025
State Disclosure:Not Selected
© 2025 Audatex North America, LLC.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG= Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM= Replace PXN Reman/Reblt
UM= Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC= Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG= Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2025 Audatex North America, LLC.
AUDATEX is a trademark owned by Audatex North America, LLC. All rights reserved.