

**OFFICE OF AUDITOR OF STATE
STATE OF IOWA**

Rob Sand
Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

December 4, 2025

Kristi Onstot
Executive Council
L O C A L

Subject: Deer Damage to Vehicle #105571 on October 27, 2025
Department of Administrative Services
Claim dated November 13, 2025
AOS Claim ID: 4181

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$8,636.47, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA
Deputy Auditor of State

CC: Kyle Wear, Fleet Services CFO, Department of Administrative Services
Ryan Betts, Fleet Services Risk Program Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



KIM REYNOLDS, GOVERNOR
CHRIS COURNOYER, LT. GOVERNOR

ADAM STEEN, DIRECTOR

Date: November 13, 2025

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

| | |
|--------------------------|--|
| Vehicle / Event | #105571 / Deer |
| Event Date | October 27, 2025 |
| Summary | Vehicle 105571 - struck a deer (Claim # 323191) |
| Amount Requested | \$8,636.47 TOTAL |
| Supporting Documentation | 29C20 Email Notification, Accident Report, & Repair Estimate |

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

A handwritten signature in black ink, appearing to read "R. Betts".

Ryan Betts
DAS Fleet Risk Program Manager
ryan.betts1@iowa.gov
515-281-8008



Risk, DAS <das.risk@iowa.gov>

Fwd: Accident Report 10-27-25

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Oct 27, 2025 at 8:41 AM

To: Tammy Hollingsworth <tammy.hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 105071 struck a deer on 10/27/2025. I will forward all information as soon as it is received.

Veh# 105571

#4181

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

510 E 12th St, Des Moines, IA 50319

515-281-8008 office

das.risk@iowa.gov<https://das.iowa.gov>Department of
Administrative Services

Claim 32391

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

----- Forwarded message -----

From: Dornack, Michael [HHS] <michael.dornack@hhs.iowa.gov>

Date: Mon, Oct 27, 2025 at 8:29 AM

Subject: Accident Report 10-27-25

To: DAS.Risk@iowa.gov <DAS.Risk@iowa.gov>

To whom it may concern,

Attached is an accident report from a CCUSO vehicle 105071 hitting a deer just east of Cherokee. The staff report the deer bolted out onto the road and they were unable to avoid the collision. No injuries to staff or patient in this collision.

Michael Dornack
Treatment Program Supervisor
Civil Commitment for Sexual Offenders
State-Operated Specialty Care Division
Department Of Health and Human Services
1251 West Cedar Loop Cherokee, Iowa 51012
712-225-6943 Ext. 2781
712-225-1576 fax
michael.dornack@hhs.iowa.gov

CONFIDENTIALITY NOTICE: This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity whom they are addressed. If you are not the intended recipient or the person responsible for the delivering of the email to the intended recipient, be advised that you have received this email in error. Any use, dissemination, forwarding, printing, or copying of this email is strictly prohibited. If you have received this email in error, please notify the sender immediately.

 **Accident Report 10-27-25.pdf**
229K



Department of Administrative Services
DAS Fleet Services- Risk Management
109 SE 13th St
Des Moines, IA 50319

Vehicle Accident Report Form

- Render aid or assistance to the injured (per Iowa Code 321.262).
- The State of Iowa is self-insured. Refer to the insurance card and accident report procedures online or in your glove box packet. If the accident involves another party, exchange information with the driver or property owner. Do not admit fault or attempt to settle your claim.
- Call local law enforcement, if a fatality, injury or property damage has occurred, and obtain a police report. On the Capitol complex, call Iowa State Patrol, Post 16 at 515-281-5608.
- Within the first 24 hours, report accident or damage to DAS Fleet Services (515-281-3162 or DAS.Risk@iowa.gov), your agency fleet contact, and supervisor. Damage caused by an act of nature or unavoidable cause MUST be reported to DAS Fleet Services within 24 hours of the incident to qualify for contingent fund use (per Iowa Code 29C.20).
- For an estimate, locate the nearest contracted auto body repair shop in the Contracted Service Providers map. A contracted auto body shop within 30 miles should be used if available.
- If towing is necessary, contact DAS Fleet Services (515-281-3162) for assistance. After hours, call National Automobile Club (NAC) FleetRescue* (866-329-3471) or local law enforcement.
- Within 72 hours, print and submit a completed Accident Report Form, including a cost estimate from the auto body shop to DAS.Risk@iowa.gov.
- Any accident in the State of Iowa that causes death, personal injury, or total property damage of \$1,500 or more must be reported on an Iowa Accident Report Form UNLESS the accident is investigated by a law enforcement agency and a report is filed. Failure to return an accident report form within 72 hours may result in suspension of driving privileges.

Vehicle Accident Report

Time and location of accident

| | | | | | |
|-----------------------------|--------------|-------|------|-----------------|---|
| Accident Date (Mo/Day/Year) | 10 - 27 - 25 | Time | 0608 | No. of Vehicles | 4 |
| County | Cherokee | State | IA | | |

Vehicle 1 (State vehicle)

| | | | | |
|----------------------------|-------------------|--|------------|--|
| Driver's Name | | Work Street Address | | |
| Kenneth Wade Stevens | | 1251 W Cedar Loop | | |
| Driver's License No./State | | City, State, Zip | | |
| 706 YY9443 IA | | Cherokee IA 51012 | | |
| Date of Birth | Department | Work Phone | Home Phone | |
| 02-13-1977 | (CUZO PS) | 712-225-6943 | | |
| License Plate No. | VIN | Year, Make, Model 2023 Ford Explorer | | |
| 105571 IA | 1FMSK8BB1PGA18469 | | | |
| Estimate (\$) of Damage | | Description of Damage | | |
| \$1500 ? | | Front Right corner bumper + head light. Hit a deer | | |

Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

| | | | |
|----------------------------|------------|------------------|-------------------|
| Driver's Name | | Street Address | |
| | | | |
| Driver's License No./State | | City, State, Zip | |
| | | | |
| Date of Birth | Work Phone | Home Phone | License Plate No. |
| | | | |
| Description of Damage | | | |
| | | | |

Property Damage other than vehicle (fence, utility pole, etc)


| | |
|---|---------------------------------|
| Owner's Name, Address and Phone | Description of Property Damaged |
| State of Iowa DAS | front Right corner |
| Injured Persons (attach additional sheets if necessary) | |
| Vehicle No. 1/ Name and Address | Describe Injuries |
| | |
| Vehicle No. 2/ Name and Address | Describe Injuries |
| | |
| Witness | |
| Name | Address/Phone |
| | |
| Name | Address/Phone |
| | |

Accident Diagram

Complete diagram below, include a description of what happened.

Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers.

Use number 1 to indicate the State vehicle.



Accident Information Exchange Sheet

Other Vehicle Information

| | |
|-------------------------------------|--|
| Driver's Name | |
| Street Address | |
| Driver Phone | |
| Driver's License No./State | |
| Vehicle Plate No. | |
| Vehicle year, make, model | |
| VIN | |
| Insurance Company Name | |
| Policy No. | |
| Agent name | |
| Agent phone | |
| Owner's Name/Address (if different) | |

Submit this information along with the accident report to DAS Fleet Service within 72 hours of the accident.

Complete the next section, tear at the dotted line and give to the other party involved.

State Vehicle Insurance Information

| | |
|----------------------------|----------------------|
| Driver's Name | Kenneth Wade Stevens |
| Driver's License No./State | 706449443 IA |
| Vehicle Plate No. | 105571 IA |
| Vehicle year, make, model | 2023 Ford Explorer |
| VIN | 1FMSK8BB1PGA18469 |

The State of Iowa is self-insured.
 If you have any questions regarding an accident, please contact
 DAS Fleet Services at 515-281-3162 or DAS.Risk@iowa.gov



CHEROKEE COLLISION CENTER

Your Complete Auto Repair Center
111 INDIAN STREET, CHEROKEE, IA 51012
Phone: (712) 225-3877
FAX: (712) 225-3878

Workfile ID: 0b420f58
Federal ID: 42-1468487
Resale Number: 1-18-006356

Preliminary Estimate

Customer: State Of Iowa

Written By: Terri Weaver

Insured: State Of Iowa Policy #: Claim #:
Type of Loss: Date of Loss: Days to Repair: 0
Point of Impact:

Owner:

State Of Iowa
Dept. of Administrative Services
Fleet & Mail Div 301 E. 7th St.
DesMoines, IA 50319-0250
(515) 418-5776 Cell
(515) 630-5238 Business

Inspection Location:

CHEROKEE COLLISION CENTER
111 INDIAN STREET
CHEROKEE, IA 51012
Repair Facility
(712) 225-3877 Business

Insurance Company:

VEHICLE

2023 FORD Explorer 4WD 4D UTV 6-3.3L Flex Fuel Gasoline Direct Injection

| | | | |
|------------------------|------------------|--------------|--------------|
| VIN: 1FMSK8BB1PGA18469 | Interior Color: | Mileage In: | Vehicle Out: |
| License: 105571 | Exterior Color: | Mileage Out: | |
| State: IA | Production Date: | Condition: | Job #: |

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Privacy Glass
Console/Storage
Overhead Console

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Message Center

Steering Wheel Touch Controls

Rear Window Wiper

Telescopic Wheel

Climate Control

Dual Air Condition

Backup Camera

Parking Sensors

Remote Starter

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

Satellite Radio

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control

Stability Control

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

Xenon or L.E.D. Headlamps

Blind Spot Detection

Lane Departure Warning

SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

3rd Row Seat

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Rear Spoiler

California Emissions

TRUCK

Power Trunk/Liftgate

Preliminary Estimate

Customer: State Of Iowa

2023 FORD Explorer 4WD 4D UTV 6-3.3L Flex Fuel Gasoline Direct Injection

| Line | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint |
|------|-----------------------------|--|-----------------|-----|-------------------|-------|-------|
| 1 | # | OEM Procedures Note: Pre and Post-Diagnostic Scanning During a Collision Repair Required Battery Disconnect and Connect - General Procedures - Battery, Mounting and Cables Power Door Window Initialization - General Procedures - Glass, Frames and Mechanisms Corrosion Prevention - General Procedures - Body Repairs - General Information Paintwork Defects and Damage - General Procedures - Paint - General Information Body and Frame - Description and Operation - Body Repairs - Vehicle Specific Information and Tolerance Checks Use of Non-OEM and Salvage Parts on Ford Motor Company Vehicles Front Bumper Cover - Removal and Installation - Bumpers Front Bumper Cover - Disassembly and Assembly - Bumpers- 1xID3 Headlamp Assembly - Removal and Installation - Exterior Lighting Fender Splash Shield - Removal and Installation - Front End Body Panels Front Fender Moulding - Removal and Installation - Exterior Trim and Ornamentation | | 1 | | | |
| 2 | PAINT IDENTIFICATION | | | | | | |
| 3 | # | Repl Clean & Degrease Vehicle for Repairs Analysis | | 1 | 8.00 | 0.5 | |
| 4 | # | Repl Buff for Color Match Reading | | 1 | 2.00 | 0.2 | |
| 5 | # | Refn Color Mix, Match and Spray out card Exterior | | | | | 1.0 |
| 6 | # | Rpr Set up Stands/Jigs for Componet(s) in Booth | | | | 0.8 | |
| 7 | # | Repl STAT gun application | | 1 | | 0.5 | |
| 8 | FRONT BUMPER | | | | | | |
| 9 | | O/H front bumper | | | | 4.5 | |
| 10 | | Repl Bumper cover w/o auto park | LB5Z17D957SCPTM | 1 | 615.14 | Incl. | 2.4 |
| 11 | | Add for Clear Coat | | | | | 1.0 |
| 12 | # | Repl Raw Plastic Paint Prep Kit | | 1 | 99.00 | 0.5 | |
| 13 | # | Repl Flexible Additive (per fascia) | | 1 | 8.00 | 0.1 | |
| 14 | | Repl RT Bracket | LB5Z17C947A | 1 | 41.73 | Incl. | |
| 15 | | Repl LT Bracket rivet | W702852S300 | 4 | 5.12 | | |
| 16 | | Repl RT Bracket rivet | W702852S300 | 4 | 5.12 | | |
| 17 | | Repl License bracket rivet | W704342S300 | 3 | 30.00 | | |
| 18 | GRILLE | | | | | | |
| 19 | | Repl Grille BASE | LB5Z8200AB | 1 | 917.68 | Incl. | |
| 20 | FRONT LAMPS | | | | | | |
| 21 | | Repl RT Headlamp assy w/o adaptive headlamps level 2 headlamps | MB5Z13008AY | 1 | 2,395.18 | 0.5 | |
| 22 | | Aim headlamps | | | | 0.5 | |
| 23 | FENDER | | | | | | |
| 24 | * | Rpr RT Fender w/o HEV | | | | 4.0 | 2.0 |
| 25 | | Add for Clear Coat | | | | | 0.8 |
| 26 | # | Rpr Feather Prime and Block (.2 per | | | | | 0.8 |

Preliminary Estimate

Customer: State Of Iowa

2023 FORD Explorer 4WD 4D UTV 6-3.3L Flex Fuel Gasoline Direct Injection

| | | | | | | |
|----|--|---|---------------|-------------|-----------------|------------|
| | | | repair hour) | | | |
| 27 | Repl | RT Wheel flare w/o auto park | | LB5Z16038AC | 1 | 280.75 |
| 28 | R&I | LT Wheel flare w/o auto park | | | | 0.3 |
| 29 | R&I | RT Fender liner | | | | 0.4 |
| 30 | R&I | LT Fender liner | | | | 0.4 |
| 31 | ELECTRICAL | | | | | |
| 32 | # | Disconnect Battery | | | 1 | 0.2 M |
| 33 | # | Rpr Memory Funstion Reset | | | | 0.2 |
| 34 | # | Connect Battery | | | 1 | 0.1 M |
| 35 | WHEELS | | | | | |
| 36 | # | Rpr lift and support vehicle | | | | 0.3 |
| 37 | R&I | LT/Front R&I wheel | | | m | 0.1 M |
| 38 | R&I | RT/Front R&I wheel | | | m | 0.1 M |
| 39 | RESTRAINT SYSTEMS | | | | | |
| 40 | # | Rpr Dis Arm Saftey Restraint System | | | | 0.4 M |
| 41 | # | Rpr Re-Arm and Connect Saftey Restraint Systems | | | | 0.1 M |
| 42 | FRONT DOOR | | | | | |
| 43 | * | Blnd RT Door shell | | | | <u>1.2</u> |
| 44 | | R&I RT Belt molding | | | | 0.3 |
| 45 | | R&I RT Mirror outside Base | | | | 0.3 |
| 46 | | R&I RT Handle, outside BASE | | | | 0.4 |
| 47 | | R&I RT R&I trim panel | | | | 0.5 |
| 48 | Repl | RT Lower molding black BASE, INTERCEPTOR | LB5Z7820878AC | 1 | 169.25 | 0.4 |
| | Note: PARTS: Part cannot be reused/reinstalled. | | | | | |
| 49 | VEHICLE DIAGNOSTICS | | | | | |
| 50 | # | Rpr Battery support during PRE/POST scans | | | | 0.2 M |
| 51 | * | Subl Pre-repair scan | | 1 | <u>120.00</u> m | |
| 52 | * | Subl Post-repair scan | | 1 | <u>120.00</u> m | |
| 53 | # | Rpr Driver window initialization | | | | 0.2 M |
| | Note: 501-11 Glass, Frames and Mechanisms2022 - 2024 Explorer, Police Interceptor General ProceduresProcedure revision date: 04/5/2022 | | | | | |
| 54 | MISCELLANEOUS OPERATIONS | | | | | |
| 55 | # | Repl Hazardous Waste Charge | | 1 | 10.00 T | |
| 56 | # | Repl Corrosion Protection | | 1 | 10.00 T | 0.3 |
| 57 | # | Repl Job cost materials | | 1 | 250.00 | |
| 58 | # | Rpr Pre Measure Body Panel Gaps | | | | 0.5 |
| 59 | # | Rpr Cross measure under hood | | | | 0.5 |
| 60 | # | Repl Cover Car for Interior | | 1 | 5.00 | 0.2 |
| 61 | # | Repl Car Cover for Repair | | 1 | 5.00 T | 0.2 |
| 62 | # | Repl Car Cover For Primer | | 1 | 5.00 | 0.2 |
| 63 | # | Car Cover for Refinish | | 1 | 10.00 | 0.3 |
| 64 | # | Rpr De Nib, Wet Sand and Buff/Polish (.5 per panel) | | | | 1.0 |
| 65 | # | Repl Wash Vehicle after De Nib/Wet | | 1 | 2.00 T | 0.2 |

Preliminary Estimate

Customer: State Of Iowa

2023 FORD Explorer 4WD 4D UTV 6-3.3L Flex Fuel Gasoline Direct Injection

| | | | | | | |
|----|---|------|--|---|-----------------|-------------|
| | | Sand | | | | |
| 66 | # | Repl | Wash Vehicle after BUFF/Polish | 1 | 2.00 | 0.2 |
| 67 | # | Repl | Road test | 1 | 3.50 | 0.5 |
| 68 | # | Rpr | check wheel torque | | | 0.2 |
| 69 | # | Repl | Final Wash, Detail and Vacuum of Vehicle | 1 | 10.00 | 2.0 |
| | | | SUBTOTALS | | 5,129.47 | 22.6 |
| | | | | | | 10.2 |

ESTIMATE TOTALS

| Category | Basis | Rate | Cost \$ |
|----------------------|----------|-----------------|-----------------|
| Parts | | | 5,102.47 |
| Body Labor | 21.2 hrs | @ \$ 85.00 /hr | 1,802.00 |
| Paint Labor | 10.2 hrs | @ \$ 150.00 /hr | 1,530.00 |
| Mechanical Labor | 1.4 hrs | @ \$ 125.00 /hr | 175.00 |
| Miscellaneous | | | 27.00 |
| Subtotal | | | 8,636.47 |
| Grand Total | | | 8,636.47 |
| Deductible | | | 0.00 |
| CUSTOMER PAY | | | 0.00 |
| INSURANCE PAY | | | 8,636.47 |

Cherokee Collision Center hereby provides a Limited Warranty on repairs preformed by this shop. This Limited Warrenty is valid only for as long as you own the vehicle stated herein, and is for the person to whom this Limited Warranty is granted and whose name appears herin and on the original work order. A three year Limited Warranty on paint against fading and peeling. A one year Limited Warranty on metalwork,excluding any rust repairs, and workmanship. All parts are OEM,original equipment manufacturer, certified, so therefore have a Limited Warranty from the manufacturer.

Customer: State Of Iowa

2023 FORD Explorer 4WD 4D UTV 6-3.3L Flex Fuel Gasoline Direct Injection

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR2MF20, CCC Data Date 11/10/2025, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category.

X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category.

M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Align.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel.

CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.

D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part.

O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet.

UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.


CHEROKEE COLLISION CENTER

111 INDIAN STREET, CHEROKEE, IA 51012

Phone: (712) 225-3877, Fax: (712) 225-3878

Image Report

| | | | | | |
|------------|---------------|---------------|----------------|-------------------|------------------|
| Owner: | State Of Iowa | Insurance: | Estimator: | Terri Weaver | Vehicle Out: |
| RO Number: | | Claim Number: | | | |
| Year: | 2023 | Color: | License Plate: | 105571 | Production Date: |
| Make: | FORD | Body Style: | State: | IA | Mileage In: |
| Model: | Explorer 4WD | Engine: | VIN: | 1FMSK8BB1PGA18469 | Condition: |



10/27/2025

Comments:



10/27/2025

Comments:



10/27/2025

Comments:



10/27/2025

Comments:



10/27/2025

Comments:



10/27/2025

Comments:

CHEROKEE COLLISION CENTER

111 INDIAN STREET, CHEROKEE, IA 51012

Phone: (712) 225-3877, Fax: (712) 225-3878

Image Report

| | | | | | |
|------------|---------------|---------------|----------------|-------------------|------------------|
| Owner: | State Of Iowa | Insurance: | Estimator: | Terri Weaver | Vehicle Out: |
| RO Number: | | Claim Number: | | | |
| Year: | 2023 | Color: | License Plate: | 105571 | Production Date: |
| Make: | FORD | Body Style: | State: | IA | Mileage In: |
| Model: | Explorer 4WD | Engine: | VIN: | 1FMSK8BB1PGA18469 | Condition: |



10/27/2025

Comments:



10/27/2025

Comments:



10/27/2025

Comments:



10/27/2025

Comments:



10/27/2025

Comments:



10/27/2025

Comments:

CHEROKEE COLLISION CENTER

111 INDIAN STREET, CHEROKEE, IA 51012

Phone: (712) 225-3877, Fax: (712) 225-3878

Image Report

| | | | | | |
|------------|---------------|---------------|----------------|-------------------|------------------|
| Owner: | State Of Iowa | Insurance: | Estimator: | Terri Weaver | Vehicle Out: |
| RO Number: | | Claim Number: | | | |
| Year: | 2023 | Color: | License Plate: | 105571 | Production Date: |
| Make: | FORD | Body Style: | State: | IA | Mileage In: |
| Model: | Explorer 4WD | Engine: | VIN: | 1FMSK8BB1PGA18469 | Condition: |



10/27/2025

Comments:



10/27/2025

Comments:



10/27/2025

Comments:



10/27/2025

Comments:



10/27/2025

Comments:



10/27/2025

Comments: