

MEMBERS OF COUNCIL

HON. KIM REYNOLDS
GOVERNOR

HON. PAUL D. PATE
SECRETARY OF STATE

HON. ROB SAND
AUDITOR OF STATE

HON. ROBY SMITH
TREASURER OF STATE

HON. MIKE NAIG
SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING
DES MOINES, IOWA 50319
PHONE: 515 281-5368
FAX: 515 281-7562

July 20, 2026

Accounting Department
Office of the Treasurer
Lucas Building
321 E 12th Street
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$11,471.80, subject to an audit of actual invoices. On April 23, 2026, Vehicle #1728 was damaged by hail. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Kristi Onstot

Kristi Onstot
Executive Secretary

cc: Kyle Wear, DAS Fleet Chief Financial Officer
Ryan Betts, Fleet Services Risk Program Manager
Matt Bender, Department of Management
Heather Hackbarth, Department of Management

AOS Claim # 4345
TOS Job # _____



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

State Capitol Building
Des Moines, Iowa 50319-0006
Telephone (515) 281-5834

Rob Sand
Auditor of State

July 14, 2026

Kristi Onstot
Executive Council

Subject: Hail Damage to Vehicle #1728 on April 23, 2026
Department of Administrative Services
Claim dated May 12, 2026
AOS Claim ID: 4345

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above-mentioned damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$11,471.80, subject to an audit of actual invoices.

Sincerely,

A handwritten signature in black ink, appearing to read "Brian R. Brustkern".

Brian R. Brustkern, CPA
Deputy Auditor of State

cc: Kyle Wear, Fleet Services CFO, Department of Administrative Services
Ryan Betts, Fleet Services Risk Program Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



Department of
Administrative Services

KIM REYNOLDS, GOVERNOR
CHRIS COURNOYER, LT. GOVERNOR

MARK CAMPBELL, DIRECTOR

Date: May 12, 2026

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#1728 / Hail
Event Date	April 23, 2026
Summary	Vehicle 1728 - sustained hail damage (Claim TL2619)
Amount Requested	\$11,471.80 Total
Supporting Documentation	29C20 Email Notification, Accident Report, & Repair Estimate

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Ryan Betts
DAS Fleet Risk Program Manager
ryan.betts1@iowa.gov
515-281-8008



Risk, DAS <das.risk@iowa.gov>

Fwd: Accident Report - Hail damage

1 message

Risk, DAS <das.risk@iowa.gov>

Fri, Apr 24, 2026 at 1:16 PM

To: Tammy Hollingsworth <tammy.hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as the initial 24 hour notification for an AON claim. Vehicle 1728 sustained hail damage on 4/23/2026. I will forward all information as soon as it is received.

4345

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

510 E 12th St, Des Moines, IA 50319

515-281-8008 office

das.risk@iowa.gov<https://das.iowa.gov>**Department of
Administrative Services**

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

----- Forwarded message -----

From: **Regennitter, Peyton** <Peyton.Regennitter@iowaagriculture.gov>

Date: Fri, Apr 24, 2026 at 9:38 AM

Subject: Accident Report - Hail damage


To: **DAS.Risk@iowa.gov** <DAS.Risk@iowa.gov>, Potter, Lisa <Lisa.Potter@iowaagriculture.gov>

State car 1728 was in Holstein, IA getting a routine oil change on 4/23/26 when a storm went through town causing some minor hail damage. I attached one picture of a dent on the hood, but with how small the dents are and the glare of the sun it is difficult to get any more pictures of the roof and trunk. I will call Cherokee collision today and get an appointment scheduled to get a quote on the damage.

Thank you,

Peyton Regennitter

2 attachments



IMG_0021.jpg
3443K



AccidentReportForm (1).pdf
219K



Department of Administrative Services

*Empowering People
Collaboration
Customer Service*

Department of Administrative Services
DAS Fleet Services- Risk Management
109 SE 13th St
Des Moines, IA 50319

Vehicle Accident Report Form

- Render aid or assistance to the injured ([per Iowa Code 321.262](#)).
- The State of Iowa is self-insured. Refer to the insurance card and accident report procedures online or in your glove box packet. If the accident involves another party, exchange information with the driver or property owner. Do not admit fault or attempt to settle your claim.
- Call local law enforcement, if a fatality, injury or property damage has occurred, and obtain a police report. On the Capitol complex, call Iowa State Patrol, Post 16 at 515-281-5608.
- Within the first 24 hours, report accident or damage to DAS Fleet Services (515-281-3162 or DAS.Risk@iowa.gov), your agency fleet contact, and supervisor. Damage caused by an act of nature or unavoidable cause MUST be reported to DAS Fleet Services within 24 hours of the incident to qualify for contingent fund use ([per Iowa Code 29C.20](#)).
- For an estimate, locate the nearest contracted auto body repair shop in the Contracted Service Providers map. A contracted auto body shop within 30 miles should be used if available.
- If towing is necessary, contact DAS Fleet Services (515-281-3162) for assistance. After hours, call National Automobile Club (NAC) FleetRescue* (866-329-3471) or local law enforcement.
- Within 72 hours, print and submit a completed Accident Report Form, including a cost estimate from the auto body shop to DAS.Risk@iowa.gov.
- Any accident in the State of Iowa that causes death, personal injury, or total property damage of \$1,500 or more must be reported on an Iowa Accident Report Form UNLESS the accident is investigated by a law enforcement agency and a report is filed. Failure to return an accident report form within 72 hours may result in suspension of driving privileges.

Vehicle Accident Report

Time and location of accident

Accident Date (Mo/Day/Year)	Time	No. of Vehicles
4/23/2026	4:00PM	1
County	State	
Ida	Iowa	


Vehicle 1 (State vehicle)

Driver's Name		Work Street Address	
Peyton Regennitter		1812 Story Ave, Correctionville, IA 51016	
Driver's License No./State		City, State, Zip	
552AG4210/ Iowa		1812 Story Ave, Correctionville, IA 51016	
Date of Birth	Department	Work Phone	Home Phone
09/21/1997	Meat and Poultry	515-499-2014	712-369-9862
License Plate No.	VIN	Year, Make, Model	
1728	1G1ZC5ST4PF124176	2023, Chevy, Malibu	
Estimate (\$) of Damage		Description of Damage	
		Hail damage on hood, roof and trunk. No broken lights or glass.	

Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

Driver's Name		Street Address	
Driver's License No./State		City, State, Zip	
Date of Birth	Work Phone	Home Phone	License Plate No.
Description of Damage			

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
Vehicle No. 2/ Name and Address	Describe Injuries
Witness	
Name	Address/Phone
Name	Address/Phone

Accident Diagram
Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers. Use number 1 to indicate the State vehicle.


Accident Information Exchange Sheet

Other Vehicle information

Driver's Name

Street Address

Driver Phone

Driver's License No./State

Vehicle Plate No.

Vehicle year, make, model

VIN

Insurance Company Name

Policy No.

Agent name

Agent phone

Owner's Name/Address (if different)

Submit this information along with the accident report to DAS Fleet Service within 72 hours of the accident.

Complete the next section, tear at the dotted line and give to the other party involved.

State Vehicle Insurance Information

Driver's Name

Driver's License No./State

Vehicle Plate No.

Vehicle year, make, model

VIN

The State of Iowa is self-insured.
If you have any questions regarding an accident, please contact
DAS Fleet Services at 515-281-3162 of DAS.Risk@iowa.gov



CHEROKEE COLLISION CENTER

Your Complete Auto Repair Center
111 INDIAN STREET, CHEROKEE, IA 51012
Phone: (712) 225-3877
FAX: (712) 225-3878

Workfile ID: a111c203
Federal ID: 42-1468487
Resale Number: 1-18-006356

Preliminary Estimate

Customer: State of Iowa

Written By: Terri Weaver

Insured: State of Iowa
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
State of Iowa

Inspection Location:
CHEROKEE COLLISION CENTER
111 INDIAN STREET
CHEROKEE, IA 51012
Repair Facility
(712) 225-3877 Business

Insurance Company:

VEHICLE

2023 CHEV Malibu LS (Fleet) 4D SED 4-1.5L Turbocharged Gasoline Direct Injection

VIN: 1G1ZC5ST4PF124176
License:
State: IA

Interior Color:
Exterior Color:
Production Date:

Mileage In:
Mileage Out:
Condition:

Vehicle Out:
Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors

DECOR

Dual Mirrors

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Backup Camera

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Communications System

Hands Free Device

Lane Departure Warning

SEATS

Cloth Seats

Bucket Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control

Stability Control

Preliminary Estimate

Customer: State of Iowa

2023 CHEV Malibu LS (Fleet) 4D SED 4-1.5L Turbocharged Gasoline Direct Injection

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	PAINT IDENTIFICATION						
2	#	Repl	Clean & Degrease Vehicle for PDR	1	8.00	0.5	
3	#	Refn	Color Mix, Match and Spray out card Exterior				1.0
4	#	Rpr	Set up Stands/Jigs for Componet(s) in Booth			0.8	
5	FRONT BUMPER & GRILLE						
6		R&I	R&I bumper cover			2.1	
7	FRONT LAMPS						
8		R&I	RT Headlamp assy			0.3	
9		R&I	LT Headlamp assy			0.3	
10	HOOD						
11	**	Repl	A/M CAPA Hood	84273742	1	792.00	2.8
12			Add for Clear Coat				1.1
13			Add for Underside(Complete)				1.4
14			Add for Clear Coat				0.3
15	FENDER						
16	*	PDR	RT Fender	1	<u>125.00</u>	T	
			Note: PDR 3 half				
17	*	PDR	LT Fender	1	<u>175.00</u>	T	
			Note: PDR 7 half				
18	*	Blnd	RT Fender				<u>1.0</u>
19	*	Blnd	LT Fender				<u>1.0</u>
20		R&I	RT Fender liner w/o ext fuel pkg			0.4	
21		R&I	LT Fender liner w/o ext fuel pkg			0.4	
22	ELECTRICAL						
23	#		Disconnect Battery	1		0.2	M
24	#		Connect Battery	1		0.1	M
25	#	Rpr	Memory Functon Reset			0.2	
26	RESTRAINT SYSTEMS						
27	#	Rpr	Dis Arm Saftey Restraint System			0.4	M
28		R&I	RT Head air bag			m	0.9
29		R&I	LT Head air bag			m	0.9
30		R&I	RT Belt & retractor black			m	0.5
31		R&I	LT Belt & retractor black			m	0.5
32		R&I	RT Outer belt assy black				0.5
33		R&I	LT Outer belt assy black				0.5
34	#	Rpr	Re-Arm and Connect Saftey Restraint Systems			0.1	M
35		Repl	Air bag system diagnosis	1		m	0.5
36	ROOF						
37	*	PDR	Roof panel	1	<u>1,550.00</u>	T	
			Note: PDR 200 nickel, 150 quarter, 100 half				
38		R&I	R&I headliner			2.9	

Preliminary Estimate

Customer: State of Iowa

2023 CHEV Malibu LS (Fleet) 4D SED 4-1.5L Turbocharged Gasoline Direct Injection

39	#	Repl	PDR Roof Underside restoration	1	164.80	0.5
			Note: flex foam on support rails, etch primer and masking			
40	PILLARS, ROCKER & FLOOR					
41	*	PDR	RT Uniside assy +25%	1	<u>593.75</u>	T s
			Note: PDR 5 nickel, 20 quarter, 15 half			
42	*	PDR	LT Uniside assy +25%	1	<u>656.25</u>	T s
			Note: PDR 10 nickel, 25 quarter, 15 half			
43	FRONT DOOR					
44	*	PDR	LT Door shell	1	<u>125.00</u>	T
			Note: PDR 1 half			
45	*	PDR	RT Door shell	1	<u>125.00</u>	T
			Note: PDR 2 half			
46		Repl	RT Belt molding	84205390	1	186.38 0.3
47		R&I	LT Belt molding			0.3
48		Repl	RT Reveal molding	84205398	1	164.95 0.4
49		Repl	LT Reveal molding	84205397	1	151.41 0.4
50		R&I	RT Applique			0.3
51		R&I	LT Applique			0.3
52		R&I	RT R&I mirror			0.3
53		R&I	LT R&I mirror			0.3
54		R&I	RT Door glass GM all			0.5
55		R&I	LT Door glass GM all			0.5
56		R&I	RT R&I trim panel			0.6
57		R&I	LT R&I trim panel			0.6
58		R&I	RT Upper trim			0.2
59		R&I	LT Upper trim			0.2
60	REAR DOOR					
61	*	PDR	RT Door shell	1	<u>125.00</u>	T
			Note: PDR 2 half			
62	*	PDR	LT Door shell	1	<u>125.00</u>	T
			Note: PDR 1 half			
63		Repl	RT Belt molding	84205386	1	142.35 0.3
64		Repl	LT Belt molding	84205385	1	178.57 0.3
65		R&I	RT Applique front			0.3
66		R&I	LT Applique front			0.3
67		R&I	RT Applique rear			0.3
68		R&I	LT Applique rear			0.3
69		Repl	RT Reveal molding	84205394	1	114.43 0.3
70		Repl	LT Reveal molding	84205393	1	117.31 0.3
71		R&I	RT R&I trim panel			0.5
72		R&I	LT R&I trim panel			0.5
73		R&I	RT Upper trim			0.1
74		R&I	LT Upper trim			0.1
75	QUARTER PANEL					
76	*	PDR	RT Quarter panel	1	<u>400.00</u>	T
			Note: PDR 5 nickel, 15 quarter, 15 half			

Preliminary Estimate

Customer: State of Iowa

2023 CHEV Malibu LS (Fleet) 4D SED 4-1.5L Turbocharged Gasoline Direct Injection

77	*	PDR	LT Quarter panel		1	475.00	T	
			Note: PDR 5 nickel, 20 quarter, 15 half					
78		R&I	RT Wheelhouse liner					0.4
79		R&I	LT Wheelhouse liner					0.4
80	TRUNK LID							
81	*	PDR	Trunk lid w/o spoiler		1	825.00	T	
			Note: PDR 25 nickel, 50 quarter, 50 half					
82		Repl	Nameplate "MALIBU" Silver	23362182	1	42.18		0.2
83	*	R&I	Emblem gold					0.2
84	#	Repl	clean and retape emblem		1	10.00		0.3
85	REAR LAMPS							
86		R&I	RT Tail lamp assy					0.4
87		R&I	LT Tail lamp assy					0.4
88	REAR BUMPER							
89		R&I	R&I bumper cover					1.8
90	VEHICLE DIAGNOSTICS							
91	#	Rpr	Battery support during PRE/POST scans					0.2 M
92	#	Repl	Pre-Repair Scan		1	120.00		
93	#	Repl	Post-Repair Scan		1	120.00		
94	MISCELLANEOUS OPERATIONS							
95	#	Repl	Cover Car for Interior		1	5.00		0.2
96	#	Repl	PDR Side panel corrosion restoration		8	101.92		0.3
97	#	Repl	Job cost materials		1			
SUBTOTALS						7,719.30	28.5	8.6

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				2,419.30
Body Labor	27.5 hrs	@	\$ 85.00 /hr	2,337.50
Paint Labor	8.6 hrs	@	\$ 150.00 /hr	1,290.00
Mechanical Labor	1.0 hrs	@	\$ 125.00 /hr	125.00
PDR				5,300.00
Subtotal				11,471.80
Grand Total				11,471.80
Deductible				0.00
CUSTOMER PAY				0.00
INSURANCE PAY				11,471.80

MyPriceLink Estimate ID / Quote ID:

1481731691746697216 / 152803136

Customer: State of Iowa

2023 CHEV Malibu LS (Fleet) 4D SED 4-1.5L Turbocharged Gasoline Direct Injection

Cherokee Collision Center hereby provides a Limited Warranty on repairs preformed by this shop. This Limited Warrenty is valid only for as long as you own the vehicle stated herein, and is for the person to whom this Limited Warranty is granted and whose name appears herin and on the original work order. A three year Limited Warranty on paint against fading and peeling. A one year Limited Warranty on metalwork,excluding any rust repairs, and workmanship. All parts are OEM,original equiptment manufacturer, certified, so therefore have a Limited Warranty from the manufacturer.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Customer: State of Iowa

2023 CHEV Malibu LS (Fleet) 4D SED 4-1.5L Turbocharged Gasoline Direct Injection

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR1CP16, CCC Data Date 05/08/2026, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: State of Iowa

2023 CHEV Malibu LS (Fleet) 4D SED 4-1.5L Turbocharged Gasoline Direct Injection

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
11	Keystone, Inc 8206 J STREET OMAHA NE 68127 (402) 553-0230	#GM1230441C A/M CAPA Hood Quote: 3458218044 Expires: 06/26/26	\$ 792.00