MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE

SEAL SEAL STATE OF 10

Executive Council of Jowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

March 3, 2025

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$4,130.74, subject to an audit of actual invoices. On January 10, 2025, Vehicle #105470 was damaged by a deer. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

(risti Onstot

Kristi Onstot

Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services

DAS Fleet Services, Risk

Matt Bender, Department of Management

Heather Hackbarth, Department of Management

OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

February 6, 2025

Kristi Onstot Executive Council L O C A L

Subject: Deer Damage to Vehicle #105470 on January 10, 2025

Department of Administrative Services

Claim dated January 10, 2025

AOS Claim ID: 3970

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$4,130.74, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA

Por R. Bress

Deputy Auditor of State

CC: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



Department of **Administrative Services**

KIM REYNOLDS, GOVERNOR CHRIS COURNOYER, LT. GOVERNOR

ADAM STEEN, DIRECTOR

Date: January 10, 2025

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#105470 / Animal
Event Date	January 10, 2025
Summary	Vehicle 105470 - struck a deer. (Claim # 297917)
Amount Requested	\$4,130.74 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, and Repair Estimate(s)

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Ryan Betts

DAS Fleet Services

ryan.betts1@iowa.gov

515-281-8008



Risk, DAS <das.risk@iowa.gov>

AON / 29C20 - Vehicle 105470 - 1/10/2025.

1 message

Risk, DAS <das.risk@iowa.gov>

Fri, Jan 10, 2025 at 9:35 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 105470 struck a deer on 1/10/2025. I will forward all information as soon as it is received.

This came in as a phone call only, no email, accident report, or estimate have been provided yet.

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

109 SE 13th St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov

https://das.iowa.gov



All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

State of Iowa - Department of Administrative Services, DAS Fleet - Risk Management

VFH	ICLE ACCIDENT REPORT
TIME AND LOCATION OF ACCIDENT	TOLL ACCIDENT REPORT
Accident Date (Mo/Day/Year) O1/10/2025 County F1046 State	f Week: No. of Vehicles
NO.1 (STATE VEHICLE) Driver's Name	
Driver's License No. / State 767473431 Date of Birth 10-22-1965 License Plate No. SR 289 Description of Damage: Bumper. Feeder door	Toyage LA
No. 2 (OTHER VEHICLE) If more than two w	ehicles - use additional forms
Driver's Name	Street Adress
Driver's License No. / State	City, State, Zip
Date of Birth Work Phone	Home Phone License Plate No.
VIN	Year, Make, Model
Owner's Name, Address (if Different)	Insurance Company Name / Agent's Name / Address and Phone
Description of Damage:	
PROPERITY DAMMAGE OTHER THAN WEHICLE (I Owner's Name, Address and Phone	Propety Damaged
INITUDEO OESCO	<u> </u>
INJURED PERSONS (Attach additional sheets in Vehicle no. 1 / Name and Address	necessary) Describe Injuries
/ehicle no. 2 / Name and Address	Describe Injuries
VITNESS : Jame	Address and Phone
ame	Address and Phone
	The state of the s

Description of Accident: Hit a deer traveling south into Rockford on 7.24 about 1/2 mile outside of town Complete Diagram Below. Use number 1 to indicate State vehicle. Rock ford IA main St Street or HWY T. 24 Echo Ave

Street or HWY



NORTH IOWA COLLISION CENTER INC.

Serving your car, light & heavy duty truck, heavy equipment & RV repair needs. 11201 265TH ST, CLEAR LAKE, IA 50428

Phone: (641) 421-8555 FAX: (641) 421-8558

Workfile ID: PartsShare: 86bd7e66 8kRTN8

Federal ID: State ID:

87-2591068 1-17-020011

Resale Number: Federal EPA:

1-17-020011 IAR000007856

Preliminary Estimate

Customer: State of Iowa - Iowa Lottery

Written By: Scott Larson

Insured:

State of Iowa - Iowa

Lottery

Policy #:

Claim #:

Type of Loss:

Point of Impact: 12 Front

Date of Loss:

Days to Repair: 0

Owner:

State of Iowa - Iowa Lottery

2900 - 4th Street SW

Mason City, IA 50401 (641) 424-6011 Cell

Inspection Location:

NORTH IOWA COLLISION CENTER INC.

11201 265TH ST

CLEAR LAKE, IA 50428

Repair Facility

(641) 421-8555 Business

Insurance Company:

VEHICLE

2021 CHRY Voyager LX FWD 4D VAN 6-3.6L Gasoline Sequential MPI Bright White Clearco

VIN:

2C4RC1CG2MR578089

Interior Color:

Black/Alloy/Black

9/2021

Mileage In:

Vehicle Out:

License: State:

Exterior Color:

Production Date:

Bright White Clearco

Mileage Out: Condition:

Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering

Power Brakes Power Windows

Power Locks

Power Mirrors

Heated Mirrors Power Driver Seat

DECOR

Dual Mirrors Privacy Glass Console/Storage Overhead Console

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control Rear Defogger

Keyless Entry

Message Center

Steering Wheel Touch Controls

Rear Window Wiper Telescopic Wheel

Climate Control **Dual Air Condition** Backup Camera

Parking Sensors

RADIO AM Radio FM Radio

Stereo Search/Seek

Auxiliary Audio Connection

Satellite Radio

SAFETY

Drivers Side Air Bag Passenger Air Bag

Anti-Lock Brakes (4) 4 Wheel Disc Brakes

Traction Control

Stability Control Front Side Impact Air Bags Head/Curtain Air Bags

Hands Free Device Blind Spot Detection **SEATS**

Cloth Seats

Reclining/Lounge Seats

3rd Row Seat Retractable Seats Captain Chairs (4)

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Rear Spoiler

California Emissions

Preliminary Estimate

Customer: State of Iowa - Iowa Lottery

2021 CHRY Voyager LX FWD 4D VAN 6-3.6L Gasoline Sequential MPI Bright White Clearco

Line		Ope		Part Number	Qty	Extended Price \$	Labor	Paint
1	#		Rental Formula 28.8 / 4 = 7		1	- 1100 φ		
2	#				_			
3	FRONT BUI	MPER & C	GRILLE					
4			O/H front bumper				3.9	
5	** <>	Repl	A/M CAPA Bumper cover	68312409AB	1	667.00	Incl.	2.2
6			Add for Clear Coat			007.00	TICI.	3.3
7		Refn	Tow eye cap					1.3
8			Add for Clear Coat					0.2
9		Repl	LT Side bracket	68229139AC	1	10.55	Incl.	0.1
10		R&I	License bracket		_	10.55	0.2	
11	#	R&I	License plate				0.2	
12		R&I	R&I upper grille				Incl.	
13	FRONT LAM	IPS					THEI.	
14		R&I	LT R&I headlamp assy				0.3	
15	RADIATOR	SUPPORT	г				0.3	
16		R&I	Sight shield				In al	
17	FENDER						Incl.	
18	**	Repl	A/M CAPA LT Fender w/o hybrid (HSS)	68372877AC	1	379.00	2.4	2.0
19			Overlap Major Non-Adj. Panel					
20			Add for Clear Coat					-0.2
21			Add for Edging					0.4
22		R&I	LT Fender liner				T1	0.5
23	PILLARS, RO	OCKER &	FLOOR				Incl.	
24		R&I	LT Glass assy Chrysler chrome				1.0	
25	**		A/M Urethane / Glass Kit		1	15.00	1.3	
26		R&I	LT Rocker molding		1	15.00	T	
27	FRONT DOOR		-				Incl.	
28	*	Rpr	LT Outer panel (HSS)				6.0	
29			Overlap Major Adj. Panel				<u>6.0</u>	2.1
30			Add for Clear Coat					-0.4
31	**	Repl	A/M Mask for Primer Application		1	F 00		0.3
32	**	Repl ,	A/M Feather edge prime and block		1 1	5.00 25.00	0.2 1.0	
33		R&I I	LT Belt molding outer chrome				0.2	
34			T R&I trim panel				0.3	
5		R&I L	T Handle, outside painted, w/hands free ent, w/o chrome stone white				0.6 0.4	
6		R&I L	T Power mirror man fold, v/painted base, w/blind spot vright white				0.5	
7 \	EHICLE DIA	GNOSTIC	S					
8 *	•	Subl P	re-repair scan +25%		1	<u>148.31</u> m		

Preliminary Estimate

0.2 0.1	nois to see if
0.2 0.1	0.2 0.1
0.2	0.2
0.2	0.2
U. 2	0.2
0 -	
0.5	0.5 M
0.!	0.5 M

ESTIMATE TOTALS

Category					
Parts	Basis		Rate	Cost \$	
Body Labor				1,461.74	
Paint Labor	17.7 hrs	@	\$ 75.00 /hr	1,327.50	
Mechanical Labor	10.1 hrs 1.0 hrs	@ @	\$ 125.00 /hr \$ 75.00 /hr	1,262.50 75.00	
Other Charges					
Subtotal				4.00	
Grand Total				4,130.74	
				4,130.74	

We appreciate the opportunity to serve you!

We offer a Limited Lifetime Warranty. Please review the following in regards to the Limited Lifetime Warranty;

The Limited Lifetime Warranty applies for the lifetime that you own the vehicle repaired.

The Limited Lifetime Warranty is not transferable.

The Limited Lifetime Warranty is for Metalwork & Paintwork for the repairs specifically itemized on your final bill. The warranty is presented with the final bill at the time of delivery after repairs are completed.

Parts, Stripes & Decals are limited to a 1 year warranty unless a Manufacturers Warranty is less or more. Mechanical Repairs are limited to 1 year as well.

There may be certain circumstances that a warranty of any kind would not apply. Your Estimator should disclose this to you if a warranty would not apply.

SPECIFICALLY EXCLUDED: No Warranty expressed or implied for rust. This includes surface rust, rust through, and/or damage caused by rusting of interior or exterior panels. Rust work of any kind is not covered by warranty. Also excluded are paint chips, corrosion, nicks or any road damage.