



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

Rob Sand
Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

March 3, 2026

Kristi Onstot
Executive Council
L O C A L

Subject: Deer Damages to Vehicle #59 on January 8, 2026
Department of Administrative Services
Claim dated January 9, 2026
AOS Claim ID: 4228

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$10,899.32, subject to an audit of actual invoices.

Sincerely,

A handwritten signature in black ink, appearing to read "Brian R. Brustkern".

Brian R. Brustkern, CPA
Deputy Auditor of State

cc: Kyle Wear, Fleet Services CFO, Department of Administrative Services
Ryan Betts, Fleet Services Risk Program Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



Department of
Administrative Services

KIM REYNOLDS, GOVERNOR
CHRIS COURNOYER, LT. GOVERNOR

MARK CAMPBELL, DIRECTOR

Date: January 9, 2026

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#59 / Deer
Event Date	January 8, 2026
Summary	Vehicle 59 - struck a deer (Claim # TBD)
Amount Requested	\$10,899.32 TOTAL
Supporting Documentation	29C20 Email Notification, Accident Report, & Repair Estimate

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you

Ryan Betts
DAS Fleet Risk Program Manager
ryan.betts1@iowa.gov
515-281-8008



Risk, DAS <das.risk@iowa.gov>

Fwd: Trooper Howard's Patrol Car

1 message

Risk, DAS <das.risk@iowa.gov>

Thu, Jan 8, 2026 at 8:00 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email the initial 24 hour notification for an AON claim. Vehicle 59 struck a deer on 1/8/2026. I will forward all information as soon as it is received.

*AOS # 4228***DAS Risk**

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

510 E 12th St, Des Moines, IA 50319

515-281-8008 office

das.risk@iowa.gov<https://das.iowa.gov>**Department of
Administrative Services**

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

----- Forwarded message -----

From: **Sitzman Joseph** <sitzman@dps.state.ia.us>

Date: Thu, Jan 8, 2026 at 7:50 AM

Subject: Trooper Howard's Patrol Car

To: vehicledamage <vehicledamage@dps.state.ia.us>, Risk, DAS <das.risk@iowa.gov>

Cc: post2sup <post2sup@dps.state.ia.us>, Adams Jeannie <jadams@dps.state.ia.us>

All,

Trooper Howard's (#59) patrol car sustained substantial damage from a car/deer accident today (01-08-26). His vehicle had to be towed to Adam's Auto Body in Albia. An estimate and all reports will be completed in the next few days.

Thanks,

Sergeant Joe Sitzman ★223★

Iowa State Patrol | District 2

Iowa Department of Public Safety

1619 Truro Pavement | Osceola, Iowa 50213

Office: 641-342-2108

sitzman@dps.state.ia.us

<https://dps.iowa.gov/>

<https://dpscareers.com/>



**Department of
Public Safety**

NOTICE This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

*****Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!**

STATE VEHICLE: (Mark if Act of Nature ☒) CASE #: 2026000451

Date: (Month/Day/Year)	01/08/2026	Time: (Time plus a.m./p.m.)	6:50 a.m.
Vehicle Plate #:	HBY969	Vehicle Mileage:	74,533
Vehicle Description: (Yr/Make/Model/ & Vin#)	2022 Dodge Charger Vin- 2C3CDXKG0NH236224		
Assigned To:	Trp. Howard	Badge #	59
Driven By:	Trp. Howard	Badge #	59
Driver's Lic #:	541AG5122	Damage:	\$10899.32
Vehicle Towed: (Yes / No)	Yes	Towed By:	Adams Auto Body
Towed To:	Adams Auto Body	Towing Cost:	\$
Seat Belt: (Yes / No)	Yes	Type of Vehicle: (Marked/Semi /Unmarked)	Unmarked
Injured/Injuries:	None		
Occupants: (Other than driver)	None		

VEHICLE #2:

DL #:	State:
Vehicle Lic. #	State:
Driver's Name:	
Driver's Address:	
Owner's Name:	
Owner's Address:	

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

OTHER INFORMATION:

Witnesses:	
Accident Location: (Street/Hwy)	Hwy 34 WB; just West of 120 th AVE
County:	Lucas County
Weather/Road Conditions:	Dry/Clear
Trp. Howard was traveling west on Hwy 34 near 120 th Ave. A deer ran out of the north ditch into the roadway. Trp. Howard struck the deer.	
Property Damage other than Vehicles:	None
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	

Investigating Officer:	Trp. Salato #403
------------------------	------------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			

Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

ADAMS AUTOBODY CO INC.
(R41409)

Workfile ID: fa7b7a7e
Federal ID: 42-1363647

adamsalbia@iowatelecom.net
1823 Hwy 137 N, ALBIA, IA 52531
Phone: (641) 932-2515
FAX: (641) 932-2445

Preliminary Estimate

Customer: ISP

Job Number:

Written By: Aimee Adams

Insured: ISP
Type of Loss:
Point of Impact: 12 Front

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner: ISP
Inspection Location: Other
Insurance Company:

VEHICLE

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Frostbite

VIN: 2C3CDXKG0NH236224	Interior Color: Black	Mileage In: 74,533	Vehicle Out:
License: HBY969	Exterior Color: Frostbite	Mileage Out:	
State: IA	Production Date: 9/2022	Condition:	Job #:

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat
Power Adjustable Pedals

DECOR

Dual Mirrors

Tinted Glass

Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera
Parking Sensors

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device
Blind Spot Detection

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions

Preliminary Estimate

Customer: ISP

Job Number:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Frostbite

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER & GRILLE					
2		O/H front bumper				3.4	
3	Repl	Bumper cover	68267765AC	1	1,010.00	Incl.	3.4
4		Add for Clear Coat					1.4
5	Repl	LT Bumper bracket	68226545AB	1	46.05	0.1	
6	Repl	Energy absorber	68214783AA	1	143.00	Incl.	
7	Repl	Upper grille black crossbars	5PP33DX8AB	1	522.00	Incl.	
8	Repl	Nameplate "DODGE" black	68227437AA	1	114.00	0.1	
9	Repl	License bracket w/o SRT	68238771AC	1	43.20	0.1	
10	R&I	Closure panel				Incl.	
11	*	R&I Lower grille w/o adaptive cruise				Incl.	
12		FRONT LAMPS					
13	Repl	LT Headlamp assy halogen	68546771AC	1	931.00	0.4	
14	*	R&I RT Headlamp assy halogen				0.4	
15	R&I	RT Side marker lamp				Incl.	
16	R&I	LT Side marker lamp				Incl.	
17		RADIATOR SUPPORT					
18	Repl	Radiator support	68200478AC	1	459.00	1.0	1.6
19		COOLING					
20	**	Repl A/M Radiator	68050126AB	1	227.82 m	1.8 M	
21		Deduct for Overlap				-0.5 M	
22	**	Repl A/M Shroud	68050294AC	1	449.51 m	0.6	
23		AIR CONDITIONER & HEATER					
24	**	Repl A/M Condenser assy	68085784AA	1	433.34 m	1.5 M	
25		AC Service evacuate & recharge R1234yf			m	1.7 M	
26		Deduct for Overlap				-1.0 M	
27		HOOD					
28	Repl	Hood (ALU)	68660690AA	1	1,625.00	1.5	3.0
29		Add for Clear Coat					1.2
30		Add for Underside(Complete)					1.5
31	Repl	RT Hinge	55113550AG	1	115.00	0.3	0.5
32		Overlap Minor Panel					-0.2
33	Repl	LT Hinge	55113551AG	1	115.00	0.3	0.5
34		Overlap Minor Panel					-0.2
35	R&I	Insulator				Incl.	
36	R&I	Front w'strip				Incl.	
37		FENDER					
38	*	Rpr RT Fender w/o wide body				2.0	2.0
39		Overlap Major Adj. Panel					-0.4
40		Add for Clear Coat					0.3
41	Repl	LT Fender w/o wide body	68660685AA	1	458.00	1.6	2.0
42		Overlap Major Adj. Panel					-0.4

Preliminary Estimate

Customer: ISP

Job Number:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Frostbite

43		Add for Clear Coat					0.3
44		Add for Edging					0.5
45	R&I	LT Fender liner 3.6, 5.7 liter				Incl.	
46	ENGINE						
47	Repl	Air cleaner assy w/police	68413351AB	1	437.00 m	0.5 M	
48	WINDSHIELD						
49	R&I	RT Washer nozzle				Incl.	
50	R&I	LT Washer nozzle				Incl.	
51	MISCELLANEOUS OPERATIONS						
52	#	Subl	Hazardous waste removal	1	4.00 T		
53	#	Repl	Flex additive	1	8.00 T		
54	#	Repl	Corrosion protection primer	1	10.00 T		
55	#	Repl	Cover Car	1	8.00 T		
56	#		Pre Scan	1	T	0.5 M	
57	#		Post Scan	1	T	0.5 M	
SUBTOTALS					7,158.92	16.8	17.0

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			7,128.92
Body Labor	11.8 hrs @	\$ 78.00 /hr	920.40
Paint Labor	17.0 hrs @	\$ 135.00 /hr	2,295.00
Mechanical Labor	5.0 hrs @	\$ 105.00 /hr	525.00
Miscellaneous			30.00
Subtotal			10,899.32
Grand Total			10,899.32
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			10,899.32

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Customer: ISP

Job Number:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Frostbite

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 01/02/2026, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Bld=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: ISP

Job Number:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Frostbite

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
20	Keystone, Inc 810 SE CORPORATE WOODS DR, SUITE 120 ANKENY IA 50021 (515) 727-7857	#RAD13157 A/M Radiator Quote: 3293616343 Expires: 02/23/26	\$ 227.82
22	Keystone, Inc 810 SE CORPORATE WOODS DR, SUITE 120 ANKENY IA 50021 (515) 727-7857	#CH3115184 A/M Shroud Quote: 3293667448 Expires: 02/23/26	\$ 449.51
24	Keystone, Inc 810 SE CORPORATE WOODS DR, SUITE 120 ANKENY IA 50021 (515) 727-7857	#CND3948 A/M Condenser assy Quote: 3293614178 Expires: 02/23/26	\$ 433.34

Customer: ISP

Job Number:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Frostbite

ALTERNATE PARTS USAGE

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Frostbite

VIN: 2C3CDXKG0NH236224

Interior Color: Black

Mileage In: 74,533

Vehicle Out:

License: HBY969

Exterior Color: Frostbite

Mileage Out:

State: IA

Production Date: 9/2022

Condition:

Job #:

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	5	4
Optional OEM	Automatically List	0	0
Reconditioned	Automatically List	0	0
Recycled	N/A	0	0

Customer: ISP

Job Number:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Frostbite

RECALL INFO

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Frostbite

VIN:	2C3CDXKG0NH236224	Interior Color:	Black	Mileage In:	74,533	Vehicle Out:
License:	HBV969	Exterior Color:	Frostbite	Mileage Out:		
State:	IA	Production Date:	9/2022	Condition:		Job #:

The National Highway Transportation and Safety Administration (NHTSA) has issued 3 safety-related recall notice(s) that may apply to the selected vehicle.

NHTSA ID: 22V866000 **Issued: Nov 11, 22** **Number of Vehicles: 00005834**

POWER TRAIN:MANUAL TRANSMISSION:COLUMN SHIFT ASSEMBLY Chrysler (FCA US, LLC) is recalling certain 2022 Dodge Charger and Durango vehicles. The shifter assembly was not properly heat-treated, which can prevent the shifter from properly engaging in the "drive" position. An improperly engaged shifter assembly may slip out of the "drive" position, resulting in a sudden loss of drive power, increasing the risk of a crash. Dealers will replace the shifter assembly, free of charge. Owner notification letters were mailed January 17, 2023. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall ZB3.

NHTSA ID: 22V808000 **Issued: Oct 10, 22** **Number of Vehicles: 00044212**

TIRES:PRESSURE MONITORING AND REGULATING SYSTEMS Chrysler (FCA US LLC) is recalling certain 2022 Dodge Challenger, Dodge Charger, and Chrysler 300 vehicles. The Tire Pressure Monitoring System (TPMS) sensor battery may fail prematurely and cause the sensor to become inoperative. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 138, "Tire Pressure Monitoring Systems." Inoperative TPMS sensors will not alert the driver to low tire pressure. In addition, a TPMS warning light that is already illuminated from a failed battery sensor will mask an actual tire pressure failure issue. Either of these scenarios can result in tire failure and increase the risk of a crash. Dealers will inspect and replace the TPMS sensors, as necessary, free of charge. Owner notification letters were mailed December 10, 2022. Owners may contact FCA US, LLC at 1-800-853-1403. FCA US, LLC's number for this recall is ZB5. This recall is an expansion of previous recall number 22V-504.

NHTSA ID: 22V504000 **Issued: Jul 7, 22** **Number of Vehicles: 00052340**

TIRES:PRESSURE MONITORING AND REGULATING SYSTEMS Chrysler (FCA US LLC) is recalling certain 2022 Dodge Challenger, Dodge Charger, and Chrysler 300 vehicles. The Tire Pressure Monitoring System (TPMS) sensor battery may fail prematurely and cause the sensor to become inoperative. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 138, "Tire Pressure Monitoring Systems." Inoperative TPMS sensors will not alert the driver to low tire pressure. In addition, a TPMS warning light that is already illuminated from a failed battery sensor will mask an actual tire pressure failure issue. Either of these scenarios can result in tire failure and increase the risk of a crash. Dealers will inspect and replace the TPMS sensors, as necessary, free of charge. Owner notification letters were mailed August 2, 2022. Owners may contact FCA US, LLC at 1-800-853-1403. FCA US, LLC's number for this recall is Z68.

ADAMS AUTOBODY CO INC. (R41409)

1823 Hwy 137 N, ALBIA, IA 52531


Phone: (641) 932-2515, Fax: (641) 932-2445

Image Report

Owner:	ISP	Insurance:		Estimator:	Aimee Adams	Vehicle Out:	
Job Number:		Claim Number:					
Year:	2022	Color:	Frostbite	License Plate:	HBV969	Production Date:	9/2022
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	74,533
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG0NH236224	Condition:	




01/09/2026
Comments:




01/09/2026
Comments:



01/09/2026
Comments:



01/09/2026
Comments:



01/09/2026
Comments:



01/09/2026
Comments:

ADAMS AUTOBODY CO INC. (R41409)

1823 Hwy 137 N, ALBIA, IA 52531

Phone: (641) 932-2515, Fax: (641) 932-2445

Image Report

Owner:	ISP	Insurance:		Estimator:	Aimee Adams	Vehicle Out:	
Job Number:		Claim Number:					
Year:	2022	Color:	Frostbite	License Plate:	HBY969	Production Date:	9/2022
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	74,533
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG0NH236224	Condition:	



01/09/2026

Comments:




01/09/2026

Comments:



01/09/2026

Comments:



01/09/2026

Comments:



01/09/2026

Comments:



01/09/2026

Comments:

ADAMS AUTOBODY CO INC. (R41409)

1823 Hwy 137 N, ALBIA, IA 52531

Phone: (641) 932-2515, Fax: (641) 932-2445

Image Report

Owner:	ISP	Insurance:		Estimator:	Aimee Adams	Vehicle Out:	
Job Number:		Claim Number:					
Year:	2022	Color:	Frostbite	License Plate:	HBY969	Production Date:	9/2022
Make:	DODG	Body Style:	4D SED	State:	IA	Mileage In:	74,533
Model:	Charger Police AW...	Engine:	6-3.6L Gasoline S...	VIN:	2C3CDXKG0NH236224	Condition:	



01/09/2026
Comments:



01/09/2026
Comments: