

MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE NAIG SECRETARY OF AGRICULTURE

Executive Council of Jowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

September 3, 2024

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on this date, approved payment of the following cost item:

This represents full and final payment.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Acting Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services

DAS Fleet Services, Risk

Matt Bender, Department of Management

Heather Hackbarth, Department of Management

OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building Des Moines, Iowa 50319-0004

Telephone (515) 281-5834

August 16, 2024

Kristi Onstot Executive Council L O C A L

Subject: Hail Damage to Vehicle #112 on May 21, 2024

Department of Administrative Services

Claim dated June 3, 2024 AOS Claim ID: 3766

In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to the damages and have found the items to be in order as shown below:

Documented request	\$ 2,301.50
Executive Council Allocation	\$ 2,301.50

Less:

Previous payments \$0.00This payment 2,301.50

Total <u>\$ 2,</u>301.50

Remaining Executive Council allocation \$ 0.00

We recommend reimbursement be made in the amount of \$2,301.50. This represents <u>full</u> and <u>final</u> payment of the loss.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Bri R Bris

cc: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services





Date: July 18, 2024

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Karl Bubser, Fleet Administrator

DAS Fleet Services

Department of Administrative Services

Re: REIMBURSEMENT REQUEST - 29C20 Claim

AOS Claim #	3766
Vehicle / Event	#112/Weather
Event Date	May 21, 2024
Summary	Vehicle 112 sustained hail damage. (281850)
Amount Requested	\$2,301.50 - TOTAL

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: **0665-005-5790-0657**.

If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,

Karl Bubser, Fleet Administrator

DAS Fleet Services karl.bubser@iowa.gov

515-281-3162





Search here...









Karl Bubser Financial User



Warrants

Edit

Cancel

* Required fields







Warrant Information

Fiscal Year 2024 **Vendor Customer**

00003032666

Amount \$2,301.50 **Line Number** **Warrant Number** 86285533 **Last Updated** 07/17/2024 07:20 PM

Issue Information

Issued 07/12/2024 12:00 AM

Duplicate No

Line Amount \$469.00

Void

Transaction Line Number

Comments

Transaction ID RISK00525193005

Stop No

Redeemed Information

Redeemed 07/17/2024 12:00 AM **Sequence Number** 02333

0992 **Redeemed Fund** 0665

Batch Number

Redeemed Bank 0022 **Redeemed Department** 005

∨ COA

Fund 0665 Sub Fund

Department 005 **Object Class**

Appropriation 0000 **Sub BSA**

Object 2715 **Sub Object** Unit

5790 **Revenue Source**

Revenue Source Class

Dept Object

Dept Revenue

Sub Unit

Sub Revenue Source

BSA

▶ Show More





Search here...











Karl Bubser Financial User

Warrants

Edit

Cancel

* Required fields

Warrant Information

Fiscal Year 2024

Vendor Customer 00003032666

Amount \$2,301.50

Line Number

Warrant Number

86285533 **Last Updated**

07/17/2024 07:20 PM

→ Issue Information

Issued

07/12/2024 12:00 AM

Duplicate No

Line Amount \$1,832.50

Void No

Transaction Line Number

2

Comments

Transaction ID

RISK00525193005

Stop No

Redeemed Information

Redeemed 07/17/2024 12:00 AM

Sequence Number

02333

Batch Number

0992

Redeemed Fund

0665

Object

Sub Object

Revenue Source

Revenue Source Class

2715

Unit

5790

Redeemed Bank

0022

Redeemed Department

005

✓ COA

Fund

0665

Sub Fund

Department

005

Object Class

Appropriation 0000

Sub BSA

Show More

Dept Object

Dept Revenue

Sub Unit

Sub Revenue Source

BSA



COPELAND AUTO BODY, INC.

estimates@copelandautobody.com 506 E 2nd St, P.O. Box 109, Hedrick, IA 52563

> Phone: (641) 653-2140 FAX: (641) 653-4301

Workfile ID: PartsShare: 95376a82 7XWbqm

281850

Final Bill

RO Number: 20294

Customer:

State Of Iowa

109 SE 13th St

Des Moines, IA 50319-9018

(319) 530-3251

Insurance:

Creative Risk Solutions

Adjuster:

Alex White

281850

Estimator:

Brandon Petrehn

Create Date:

5/29/2024

Phone: Claim:

Loss Date:

Deductible:

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Dark Grey

VIN: License:

State:

2C3CDXKG5NH240978

112

IΑ

Interior Color:

Production Date:

Black

Mileage In:

Vehicle Out:

Exterior Color:

Dark Grey 11/2022

Mileage Out: Condition:

Good

21,353

Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
1	E01		HOOD						
2	E01	PDR	Hood (ALU)	1	375.00	Other			
3	E01	PDR	Oversized Dents 1.5-2.5 \$40 EA 1 80.00 Other Number2 items						
4	E01	Remove/Install	R&I hood assy				0.6	Body	
5	E01	Remove/Install	Insulator				0.3	Body	
6	E01		ELECTRICAL						
7	E01	Remove/Install	Antenna				0.3	Body	
8	E01		ROOF						
9	E01	PDR	Roof panel w/o sunroof	1	275.00	Other			
10	E01	Remove/Install	Headliner w/o sunroof w/o options				3.9	Body	
11	E01	Remove/Install	Lt Roof molding				0.5	Body	
12	E01	Remove/Install	Rt Roof molding				0.5	Body	
13	E01	PDR	LT Outer Upper Roof Rail Dime Size Dents 1-5	1	125.00	Other			
14	E01	PDR	RT Outer Upper Roof Rail Nickel Size Dents 1-5	1	175.00	Other			
15	E01		REAR DOOR						
16	E01	PDR	RT Door shell w/o wide body (HSS)	1	150.00	Other			
17	E01	Remove/Install	RT Belt w'strip				0.3	Body	
18	E01		QUARTER PANEL						
19	E01	PDR	LT Wheelhouse liner w/o vented bumper	1	75.00	Other			
20	E01	PDR	RT Wheelhouse liner w/o vented bumper	1	150.00	Other			
21	E01		TRUNK LID						
22	E01	PDR	Trunk lid all	1	200.00	Other			
23	E01	Remove/Install	Trunk lid trim				0.3	Body	
24	E01	PDR	Corrosion Protection	1	30.00	Other			

RO Number: 20294

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Dark Grey

25 E01 PDR

Glue pull material

1

10.00 Other

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Labor, Body			70.00	6.7	469.00
Miscellaneous		187.50			1,832.50
Subtotal					2,301.50
Sales Tax					0.00
Grand Total					2,301.50
Net Total					2,301.50

Estimate Version	Total \$
Original	2,301.50
Insurance Total \$:	2,301.50
Received from Insurance \$:	0.00
Balance due from Insurance \$:	2,301.50
Customer Total \$:	0.00
Received from Customer \$:	0.00
Balance due from Customer \$:	0.00

ATTENTION: WHEELS NEED TO BE RE-TORQUED WITHIN 100 MILES. FAILURE TO DO SO MAY RESULT IN FURTHER DAMAGE!

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural





Date: June 3, 2024

Γο: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Karl Bubser, Fleet Administrator

DAS Fleet Services

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#112/Weather
Event Date	May 21, 2024
Summary	Vehicle 112 sustained hail damage (281850)
Amount Requested	\$2,301.50 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Karl Bubser, Fleet Administrator

DAS Fleet Services

Karl.Bubser@iowa.gov

515-281-3162



A05 # 3766

Risk, DAS <das.risk@iowa.gov>

29C20

Risk, DAS <das.risk@iowa.gov>

Tue, May 21, 2024 at 1:44 PM

Draft To: TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>, Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 112 sustained hail damage on 5/21/24 I will forward all information as soon as it is received.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,


DAS Risk

Central Procurement and Fleet Services Enterprise lowa Department of Administrative Services 109 SE 13th St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov

https://das.iowa.gov



State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: <u>vehicledamage@dps.state.ia.us</u>; <u>das.risk@iowa.gov</u>

- > One Repair Estimate from Approved State Bid Shop
- > DOT MARS Report (if reportable)
- > Memo from the Driver of the State Vehicle
- > 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature⊠) CASE #:2024012558

STATE VEHICL	⊏: (<i>n</i>	nark II ACLOI I	Nature⊠) CASE #:2	2024012556		
Date: (Month/Day/Year)	05/2	21/24	Time: (Time plus a.m./p.m.)	1315 hrs.		
Vehicle Plate #:			Vehicle Mileage:	20,744		
Vehicle Description: (Yr/Make/Model/ & Vin#)		2022 Dodge Charger VIN:2C3CDXKG5NH240978				
Assigned To:		Tracy derwiel	Badge #	112		
Driven By:	Park	red	Badge #	N/A		
Driver's Lic #:	132	-BB-0416	Damage:	Estimate Pending		
Vehicle Towed: (Yes / No)	N/A		Towed By:	N/A		
Towed To:	N/A		Towing Cost:	\$N/A		
Seat Belt: N/A (Yes / No)			Type of Vehicle: (Marked/Semi /Unmarked)	Marked		
Injured/Injuries:		N/A				
Occupants: (Other than driver)		N/A				

VEHICLE #2:

DL #:	State:	
Vehicle Lic. #	State:	
Driver's Name:		
Driver's Address:		
Owner's Name:		
Owner's Address:		

Owner's Phone:								
			· · · · · · · · · · · · · · · · · · ·	*****				
Insurance Info:								
(Carrier/Policy #/Phone)			*****					
Veh Description: (Yr/Make/Model & Vin#)								
(177Wake/Woder & VIII#)								
Damage:	\$	·	Seat Belt:					
Damage.	Ψ		(Yes / No)					
Injured/Injuries:				M 1/1/2				
Occupants:				** ***********************************				
(Other than driver)								
Occupant(s) Weari	ng Seat B	elt: (Yes/No	p)	A Million of the Control of the Cont				
OTHER INFORMA	TION:							
Witnesses:		N/A	**************************************					
Accident Location:		Residen	ce:					
(Street/Hwy)		216 Diag	gonal Street					
			lowa 50207					
County:		Mahaska						
Weather/Road Con	ditions:							
Weather/Road Conditions: Damaging storm with hail Trooper Vanderwiel #112 received hail damage to his patrol vehicle after								
Trooper Vanderwie	l #112 rec	eived hai	l damage to his p	patrol vehicle after				
	l #112 rec	eived hai	l damage to his p	patrol vehicle after				
Trooper Vanderwie	l #112 rec	eived hai	l damage to his p	patrol vehicle after				
Trooper Vanderwie	l #112 rec	eived hai	l damage to his p	patrol vehicle after				
Trooper Vanderwie	l #112 rec	eived hai	l damage to his p	patrol vehicle after				
Trooper Vanderwie	l #112 rec	eived hai	l damage to his p	patrol vehicle after				
Trooper Vanderwie	l #112 rec evere stori	eived hai	l damage to his p	patrol vehicle after				
Trooper Vanderwie several waves of se	l #112 rec evere stori	eived hai	l damage to his p	patrol vehicle after				
Trooper Vanderwie several waves of se	l #112 rec evere stori	eived hai	l damage to his p	patrol vehicle after				
Trooper Vanderwie several waves of sever	l #112 recevere stori	None	l damage to his p	patrol vehicle after				
Trooper Vanderwie several waves of sever	ther than	None	l damage to his p	patrol vehicle after				
Property Damage of Vehicles: Cost: Citations Issued To	ther than	None	l damage to his p	patrol vehicle after				
Property Damage of Vehicles: Cost: Citations Issued To	ther than Code(s))	None	I damage to his point the are	atrol vehicle after a.				
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute	ther than Code(s))	None	l damage to his p	atrol vehicle after a.				
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute	ther than Code(s))	None	I damage to his point the are	atrol vehicle after a.				
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute	ther than Code(s))	None N/A N/A	I damage to his post through the are	atrol vehicle after				
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute) Investigating Office	ther than Code(s))	None N/A N/A	I damage to his post through the are	atrol vehicle after a.				
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute) Investigating Office VEHICLE #3: (If ne this portion)	ther than Code(s))	None N/A N/A	I damage to his post through the are Sgt. Morey #431	atrol vehicle after				
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute) Investigating Office VEHICLE #3: (If ne this portion) DL #:	ther than Code(s))	None N/A N/A	I damage to his positive distributed through the are Sgt. Morey #431 Sgt. Morey #431 State:	atrol vehicle after				
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute) Investigating Office VEHICLE #3: (If ne this portion) DL #: Vehicle Lic. #	ther than Code(s))	None N/A N/A	I damage to his post through the are Sgt. Morey #431	atrol vehicle after				
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute) Investigating Office VEHICLE #3: (If ne this portion) DL #:	ther than Code(s))	None N/A N/A	I damage to his positive distributed through the are Sgt. Morey #431 Sgt. Morey #431 State:	atrol vehicle after				

Owner's Name:			
Owner's Address:			
Owner's Phone:			— /ul-7:
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Weari	ng Seat Belt	(Yes/No)	



MEMORANDUM

TO: Sgt. Morey #431

FROM: Trooper Tracy Vanderwiel #112

DATE: May 22nd, 2024

SUBJECT: Hail Damage

On Tuesday May 21 at approximately 11:30am my patrol vehicle sustained some hail damage during a storm.



COPELAND AUTO BODY, INC.

estimates@copelandautobody.com 506 E 2nd St, P.O. Box 109, Hedrick, IA 52563

> Phone: (641) 653-2140 FAX: (641) 653-4301

Preliminary Estimate

Customer: State Of Iowa

Written By: Brandon Petrehn Adjuster: White, Alex

Insured:

State Of Iowa

Type of Loss:

Point of Impact: 27 Hail

Other

Policy #:

Date of Loss:

Claim #:

Days to Repair: 0

Workfile ID:

PartsShare:

Federal ID:

95376a82

7XWbqm

42-1488559

Owner:

State Of Iowa 109 SE 13th St

Des Moines, IA 50319-9018

(319) 530-3251 Cell

Inspection Location:

COPELAND AUTO BODY, INC.

506 E 2nd St

P.O. Box 109

Hedrick, IA 52563 Repair Facility

(641) 653-2140 Business

Insurance Company: Creative Risk Solutions

VEHICLE

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Dark Grey

VIN:

2C3CDXKG5NH240978

Interior Color:

Black

Mileage In:

21,353

Good

Vehicle Out:

License: 112

Exterior Color:

Dark Grey

Mileage Out:

State:

IΑ

Production Date:

11/2022

Condition:

Job #:

TRANSMISSION

Automatic Transmission

4 Wheel Drive

POWER

Power Steering Power Brakes

Power Windows

Power Locks

Power Mirrors

Power Driver Seat **DECOR**

Dual Mirrors Tinted Glass

Overhead Console

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control Rear Defogger

Keyless Entry

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Climate Control

Backup Camera Parking Sensors

RADIO

AM Radio

FM Radio

Stereo Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag Passenger Air Bag

Anti-Lock Brakes (4) 4 Wheel Disc Brakes Front Side Impact Air Bags

Head/Curtain Air Bags Hands Free Device

SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control Stability Control California Emissions

Get live updates at www.carwise.com/e/4Nr8Yy

5/30/2024 10:09:00 AM 312629 Page 1

Preliminary Estimate

Customer: State Of Iowa

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Dark Grey

Line		Oper	Description Pa	art Number Qty	Extended Price \$	Labor	Pain
1	HOOD				·		
2	*	PDR	Hood (ALU) +25%	1	<u>468.75</u> T		
			Note: PDR 20 quarter 25% Markup Aluminum Panel				
3	#	PDR	Oversized Dents 1.5-2.5 \$40 EA Number2 items	1	80.00 T		
4		R&I	R&I hood assy			0.6	
5		R&I	Insulator			0.3	
6	ELECTRICAL						
7		R&I	Antenna			0.3	
8	ROOF						
9	*	PDR	Roof panel w/o sunroof	1	<u>275.00</u> T		
			Note: PDR 12 nickel				
10	*	R&I	Headliner w/o sunroof w/o options			<u>3.9</u>	
11	#	R&I	Lt Roof molding			0.5	•
12	#	R&I	Rt Roof molding			0.5	
13	#	PDR	LT Outer Upper Roof Rail Dime Size Dents 1-5	1	125.00 T		
			Note: Base 25% Markup built into roof rail	pricing.			
14	#	PDR	RT Outer Upper Roof Rail Nickel Size Dents 1-5	1	175.00 T		
			Note: Base 25% Markup built into roof rail	pricing.			
15	REAR DOOR		· · · · · · · · · · · · · · · · · · ·				
16	*	PDR	RT Door shell w/o wide body (HSS) +25%	1	<u>187.50</u> T		
			Note: PDR 1 quarter 25% Markup High Strength Steel				
17		R&I	RT Belt w'strip			0.3	
18	QUARTER PAI	NEL					
19	*	PDR	LT Wheelhouse liner w/o vented bumper +25%	1	<u>93.75</u> T		
			Note: PDR 1 dime 25% Markup Double Panel/Glue Pull				
20	*	PDR	RT Wheelhouse liner w/o vented bumper +25%	1	<u>187.50</u> T		
			Note: PDR 1 quarter 25% Markup Double Panel/Glue Pull				
21	TRUNK LID						
22	*	PDR	Trunk lid all	1	<u>200.00</u> T		
			Note: PDR 1 quarter				
23		R&I	Trunk lid trim			0.3	
24	#	PDR	Corrosion Protection	1	30.00 T		
25	#	PDR	Glue pull material	1	10.00 T		
			SUBT	OTALS	1,832.50	6.7	0.

Customer: State Of Iowa

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Dark Grey

NOTES

Prior Damage Notes: None

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			0.00
Body Labor	6.7 hrs @	\$ 70.00 /hr	469.00
PDR			1,832.50
Subtotal			2,301.50
Grand Total			2,301.50
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			2,301.50

ATTENTION: WHEELS NEED TO BE RE-TORQUED WITHIN 100 MILES. FAILURE TO DO SO MAY RESULT IN FURTHER DAMAGE!

Preliminary Estimate

Customer: State Of Iowa

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Dark Grey

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 05/16/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.