

MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE NAIG SECRETARY OF AGRICULTURE

Executive Council of Jowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

September 3, 2024

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on this date, approved payment of the following cost item:

This represents full and final payment, \$77.00 will be reverted and this allocation closed.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Acting Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services

DAS Fleet Services, Risk

Matt Bender, Department of Management

Heather Hackbarth, Department of Management

OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

August 16, 2024

Kristi Onstot Executive Council L O C A L

Subject: Storm Damage to Vehicle #1294 on May 21, 2024

Department of Administrative Services

Claim dated May 24, 2024 AOS Claim ID: 3782

In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to the damages and have found the items to be in order as shown below:

Less:

cc:

Previous payments \$0.00This payment \$6,880.67

Total \$ 6,880.67

Remaining Executive Council allocation \$ 77.00

We recommend reimbursement be made in the amount of \$6,880.67. This represents <u>full</u> and <u>final</u> payment of the loss. The remaining allocation should be reverted to the State Treasury.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Bri R Bris

Adam Steen, Director, Department of Administrative Services Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services





Date: July 18, 2024

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Karl Bubser, Fleet Administrator

DAS Fleet Services

Department of Administrative Services

Re: REIMBURSEMENT REQUEST - 29C20 Claim

AOS Claim #	3782
Vehicle / Event	#1294/Weather
Event Date	May 21, 2024
Summary	Vehicle 1294 sustained storm damage. (281400)
Amount Requested	\$6,880.67 - TOTAL

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: **0665-005-5790-0657**.

If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,

Karl Bubser, Fleet Administrator

DAS Fleet Services karl.bubser@iowa.gov

515-281-3162





Search here...











Karl Bubser Financial User



Warrants

Edit


Cancel

* Required fields









Fiscal Year 2024 **Vendor Customer** 00002107976

Amount \$6,880.67 **Line Number** **Warrant Number** 73151410 **Last Updated** 07/16/2024 07:19 PM

→ Issue Information

Issued 07/16/2024 12:00 AM **Duplicate**

Line Amount \$6,880.67

Void

Transaction Line Number

Comments

Transaction ID RISK00524197508

Stop No

Redeemed Information

Redeemed

Batch Number

Redeemed Bank

Sequence Number

Redeemed Fund

Redeemed Department

∨ COA

Fund 0665

Sub Fund

Department 005 **Object Class**

Unit 5790

Object

2715

Sub Object

Revenue Source

Dept Object

Dept Revenue

Sub Unit

Sub Revenue Source

Revenue Source Class

B\$A

Sub BSA

0000

▶ Show More

Appropriation



Abra - Dubuque

When You're Ready 3400 Center Grove Dr., Dubuque, IA 52003 Phone: (563) 556-0696

FAX: (563) 556-1899

Workfile ID: Federal ID:

148a49c4 42-0782245

1294 み別 400

Final Bill

RO Number: 35816

Customer:

Insurance:

Adjuster:

Estimator:

Chad Hahn

STATE OF IOWA

STATE OF IOWA

Phone:

Create Date:

5/22/2024

(563) 872-4976

Claim:

Loss Date:

UNIT-1294

Deductible:

2015 CHEV Silverado 2500 HD Work Truck Crew Cab 167.7" WB 4WD 4D LONG 8-6.0L Flex Fuel Electronic Fuel Injection WHITE

VIN:

1GC1KUEG6FF596099

Interior Color:

Production Date:

Mileage In:

58,323

Vehicle Out: 6/2

6/25/2024

License: State:

1294 IA Exterior Color:

WHITE 3/2015 Mileage Out: Condition:

n: Jol

Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
1	E01		FRONT BUMPER						
2	E01	Remove/Install	R&I bumper assy				1.6T	Body	
3	E01		GRILLE						
4	E01	Remove/Install	Grille assy standard w/o body color				0.0T	Body	
5	E01		FRONT LAMPS						
6	E01	Remove/Install	RT Headlamp assy w/o body color				0.3T	Body	
7	E01		RADIATOR SUPPORT						
8	E01	Remove/Install	Sight shield Chevrolet 6.0 liter				0.2T	Body	
9	E01		HOOD						
10	E01	Remove/Replace	Hood	1	737.00T	A/M	1.4T	Body	3.0T
11	E01		Add for Clear Coat						
12	E01		Add for Underside(Complete)						1.5T
13	E01		FENDER						
14	E01	Remove/Replace	RT Fender	1	690.00T	A/M	2.4T	Body	2.0T
15	E01		Overlap Major Adj. Panel						(0.4)T
16	E01		Add for Clear Coat						
17	E01		Add for Edging						0.5T
18	E01		Add for Inside						1.2T
19	E01		ELECTRICAL						
20	E01	Remove/Replace	Antenna mast	1	94.60T	OEM	0.1T	Body	
21	E01		CAB						
22	E01	Repair	Roof panel w/o roof lamps w/o Onstar				10.0T	Body	3.4T
23	E01		Overlap Major Adj. Panel						(0.4)T
24	E01		Add for Clear Coat						
25	E01	Repair	RT Uniside assy				10.0T	Body	4.0T
26	E01		Overlap Major Adj. Panel						(0.4)T

RO Number: 35816

2015 CHEV Silverado 2500 HD Work Truck Crew Cab 167.7" WB 4WD 4D LONG 8-6.0L Flex Fuel Electronic Fuel Injection WHITE

27	E01		Add for Clear Coat						
28	E01	Remove/Replace	RT Roof molding	1	144.92T	OEM	0.3T E	Body	
29	E01	Remove/Replace	LT Roof molding	1	156.52T	OEM	0.3T E	Body	
30	E01	Remove/Install	Cowl grille Chevrolet 6.0 liter				0.5T E	Body	
31	E01		FRONT DOOR						
32	E01	Repair	RT Outer panel double & crew cab				1.0T E	Body	2.4T
33	E01		Overlap Major Adj. Panel						(0.4)T
34	E01		Add for Clear Coat						
35	E01	Remove/Install	RT Belt molding double & crew cab black				0.3T I	Body	
36	E01	Remove/Replace	RT Nameplate "2500 HD"	1	74.58T	OEM	0.3T E	Body	
37	E01	Remove/Install	RT R&I mirror				0.3T E	Body	
38	E01	Remove/Install	RT Handle, outside black				0.3T E	Body	
39	E01	Remove/Install	RT R&I trim panel				0.4T I	Body	
40	E01	Remove/Install	RT Upper trim				0.2T E	Body	
41	E01	Repair	Remove decal				0.5T i	Body	
42	E01		REAR DOOR						
43	E01	Repair	RT Outer panel				2.0T &	Body	2.4T
44	E01		Overlap Major Adj. Panel						(0.4)T
45	E01		Add for Clear Coat						
46	E01	Remove/Install	RT Belt molding black				0.3T E	Body	
47	E01	Remove/Install	RT Door glass GM w/o deep tint				0.3T E	Body	
48	E01	Remove/Install	RT Run w'strip				0.3T I	Body	
49	E01	Remove/Install	RT Handle, outside black				0.3T I	Body	
50	E01	Remove/Install	RT R&I trim panel				0.4T I	Body	
51	E01	Remove/Install	RT Upper trim				0.2T I	Body	
52	E01		REAR LAMPS						
53	E01	Remove/Replace	RT Tail lamp assy	1	177.00T	LKQ	0.3T E	Body	
54	E01	Repair	Rope Windshield				0.3T E	Body	
55	E01	Remove/Replace	Seam Sealer	1	10.00	A/M	0.5T E	Body	
56	E01		Hazardous waste removal	1	3.00T	Other			
57	E01	Remove/Replace	Cover Car	1	5.00T	Other			
58	E01	Remove/Replace	Corrosion Protection	1	5.00T	Other			
59	E01	Refinish	Prime and Block						1.0T
60	E01		Clear coat cap						2.5T

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts		44.25		-	2,131.87
Labor, Body			66.00	35.3	2,329.80
Labor, Refinish			66.00	21.9	1,445.40
Material, Paint					963.60
Miscellaneous			-		10.00
Subtotal					6,880.67
Sales Tax					0.00
Grand Total					6,880.67

6/26/2024 8:55:49 AM

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 35816

2015 CHEV Silverado 2500 HD Work Truck Crew Cab 167.7" WB 4WD 4D LONG 8-6.0L Flex Fuel Electronic Fuel Injection WHITE

Net Total		6,880.67
	Estimate Version	Total \$
	Original	6,880.67
	Insurance Total \$:	0.00
	Received from Insurance \$:	0.00
	Balance due from Insurance \$:	0.00
	Customer Total \$:	6,880.67
	Received from Customer \$:	0.00
	Balance due from Customer \$:	6,880.67

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural





Date: May 24, 2024

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Karl Bubser, Fleet Administrator

DAS Fleet Services

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#1294/Weather
Event Date	May 21, 2024
Summary	Vehicle 1294 sustained storm damage. (281400) AOS #3782
Amount Requested	\$6,957.67 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Karl Bubser, Fleet Administrator DAS Fleet Services Karl.Bubser@iowa.gov 515-281-3162

29C20

Risk, DAS <das.risk@iowa.gov>

Wed, May 22, 2024 at 10:57 AM

Draft To: DAS Risk <as.risk@iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>, Tammy Hollingsworth Tammy.Hollingsworth@aos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 1294 sustained storm damage on 5/21/24. I will forward all information as soon as it is received.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

109 SE 13th St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov

https://das.iowa.gov





Department of Administrative Services
DAS Fleet Services- Risk Management
109 SE 13th St
Des Moines, IA 50319

Vehicle Accident Report Form

- Render aid or assistance to the injured (per Iowa Code 321.262).
- The State of lowa is self-insured. Refer to the insurance card and accident report procedures online
 or in your glove box packet. If the accident involves another party, exchange information with the
 driver or property owner. Do not admit fault or attempt to settle your claim.
- Call local law enforcement, if a fatality, injury or property damage has occurred, and obtain a police report. On the Capitol complex, call lowa State Patrol, Post 16 at 515-281-5608.
- Within the first 24 hours, report accident or damage to DAS Fleet Services (515-281-3162 or <u>DAS.Risk@iowa.gov</u>), your agency fleet contact, and supervisor. Damage caused by an act of nature or unavoidable cause MUST be reported to DAS Fleet Services within 24 hours of the incident to qualify for contingent fund use (<u>per Iowa Code 29C.20</u>).
- For an estimate, locate the nearest contracted auto body repair shop in the Contracted Service Providers map. A contracted auto body shop within 30 miles should be used if available.
- If towing is necessary, contact DAS Fleet Services (515-281-3162) for assistance. After hours, call National Automobile Club (NAC) FleetRescue* (866-329-3471) or local law enforcement.
- Within 72 hours, print and submit a completed Accident Report Form, including a cost estimate from the auto body shop to <u>DAS.Risk@iowa.gov</u>.
- Any accident in the State of lowa that causes death, personal injury, or total property damage of \$1,500 or more must be reported on an lowa Accident Report Form UNLESS the accident is investigated by a law enforcement agency and a report is filed. Failure to return an accident report form within 72 hours may result in suspension of driving privileges.

Vehicle Accident Report

Time and location of accide	nt					
Accident Date (Mo/Day/Year)		Time	No. of Vehicles			
5/2·	1/24	7:30pm	1			
County		State				
Jack	kson	lov	wa			
Vehicle 1 (State vehicle)						
Driver's Name		Work Street Address				
n,	/a	24143 Hi	ghway 52			
Driver's License No./State		City, State, Zip				
n,	/a	Bellevue,	IA 52031			
Date of Birth	Department	Work Phone	Home Phone			
n/a	Natural Resources	563-872-4976				
License Plate No.	VIN	Year, Make, Model	•			
1294	1GC1KUEG6FF596099	2014 Chevrolet K2500 HD				
Estimate (\$) of Damage		Description of Damage				
\$6,957.67		Tree fell on it, smashed the passenger side hood and front end.				
Vehicle 2 (other vehicle) if n	nore than two vehicles-use ac	dditional forms				
Driver's Name		Street Address				
Driver's License No./State		City, State, Zip				
Date of Birth	Work Phone	Home Phone	License Plate No.			
Description of Damage						

Property Damage other than vehicle (fence, utility pole, etc)							
Owner's Name, Address and Phone	Description of Property Damaged						
Injured Persons (attach additional sheets if necessary)							
Vehicle No. 1/ Name and Address	Describe Injuries						
Vehicle No. 2/ Name and Address	Describe Injuries						
Witness							
Name	Address/Phone						
Name	Address/Phone						

Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers. Use number 1 to indicate the State vehicle. Truck was parked in parking lot. A significant storm passed through and caused significant wind damage, including breaking off the top of a large tree. The tree fell on top of the truck, across the passenger side and hood.

	Accident Information Exchange Sheet							
Other Vehicle information								
Driver's Name								
Street Address								
Driver Phone								
Driver's License No./State								
Vehicle Plate No.								
Vehicle year, make, model								
VIN								
Insurance Company Name								
Policy No.								
Agent name								
Agent phone								
Owner's Name/Address (if different)	,							
Submit this information	along with the accident report to DAS Fleet Service within 72 hours of the accident.							
Complete the	next section, tear at the dotted line and give to the other party involved.	-						
State Vehicle Insurance In	ormation							
Driver's Name								
Driver's License No./State	·							
Vehicle Plate No.								
Vehicle year, makel, model								
VIN								
If	The State of Iowa is self-insured. you have any questions regarding an accident, please contact DAS Fleet Services at 515-281-3162 of DAS.Risk@iowa.gov							



Abra - Dubuque

When You're Ready 3400 Center Grove Dr., Dubuque, IA 52003

Phone: (563) 556-0696 FAX: (563) 556-1899

Workfile ID: Federal ID: State ID: Resale Number: Federal EPA: State EPA:

License Number:

148a49c4 42-0782245 IΑ 31-007262 IAR000004861 NA 433840

na

BAR:

Preliminary Estimate

Customer: STATE OF IOWA

Written By: Chad Hahn

Insured:

STATE OF IOWA

Policy #:

Claim #:

UNIT-1294

Type of Loss:

Owner:

Point of Impact:

Date of Loss:

Days to Repair:

STATE OF IOWA (563) 872-4976 Cell **Inspection Location:**

Abra - Dubuque

3400 Center Grove Dr. Dubuque, IA 52003

Repair Facility

(563) 556-0696 Business

Insurance Company:

STATE OF IOWA

58,323

VEHICLE

2015 CHEV Silverado 2500 HD Work Truck Crew Cab 167.7" WB 4WD 4D LONG 8-6.0L Flex Fuel Electronic Fuel Injection WHITE

VIN:

1GC1KUEG6FF596099

Interior Color:

Mileage In:

Vehicle Out:

License:

1294

Exterior Color:

WHITE

Mileage Out:

State:

IΑ

Production Date:

3/2015

Condition:

Job #:

TRANSMISSION

Automatic Transmission

Overdrive

4 Wheel Drive

POWER

Power Steering

Power Brakes

Power Windows

Power Locks **DECOR**

Dual Mirrors

Tinted Glass

CONVENIENCE

Air Conditioning Tilt Wheel

Cruise Control

Message Center

RADIO

AM Radio

FM Radio

Stereo Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control Stability Control

Front Side Impact Air Bags

Head/Curtain Air Bags Hands Free Device

SEATS

Cloth Seats

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

TRUCK

Rear Step Bumper

Customer: STATE OF IOWA

2015 CHEV Silverado 2500 HD Work Truck Crew Cab 167.7" WB 4WD 4D LONG 8-6.0L Flex Fuel Electronic Fuel Injection WHITE

Line	O	per	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUMPER						· · · · ·	
2	R	R&I	R&I bumper assy		0	0.00	1.6	0.0
3	GRILLE							
4	R	1.85	Grille assy standard w/o body color		0	0.00	Incl.	0.0
5	FRONT LAMPS							
6	R	R&I	RT Headlamp assy w/o body color		0	0.00	0.3	0.0
7	RADIATOR SUPP	ORT	•					
8	R	1.83	Sight shield Chevrolet 6.0 liter		0	0.00	0.2	0.0
9	HOOD							
10	** Re	.epl	A/M CAPA Hood	84348413	1	737.00	1.4	3.0
11			Add for Clear Coat		0	0.00	0.0	1.2
12			Add for Underside(Complete)		0	0.00	0.0	1.5
13	FENDER							
14	** Re	epl	A/M CAPA RT Fender	84214215	1	690.00	2.4	2.0
15			Overlap Major Adj. Panel		0	0.00	0.0	-0.4
16			Add for Clear Coat		0	0.00	0.0	0.3
17			Add for Edging		0	0.00	0.0	0.5
18			Add for Inside		0	0.00	0.0	1.2
19	ELECTRICAL							
20	Re	epl	Antenna mast	84170994	1	94.60	0.1	0.0
21	CAB							
22	* R	pr	Roof panel w/o roof lamps w/o Onstar		0	0.00	<u>10.0</u>	3.4
23			Overlap Major Adj. Panel		0	0.00	0.0	-0.4
24			Add for Clear Coat		0	0.00	0.0	0.6
25	* R	≀pr	RT Uniside assy		0	0.00 s	<u>10.0</u>	<u>4.0</u>
26			Overlap Major Adj. Panel		0	0.00	0.0	-0.4
27	*		Add for Clear Coat		0	0.00	0.0	0.7
28	Re	epl	RT Roof molding	84293173	1	144.92	0.3	0.0
29	Re	epl	LT Roof molding	84293172	1	156.52	0.3	0.0
30	R	l&I	Cowl grille Chevrolet 6.0 liter		0	0.00	0.5	0.0
31	FRONT DOOR							
32	* R	tpr	RT Outer panel double & crew cab		0	0.00	<u>1.0</u>	2.4
33			Overlap Major Adj. Panel		0	0.00	0.0	-0.4
34	*		Add for Clear Coat		0	0.00	0.0	0.4
35	R	.&I	RT Belt molding double & crew cab black		0	0.00	0.3	0.0
36	Re	epl	RT Nameplate "2500 HD"	15129644	1	74.58	0.3	0.0
37	R	.&I	RT R&I mirror		0	0.00	0.3	0.0
38	R	.&I	RT Handle, outside black		0	0.00	0.3	0.0
39	R	.&I	RT R&I trim panel		0	0.00	0.4	0.0

Customer: STATE OF IOWA

2015 CHEV Silverado 2500 HD Work Truck Crew Cab 167.7" WB 4WD 4D LONG 8-6.0L Flex Fuel Electronic Fuel Injection WHITE

				SUBTOTALS		2,143.87	35.3	23.0
59	#	Refn	Prime and Block		0	0.00	0.0	1.0
58	#	Repl	Corrosion Protection		1	5.00	0.0	0.0
57	#	Repl	Cover Car		1	5.00	0.0	0.0
56	#		Hazardous waste removal		1	5.00	0.0	0.0
55	**	Repl	A/M Seam Sealer		1	10.00 T	0.5	0.0
54	#	Rpr	Rope Windshield		0	0.00	0.3	0.0
53	*	Repl	LKQ RT Tail lamp assy +25%	84288723	1	221.25	<u>0.3</u>	0.0
52	REAR LAMPS							
51		R&I	RT Upper trim		0	0.00	0.2	0.0
50		R&I	RT R&I trim panel		0	0.00	0.4	0.0
49		R&I	RT Handle, outside black		0	0.00	0.3	0.0
48		R&I	RT-Run w'strip		0	0.00	0.3	0.0
47		R&I	RT Door glass GM w/o deep tint		0	0.00	0.3	0.0
46		R&I	RT Belt molding black		0	0.00	0.3	0.0
45	*		Add for Clear Coat		0	0.00	0.0	0.4
44			Overlap Major Adj. Panel		0	0.00	0.0	-0.4
43	*	Rpr	RT Outer panel		0	0.00	2.0	2.4
42	REAR DOOR							
41	#	Rpr	Remove decal		0	0.00	0.5	0.0
40		R&I	RT Upper trim		0	0.00	0.2	0.0

NOTES

Estimate Notes:

Windshield may need to be taken out to do repair, unsure at this time.

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				2,133.87
Body Labor	35.3 hrs	@	\$ 66.00 /hr	2,329.80
Paint Labor	23.0 hrs	@	\$ 108.00 /hr	2,484.00
Miscellaneous				10.00
Subtotal				6,957.67
Grand Total				6,957.67

MyPriceLink Estimate ID / Quote ID:

1222944138463289344 /

Customer: STATE OF IOWA

2015 CHEV Silverado 2500 HD Work Truck Crew Cab 167.7" WB 4WD 4D LONG 8-6.0L Flex Fuel Electronic Fuel Injection WHITE

WARRANTY VALID ONLY WITH ORIGIONAL COPY OF YOUR RECEIPT PARTS SUBJECT TO INVOICE NO GUARANTEE ON RUST ALL PARTS NEW, UNLESS OTHERWISE NOTED

HIRING AUTO BODY TECHNICIANS! OFFERING TOP FLAT RATE PAY!

Have a high schooler interested in becoming a body technician or painter? ASK ABOUT OUR TUTION REIMBURSMENT PROGRAM! CONTACT: Taylor Weber at tweber@abraauto.com

WARRANTY VALID ONLY WITH ORIGIONAL COPY OF RECEIPT. PARTS SUBJECT TO INVOICE. NO GUARANTEES ON RUST. ALL PARTS NEW, UNLESS OTHERWISE SPECIFIED.

HIRING AUTO BODY TECHNICIANS! OFFERING TOP FLAT RATE PAY!

Have a high schooler interested in becoming a body technician or painter? ASK ABOUT OUR TUTION REIMBURSMENT PROGRAM! CONTACT: Taylor Weber at tweber@abraauto.com

Customer: STATE OF IOWA

2015 CHEV Silverado 2500 HD Work Truck Crew Cab 167.7" WB 4WD 4D LONG 8-6.0L Flex Fuel Electronic Fuel Injection WHITE

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR1GH15, CCC Data Date 05/16/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Customer: STATE OF IOWA

2015 CHEV Silverado 2500 HD Work Truck Crew Cab 167.7" WB 4WD 4D LONG 8-6.0L Flex Fuel Electronic Fuel Injection WHITE

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
10	Keystone, Inc	#GM1230446PP	\$ 737.00
	2400 KERPER BLVD., SUITE E100A	A/M CAPA Hood	
	DUBUQUE IA 52001	Quote: 2515979026	
	(563) 556-5030	Expires: 07/07/24	
14	Keystone, Inc	#GM1241385PP	\$ 690.00
	2400 KERPER BLVD., SUITE E100A	A/M CAPA RT Fender	
	DUBUQUE IA 52001	Quote: 2515980445	
	(563) 556-5030	Expires: 07/07/24	
53	LKQ Corp	#~379213451	\$ 177.00
	2101 Beloit Avenue	LKQ RT Tail lamp assy +25%	
	Janesville WI 53546	Tail Lamp R, W/O HIGH DESERT PACKAGE; W/O LED; PICKUP (WITH BOX), R.,S#\$N0484	
	(800) 362-9451	Quote: 2516009062	
		Expires: 07/07/24	