MEMBERS OF COUNCIL

HON. KIM REYNOLDS
GOVERNOR

HON. PAUL D. PATE
SECRETARY OF STATE

HON. ROB SAND
AUDITOR OF STATE

HON. ROBY SMITH
TREASURER OF STATE

HON. MIKE NAIG
SECRETARY OF AGRICULTURE

Executive Council of Iowa

CAPITOL BUILDING
DES MOINES, IOWA 50319
PHONE: 515 281-5368
FAX: 515 281-7562

October 5, 2026

Accounting Department
Office of the Treasurer
Lucas Building
321 E 12th Street
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of $4,660.80, subject to an audit of actual invoices. On August 16, 2026, Vehicle #64 was damaged by vandalism. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Kristi Onstot

Kristi Onstot
Executive Secretary

cc: Kyle Wear, DAS Fleet Chief Financial Officer
Ryan Betts, Fleet Services Risk Program Manager
Matt Bender, Department of Management
Heather Hackbarth, Department of Management

AOS Claim # 4494
TOS Job # ____

OFFICE OF AUDITOR OF STATE
STATE OF IOWA

State Capitol Building
Des Moines, Iowa 50319-0006

Telephone (515) 281-5834
www.auditor.iowa.gov

Rob Sand
Auditor of State

September 17, 2026

Kristi Onstot
Executive Council

Subject: Vandalism Damage to Vehicle #64 on August 16, 2026
Department of Administrative Services
Claim dated August 17, 2026
AOS Claim ID: 4494

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of $4,660.80, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA
Deputy Auditor of State

cc: Kyle Wear, Fleet Services CFO, Department of Administrative Services
Ryan Betts, Fleet Services Risk Program Manager, Department of Administrative Services
Heather Hackbarth, Department of Management

Claim: C270037 as of 08/24/2026

Claim Number	DAS Vehicle Number	State Driver	Vehicle Agency	Loss Date	Status	Total Incurred
C270037	64-240979	Rodriguez, Justin	Public Safety - Administrative Services	08/16/2026	Open	0.00

ADMIN Only Claim Status

Overall Claim Status	New	Total Loss Status	
Overall Claim Status Date	08/24/2026	Total Loss Status Date	
Overall Incident Status	Closed-Claim Created	Restitution Status	
Overall Incident Status Date	08/24/2026	Restitution Status Date	
29C20 Status	Allocation Requested	Subrogation Status	
29C20 Status Date	08/24/2026	Subrogation Status Date	
Repair Status	Under Review	TORT Status	
Repair Status Date	08/24/2026	TORT Status Date	

ADMIN Only

Notification Date	08/24/2026 11:32 AM	Potential Tort?	No
Entry User	Ryan Betts	29C20 Claim?	Yes
Historical Claim?	No	Subrogation?	No
Group ID		Restitution?	No
		Total Loss?	No
Accident Type	Vandalism	SOI Driver at Fault?	No
Accident Type Description			
Object Struck		Driver's Agency	595-1 - Public Safety - Administrative Services
Object Struck Description		Driver's Agency Number	595
Contributing Circumstances	01-None Apparent	Driver's Agency Name	DPS
		Driver's Agency Email	jadams@dps.state.ia.us
Accident Description ADMIN	DPS vehicle vandalism/keyed while parked at Iowa State Fair.	Vehicle's Agency	595-1 - Public Safety - Administrative Services
		Vehicle's Agency Number	595
Incident Review Date	08/17/2026 Populating this field will send an alert to the Driver's Agency Fleet contact that an accident has occurred	Vehicle's Agency Name	DPS
		Vehicle's Agency Email	jadams@dps.state.ia.us

Estimate Approvals

Add Estimate

Entry Date	Estimate Type	Estimate Amount	Approved Estimate Amount	Body Shop Name	MA Number	CRS Claim?	
08/24/2026 11:36 AM	Initial Estimate	4,660.80		Calibur Collision		No	✖
		4,660.80					

ADMIN Only Invoicing

Repair Costs

Bodyshop Repair Amount	
Towing Amount	
Storage Amount	
Other Amount	
Final Total	0.00

Triggers creation/email of Payment Request Cover Sheet (REP5)

Bodyshop Payment Date	
Bodyshop Name	
Bodyshop MA Number	
Communication Preference	

ADMIN Only 29C20

Triggers Initial Notification to AOS from the Incident Form!!

Claim Type	Vandalism
AOS Notification Date	08/17/2026

Triggers Allocation Request to AOS (AON2)

Triggers Reimbursement Request to AOS (AON4-Standard or AON5-Total Loss)

Reimbursement Request Date	
Reimbursement Amount Requested	

Allocation Request Date 08/24/2026

Allocation Request Amount 4,660.80

Triggers 29C20 status update only (AON3)

AOS Recommendation date

AOS Claim Number

Triggers 29C20 Status update only (AON6)

Reimbursement Letter Received Date

Other Information

29C20 Notes

ADMIN Only Total Loss

Triggers ACV Request (TL1)

Total Loss NADA Amount

Total Loss ACV Request Date

Triggers Vehicle Prep email to DPS or Driver (TL2)

Is equipment teardown needed?

Vehicle Prep Request Date

Does the Vehicle have a GPS Unit?

Triggers Dispatch to Auction email (TL3)

Has the Inspection Report been completed?

Dispatched to Auction Date

Current Vehicle Location Name

Current Vehicle Location Address

Current Vehicle Location City

Current Vehicle Location State

Current Vehicle Location Zipcode

Current Vehicle Location Phone

Triggers tasks for any special handling (TL5)

Total Loss ACV Amount

Total Loss Salvage Amount

Total Loss Vehicle Sold Date

Other Information

Special Instructions

› Admin Only - Tort Claims

› Admin Only - Restitution

⌄ ADMIN Only Subrogation

Triggers Subrogation Request email to Insurance Company (SUB2)

Subrogation Request Date

Total Subrogation Demand

Subrogation Vehicle Owner

Subrogation Insurance

Triggers Subrogation Acceptance email to Insurance Company (SUB3)

Subrogation Acceptance Date

Subrogee Claim Number

Accepted Subrogation amount

Other Information

Subrogation Notes

⌄ ADMIN Only CRS Info

CRS Claim Created

CRS Department Name

CRS Claimants

CRS Claim Created

CRS Claim Type

CRS Fee

CRS Date of Loss	
CRS Reviewed	
CRS Review Notes	

Accident Details

Claim Number	C270037
Claimant	Rodriguez, Justin
Accident Date	08/16/2026
Accident Time	1:30 AM
Accident Street/Location	Iowa State Fair
Accident City	Des Moines
Accident State	Iowa
Accident Postal	50319
Accident County	Polk
Incident Contact Email Address	jadams@dps.state.ia.us
DSP Incident?	Yes
More than 1 driver involved?	No
More than 1 vehicle involved?	No
Accident Description Quick	Keyed Car
Accident Description Full	Trooper Rodriguez #64 was assigned to work nightshift at the Iowa State Fair on 8/16/2026. We had a report of damage on Trooper Trail's patrol car earlier in the day. Troopers were advised to look at their cars and check for damage. Around 01:37 AM Trooper Rodrigues observed a large scratch on the front bumper, rear bumper and mirror of his patrol car that caused damage to the paint. The patrol car was parked in Prairie Meadows Parking Lot.

Click **Edit Collision Diagram** below to complete an a diagram of the accident.

State Driver Details

Driver's First Name	Justin
Driver's Last Name	Rodriguez
Drivers License Number	999AA9999
Drivers License State	Iowa
Driver's DoB	01/01/1900
Driver's Phone Number	(999) 999-9999

Other Driver Details

Driver 2 First Name	
Driver 2 Last Name	
Driver 2 License Number	
Driver 2 License State	
Driver 2 DoB	
Driver 2 Phone Number	
Driver 2 Email Address	

State Vehicle Details

Vehicle	2C3CDXKG7NH240979
DAS Vehicle Number	64-240979
Vehicle License Plate Number (if different than vehicle number)	
VIN	2C3CDXKG7NH240979
Vehicle Year	2022
Vehicle Make	DODGE
Vehicle Model	CHARGER
Fund Source	
Tow Required?	No
Towed by what Company?	
Towed to where?	
Vehicle Mileage	107,568
Brief Description of Vehicle Damage	Vandalism/scratches on front, back and mirrors of vehicle.

Other Vehicle Details

Vehicle 2 License Plate Number	
Vehicle 2 VIN	
Vehicle 2 Year	
Vehicle 2 Make	
Vehicle 2 Model	
Vehicle 2 Require Tow	
Vehicle 2 Towed by what Company?	
Vehicle 2 Towed to where?	
Vehicle 2 Mileage	
Vehicle 2 Description of Damage	

Other Vehicle Insurance Information

Insurance Company Name	
Address	
City	
State	
Zipcode	
Agent's Name	
Agent's Phone	
Agent's Email	
Policy #	

Conditions

Location Type	01-Business District (Central)	Surface Conditions	08-Unknown
Weather Conditions	09-Unknown	Vision Obscured	15-Other (Explain in Narrative)
Light Conditions	05-Darkness-Roadway Not Lighted	Apparent Driver Conditions	12-Other (Explain in Narrative)
		Other Comments from Driver	vandalism occurred while vehicle was parked, unoccupied, and with no known witnesses.

Was anyone Injured?

Were you Injured?	No
Was anyone else injured?	No

Where there any Witnesses?

Were there any Witnesses?	No
If yes, were you able to collect their information?	
If you weren't able to collect their information, why not?	

Witness List

Was any Property Damaged other than the Vehicles listed above?

Was any property damaged	No

Attach photos or other incident related documents.

Upload File

File Name	Folder	Document Type	Description
AON Initial Notification 2026-07-27.pdf	29C20	29C20 Initial Notification	
MEMORANDUM 8.17.26 (1).docx	Accident Details	Memos/Other Docs	
Trp Rodriguez #64 State Vehicle Damage Rpt form (1).doc	Accident Details	Memos/Other Docs	
Estimate (17).pdf	Estimates	Estimate - Initial	
IMG_0323.jpeg	Accident Details	Accident Photos	
IMG_0316.jpeg	Accident Details	Accident Photos	
29C20 Allocation Request Summary - 2026-07-27.pdf	29C20	29C20 Allocation Request Summary	

Key Workflow Contacts

Fleet Admin MGR Contact	Fucaloro, Mariah
Fleet Admin Contact	Betts, Ryan
Fleet Finance Contact	Wear, Kyle
Fleet Inbox	Betts, Ryan
AOS 29C20 Contact	AOS,
TOS 29C20 Contact	ExecutiveCouncil@TOS.Iowa.Gov,
DPS Primary Contact	Adams, Jeannie
Fleet Salvage Dispatch Contact	Kieffer, Michelle
Fleet MA Contact	Rudawski, Michael
Finance Invoice Payment Contact	DAS, Finance
Environment	

Files

File	Description	Folder	Attached By	Attach Date	Size
29C20 Allocation Request Summary - 2026-07-27.pdf		29C20	Ryan Betts	08/24/2026	157kb
IMG_0316.jpeg		Accident Details	Ryan Betts	08/24/2026	12757kb
IMG_0323.jpeg		Accident Details	Ryan Betts	08/24/2026	13927kb
Estimate (17).pdf		Estimates	Ryan Betts	08/24/2026	177kb
Estimate (17).pdf		Estimates	Ryan Betts	08/24/2026	177kb
Trp Rodriguez #64 State Vehicle Damage Rpt form (1).doc		Accident Details	Ryan Betts	08/24/2026	99kb
Trp Rodriguez #64 State Vehicle Damage Rpt form (1).doc		Accident Details	Ryan Betts	08/24/2026	99kb
MEMORANDUM 8.17.26 (1).docx		Accident Details	Ryan Betts	08/24/2026	18kb
MEMORANDUM 8.17.26 (1).docx		Accident Details	Ryan Betts	08/24/2026	18kb
AON Initial Notification 2026-07-27.pdf		29C20	Ryan Betts	08/17/2026	168kb
AON Initial Notification 2026-07-27.pdf		29C20	Ryan Betts	08/17/2026	168kb

Images

IMG_0316.jpeg



IMG_0323.jpeg



IOWA | Department of Administrative Services

KIM REYNOLDS, GOVERNOR
CHRIS COURNOYER, LT. GOVERNOR

MARK CAMPBELL, DIRECTOR

Date: August 17, 2026

To: AOS, Auditor of State

Executive Council, Treasurer of State

Re: 29C20 Initial Notification

Vehicle / Event	64-240979 / Vandalism
Event Date	08/16/2026 at 1:30 AM
Summary	DPS vehicle vandalism/keyed while parked at Iowa State Fair.
State Driver	Justin Rodriguez

This document provides the initial 24 hour notification for an AON claim and provides the high level details provided in the initial report.

Additional details will be forthcoming from DAS Fleet Risk Management.

If you have any questions or concerns, please do not hesitate to contact me.

Thank you.

Ryan Betts
Fleet Services Risk Program Manager
Iowa Department of Administrative Services
510 E 12th Street, Des Moines, IA 50319
(515) 281-8008
das.risk@das.iowa.gov

CALIBER COLLISION

CALIBER - MARION

RESTORING THE RHYTHM OF YOUR LIFE
1075 Lyons Lane, MARION, IA 52302
Phone: (319) 432-0021
FAX: (319) 432-0022

Workfile ID:	0854187a
Federal ID:	33-0730794
State ID:	33-0730794
Federal EPA:	N/A
State EPA:	N/A

Preliminary Estimate

Customer: Iowa State Patrol

Written By: Gabrielle Bavaro, -

Insured:	Iowa State Patrol	Policy #:		Claim #:	STATEPATROL08212026
Type of Loss:		Date of Loss:		Days to Repair:	0
Point of Impact:	19 All Over				

Owner:
Iowa State Patrol
(319) 931-4932 Business

Inspection Location:
CALIBER - MARION
1075 Lyons Lane
MARION, IA 52302
Repair Facility
(319) 432-0021 Business

Insurance Company:
CUSTOMER PAY

VEHICLE

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Granite Pearlcoat

VIN:	2C3CDXKG7NH240979	Interior Color:	Black	Mileage In:	107,568	Vehicle Out:	
License:	64	Exterior Color:	Granite Pearlcoat	Mileage Out:			
State:	IA	Production Date:	10/2022	Condition:		Job #:	

TRANSMISSION
Automatic Transmission
4 Wheel Drive

POWER
Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat
Power Adjustable Pedals

DECOR
Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE
Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera
Parking Sensors

RADIO
AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY
Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device
Blind Spot Detection

SEATS
Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS
Styled Steel Wheels

PAINT
Clear Coat Paint

OTHER
Traction Control
Stability Control
California Emissions

Customer: Iowa State Patrol

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Granite Pearlcoat

Line		Oper	Description	Part Number	Qty	Extended Price $		Labor	Paint
1	#		ESTIMATE SUBJECT TO CHANGE, THIS IS NOT A FINAL BILL		1				
2	**FRONT BUMPER & GRILLE**								
3		R&I	R&I bumper cover					1.9	
4	* <>	Rpr	Bumper cover					3.7	3.4
			Note: sand out and repair crack in ft bumper cover, cracked						
5			Add for Clear Coat						1.4
6		Repl	Add for fog lamps		1			0.3	
7	#		Adhesion Promoter		1	15.00	T	0.1	
8	*	R&I	Lower grille w/o adaptive cruise					0.3	
9		R&I	Closure panel					0.1	
10		R&I	License bracket w/o SRT					0.1	
11	*	R&I	Bezel					0.1	
12		R&I	Upper grille black crossbars					0.7	
13	#	R&I	brush guard					2.0	
14	**ELECTRICAL**								
15		R&I	Camera all				m	0.1	
16	**FRONT DOOR**								
17	*	Rpr	LT Outer panel (HSS)					0.5	2.1
			Note: repair chip on door edge						
18			Overlap Major Non-Adj. Panel						-0.2
19			Add for Clear Coat						0.4
20	#	Repl	Corrosion Protection / Primer		1	15.00	T	0.3	
21		R&I	LT Belt w'strip					0.3	
22	*	R&I	LT Power mirror					0.6	
23		R&I	LT Handle, outside granite					0.4	
24		R&I	LT R&I trim panel					0.5	
25	#	Subl	re-wrap "iowa state patrol"		1	150.00	T		
			Note: per inv						
26	*	R&I	LT Door w'strip					0.3	
			Note: time reduced to drop top for proper refinish of roof rail						
27	**REAR DOOR**								
28	*	Rpr	LT Door shell w/o wide body (HSS)					2.0	2.0
			Note: repair scratches spanning across rear door						
29			Overlap Major Adj. Panel						-0.4
30			Add for Clear Coat						0.3
31	#		Mask for Primer		1	12.00	T	0.3	
32	#	Repl	Cavity Wax		1	18.00	T	0.5	
33		R&I	LT Belt w'strip					0.3	
34		R&I	LT Handle, outside granite					0.4	
35		R&I	LT R&I trim panel					0.5	
36	*	R&I	LT Door w'strip					0.3	
			Note: time reduced for drop top for proper pillar refinish						

Customer: Iowa State Patrol

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Granite Pearlcoat

37	**QUARTER PANEL**							
38	*	Blnd	LT Quarter panel w/o wide body					2.6
39		R&I	LT Wheelhouse liner w/o vented bumper				0.4	
40	*	Blnd	Fuel door					0.3
41	#	Subl	re-wrap american flag	1	100.00	T		
			Note: per invoice					
42	#	R&I	light bar				2.0	
43	#	Refn	Left Roof Rail Clear Only					0.8
44	*	Rpr	RT Quarter panel w/o wide body				1.5	2.6
			Note: scratch in clear coat, fairly deep, however may buff as it is not past the clear coat. I already spent some time buffing and got most out, if sanding and buffing doesn't work out and we cut past through the clear, we will have to refinish the full quarter panel					
45			Overlap Major Non-Adj. Panel					-0.2
46	*		Add for Clear Coat					0.5
47	**TRUNK LID**							
48	*	Rpr	Trunk lid all				1.5	2.3
			Note: time to sand out scratches					
49			Overlap Major Adj. Panel					-0.4
50	*		Add for Clear Coat					0.4
51	#	R&I	3 antennas				2.0	
52		R&I	Trunk lid trim				0.3	
53	**REAR LAMPS**							
54		R&I	LT Tail lamp assy				0.3	
55		R&I	Backup lamp				0.3	
56	**REAR BUMPER**							
57		R&I	R&I bumper cover				1.2	
58	**VEHICLE DIAGNOSTICS**							
59	#		Pre-repair scan	1	40.00	X	0.5	
60	#		Post-repair scan	1	80.00	X	0.5	
61	#	Subl	Hazardous Waste Disposal	1	12.00	T		
62	#		Cover Car for Overspray	1	12.00	T	0.3	
			SUBTOTALS		**454.00**		**27.4**	**17.9**

Customer: Iowa State Patrol

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Granite Pearlcoat

ESTIMATE TOTALS

Category	Basis		Rate	Cost $
Parts				0.00
Body Labor	27.4 hrs	@	$ 77.00 /hr	2,109.80
Paint Labor	17.9 hrs	@	$ 77.00 /hr	1,378.30
Paint Supplies	17.9 hrs	@	$ 51.00 /hr	912.90
Miscellaneous				454.00
Pre-Tax Discount			-4.0 %	-194.20
Subtotal				4,660.80
Sales Tax	$ 4,545.60	@	7.0000 %	318.19
Grand Total				**4,978.99**

==========

Caliber Collision is the industry leader in quality collision repair. Since day one, our highest purpose has been to get people just like you back on the road as quickly as possible and fully restored to the rhythm of your life. You can be sure we do everything possible to ensure your complete satisfaction including:

Personalized, high quality service from the largest collision repair company in the U.S.
Consistently ranked among the highest customer satisfaction scores in the industry.
Approved by every major insurance company in the U.S.
Expedited car rental and towing services to get you back on the road again in no time.
Repair work backed by a written, lifetime warranty honored at every location.
24/7/365 customer service to answer questions and put your mind at ease.

This is a preliminary estimate based on visible damage. There may be additional repairs needed once the vehicle is taken apart by our I-CAR Gold Class technicians to identify any additional damage.

If an insurance company has written an estimate for you, please provide us with a copy. Properly endorsed insurance company checks are welcome as payment for the repair of your vehicle. Caliber Collision gladly accepts all major credit cards, debit cards, cashier's and traveler's checks. See your Caliber Collision center for details on acceptance of personal checks.

Before leaving your vehicle with us, please remove all important personal and valuable items from your vehicle. Caliber Collision is not responsible for belongings left in your vehicle.

Please let us know how we can be of further assistance, and when we can schedule an appointment for your vehicle to be repaired.

Caliber Collision - Restoring The Rhythm Of Your Life

==========

Customer: Iowa State Patrol

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Granite Pearlcoat

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 08/10/2026, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:
m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:
D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:
Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:
BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

IOWA | Department of Administrative Services

KIM REYNOLDS, GOVERNOR
CHRIS COURNOYER, LT. GOVERNOR

MARK CAMPBELL, DIRECTOR

Date: August 24, 2026

To: AOS, Auditor of State
Executive Council, Treasurer of State

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	64-240979 / Vandalism
Event Date:	08/16/2026 at 1:30 AM
Summary	DPS vehicle vandalism/keyed while parked at Iowa State Fair.
Amount Requested	4,660.80
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Ryan Betts
Fleet Services Risk Program Manager
Iowa Department of Administrative Services
510 E 12th Street, Des Moines, IA 50319
Office Phone: (515) 281-8008
das.risk@das.iowa.gov