



Governor Kim Reynolds  
Lt. Governor Adam Gregg  
Adam Steen, Director

Date: July 29, 2021

To: Tammy Hollingsworth, Auditor of State  
Victoria Newton, Treasurer of State  
Executive Council

From: Mariah Flowers, Risk Coordinator  
DAS Fleet Services  
Department of Administrative Services

**Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration**

Vehicle / Event	#309, 561, 774, 101, 212/Hail
Event Date	July 9, 2021
Summary	Vehicles sustained hail damage. (Fleet Ref# 223213, 223531, 223216, 223239, 223278)
Amount Requested	\$13,987 - Estimates
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Risk Coordinator  
DAS Fleet Services  
[Mariah.Flowers@iowa.gov](mailto:Mariah.Flowers@iowa.gov)  
515-725-2243



Risk, DAS <das.risk@iowa.gov>

223213

1350-15

**Fwd: LT. Lampe - Vehicle Damage (Hail)**

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Jul 19, 2021 at 11:50 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS Executive Council <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 309 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



**DAS Fleet Services, Risk**

Iowa Department of Administrative Services  
Division of Business and Property Services  
Office: 515-725-2243  
Das.Risk@iowa.gov  
<https://das.iowa.gov>

----- Forwarded message -----

From: Risk, DAS <das.risk@iowa.gov>

Date: Mon, Jul 19, 2021 at 11:41 AM

Subject: Fwd: LT. Lampe - Vehicle Damage (Hail)

To: Electronic Claims <eclaims@creativerisksolutions.com>

Vehicle 309  
Agency 595

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



**DAS Fleet Services, Risk**

Iowa Department of Administrative Services  
Division of Business and Property Services  
Office: 515-725-2243  
Das.Risk@iowa.gov  
<https://das.iowa.gov>

----- Forwarded message -----

From: Lampe Benjamin <blampe@dps.state.ia.us>

Date: Fri, Jul 16, 2021 at 8:27 AM

Subject: LT. Lampe - Vehicle Damage (Hail)

To: DAS Risk <das.risk@iowa.gov>, vehicledamage <vehicledamage@dps.state.ia.us>  
Cc: Guill Bryan <guill@dps.state.ia.us>, Current Michael <current@dps.state.ia.us>, Adams Jeannie <jadams@dps.state.ia.us>, Tjepkes Brett <tjepkes@dps.state.ia.us>

All Concerned –

Please see my attached SVD Report and supporting documents. The photos don't really show much since I couldn't get in the right light, but Sullivan's Auto Body took some better photos to document it better. Let me know when I can get this fixed and if you need anything else.

Respectfully,

*Lt. Ben Lampe #309*

Bureau Chief,


Professional Development Bureau

215 E. 7<sup>th</sup> Street

Des Moines, IA 50319


Office: 515-725-6276

Cell: 515-443-6134




---

**6 attachments**



**IMG\_0046.JPG**  
53K

**IMG\_0049.JPG**



32K



IMG\_0047.JPG

63K



**Lt. Lampe - State Vehicle Damage Report (Hail 7-09-2021).doc**  
88K



**Lampe - Hail Damage Estimate (July 2021).pdf**  
406K



**Lampe Memo - Act of Nature Memo (Hail - July 2021).pdf**  
215K



## State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: [vehicledamage@dps.state.ia.us](mailto:vehicledamage@dps.state.ia.us) ; [das.risk@iowa.gov](mailto:das.risk@iowa.gov)

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

### STATE VEHICLE: (Mark if Act of Nature ☒ ) CASE #: 2021016414

Date: (Month/Day/Year)	July 9 <sup>th</sup> , 2021	Time: (Time plus a.m./p.m.)	2:00 PM
Vehicle Plate #:	JXN327	Vehicle Mileage:	58,665
Vehicle Description: (Yr/Make/Model/ & Vin#)	2019 Dodge Charger Police (Unmarked) VIN#: 2CECDXKT0KH622778		
Assigned To:	Lt. Ben Lampe	Badge #	#309
Driven By:	Parked	Badge #	
Driver's Lic #:	751YY6755	Damage:	\$1,350.15
Vehicle Towed: (Yes / No)	N/A	Towed By:	N/A
Towed To:		Towing Cost:	\$
Seat Belt: (Yes / No)	N/A	Type of Vehicle: (Marked/Semi /Unmarked)	Unmarked
Injured/Injuries:	N/A		
Occupants: (Other than driver)	None (parked)		

### VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

### OTHER INFORMATION:

Witnesses:	S/A Doug Hurley
Accident Location: (Street/Hwy)	Parked in DPS HQ Parking Lot
County:	Polk
Weather/Road Conditions:	Thunderstorm, winds and large hail
<p>On Friday, July 9<sup>th</sup>, 2021, while working at the DPS Headquarters my assigned patrol car was parked outside in the parking lot. At approximately 1400 hours, the Des Moines area was hit with a severe thunderstorm with hail (quarter to golf ball size and larger). My patrol car did sustain significant hail damage.</p>	
Property Damage other than Vehicles:	None
Cost:	
Citations Issued To: (List Charge(s) and Statute Code(s))	

Investigating Officer:	
------------------------	--

### VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

**SULLIVAN AUTO BODY INC.**

1400 S 5th Ave E, Newton, IA 50208

Phone: (641) 792-2006

FAX: (641) 792-1458

Workfile ID: 248d33d5

PartsShare: 6kPLYQ

Federal ID: 42-1370211

Resale Number: 1-50-009555

**Preliminary Estimate****Customer: IOWA HIGHWAY PATROL**

Written By: Pat Sullivan

**JXN 327**

Insured: IOWA HIGHWAY PATROL

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact: 27 Hall

**Owner:**

IOWA HIGHWAY PATROL

DES MOINES, IA

(641) 417-9309 Cell

**Inspection Location:**

SULLIVAN AUTO BODY INC.

1400 S 5th Ave E

Newton, IA 50208

Repair Facility

(641) 792-2006 Business

**Insurance Company:**

STATE OF IOWA

**VEHICLE**

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI GRAY

VIN: 2C3CDXKT0KH622778

Interior Color:

Mileage In: 58,895

Vehicle Out:

License: JXN327

Exterior Color: GRAY

Mileage Out:

State: IA

Production Date: 3/2019

Condition: Excellent

Job #:

**TRANSMISSION**

Automatic Transmission

4 Wheel Drive

**POWER**

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

Power Driver Seat

**DECOR**

Dual Mirrors

Tinted Glass

Overhead Console

**CONVENIENCE**

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Climate Control

Backup Camera

Parking Sensors

**RADIO**

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

**SAFETY**

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

**SEATS**

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

**WHEELS**

Styled Steel Wheels

**PAINT**

Clear Coat Paint

**OTHER**

Traction Control

Stability Control

California Emissions

Power Trunk/Liftgate

Get live updates at [www.carwise.com/e/43Fp4y](http://www.carwise.com/e/43Fp4y)

# Preliminary Estimate

**Customer: IOWA HIGHWAY PATROL**

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI GRAY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		<b>HOOD</b>					
2	R&I	R&I hood assy				0.6	
3	*	PDR Hood (ALU) +25% Note: PDR 10 quarter MARKUP FOR ALUMINUM		1	218.75 T		
4	R&I	Insulator				0.3	
5		<b>FENDER</b>					
6	*	PDR RT Fender Note: PDR 1 dime		1	65.00 T		
7		<b>ROOF</b>					
8	*	PDR Roof panel w/o sunroof Note: PDR 7 half		1	250.00 T		
9	R&I	R&I headliner				3.4	
10		<b>PILLARS, ROCKER &amp; FLOOR</b>					
11	*	PDR LT Aperture panel Note: PDR 2 half		1	125.00 T s		
12		<b>FRONT DOOR</b>					
13	*	PDR LT Door shell (HSS) Note: PDR 1 dime		1	65.00 T		
14		<b>QUARTER PANEL</b>					
15	*	PDR RT Quarter panel Note: PDR 1 dime		1	65.00 T		
16	*	PDR LT Quarter panel Note: PDR 1 quarter		1	100.00 T		
17		<b>TRUNK LID</b>					
18	*	PDR Trunk lid w/police w/camera Note: PDR 4 half		1	125.00 T		
19	#	Repl CORROSION PROTECTION		1	10.00		
20	R&I	R&I trunk lid				0.8	
<b>SUBTOTALS</b>					<b>1,023.75</b>	<b>5.1</b>	<b>0.0</b>

## Preliminary Estimate

### Customer: IOWA HIGHWAY PATROL

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI GRAY

#### ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			10.00
Body Labor	5.1 hrs @	\$ 64.00 /hr	326.40
PDR			1,013.75
Subtotal			1,350.15
<b>Grand Total</b>			<b>1,350.15</b>
Deductible			0.00
<b>CUSTOMER PAY</b>			<b>0.00</b>
<b>INSURANCE PAY</b>			<b>1,350.15</b>

THIS IS AN ESTIMATE ONLY

WORKMANSHIP AND PARTS ARE WARRANTED FOR ONE YEAR. (EXCLUDING BELTS, TIRES, LIGHT BULBS AND NORMAL WEAR ITEMS)

RUST REPAIRS ARE NOT WARRANTED

OUR PPG PAINT SYSTEM HAS A LIMITED LIFETIME WARRANTY ON ALL O.E.M. REPLACEMENT PARTS AND A 7 YEAR LIMITED WARRANTY ON PANELS WITH O.E.M. FINISHES



22531

1135.27

**Fwd: FW: Car 561 DCI, hail estimate and report**

1 message

Risk, DAS &lt;das.risk@iowa.gov&gt;


Thu, Jul 22, 2021 at 1:48 PM

To: Tammy Hollingsworth &lt;Tammy.Hollingsworth@aos.iowa.gov&gt;, TOS Executive Council &lt;executivecouncil@tos.iowa.gov&gt;

Please accept this email as initial 24 hr notification for AON, vehicle 561 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

**DAS Fleet Services, Risk**

Iowa Department of Administrative Services

Division of Business and Property Services

Office: 515-725-2243

Das.Risk@iowa.gov

<https://das.iowa.gov>

----- Forwarded message -----

From: **Adams Jeannie** <jadams@dps.state.ia.us>

Date: Thu, Jul 22, 2021 at 10:38 AM

Subject: FW: Car 561 DCI, hail estimate and report

To: VAFMAILBOX@IOWA.GOV &lt;VAFMAILBOX@iowa.gov&gt;, DAS.Risk (DAS.Risk@iowa.gov) &lt;DAS.Risk@iowa.gov&gt;

Jeannie Adams

ISP Fleet &amp; Supply, Fleet Asset Manager

Department of Public Safety

30 N.E. 48<sup>th</sup> Place

Des Moines, Iowa 50313

Direct #: 515-725-0643

Cell Phone: 515-204-3019

Shop: 515-281-3277

Fax: 515-242-6321

Email: jadams@dps.state.ia.us

**From:** Lamp Scott <selamp@dps.state.ia.us>  
**Sent:** Thursday, July 22, 2021 9:26 AM  
**To:** Adams Jeannie <jadams@dps.state.ia.us>; Guill Bryan <guill@dps.state.ia.us>  
**Cc:** Current Michael <current@dps.state.ia.us>  
**Subject:** Car 561 DCI, hail estimate and report

FYI, this one will be repaired

Scott E. Lamp, M.A. | Special Agent in Charge

Iowa Division of Criminal Investigation - Department of Public Safety

Iowa Department of Public Safety | Division of Criminal Investigation

Support Operations Bureau: Administration//Transcription//CCH Records-Dissemination

Identification//Fingerprints//Training// Equipment//Fleet & Supply

215 East 7<sup>th</sup> Street | Des Moines | Iowa 50319

Office: 515-725-6025 (phone) | Cell: 712-898-0478

State Peace Officer proudly serving since 1994, Badge # I-65


[selamp@dps.state.ia.us](mailto:selamp@dps.state.ia.us)

*Correspondence is Discoverable in State/Federal Courts*

\*NOTICE\* This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain

confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited.

If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message.



---

#### 4 attachments

**Vehicle 561 hail photo 1.jpg**  
64K



**Vehicle 561 hail photo 2.jpg**  
54K

 **State Vehicle Damage Rpt form, 561 hail from 7-09-21.doc**  
105K

 **7-21-21 DCI Car 561 Hail estimate.pdf**  
83K

## State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: [vehicledamage@dps.state.ia.us](mailto:vehicledamage@dps.state.ia.us) ; [das.risk@iowa.gov](mailto:das.risk@iowa.gov)

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

### STATE VEHICLE: (Mark if Act of Nature ☒ ) CASE #:

Date: (Month/Day/Year)	7-09-2021	Time: 3:00pm (Time plus a.m./p.m.)	
Vehicle Plate #:	561	Vehicle Mileage:	51600
Vehicle Description: (Yr/Make/Model/ & Vin#)	2017 Ford Taurus, Four door, VIN is 1FAHP2MK3HG129431		
Assigned To:	Scott Lamp	Badge #	I-65
Driven By:	Scott Lamp	Badge #	I-65
Driver's Lic #:	540xx9335	Damage:	Hail dents
Vehicle Towed: (Yes / No)	NA	Towed By:	
Towed To:		Towing Cost:	
Seat Belt: (Yes / No)		Type of Vehicle: (Marked/Semi /Unmarked)	
Injured/Injuries:			
Occupants: (Other than driver)	NA		

### VEHICLE #2:

DL #:	NONE	State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

**OTHER INFORMATION:**

Witnesses:	NONE
Accident Location: (Street/Hwy)	
County:	
Weather/Road Conditions:	
Vehicle 561 was parked in the Oran Pape lot on 7-09-21 and has two hail dents that will not show up on my photos. Estimate on 7-21-21 from Dent Eliminators is \$1,135.27.	
Property Damage other than Vehicles:	
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	

Investigating Officer:	
------------------------	--

**VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)**

DL #:	NONE	State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			

Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			





**Dent Eliminators**  
<https://www.denteliminators.com/>

**ESTIMATE# 1206**  
 Date: 07/22/2021  
 Estimated By: Dent Eliminators

---

**State Of Iowa**

---

Year: 2017	Vin: 1FAHP2MK3HG129431	Total: <b>\$1,061.00</b>
Make: Ford	Stock/Ro#:	
Model: Taurus	Odometer:	
Color: Black	License:	

**Services Summary:**

**Hail:** \$725.00 - **LT Fender:** \$100.00, **RT Front Door:** \$100.00, **LT Rear Door:** \$150.00, **Roof:** \$150.00, **RT Roof Rail:** \$125.00, **RT Quarter:** \$100.00

**R&I/R&R:** \$336.00 - **LT Fender:** \$24.00, **RT Front Door:** \$24.00, **LT Rear Door:** \$24.00, **Roof:** \$240.00, **RT Quarter:** \$24.00

**Vehicle Notes:** - Car #561

Service Type	Description	Body Hours	Paint Hours	Total
<b>LT Fender</b>				
PDR - \$100.00   R&I - \$24.00				
PDR	1-5 dents, Quarter	-	-	\$100.00
Labor, R&I	Fender Liner	0.4	-	\$24.00
<b>RT Front Door</b>				
PDR - \$100.00   R&I - \$24.00				
PDR	1-5 dents, Quarter	-	-	\$100.00
Labor, R&I	Interior Trim Panel	0.4	-	\$24.00
<b>LT Rear Door</b>				
PDR - \$150.00   R&I - \$24.00				
PDR	6-15 dents, Quarter	-	-	\$150.00
Labor, R&I	Interior Trim Panel	0.4	-	\$24.00
<b>Roof</b>				
PDR - \$150.00   R&I - \$240.00				
PDR	1-5 dents, Quarter	-	-	\$150.00
Labor, R&I	Headliner	3.7	-	\$222.00
Labor, R&I	Antenna	0.3	-	\$18.00
<b>RT Roof Rail</b>				
PDR - \$125.00				
PDR	1-5 dents, Quarter	-	-	\$100.00
Add-On	Glue Pull, 25.0%	-	-	\$25.00
<b>RT Quarter</b>				
PDR - \$100.00   R&I - \$24.00				
PDR	1-5 dents, Quarter	-	-	\$100.00
Labor, R&I	Taillight	0.4	-	\$24.00

---

**Estimate Totals**

Service Type

**PDR****Labor, R&I / R&R**

Rate	Hours	Total
--	--	\$725.00
\$60.00	5.6	\$336.00

**Subtotal: \$1,061.00****Taxable Subtotal: \$1,061.00****Tax Rate Labor (7.00%): \$74.27****ESTIMATE TOTAL: \$1,135.27**

By signing above, I hereby authorize DENT ELIMINATORS to perform the estimated repairs to my vehicle(s), and hereby grant you and/or your employees, permission to operate the vehicle(s) herein described on streets, highways or elsewhere for the purpose of testing and/or inspection and/or transport to the repair location. DENT ELIMINATORS will not be held responsible for loss or damage to the vehicle(s) or any articles left in the vehicle in case of fire, theft, accident or any other cause beyond our control.

---



223216

Risk, DAS <das.risk@iowa.gov>

**Fwd: FW: 774 Vehicle Damage, Hail**

1 message

1889.89

**Risk, DAS** <das.risk@iowa.gov>

Mon, Jul 19, 2021 at 11:55 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 774 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

**All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.**

Thank you,



**DAS Fleet Services, Risk**

Iowa Department of Administrative Services  
Division of Business and Property Services  
Office: 515-725-2243  
Das.Risk@iowa.gov  
<https://das.iowa.gov>

----- Forwarded message -----

From: **Risk, DAS** <das.risk@iowa.gov>

Date: Mon, Jul 19, 2021 at 11:55 AM

Subject: Fwd: FW: 774 Vehicle Damage, Hail

To: Electronic Claims <eclaims@creativerisksolutions.com>

Vehicle 774  
Agency 595

**All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.**

Thank you,



**DAS Fleet Services, Risk**

Iowa Department of Administrative Services  
Division of Business and Property Services  
Office: 515-725-2243  
Das.Risk@iowa.gov  
<https://das.iowa.gov>

----- Forwarded message -----

From: **Adams Jeannie** <jadams@dps.state.ia.us>

Date: Tue, Jul 13, 2021 at 1:18 PM

Subject: FW: 774 Vehicle Damage, Hail

To: vehicledamage <vehicledamage@dps.state.ia.us>, DAS.Risk (DAS.Risk@iowa.gov) <DAS.Risk@iowa.gov>

Jeannie Adams

ISP Fleet & Supply, Fleet Asset Manager

Department of Public Safety

30 N.E. 48<sup>th</sup> Place

Des Moines, Iowa 50313

Direct #: 515-725-0643

Cell Phone: 515-204-3019

Shop: 515-281-3277

Fax: 515-242-6321

Email: jadams@dps.state.ia.us

---

**From:** Humphrey Ronald <humphrey@dps.state.ia.us>

**Sent:** Tuesday, July 13, 2021 8:02 AM

**To:** Lamp Scott <selamp@dps.state.ia.us>; Adams Jeannie <jadams@dps.state.ia.us>; Wood Daniel <wood@dps.state.ia.us>

**Subject:** 774 Vehicle Damage, Hail

Here is the vehicle damage report. As with Shupe's I attempted to take photos but they don't show up. I have 10-15 small/shallow dents on the hood and a few on the roof and topper.

I will get an estimate in the next few days.

Jeannie or Scott,


Is there a shop that you suggest I get the estimate from in the Des Moines Area?

*Ronald A. Humphrey*

Special Agent in Charge//Bomb Squad Commander

Iowa Department of Public Safety

State Fire Marshal Division  
Arson and Explosives Bureau  
215 East 7th Street  
Des Moines, IA 50319  
515-725-6145  
515-725-6172 fax  
humphrey@dps.state.ia.us  
www.dps.state.ia.us



\*NOTICE\* This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

---

**2 attachments**



**Humphrey 7-9-21 State Vehicle Damage Report.doc**  
102K



**Email\_estimate1042\_60ef0aedd351ec0074d43996\_5a6cd9a377a01300279433ba\_1626279072.pdf**  
82K

## State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: [vehicledamage@dps.state.ia.us](mailto:vehicledamage@dps.state.ia.us) ; [das.risk@iowa.gov](mailto:das.risk@iowa.gov)

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

### STATE VEHICLE: (Mark if Act of Nature ☒ ) CASE #:

Date: <small>(Month/Day/Year)</small>	7/9/2021	Time: <small>(Time plus a.m./p.m.)</small>	@2:30 p.m.
Vehicle Plate #:	IJM693	Vehicle Mileage:	21448
Vehicle Description: <small>(Yr/Make/Model/ &amp; Vin#)</small>	2019/Ram/2500 3C6UR5CJ6KG672594		
Assigned To:	Ron Humphrey	Badge #	774
Driven By:	Ron Humphrey	Badge #	774
Driver's Lic #:	678ZZ5501	Damage:	\$
Vehicle Towed: <small>(Yes / No)</small>	No	Towed By:	NA
Towed To:	NA	Towing Cost:	\$
Seat Belt: <small>(Yes / No)</small>	No	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Unmarked
Injured/Injuries:	None		
Occupants: <small>(Other than driver)</small>	None		

### VEHICLE #2:

DL #:	N/A	State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			



Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

### OTHER INFORMATION:

Witnesses:	N/A
Accident Location: (Street/Hwy)	7027 Carey Court Johnston, IA 50131
County:	Polk
Weather/Road Conditions:	Hail Storm, Heavy Rain
<p><b>The vehicle was parked in the driveway of my residence when a hail storm went over. Looking outside the hail stones appeared approximately quarter to pea sized.</b></p> <p>Photos were attempted but the numerous dents are too shallow to show up in photographs.</p>	
Property Damage other than Vehicles:	None
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	N/A

Investigating Officer:	Shupe
------------------------	-------

### VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			



## Dent Eliminators

<https://www.denteliminators.com/>

**ESTIMATE# 1042**

Date: 07/14/2021

Estimated By: Dent Eliminators

---

### Humphrey, Ron

| (515) 208-7648 | [humphrey@dps.state.ia.us](mailto:humphrey@dps.state.ia.us)

---

Year: 2019  
Make: Ram  
Model: Ram Pickup 2500  
Color: Gray

Vin: 3C6UR5CJ6KG672594  
Stock/Ro#:  
Odometer:  
License:

Total: **\$1,766.25**

#### Services Summary:

**Hail:** \$1,406.25 - **Hood:** \$781.25, **Roof:** \$625.00  
**R&I/R&R:** \$360.00 - **Hood:** \$54.00, **Roof:** \$306.00

Service Type	Description	Body Hours	Paint Hours	Total
<b>Hood</b>				
PDR - \$781.25   R&I - \$54.00				
PDR	51-75 dents, Quarter	-	-	\$625.00
Add-On	Aluminum, 25.0%	-	-	\$156.25
Labor, R&I	Insulator	0.3	-	\$18.00
Labor, R&I	Hood	0.6	-	\$36.00
<b>Roof</b>				
PDR - \$625.00   R&I - \$306.00				
PDR	51-75 dents, Quarter	-	-	\$625.00
Labor, R&I	Headliner	2.2	-	\$132.00
Labor, R&I	Antenna	1.2	-	\$72.00
Labor, R&I	Third Brake Light	0.2	-	\$12.00
Labor, R&I	Remove Topper	1.5	-	\$90.00

---

**Estimate Totals**

Service Type	Rate	Hours	Total
<b>PDR</b>	--	--	\$1,406.25
<b>Labor, R&amp;I / R&amp;R</b>	\$60.00	6.0	\$360.00

**Subtotal:** \$1,766.25

**Taxable Subtotal:** \$1,766.25

**Tax Rate Labor (7.00%):** \$123.64

**ESTIMATE TOTAL: \$1,889.89**

By signing above, I hereby authorize DENT ELIMINATORS to perform the estimated repairs to my vehicle(s), and hereby grant you and/or your employees, permission to operate the vehicle(s) herein described on streets, highways or elsewhere for the purpose of testing and/or inspection and/or transport to the repair location. DENT ELIMINATORS will not be held responsible for loss or damage to the vehicle(s) or any articles left in the vehicle in case of fire, theft, accident or any other cause beyond our control.



Risk, DAS <das.risk@iowa.gov>

223239

541269

**Fwd: 101 hail damage estimate**

1 message

**Risk, DAS** <das.risk@iowa.gov>

Mon, Jul 19, 2021 at 1:47 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS Executive Council <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 101 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

**All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.**

Thank you,



**DAS Fleet Services, Risk**

Iowa Department of Administrative Services

Division of Business and Property Services

Office: 515-725-2243

Das.Risk@iowa.gov

<https://das.iowa.gov>

----- Forwarded message -----

From: **Andreasen Jeremy** <andreasen@dps.state.ia.us>

Date: Wed, Jul 14, 2021 at 10:49 AM

Subject: 101 hail damage estimate

To: vehicledamage <vehicledamage@dps.state.ia.us>, das.risk@iowa.gov <das.risk@iowa.gov>

Cc: Halverson David <dhalvers@dps.state.ia.us>, Jalas Dean <jalas@dps.state.ia.us>, Morey Russell <morey@dps.state.ia.us>, Dolf Ryan <dolf@dps.state.ia.us>

Attached are the documents pertaining to Trooper Taeger's hail damage.

Let me know if anything else is needed.

Thanks.

**SERGEANT JEREMY ANDREASEN ★161★**

**Assistant District Commander**

Iowa State Patrol District #13

1300 S. Grand Ave. Suite #201

Mount Pleasant, Iowa 52641

Phone (319) 385-8715

Fax (319) 385-2743

[andreasen@dps.state.ia.us](mailto:andreasen@dps.state.ia.us)



*\*NOTICE\* This email message (including any file attachments transmitted with it) is for the sole use of the intended recipients(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this email in error, please notify the sender by return email and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.*

---

### 3 attachments



**101 State Vehicle Damage Rpt form .doc**  
87K



**101 memo.doc**  
27K



**Unmarked GXB425 Hail Estimate.pdf**  
182K



## State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: [vehicledamage@dps.state.ia.us](mailto:vehicledamage@dps.state.ia.us) ; [das.risk@iowa.gov](mailto:das.risk@iowa.gov)

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

**STATE VEHICLE: (Mark if Act of Nature ☒ ) CASE #: 2021016414**

Date: (Month/Day/Year)	07/09/2021	Time: (Time plus a.m./p.m.)	1900
Vehicle Plate #:	101	Vehicle Mileage:	61,292
Vehicle Description: (Yr/Make/Model/ & Vin#)	2019 Dodge Charger VIN: 2C3CDXKT5KH579541		
Assigned To:	Trp Luke Taeger	Badge #	101
Driven By:	Parked	Badge #	
Driver's Lic #:		Damage:	\$5412.69
Vehicle Towed: (Yes / No)	N/A	Towed By:	
Towed To:		Towing Cost:	\$
Seat Belt: (Yes / No)		Type of Vehicle: (Marked/Semi /Unmarked)	Unmarked
Injured/Injuries:			
Occupants: (Other than driver)	None		

### VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

### OTHER INFORMATION:

Witnesses:			
Accident Location: (Street/Hwy)	11581 Timber Ridge Road West Burlington, IA 52655		
County:	Des Moines		
Weather/Road Conditions:	Damaging storm with hail		
On the evening of 07/09/21 a heavy storm with hail affected the area of Trooper Luke Taeger's residence in Des Moines County. When he reported for duty the next day, Trooper Taeger noticed the hail damage to his patrol car which was parked outside his residence during the storm.			
Property Damage other than Vehicles:	None		
Cost:			
Citations Issued To: (List Charge(s) and Statute Code(s))			

Investigating Officer:	SGT Andreasen #161
------------------------	--------------------

### VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

**COPELAND AUTO BODY, INC.**

506 E 2nd St, P.O. Box 109, Hedrick, IA 52563  
Phone: (641) 653-2140  
FAX: (641) 653-4301

Workfile ID: 6d5446b8  
PartsShare: 6kHNrs  
Federal ID: 42-1488559

**Preliminary Estimate****Customer: State Of Iowa****Job Number:**

Written By: Steve Copeland

Insured: State Of Iowa  
Type of Loss:  
Point of Impact: 27 Hail

Policy #:  
Date of Loss:

Claim #: UNMARKED GXB425 HAIL  
Days to Repair: 0

**Owner:**

State Of Iowa  
301 E 7th St  
Des Moines, IA 50319  
(319) 385-8715 Business

**Inspection Location:**

COPELAND AUTO BODY, INC.  
506 E 2nd St  
P.O. Box 109  
Hedrick, IA 52563  
Repair Facility  
(641) 653-2140 Business

**Insurance Company:**

Creative Risk Solutions

**VEHICLE**

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Navy Blue

VIN: 2C3CDXKT5KH579541	Interior Color: Black	Mileage In: 61,805	Vehicle Out:
License: GXB425	Exterior Color: Navy Blue	Mileage Out:	
State: IA	Production Date:	Condition: Good	Job #:

**TRANSMISSION**

Automatic Transmission  
4 Wheel Drive

**POWER**

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors  
Power Driver Seat

**DECOR**

Dual Mirrors  
Tinted Glass  
Overhead Console

**CONVENIENCE**

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Keyless Entry  
Message Center  
Steering Wheel Touch Controls  
Telescopic Wheel  
Climate Control  
Backup Camera  
Parking Sensors

**RADIO****AM Radio**

FM Radio  
Stereo  
Search/Seek  
Auxiliary Audio Connection

**SAFETY**

Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)  
4 Wheel Disc Brakes  
Front Side Impact Air Bags  
Head/Curtain Air Bags  
Hands Free Device

**SEATS****Cloth Seats**

Bucket Seats  
Reclining/Lounge Seats

**WHEELS**

Styled Steel Wheels

**PAINT**

Clear Coat Paint

**OTHER**

Traction Control  
Stability Control  
California Emissions  
Power Trunk/Liftgate

Get live updates at [www.carwise.com/e/43BBbd](http://www.carwise.com/e/43BBbd)

# Preliminary Estimate

**Customer: State Of Iowa**

**Job Number:**

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Navy Blue

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		<b>FRONT LAMPS</b>					
2	R&I	RT R&I headlamp assy				0.3	
3	R&I	LT R&I headlamp assy				0.3	
4		<b>HOOD</b>					
5	*	PDR Hood (ALU) Note: PDR 20 dime, 15 nickel, 5 quarter, 20 half		1	<u>750.00</u>		
6	#	Aluminum Upcharge (Hood) (25%)		1	187.50		
7	#	Oversize Dents (\$40 each) (4 items)		1	160.00		
8	R&I	R&I hood assy				0.6	
9	R&I	Insulator				0.3	
10		<b>FENDER</b>					
11	*	PDR LT Fender Note: PDR 5 quarter		1	<u>100.00</u>		
12	*	PDR RT Fender Note: PDR 10 quarter		1	<u>150.00</u>		
13		<b>ROOF</b>					
14	*	PDR Roof panel w/o sunroof Note: PDR 10 dime, 10 nickel, 10 quarter, 10 half		1	<u>850.00</u>		
15	#	Oversize Dents (\$40 each) (4 items)		1	160.00		
16	#	LT Roof Rail		1	325.00		
17	#	RT Roof Rail		1	175.00		
18	R&I	R&I headliner				3.4	
19		<b>FRONT DOOR</b>					
20	*	PDR LT Door shell (HSS) Note: PDR 5 quarter		1	<u>100.00</u>		
21	#	Double Panel/Glue Pull Upcharge (25%)		1	25.00		
22	*	PDR RT Door shell (HSS) Note: PDR 5 nickel, 5 half		1	<u>200.00</u>		
23	#	Double Panel/Glue Pull Upcharge (25%)		1	50.00		
24		<b>REAR DOOR</b>					
25	*	PDR LT Door shell (HSS) Note: PDR 5 nickel, 5 half		1	<u>200.00</u>		
26	#	Double Panel/Glue Pull Upcharge (25%)		1	50.00		
27	*	PDR RT Door shell (HSS) Note: PDR 5 quarter		1	<u>100.00</u>		
28	#	Double Panel/Glue Pull Upcharge (25%)		1	25.00		
29		<b>QUARTER PANEL</b>					

## Preliminary Estimate

**Customer: State Of Iowa**

**Job Number:**

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI Navy Blue

30	*	PDR	LT Quarter panel	1	<u>300.00</u>		
			Note: PDR 5 nickel, 5 quarter, 5 half				
31	#		Oversize Dents (\$40 each) (1 item)	1	40.00		
32	*	PDR	RT Quarter panel	1	<u>175.00</u>		
			Note: PDR 5 nickel, 5 quarter				
33	<b>TRUNK LID</b>						
34	*	PDR	Trunk lid w/police w/camera	1	<u>650.00</u>		
			Note: PDR 10 dime, 20 nickel, 10 quarter, 10 half				
35	#		Oversize Dents (\$40 each) (5 items)	1	200.00		
36		R&I	R&I trunk lid			0.8	
37		R&I	Trunk lid trim			0.3	
38	<b>REAR LAMPS</b>						
39		R&I	RT Tail lamp assy			0.3	
40		R&I	LT Tail lamp assy			0.3	
41	#		Corrosion Protection	1	30.00		
<b>SUBTOTALS</b>					<b>5,002.50</b>	<b>6.6</b>	<b>0.0</b>

### ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			1,427.50
Body Labor	6.6 hrs @	\$ 62.15 /hr	410.19
PDR			3,575.00
Subtotal			5,412.69
<b>Grand Total</b>			<b>5,412.69</b>
Deductible			0.00
<b>CUSTOMER PAY</b>			<b>0.00</b>
<b>INSURANCE PAY</b>			<b>5,412.69</b>

223218

**Fwd: P3 212 State Vehicle Damage Hailstorm at Camp Dodge 7-09-21**

1 message

4,199

Risk, DAS &lt;das.risk@iowa.gov&gt;

Mon, Jul 19, 2021 at 1:42 PM

To: Tammy Hollingsworth &lt;Tammy.Hollingsworth@aos.iowa.gov&gt;, TOS Executive Council &lt;executivecouncil@tos.iowa.gov&gt;

Please accept this email as initial 24 hr notification for AON, vehicle 212 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

**DAS Fleet Services, Risk**

Iowa Department of Administrative Services

Division of Business and Property Services

Office: 515-725-2243

Das.Risk@iowa.gov

<https://das.iowa.gov>

----- Forwarded message -----

From: **Ehler Joel** <ehler@dps.state.ia.us>

Date: Wed, Jul 14, 2021 at 10:09 AM

Subject: P3 212 State Vehicle Damage Hailstorm at Camp Dodge 7-09-21

To: vehicledamage &lt;vehicledamage@dps.state.ia.us&gt;, DAS.Risk@iowa.gov &lt;DAS.Risk@iowa.gov&gt;

Cc: post3sup &lt;post3sup@dps.state.ia.us&gt;

Please advise when repairs are authorized for scheduling purposes.

Thank you.

Lieutenant J. Ehler 212  
District Commander  
Iowa State Patrol District #3  
2025 Hunt Avenue  
Council Bluffs, IA 51503  
Phone # 712-328-8001  
Fax # 712-328-1504  
ehler@dps.state.ia.us

**\*NOTICE\*** This email message is intended only for the addressee(s) and contains information that may be confidential. If you are not the intended recipient please notify the sender by reply email and immediately delete this email. Use, disclosure or reproduction of this email by anyone other than the intended recipient(s) is strictly prohibited. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

7 attachments



IMG\_0544.jpg  
102K



IMG\_0545.jpg  
70K



IMG\_0546.jpg  
63K



IMG\_0547.jpg  
48K



IMG\_0548.jpg  
102K



 212 Estimate.pdf  
1375K

## State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: [vehicledamage@dps.state.ia.us](mailto:vehicledamage@dps.state.ia.us) ; [das.risk@iowa.gov](mailto:das.risk@iowa.gov)

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

**STATE VEHICLE: (Mark if Act of Nature ☒ ) CASE #: 2021016414**

Date: (Month/Day/Year)	7/09/21	Time: (Time plus a.m./p.m.)	1:40 PM
Vehicle Plate #:	212	Vehicle Mileage:	31650
Vehicle Description: (Yr/Make/Model/ & Vin#)	2019 Dodge Charger		
Assigned To:	Lt Ehler	Badge #	212
Driven By:	Parked	Badge #	
Driver's Lic #:	N/A	Damage:	\$4199.00
Vehicle Towed: (Yes / No)	N/A	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$ N/A
Seat Belt: (Yes / No)	N/A	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:	N/A		
Occupants: (Other than driver)	N/A		

### VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

### OTHER INFORMATION:

Witnesses:	Major M. Stine #319
Accident Location: (Street/Hwy)	7105 NW 70th Ave, Johnston, IA 50131 MCTC Parking Lot at Camp Dodge
County:	Polk
Weather/Road Conditions:	Severe Thunderstorm with quarter-size hailstones
Property Damage other than Vehicles:	None
Cost:	\$4199.00
Citations Issued To: (List Charge(s) and Statute Code(s))	N/A

Investigating Officer:	Lt Ehler #212 reporting
------------------------	-------------------------

### VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

All Makes Collision Center  
524 23rd Ave Council Bluffs, IA 51501  
Phone: (712) 256-3195

\*\*\* PRELIMINARY ESTIMATE \*\*\*

07/13/2021 02:20 PM

Owner

Owner: state of iowa

Inspection

Inspection Date: 07/13/2021 02:21 PM

Inspection Type:

Repairer

Repairer: ALL MAKES COLLISION  
Address: 524 23rd ave  
City State Zip: COUNCIL BLUFFS, IA 51501  
Email: KARL.AAAUTO@LIVE.COM

Contact: KARL GETZSCHMAN  
Work/Day: (712)256-3195  
Work/Day:

Target Complete Date/Time:

Days To Repair: 7

Vehicle

2019 Dodge Charger Police 4 DR Sedan  
8cyl Gasoline 5.7 HEMI  
5 Speed Automatic

Lic Expire:  
Veh Insp# :  
Condition:  
Ext. Refinish: Two-Stage

VIN: 2C3CDXKT7KH755361  
Mileage Type: Actual  
Code: N3093F  
Int. Refinish: Two-Stage

Options

1st Row LCD Monitor(s)  
AM/FM Stereo  
Auto Load Leveling  
Bucket Seats  
Courtesy/Warning Lights  
Driver Information Sys  
Dual Zone Auto A/C  
Full Size Spare Tire  
Heated W/S Wiper Washers  
Intermittent Wipers  
Keyless Ignition System  
Leather Steering Wheel  
Power Brakes  
Power Windows  
Rear View Camera  
Reverse Sensing System  
Steel Wheels  
Theft Deterrent System  
Tire Pressure Monitor  
Trip Computer  
Wireless Phone Connect

2nd Row Head Airbags  
Anti-Lock Brakes  
Auxiliary Audio Input  
Center Console  
Cruise Control  
Dual Airbags  
Elect. Stability Control  
Halogen Headlights  
Heavy Duty Suspension  
Keyless Access System  
LED Brakelights  
MP3 Decoder  
Power Drivers Seat  
Pwr Accessory Outlet(s)  
Rear Window Defroster  
Roll Over Prot. System  
Strg Wheel Radio Control  
Tilt & Telescopic Steer  
Touch Screen Display  
USB Audio Input(s)

4-Wheel Drive  
Auto Headlamp Control  
Black Grille  
Color-Keyed Bumper(s)  
Daytime Running Lights  
Dual Exhaust System  
Electro-Hyd Steering  
Head Airbags  
Illuminated Visor Mirror  
Keyless Entry System  
LED Daytime Running Lts  
Overhead Console  
Power Mirrors  
Rear Bench Seat  
Rem Trunk-L/Gate Release  
Side Airbags  
Temperature Gauge(s)  
Tinted Glass  
Traction Control System  
Velour/Cloth Seats

**Damages**

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
<b>Front Body And Windshield</b>									
1	E	83	46	Panel,Hood Aluminum	68265445AB	\$1,120.00	-5.00	1.1	SM
2	L	83	13	Panel,Hood	Refinish 3.1 Surface 1.2 Edge 0.6 Two-stage setup 0.8 Two-stage			5.7	RF
3	BR	104		Fender,Front RT	Blend Refinish 0.9 Blend 0.4 Two-stage			1.3	RF

**Roof**

4	RI	347		Roof Headliner R & I	R & I Assembly			4.5	SM
---	----	-----	--	----------------------	----------------	--	--	-----	----

**Deck Lid And Back Glass**

5	I	479		Lid,Rear Deck	Repair			6.5*	SM
6	L	479		Lid,Rear Deck	Refinish 2.5 Surface 0.5 Two-stage			3.0	RF

**Manual Entries**

7	SB			pdr rt fender	Sublet Repair	\$120.00*			SM*
8	SB			pdr rt door	Sublet Repair	\$135.00*			SM*
9	SB			pdr rt rear door	Sublet Repair	\$125.00*			SM*
10	SB			pdr rt qtr pillar	Sublet Repair	\$325.00*			SM*
11	SB			pdr roof	Sublet Repair	\$925.00*			SM*
12	I			r and i police equipt	Repair				SM*
12	Items								

**MC Message**

13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE
46	PRINTABLE ALTERNATE PARTS COMPARE

**Estimate Total & Entries**

OEM Parts	\$1,120.00	
Line Item Discount	\$56.00-	
Parts & Material Total		\$1,064.00

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$50.00	5.6	6.5	12.1	\$605.00
Mech/Elec (ME)	\$50.00				
Frame (FR)	\$50.00				
Refinish (RF)	\$90.00	10.0		10.0	\$900.00
Labor Total				22.1 Hours	\$1,505.00
Sublet Repairs					\$1,630.00
Gross Total					\$4,199.00
Net Total					\$4,199.00

Alternate Parts Y/01/00/00/01/01 Cumulative 01/00/00/01/01 Zip Code: 51501 Default  
Rate Name Default

Audatex Estimating 8.1.209 ES 07/13/2021 02:24 PM REL 8.1.209 DT 06/01/2021  
State Disclosure: Not Selected  
© 2021 Audatex North America, Inc.

2.3 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

#### Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Rebld
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



**Audatex**

This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2021 Audatex North America, Inc.  
AUDATEX is a trademark owned by Audatex  
North America, Inc. All rights reserved.

