

MEMBERS OF COUNCIL

HON. KIM REYNOLDS
GOVERNOR

HON. PAUL D. PATE
SECRETARY OF STATE

HON. ROB SAND
AUDITOR OF STATE

HON. ROBY SMITH
TREASURER OF STATE

HON. MIKE NAIG
SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING
DES MOINES, IOWA 50319
PHONE: 515 281-5368
FAX: 515 281-7562

July 6, 2026

Accounting Department
Office of the Treasurer
Lucas Building
321 E 12th Street
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$11,029.85, subject to an audit of actual invoices. On April 23, 2026, Vehicles #363 and #477 were damaged by hail. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Kristi Onstot

Kristi Onstot
Executive Secretary

cc: Kyle Wear, DAS Fleet Chief Financial Officer
Ryan Betts, Fleet Services Risk Program Manager
Matt Bender, Department of Management
Heather Hackbarth, Department of Management

AOS Claim # 4342
TOS Job # _____



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

State Capitol Building
Des Moines, Iowa 50319-0006
Telephone (515) 281-5834

Rob Sand
Auditor of State

June 1, 2026

Kristi Onstot
Executive Council

Subject: Hail Damage to Vehicles #363 & #477 on April 23, 2026
Department of Administrative Services
Claim dated April 30, 2026
AOS Claim ID: 4342

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above-mentioned damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$11,029.85, subject to an audit of actual invoices.

Sincerely,

A handwritten signature in black ink, appearing to read "Brian R. Brustkern".

Brian R. Brustkern, CPA
Deputy Auditor of State

cc: Kyle Wear, Fleet Services CFO, Department of Administrative Services
Ryan Betts, Fleet Services Risk Program Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



Department of
Administrative Services

KIM REYNOLDS, GOVERNOR
CHRIS COURNOYER, LT. GOVERNOR

MARK CAMPBELL, DIRECTOR

Date: April 30, 2026

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#363 & 477 / Hail
Event Date	April 23, 2026
Summary	Vehicles 363 & 477 - sustained hail damage (Claims TBD)
Amount Requested	\$1,475.00 for vehicle 363 (AOS # 4343) \$9,554.85 for vehicle 477 (AOS # 4342) \$11,029.85 combined total (to reach \$2,000 minimum)
Supporting Documentation	29C20 Email Notification, Accident Report, & Repair Estimate

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Ryan Betts
DAS Fleet Risk Program Manager
ryan.betts1@iowa.gov
515-281-8008



Risk, DAS <das.risk@iowa.gov>

Fwd: Trooper Costello #363 Hail damage Harrison Co 4/23/26 #202600107451

1 message

Risk, DAS <das.risk@iowa.gov>

Fri, Apr 24, 2026 at 1:17 PM

To: Tammy Hollingsworth <tammy.hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as the initial 24 hour notification for an AON claim. Vehicle 363 sustained hail damage on 4/23/2026. I will forward all information as soon as it is received.

4343

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

510 E 12th St, Des Moines, IA 50319

515-281-8008 office

das.risk@iowa.gov<https://das.iowa.gov>**Department of
Administrative Services**

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

----- Forwarded message -----

From: **Leffler Kevin** <leffler@dps.state.ia.us>

Date: Fri, Apr 24, 2026 at 10:30 AM

Subject: Trooper Costello #363 Hail damage Harrison Co 4/23/26 #202600107451

To: DAS Risk <das.risk@iowa.gov>, vehicledamage <vehicledamage@dps.state.ia.us>

Cc: Cunningham Jeffrey <cunninggh@dps.state.ia.us>, Cunningham Michael <mcunning@dps.state.ia.us>, Luke Tracy <tluke@dps.state.ia.us>

All,

While on patrol, Trooper Costello #363 received hail damage on his patrol vehicle in Harrison County yesterday, 4/23/26 around 3:15 P.M.

An estimate will be completed at ALL-Makes in Council Bluffs on Monday 4/27/26. All required information will be forthcoming.

Thanks,

Sergeant Kevin Leffler ★141★

Iowa State Patrol Post 4

Iowa Department of Public Safety

3710 Highway 30 East

Denison, Iowa 51442

Office: 712-263-4621

Fax: 712-263-2325

leffler@dps.state.ia.us

<https://dps.iowa.gov/>

<https://dpscareers.com/>



**Department of
Public Safety**

****NOTICE**** This e-mail message (including any file attachment transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this e-mail by an unintended recipient is prohibited. If you have received this e-mail in error, please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this e-mail or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: ***Vehicledamage***

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

*****Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!**

STATE VEHICLE: (Mark if Act of Nature ☒) CASE #: 202600107451

Date: (Month/Day/Year)	4/23/2026	Time: (Time plus a.m./p.m.)	3:15 p.m.
Vehicle Plate #:	363	Vehicle Mileage:	19,894
Vehicle Description: (Yr/Make/Model/ & Vin#)	2024 Dodge Durango 1C4SDJFT0RC153901		
Assigned To:	Trp. Costello	Badge #	363
Driven By:	Trp. Costello	Badge #	363
Driver's Lic #:	840AY4797	Damage:	\$1,475.00
Vehicle Towed: (Yes / No)	No	Towed By:	n/a
Towed To:	n/a	Towing Cost:	\$0
Seat Belt: (Yes / No)	Yes	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:	no		
Occupants: (Other than driver)	none		

VEHICLE #2:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			

Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:	N/A		
Occupants: (Other than driver)	N/A		
Occupant(s) Wearing Seat Belt: (Yes/No)		No	

OTHER INFORMATION:

Witnesses:	None
Accident Location: (Street/Hwy)	Hwy 30, Woodbine
County:	Harrison County
Weather/Road Conditions:	Rain/Hail-Wet
Narrative: Trooper Costello was patrolling on Hwy 30 around Woodbine Iowa at the start of his nightshift. The national weather service had issued a thunderstorm warning with hail expected for the area. Trooper Costello received hail damage to his roof and hood on his patrol car.	
Property Damage other than Vehicles:	None
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	

Investigating Officer:	Sgt. Leffler #141
-------------------------------	-------------------

VEHICLE #3:

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

All Makes Collision Center
524 23rd Ave Council Bluffs, IA 51501
Phone: (712) 256-3195

*** PRELIMINARY ESTIMATE ***

04/27/2026 10:11 AM

Owner

Owner: State of Iowa

Control Information

Claim # : 363

Insured Policy # :

Inspection

Inspection Date: 04/27/2026 10:12 AM

Inspection Type:

Appraiser Name: Kortnie Getzschman

Appraiser License #2 :

Repairer

Repairer: ALL MAKES COLLISION

Address: 524 23rd ave

City State Zip: COUNCIL BLUFFS, IA 51501

Email: KARL.AAAUTO@LIVE.COM

Contact: KARL GETZSCHMAN

Work/Day: (712)256-3195

Cell: (712)355-0860

Work/Day:

Vehicle

2024 Dodge Durango Pursuit 4 DR Wagon
8cyl Gasoline 5.7 HEMI
8-Speed Automatic

Lic Expire:

Veh Insp# :

Condition:

Ext. Refinish: Two-Stage

VIN: 1C4SDJFT0RC153901

Mileage Type: Actual

Code: N7143A

Int. Refinish: Two-Stage

Options

2nd Row Head Airbags
Aluminum/Alloy Wheels
Auto Headlamp Control
Automatic High Beam
Blind Spot Sensor
Color-Keyed Bumper(s)
Dual Airbags
Floor Mats
Heated Power Mirrors
In-Vehicle WiFi
Knee Air Bags
LED Headlamps
Manual Locking Hubs
Parking Assist System
Power Rear Window

3rd Row Head Airbags
Anti-Lock Brakes
Auto Load Leveling
Auxiliary Audio Input
Bucket Seats
Compact Spare Tire
Dual Zone Auto A/C
Head Airbags
Heated Steering Wheel
Keyless Entry System
LED Brakelights
Laminated Glass
Navigation System
Power Door Locks
Power Steering

4-Wheel Drive
Armrest(s)
Automatic Dimming Mirror
Black Grille
Center Console
Cruise Control
Elect. Stability Control
Heated Front Seats
High Definition Radio
Keyless Ignition System
LED Daytime Running Lts
Leather Steering Wheel
Overhead Console
Power Drivers Seat
Power Windows

Pwr Accessory Outlet(s)	Pwr Driver Lumbar Supp	Rain-Sensing W/S Wipers
Rear Bench Seat	Rear Center Arm Rest	Rear Collisn Mitigation
Rear Heater	Rear Lip Spoiler	Rear Step Bumper
Rear View Camera	Rear Window Defroster	Roll Over Prot. System
Side Airbags	SiriusXM Satellite Radio	Strg Wheel Radio Control
Theft Deterrent System	Tilt & Telescopic Steer	Tinted Glass
Tire Pressure Monitor	Touch Screen Display	Traction Control System
Trailer Hitch	Trip Computer	USB Audio Input(s)
Vehicle Tracking Service	Velour/Cloth Seats	Wireless Phone Connect

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Front Body And Windshield										
1	SB	83		Panel,Hood Aluminum	Sublet Repair	\$575.00*				SM
2	SB	104		Fender,Front RT	Sublet Repair	\$125.00*				SM
Roof										
3	SB	341		Panel,Roof	Sublet Repair	\$550.00*				SM
Quarter And Rocker Panel										
4	SB	392		Panel,Quarter RT	Sublet Repair	\$225.00*				SM
4		Items								

Estimate Total & Entries

Labor	Rate	Replace	Repair Hrs	Total Hrs
		Hrs		
Sheet Metal (SM)	\$55.00			
Mech/Elec (ME)	\$55.00			
Frame (FR)	\$55.00			
Refinish (RF)	\$100.00			

Sublet Repairs	\$1,475.00	
Gross Total		\$1,475.00
Net Total		\$1,475.00 USD

ClaimID: ABDDC30D-36E7-4F13-B537-561A621A618D
Alternate Parts Y/00/00/00/00/00 Cumulative 00/00/00/00/00 Zip Code: 51501 Default
Rate Name Default

Audatex Estimating 10.35.99 ES 04/27/2026 10:16 AM REL 10.35.99 DT 04/01/2026 DB 04/22/2026
State Disclosure:IA
© 2026 Audatex North America, LLC.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2026 Audatex North America, LLC.
AUDATEX is a trademark owned by Audatex North America, LLC. All rights reserved.



Risk, DAS <das.risk@iowa.gov>

Fwd: #477 Patrol Vehicle Hail Damage 04-23-2026

1 message

Risk, DAS <das.risk@iowa.gov>

Fri, Apr 24, 2026 at 1:16 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as the initial 24 hour notification for an AON claim. Vehicle 447 sustained hail damage on 4/23/2026. I will forward all information as soon as it is received.

Handwritten notes: A circle around "447" with an arrow pointing to "477", and "# 4342" below it.

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

510 E 12th St, Des Moines, IA 50319

515-281-8008 office

das.risk@iowa.gov<https://das.iowa.gov>**Department of
Administrative Services**

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

----- Forwarded message -----

From: **Albrecht Nicholas** <albrecht@dps.state.ia.us>

Date: Fri, Apr 24, 2026 at 8:45 AM

Subject: #477 Patrol Vehicle Hail Damage 04-23-2026

To: vehicledamage <vehicledamage@dps.state.ia.us>, DAS.Risk (DAS.Risk@iowa.gov) <das.risk@iowa.gov>Cc: Selk Luke <selk@dps.state.ia.us>, Hansen Jeffrey <jhansen@dps.state.ia.us>, Harpenau Kara <harpenau@dps.state.ia.us>

Good morning,

Trooper Thygesen #477 patrol vehicle sustained hail damage on 04-23-2026. Attached is the state vehicle damage report and supporting documents. The repair estimate will be submitted as soon as it is complete.

Respectfully,

Lieutenant Nick Albrecht ★71★

District Commander

Iowa State Patrol | District 5

5116 Highway 3

Cherokee, IA 51012

Office: (712)-225-5119

Fax: (712)-225-6304

Radio: (712)-732-1341

albrecht@dps.state.ia.us

<https://dps.iowa.gov/>

<https://dpscarers.com/>



**Department of
Public Safety**

5 attachments



#477 1.jpg
135K



#477 2.jpg
111K



#477 3.jpg
119K



#477 State Vehicle Damage Report - Hail Damage 04-23-2026.doc
103K



#477 Vehicle Damage Memo.docx
78K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: *DPS – Vehicle Damage; DAS – Risk*

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

*****Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!**

STATE VEHICLE: (Mark if Act of Nature ☒) CASE #: 202600107189

Date: (Month/Day/Year)	04-23-2026	Time: (Time plus a.m./p.m.)	04:30 p.m.
Vehicle Plate #:	477	Vehicle Mileage:	107,691
Vehicle Description: (Yr/Make/Model/ & Vin#)	2022 Dodge Charger 2C3CDXKG4NH259800		
Assigned To:	Trp. Thygesen	Badge #	477
Driven By:	N/A	Badge #	
Driver's Lic #:		Damage:	\$
Vehicle Towed: (Yes / No)	No	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$N/A
Seat Belt: (Yes / No)	Yes	Type of Vehicle: (Marked/Semi /Unmarked)	Marked
Injured/Injuries:	N/A		
Occupants: (Other than driver)	N/A		

VEHICLE #2:

DL #:	State:
Vehicle Lic. #	State:
Driver's Name:	
Driver's Address:	
Owner's Name:	
Owner's Address:	
Owner's Phone:	

Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt:	(Yes/No)	Yes	

OTHER INFORMATION:

Witnesses:	None
Accident Location: (Street/Hwy)	Holstein, Iowa
County:	Ida
Weather/Road Conditions:	Severe Thunderstorm With Hail
Narrative: On Thursday April 23, 2026 at approximately 16:30 Hrs, a severe thunderstorm moved through northwest Iowa, producing large amounts of hail. Trooper Thygesen's patrol vehicle recived body damage from the hail.	
Property Damage other than Vehicles:	None
Cost:	\$Estimate Pending
Citations Issued To: (List Charge(s) and Statute Code(s))	

Investigating Officer:	Sgt. Selk #351
------------------------	----------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		



CHEROKEE COLLISION CENTER

Your Complete Auto Repair Center
111 INDIAN STREET, CHEROKEE, IA 51012
Phone: (712) 225-3877
FAX: (712) 225-3878

Workfile ID: 3e1c2c3d
Federal ID: 42-1468487
Resale Number: 1-18-006356

Preliminary Estimate

Customer: Iowa State Patrol

Written By: Terri Weaver

Insured: Iowa State Patrol
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
Iowa State Patrol
5116 IA-3
Cherokee, IA 51012
(712) 225-5119 Business

Inspection Location:
CHEROKEE COLLISION CENTER
111 INDIAN STREET
CHEROKEE, IA 51012
Repair Facility
(712) 225-3877 Business

Insurance Company:

VEHICLE

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

VIN: 2C3CDXKG4NH259800
License:
State: IA

Interior Color:
Exterior Color:
Production Date:

Mileage In:
Mileage Out:
Condition:

Vehicle Out:
Job #:

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera
Parking Sensors

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions

Preliminary Estimate

Customer: Iowa State Patrol

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	PAINT IDENTIFICATION						
2	#	Refn Color Mix, Match and Spray out card Exterior					1.0
3	#	Rpr Set up Stands/Jigs for Componet(s) in Booth				0.8	
4	#	Repl STAT gun application		1		0.5	
5	HOOD						
6	**	Repl A/M CAPA Hood (ALU)	68660690AA	1	1,102.00	1.5	3.0
7		Add for Clear Coat					1.2
8		Add for Underside(Complete)					1.5
9		Add for Clear Coat					0.3
10	FENDER						
11	*	PDR RT Fender w/o wide body Note: PDR 4 half		1	<u>125.00</u> T		
12		R&I RT Fender liner 3.6, 5.7 liter				0.3	
13	ELECTRICAL						
14	#	Disconnect Battery		1		0.2 M	
15	#	Connect Battery		1		0.1 M	
16	#	Rpr Memory Function Reset				0.2	
17	RESTRAINT SYSTEMS						
18	#	Rpr Dis Arm Saftey Restraint System				0.4 M	
19		R&I RT Head air bag				m 0.8 M	
20		R&I LT Head air bag				m 0.8 M	
21	#	Rpr Re-Arm and Connect Saftey Restraint Systems				0.1 M	
22		Repl Air bag system diagnosis		1		m 0.5 M	
23	ROOF						
24	*	PDR Roof panel w/o sunroof Note: PDR 65 quarter, 145 half		1	<u>1,575.00</u> T		
25		R&I R&I headliner				3.4	
26	#	R&I Police package				4.0	
27	#	Repl PDR Roof Underside restoration		1	164.80	0.5	
28	PILLARS, ROCKER & FLOOR						
29	*	PDR LT Aperture panel w/o wide body +25% Note: PDR 2 half		1	<u>156.25</u> T		
30	*	PDR RT Aperture panel w/o wide body +25% Note: PDR 2 half		1	<u>156.25</u> T		
31		R&I RT W/S pillar trim w/police				Incl.	
32		R&I LT W/S pillar trim w/police				Incl.	
33		R&I RT Center plr trim				Incl.	
34		R&I LT Center plr trim				Incl.	
35	FRONT DOOR						

Preliminary Estimate

Customer: Iowa State Patrol

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

36	*	PDR	LT Door shell (HSS)		1	<u>125.00</u>	T	
			Note: PDR 1 half					
37		R&I	LT R&I trim panel					0.5
38	*	R&I	LT Power mirror					<u>0.6</u>
39		R&I	LT Belt w'strip					0.3
40	*	PDR	RT Door shell (HSS)		1	<u>125.00</u>	T	
			Note: PDR 1 half					
41		R&I	RT R&I trim panel					0.5
42	*	R&I	RT Power mirror					<u>0.5</u>
43		R&I	RT Belt w'strip					0.3
44	REAR DOOR							
45	*	PDR	LT Door shell w/o wide body (HSS)		1	<u>125.00</u>	T	
			Note: PDR 3 half					
46		R&I	LT Belt w'strip					0.3
47	*	PDR	RT Door shell w/o wide body (HSS)		1	<u>125.00</u>	T	
			Note: PDR 2 half					
48		R&I	RT Belt w'strip					0.3
49	QUARTER PANEL							
50	*	PDR	LT Quarter panel w/o wide body		1	<u>175.00</u>	T	
			Note: PDR 9 half					
51	*	PDR	RT Quarter panel w/o wide body		1	<u>275.00</u>	T	
			Note: PDR 4 quarter, 12 half					
52		R&I	RT Upper qtr trim					Incl.
53		R&I	LT Upper qtr trim					Incl.
54	TRUNK LID							
55		Repl	Nameplate "CHARGER" chrome	68280000AA	1	78.40		0.2
56	*	Repl	LKQ trunk lid assy	68660719AA	1	1,006.15		1.1
57			Overlap Major Non-Adj. Panel					-0.2
58			Add for Clear Coat					0.4
59			Refn trunk lid underside					1.2
60		Repl	Nameplate "AWD"	68216158AB	1	82.10		0.2
61	REAR LAMPS							
62		R&I	LT Tail lamp assy					0.3
63		R&I	RT Tail lamp assy					0.3
64	VEHICLE DIAGNOSTICS							
65	#	Rpr	Battery support during PRE/POST scans					0.2 M
66	*	Subl	Pre-repair scan		1	<u>120.00</u>	m	
67	*	Subl	Post-repair scan		1	<u>120.00</u>	m	
68	MISCELLANEOUS OPERATIONS							
69	#	Repl	Job cost materials		1			
70	#	Rpr	De Nib, Wet Sand and Buff/Polish (.5 per panel)					1.0
71	#	Repl	PDR Side panel corrosion restoration		10	127.40		0.3

Preliminary Estimate

Customer: Iowa State Patrol

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

72	#	Repl	Cover Car for Interior	1	5.00	0.2	
73	#		Car Cover for Refinish	1	10.00	0.3	
74	#	Repl	Hazardous Waste Charge	1	5.00	T	
75	#	Rpr	De Nib, Wet Sand and Buff/Polish (.5 per panel)				1.0
SUBTOTALS				5,783.35	20.5	12.7	

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				2,815.85
Body Labor	17.4 hrs	@	\$ 85.00 /hr	1,479.00
Paint Labor	12.7 hrs	@	\$ 150.00 /hr	1,905.00
Mechanical Labor	3.1 hrs	@	\$ 125.00 /hr	387.50
Miscellaneous				5.00
PDR				2,962.50
Subtotal				9,554.85
Grand Total				9,554.85
Deductible				0.00
CUSTOMER PAY				0.00
INSURANCE PAY				9,554.85

Cherokee Collision Center hereby provides a Limited Warranty on repairs preformed by this shop. This Limited Warrenty is valid only for as long as you own the vehicle stated herein, and is for the person to whom this Limited Warranty is granted and whose name appears herin and on the original work order. A three year Limited Warranty on paint against fading and peeling. A one year Limited Warranty on metalwork,excluding any rust repairs, and workmanship. All parts are OEM,original equiptment manufacturer, certified, so therefore have a Limited Warranty from the manufacturer.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Customer: Iowa State Patrol

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PB11, CCC Data Date 04/16/2026, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinishing operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: Iowa State Patrol

2022 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
6	Keystone, Inc 8206 J STREET OMAHA NE 68127 (402) 553-0230	#CH1230305PP A/M CAPA Hood (ALU) Quote: 3440879240 Expires: 06/12/26	\$ 1,102.00
56	LKQ Corp 8901 Irvington Road Omaha NE 68122 (402) 571-4424	#~454006507 LKQ trunk lid assy Decklid / Tailgate W/O SPOILER; W/O LOCK CYLINDER,S#\$QM617 Quote: 3440880511 Expires: 06/12/26	\$ 756.50