MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

August 5, 2024

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$5,592.20, subject to an audit of actual invoices. On May 21, 2024, Vehicle #105539 was damaged by a fallen tree. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Kristi Onstot

Kristi Onstot Executive Secretary

 cc: Adam Steen, Director, Department of Administrative Services DAS Fleet Services, Risk Matt Bender, Department of Management Heather Hackbarth, Department of Management

> AOS Claim # 3780 TOS Job # ____



OFFICE OF AUDITOR OF STATE

STATE OF IOWA

State Capitol Building Des Moines, Iowa 50319-0004 Telephone (515) 281-5834 Rob Sand Auditor of State

July 24, 2024

Kristi Onstot Executive Council L O C A L

Subject: Vehicle #105539 Damaged by Fallen Tree on May 21, 2024 Department of Administrative Services Claim dated June 3, 2024 AOS Claim ID: 3780

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$5,592.20, subject to an audit of <u>actual</u> invoices.

Sincerely,

hi Rho

Brian R. Brustkern, CPA Deputy Auditor of State

CC: Adam Steen, Director, Department of Administrative Services Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services Heather Hackbarth, Department of Management



Governor Kim Reynolds Lt. Governor Adam Gregg

Adam Steen, Director

Date: June 3, 2024

To: Tammy Hollingsworth, Auditor of State Victoria Newton, Treasurer of State Executive Council

From: Karl Bubser, Fleet Administrator DAS Fleet Services Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

| Vehicle / Event | #105539/Hail |
|-----------------------------|--|
| Event Date | May 21, 2024 |
| Summary | Vehicle 105539 sustained storm damage. (281834) |
| Amount Requested | \$4,733.20 - Estimate <u>\$ 859.00 - Tow</u> \$5,592.20 - Total |
| Supporting Documentation | 29C20 Email Notification, Accident Report, Repair Estimate(s), Photos |

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you, 6

Karl Bubser, Fleet Administrator DAS Fleet Services Karl.Bubser@iowa.gov 515-281-3162

Hoover State Office Building | 1305 East Walnut Street | Des Moines, IA 50319 | (515) 281-5360 | http://das.iowa.gov



AOS # 3780

29C20

Risk, DAS <das.risk@iowa.gov>

Thu, May 23, 2024 at 8:19 AM Draft To: TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>, Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 105539 has had a tree fall on it on 5/21/28. It was unsafe for the driver to get the details of the vehicle sent until today. I will forward all information as soon as it is received.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

109 SE 13th St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov

https://das.iowa.gov



Department of Administrative Services



Department of Administrative Services DAS Fleet Services- Risk Management 109 SE 13th St Des Moines, IA 50319

Vehicle Accident Report Form

- Render aid or assistance to the injured (per lowa Code 321.262).
- The State of Iowa is self-insured. Refer to the insurance card and accident report procedures online or in your glove box packet. If the accident involves another party, exchange information with the driver or property owner. Do not admit fault or attempt to settle your claim.
- Call local law enforcement, if a fatality, injury or property damage has occurred, and obtain a police report. On the Capitol complex, call Iowa State Patrol, Post 16 at 515-281-5608.
- Within the first 24 hours, report accident or damage to DAS Fleet Services (515-281-3162 or <u>DAS.Risk@iowa.gov</u>), your agency fleet contact, and supervisor. Damage caused by an act of nature or unavoidable cause MUST be reported to DAS Fleet Services within 24 hours of the incident to qualify for contingent fund use (per Iowa Code 29C.20).
- For an estimate, locate the nearest contracted auto body repair shop in the Contracted Service Providers map. A contracted auto body shop within 30 miles should be used if available.
- If towing is necessary, contact DAS Fleet Services (515-281-3162) for assistance. After hours, call National Automobile Club (NAC) FleetRescue* (866-329-3471) or local law enforcement.
- Within 72 hours, print and submit a completed Accident Report Form, including a cost estimate from the auto body shop to <u>DAS.Risk@iowa.gov</u>.
- Any accident in the State of Iowa that causes death, personal injury, or total property damage of \$1,500 or more must be reported on an Iowa Accident Report Form UNLESS the accident is investigated by a law enforcement agency and a report is filed. Failure to return an accident report form within 72 hours may result in suspension of driving privileges.

DAS Fleet Services ● 109 S.E. 13th St. ● Des Moines, IA 50319 ● 515-281-3162 Website: <u>https://das.iowa.gov/procurement/fleet.services</u> ● Email: das.risk@iowa.gov

Vehicle Accident Report

| Time and location of accide | nt | | | |
|--------------------------------|--------------------------------|---|-------------------|--|
| Accident Date (Mo/Day/Year) | | Time | No. of Vehicles | |
| May 2 | 1, 2024 | 8pm | 1 | |
| County | | State | | |
| Jac | kson | lov | wa | |
| Vehicle 1 (State vehicle) | | | | |
| Driver's Name | | Work Street Address | | |
| Rebecca | Nowachek | domicile- 465 | 52 138th Ave. | |
| Driver's License No./State | | City, State, Zip | | |
| 766Y | Y2846 | Maquoketa | a, la 52060 | |
| Date of Birth | Department | Work Phone | Home Phone | |
| 02/22/1980 | HHS- Division of Public Health | 515-201-5435 | 563-212-1059 | |
| License Plate No. | VIN | Year, Make, Model | | |
| 105539 | 1C3CCCAB7FN709708 | ⁷⁰⁸ 2015 Chrysler 200 | | |
| Estimate (\$) of Damage | · · · | Description of Damage | | |
| Unknown at this time | | During the storms on May 21, 2024 the car had a tree branch fall on it while parked at domicile. At first glance, there is damage to the windshield, passenger side panel, and hood. The damage to the windshield will likely deem the car unsafe to drive to nearest contracted auto body shop (about 36 miles away). | | |
| Vehicle 2 (other vehicle) if r | more than two vehicles-use a | dditional forms | | |
| Driver's Name | | Street Address | | |
| Ν | IA | NA | | |
| Driver's License No./State | | City, State, Zip | | |
| Ν | IA | NA | | |
| Date of Birth | Work Phone | Home Phone | License Plate No. | |
| NA | NA | NA | NA | |
| Description of Damage | | | | |
| NA | | , | | |

DAS Fleet Services ● 109 S.E. 13th St. ● Des Moines, IA 50319 ● 515-281-3162 Website: <u>https://das.iowa.gov/procurement/fleet.services</u> ● Email: das.risk@iowa.gov

| Property Damage other than vehicle (fence, utility pole, | Property Damage other than vehicle (fence, utility pole, etc) | | | | |
|--|---|--|--|--|--|
| Owner's Name, Address and Phone | Description of Property Damaged | | | | |
| NA | NA | | | | |
| Injured Persons (attach additional sheets if necessary) | | | | | |
| Vehicle No. 1/ Name and Address | Describe Injuries | | | | |
| NA | NA | | | | |
| Vehicle No. 2/ Name and Address | Describe Injuries | | | | |
| NA | NA | | | | |
| Witness | | | | | |
| Name | Address/Phone | | | | |
| NA | NA | | | | |
| Name | Address/Phone | | | | |
| NA | NA | | | | |

Accident Diagram

Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers.

Use number 1 to indicate the State vehicle.

DAS Fleet Services ● 109 S.E. 13th St. ● Des Moines, IA 50319 ● 515-281-3162 Website: <u>https://das.iowa.gov/procurement/fleet.services</u> ● Email: das.risk@iowa.gov

| | Accident Information Exchange Sheet |
|--|--|
| Other Vehicle informatio | n |
| Driver's Name | NA |
| Street Address | NA |
| Driver Phone | NA |
| Driver's License No./State | NA |
| Vehicle Plate No. | NA |
| Vehicle year, make, model | NA |
| VIN | NA |
| Insurance Company Name | NA |
| Policy No. | NA |
| Agent name | NA |
| Agent phone | NA |
| Owner's Name/Address (if different) | NA |
| Submit this informatio | n along with the accident report to DAS Fleet Service within 72 hours of the accident. |

Complete the next section, tear at the dotted line and give to the other party involved.

| State Vehicle Insurance Ir | ofrmation |
|----------------------------|--|
| Driver's Name | |
| Driver's License No./State | |
| Vehicle Plate No. | |
| Vehicle year, makel, model | |
| VIN | |
| | The State of Iowa is self-insured. f you have any questions regarding an accident, please contact DAS Fleet Services at 515-281-3162 of <u>DAS.Risk@iowa.gov</u> |

.

DAS Fleet Services • 109 S.E. 13th St. • Des Moines, IA 50319 • 515-281-3162 Website: <u>https://das.iowa.gov/procurement/fleet.services</u> • Email: das.risk@iowa.gov



5329 NW 2nd St. Des Moines, Iowa 50313 Phone: (515) 243-3205 Fax: (515) 243-1409

Customer

State Of Iowa

109 SE 13th St. Des Moines, Iowa 50319

| | 250619 | 28-May-2024 | 376017 | | |
|--------------|--|--------------------|--------|--|--|
| | | | | | |
| Summary | | | | | |
| Location: | 4652 138th Ave, Maquok | eta, IA 52060, USA | | | |
| Destination: | 3400 Center Grove Dr, Dubuque, IA 52003, USA | | | | |
| Reason: | Accident | | | | |
| Vehicle: | 2015 Chrysler 200 (Ligh | t Blue) | | | |

Date

Call #

Invoice #

| venicie: | 2015 Chrysler 200 | Light Blue | e) | |
|------------|-------------------|------------|---------|-----|
| Owner: | State Of Iowa | | | |
| Phone: | | | | |
| VIN: | 1C3CCCAB7FN7097 | 08 | | |
| Plate/Tag: | 105539 | IA | Truck: | 75 |
| Mileage: | | | Driver: | CC1 |

Terms: Net 30

| Date Incident # Club/PO # | Service | Quantity | Rate | Amount |
|--|---------------------------|------------|-------|--------|
| 28-May-2024 | | | | |
| | Car Mileage | 215.00 | 3.00 | 645.00 |
| | Car Private | 1.00 | 85.00 | 85.00 |
| | Fuel Surcharge | 215.00 | 0.60 | 129.00 |
| | | 215100 | 0.00 | 125100 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| 1 | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| × | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| A Convenience Fee of 3% will be charged on all c | redit card navments. | Sub Total | | 859.00 |
| A containence rec or 570 min be enalged on an e | none on a paymonon | | | 0.00 |
| A Late Payment Fee of 10% will be applied to all | invoices not paid in full | | | 0.00 |
| 30 days after invoice date. | • | | | |
| | | TOTAL | | 859.00 |
| | | Payments | : | 0.00 |
| | | | | 0.00 |
| | | | | |
| | | Balance Ow | ing | 859.00 |
| | | <u> </u> | | |

Invoice



Abra - Dubuque

When You're Ready 3400 Center Grove Dr., Dubuque, IA 52003 Phone: (563) 556-0696 FAX: (563) 556-1899 Workfile ID: Federal ID: State ID: Resale Number: Federal EPA: State EPA: License Number: BAR: 32bbdbbd 42-0782245 IA 31-007262 IAR000004861 NA 433840 na

Preliminary Estimate

Customer: STATE OF IOWA

Point of Impact: 16 Non-Collision

STATE OF IOWA

Written By: Chad Hahn

Policy #: Date of Loss:

Abra - Dubuque

Inspection Location:

3400 Center Grove Dr. Dubuque, IA 52003 Repair Facility

(563) 556-0696 Business

Claim #: 105539 Days to Repair: 0

Insurance Company: STATE OF IOWA

Owner: STATE OF IOWA (515) 201-5435 Cell

Insured:

Type of Loss:

VEHICLE

2015 CHRY 200 Limited FWD 4D SED 4-2.4L Gasoline Sequential MPI LT BLUE

| VIN: | 1C3CCCAB7FN709708 | Interior Color: | | Mileage In: | 83,654 | Vehicle Out: |
|----------|-------------------|------------------|---------|--------------|--------|--------------|
| License: | 105539 | Exterior Color: | LT BLUE | Mileage Out: | | |
| State: | IA | Production Date: | 4/2015 | Condition: | Good | Job #: |

| TRANSMISSION | CONVENIENCE | FM Radio | Cloth Seats |
|------------------------|-------------------------------|----------------------------|------------------------|
| Automatic Transmission | Air Conditioning | Stereo | Bucket Seats |
| POWER | Intermittent Wipers | Search/Seek | Reclining/Lounge Seats |
| Power Steering | Tilt Wheel | Auxiliary Audio Connection | WHEELS |
| Power Brakes | Cruise Control | SAFETY | Aluminum/Alloy Wheels |
| Power Windows | Rear Defogger | Drivers Side Air Bag | PAINT |
| Power Locks | Keyless Entry | Passenger Air Bag | Clear Coat Paint |
| Power Mirrors | Alarm | Anti-Lock Brakes (4) | OTHER |
| DECOR | Message Center | 4 Wheel Disc Brakes | Traction Control |
| Dual Mirrors | Steering Wheel Touch Controls | Front Side Impact Air Bags | Stability Control |
| Tinted Glass | Telescopic Wheel | Head/Curtain Air Bags | |
| Console/Storage | RADIO | Hands Free Device | |
| Overhead Console | AM Radio | SEATS | |

2015 CHRY 200 Limited FWD 4D SED 4-2.4L Gasoline Sequential MPI LT BLUE

| Line | | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint |
|------|---------------------------------------|--------|---|---------------------------------------|-----|----------------------|------------|-------|
| 1 | INFORMATION | N LABE | ELS | | | | | |
| 2 | | Repl | Emission label 2.4 liter | 4722007AB | 1 | 17.75 | 0.2 | 0.0 |
| 3 | FRONT BUMPE | R & G | RILLE | | | | | |
| 4 | | R&I | R&I bumper cover | | 0 | 0.00 | 1.7 | 0.0 |
| 5 | FRONT LAMPS | ; | | | | | | |
| 6 | | R&I | RT R&I headlamp assy | | 0 | 0.00 | 0.3 | 0.0 |
| 7 | HOOD | | | | | | | |
| 8 | * | Repl | LKQ hood +25% | 68143614AC | 1 | 737.50 | 0.7 | 2.8 |
| 9 | | | Add for Clear Coat | | 0 | 0.00 | 0.0 | 1.1 |
| 10 | | | Refn underside | | 0 | 0.00 | 0.0 | 1.4 |
| 11 | | R&I | Insulator | | 0 | 0.00 | 0.3 | 0.0 |
| 12 | * | R&I | Weatherstrip | | 0 | 0.00 | <u>0.3</u> | 0.0 |
| 13 | | R&I | RT Shock | | 0 | 0.00 | 0.2 | 0.0 |
| 14 | · · · · · · · · · · · · · · · · · · · | R&I | LT Shock | · · · · · · · · · · · · · · · · · · · | 0 | 0.00 | 0.2 | 0.0 |
| 15 | FENDER | | | | | | | |
| 16 | * | Repl | LKQ RT fender assy +25% | 68143656AA | 1 | <u>206.25</u> | 2.1 | 1.8 |
| 17 | | | Overlap Major Adj. Panel | | 0 | 0.00 | 0.0 | -0.4 |
| 18 | | | Add for Clear Coat | | 0 | 0.00 | 0.0 | 0.3 |
| 19 | | | Refn edges | | 0 | 0.00 | 0.0 | 0.5 |
| 20 | | R&I | RT Fender liner w/o ride & handling | | 0 | 0.00 | 0.4 | 0.0 |
| 21 | WINDSHIELD | | | | | | | |
| 22 | | R&I | RT Washer nozzle | | 0 | 0.00 | 0.2 | 0.0 |
| 23 | | R&I | LT Washer nozzle | | 0 | 0.00 | 0.2 | 0.0 |
| 24 | ** | Repl | A/M Windshield NAGS, w/o acoustic w/o rain sensing | DW02162GTY | 1 | <u>500.00</u> | <u>0.0</u> | 0.0 |
| | | | Note: Price is for glass, install and | urethane kit. | | | | |
| 25 | PILLARS, ROC | KER & | FLOOR | | | | | |
| 26 | | R&I | RT Rocker molding vivid blue | | 0 | 0.00 | 1.1 | 0.0 |
| 27 | FRONT DOOR | | | | | | | |
| 28 | * | Repl | LKQ RT door assy +25% | 68248176AC | 1 | <u>662.50</u> | 1.9 | 3.0 |
| 29 | | | Overlap Major Adj. Panel | | õ | 0.00 | 0.0 | -0.4 |
| 30 | | | Add for Clear Coat | | 0 | 0.00 | 0.0 | 0.5 |
| 31 | | R&I | RT Door w'strip | | 0 | 0.00 | 0.6 | 0.0 |
| 32 | | R&I | RT Front seal | | 0 | 0.00 | 0.3 | 0.0 |
| 33 | | R&I | RT Pad | | 0 | 0.00 | 0.1 | 0.0 |
| 34 | | R&I | RT Lower seal | | 0 | 0.00 | 0.2 | 0.0 |
| 35 | | R&I | RT Belt molding chrome | | 0 | 0.00 | 0.3 | 0.0 |
| 36 | | R&I | RT Applique | | 0 | 0.00 | 0.3 | 0.0 |
| 37 | | R&I | RT R&I mirror | | 0 | 0.00 | 0.4 | 0.0 |
| 38 | | R&I | RT Door glass Chrysler w/o acoustic layer | | 0 | 0.00 | 0.5 | 0.0 |
| 39 | | R&I | RT Glass run chrome | | 0 | 0.00 | 0.4 | 0.0 |
| | | | | | | | | |

2015 CHRY 200 Limited FWD 4D SED 4-2.4L Gasoline Sequential MPI LT BLUE

| | | | | SUBTOTALS | | 2,134.00 | 20.4 | 11.6 |
|----------|-----------|------------|---|-----------|--------|--------------|---------------------|------------|
| 61 | # | Repl | Cover Car | | 1 | 5.00 | 0.0 | 0.0 |
| 60 | # | Rpr | Glass Cleanup | | 0 | 0.00 | 1.0 | 0.0 |
| 59 | # | | Hazardous waste removal | | 1 | 5.00 | 0.0 | 0.0 |
| 58 | | R&I | RT R&I trim panel | | 0 | 0.00 | 0.5 | 0.0 |
| 57 | | R&I | RT Carrier w/o speakers | | 0 | 0.00 | 0.9 | 0.0 |
| 56 | | R&I | RT Handle, outside w/o chrome strip vivid blue | | 0 | 0.00 | 0.4 | 0.0 |
| 55 | | R&I | RT Glass run chrome | | 0 | 0.00 | 0.6 | 0.0 |
| 54 | | R&I | RT Door glass Chrysler | | 0 | 0.00 | 0.5 | 0.0 |
| 53 | | R&I | RT Belt molding chrome | | 0 | 0.00 | 0.3 | 0.0 |
| 52 | * | Blnd | RT Outer panel (HSS) | | 0 | 0.00 | 0.0 | <u>1.0</u> |
| 51 | REAR DOOR | | | | | , | | |
| 50 | | R&I | RT Corner molding LX & Limited | | 0 | 0.00 | 0.2 | 0.0 |
| 49 | | R&I | RT Check strap | | 0 | 0.00 | 0.2 | 0.0 |
| 48 | | R&I | RT Lower hinge | | 0 | 0.00 | 0.3 | 0.0 |
| 47 | | R&I | RT Upper hinge | | 0 | 0.00 | 0.3 | 0.0 |
| 46 | | R&I | RT Carrier | | 0 | 0.00 | 0.9 | 0.0 |
| 45 | * | R&I | RT Handle, inside | | ů O | 0.00 | 0.2 | 0.0 |
| 44 | * | R&I | RT Latch w/o passive entry | | ů 0 | 0.00 | <u>0.2</u> | 0.0 |
| 43 | | R&I | strip vivid blue RT Handle base | | 0 | 0.00 | 0.4 | 0.0 |
| 41 | | R&I | RT Handle, outside w/o chrome | | 0 | 0.00 0.00 | <u>Incl.</u> 0.4 | 0.0 0.0 |
| 40 41 | * | R&I R&I | RT Window regulator RT Window motor auto down | | 0 | 0.00 | <u>0.3</u> | 0.0 |

| Category | Basis | | Rate | Cost \$ |
|-------------|----------|---|---------------|----------|
| Parts | | | | 2,134.00 |
| Body Labor | 20.4 hrs | @ | \$ 66.00 /hr | 1,346.40 |
| Paint Labor | 11.6 hrs | @ | \$ 108.00 /hr | 1,252.80 |
| Subtotal | | | | 4,733.20 |
| Grand Total | | | | 4,733.20 |

WARRANTY VALID ONLY WITH ORIGIONAL COPY OF YOUR RECEIPT PARTS SUBJECT TO INVOICE NO GUARANTEE ON RUST ALL PARTS NEW, UNLESS OTHERWISE NOTED

HIRING AUTO BODY TECHNICIANS! OFFERING TOP FLAT RATE PAY!

Have a high schooler interested in becoming a body technician or painter? ASK ABOUT OUR TUTION REIMBURSMENT PROGRAM! CONTACT: Taylor Weber at tweber@abraauto.com

2015 CHRY 200 Limited FWD 4D SED 4-2.4L Gasoline Sequential MPI LT BLUE

WARRANTY VALID ONLY WITH ORIGIONAL COPY OF RECEIPT. PARTS SUBJECT TO INVOICE. NO GUARANTEES ON RUST. ALL PARTS NEW, UNLESS OTHERWISE SPECIFIED.

HIRING AUTO BODY TECHNICIANS! OFFERING TOP FLAT RATE PAY!

Have a high schooler interested in becoming a body technician or painter? ASK ABOUT OUR TUTION REIMBURSMENT PROGRAM! CONTACT: Taylor Weber at tweber@abraauto.com

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PR15, CCC Data Date 05/16/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

2015 CHRY 200 Limited FWD 4D SED 4-2.4L Gasoline Sequential MPI LT BLUE

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

2015 CHRY 200 Limited FWD 4D SED 4-2.4L Gasoline Sequential MPI LT BLUE

PARTS SUPPLIER LIST

| Line | Supplier | Description | Price |
|------|---------------------|---|-----------|
| 8 | LKQ Corp | #~387798311 | \$ 590.00 |
| | 2101 Beloit Avenue | LKQ hood +25% | |
| | Janesville WI 53546 | Hood (SDN),S#\$A0415 | |
| | (800) 362-9451 | Quote: 2521940665 | , |
| | | Expires: 07/13/24 | |
| 16 | LKQ Corp | #~386996908 | \$ 165.00 |
| | 2101 Beloit Avenue | LKQ RT fender assy +25% | |
| | Janesville WI 53546 | Fender (SDN), R.,S#\$W3856 | |
| | (800) 362-9451 | Quote: 2521963199 | |
| | | Expires: 07/13/24 | |
| 28 | LKQ Corp | #~376942556 | \$ 530.00 |
| | 2101 Beloit Avenue | LKQ RT door assy +25% | |
| | Janesville WI 53546 | Door Assembly, Front R, (ELECTRIC), (SDN), R., 2 PIN WINDOW REGULATOR ,S#\$Y0747 | |
| | (800) 362-9451 | Quote: 2521983801 | |
| | | Expires: 07/13/24 | |