

MEMBERS OF COUNCIL

HON. KIM REYNOLDS
GOVERNOR

HON. PAUL D. PATE
SECRETARY OF STATE

HON. ROB SAND
AUDITOR OF STATE

HON. ROBY SMITH
TREASURER OF STATE

HON. MICHAEL L. NAIG
SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING
DES MOINES, IOWA 50319
PHONE: 515 281-5368

September 5, 2023

Accounting Department
Office of the Treasurer
Lucas Building
321 E 12th Street
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved the Department of Public Safety's request for an emergency allocation in the amount of \$9,436.25, subject to an audit of actual invoices. On April 19, 2023, State Patrol Vehicles #44, #167, #636 and #662 were damaged by hail. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Victoria Newton
Executive Secretary

cc: Jeannie Adams, Iowa State Patrol, Department of Public Safety
DAS Fleet Services, Department of Administrative Services
Joel Lunde, Department of Management

AOS Claim # 3494
TOS Job # _____



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

Rob Sand
Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834 Facsimile (515) 281-6518

August 2, 2023

Victoria Newton
Executive Council
L O C A L

Subject: Hail Damage to Vehicle #'s 44, 167, 636 and 662 on April 19, 2023
Department of Public Safety – Iowa State Patrol
Claim dated April 28, 2023
AOS Claim ID: 3494

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Public Safety – Iowa State Patrol is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$9,436.25, subject to an audit of actual invoices. Estimate for vehicle 662 has not been received and will be added to the total when received.

Sincerely,

A handwritten signature in blue ink, appearing to read "Ernest H. Ruben, Jr.".

Ernest H. Ruben, Jr., CPA
Deputy Auditor of State

cc: Jeannie Adams, Iowa State Patrol, Department of Public Safety
Mariah Flowers, Fleet Services Manager, Department of Administrative Services
Joel Lunde, Department of Management



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: April 28, 2023

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#44/Hail
Event Date	April 19, 2023
Summary	Vehicle #44 sustained hail damage. (255533)
Amount Requested	\$3,438.00 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-414-6582



Risk, DAS <das.risk@iowa.gov>

Hail /AON 24hr Notification

1 message

Guill Bryan <guill@dps.state.ia.us>

Thu, Apr 20, 2023 at 4:57 PM

To: "ExecutiveCouncil@tos.iowa.gov" <ExecutiveCouncil@tos.iowa.gov>, "DAS.Risk (DAS.Risk@iowa.gov)" <das.risk@iowa.gov>, "tammy.hollingsworth@aos.iowa.gov" <Tammy.Hollingsworth@aos.iowa.gov>
Cc: Adams Jeannie <jadams@dps.state.ia.us>

All

I have been notified of several incidents of hail damage from last evening. 4/19/23 storm system.

Please accept this email as notification please.

I have knowledge of cars 44, 167, 636, & 662.

More information will be forthcoming for applicable vehicles.

Thanks

Bryan

Lt. Bryan Guill ★498★

Commander Fleet & Supply

Iowa Department of Public Safety

30 NE 48th Place

Des Moines, IA 50313

F&S Main 515-281-3391

Direct 515-281-3118

Cell 515-201-9958

guill@dps.state.ia.us

1033program@dps.state.ia.us

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #:

Date: <small>(Month/Day/Year)</small>	04/19/2023	Time: <small>(Time plus a.m./p.m.)</small>	10:30 p.m.
Vehicle Plate #:	44	Vehicle Mileage:	29,064
Vehicle Description: <small>(Yr/Make/Model/ & Vin#)</small>	2021 DODGE CHARGER VIN# 2C3CDXKG2MH528634		
Assigned To:	Jeremy Sabin	Badge #	44
Driven By:	N/A	Badge #	N/A
Driver's Lic #:	083CC7461	Damage:	~\$3,000
Vehicle Towed: <small>(Yes / No)</small>	No	Towed By:	N/A
Towed To:	N/A	Towing Cost:	0
Seat Belt: <small>(Yes / No)</small>	N/A	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Marked
Injured/Injuries:	None		
Occupants: <small>(Other than driver)</small>	None		

VEHICLE #2:

DL #:		State:	IA
Vehicle Lic. #		State:	IA
Driver's Name:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info:			

(Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:		Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

OTHER INFORMATION:

Witnesses:	None
Accident Location: (Street/Hwy)	800 Block of Hickory Dr in Huxley, IA
County:	Story
Weather/Road Conditions:	Heavy rain/Hail
Trooper Sabin's squad car was parked in the street by his residence in Huxley, Iowa on April 19 th , 2023. Around 10:30 p.m., a severe thunderstorm went over the Huxley area dropping "pea" to "quarter" sized hail. The morning of April 20 th , Trooper Sabin inspected his vehicle and observed numerous dents to the hood and roof areas.	
Property Damage other than Vehicles:	None
Cost:	N/A
Citations Issued To: (List Charge(s) and Statute Code(s))	N/A

Investigating Officer:	SGT. KYLE RATZESBERGER #140
------------------------	-----------------------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			

Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			



MEMORANDUM

TO: Sergeant Kyle Ratzesberger #140
FROM: Trooper Pilot Jeremy Sabin #44
DATE: April 20, 2023
SUBJECT: Act of Nature Vehicle Damage

Sergeant Ratzesberger:

Yesterday, April 19, 2023, at approximately 10:30 pm, a thunderstorm that produced hail passed over my residence. My patrol car was parked on the street in the 800 block of Hickory Drive in Huxley, Iowa. Approximately quarter size hail fell. Today, when I checked my patrol car for damage, I saw several small dents on the hood of the vehicle, particularly more on the driver's side. I also saw at least one dent on the roof in front of the light bar.

I took some pictures that will accompany this memo in an email. It is still raining on and off here, so the dents don't show up very well in the pictures.

My patrol car mileage is 29,064.

Respectfully,

Trooper Pilot Jeremy Sabin ★44★
Iowa Department of Public Safety
Iowa State Patrol Air Wing
(515) 725-0010

Karl Chevrolet Collision Center Ankeny

Workfile ID: a67cfb3d
PartsShare: 7jFQRj
Federal ID: 42-1092272

Your Dealer for Life
1101 Southeast Oralabor Road, Ankeny, IA 50021
Phone: (515) 299-4337
FAX: (515) 964-2293

Estimate

RO Number:

Customer: STATE OF IOWA 44	Insurance: STATE OF IOWA	Adjuster: Phone: Claim: 44	Estimator: Michael Wright Create Date: 4/24/2023
(515) 725-0010		Loss Date: Deductible:	

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI GREY

VIN: 2C3CDXKG2MH528634	Interior Color: BLACK	Mileage In: 29,090	Vehicle Out:
License: 44	Exterior Color: GREY	Mileage Out:	
State: IA	Production Date: 12/2020	Condition:	Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		HOOD						
2	E01	PDR	Hood (ALU) NOTE: PDR 450 nickel	1	1,260.00	Other			
3	E01	Remove/Install	Insulator				0.3	Body	
4	E01		FENDER						
5	E01	PDR	LT Fender w/o wide body NOTE: PDR 3 quarter	1	100.00	Other			
6	E01	PDR	RT Fender w/o wide body NOTE: PDR 30 quarter	1	225.00	Other			
7	E01		ROOF						
8	E01	PDR	Roof panel w/o sunroof NOTE: PDR 20 quarter	1	430.00	Other			
9	E01		PILLARS, ROCKER & FLOOR						
10	E01	PDR	RT Aperture panel w/o wide body NOTE: PDR 2 quarter	1	100.00	Other			
11	E01		REAR DOOR						
12	E01	PDR	RT Outer panel (HSS) NOTE: PDR 4 quarter	1	100.00	Other			
13	E01		QUARTER PANEL						
14	E01	PDR	RT Quarter panel w/o wide body NOTE: PDR 40 quarter	1	275.00	Other			
15	E01	PDR	LT Quarter panel w/o wide body NOTE: PDR 10 quarter	1	150.00	Other			
16	E01		TRUNK LID						
17	E01	PDR	Trunk lid w/o police	1	450.00	Other			

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Estimate

RO Number:

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI GREY

NOTE: PDR 50 quarter

18 E01 Remove/Install Trunk lid trim 0.3 Body

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts		315.00			3,405.00
Labor, Body			55.00	0.6	33.00
Subtotal					3,438.00
Sales Tax					0.00
Grand Total					3,438.00
Net Total					3,438.00

Estimate Version	Total \$
Original	3,438.00

Insurance Total \$:	3,438.00
Received from Insurance \$:	0.00
Balance due from Insurance \$:	3,438.00
Customer Total \$:	0.00
Received from Customer \$:	0.00
Balance due from Customer \$:	0.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: April 24, 2022

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#167/Hail
Event Date	April 19, 2023
Summary	Vehicle #167 sustained hail damage during a storm. (255416)
Amount Requested	\$3,193.25 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-414-6582



Risk, DAS <das.risk@iowa.gov>

Hail /AON 24hr Notification

1 message

Guill Bryan <guill@dps.state.ia.us>

Thu, Apr 20, 2023 at 4:57 PM

To: "ExecutiveCouncil@tos.iowa.gov" <ExecutiveCouncil@tos.iowa.gov>, "DAS.Risk (DAS.Risk@iowa.gov)" <das.risk@iowa.gov>, "tammy.hollingsworth@aos.iowa.gov" <Tammy.Hollingsworth@aos.iowa.gov>

Cc: Adams Jeannie <jadams@dps.state.ia.us>

All

I have been notified of several incidents of hail damage from last evening. 4/19/23 storm system.

Please accept this email as notification please.

I have knowledge of cars 44, 167, 636, & 662.

More information will be forthcoming for applicable vehicles.

Thanks

Bryan

Lt. Bryan Guill ★498★

Commander Fleet & Supply

Iowa Department of Public Safety

30 NE 48th Place

Des Moines, IA 50313

F&S Main 515-281-3391

Direct 515-281-3118

Cell 515-201-9958

guill@dps.state.ia.us

1033program@dps.state.ia.us

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #:

Date: (Month/Day/Year)	4/19/2023	Time: (Time plus a.m./p.m.)	1030 p.m.
Vehicle Plate #:	167	Vehicle Mileage:	66413
Vehicle Description: (Yr/Make/Model/ & Vin#)	2019, Dodge/Charger/2C3CDXKT1KH577267		
Assigned To:	SGT MOSES	Badge #	167
Driven By:	N/A	Badge #	
Driver's Lic #:	338XX5680	Damage:	\$3193.25
Vehicle Towed: (Yes / No)	N/A	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$N/A
Seat Belt: (Yes / No)	N/A	Type of Vehicle: (Marked/Semi /Unmarked)	MARKED
Injured/Injuries:	N/A		
Occupants: (Other than driver)	N/A		

VEHICLE #2:

DL #:		State:	IA
Vehicle Lic. #		State:	IA
Driver's Name:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info:			

(Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:		Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			

OTHER INFORMATION:

Witnesses:			
Accident Location: (Street/Hwy)	1111 RIDGETOP DR. HUXLEY, IA.50214		
County:	STORY		
Weather/Road Conditions:	THUNDERSTORMS/RAIN/HAIL		
Marked patrol car was parked in Sgt. Moses' driveway at his residence. Heavy thunderstorm came through area and vehicle was struck by hail causing damage to the hood area and trunk lid.			
Property Damage other than Vehicles:	N/A		
Cost:	N/A		
Citations Issued To: (List Charge(s) and Statute Code(s))	N/A		

Investigating Officer:	LT. J. TRAINOR #490
------------------------	---------------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			

Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			



MEMORANDUM

TO: Lt. Trainor #490
FROM: Sgt. Moses #167
DATE: 14:06
SUBJECT: Hail Damage

Sir,

On April 19th, 2023, I was off-duty, and my squad car was parked in my driveway at my residence. Address 1111 Ridgetop Dr Huxley, IA 50124. A heavy thunderstorm with slightly larger than "pea" sized hail came through town. This was around 10:30 p.m. This morning, April 20th, I dried off the hood and could see it had sustained hail damage to the hood, some roof, and trunk lid areas. I emailed you to advise of the damage and took photos.

Respectfully,

Sgt. Moses #167

Karl Chevrolet Collision Center Ankeny

Workfile ID: f1e8e416
PartsShare: 7jrN8x
Federal ID: 42-1092272

Your Dealer for Life
1101 Southeast Oralabor Road, Ankeny, IA 50021
Phone: (515) 299-4337
FAX: (515) 964-2293

Estimate

RO Number:

Customer:	Insurance:	Adjuster:	Estimator:
STATE OF IOWA 167	STATE OF IOWA	Phone:	Michael Wright
		Claim: 167	Create Date: 4/20/2023
		Loss Date:	
(515) 725-0010		Deductible:	

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI SILVER

VIN: 2C3CDXKT1KH577267	Interior Color: BLACK	Mileage In: 66,433	Vehicle Out:
License: 167	Exterior Color: SILVER	Mileage Out:	
State: IA	Production Date: 1/2019	Condition:	Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		HOOD						
2	E01	Remove/Replace	Hood (ALU)	1	1,315.00	OEM	1.5	Body	3.0
3	E01		Add for Clear Coat						1.2
4	E01		Add for Underside(Complete)						1.5
5	E01		Add for Clear Coat						0.3
6	E01		ROOF						
7	E01	PDR	Roof panel w/o sunroof NOTE: PDR 20 nickel	1	315.00	Other			
8	E01		PILLARS, ROCKER & FLOOR						
9	E01	PDR	RT Aperture panel NOTE: PDR 3 quarter	1	100.00	Other			
10	E01	PDR	LT Aperture panel NOTE: PDR 3 quarter	1	100.00	Other			
11	E01		FRONT DOOR						
12	E01	Remove/Replace	RT Frame molding	1	125.00	OEM	0.3	Body	
13	E01	Remove/Install	RT Power mirror w/o heat, w/o memory, w/o blind spot blue				0.5	Body	
14	E01	Remove/Install	RT R&I trim panel				0.5	Body	
15	E01		REAR DOOR						
16	E01	PDR	RT Outer panel (HSS) NOTE: PDR 1 quarter	1	100.00	Other			
17	E01		QUARTER PANEL						
18	E01	PDR	2 OVERSIZE	1	100.00	Other			
19	E01	PDR	RT Quarter panel NOTE: PDR 10 quarter	1	150.00	Other			

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Estimate

RO Number:

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI SILVER


20	E01	PDR	LT Quarter panel NOTE: PDR 15 quarter	1	150.00	Other		
21	E01		TRUNK LID					
22	E01	PDR	Trunk lid w/police w/camera NOTE: PDR 5 quarter	1	200.00	Other		
23	E01		MISCELLANEOUS OPERATIONS					
24	E01	Sublet	Hazardous waste removal	1	5.00	Other		
25	E01	Refinish	Color tint					0.5
26	E01	Remove/Replace	Seam sealer	1	49.95	Other	1.0	Body
27	E01		Post Repair Scan- Per OEM Guideline				0.5	Body

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts	(403.20)				2,301.75
Sublet/Miscellaneous					5.00
Labor, Body			55.00	4.3	236.50
Labor, Refinish			100.00	6.5	650.00
Subtotal					3,193.25
Sales Tax					0.00
Grand Total					3,193.25
Net Total					3,193.25

Estimate Version	Total \$
Original	3,193.25

Insurance Total \$:	3,193.25
Received from Insurance \$:	0.00
Balance due from Insurance \$:	3,193.25
Customer Total \$:	0.00
Received from Customer \$:	0.00
Balance due from Customer \$:	0.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: April 24, 2022

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#636/Hail
Event Date	April 19, 2023
Summary	Vehicle #636 sustained hail damage during a storm. (255402)
Amount Requested	\$2,805.00 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

A handwritten signature in black ink, appearing to read "MF Flowers".

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-414-6582



Risk, DAS <das.risk@iowa.gov>

FW: Salyers Vehicle Damage from 04/19/23

1 message

Adams Jeannie <jadams@dps.state.ia.us>

Thu, Apr 20, 2023 at 2:29 PM

To: "ExecutiveCouncil [TOS]" <ExecutiveCouncil@tos.iowa.gov>, Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>

Cc: "Risk, DAS (das.risk@iowa.gov)" <das.risk@iowa.gov>

Please find attached the information on hail damage to vehicle 636.

Jeannie Adams
 ISP Fleet & Supply, Fleet Asset Manager
 Department of Public Safety
 30 N.E. 48th Place
 Des Moines, Iowa 50313
 Direct #: 515-725-0643
 Cell Phone: 515-204-3019
 Shop: 515-281-3277
 Fax: 515-242-6321
 Email: jadams@dps.state.ia.us<mailto:jadams@dps.state.ia.us>

From: Salyers Jonathan <salyers@dps.state.ia.us>
 Sent: Thursday, April 20, 2023 1:57 PM
 To: Lamp Scott <selamp@dps.state.ia.us>; Dales David <dales@dps.state.ia.us>; Adams Jeannie <jadams@dps.state.ia.us>; Risk, DAS <das.risk@iowa.gov>
 Subject: Salyers Vehicle Damage from 04/19/23

On 04/19/23, at approximately 5:37 p.m. and again at 8:30 p.m., my unmarked vehicle received hail damage while parked in rural Glenwood, IA. Please see attachments included for more information.

Thank you,
 Jon

Jonathan T. Salyers - Special Agent
 SW Iowa - Special Enforcement Operations Bureau
 Iowa Division of Criminal Investigation
 Iowa Department of Public Safety
 #1 Harrah's Blvd.
 Council Bluffs, Iowa 51501
 Cell: 515-322-1555
 salyers@dps.state.ia.us<mailto:salyers@dps.state.ia.us>

[cid:image001.png@01D9738F.9592E550]

NOTICE This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

7 attachments

provide necessary services to the benefit of Iowa, maintaining the highest professional and ethical standards that go beyond mere compliance with the law.

image001.png
 68K



IMG_0158.jpg
128K



IMG_0161.jpg
139K



IMG_0164.jpg
154K

 **Salyers State Vehicle Damage Report.Form.doc**
79K

 **Vehicle Damage Memo.docx**
69K

 **636 Hail Estimate.pdf**
996K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: **DPS – Vehicle Damage; DAS – Risk**

- **One Repair Estimate from Approved State Bid Shop**
- **DOT MARS Report (if reportable)**
- **Memo from the Driver of the State Vehicle**
- **3-4 photos of the vehicle damage**

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #:

Date: (Month/Day/Year)	04/19/2023	Time: (Time plus a.m./p.m.)	05:37 p.m.
Vehicle Plate #:	636	Vehicle Mileage:	64,465
Vehicle Description: (Yr/Make/Model/ & Vin#)	2017 Ford Taurus 1FAHP2DK5HG129432		
Assigned To:	Jonathan Salyers	Badge #	I-114
Driven By:	Jonathan Salyers	Badge #	I-114
Driver's Lic #:	972AA5804	Damage:	\$2805.00
Vehicle Towed: (Yes / No)	No	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$N/A
Seat Belt: (Yes / No)	No	Type of Vehicle: (Marked/Semi /Unmarked)	Unmarked
Injured/Injuries:	N/A		
Occupants: (Other than driver)	N/A		

OTHER INFORMATION:

Witnesses:	N/A
Accident Location: (Street/Hwy)	Hail damage while vehicle was parked.
County:	Mills
Weather/Road Conditions:	Rain/Hail
Narrative: On 04/19/23 at approximately 05:37 p.m. and again at 8:30 p.m., hail/rain storms did damage to the vehicle listed. The vehicle was parked at the time the damage occurred in rural Glenwood, Iowa. An estimate was completed at All Makes on 04/20/23 at approximately 8:00 a.m.	

--	--

Property Damage other than Vehicles:	N/A
--------------------------------------	-----

Cost:	\$N/A
-------	-------

Citations Issued To: (List Charge(s) and Statute Code(s))	N/A
--	-----

Investigating Officer:	
------------------------	--



State of Iowa
Department of Public Safety

Division of Criminal Investigation

Harrah's Casino
#1 Harrah's Blvd
Council Bluffs, IA 51501

DATE: 19:50
TO: SAC DAVE DALES
FROM: S/A JON SALYERS
RE: VEHICLE DAMAGE

INFORMATION:

Per our conversation this morning, I had hail damage to my state vehicle while it was parked at my residence on 04/19/23, at approximately 5:37 p.m. and again at 8:30 p.m. I had All Makes complete an estimate on 04/20/23 at 8:00 a.m. I have completed a vehicle damage report which will be sent in today.

Thank you,
SA Salyers

All Makes Collision Center
524 23rd Ave Council Bluffs, IA 51501
Phone: (712) 256-3195

*** PRELIMINARY ESTIMATE ***

04/20/2023 08:18 AM

Owner

Owner: state of iowa

Inspection

Inspection Date: 04/20/2023 08:21 AM

Inspection Type:

Appraiser Name: Kortnie Getzschman

Appraiser License # :

Repairer

Repairer: ALL MAKES COLLISION
Address: 524 23rd ave
City State Zip: COUNCIL BLUFFS, IA 51501
Email: KARL.AAAUTO@LIVE.COM

Contact: KARL GETZSCHMAN
Work/Day: (712)256-3195
Work/Day:

Target Complete Date/Time:

Days To Repair: 2

Vehicle

OEM Part Price Quote ID: ****

2017 Ford Taurus Police Intercptr 4 DR Sedan
6cyl Gasoline 3.7
6-Speed Automatic

Lic.Plate: 636
Lic Expire:
Veh Insp# :
Condition:
Ext. Refinish: Two-Stage

Lic State:
VIN: 1FAHP2MK5HG129432
Mileage Type: Actual
Code: P3133G
Int. Refinish: Two-Stage

Options

1st Row LCD Monitor(s)	2nd Row Head Airbags	4-Wheel Drive
AM/FM CD Player	Air Conditioning	Anti-Lock Brakes
Black Grille	Bucket Seats	Color-Keyed Bumper(s)
Cruise Control	Driver Information Sys	Dual Airbags
Elect. Stability Control	Electric Steering	Full Size Spare Tire
Halogen Headlights	Head Airbags	Intermittent Wipers
Laminated Glass	MP3 Decoder	Overhead Console
Power Adjustable Pedals	Power Brakes	Power Door Locks
Power Drivers Seat	Power Mirrors	Power Windows
Rear View Camera	Rear Window Defroster	Rem Trunk-L/Gate Release
Side Airbags	Skid Plates	Split Folding Rear Seat
Stability Cntrl Suspensn	Steel Wheels	Strg Wheel Radio Control
Tachometer	Tilt & Telescopic Steer	Tinted Glass
Tire Pressure Monitor	Traction Control System	Trip Computer
Velour/Cloth Seats		

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Front Body And Windshield										
1	SB	83		Panel,Hood >> pdr	Sublet Repair	\$625.00*				SM
2	SB	103		Fender,Front LT >> pdr	Sublet Repair	\$125.00*				SM
Roof										
3	SB	341		Panel,Roof >> pdr	Sublet Repair	\$755.00*				SM
4	RI	343		Roof Headliner R & I	R & I Assembly				5.2	SM
Front Doors										
5	SB	207		Door Shell,Front LT >> pdr	Sublet Repair	\$100.00*				SM
Rear Doors										
6	SB	287		Door Shell,Rear LT	Sublet Repair	\$135.00*				SM
Quarter And Rocker Panel										
7	SB	389		Panel,Quarter LT >> pdr	Sublet Repair	\$410.00*				SM
Deck Lid And Back Glass										
8	SB	479		Lid,Rear Deck >> pdr	Sublet Repair	\$395.00*				SM
8	Items									

Estimate Total & Entries

Labor	Rate	Replace	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$50.00		5.2	5.2	\$260.00
Mech/Elec (ME)	\$50.00				
Frame (FR)	\$50.00				
Refinish (RF)	\$90.00				
Labor Total				5.2 Hours	\$260.00
Sublet Repairs					\$2,545.00
Gross Total					\$2,805.00
Net Total					\$2,805.00

Alternate Parts Y/00/00/00/00/00 Cumulative 00/00/00/00/00 Zip Code: 51501 Default
 OEM Part Prices DT 04/20/2023 08:20 AM EstimateID 1078305280338436096 QuoteID ****
 Rate Name Default

Audatex Estimating 8.1.519 Update 4 ES 04/20/2023 08:27 AM REL 8.1.519 Update 4 DT 03/01/2023
State Disclosure: Not Selected

© 2023 Audatex North America, Inc.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2023 Audatex North America, Inc.
AUDATEX is a trademark owned by Audatex
North America, Inc. All rights reserved.