

MEMBERS OF COUNCIL

HON. KIM REYNOLDS
GOVERNOR

HON. PAUL D. PATE
SECRETARY OF STATE

HON. ROB SAND
AUDITOR OF STATE

HON. ROBY SMITH
TREASURER OF STATE

HON. MICHAEL L. NAIG
SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING
DES MOINES, IOWA 50319
PHONE: 515 281-5368

July 10, 2023

Accounting Department
Office of the Treasurer
Lucas Building
321 E 12th Street
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved the Department of Public Safety's request for an emergency allocation in the amount of \$4,321.90, subject to the audit of actual invoices. On March 31, 2023, State Patrol Vehicle #803 was damaged by hail. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Victoria Newton
Executive Secretary

cc: Lieutenant Bryan Guill, Iowa State Patrol, Department of Public Safety
DAS Fleet Services
Joel Lunde, Department of Management

AOS Claim # 3466
TOS Job # _____



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

Rob Sand
Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834 Facsimile (515) 281-6518

May 31, 2023

Victoria Newton
Executive Council
L O C A L

Subject: Hail Damage to Vehicle #803 on March 31, 2023
Department of Public Safety
Claim dated April 18, 2023
AOS Claim ID: 3466

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damages. It is our conclusion that the above damage incurred by the Department of Public Safety – Iowa State Patrol is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend Executive Council approval in the amount of \$4,321.90, subject to an audit of actual invoices.

Sincerely,

A handwritten signature in blue ink, appearing to read "Ernest H. Ruben, Jr.".

Ernest H. Ruben, Jr., CPA
Deputy Auditor of State

cc: Lieutenant Bryan Guill, Iowa State Patrol, Department of Public Safety
Mariah Flowers, Fleet Services Manager, Department of Administrative Services
Joel Lunde, Department of Management



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: April 18, 2023

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#803/Hail
Event Date	March 31, 2023
Summary	Vehicle 803 sustained hail damage during a storm. (255080)
Amount Requested	\$4,321.90 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-414-6582



Risk, DAS <das.risk@iowa.gov>

FW: Hail Damage to Vehicle #803 (DNE SA Hurley)

1 message

Adams Jeannie <jadams@dps.state.ia.us>

Mon, Apr 3, 2023 at 3:54 PM

To: "Risk, DAS (das.risk@iowa.gov)" <das.risk@iowa.gov>, "ExecutiveCouncil [TOS]" <ExecutiveCouncil@tos.iowa.gov>, Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>

From: Hurley Douglas <hurley@dps.state.ia.us>
 Sent: Monday, April 3, 2023 3:49 PM
 To: vehicledamage <vehicledamage@dps.state.ia.us>
 Cc: Moore Ryan <rmoore@dps.state.ia.us>
 Subject: Hail Damage to Vehicle #803 (DNE SA Hurley)

At or about 2:52 PM on Friday, March 31, 2023, I was travelling southbound on Highway 5 near Centerville, Appanoose County, Iowa. During the time of my travels, a large storm was moving through the area with intermittent rain, wind and hail. Between the area of the Chariton River bridge, which is located between 470th Street and Hwy J29, I ran into light rain followed by a large amount of hail. The hail was intermittent but there were large pieces bouncing off of my truck and top. As I continued south into Centerville, the hail started again yet becoming larger.

Once parked at my residence located at 1212 West Orchard Street, Centerville, Appanoose County, Iowa, the hail occurred on at least 2 additional occasions which resulted in more damage to my state issued vehicle.

The hail damage is noticeable but not as extreme as I expected it to be.

Additional details will be provided once I have an estimate from a state approved body shop.

Vehicle #803
 Iowa License Plate # DAL553
 Assigned to John Douglas Hurley, I-124
 VIN: 1C6RR7KTOKS66789

Best,
 Doug

J. Douglas Hurley, Special Agent
 Professional Development Bureau
 Iowa Department of Public Safety
 Iowa Division of Narcotics Enforcement
 215 E. 7th St.
 Des Moines, IA 50319
 C) 641.895.2527
 hurley@dps.state.ia.us<mailto:hurley@dps.state.ia.us>

<https://dpscareers.com><<https://gcc02.safelinks.protection.outlook.com/?url=https%3A%2F%2Fdpscareers.com%2F&data=05%7C01%7Cjadams%40dps.state.ia.us%7Ce3636d49d8714fbc24b908db3484de65%7C8e7368ae110346c7aec2d08e01c2d874%7C0%7C0%7C638161517502019566%7CUnknown%7CTWFpbGZsb3d8eyJWljoImC4wLjAwMDAiLCJQIjoiV2luMzIiLCJBTiI6IjEhaWwiLCJXVCi6Mn0%3D%7C3000%7C%7C&sdata=Am9Snpr3xVKt3dmjkcYeOHjQy46qKhX4Pap50Nwodw%3D&reserved=0>>
 [DPS Careers Graphic]

NOTICE This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.



image001.png
29K



State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #:

Date: (Month/Day/Year)	03 31 2023	Time: (Time plus a.m./p.m.)	2:52 P.m.
Vehicle Plate #:	DAL 553	Vehicle Mileage:	66,130
Vehicle Description: (Yr/Make/Model/ & Vin#)	IA License Plate # DAL 553 2019 Black Dodge Ram 4x4 w/ fiberglass topper VIN: 1C6RR7KTK0KS66789		
Assigned To:	SA J. Douglas Hurley	Badge #	I-124
Driven By:	SA J. Douglas Hurley	Badge #	I-124
Driver's Lic #:	732 44 5274	Damage:	\$ 4,321.90
Vehicle Towed: (Yes / No)	No	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$ N/A
Seat Belt: (Yes / No)	Yes	Type of Vehicle: (Marked/Semi./Unmarked)	Marked and Unmarked
Injured/Injuries:	N/A		
Occupants: (Other than driver)	None		

VEHICLE #2: N/A

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)			Yes

OTHER INFORMATION:

Witnesses:	None
Accident Location: (Street/Hwy)	Hwy 5 South - Between Moravia & Centerville
County:	Appanoose
Weather/Road Conditions:	Rain, Wind, Hail
Narrative: At or about 2:52 pm on 3/31/2023, I was travelling on Hwy 5 in Appanoose County, Iowa, when my state issued vehicle was struck by a large amount of hail resulting in damage to the hood, roof, and passenger side of vehicle #805. (I have video of hail hitting vehicle)	
Property Damage other than Vehicles:	No
Cost:	\$
Citations Issued To: (List Charge(s) and Statute Code(s))	None

Investigating Officer:	None
------------------------	------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion) N/A

DL #:	State:
Vehicle Lic. #	State:
Driver's Name:	
Driver's Address:	
Owner's Name:	

August 2018

Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

August 2018





Centerville Body Shop
 1312 S 18th St, Centerville, IA 52544
 Office: (641) 856-6328
 Fax: (641) 856-6733
 jerrycbs@iowatelecom.net
 EPA: IAD981721962 Tax ID: 271972063

Estimate ID
 13468838
 Original

Owner
 State of Iowa
 (641) 895-1815 (Mobile)

Appraiser
 John Stewart
 jerrycbs@iowatelecom.net

IA License
 1

Classification
 None

Loss Type Deductible
 Unknown Unknown

2019 Ram 1500 Classic Tradesman 4 Door Crew Cab 140" WB 6 Foot Bed 5.7L 8 Cyl Gas Injected 4WD

License VIN Drivable Odometer
 IA-DAL 553 1C6RR7KT0KS667789 Unknown 67085

Mitchell Service Code
 911579

Options

4 Wheel Drive	4WD or AWD	Air Conditioning	AM-FM Stereo	Anti-Lock Brake Sys. (ABS)
Automatic Headlights	Auxiliary Input	Bed Liner	Cruise Control	Driver-Front Air Bag
Electronic Stability Control	First Row Split Bench Seat	Heated Mirror	Interior Automatic Day/Night Or Electrochromatic Mirror	Left-Curtain Air Bag
MP3 Player	Passenger-Front Air Bag	Power Door Locks	Power Remote Mirror	Power Steering
Power Windows	Privacy Glass	Rear Bench Seat	Rearview Camera	Second Row Side Airbag With Head Protection
Side Airbags	Tilt Steering Wheel	Tire Pressure Monitoring System	Traction Control/Electronic	Trailer Hitch

Vinyl Seat

State of Iowa | 2019 Ram 1500 Classic Tradesman

Description Parts Profile Parts Profile Version
 UNIT # 803 N/A N/A

Line #	Description	LABOR			PART					
		Operation	Type	Total Units	CEG	Type	Number	Qty	Total Price	Tax
Grille										
1	101837 Grille Assy	Remove / Install	Body	0.5#	0.5	Existing				
Front Lamps										
2	100112 R Front Combination Lamp	Remove / Install	Body	0.3#	0.6	Existing				

Line #	Description	LABOR				PART				
		Operation	Type	Total Units	CEG	Type	Number	Qty	Total Price	Tax
3	100113 L Front Combination Lamp	Remove / Install	Body	0.3#	0.6	Existing				
Hood										
4	103827 Hood Assy	Remove / Install	Body	0.6	0.6	Existing				
5	103828 R Hood Washer Nozzle	Remove / Install	Body	0.2#	0.2	Existing				
6	103829 L Hood Washer Nozzle	Remove / Install	Body	0.2#	0.2	Existing				
7	101221 Hood Panel (Alum)	Paintless Repair	Body	0.0*	1.7	Sublet			\$550.00*	
8	103831 Hood Insulator	Remove / Install	Body	0.3r	0.3	Existing				
9	103832 Hood Insulator Retainer (7 @ \$5.20)	Remove / Replace	Body	0.0	0.0	New	4878883AA	7	\$36.40	Yes
10	900500 Hood 1 Oversize dent @ 40	Paintless Repair	Body*	0.0*	0.0	Sublet			\$40.00*	
11	900500 Hood Aluminum 25% Upcharge	Paintless Repair	Body*	0.0*	0.0	Sublet			\$137.50*	
Front Fender										
12	102214 R Fender Panel	Paintless Repair	Body	0.0*#	1.3	Sublet			\$150.00*	
13	102215 L Fender Panel	Paintless Repair	Body	0.0*#	1.7	Sublet			\$200.00*	
14	102272 R Fender Antenna Cable	Remove / Install	Body	0.8r#	0.8	Existing				
Cab										
15	100519 Cab Roof Panel	Paintless Repair	Body	0.0*	17.7	Sublet			\$600.00*	
16	900500 Roof Extended Panel 25% Upcharge	Paintless Repair	Body*	0.0*	0.0	Sublet			\$150.00*	
17	900500 Roof 5 oversize dents @ 40	Paintless Repair	Body*	0.0*	0.0	Sublet			\$200.00*	
18	900500 R Roof Rail	Paintless Repair	Body*	0.0*	0.0	Sublet			\$225.00*	
19	100468 Roof Headliner	Remove / Install	Body	3.8#	3.8	Existing				
20	AUTO Windshield	Remove / Install	Glass	1.8#	3.4					
21	100469 Add w/Roof Overhead Console	Remove / Replace	Body	0.4	0.4					
Front Door										
22	102625 R Frt Door Shell	Paintless Repair	Body	0.0*#	5.4	Sublet			\$200.00*	
23	900500 RF Door 1 oversize @ 40	Paintless Repair	Body*	0.0*	0.0	Sublet			\$40.00*	
24	101098 R Frt Otr Door Belt Moulding	Remove / Install	Body	0.3	0.3	Existing				
25	101100 R Frt Rear View Mirror	Remove / Install	Body	0.7#	0.7	Existing				
Rear Door										
26	101498 R Rear Door Shell	Paintless Repair	Body	0.0*#	4.8	Sublet			\$150.00*	

Line #	Description	LABOR				PART				
		Operation	Type	Total Units	CEG	Type	Number	Qty	Total Price	Tax
27	101499 L Rear Door Shell	Paintless Repair	Body	0.0*#	4.8	Sublet			\$75.00*	
28	101500 R Rear Otr Door Belt Moulding	Remove / Install	Body	0.3	0.3	Existing				
29	101501 L Rear Otr Door Belt Moulding	Remove / Install	Body	0.3	0.3	Existing				
Back Window										
30	101704 Back Window Glass	Remove / Install	Glass	2.0#	2.0	Existing				
Pickup Bed										
31	101600 R Pickup Bed Side Panel	Paintless Repair	Body	0.0*	12.0	Sublet			\$325.00*	
32	100150 L Pickup Bed Side Panel	Paintless Repair	Body	0.0*	12.5	Sublet			\$225.00*	
Tailgate										
33	100257 Tailgate Assembly	Remove / Install	Body	0.3	0.3	Existing				
34	100258 Tailgate Access Panel	Remove / Install	Body	0.3	0.3	Existing				
Rear Lamps										
35	100382 R Rear Combination Lamp	Remove / Install	Body	0.3	0.3	Existing				
36	100383 L Rear Combination Lamp	Remove / Install	Body	0.3	0.3	Existing				
37	100321 High Mount Stop Lamp	Remove / Install	Body	0.2#	0.2	Existing				
Additional Operations										
38	933005 Restore Corrosion Protection	Additional Operation	Body	0.0	0.0				\$30.00*	
Special / Manual Entry										
39	900500 Topper	Remove / Install	Body*	1.0*	0.0	Existing				

* Judgment Item

T Included in Two Tone Calculation

Labor Note Applies

d Discontinued by Manufacturer

C Included in Clear Coat Calculation

A Included in Clear Coat and Two Tone Calculation

r CEG R&R Time Used for this Labor Operation

[] Verify the part number and price before ordering

Estimate Totals

Labor	Units	Rate	Sublet	Add'l Amount	Totals
Body Labor	11.4	\$65.00	\$3,267.50	\$30.00	\$4,038.50
Glass Labor	3.8	\$65.00			\$247.00
Total Labor	15.2				\$4,285.50
					Taxable \$4,285.50
					Tax 0.0000% \$0.00
					Non-Taxable \$0.00
					Labor Total \$4,285.50
Parts		Amount			
Taxable Parts		\$36.40			\$36.40
					Parts Adjustments \$0.00
					Tax 0.0000% \$0.00
					Non-Taxable \$0.00
					Parts Total \$36.40
Costs		Amount			

Estimate Totals

Other Additional Costs	\$0.00	\$0.00
Paint Materials	\$0.00	\$0.00
		Taxable \$0.00
		Tax 0.0000% \$0.00
		Non-Taxable \$0.00
		Costs Total \$0.00
Gross Totals		
	Amount	
Gross Total	\$4,321.90	\$4,321.90
		Taxable \$4,321.90
		Tax \$0.00
		Non-Taxable \$0.00
		Gross Total \$4,321.90
Adjustments		
	Amount	
Total Customer Responsibility		\$0.00
	Net Estimate Total	\$4,321.90

Disclaimer: Any person who knowingly presents a false or fraudulent claim for payment of a loss or benefit or knowingly presents false information in an application for insurance is guilty of a crime and may be subject to fines and confinement in prison.

Estimate Event Log

Job Created 4/11/2023 07:49 PM
 Estimate Started 4/11/2023 07:56 PM
 Estimate Printed 4/13/2023 08:49 AM
 Estimate Committed Estimate Not Committed