MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE



Executive Council of Jowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

December 4, 2023

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$3,052.10, subject to the audit of actual invoices. On September 18, 2023, Vehicle #164 was damaged by a deer. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Victoria Newton Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services

DAS Fleet Services, Risk

Joel Lunde, Department of Management



OFFICE OF AUDITOR OF STATE

STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004

Telephone (515) 281-5834 Facsimile (515) 281-6518

November 14, 2023

Victoria Newton Executive Council L O C A L

Subject: Deer Damage to Vehicle #164 on September 18, 2023

Department of Administrative Services

Claim dated October 5, 2023

AOS Claim ID: 3599

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$3,052.10, subject to an audit of actual invoices.

Sincerely,

Ernest H. Ruben, Jr., CPA Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services Mariah Flowers, Fleet Services Manager, Department of Administrative Services Joel Lunde, Department of Management





Date: October 5, 2023

Tammy Hollingsworth, Auditor of State To:

Victoria Newton, Treasurer of State

Executive Council

From: Mariah Flowers, Fleet Manager

DAS Fleet Services

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#164/Deer
Event Date	September 18, 2023
Summary	Vehicle 164 struck a deer. (266252)
Amount Requested	\$3,052.10 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Fucaloro, Fleet Manager **DAS Fleet Services**

Mariah.Fucaloro@iowa.gov

515-414-6582



Risk, DAS <das.risk@iowa.gov>

29C20

Risk, DAS <das.risk@iowa.gov>

Mon, Sep 18, 2023 at 3:54 PM

< Tammy. Hollingsworth@aos.iowa.gov> Draft To: TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>, Tammy Hollingsworth

forward all information as soon as it is received Please accept this email as initial 24 hr notification for AON, vehicle 164 struck a deer on 9/18/23. I will

repairs to vehicles once approval is given. reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident

Thank you,



DAS Fleet Services, Risk

Iowa Department of Administrative Services

Division of Business and Property Services

Office: 515-725-2243

Das.Risk@iowa.gov

https://das.iowa.gov

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: <u>vehicledamage@dps.state.ia.us</u>; <u>das.risk@iowa.gov</u>

- > One Repair Estimate from Approved State Bid Shop
- > DOT MARS Report (if reportable)
- > Memo from the Driver of the State Vehicle
- > 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature ≥) CASE #: 2023024328

STATE VEHICLE	⊏. (II	nark II ACL OI I	valure) CASE #.	2023024320		
Date:	09/1	18/2023	Time:	7:58am		
(Month/Day/Year)			(Time plus a.m./p.m.)			
Vehicle Plate #:	164		Vehicle Mileage:	82,370		
Vehicle Description: (Yr/Make/Model/ & Vin#)		Dodge Charger 2C3CDXKT4LH124231				
Assigned To:	Trp	Mike Telfer	Badge #	164		
Driven By:	Trp Mike Telfer		Badge #	164		
Driver's Lic #:	239	CC3537	Damage:	\$		
Vehicle Towed: No		Towed By:				
Towed To:			Towing Cost:	\$		
Seat Belt: Yes (Yes / No)		Type of Vehicle: (Marked/Semi /Unmarked)	Marked			
Injured/Injuries:		None				
Occupants: (Other than driver)						

VEHICLE #2:

DL #:	State:
Vehicle Lic. #	State:
Driver's Name:	
Driver's Address:	
Owner's Name:	
Owner's Address:	

Owner's Phone:						
Insurance Info:		3 - 20				
(Carrier/Policy #/Phone)						
Veh Description:						
(Yr/Make/Model & Vin#)						
				· · · · · · · · · · · · · · · · · · ·		
Damage:	\$		Seat Belt:			
10			(Yes / No)			
Injured/Injuries:	100					
Occupants:						
(Other than driver)	ag Soot P	olt: or or				
Occupant(s) Weari	ig Seal b	eit. (Yes/No)			
OTHER INFORMA	TION:					
Witnesses:						
Accident Location:		330th St.	approx 1 mile	east of Rutledge Ave		
(Street/Hwy)				5		
County:		Mahaska	a			
Weather/Road Con	ditions:	Normal				
Property Damage o	ther than	None				
Vehicles:	ulei ulali	INOTIE				
Cost:		•				
		\$				
Citations Issued To	- 1					
(List Charge(s) and Statute	Code(s))	140	*			
Investigating Office	•		Cat Androsson	44.04		
Investigating Office			Sgt. Andreasen	#161		
	64 PAGES 11400F-107	9				
VEHICLE #3: (If ne	eded) (F	or more	vehicles, please	make extra copies of		
this portion)						
DL #:			State:			
Vehicle Lic. #			State:			
Driver's Name:			1			
Driver's Address:						
Owner's Name:			W4 4 3 10 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4			
OWITO STRAITIO.						

Owner's Address:				
Owner's Phone:				
Insurance Info: (Carrier/Policy #/Phone)				
Veh Description: (Yr/Make/Model & Vin#)				
Damage:	\$	Seat (Yes / N		Yes
Injured/Injuries:				
Occupants: (Other than driver)				
Occupant(s) Wearing	ng Seat Belt: (Yes/No)	Yes	

QUALITY CLAIMS SOLUTIONS

Workfile ID:

7fc25e12

105 N Krohn Place SIOUX FALLS, SD 57103 Phone: (877) 237-3727, FAX:(605) 800-8591 qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Preliminary Estimate

Owner: STATE OF IOWA

Job Number:

Written By: Wayne Malsam

Insured:

STATE OF IOWA

Policy #:

UNKNOWN

Claim #:

APDSOI0266252-001

Type of Loss:

Collision

Date of Loss:

9/21/2023 12:00 PM

Days to Repair:

Point of Impact:

02 Right Front Pillar (Right

Side)

Owner:

301 E 7TH ST

STATE OF IOWA

DES MOINES, IA 50319

Inspection Location:

COPELAND AUTO BODY INC.

506 E 2ND STREET

HEDRICK, IA 52563

Other

(641) 653-2140 Evening

Repair Facility:

VEHICLE

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

VIN:

2C3CDXKT4LH124231

Production Date:

82,370

Interior Color:

License: State:

Condition:

Odometer:

Exterior Color:

TRANSMISSION

Automatic Transmission

4 Wheel Drive

POWER

Power Steering Power Brakes Power Windows

Power Locks

Power Mirrors Power Driver Seat

DECOR Dual Mirrors Tinted Glass

Overhead Console

CONVENIENCE

Air Conditioning Intermittent Wipers

Tilt Wheel

Cruise Control Rear Defogger

Keyless Entry Message Center

Steering Wheel Touch Controls

Telescopic Wheel Climate Control

Backup Camera

Parking Sensors **RADIO**

AM Radio

FM Radio Stereo

Search/Seek Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4) 4 Wheel Disc Brakes Front Side Impact Air Bags Head/Curtain Air Bags

Hands Free Device **SEATS**

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control Stability Control California Emissions Power Trunk/Liftgate

Preliminary Estimate

Owner: STATE OF IOWA

Job Number:

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUMP	ER & G	RILLE					***
2			O/H bumper assy				3.4	
3	*	Rpr	Bumper cover				0.5	3.4
4			Add for Clear Coat					1.4
5	#	R&I	push bumper				1.5	
6	FRONT LAMPS	S						
7		R&I	RT R&I headlamp assy				0.3	
8	HOOD							
9		Blnd	Hood (ALU)					1.5
10	FENDER							
11	**	Repl	A/M RT Fender w/o wide body	68213060AC	1	322.00	1.6	2.0
12			Add for Clear Coat					0.8
13			Add for Edging					0.5
14			Add for Clear Coat					0.1
15		R&I	RT Fender liner 3.6, 5.7 liter				Incl.	
16	PILLARS, ROC	KER &						
17		R&I	RT Rocker molding				Incl.	
18		Repl	RT Rocker molding rivet	6509049AA	8	73.20		
19	FRONT DOOR							
20	*	Rpr	RT Door shell (HSS)				1.0	2.1
21			Overlap Major Adj. Panel					-0.4
22			Add for Clear Coat					0.3
23		R&I	RT Belt w'strip				0.3	
24		R&I	RT Power mirror w/o heat, w/o memory, w/o blind spot blue				0.5	
25		R&I	RT Handle, outside black				0.4	
26		R&I	RT R&I trim panel				0.5	
27		Repl	RT Front w'strip	68040048AC	1	49.95	0.2	
28	VEHICLE DIAG	NOST	ics					
29	*	Repl	Pre-repair scan		1	60.00 m	0.5 M	
30	*	Repl	Post-repair scan		1	129.95 m	<u>0.5</u> M	
31	#		Cover Car		1	10.00	0.2	
32	#		Hazardous Waste		1	4.00		
33	#		Color Sand/ Buff		1		1.5	
34	#		Flex Agent		1	6.00		
35	#		decals		1		1.0	
				SUBTOTALS		655.10	13.9	11.7

Preliminary Estimate

Owner: STATE OF IOWA Job Number:

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				655.10
Body Labor	12.9 hrs	@	\$ 70.00 /hr	903.00
Paint Labor	11.7 hrs	@	\$ 120.00 /hr	1,404.00
Mechanical Labor	1.0 hrs	@	\$ 90.00 /hr	90.00
Subtotal				3,052.10
Total Cost of Repairs				3,052.10
Deductible				0.00
Total Adjustments				0.00
Net Cost of Repairs				3,052.10

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.