



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

Rob Sand
Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

September 22, 2025

Kristi Onstot
Executive Council
L O C A L

Subject: Deer Damage to Vehicle #1034 on August 21, 2025
Department of Administrative Services
Claim dated August 22, 2025
AOS Claim ID: 4156

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$5,335.36, subject to an audit of actual invoices.

Sincerely,

A handwritten signature in black ink, appearing to read "Brian R. Brustkern".

Brian R. Brustkern, CPA
Deputy Auditor of State

cc: Kyle Wear, Fleet Services CFO, Department of Administrative Services
Ryan Betts, Fleet Services Risk Program Manager, Department of Administrative Services
Heather Hackbarth, Department of Management



Department of
Administrative Services

KIM REYNOLDS, GOVERNOR
CHRIS COURNOYER, LT. GOVERNOR

ADAM STEEN, DIRECTOR

Date: August 22, 2025

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#1093 / Deer Agency confirmed via email (attached) this should be vehicle #1034
Event Date	August 21, 2025
Summary	Vehicle 1093- struck a deer (Claim # TBD)
Amount Requested	\$5,335.36 TOTAL
Supporting Documentation	29C20 Email Notification, Accident Report, & Repair Estimate

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,



Ryan Betts
DAS Fleet Risk Program Manager
ryan.betts1@iowa.gov
515-281-8008



Risk, DAS <das.risk@iowa.gov>

Fwd: Run-in with deer (vehicle 1034)

1 message

Risk, DAS <das.risk@iowa.gov>

Fri, Aug 22, 2025 at 3:41 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 1034 struck a deer on 8/21/2025. I will forward all information as soon as it is received.

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

510 E 12th St, Des Moines, IA 50319

515-281-8008 office

das.risk@iowa.gov<https://das.iowa.gov>**Department of
Administrative Services**

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

----- Forwarded message -----

From: **Kintner, Mike** <Mike.Kintner@iowaagriculture.gov>

Date: Fri, Aug 22, 2025 at 3:34 PM

Subject: Run-in with deer (vehicle 1034)

To: DAS.Risk@iowa.gov <DAS.Risk@iowa.gov>Cc: Potter, Lisa <Lisa.Potter@iowaagriculture.gov>

While most of the way on my return drive to Davenport following a work meeting, a deer jumped in front of my truck on Hwy 61 in Iowa last evening. I hit the brakes but still clipped the deer. My truck took on some damage but was still drivable. I see no damage to the hood, minimal cracks to the front plastic grill, but the front drivers side corner bumper area is damaged. In the photo below you can see the dented bumper, with deer hair stuck to the bumper and some splatters down the side of the truck.

I am sending this notice to report as a requirement of DAS, as well as sending the requested (1) Accident Report Form, (2) estimate, and (3) estimate related images (all three attached).

Lisa Potter w/IDALS, and my supervisor, were already notified earlier today.

Let me know if you need anything beyond what has been shared here.



--

Mike Kintner

Entomologist | EAB & Spongy Moth Outreach

and Regulatory Coordinator



515-745-2877

Mike.Kintner@iowaagriculture.gov

3 attachments



AccidentReportForm_8_21_2025_vehicle 1034_IDALS.pdf
104K



#1034 ESTIMATE.pdf
193K



#1034 IMAGES.pdf
8104K

Vehicle Accident Report

Time and location of accident

Accident Date (Mo/Day/Year)	Time	No. of Vehicles
8/21/2025	9:00pm	1
County	State	
Jackson	Iowa	

Vehicle 1 (State vehicle)

Driver's Name		Work Street Address	
Michael Kintner		5009 Davis St.	
Driver's License No./State		City, State, Zip	
628YY5092 / Iowa		Bettendorf, IA	
Date of Birth	Department	Work Phone	Home Phone
6/12/1976	IA Dept. of Ag	515-745-2877	563-505-7126
License Plate No.	VIN	Year, Make, Model	
1034	1C6RR6FG7MS500744	2021, Dodge, 1500 Ram	
Estimate (\$) of Damage		Description of Damage	
\$5,335 (per actual estimate)		Lower and upper front corner bumper; crack to front grill; loose front drivers side lamp; minimal paint cracks/chips and dent directly behind front lamp on body on drivers side; alignment seems off. (Incident due to deer hitting vehicle)	

Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

Driver's Name		Street Address	
NA			
Driver's License No./State		City, State, Zip	
Date of Birth	Work Phone	Home Phone	License Plate No.
Description of Damage			

Property Damage other than vehicle (fence, utility pole, etc)

Owner's Name, Address and Phone

Description of Property Damaged

NA

Injured Persons (attach additional sheets if necessary)

Vehicle No. 1/ Name and Address

Describe Injuries

Vehicle No. 2/ Name and Address

Describe Injuries

Witness

Name

Address/Phone

Name


Address/Phone

Accident Diagram

Complete diagram below, include a description of what happened.

Use the outline below to sketch the scene of your accident,
writing in street or highway names or numbers.

Use number 1 to indicate the State vehicle.



Driving southbound on Hwy 61 in Jackson County (rural Maquoketa, IA) in the evening on way back from a work meeting. A deer dashed onto Hwy 61, I hit the brakes to miss the deer, but clipped it on the front corner driver's side of the vehicle, between Esgate Rd and 63rd St, along Hwy 61. No other vehicles or property was involved.

Note: Lisa Potter w/IDALS (fleet contact) shared: 'Feel free to use the diagram on the form or just type in the area provided.'

Accident Information Exchange Sheet

Other Vehicle information

Driver's Name	NA
Street Address	
Driver Phone	
Driver's License No./State	
Vehicle Plate No.	
Vehicle year, make, model	
VIN	
Insurance Company Name	
Policy No.	
Agent name	
Agent phone	
Owner's Name/Address (if different)	

Submit this information along with the accident report to DAS Fleet Service within 72 hours of the accident.

Complete the next section, tear at the dotted line and give to the other party involved.

State Vehicle Insurance Information

Driver's Name	Michael Kintner
Driver's License No./State	628YY5092 / Iowa
Vehicle Plate No.	1034
Vehicle year, make, model	2021, Dodge, Ram
VIN	1C6RR6FG7MS500744

The State of Iowa is self-insured.
If you have any questions regarding an accident, please contact
DAS Fleet Services at 515-281-3162 of DAS.Risk@iowa.gov



DURANT COLLISION REPAIR

durantcollision@iowatelecom.net
1303 5th St, P O Box 638, DURANT, IA 52747
Phone: (563) 785-6353
FAX: (563) 785-6659

Workfile ID: f0a9d530
Federal ID: 202958038
State ID: 116006756

Preliminary Estimate

Customer: Iowa Department of Agriculture

Written By: Craig Moeller

Insured: Iowa Department of
Agriculture

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 5

Point of Impact: 11 Left Front

Owner:

Iowa Department of Agriculture
1305 E Walnut St.
Des Moines, IA 50319
(515) 745-2877 Cell

Inspection Location:

DURANT COLLISION REPAIR
1303 5th St
P O Box 638
DURANT, IA 52747
Repair Facility
(563) 785-6353 Business

Insurance Company:

VEHICLE

2021 RAM 1500 Classic Tradesman Quad Cab w/6'4" Box 4D P/U 6-3.6L Gasoline Sequential MPI white

VIN: 1C6RR6FG7MS500744
License: 1034
State: IA

Interior Color:
Exterior Color: white
Production Date: 12/2020

Mileage In: 96,510
Mileage Out:
Condition:

Vehicle Out:
Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors

DECOR

Dual Mirrors
Privacy Glass

Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Message Center
Backup Camera

RADIO

AM Radio
FM Radio
Stereo

Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

California Emissions

TRUCK

Rear Step Bumper
Trailer Hitch
Trailer Package

Get live updates at www.carwise.com/e/5a6AkU

Preliminary Estimate

Customer: Iowa Department of Agriculture

2021 RAM 1500 Classic Tradesman Quad Cab w/6'4" Box 4D P/U 6-3.6L Gasoline Sequential MPI white

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER					
2		O/H front bumper				3.4	
3	**	Repl A/M CAPA Bumper black molded	68160856AC	1	496.00	Incl.	
4		Repl Lower deflector w/o air suspension black	68164793AA	1	204.00	Incl.	
5	**	Repl A/M CAPA Center support	68104942AD	1	60.00	Incl.	
6		Repl Filler panel w/o tow hooks	68196984AA	1	68.25	Incl.	
7	**	Repl A/M CAPA LT Upper cover inner support	68104945AE	1	65.00	Incl.	
8	**	Repl A/M CAPA Upper cover black molded	68207014AA	1	152.25	Incl.	
9	**	Repl Opt OEM Lamp bracket	68232454AA	1	92.36	Incl.	
10		Repl Bumper bracket	68232485AB	1	306.00	Incl.	
11	**	Repl A/M CAPA Side retainer	68196983AA	1	45.00	Incl.	
12		GRILLE					
13		Repl Grille black hexagon, primed surround bars	68197703AA	1	380.00	Incl.	1.5
14		Add for Clear Coat					0.6
15		Dis/reassmble to refn				0.6	
16		Repl Emblem chrome	68140322AA	1	197.00	Incl.	
17		FRONT LAMPS					
18	**	Repl A/M CAPA LT Headlamp assy clear lens	68096439AJ	1	274.50	0.6	
19		Aim headlamps				0.5	
20		FENDER					
21	**	Repl A/M CAPA LT Fender	68054339AJ	1	426.00	1.8	2.6
22		Overlap Major Non-Adj. Panel					-0.2
23		Add for Clear Coat					0.5
24		Add for Edging					0.5
25		Add for Clear Coat					0.1
26		Repl LT Fender liner all	55112807AA	1	101.00	Incl.	
27	**	Repl A/M CAPA LT Front reinf	55372839AD	1	53.00	0.3	0.2
28		Add for Clear Coat					0.1
29		R&I LT Protector				0.2	
30		RADIATOR SUPPORT					
31		R&I Sight shield w/o diesel				Incl.	
32	*	Rpr Radiator support w/o diesel				1.5	1.0
33	**	Repl A/M LT Mount bracket	68222827AB	1	159.00	0.3	
34		FRONT DOOR					
35	*	Blnd LT Door shell 4 door					2.0
36		R&I LT Belt w/strip 4 door black				0.3	
37		Repl LT Nameplate "RAM 1500 CLASSIC" chrome	68448645AA	1	186.00	0.2	
38		R&I LT Mirror assy				0.3	

Preliminary Estimate

Customer: Iowa Department of Agriculture

2021 RAM 1500 Classic Tradesman Quad Cab w/6'4" Box 4D P/U 6-3.6L Gasoline Sequential MPI white

39	R&I	LT Handle, outside black molded w/o keyless entry			0.3	
40	R&I	LT R&I trim panel			0.5	
41	#	R&I REMOVE DECAL TO BLEND DOOR			0.5	
42	R&I	LT Lower molding			0.3	
43	**	A/M ***** ADD-ONS *****	1			
44	#	Repl Cover Car	1	10.00	0.2	
45	#	Color tint / color match	1			0.5
46	#	Rpr Color sand and buff			1.0	
47	#	Repl Corrosion protection primer	1	10.00	0.2	
48	VEHICLE DIAGNOSTICS					
49	*	Pre-repair scan	1	m	<u>0.5</u>	M
50	*	Post-repair scan	1	m	<u>0.5</u>	M
SUBTOTALS				3,285.36	14.0	9.4

ESTIMATE TOTALS

Category	Basis			Rate	Cost \$
Parts					3,285.36
Body Labor	13.0 hrs	@		\$ 68.00 /hr	884.00
Paint Labor	9.4 hrs	@		\$ 115.00 /hr	1,081.00
Mechanical Labor	1.0 hrs	@		\$ 85.00 /hr	85.00
Subtotal					5,335.36
Grand Total					5,335.36
Deductible					0.00
CUSTOMER PAY					0.00
INSURANCE PAY					5,335.36

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Customer: Iowa Department of Agriculture

2021 RAM 1500 Classic Tradesman Quad Cab w/6'4" Box 4D P/U 6-3.6L Gasoline Sequential MPI white

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3TM13, CCC Data Date 08/15/2025, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: Iowa Department of Agriculture

2021 RAM 1500 Classic Tradesman Quad Cab w/6'4" Box 4D P/U 6-3.6L Gasoline Sequential MPI white

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
3	Keystone, Inc 4725 44TH STREET MOLINE IL 61265 (309) 517-2450	#CH1002401DSC A/M CAPA Bumper black molded Quote: 3107440041 Expires: 10/06/25	\$ 496.00
5	Keystone, Inc 4725 44TH STREET MOLINE IL 61265 (309) 517-2450	#CH1025102C A/M CAPA Center support Quote: 3107442083 Expires: 10/06/25	\$ 60.00
7	Keystone, Inc 4725 44TH STREET MOLINE IL 61265 (309) 517-2450	#CH1042121C A/M CAPA LT Upper cover inner support Quote: 3107443015 Expires: 10/06/25	\$ 65.00
8	Keystone, Inc 4725 44TH STREET MOLINE IL 61265 (309) 517-2450	#CH1014107PP A/M CAPA Upper cover black molded Quote: 3107444840 Expires: 10/06/25	\$ 152.25
9	Billion Automotive Group 3015 S. Minnesota Ave Sioux Falls SD 57105	#68232454AA Opt OEM Lamp bracket Quote: 11704352933 Expires: 09/21/25	\$ 92.36
11	Keystone, Inc 4725 44TH STREET MOLINE IL 61265 (309) 517-2450	#CH1061118PP A/M CAPA Side retainer Quote: 3107448437 Expires: 10/06/25	\$ 45.00
18	Keystone, Inc 4725 44TH STREET MOLINE IL 61265 (309) 517-2450	#CH2502282C A/M CAPA LT Headlamp assy clear lens Quote: 3107452955 Expires: 10/06/25	\$ 274.50
21	Keystone, Inc 4725 44TH STREET MOLINE IL 61265 (309) 517-2450	#CH1240269PP A/M CAPA LT Fender Quote: 3107453762 Expires: 10/06/25	\$ 426.00
27	Keystone, Inc 4725 44TH STREET MOLINE IL 61265 (309) 517-2450	#CH1244109C A/M CAPA LT Front reinf Quote: 3107461836 Expires: 10/06/25	\$ 53.00

Customer: Iowa Department of Agriculture

2021 RAM 1500 Classic Tradesman Quad Cab w/6'4" Box 4D P/U 6-3.6L Gasoline Sequential MPI white

33	Keystone, Inc	#CH2508108	\$ 159.00
	4725 44TH STREET	A/M LT Mount bracket	
	MOLINE IL 61265	Quote: 3107481306	
	(309) 517-2450	Expires: 10/06/25	

Customer: Iowa Department of Agriculture

2021 RAM 1500 Classic Tradesman Quad Cab w/6'4" Box 4D P/U 6-3.6L Gasoline Sequential MPI white

ALTERNATE PARTS USAGE

2021 RAM 1500 Classic Tradesman Quad Cab w/6'4" Box 4D P/U 6-3.6L Gasoline Sequential MPI white

VIN:1C6RR6FG7MS500744

Interior Color:

Mileage In:96,510

Vehicle Out:

License:1034

Exterior Color:white

Mileage Out:

State:IA

Production Date:12/2020

Condition:


Job #:

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	9	10
Optional OEM	Automatically List	1	1
Reconditioned	Automatically List	0	0
Recycled	N/A	0	0

DURANT COLLISION REPAIR
1303 5th St, P O Box 638, DURANT, IA 52747
Phone: (563) 785-6353, Fax: (563) 785-6659

Image Report

Owner:	Iowa Department of	Insurance:		Estimator:	Craig Moeller	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2021	Color:	white	License Plate:	1034	Production Date:	12/2020
Make:	RAM	Body Style:	4D P/U	State:	IA	Mileage In:	96,510
Model:	1500 Classic Trade...	Engine:	6-3.6L Gasoline S...	VIN:	1C6RR6FG7MS500744	Condition:	



8/22/2025
Comments: ODOMETER 96,510



8/22/2025
Comments: RF



8/22/2025
Comments: FRONT



8/22/2025
Comments: LF



8/22/2025
Comments: LR



8/22/2025
Comments: REAR

DURANT COLLISION REPAIR

1303 5th St, P O Box 638, DURANT, IA 52747

Phone: (563) 785-6353, Fax: (563) 785-6659

Image Report


Owner:	Iowa Department of	Insurance:		Estimator:	Craig Moeller	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2021	Color:	white	License Plate:	1034	Production Date:	12/2020
Make:	RAM	Body Style:	4D P/U	State:	IA	Mileage In:	96,510
Model:	1500 Classic Trade...	Engine:	6-3.6L Gasoline S...	VIN:	1C6RR6FG7MS500744	Condition:	



8/22/2025
Comments: RR



8/22/2025
Comments: GRILLE



8/22/2025
Comments: LT HLAMP



8/22/2025
Comments: UPPER BUMPER CAP



8/22/2025
Comments: BUMPER REPLACE



8/22/2025
Comments: LT BRACKET


DURANT COLLISION REPAIR
1303 5th St, P O Box 638, DURANT, IA 52747
Phone: (563) 785-6353, Fax: (563) 785-6659

Image Report

Owner:	Iowa Department of	Insurance:		Estimator:	Craig Moeller	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2021	Color:	white	License Plate:	1034	Production Date:	12/2020
Make:	RAM	Body Style:	4D P/U	State:	IA	Mileage In:	96,510
Model:	1500 Classic Trade...	Engine:	6-3.6L Gasoline S...	VIN:	1C6RR6FG7MS500744	Condition:	



8/22/2025
Comments: BUMPER



8/22/2025
Comments: LT FENDER



8/22/2025
Comments: LT FENDER



8/22/2025
Comments: FRONT




8/22/2025
Comments: REPAIR RADIATOR SUPPORT




8/22/2025
Comments: LT BUMPER BRACKETS

Image Report					
Owner:	Iowa Department of	Insurance:	Estimator:	Craig Moeller	Vehicle Out:
RO Number:		Claim Number:			
Year:	2021	Color:	white	License Plate:	1034
Make:	RAM	Body Style:	4D P/U	State:	IA
Model:	1500 Classic Trade...	Engine:	6-3.6L Gasoline S...	VIN:	1C6RR6FG7MS500744
					Production Date: 12/2020
					Mileage In: 96,510
					Condition:



8/22/2025
Comments: LT BUMPER BRACKETS




8/22/2025
Comments: VINTAG



8/22/2025
Comments: replace fender bucked at rear of wheel well



8/22/2025
Comments: blend LF door



8/22/2025
Comments: VALANCE

From: [Tammy Hollingsworth](#)
To: [Risk, DAS](#)
Cc: [ExecutiveCouncil \[TOS\]](#)
Subject: RE: Vehicle 1093 - 8/21/2025 - Claim TBD - 29C20 Allocation Request
Date: Tuesday, August 26, 2025 10:55:26 AM

Nope! I will just add a note to it.

From: ryan.betts1@iowa.gov <ryan.betts1@iowa.gov> **On Behalf Of** Risk, DAS
Sent: Tuesday, August 26, 2025 10:54 AM
To: Tammy Hollingsworth <Tammy.Hollingsworth@AOS.IOWA.GOV>
Cc: TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>
Subject: Re: Vehicle 1093 - 8/21/2025 - Claim TBD - 29C20 Allocation Request

CAUTION: This email originated from outside of AOS. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Sorry about that, it should be vehicle 1034. I'll update that on my end, do you want an updated coversheet?

Thanks!

DAS Risk

Central Procurement and Fleet Services Enterprise
Iowa Department of Administrative Services

510 E 12th St, Des Moines, IA 50319

515-281-8008 office

das.risk@iowa.gov

<https://das.iowa.gov>



All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

On Tue, Aug 26, 2025 at 10:50 AM Tammy Hollingsworth

<Tammy.Hollingsworth@aos.iowa.gov> wrote:

I just wanted to check on the vehicle # for this claim. The notification said #1034, but this allocation request says #1093.

From: ryan.betts1@iowa.gov <ryan.betts1@iowa.gov> **On Behalf Of** Risk, DAS

Sent: Friday, August 22, 2025 3:54 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@AOS.IOWA.GOV>; TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Subject: Vehicle 1093 - 8/21/2025 - Claim TBD - 29C20 Allocation Request

CAUTION: This email originated from outside of AOS. Do not click links or open attachments unless you recognize the sender and know the content is safe.

29C20 Allocation Request attached.

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

510 E 12th St, Des Moines, IA 50319

515-281-8008 office

das.risk@iowa.gov

<https://das.iowa.gov>



All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

----- Forwarded message -----

From: **CPE Printer 06** <CPEPRN06@iowa.gov>

Date: Fri, Aug 22, 2025 at 3:51 PM

Subject: Send data from MFP14388449 08/22/2025 13:41

To: DAS Risk <das.risk@iowa.gov>

Scanned from MFP14388449

Date:08/22/2025 13:41

Pages:18

Resolution:300x300 DPI

This email message and its attachments may contain confidential information that is exempt from disclosure under Iowa Code chapters 22, 139A, and other applicable law. Confidential information is for the sole use of the intended recipient. If you believe that you have received this transmission in error, please reply to the sender, and then delete all copies of this message and any attachments. If you are not the intended recipient, you are hereby notified that any review, use, retention, dissemination, distribution, or copying of this message may be prohibited by law.

Auditor.Iowa.Gov

This email message and its attachments may contain confidential information that is exempt from disclosure under Iowa Code chapters 22, 139A, and other applicable law. Confidential information is for the sole use of the intended recipient. If you believe that you have received this transmission in error, please reply to the sender, and then delete all copies of this message and any attachments. If you are not the intended recipient, you are hereby notified that any review, use, retention, dissemination, distribution, or copying of this message may be prohibited by law.

Auditor.Iowa.Gov