

MEMBERS OF COUNCIL

HON. KIM REYNOLDS
GOVERNOR

HON. PAUL D. PATE
SECRETARY OF STATE

HON. ROB SAND
AUDITOR OF STATE

HON. ROBY SMITH
TREASURER OF STATE

HON. MIKE NAIG
SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING
DES MOINES, IOWA 50319
PHONE: 515 281-5368

January 9, 2024

Accounting Department
Office of the Treasurer
Lucas Building
321 E 12th Street
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$29,400.01, subject to audit of actual invoices. On September 9, 2023, numerous vehicles were vandalized. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Victoria Newton
Executive Secretary

cc: Jeannie Adams, Department of Public Safety
DAS Fleet Services, Risk
Matt Bender, Department of Management

AOS Claim # 3593
TOS Job # _____



OFFICE OF AUDITOR OF STATE
STATE OF IOWA

Rob Sand
Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834 Facsimile (515) 281-6518

December 4, 2023

Victoria Newton
Executive Council
L O C A L

Subject: Vandalism to Numerous State Patrol Cars on September 9, 2023
Department of Public Safety – Iowa State Patrol
Claim dated October 26, 2023
AOS Claim ID: 3593

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Public Safety – Iowa State Patrol is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$29,400.01, subject to an audit of actual invoices.

Sincerely,

A handwritten signature in blue ink, appearing to read "Ernest H. Ruben, Jr.".

Ernest H. Ruben, Jr., CPA
Deputy Auditor of State

cc: Jeannie Adams, Iowa State Patrol, Department of Public Safety
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services
Joel Lunde, Department of Management



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: October 26, 2023

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

| | |
|--------------------------|---|
| Vehicle / Event | #139, 238, 266, 189, 449, 500, 171, 512, 163, 541/Vandalism |
| Event Date | September 9, 2023 |
| Summary | Multiple vehicles were vandalized at the ISU/UofI game. (266330-002 thru 012) |
| Amount Requested | \$29,400.01 - Estimates |
| Supporting Documentation | 29C20 Email Notification, Accident Report, Repair Estimate(s), Photos |

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Fucaloro, Fleet Manager
DAS Fleet Services
Mariah.Fucaloro@iowa.gov
515-414-6582



Governor Kim Reynolds
 Lt. Governor Adam Gregg
 Adam Steen, Director

Date: October 26, 2023

To: Tammy Hollingsworth, Auditor of State
 Victoria Newton, Treasurer of State
 Executive Council

From: Mariah Flowers, Fleet Manager
 DAS Fleet Services
 Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

| | |
|--------------------------|---|
| Vehicle / Event | #139, 238, 266, 189, 449, 500, 171, 512, 163, 541/Vandalism |
| Event Date | September 9, 2023 |
| Summary | Multiple vehicles were vandalized at the ISU/UofI game. (266330-002 thru 012) |
| Amount Requested | \$29,154.81 - Estimates |
| Supporting Documentation | 29C20 Email Notification, Accident Report, Repair Estimate(s), Photos |

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Fucaloro, Fleet Manager
 DAS Fleet Services
Mariah.Fucaloro@iowa.gov
 515-414-6582

My Repair Totals

| | |
|-----|---------|
| 139 | 3493.68 |
| 238 | 1713.6 |
| 266 | 3985.4 |
| 189 | 2118.5 |
| 449 | 3823.4 |
| 500 | 2548.5 |
| 171 | 510.6 |
| 512 | 3598.95 |
| 163 | 4672.15 |
| 541 | 2935.23 |

TOTAL 29,400.01

See revised letter



Risk, DAS <das.risk@iowa.gov>

Fwd: Vehicle Damage at Jack Trice Stadium

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Sep 11, 2023 at 8:37 AM

To: TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>, Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>

Please accept this email as initial 24 hr notification, please see email chain for vandalism claim. I will forward all information as soon as it is received.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



DAS Fleet Services, Risk
Iowa Department of Administrative Services
Division of Business and Property Services
Office: 515-725-2243
Das.Risk@iowa.gov
<https://das.iowa.gov>

----- Forwarded message -----

From: **Albright Andrew** <albright@dps.state.ia.us>

Date: Sat, Sep 9, 2023 at 6:50 PM

Subject: Vehicle Damage at Jack Trice Stadium

To: das.risk@iowa.gov <das.risk@iowa.gov>, vehicledamage <vehicledamage@dps.state.ia.us>, Guill Bryan <guill@dps.state.ia.us>, Adams Jeannie <jadams@dps.state.ia.us>

Cc: post1sup <post1sup@dps.state.ia.us>, Andrews Nathan <andrews@dps.state.ia.us>

All concerned,

While parked in lot G2 at Jack Trice Stadium for the Iowa/Iowa State football game today, approximately 11 patrol cars were keyed and/or otherwise damaged. I'm still waiting on final numbers, photos, etc., but I will forward them when they are received. When I get all the information, can this all be done on one vehicle damage report? Preliminary troopers involved:

Nick Henkle #139

500

Seth Bean #149

171

Jordan Barnes #238

512

Conner Simpson #266

143

Joe Nickell #189

415

Ron Schipper #449

Tracy Barker # 500

Carlos Lopez #171

Alex Taylor #512

Brian Koob #163

~~Kyle Rich #415~~

SERGEANT ANDY ALBRIGHT ★26★

Iowa State Patrol District 1

260 NW 48th Pl.

Des Moines, IA 50313

Office: (515) 725-0010

Cell: (515) 443-6119

State Radio: (515) 323-4360

Email: albright@dps.state.ia.us

cid:image003.png@01D942A6.39415E90 cid:image004.png@01D942A6.39415E90

4 attachments



image005.png
26K



image006.png
10K



image005.png
26K



image006.png
10K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us ; das.risk@iowa.gov

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature) CASE #:

| | | | |
|---|--------------------------------------|---|-----------|
| Date: (Month/Day/Year) | 9/9/2023 | Time: (Time plus a.m./p.m.) | 2:30 p.m. |
| Vehicle Plate #: | 238 | Vehicle Mileage: | 61,698 |
| Vehicle Description: (Yr/Make/Model/ & Vin#) | 2020 Dodge Charger 2C3CDXKT6LH120178 | | |
| Assigned To: | Trp. Barnes | Badge # | 238 |
| Driven By: | NA | Badge # | NA |
| Driver's Lic #: | | Damage: | \$2004.56 |
| Vehicle Towed: (Yes / No) | No | Towed By: | NA |
| Towed To: | NA | Towing Cost: | \$0 |
| Seat Belt: (Yes / No) | NA | Type of Vehicle: (Marked/Semi /Unmarked) | Marked |
| Injured/Injuries: | None | | |
| Occupants: (Other than driver) | No occupants | | |

STATE VEHICLE: (Mark if Act of Nature) CASE #:

| | | | |
|---|--|--------------------------------|-----------|
| Date: (Month/Day/Year) | 9/9/2023 | Time: (Time plus a.m./p.m.) | 2:30 p.m. |
| Vehicle Plate #: | 449 | Vehicle Mileage: | 76,701 |
| Vehicle Description: (Yr/Make/Model/ & Vin#) | 2018 Chevrolet Tahoe 1GNSKDEC7JR240082 | | |
| Assigned To: | Trp. Schipper | Badge # | 449 |
| Driven By: | NA | Badge # | NA |
| Driver's Lic #: | | Damage: | \$3659.00 |

| | | | |
|-----------------------------------|--------------|---|--------|
| Vehicle Towed: (Yes / No) | No | Towed By: | NA |
| Towed To: | NA | Towing Cost: | \$0 |
| Seat Belt: (Yes / No) | NA | Type of Vehicle: (Marked/Semi /Unmarked) | Marked |
| Injured/Injuries: | None | | |
| Occupants: (Other than driver) | No occupants | | |

STATE VEHICLE: (Mark if Act of Nature) CASE #:

| | | | |
|---|--|---|-----------|
| Date: (Month/Day/Year) | 9/9/2023 | Time: (Time plus a.m./p.m.) | 2:30 p.m. |
| Vehicle Plate #: | 139 | Vehicle Mileage: | 67,546 |
| Vehicle Description: (Yr/Make/Model/ & Vin#) | 2021 Chevrolet Tahoe 1GNSKLED4MR265481 | | |
| Assigned To: | Trp. Henkle | Badge # | 139 |
| Driven By: | NA | Badge # | NA |
| Driver's Lic #: | | Damage: | \$3493.68 |
| Vehicle Towed: (Yes / No) | No | Towed By: | NA |
| Towed To: | NA | Towing Cost: | \$0 |
| Seat Belt: (Yes / No) | NA | Type of Vehicle: (Marked/Semi /Unmarked) | Marked |
| Injured/Injuries: | None | | |
| Occupants: (Other than driver) | No occupants | | |

STATE VEHICLE: (Mark if Act of Nature) CASE #:

| | | | |
|---|--|---|-----------|
| Date: (Month/Day/Year) | 9/9/2023 | Time: (Time plus a.m./p.m.) | 2:30 p.m. |
| Vehicle Plate #: | 500 | Vehicle Mileage: | 139,229 |
| Vehicle Description: (Yr/Make/Model/ & Vin#) | 2017 Chevrolet Tahoe 1GNSKDEC8HR196264 | | |
| Assigned To: | Trp. Barker | Badge # | 500 |
| Driven By: | NA | Badge # | NA |
| Driver's Lic #: | | Damage: | \$2548.50 |
| Vehicle Towed: (Yes / No) | No | Towed By: | NA |
| Towed To: | NA | Towing Cost: | \$0 |
| Seat Belt: (Yes / No) | NA | Type of Vehicle: (Marked/Semi /Unmarked) | Marked |
| Injured/Injuries: | None | | |
| Occupants: | No occupants | | |

(Other than driver)

STATE VEHICLE: (Mark if Act of Nature) CASE #:

| | | | |
|---|--------------------------------------|---|-----------|
| Date: (Month/Day/Year) | 9/9/2023 | Time: (Time plus a.m./p.m.) | 2:30 p.m. |
| Vehicle Plate #: | 266 | Vehicle Mileage: | 54,703 |
| Vehicle Description: (Yr/Make/Model/ & Vin#) | 2021 Dodge Charger 2C3CDXKG5MH528627 | | |
| Assigned To: | Trp. Simpson | Badge # | 266 |
| Driven By: | NA | Badge # | NA |
| Driver's Lic #: | | Damage: | \$3731.20 |
| Vehicle Towed: (Yes / No) | No | Towed By: | NA |
| Towed To: | NA | Towing Cost: | \$0 |
| Seat Belt: (Yes / No) | NA | Type of Vehicle: (Marked/Semi /Unmarked) | Marked |
| Injured/Injuries: | None | | |
| Occupants: (Other than driver) | No occupants | | |

STATE VEHICLE: (Mark if Act of Nature) CASE #:

| | | | |
|---|--|---|-----------|
| Date: (Month/Day/Year) | 9/9/2023 | Time: (Time plus a.m./p.m.) | 2:30 p.m. |
| Vehicle Plate #: | 163 | Vehicle Mileage: | 56,145 |
| Vehicle Description: (Yr/Make/Model/ & Vin#) | 2021 Chevrolet Tahoe 1GNSKLED4MR255873 | | |
| Assigned To: | Trp. Koob | Badge # | 163 |
| Driven By: | NA | Badge # | NA |
| Driver's Lic #: | | Damage: | \$4672.15 |
| Vehicle Towed: (Yes / No) | No | Towed By: | NA |
| Towed To: | NA | Towing Cost: | \$0 |
| Seat Belt: (Yes / No) | NA | Type of Vehicle: (Marked/Semi /Unmarked) | Marked |
| Injured/Injuries: | None | | |
| Occupants: (Other than driver) | No occupants | | |

STATE VEHICLE: (Mark if Act of Nature) CASE #:

| | | | |
|---------------------------|----------|--------------------------------|-----------|
| Date: (Month/Day/Year) | 9/9/2023 | Time: (Time plus a.m./p.m.) | 2:30 p.m. |
| Vehicle Plate #: | 512 | Vehicle Mileage: | 81,881 |
| Vehicle | | | |

| | | | |
|---|--|---|-----------|
| Description: (Yr/Make/Model/ & Vin#) | 2019 Chevrolet Tahoe 1GNSKDEC9KR236942 | | |
| Assigned To: | Trp. Taylor | Badge # | 512 |
| Driven By: | NA | Badge # | NA |
| Driver's Lic #: | | Damage: | \$3532.00 |
| Vehicle Towed: (Yes / No) | No | Towed By: | NA |
| Towed To: | NA | Towing Cost: | \$0 |
| Seat Belt: (Yes / No) | NA | Type of Vehicle: (Marked/Semi /Unmarked) | Marked |
| Injured/Injuries: | None | | |
| Occupants: (Other than driver) | No occupants | | |

STATE VEHICLE: (Mark if Act of Nature) CASE #:

| | | | |
|---|--|---|-----------|
| Date: (Month/Day/Year) | 9/9/2023 | Time: (Time plus a.m./p.m.) | 2:30 p.m. |
| Vehicle Plate #: | 189 | Vehicle Mileage: | 69,334 |
| Vehicle Description: (Yr/Make/Model/ & Vin#) | 2020 Chevrolet Tahoe 1GNSKDECXLR260989 | | |
| Assigned To: | Trp. Nickell | Badge # | 189 |
| Driven By: | NA | Badge # | NA |
| Driver's Lic #: | | Damage: | \$2118.50 |
| Vehicle Towed: (Yes / No) | No | Towed By: | NA |
| Towed To: | NA | Towing Cost: | \$0 |
| Seat Belt: (Yes / No) | NA | Type of Vehicle: (Marked/Semi /Unmarked) | Marked |
| Injured/Injuries: | None | | |
| Occupants: (Other than driver) | No occupants | | |

STATE VEHICLE: (Mark if Act of Nature) CASE #:

| | | | |
|---|--------------------------------------|--------------------------------|-----------|
| Date: (Month/Day/Year) | 9/9/2023 | Time: (Time plus a.m./p.m.) | 2:30 p.m. |
| Vehicle Plate #: | 541 | Vehicle Mileage: | 104,185 |
| Vehicle Description: (Yr/Make/Model/ & Vin#) | 2019 Dodge Charger 2C3CDXKT6KH577250 | | |
| Assigned To: | District 16 | Badge # | NA |
| Driven By: | NA | Badge # | NA |
| Driver's Lic #: | | Damage: | \$2834.88 |

| | | | |
|-----------------------------------|--------------|---|--------|
| Vehicle Towed: (Yes / No) | No | Towed By: | NA |
| Towed To: | NA | Towing Cost: | \$0 |
| Seat Belt: (Yes / No) | NA | Type of Vehicle: (Marked/Semi /Unmarked) | Marked |
| Injured/Injuries: | None | | |
| Occupants: (Other than driver) | No occupants | | |

STATE VEHICLE: (Mark if Act of Nature) CASE #:

| | | | |
|---|--------------------------------------|---|-----------|
| Date: (Month/Day/Year) | 9/9/2023 | Time: (Time plus a.m./p.m.) | 2:30 p.m. |
| Vehicle Plate #: | JHU738 | Vehicle Mileage: | 54,506 |
| Vehicle Description: (Yr/Make/Model/ & Vin#) | 2021 Dodge Charger 2C3CDXKG2MH528651 | | |
| Assigned To: | Trp. Lopez | Badge # | 171 |
| Driven By: | NA | Badge # | NA |
| Driver's Lic #: | | Damage: | \$510.60 |
| Vehicle Towed: (Yes / No) | No | Towed By: | NA |
| Towed To: | NA | Towing Cost: | \$0 |
| Seat Belt: (Yes / No) | NA | Type of Vehicle: (Marked/Semi /Unmarked) | Unmarked |
| Injured/Injuries: | None | | |
| Occupants: (Other than driver) | No occupants | | |

266330

- 139 - \$3,493.68 - 002
 - 238 - \$1,713.60 - 003
 - 266 - \$3,731.20 - 004
 - 189 - \$2,213.15 - 005
 - 449 - \$4,110.90 - Repairs Completed - 000
 - 500 - \$2,675.45 - 007
 - 171 - \$524.60 - 008
 - 512 - \$3,598.95 - Repairs Completed 009
 - 163 - \$4,158.05 - 010
 - 541 - \$2,935.23 - 012
- Estimated Total: \$29,154.81.

~~415 - 007~~

29C20
#139
266330-002

QUALITY CLAIMS SOLUTIONS

105 N Krohn Place
SIOUX FALLS, SD 57103
Phone: (877) 237-3727, FAX:(605) 800-8591
qcs@qcsdirect.com

Workfile ID: 997b0849

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: STATE OF IOWA, STATE OF IOWA

Job Number:

Written By: Ryland Malsam

Insured: STATE OF IOWA, STATE OF IOWA Policy #: UNKNOWN Claim #: APDSOI0266330-001
Type of Loss: Collision Date of Loss: 10/12/2023 12:00 PM Days to Repair: 0
Point of Impact: 03 Right T-Bone (Right Side)

Owner:
STATE OF IOWA, STATE OF IOWA
CARROLL, IA 51401

Inspection Location:
WITTRUCK MOTOR COMPANY
1019 HWY 30 WEST
CARROLL, IA 51401
Other
(712) 792-9234 Evening

Repair Facility:

VEHICLE

2021 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection

VIN: 1GNSKLED4MR265481 Production Date: Interior Color:
License: Odometer: 67,576 Exterior Color:
State: Condition:

TRANSMISSION

Automatic Transmission
Overdrive
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat

DECOR

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Rear Window Wiper
Telescopic Wheel
Climate Control
Dual Air Condition

AM Radio

FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags

Positraction

Lane Departure Warning

ROOF

Luggage/Roof Rack

SEATS

3rd Row Seat

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

TRUCK

Trailer Hitch
Trailer Package
Running Boards/Side Steps

Estimate of Record

Owner: STATE OF IOWA, STATE OF IOWA

Job Number:

2021 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection

Dual Mirrors

Privacy Glass

Console/Storage

Backup Camera

Parking Sensors

RADIO

Communications System

Hands Free Device

Xenon or L.E.D. Headlamps

Estimate of Record

Owner: STATE OF IOWA, STATE OF IOWA

Job Number:

2021 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection

| Line | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint |
|------|------|---|-------------|-----|-------------------|-------|-------|
| 1 | | FRONT DOOR | | | | | |
| 2 | * | Rpr RT Door shell w/o body side moldings | | | | 2.5 | 2.1 |
| 3 | | R&I RT Front w'strip | | | | 0.1 | |
| 4 | * | R&I RT Belt molding chrome | | | | 0.3 | |
| 5 | | R&I RT Upper molding chrome | | | | 0.2 | |
| 6 | | R&I RT R&I mirror | | | | 0.4 | |
| 7 | | R&I RT R&I trim panel | | | | 0.4 | |
| 8 | | R&I RT Handle, outside w/o chrome | | | | 0.4 | |
| 9 | | R&I RT Water shield | | | | 0.2 | |
| 10 | | R&I RT Window molding | | | | 0.2 | |
| 11 | | R&I RT Run w'strip | | | | 0.2 | |
| 12 | * | Repl RT Upper molding rivet -10% | 9132667 | 9 | 67.68 | | |
| 13 | # | R&I DECAL | | | | 0.6 | |
| 14 | | REAR DOOR | | | | | |
| 15 | * | Rpr RT Door shell w/o body side moldings | | | | 2.5 | 2.1 |
| 16 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 17 | | R&I RT Front w'strip | | | | 0.1 | |
| 18 | | R&I RT Rear w'strip | | | | 0.1 | |
| 19 | * | R&I RT Belt molding chrome | | | | 0.3 | |
| 20 | | R&I RT R&I trim panel | | | | 0.4 | |
| 21 | * | R&I RT Handle, outside w/o chrome | | | | 0.4 | |
| 22 | | R&I RT Window molding | | | | 0.2 | |
| 23 | | R&I RT Water shield | | | | 0.2 | |
| 24 | | QUARTER PANEL | | | | | |
| 25 | * | Rpr LT Quarter panel | | | | 2.5 | 3.1 |
| 26 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 27 | * | Rpr RT Quarter panel | | | | 3.0 | 3.1 |
| 28 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 29 | * | R&I Fuel pocket gas w/o lock cntrl | | | | 0.3 | |
| 30 | | R&I LT Wheelhouse liner | | | | 0.3 | |
| 31 | * | Rpr Fuel door | | | | 0.5 | 0.5 |
| 32 | | Overlap Minor Panel | | | | | -0.2 |
| 33 | | R&I RT Front molding chrome | | | | 0.2 | |
| 34 | | R&I LT Front molding chrome | | | | 0.2 | |
| 35 | | LIFT GATE | | | | | |
| 36 | * | Rpr Lift gate | | | | 1.5 | 2.4 |
| 37 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 38 | | Clear Coat | | | | | 2.5 |
| 39 | | R&I Lower trim panel manual lift gate black | | | | 0.6 | |
| 40 | | R&I RT Side gate trim black | | | | 0.3 | |

Estimate of Record

Owner: STATE OF IOWA, STATE OF IOWA

Job Number:

2021 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection

| | | | | | | |
|-------------------------------|-----|-------------------------|---|---------------|-------------|-------------|
| 41 | R&I | LT Side gate trim black | | | 0.3 | |
| 42 | R&I | Upper gate trim black | | | Incl. | |
| 43 | R&I | Applique panel type 1 | | | 0.5 | |
| 44 | * | R&I Switch cover | | | <u>0.4</u> | |
| 45 | # | R&I DECAL | | | 0.5 | |
| 46 REAR LAMPS | | | | | | |
| 47 | R&I | RT Tail lamp | | | 0.4 | |
| 48 | R&I | LT Tail lamp | | | 0.4 | |
| 49 REAR BUMPER | | | | | | |
| 50 | R&I | R&I bumper cover | | | 1.1 | |
| 51 VEHICLE DIAGNOSTICS | | | | | | |
| 52 | | Pre-repair scan | 1 | | m | |
| 53 | * | Post-repair scan | 1 | <u>80.00</u> | m | |
| 54 | # | Hazardous Waste | 1 | 5.00 | | |
| 55 | # | Cover Car | 1 | 10.00 | 0.2 | |
| 56 | # | Tint Color | 1 | | | 1.0 |
| 57 | # | Corrosion Protection | 1 | 10.00 | | |
| 58 | # | MASK GLASS | 1 | 10.00 | 0.5 | |
| 59 | # | Color Sand/ Buff | 1 | 10.00 | 2.0 | |
| SUBTOTALS | | | | 192.68 | 25.4 | 15.0 |

| ESTIMATE TOTALS | Basis | Rate | Cost \$ |
|------------------------------|---------------------|---------------|--------------------------|
| Parts | | | 192.68 A |
| Body Labor | B 25.4 hrs @ | \$ 65.00 /hr | 1,651.00 R |
| Paint Labor | C 15.0 hrs @ | \$ 110.00 /hr | 1,650.00 R |
| Subtotal | | | 3,493.68 |
| Total Cost of Repairs | | | 3,493.68 F |
| Deductible | | | 0.00 |
| Total Adjustments | | | 0.00 |
| Net Cost of Repairs | | | 3,493.68 F |

MyPriceLink Estimate ID / Quote ID:

1141803243920171008 / 130327200

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.

QUALITY CLAIMS SOLUTIONS

Workfile ID: e136b1c6

105 N Krohn Place
SIOUX FALLS, SD 57103
Phone: (877) 237-3727, FAX:(605) 800-8591
qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: ISP #238

Job Number:

Written By: Wayne Malsam

Insured: ISP #238 Policy #: UNKNOWN Claim #: APDSOI0266330-003
Type of Loss: Collision Date of Loss: 9/22/2023 12:00 PM Days to Repair: 0
Point of Impact: 03 Right T-Bone (Right Side)

Owner:

ISP #238
WATERLOO, IA 50702

Inspection Location:

WITHAM COLLISION CENTER
2033 LAPORTE RD
Waterloo, IA 50702
Other
(319) 236-7217 Evening

Repair Facility:



VEHICLE

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

VIN: 2C3CDXKT6LH120178 Production Date: Interior Color:
License: Odometer: 61,875 Exterior Color:
State: 238 Condition:

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera
Parking Sensors

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions
Power Trunk/Liftgate

Estimate of Record

Owner: ISP #238

Job Number:

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

| Line | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint |
|------------------|------|---|-------------|-----|-------------------|-------------|------------|
| 1 | | VEHICLE DIAGNOSTICS | | | | | |
| 2 | * | Repl Post-repair scan | | 1 | m | 1.0 | M |
| 3 | | PILLARS, ROCKER & FLOOR | | | | | |
| 4 | * | Blnd RT Aperture panel w/o wide body | | | | | 1.4 |
| 5 | | REAR DOOR | | | | | |
| 6 | | Blnd RT Door shell w/o wide body (HSS) | | | | | 1.0 |
| 7 | | R&I RT Belt w'strip | | | | 0.3 | |
| 8 | | R&I RT Handle, outside black | | | | 0.4 | |
| 9 | | R&I RT R&I trim panel | | | | 0.5 | |
| 10 | | R&I RT Lower w'strip | | | | 0.2 | |
| 11 | | R&I RT Rear w'strip | | | | 0.2 | |
| 12 | | QUARTER PANEL | | | | | |
| 13 | | R&I RT Wheelhouse liner w/o vented bumper | | | | 0.4 | |
| 14 | * | Rpr RT Quarter panel | | | | 3.0 | 2.6 |
| 15 | | Add for Clear Coat | | | | | 1.0 |
| 16 | | REAR LAMPS | | | | | |
| 17 | | R&I RT Tail lamp assy | | | | 0.3 | |
| 18 | | REAR BUMPER | | | | | |
| 19 | | R&I R&I bumper cover | | | | 1.2 | |
| 20 | # | Hazardous Waste | | 1 | 4.00 X | | |
| 21 | # | Corrosion Protection | | 1 | 10.00 | 0.3 | |
| 22 | # | lift reveal | | 1 | | 0.5 | |
| 23 | # | Feather Prime and Block | | 1 | | 1.0 | |
| 24 | # | buff deck lid | | 1 | | 1.5 | |
| 25 | # | R&I quarter decal | | | | 1.0 | |
| SUBTOTALS | | | | | 14.00 | 11.8 | 6.0 |

sum of A sum of B C
F F F

Estimate of Record

Owner: ISP #238

Job Number:

2020 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

ESTIMATE TOTALS

| Category | Basis | Rate | Cost \$ |
|------------------------------|---------------------|---------------|-----------------|
| Parts | | | 10.00 |
| Body Labor | B 10.8 hrs @ | \$ 72.00 /hr | 777.60 |
| Paint Labor | C 6.0 hrs @ | \$ 132.00 /hr | 792.00 |
| Mechanical Labor | B 1.0 hrs @ | \$ 130.00 /hr | 130.00 |
| Miscellaneous | | | 4.00 |
| Subtotal | | | 1,713.60 |
| Total Cost of Repairs | | | 1,713.60 |
| Deductible | | | 0.00 |
| Total Adjustments | | | 0.00 |
| Net Cost of Repairs | | | 1,713.60 |

A
R
R
A
F

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.

QUALITY CLAIMS SOLUTIONS

Workfile ID: 13ca0a07

105 N Krohn Place
SIOUX FALLS, SD 57103
Phone: (877) 237-3727, FAX:(605) 800-8591
qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: STATE OF IOWA, STATE OF IOWA

Job Number:

Written By: Ryland Malsam

| | | | | | |
|------------------|------------------------------|---------------|--------------------|-----------------|-------------------|
| Insured: | STATE OF IOWA, STATE OF IOWA | Policy #: | UNKNOWN | Claim #: | APDSOI0266330-004 |
| Type of Loss: | Collision | Date of Loss: | 9/24/2023 12:00 PM | Days to Repair: | 0 |
| Point of Impact: | 09 Left T-Bone (Left Side) | | | | |

Owner:
STATE OF IOWA, STATE OF IOWA


1619 TRURO PAVEMENT
OSCEOLA, IA 50213

Inspection Location:
STEW HANSEN'S URBANDALE COLLISION
C
12103 HICKMAN ROAD
DES MOINES, IA 50323
Other
(515) 331-2904 Evening

Repair Facility:

VEHICLE

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

| | | | | | |
|----------|---|------------------|--------|-----------------|--|
| VIN: | 2C3CDXKG5MH528627 | Production Date: | | Interior Color: | |
| License: |  | Odometer: | 54,703 | Exterior Color: | |
| State: | | Condition: | | | |

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel

CLIMATE

Climate Control
Backup Camera
Parking Sensors

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions
Power Trunk/Liftgate

Estimate of Record

Owner: STATE OF IOWA, STATE OF IOWA

Job Number:

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

| Line | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint |
|------|------|---|-------------|-----|-------------------|--------------|-------|
| 1 | | FRONT BUMPER & GRILLE | | | | | |
| 2 | R&I | R&I bumper cover | | | | 1.9 | |
| 3 | # | R&I PUSH BAR | | | | 2.0 | |
| 4 | | FRONT LAMPS | | | | | |
| 5 | * | R&I LT Headlamp assy halogen | | | | <u>0.4</u> | |
| 6 | | Repl Aim headlamps | | 1 | | 0.5 | |
| 7 | | FENDER | | | | | |
| 8 | * | Rpr LT Fender w/o wide body | | | | <u>1.0</u> | 2.0 |
| 9 | # | DECAL REMOVAL | | 1 | | 1.0 | |
| 10 | # | R&I SPOT LAMP | | | | 2.0 | |
| 11 | | ELECTRICAL | | | | | |
| 12 | * | R&I Battery 730 CCA | | | | m <u>0.2</u> | |
| 13 | | R&I Camera all | | | | m 0.1 | |
| 14 | | PILLARS, ROCKER & FLOOR | | | | | |
| 15 | R&I | LT Rocker molding | | | | 0.8 | |
| 16 | | Repl LT Rocker molding rivet | 6509049AA | 8 | 73.20 | | |
| 17 | | FRONT DOOR | | | | | |
| 18 | R&I | LT R&I door assy | | | | 1.2 | |
| 19 | * | Rpr LT Door shell (HSS) | | | | <u>1.0</u> | 2.1 |
| 20 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 21 | # | R&I DECAL REMOVAL | | | | 0.5 | |
| 22 | | R&I LT Front w'strip | | | | 0.2 | |
| 23 | | R&I LT Power mirror w/o heat, w/o memory, w/o blind spot blue | | | | 0.5 | |
| 24 | | R&I LT Belt w'strip | | | | 0.3 | |
| 25 | | R&I LT R&I trim panel | | | | 0.5 | |
| 26 | | R&I LT Handle, outside black | | | | 0.4 | |
| 27 | | REAR DOOR | | | | | |
| 28 | * | Rpr LT Outer panel w/o wide body (HSS) | | | | <u>2.0</u> | 2.0 |
| 29 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 30 | | R&I LT Belt w'strip | | | | 0.3 | |
| 31 | | R&I LT R&I trim panel | | | | 0.5 | |
| 32 | | R&I LT Handle, outside black | | | | 0.4 | |
| 33 | | BACK GLASS | | | | | |
| 34 | * | Rpr Back glass Dodge Note: ROPE | | | | <u>1.0</u> | |
| 35 | | QUARTER PANEL | | | | | |
| 36 | * | Rpr LT Quarter panel | | | | <u>2.0</u> | 2.6 |
| 37 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 38 | | Add for Edging | | | | | 0.3 |
| 39 | | R&I Fuel door | | | | 0.3 | |
| 40 | * | Rpr Fuel door | | | | <u>0.5</u> | 0.3 |

Estimate of Record

Owner: STATE OF IOWA, STATE OF IOWA

Job Number:

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

| | | | | | | | | | | |
|----|----------------------------|-----|--------------------------|--|--|------------------|-------|--------------|-------------|-------------|
| 41 | # | R&I | DECAL REMOVAL | | | | | 1.0 | | |
| 42 | * | Rpr | RT Quarter panel | | | | | <u>1.0</u> | 2.6 | |
| 43 | | | Overlap Major Adj. Panel | | | | | | -0.4 | |
| 44 | TRUNK LID | | | | | | | | | |
| 45 | | R&I | R&I trunk lid | | | | | 0.8 | | |
| 46 | * | Rpr | Trunk lid all | | | | | <u>2.0</u> | 2.3 | |
| 47 | | | Overlap Major Adj. Panel | | | | | | -0.4 | |
| 48 | | | Clear Coat | | | | | | 2.5 | |
| 49 | | R&I | Trunk lid trim | | | | | 0.3 | | |
| 50 | # | | TRUNK LID ANTENNAS | | | 1 | | 1.0 | | |
| 51 | REAR LAMPS | | | | | | | | | |
| 52 | | R&I | RT Tail lamp assy | | | | | 0.3 | | |
| 53 | | R&I | LT Tail lamp assy | | | | | 0.3 | | |
| 54 | | R&I | Backup lamp | | | | | 0.3 | | |
| 55 | REAR BUMPER | | | | | | | | | |
| 56 | | R&I | R&I bumper cover | | | | | 1.2 | | |
| 57 | VEHICLE DIAGNOSTICS | | | | | | | | | |
| 58 | * | | Pre-repair scan | | | 1 | m | <u>0.5</u> M | | |
| 59 | * | | Post-repair scan | | | 1 | m | <u>0.5</u> M | | |
| 60 | # | | Tint Color | | | 1 | | | 0.5 | |
| 61 | # | | Corrosion Protection | | | 1 | 15.00 | | | |
| 62 | # | | Cover Car | | | 1 | 5.00 | | | |
| 63 | # | | Hazardous Waste | | | 1 | 4.00 | | | |
| | | | | | | SUBTOTALS | | 97.20 | 30.7 | 15.2 |

| | | | | | | | | |
|------------------------------|--|----------|----------|--------------|--|----------|-----------------|--------------------------|
| | | | | | | A | sum of B | C |
| | | | | | | F | F | F |
| ESTIMATE TOTALS | | | | | | | | |
| Category | | | | Basis | | | Rate | Cost \$ |
| Parts | | | | | | | | 97.20 A |
| Body Labor | | B | 29.7 hrs | @ | | | \$ 68.00 /hr | 2,019.60 R |
| Paint Labor | | C | 15.2 hrs | @ | | | \$ 118.00 /hr | 1,793.60 R |
| Mechanical Labor | | B | 1.0 hrs | @ | | | \$ 75.00 /hr | 75.00 R |
| Subtotal | | | | | | | | 3,985.40 |
| Total Cost of Repairs | | | | | | | | 3,985.40 F |
| Deductible | | | | | | | | 0.00 |
| Total Adjustments | | | | | | | | 0.00 |
| Net Cost of Repairs | | | | | | | | 3,985.40 |

Karl Chevrolet Collision Center Ankeny

Workfile ID: 6704821e
PartsShare: 7y8xy6
Federal ID: 42-1092272

Your Dealer for Life
1101 Southeast Oralabor Road, Ankeny, IA 50021
Phone: (515) 299-4337
FAX: (515) 964-2293

Estimate

RO Number:

| | | | |
|------------------------|---------------|-------------|------------------------|
| Customer: | Insurance: | Adjuster: | Estimator: |
| STATE OF IOWA UNIT 189 | STATE OF IOWA | Phone: | Michael Wright |
| | | Claim: 189 | Create Date: 9/13/2023 |
| (515) 725-0010 | | Loss Date: | |
| | | Deductible: | |

189

2020 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection WHITE

| | | | |
|------------------------|-------------------------|--------------------|--------------|
| VIN: 1GNSKDECXLR260989 | Interior Color: BLACK | Mileage In: 69,334 | Vehicle Out: |
| License: 189 | Exterior Color: WHITE | Mileage Out: | |
| State: IA | Production Date: 2/2020 | Condition: | Job #: |

| Line | Ver | Operation | Description | Qty | Extended Price \$ | Part Type | Labor | Type | Paint |
|------|-----|----------------|---|-----|-------------------|-----------|-------|------|-------|
| 1 | E01 | | HOOD | | | | | | |
| 2 | E01 | Repair | Hood (ALU) | | | | 3.0 | Body | 3.3 |
| 3 | E01 | | Add for Clear Coat | | | | | | 1.3 |
| 4 | E01 | | FRONT DOOR | | | | | | |
| 5 | E01 | Remove/Install | LT Belt molding chrome | | | | 0.3 | Body | |
| 6 | E01 | Remove/Install | LT Applique | | | | 0.2 | Body | |
| 7 | E01 | Remove/Install | LT R&I mirror | | | | 0.4 | Body | |
| 8 | E01 | Remove/Install | LT Handle, outside body color, w/o chrome w/o passive | | | | 0.4 | Body | |
| 9 | E01 | Remove/Install | LT R&I trim panel | | | | 0.4 | Body | |
| 10 | E01 | Blend | LT Outer panel Tahoe & Yukon | | | | | | 1.1 |
| 11 | E01 | Remove/Install | LT Upper molding chrome | | | | 0.2 | Body | |
| 12 | E01 | | REAR DOOR | | | | | | |
| 13 | E01 | Repair | LT Outer panel Tahoe & Yukon | | | | 3.0 | Body | 2.1 |
| 14 | E01 | | Overlap Major Non-Adj. Panel | | | | | | (0.2) |
| 15 | E01 | | Add for Clear Coat | | | | | | 0.4 |
| 16 | E01 | Remove/Install | LT Belt w'strip chrome | | | | 0.3 | Body | |
| 17 | E01 | Remove/Install | LT Handle, outside w/o chrome w/o passive | | | | 0.4 | Body | |
| 18 | E01 | Remove/Install | LT R&I trim panel | | | | 0.4 | Body | |
| 19 | E01 | | QUARTER PANEL | | | | | | |
| 20 | E01 | Repair | LT Quarter panel | | | | 3.0 | Body | 3.1 |
| 21 | E01 | | Overlap Major Adj. Panel | | | | | | (0.4) |
| 22 | E01 | | Add for Clear Coat | | | | | | 0.5 |

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Estimate

RO Number:

2020 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection WHITE

| | | | | | | | | |
|----|-----|----------------|-------------------------------------|---|-------|-------|-----|------|
| 23 | E01 | Remove/Install | LT Front molding chrome | | | | 0.2 | Body |
| 24 | E01 | Remove/Install | LT Rear molding | | | | 0.4 | Body |
| 25 | E01 | | REAR LAMPS | | | | | |
| 26 | E01 | Remove/Install | LT Combo lamp assy | | | | 0.3 | Body |
| 27 | E01 | | REAR BUMPER | | | | | |
| 28 | E01 | Remove/Install | R&I bumper cover | | | | 1.0 | Body |
| 29 | E01 | | MISCELLANEOUS OPERATIONS | | | | | |
| 30 | E01 | Sublet | Hazardous waste removal | 1 | 5.00 | Other | | |
| 31 | E01 | Remove/Replace | Cover Car | 1 | 10.00 | A/M | | |
| 32 | E01 | Remove/Replace | Corrosion protection | 1 | 10.00 | A/M | 0.3 | Body |
| 33 | E01 | | Post Repair Scan- Per OEM Guideline | | | | 0.5 | Body |
| 34 | E01 | | REMOVE DECALS | | | | 3.0 | Body |

| | | | | | | | | |
|------------------------|--------------------|------------------|----------------------|--|--------------------|---------------|----------|--------------------------|
| | | | F 25 sum of A | | B 17.7 | C 11.2 | F | |
| Estimate Totals | Discount \$ | Markup \$ | Rate \$ | | Total Hours | | | Total \$ |
| Parts | | | | | | | | 20.00 A |
| Sublet/Miscellaneous | | | | | | | | 5.00 A |
| Labor, Body | | | 55.00 | | B 17.7 | | | 973.50 R |
| Labor, Refinish | | | 100.00 | | C 11.2 | | | 1,120.00 R |
| Subtotal | | | | | | | | 2,118.50 |
| Sales Tax | | | | | | | | 0.00 |
| Grand Total | | | | | | | | 2,118.50 F |
| Net Total | | | | | | | | 2,118.50 |

| Estimate Version | Total \$ |
|------------------|----------|
| Original | 2,118.50 |

| | |
|--------------------------------|----------|
| Insurance Total \$: | 2,118.50 |
| Received from Insurance \$: | 0.00 |
| Balance due from Insurance \$: | 2,118.50 |
| Customer Total \$: | 0.00 |
| Received from Customer \$: | 0.00 |
| Balance due from Customer \$: | 0.00 |

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

QUALITY CLAIMS SOLUTIONS

Workfile ID: 2e71383e

105 N Krohn Place
SIOUX FALLS, SD 57103
Phone: (877) 237-3727, FAX:(605) 800-8591
qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: STATE OF IOWA UNIT 449, STATE OF IOWA UNIT 449

Job Number:

Written By: Ryland Malsam

| | | | | | |
|------------------|---|---------------|--------------------|-----------------|-------------------|
| Insured: | STATE OF IOWA UNIT 449, STATE OF IOWA UNIT 449 | Policy #: | UNKNOWN | Claim #: | APDSOI0266330-006 |
| Type of Loss: | Collision | Date of Loss: | 9/22/2023 12:00 PM | Days to Repair: | 0 |
| Point of Impact: | 12 Front | | | | |

Owner:
STATE OF IOWA UNIT 449, STATE OF IOWA UNIT 449
ANKENY, IA 50021

Inspection Location:
KARL CHEVROLET COLLISION CENTER
ANK
1101 SOUTHEAST ORLABOR ROAD
Ankeny, IA 50021
Other
(515) 299-4337 Evening

Repair Facility:

VEHICLE

2018 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection

| | | | | | |
|----------|-------------------|------------------|--------|-----------------|--|
| VIN: | 1GNSKDEC7JR240082 | Production Date: | | Interior Color: | |
| License: | 449 | Odometer: | 76,893 | Exterior Color: | |
| State: | | Condition: | | | |

TRANSMISSION

Automatic Transmission
Overdrive
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat

Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Rear Window Wiper
Climate Control

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
CD Player
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control

Communications System

Hands Free Device
Positraction

SEATS

Cloth Seats
Reclining/Lounge Seats
3rd Row Seat

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

TRUCK

Trailer Hitch

Estimate of Record

Owner: STATE OF IOWA UNIT 449, STATE OF IOWA UNIT
449

Job Number:

2018 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection

DECOR

Dual Mirrors
Privacy Glass

Dual Air Condition
Backup Camera
Parking Sensors

Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags

Trailer Package
Running Boards/Side Steps

Estimate of Record

Owner: STATE OF IOWA UNIT 449, STATE OF IOWA UNIT 449

Job Number:

2018 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection

| Line | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint |
|------|------|--|-------------|-----|-------------------|------------|-------|
| 1 | # | *QCS REVIEW USING CONTRACT RATES* | | 1 | | | |
| | | Note: RATES- BODY-57.5 PAINT-104.5 MECHANICAL/FRAME-57.5 DISCOUNTS- 28% ON OEM -DOMESTIC 20% ON OEM- IMPORT 25% ON AM | | | | | |
| 2 | | FRONT BUMPER | | | | | |
| 3 | R&I | R&I bumper cover | | | | 1.2 | |
| 4 | | FRONT LAMPS | | | | | |
| 5 | R&I | RT Headlamp assy w/o HID lamps w/o RST pkg | | | | 0.5 | |
| 6 | R&I | LT Headlamp assy w/o HID lamps w/o RST pkg | | | | 0.5 | |
| 7 | | HOOD | | | | | |
| 8 | * | Rpr Hood (ALU) | | | | <u>3.0</u> | 3.3 |
| 9 | | FENDER | | | | | |
| 10 | * | Rpr RT Fender Tahoe | | | | <u>4.0</u> | 2.2 |
| 11 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 12 | * | Rpr LT Fender Tahoe | | | | <u>2.0</u> | 2.2 |
| 13 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 14 | | FRONT DOOR | | | | | |
| 15 | * | Rpr RT Outer panel Tahoe & Yukon | | | | <u>3.0</u> | 2.1 |
| 16 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 17 | * | Rpr LT Outer panel Tahoe & Yukon | | | | <u>2.0</u> | 2.1 |
| 18 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 19 | R&I | RT Belt molding chrome | | | | 0.3 | |
| 20 | R&I | LT Belt molding chrome | | | | 0.3 | |
| 21 | R&I | RT Upper molding chrome | | | | 0.2 | |
| 22 | R&I | LT Upper molding chrome | | | | 0.2 | |
| 23 | R&I | RT Applique | | | | 0.2 | |
| 24 | R&I | LT Applique | | | | 0.2 | |
| 25 | R&I | RT R&I mirror | | | | 0.4 | |
| 26 | R&I | LT R&I mirror | | | | 0.4 | |
| 27 | R&I | RT Handle, outside body color, w/o chrome w/o passive | | | | 0.4 | |
| 28 | R&I | LT Handle, outside body color, w/o chrome w/o passive | | | | 0.4 | |
| 29 | R&I | RT R&I trim panel | | | | 0.4 | |
| 30 | R&I | LT R&I trim panel | | | | 0.4 | |
| 31 | | REAR DOOR | | | | | |

Estimate of Record

Owner: STATE OF IOWA UNIT 449, STATE OF IOWA UNIT 449

Job Number:

2018 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection

| | | | | | | | | | |
|-------------------------------|---|-----|---|---|-------|---|--------------|-------------|-------------|
| 32 | * | Rpr | RT Outer panel Tahoe & Yukon | | | | <u>3.0</u> | 2.1 | |
| 33 | | | Overlap Major Adj. Panel | | | | | -0.4 | |
| 34 | | R&I | RT Belt w'strip chrome | | | | 0.3 | | |
| 35 | | R&I | RT R&I trim panel | | | | 0.4 | | |
| 36 | | R&I | RT Handle, outside w/o chrome w/o passive | | | | 0.4 | | |
| 37 QUARTER PANEL | | | | | | | | | |
| 38 | * | Rpr | RT Quarter panel | | | | <u>3.0</u> | 3.1 | |
| 39 | | | Overlap Major Adj. Panel | | | | | -0.4 | |
| 40 | | | Clear Coat | | | | | 2.5 | |
| 41 | | R&I | RT Front molding chrome | | | | 0.2 | | |
| 42 | | R&I | RT Rear molding | | | | 0.4 | | |
| 43 REAR LAMPS | | | | | | | | | |
| 44 | | R&I | RT Combo lamp assy | | | | 0.3 | | |
| 45 REAR BUMPER | | | | | | | | | |
| 46 | | R&I | R&I bumper cover | | | | 1.0 | | |
| 47 | # | | Cover Car | 1 | 5.00 | | | | |
| 48 | # | | Hazardous Waste | 1 | 10.00 | | | | |
| 49 | # | | Corrosion Protection | 1 | 10.00 | | 0.3 | | |
| 50 | # | R&I | DECAL REMOVAL | | | | 3.0 | | |
| 51 VEHICLE DIAGNOSTICS | | | | | | | | | |
| 52 | | | Pre-repair scan | 1 | | m | | | |
| 53 | * | | Post-repair scan | 1 | | m | <u>0.5</u> | | |
| 54 | # | R&I | PUSH BAR | | | | 2.0 | | |
| SUBTOTALS | | | | | | | 25.00 | 34.8 | 17.2 |

| | | | | | | |
|------------------------------|---------------------|---------------|-----------------|----------|----------|----------|
| ESTIMATE TOTALS | | | | A | B | C |
| | | | | F | F | F |
| Category | Basis | Rate | Cost \$ | | | |
| Parts | | | 25.00 | | | A |
| Body Labor | B 34.8 hrs @ | \$ 57.50 /hr | 2,001.00 | | | R |
| Paint Labor | C 17.2 hrs @ | \$ 104.50 /hr | 1,797.40 | | | R |
| Subtotal | | | 3,823.40 | | | |
| Total Cost of Repairs | | | 3,823.40 | | | F |
| Deductible | | | 0.00 | | | |
| Total Adjustments | | | 0.00 | | | |
| Net Cost of Repairs | | | 3,823.40 | | | |

MyPriceLink Estimate ID / Quote ID:

1134494684584878080 /

Karl Chevrolet Collision Center Ankeny

Workfile ID: 8d215ee8
PartsShare: 7y8J9s
Federal ID: 42-1092272

Your Dealer for Life
1101 Southeast Oralabor Road, Ankeny, IA 50021
Phone: (515) 299-4337
FAX: (515) 964-2293

Estimate

RO Number:

| | | | |
|---|-----------------------------|--|---|
| Customer: STATE OF IOWA UNIT 500 (515) 725-0010 | Insurance: STATE OF IOWA | Adjuster: Phone: Claim: 500 Loss Date: Deductible: | Estimator: Michael Wright Create Date: 9/13/2023 |
|---|-----------------------------|--|---|

2017 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection WHITE

| | | | |
|------------------------|--------------------------|---------------------|--------------|
| VIN: 1GNSKDEC8HR196264 | Interior Color: BLACK | Mileage In: 139,229 | Vehicle Out: |
| License: 500 | Exterior Color: WHITE | Mileage Out: | |
| State: IA | Production Date: 12/2016 | Condition: | Job #: |

| Line | Ver | Operation | Description | Qty | Extended Price \$ | Part Type | Labor | Type | Paint |
|------|-----|----------------|---|-----|-------------------|-----------|-------|------|-------|
| 1 | E01 | | FRONT DOOR | | | | | | |
| 2 | E01 | Repair | RT Outer panel Tahoe & Yukon | | | | 2.0 | Body | 2.1 |
| 3 | E01 | | Add for Clear Coat | | | | | | 0.8 |
| 4 | E01 | Remove/Install | RT Belt molding | | | | 0.3 | Body | |
| 5 | E01 | Remove/Install | RT Upper molding | | | | 0.2 | Body | |
| 6 | E01 | Remove/Install | RT Applique | | | | 0.2 | Body | |
| 7 | E01 | Remove/Install | RT R&I mirror | | | | 0.4 | Body | |
| 8 | E01 | Remove/Install | RT Handle, outside body color, w/o chrome w/o passive | | | | 0.4 | Body | |
| 9 | E01 | Remove/Install | RT R&I trim panel | | | | 0.4 | Body | |
| 10 | E01 | | REAR DOOR | | | | | | |
| 11 | E01 | Repair | RT Outer panel Tahoe & Yukon | | | | 2.0 | Body | 2.1 |
| 12 | E01 | | Overlap Major Adj. Panel | | | | | | (0.4) |
| 13 | E01 | | Add for Clear Coat | | | | | | 0.3 |
| 14 | E01 | Repair | LT Outer panel Tahoe & Yukon | | | | 2.0 | Body | 2.1 |
| 15 | E01 | | Overlap Major Adj. Panel | | | | | | (0.4) |
| 16 | E01 | | Add for Clear Coat | | | | | | 0.3 |
| 17 | E01 | Remove/Install | RT Belt w'strip | | | | 0.3 | Body | |
| 18 | E01 | Remove/Install | LT Belt w'strip | | | | 0.3 | Body | |
| 19 | E01 | Remove/Install | RT Handle, outside w/o chrome w/o passive | | | | 0.4 | Body | |
| 20 | E01 | Remove/Install | LT Handle, outside w/o chrome w/o passive | | | | 0.4 | Body | |
| 21 | E01 | Remove/Install | RT R&I trim panel | | | | 0.4 | Body | |

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Estimate

RO Number:

2017 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection WHITE

| | | | | | | | | | |
|----|-----|----------------|-------------------------------------|---|-------|-------|-----|------|-------|
| 22 | E01 | Remove/Install | LT R&I trim panel | | | | 0.4 | Body | |
| 23 | E01 | | QUARTER PANEL | | | | | | |
| 24 | E01 | Repair | LT Quarter panel | | | | 3.0 | Body | 3.1 |
| 25 | E01 | | Overlap Major Adj. Panel | | | | | | (0.4) |
| 26 | E01 | | Add for Clear Coat | | | | | | 0.5 |
| 27 | E01 | Repair | RT Quarter panel | | | | 2.0 | Body | 3.1 |
| 28 | E01 | | Overlap Major Adj. Panel | | | | | | (0.4) |
| 29 | E01 | | Add for Clear Coat | | | | | | 0.5 |
| 30 | E01 | Remove/Install | RT Front molding | | | | 0.2 | Body | |
| 31 | E01 | Remove/Install | LT Front molding | | | | 0.2 | Body | |
| 32 | E01 | Remove/Install | RT Rear molding | | | | 0.4 | Body | |
| 33 | E01 | Remove/Install | LT Rear molding | | | | 0.4 | Body | |
| 34 | E01 | | REAR LAMPS | | | | | | |
| 35 | E01 | Remove/Install | RT Combo lamp assy | | | | 0.3 | Body | |
| 36 | E01 | Remove/Install | LT Combo lamp assy | | | | 0.3 | Body | |
| 37 | E01 | | REAR BUMPER | | | | | | |
| 38 | E01 | Remove/Install | R&I bumper cover | | | | 1.0 | Body | |
| 39 | E01 | | MISCELLANEOUS OPERATIONS | | | | | | |
| 40 | E01 | Sublet | Hazardous waste removal | 1 | 5.00 | Other | | | |
| 41 | E01 | Remove/Replace | Corrosion protection | 1 | 10.00 | A/M | 0.3 | Body | |
| 42 | E01 | Remove/Replace | Cover Car | 1 | 10.00 | A/M | | | |
| 43 | E01 | | Post Repair Scan- Per OEM Guideline | | | | 0.5 | Body | |
| 44 | E01 | | REMOVE DECALS | | | | 3.0 | Body | |

| | | | | | | | | | | |
|------------------------|--------------------|------------------|----------------|--------------------|--|--------------------|---------------|--|-----------------|----------|
| | | | | 25 sum of A | | | 21.7 B | | 13.3 C | F |
| Estimate Totals | Discount \$ | Markup \$ | Rate \$ | | | Total Hours | | | Total \$ | |
| Parts | | | | | | | | | 20.00 | A |
| Sublet/Miscellaneous | | | | | | | | | 5.00 | A |
| Labor, Body | | | 55.00 | | | B 21.7 | | | 1,193.50 | R |
| Labor, Refinish | | | 100.00 | | | C 13.3 | | | 1,330.00 | R |
| Subtotal | | | | | | | | | 2,548.50 | |
| Sales Tax | | | | | | | | | 0.00 | |
| Grand Total | | | | | | | | | 2,548.50 | F |
| Net Total | | | | | | | | | 2,548.50 | |

| | |
|-------------------------|-----------------|
| Estimate Version | Total \$ |
| Original | 2,548.50 |

| | |
|--------------------------------|----------|
| Insurance Total \$: | 2,548.50 |
| Received from Insurance \$: | 0.00 |
| Balance due from Insurance \$: | 2,548.50 |
| Customer Total \$: | 0.00 |

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Estimate

RO Number:

2017 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection WHITE

| | |
|-------------------------------|------|
| Received from Customer \$: | 0.00 |
| Balance due from Customer \$: | 0.00 |

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural



NORTH IOWA COLLISION CENTER INC.

Serving your car, light & heavy duty truck, heavy
equipment & RV repair needs.
11201 265TH ST, CLEAR LAKE, IA 50428
Phone: (641) 421-8555
FAX: (641) 421-8558

Workfile ID: 3bb46637
PartsShare: 7yngk8
Federal ID: 87-2591068
State ID: 1-17-020011
Resale Number: 1-17-020011
Federal EPA: IAR000007856

Preliminary Estimate

Customer: Iowa State Patrol

Written By: Scott Larson

Insured: Iowa State Patrol
Type of Loss:
Point of Impact: 29 Vandalism

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:

Iowa State Patrol
4425 S Washington
Mason City, IA 50401
(111) 111-1111 Cell

Inspection Location:

NORTH IOWA COLLISION CENTER INC.
11201 265TH ST
CLEAR LAKE, IA 50428
Repair Facility
(641) 421-8555 Business

Insurance Company:

VEHICLE

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Blue Metallic

VIN: 2C3CDXKG2MH528651 Interior Color: Mileage In: 55,508 Vehicle Out:
License: JUH738 Exterior Color: Blue Metallic Mileage Out:
State: IA Production Date: 12/2020 Condition: Job #:

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel

CLIMATE

Climate Control
Backup Camera
Parking Sensors

RADIO

AM Radio

FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions
Power Trunk/Liftgate

Get live updates at www.carwise.com/e/4BcPmK

Preliminary Estimate

Customer: Iowa State Patrol

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI Blue Metallic

| Line | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint |
|------------------|------|---------------------------------|-------------|-----|-------------------|------------|------------|
| 1 | | TRUNK LID | | | | | |
| 2 | * | Rpr Trunk lid all | | | | 1.0 | 1.0 |
| 3 | | Add for Clear Coat | | | | | 0.4 |
| 4 | | R&I Lock cylinder | | | | 0.3 | |
| 5 | | Repl Nameplate "CHARGER" chrome | 68280000AA | 1 | 64.80 | 0.2 | |
| 6 | | Repl Nameplate "AWD" | 68216158AB | 1 | 64.80 | 0.2 | |
| 7 | # | Rpr Clean up of adhesive | | | | 0.1 | |
| 8 | | R&I Trunk lid trim | | | | 0.3 | |
| 9 | | REAR LAMPS | | | | | |
| 10 | | R&I Backup lamp | | | | 0.3 | |
| 11 | | MISCELLANEOUS OPERATIONS | | | | | |
| 12 | ** | Repl A/M Cover car/bag | | 1 | 10.00 | 0.2 | |
| 13 | ** | Repl A/M Corrosion Protection | | 1 | 10.00 | 0.2 | |
| 14 | | OTHER CHARGES | | | | | |
| 15 | # | Haz-Waste | | 1 | 4.00 | | |
| SUBTOTALS | | | | | 153.60 | 2.8 | 1.4 |
| NOTES | | | | | sum of A | B | C |
| | | | | | F | F | F |

Prior Damage Notes:
Normal wear

ESTIMATE TOTALS

| Category | Basis | Rate | Cost \$ |
|--------------------|--------------------|---------------|------------------------|
| Parts | | | 149.60 A |
| Body Labor | B 2.8 hrs @ | \$ 68.00 /hr | 190.40 R |
| Paint Labor | C 1.4 hrs @ | \$ 119.00 /hr | 166.60 R |
| Other Charges | | | 4.00 A |
| Subtotal | | | 510.60 |
| Grand Total | | | 510.60 F |

QUALITY CLAIMS SOLUTIONS

Workfile ID: 1b1baad0

105 N Krohn Place
SIOUX FALLS, SD 57103
Phone: (877) 237-3727, FAX:(605) 800-8591
qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: STATE OF IOWA

Job Number:

Written By: Mike Mayer

Insured: STATE OF IOWA
Type of Loss: Collision
Point of Impact: 17 Left & Right Side

Policy #: UNKNOWN
Date of Loss: 9/22/2023 12:00 PM

Claim #: APDSOI0266330-009
Days to Repair: 0

Owner:
STATE OF IOWA

ANKENY, IA 50021

Inspection Location:
KARL CHEVROLET COLLISION CENTER
ANK
1101 SOUTHEAST ORLABOR ROAD
Ankeny, IA 50021
Other
(515) 299-4337 Evening

Repair Facility:

VEHICLE

2019 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection White

VIN: 1GNSKDEC9KR236942
License: 512
State: IA

Production Date:
Odometer: 81,881
Condition:

Interior Color:
Exterior Color: White

512

TRANSMISSION

Automatic Transmission
Overdrive
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat

DECOR

Dual Mirrors

Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Rear Window Wiper
Climate Control
Dual Air Condition
Backup Camera

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
CD Player
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags

Communications System

Hands Free Device
Positraction

SEATS

Cloth Seats
Reclining/Lounge Seats
3rd Row Seat

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

TRUCK

Trailer Hitch
Trailer Package
Running Boards/Side Steps

Estimate of Record

Owner: STATE OF IOWA

Job Number:

2019 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection White

Privacy Glass

Parking Sensors

Head/Curtain Air Bags

Estimate of Record

Owner: STATE OF IOWA

Job Number:

2019 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection White

| Line | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint |
|------|------|---|-------------|-----|-------------------|------------|-------|
| 1 | | FRONT BUMPER | | | | | |
| 2 | R&I | R&I bumper cover | | | | 1.2 | |
| 3 | | FRONT LAMPS | | | | | |
| 4 | R&I | RT Headlamp assy w/o HID lamps w/o RST pkg | | | | 0.5 | |
| 5 | | FENDER | | | | | |
| 6 | * | Rpr RT Fender Tahoe | | | | <u>3.0</u> | 2.2 |
| 7 | | FRONT DOOR | | | | | |
| 8 | * | Rpr RT Outer panel Tahoe & Yukon | | | | <u>2.0</u> | 2.1 |
| 9 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 10 | R&I | RT Belt molding chrome | | | | 0.3 | |
| 11 | R&I | RT Upper molding chrome | | | | 0.2 | |
| 12 | R&I | RT Applique | | | | 0.2 | |
| 13 | R&I | RT R&I mirror | | | | 0.4 | |
| 14 | R&I | RT Handle, outside body color, w/o chrome w/o passive | | | | 0.4 | |
| 15 | R&I | RT R&I trim panel | | | | 0.4 | |
| 16 | | REAR DOOR | | | | | |
| 17 | * | Rpr RT Outer panel Tahoe & Yukon | | | | <u>2.0</u> | 2.1 |
| 18 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 19 | * | Rpr LT Outer panel Tahoe & Yukon | | | | <u>2.0</u> | 2.1 |
| 20 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 21 | R&I | RT Belt w/strip chrome | | | | 0.3 | |
| 22 | R&I | LT Belt w/strip chrome | | | | 0.3 | |
| 23 | R&I | RT Handle, outside w/o chrome w/o passive | | | | 0.4 | |
| 24 | R&I | LT Handle, outside w/o chrome w/o passive | | | | 0.4 | |
| 25 | R&I | RT R&I trim panel | | | | 0.4 | |
| 26 | R&I | LT R&I trim panel | | | | 0.4 | |
| 27 | | QUARTER PANEL | | | | | |
| 28 | * | Rpr RT Quarter panel | | | | <u>2.0</u> | 3.1 |
| 29 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 30 | * | Rpr LT Quarter panel | | | | <u>2.0</u> | 3.1 |
| 31 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 32 | R&I | RT Front molding chrome | | | | 0.2 | |
| 33 | R&I | LT Front molding chrome | | | | 0.2 | |
| 34 | R&I | RT Rear molding | | | | 0.4 | |
| 35 | R&I | LT Rear molding | | | | 0.4 | |
| 36 | | LIFT GATE | | | | | |
| 37 | * | Rpr Lift gate (ALU) | | | | <u>2.0</u> | 2.3 |
| 38 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 39 | | Clear Coat | | | | | 2.5 |

Estimate of Record

Owner: STATE OF IOWA

Job Number:

2019 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Flex Fuel Direct Injection White

| | | | | | |
|------------------------------------|-----|--|---|--------------|-------------|
| 40 | R&I | Handle | | | 0.4 |
| 41 | R&I | Upper gate trim black | | | Incl. |
| 42 | R&I | Lower trim panel w/o power lift gate black | | | 0.6 |
| 43 REAR LAMPS | | | | | |
| 44 | R&I | RT Combo lamp assy | | | 0.3 |
| 45 | R&I | LT Combo lamp assy | | | 0.3 |
| 46 | * | Rpr LT Combo lamp assy | | | <u>1.0</u> |
| 47 REAR BUMPER | | | | | |
| 48 | R&I | R&I bumper cover | | | 1.0 |
| 49 VEHICLE DIAGNOSTICS | | | | | |
| 50 | * | Rpr Post-repair scan | | m | <u>0.5</u> |
| 51 MISCELLANEOUS OPERATIONS | | | | | |
| 52 | * | Repl Cover car/bag | 1 | <u>10.00</u> | <u>0.0</u> |
| 53 | # | Hazardous Waste | 1 | 3.00 | |
| 54 | # | Corrosion Protection | 1 | 5.00 | 0.1 |
| 55 | # | Remove Decals | 1 | | 3.0 |
| 56 | # | R&I Push Bar | | | 2.0 |
| SUBTOTALS | | | | 18.00 | 31.2 |
| | | | | A | B |
| | | | | F | F |
| | | | | | C |
| | | | | | F |

| ESTIMATE TOTALS | Basis | Rate | Cost \$ |
|------------------------------|---------------------|---------------|-----------------|
| Parts | | | 18.00 |
| Body Labor | B 31.2 hrs @ | \$ 57.50 /hr | 1,794.00 |
| Paint Labor | C 17.1 hrs @ | \$ 104.50 /hr | 1,786.95 |
| Subtotal | | | 3,598.95 |
| Total Cost of Repairs | | | 3,598.95 |
| Deductible | | | 0.00 |
| Total Adjustments | | | 0.00 |
| Net Cost of Repairs | | | 3,598.95 |

MyPriceLink Estimate ID / Quote ID:

1134479096177238016 /

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.



NORTH IOWA COLLISION CENTER INC.

Serving your car, light & heavy duty truck, heavy
equipment & RV repair needs.
11201 265TH ST, CLEAR LAKE, IA 50428
Phone: (641) 421-8555
FAX: (641) 421-8558

WorkMe ID: 1D14a5aR
PartsShare: 7y7KjM
Federal ID: 87-2591068
Resale Number: 1-17-020011
Federal EPA: IAR000007856

Estimate

RO Number:

| | | | |
|----------------------|------------|-------------|------------------------|
| Customer: | Insurance: | Adjuster: | Estimator: |
| Iowa State Patrol | | Phone: | Scott Larson |
| 4425 S Washington | | Claim: | Create Date: 9/13/2023 |
| Mason City, IA 50401 | | Loss Date: | |
| (111) 111-1111 | | Deductible: | |

2021 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection White

| | | | |
|------------------------|--------------------------|--------------------|--------------|
| VIN: 1GNSKLED4MR255873 | Interior Color: | Mileage In: 56,145 | Vehicle Out: |
| License: 163 | Exterior Color: White | Mileage Out: | |
| State: | Production Date: 10/2020 | Condition: | Job #: |

| Line | Ver | Operation | Description | Qty | Extended Price \$ | Part Type | Labor | Type | Paint |
|------|-----|----------------|------------------------------------|-----|-------------------|-----------|-------|------|-------|
| 1 | E01 | | FRONT BUMPER & GRILLE | | | | | | |
| 2 | E01 | Remove/Install | R&I bumper cover | | | | 1.7 | Body | |
| 3 | E01 | Remove/Install | Push Bar | | | | 1.5 | Body | |
| 4 | E01 | | FRONT LAMPS | | | | | | |
| 5 | E01 | Remove/Install | LT Headlamp assy | | | | 0.5 | Body | |
| 6 | E01 | | HOOD | | | | | | |
| 7 | E01 | Repair | Hood | | | | 1.0 | Body | 3.2 |
| 8 | E01 | | Add for Clear Coat | | | | | | 1.3 |
| 9 | E01 | | FENDER | | | | | | |
| 10 | E01 | Repair | LT Fender | | | | 1.0 | Body | 2.2 |
| 11 | E01 | | Overlap Major Adj. Panel | | | | | | (0.4) |
| 12 | E01 | | Add for Clear Coat | | | | | | 0.4 |
| 13 | E01 | Remove/Replace | Decal " State Trooper" | | | A/M | 0.5 | Body | |
| 14 | E01 | | PILLARS, ROCKER & FLOOR | | | | | | |
| 15 | E01 | Remove/Install | LT Step bar assy black | | | | 0.7 | Body | |
| 16 | E01 | | FRONT DOOR | | | | | | |
| 17 | E01 | Remove/Install | LT R&I door assy | | | | 0.5 | Body | |
| 18 | E01 | Repair | LT Outer panel | | | | 1.0 | Body | |
| 19 | E01 | Remove/Install | LT Front w'strip | | | | 0.1 | Body | |
| 20 | E01 | Remove/Install | LT Belt molding black | | | | 0.3 | Body | |
| 21 | E01 | Remove/Install | LT Upper molding black | | | | 0.2 | Body | |
| 22 | E01 | Remove/Replace | LT Upper molding rivet | 3 | 25.05 | OEM | | | |

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number:

2021 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection White

| | | | | | | | | | | | | |
|----|-----|----------------|---|---|-------|-----|--|--|--|-----|------|-------|
| 23 | E01 | Remove/Install | LT Front applique | | | | | | | 0.2 | Body | |
| 24 | E01 | Remove/Install | LT Rear applique | | | | | | | 0.2 | Body | |
| 25 | E01 | Remove/Replace | Decal "Iowa State Patrol" | | | A/M | | | | 0.5 | Body | |
| 26 | E01 | Remove/Install | LT R&I mirror | | | | | | | 0.4 | Body | |
| 27 | E01 | Remove/Install | LT Handle, outside w/o chrome | | | | | | | 0.4 | Body | |
| 28 | E01 | Remove/Install | LT Window molding | | | | | | | 0.2 | Body | |
| 29 | E01 | Remove/Install | LT Door trim panel support bracket | | | | | | | | | |
| 30 | E01 | Remove/Install | LT R&I trim panel | | | | | | | 0.4 | Body | |
| 31 | E01 | | REAR DOOR | | | | | | | | | |
| 32 | E01 | Repair | LT Outer panel | | | | | | | 1.5 | Body | |
| 33 | E01 | Remove/Install | LT Front w'strip | | | | | | | 0.1 | Body | |
| 34 | E01 | Remove/Install | LT Rear w'strip | | | | | | | 0.1 | Body | |
| 35 | E01 | Remove/Install | LT Belt molding black | | | | | | | 0.3 | Body | |
| 36 | E01 | Remove/Install | LT Upper molding black | | | | | | | 0.2 | Body | |
| 37 | E01 | Remove/Replace | LT Upper molding rivet | 3 | 25.05 | OEM | | | | | | |
| 38 | E01 | Remove/Install | LT Front applique | | | | | | | 0.2 | Body | |
| 39 | E01 | Remove/Install | LT Rear applique | | | | | | | 0.2 | Body | |
| 40 | E01 | Remove/Install | LT Door glass GM w/privacy tint | | | | | | | 0.5 | Body | |
| 41 | E01 | Remove/Install | LT Fixed glass GM w/privacy tint | | | | | | | 0.7 | Body | |
| 42 | E01 | Remove/Install | LT Handle, outside w/o chrome | | | | | | | 0.4 | Body | |
| 43 | E01 | Remove/Install | LT Water shield | | | | | | | 0.2 | Body | |
| 44 | E01 | Remove/Install | LT R&I trim panel | | | | | | | 0.4 | Body | |
| 45 | E01 | | QUARTER PANEL | | | | | | | | | |
| 46 | E01 | Repair | LT Quarter panel | | | | | | | 1.5 | Body | 3.1 |
| 47 | E01 | | Overlap Major Non-Adj. Panel | | | | | | | | | (0.2) |
| 48 | E01 | | Add for Clear Coat | | | | | | | | | 0.6 |
| 49 | E01 | Remove/Install | Fuel door | | | | | | | 0.3 | Body | |
| 50 | E01 | Repair | Fuel door | | | | | | | 0.5 | Body | 0.5 |
| 51 | E01 | | Overlap Minor Panel | | | | | | | | | (0.2) |
| 52 | E01 | | Add for Clear Coat | | | | | | | | | 0.1 |
| 53 | E01 | Remove/Install | LT Front molding black | | | | | | | 0.2 | Body | |
| 54 | E01 | Remove/Install | LT Rear molding | | | | | | | 0.4 | Body | |
| 55 | E01 | Remove/Install | LT Upper molding black | | | | | | | 0.2 | Body | |
| 56 | E01 | Remove/Install | LT Qtr glass GM, w/glass breakage sensor w/privacy tint | | | | | | | 2.0 | Body | |
| 57 | E01 | Remove/Replace | Urethane / Glass Kit | 1 | 25.00 | A/M | | | | | | |
| 58 | E01 | Remove/Install | LT Lock pillar trim black | | | | | | | 0.0 | Body | |
| 59 | E01 | Remove/Install | LT Rear pillar trim black | | | | | | | 0.1 | Body | |
| 60 | E01 | Remove/Install | LT Lower qtr trim manual fold seat black | | | | | | | 0.7 | Body | |
| 61 | E01 | | LIFT GATE | | | | | | | | | |
| 62 | E01 | Repair | Lift gate | | | | | | | 2.0 | Body | 2.4 |
| 63 | E01 | | Overlap Major Adj. Panel | | | | | | | | | (0.4) |
| 64 | E01 | | Add for Clear Coat | | | | | | | | | 0.4 |

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Estimate

RO Number:

2021 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection White

| | | | | | | | | |
|----|-----|----------------|---|---|--------|--------|-----|------|
| 65 | E01 | Remove/Install | Applique panel type 2 | | | | 0.5 | Body |
| 66 | E01 | Remove/Install | Handle | | | | 0.3 | Body |
| 67 | E01 | Remove/Install | Lift gate glass GM w/privacy tint | | | | 1.6 | Body |
| 68 | E01 | Remove/Replace | Urethane / Glass Kit | 1 | 25.00 | A/M | | |
| 69 | E01 | Remove/Install | R&I spoiler | | | | 0.5 | Body |
| 70 | E01 | Remove/Replace | Decal & reflective tape "State Trooper" | | | A/M | 0.5 | Body |
| 71 | E01 | Remove/Install | Upper gate trim black | | | | 0.3 | Body |
| 72 | E01 | Remove/Install | RT Side gate trim black | | | | 0.3 | Body |
| 73 | E01 | Remove/Install | LT Side gate trim black | | | | 0.3 | Body |
| 74 | E01 | | REAR LAMPS | | | | | |
| 75 | E01 | Remove/Install | LT Tail lamp | | | | 0.4 | Body |
| 76 | E01 | | REAR BUMPER | | | | | |
| 77 | E01 | Remove/Install | R&I bumper cover | | | | 1.1 | Body |
| 78 | E01 | | VEHICLE DIAGNOSTICS | | | | | |
| 79 | E01 | Sublet | Pre-repair scan | 1 | 96.50 | Sublet | | |
| 80 | E01 | Repair | Pre Repair Scan Labor | | | | 0.5 | Mech |
| 81 | E01 | Sublet | Post-repair scan | 1 | 128.95 | Sublet | | |
| 82 | E01 | Repair | Post Repair Scan Labor | | | | 0.5 | Mech |
| 83 | E01 | | MISCELLANEOUS OPERATIONS | | | | | |
| 84 | E01 | Remove/Replace | Cover car/bag | 1 | 10.00 | A/M | 0.2 | Body |
| 85 | E01 | Remove/Replace | Corrosion Protection | 1 | 10.00 | A/M | 0.2 | Body |

sum of A 345.55 31.2 sum of B 13 C
 F F F

| Estimate Totals | Discount \$ | Markup \$ | Rate \$ | Total Hours | Total \$ |
|------------------------|--------------------|------------------|----------------|--------------------|--------------------------|
| Parts | | | | | 120.10 A |
| Sublet/Miscellaneous | | | | | 225.45 A |
| Labor, Body | | | 68.00 | B 30.2 | 2,053.60 R |
| Labor, Refinish | | | 119.00 | C 13.0 | 1,547.00 R |
| Labor, Mechanical | | | 72.00 | B 1.0 | 72.00 R |
| Material, Paint | | | 50.00 | C 13.0 | 650.00 R |
| E.P.C. | | | | | 4.00 |
| Subtotal | | | | | 4,672.15 |
| Sales Tax | | | | | 0.00 |
| Grand Total | | | | | 4,672.15 F |
| Net Total | | | | | 4,672.15 |

| Estimate Version | Total \$ |
|-------------------------|-----------------|
| Original | 4,672.15 |

| | |
|---------------------------------------|-------------|
| Insurance Total \$: | 0.00 |
| Received from Insurance \$: | 0.00 |
| Balance due from Insurance \$: | 0.00 |

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

QUALITY CLAIMS SOLUTIONS

Workfile ID:

ff50b564

105 N Krohn Place
SIOUX FALLS, SD 57103
Phone: (877) 237-3727, FAX:(605) 800-8591
qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: STATE OF IOWA, STATE OF IOWA

Job Number:

Written By: Jon Gustafson

Insured: STATE OF IOWA, STATE OF IOWA Policy #: UNKNOWN Claim #: APDSOI0266330-012
Type of Loss: Collision Date of Loss: 10/12/2023 12:00 PM Days to Repair: 0
Point of Impact: 03 Right T-Bone (Right Side)

Owner:
STATE OF IOWA, STATE OF IOWA

ANKENY, IA 50021

Inspection Location:
KARL CHEVROLET COLLISION CENTER
ANK
1101 SOUTHEAST ORLABOR ROAD
Ankeny, IA 50021
Other
(515) 299-4337 Evening

Repair Facility:

#541

VEHICLE

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

VIN: 2C3CDXKT6KH577250 Production Date: 12/2018 Interior Color:
License: Odometer: 104,185 Exterior Color:
State: Condition:

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera
Parking Sensors

AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
California Emissions
Power Trunk/Liftgate

Estimate of Record

Owner: STATE OF IOWA, STATE OF IOWA

Job Number:

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

Overhead Console

RADIO

SEATS

Estimate of Record

Owner: STATE OF IOWA, STATE OF IOWA

Job Number:

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

| Line | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint |
|------|------|---|-------------|-----|-------------------|-------|-------|
| 1 | | FRONT BUMPER & GRILLE | | | | | |
| 2 | R&I | R&I bumper cover | | | | 1.9 | |
| 3 | | FRONT LAMPS | | | | | |
| 4 | R&I | RT R&I headlamp assy | | | | 0.3 | |
| 5 | | FENDER | | | | | |
| 6 | Blnd | RT Fender | | | | | 1.0 |
| 7 | | FRONT DOOR | | | | | |
| 8 | * | Rpr RT Outer panel (HSS) | | | | 3.0 | 2.1 |
| 9 | | Add for Clear Coat | | | | | 0.8 |
| 10 | R&I | RT Belt w'strip | | | | 0.3 | |
| 11 | Repl | RT Applique | 57010426AE | 1 | 133.00 | 0.2 | |
| 12 | R&I | RT Power mirror w/o heat, w/o memory, w/o blind spot blue | | | | 0.5 | |
| 13 | R&I | RT Handle, outside black | | | | 0.4 | |
| 14 | R&I | RT R&I trim panel | | | | 0.5 | |
| 15 | | REAR DOOR | | | | | |
| 16 | * | Rpr RT Outer panel (HSS) | | | | 3.0 | 2.0 |
| 17 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 18 | | Add for Clear Coat | | | | | 0.3 |
| 19 | R&I | RT Belt w'strip | | | | 0.3 | |
| 20 | Repl | RT Applique | 57010428AD | 1 | 121.00 | 0.2 | |
| 21 | R&I | RT Handle, outside black | | | | 0.4 | |
| 22 | R&I | RT R&I trim panel | | | | 0.5 | |
| 23 | | QUARTER PANEL | | | | | |
| 24 | * | Rpr RT Quarter panel | | | | 3.0 | 2.6 |
| 25 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 26 | | Add for Clear Coat | | | | | 0.4 |
| 27 | * | Rpr LT Quarter panel | | | | 2.0 | 2.6 |
| 28 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 29 | | Add for Clear Coat | | | | | 0.4 |
| 30 | | TRUNK LID | | | | | |
| 31 | * | Rpr Trunk lid w/police w/camera | | | | 3.0 | 1.5 |
| 32 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 33 | | Add for Clear Coat | | | | | 0.2 |
| 34 | | REAR LAMPS | | | | | |
| 35 | R&I | RT Tail lamp assy | | | | 0.3 | |
| 36 | R&I | LT Tail lamp assy | | | | 0.3 | |
| 37 | R&I | Backup lamp | | | | 0.3 | |
| 38 | | REAR BUMPER | | | | | |
| 39 | R&I | R&I bumper cover | | | | 1.2 | |
| 40 | # | Hazardous Waste | | 1 | 3.00 | | |
| 41 | # | Corrosion Protection | | 1 | 5.00 | 0.1 | |
| 42 | # | Cover Car | | 1 | 10.00 | | |

Estimate of Record

Owner: STATE OF IOWA, STATE OF IOWA

Job Number:

2019 DODG Charger Police AWD (Fleet) 4D SED 8-5.7L Gasoline Sequential MPI

| | | | | |
|------------------|---|---------------|---------------|-------------|
| 43 | # | Remove Decals | 1 | 3.0 |
| 44 | # | Post Scan | 1 | 0.5 |
| SUBTOTALS | | | 272.00 | 25.2 |

| ESTIMATE TOTALS | Basis | Rate | Cost \$ |
|------------------------------|---------------------|---------------|-------------------|
| Parts | | | 272.00 A |
| Parts Discount | \$ 254.00 | -28.0 % | -71.12 R |
| Body Labor | B 25.2 hrs @ | \$ 57.50 /hr | 1,449.00 R |
| Paint Labor | C 12.3 hrs @ | \$ 104.50 /hr | 1,285.35 R |
| Subtotal | | | 2,935.23 F |
| Total Cost of Repairs | | | 2,935.23 |
| Deductible | | | 0.00 |
| Total Adjustments | | | 0.00 |
| Net Cost of Repairs | | | 2,935.23 |

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.